

Replace a Supervisor Module or Stack Member of Catalyst 9000 in HA

Contents

[Introduction](#)

[Prerequisites](#)

[Requirements](#)

[Components Used](#)

[Background Information](#)

[Replace a Member of C9300 or C9200 Stack](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Redundant Supervisor of C9400 Standalone Chassis](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Supervisor of C9400 Dual-Sup StackWise-Virtual](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Member of the C9500 StackWise-Virtual](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Redundant Supervisor of C9600 Dual-Sup Standalone Chassis](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Supervisor of C9600 Dual-Sup StackWise-Virtual](#)

[Verify Pre-Replacement](#)

[Replace](#)

[Verify Post-Replacement](#)

[Replace a Supervisor of C9600 Quad-Sup StackWise-Virtual](#)

[Replace and Verify](#)

Introduction

This document describes how to replace a supervisor module or a stack member of Catalyst 9K switches in HA (High Availability) setup.

Prerequisites

Requirements

Cisco recommends that you are familiar with stacking, stackwise-virtual (SVL), and "bundle" Vs "install" boot mode related concepts on Catalyst 9K switches.

Components Used

The information in this document is based on these software and hardware versions:

- C9200
- C9300
- C9400
- C9500
- C9600

Note: Consult the appropriate configuration guide for the commands that are used in order to enable these features on other Cisco platforms.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, ensure that you understand the potential impact of any command.

Background Information

This document includes the processes to replace a member of stackable switch types:

- C9200/C9300 stack member
- C9500 using SVL
- Supervisor of a C9400/C9600 chassis in their various mode of operations (standalone, dual-sup, SVL and quad-sup SVL).

Replace a Member of C9300 or C9200 Stack

In this example, you **replace a member** of a C9300 stack. (The switch is in this example uses switch 2 in "Install" boot mode).

Note: The same process can be used for the replacement of a **C9200** stack member.



Verify Pre-Replacement

Check the current stack state and prepare for the swap. Ensure that **boot variable** on switch is set pointing to correct package file (if boot mode is Install) or bin file (bundle boot mode) and **auto-boot** is enabled.

```
<#root>
```

```
cat9K#
```

```
show boot
```

```
-----  
Switch 1  
-----
```

```
Current Boot Variables:
```

```
BOOT variable =
```

```
flash:packages.conf;
```

```
Boot Variables on next reload:
```

```
BOOT variable =
```

```
flash:packages.conf;
```

```
Manual Boot = no
```

```
Enable Break = yes
```

```
Boot Mode = DEVICE
```

```
iPXE Timeout = 0
```

Note: If the switch is in "**Install**" boot mode, **verify** that software auto-upgrade is enabled. If not, then enable that by configuring "**software auto-upgrade enable**" from global configuration mode.

```
<#root>
```

```
C9300#
```

```
show run all | in software auto
```

```
no software auto-upgrade source url
```

```
software auto-upgrade enable
```

Note: If the stack is in "**Bundle**" boot mode, you need a copy of the IOS-XE .bin file that is in use on active on an USB stick or local TFTP server which can be accessed from new switch/member, through it's out-of-band (OOB) management port

Check that the stack is physically connected in **full-ring**, i.e if you power off the switch member in question, then existing stack would not split to cause **stack-merge**. Once verified, move to next steps.

```
<#root>
```

```
Switch#
```

```
sh switch neighbors
```

```
Switch #  Port 1  Port 2
-----  -
1
2          3
2
3          2
3
1          2
```

Note: If **active** switch member needs to be replaced, perform a **failover** to the **standby** switch in the stack, and wait for it to take over the **active** role. Skip this step, if you are going to replace any other member of the stack.

```
<#root>
```

```
C9300#
```

```
redundancy force-switchover
```

```
System configuration has been modified. Save? [yes/no]: yes
```

```
Building configuration...
```

```
Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi
```

Replace

Power off the member switch that needs to be replaced, disconnect power-stack and data-stack cables from it. **Replace the member** with new one at powered down state, reconnect the data-stack cables and power it on.

Note: IF the new unit is not running same software version as existing stack, you need to match that. For example, existing stack is running 17.3.1 and new unit is running 16.9.3.

If your stack is in "Bundle" boot mode, break into the ROMMON of new switch, while it is booting up.

With help of an USB stick or OOB TFTP access, manually boot the new switch with same software version as existing stack.

```
<#root>
```

```
Preparing to autoboot. [Press Ctrl-C to interrupt] 3 (interrupted)
```

```
rommon 1 >
```

```
rommon 2 >
```

```
boot usbflash0:cat9k_iosxe.17.03.01.SPA.bin
```

If the stack is in "Install" boot mode, automatic software upgrade must be kicked in by current active of the stack, as soon it detects an incompatible software version or boot mode on new member switch. Typically, no manual intervention is needed at this stage.

Note: During the software auto-upgrade process, if there is need of microcode_update, the process can take several minutes. Please be patient and monitor the process closely.

```
<#root>
```

```
Logs from Stack Active
```

```
Sep 13 07:20:21.261 UTC: %STACKMGR-4-SWITCH_ADDED: Switch 1 R0/0: stack_mgr: Switch 2 has been added to  
Sep 13 07:20:22.268 UTC: %STACKMGR-4-SWITCH_ADDED: Switch 1 R0/0: stack_mgr: Switch 2 has been added to  
Sep 13 07:20:22.546 UTC: %BOOT-3-BOOTTIME_INCOMPATIBLE_SW_DETECTED: Switch 1 R0/0: issu_stack:
```

```
Incompatible software detected
```

```
.  
** snip **
```

```
Sep 13 07:47:37.443 UTC: %AUTO_UPGRADE-5-AUTO_UPGRADE_INITIATED: Switch 1 R0/0: auto_upgrade_trigger:
```

```
Auto upgrade initiated for switch 2.
```

```
Sep 13 07:47:37.496 UTC: %AUTO_UPGRADE-5-AUTO_UPGRADE_SEARCH: Switch 1 R0/0: auto_upgrade_trigger: Search  
Sep 13 07:47:37.519 UTC: %AUTO_UPGRADE-5-AUTO_UPGRADE_FOUND: Switch 1 R0/0: auto_upgrade_trigger: Found  
Sep 13 07:47:37.538 UTC: %AUTO_UPGRADE-5-AUTO_UPGRADE_START: Switch 1 R0/0: auto_upgrade_trigger: Upgrade  
Sep 13 07:47:46.769 UTC: %AUTO_UPGRADE_MODULAR-5-SMU_AUTO_UPGRADE_INITIATING: Switch 1 R0/0: auto_upgrade  
Sep 13 07:47:47.272 UTC: %AUTO_UPGRADE-5-AUTO_UPGRADE_FINISH: Switch 1 R0/0: auto_upgrade_trigger:
```

```
Finished installing software on switch 2.
```

```
** snip **
```

```
Sep 13 07:57:18.981 UTC: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event)  
Sep 13 07:57:18.981 UTC: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event)  
Sep 13 07:57:49.863 UTC: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEEDED:
```

```
Bulk Sync succeeded
```

Sep 13 07:57:50.865 UTC:

%RF-5-RF_TERMINAL_STATE: Terminal state reached for (SSO)

Verify Post-Replacement

Check the state of the switches once **SSO is completed**. At this time, you can reconnect the stack-power cables, if applicable.

<#root>

C9300#

show switch

Switch/Stack Mac Address : 70d3.79be.6c80 - Local Mac Address

Mac persistency wait time: Indefinite

H/W Current

Switch#	Role	Mac Address	Priority	Version	State
---------	------	-------------	----------	---------	-------

*1	Active	70d3.79be.6c80	1	V01	Ready
2	Standby	70d3.7984.8580	2	V01	Ready

!

C9300#

show module

Switch	Ports	Model	Serial No.	MAC address	Hw Ver.	Sw Ver.
1	41	C9300-24U	FCW2125L0BH	70d3.79be.6c80	V01	17.03.01
2	41	C9300-24U	FCW2125L03W	70d3.7984.8580	V01	17.03.01

<#root>

C9300#

show redundancy

Redundant System Information :

Available system uptime = 58 minutes

Switchovers system experienced = 0

Standby failures = 0

Last switchover reason = none

Hardware Mode = Duplex

Configured Redundancy Mode = sso

Operating Redundancy Mode = sso

Maintenance Mode = Disabled

Communications = Up

Current Processor Information :

Active Location = slot 1

Current Software state = ACTIVE

Uptime in current state = 58 minutes

```
Image Version = Cisco IOS Software [Amsterdam], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.3
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Fri 07-Aug-20 21:32 by mcpre
BOOT = flash:packages.conf;flash:;
CONFIG_FILE =
Configuration register = 0x102
```

```
Peer Processor Information :
-----
```


```
Standby Location = slot 2
```

```
Current Software state = STANDBY HOT
```

```
Uptime in current state = 4 minutes
Image Version = Cisco IOS Software [Amsterdam], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.3
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Fri 07-Aug-20 21:32 by mcpre
BOOT = flash:packages.conf;flash:;
CONFIG_FILE =
Configuration register = 0x102
```

Replace a Redundant Supervisor of C9400 Standalone Chassis

In this example, you replace the **Active** supervisor of a C9404 chassis. (The switch in this example uses in slot 3 in "Install" boot mode.)



Verify Pre-Replacement

Check that the boot variable on switch is set pointing to correct package file (if boot mode is Install) or bin

file (bundle boot mode) and auto-boot is enabled.

Note: If the switch is in **"Install"** boot mode, verify that software auto-upgrade is enabled. If not, then enable that by configuring **"software auto-upgrade enable"** from global configuration mode.

```
<#root>
```

```
C9400#
```

```
show run all | in software auto
```

```
no software auto-upgrade source url
```

```
software auto-upgrade enable
```

Note: If your active supervisor is running in "Bundle" boot mode, please keep a copy of running software file (.bin file that you are running on active) in an USB stick or local TFTP server which can be accessed from new supervisor, through it's out-of-band (OOB) management port.

If active supervisor needs to be replaced (like in this example of ours), perform a failover to standby supervisor and wait for it to take over active's role. Skip this step if you are going to replace standby supervisor.

```
<#root>
```

```
C9400#
```

```
redundancy force-switchover
```

```
System configuration has been modified. Save? [yes/no]: yes
```

```
Building configuration...
```

```
Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi
```

Replace

Remove faulty supervisor from chassis and insert the new one, with a console cable plugged into it.

Note: Initially both supervisors might not be on same software version and you need to match them. For example, active supervisor could be running 16.9.5 and new/standby 16.9.4.

If your active supervisor is running in "Bundle" boot mode, then break into the ROMMON of new supervisor, while it is booting up. With help of an USB stick or OOB TFTP access, manually boot the supervisor with same software version as your active supervisor.

```
<#root>
```

```
Preparing to autoboot. [
```


Press Ctrl-C to interrupt

] 3 (interrupted)

rommon 1 >

rommon 2 >

boot usbflash0:cat9k_iosxe.16.09.05.SPA.bin

If your active supervisor is running in "Install" boot mode, automatic software upgrade must be kicked in by current active supervisor, as soon it detects an incompatible software version or boot mode on new/standby supervisor. Typically, no manual intervention is needed at this stage.

<#root>

*Jun 16 19:50:15.122: %IOSXE_OIR-6-INSSPA: SPA inserted in subslot 3/0

*Jun 16 19:50:42.374: %SPA_OIR-6-ONLINECARD: SPA (C9400-SUP-1) online in subslot 3/0

C9400#

*Jun 16 19:50:43.376: 3 0 0:Ignore this incremental sync, session not ready

C9400#

*Jun 16 19:52:10.003: %IOSXE_OIR-6-INSCARD: Card (fp) inserted in slot F1

C9400#

*Jun 16 19:51:16.469: %IOSXE-3-PLATFORM: R1/0: kernel: dplr_intrpt: Entered dplr_intrpt_module_init dplr

*Jun 16 19:51:16.472: %IOSXE-3-PLATFORM: R1/0: kernel: chr_mmap: Allocating DMA Reserve Pool ...

*Jun 16 19:52:27.950: %IOSXE_OIR-6-ONLINECARD: Card (rp) online in slot R1

*Jun 16 19:52:28.727: %AUTO_UPGRADE-5-AUTO_UPGRADE_INITIATED: R0/0: auto_upgrade_client:

Auto upgrade initiated for RP 1.

*Jun 16 19:52:28.748: %AUTO_UPGRADE-5-AUTO_UPGRADE_SEARCH: R0/0: auto_upgrade_client: Searching stack for

*Jun 16 19:52:28.760: %AUTO_UPGRADE-5-AUTO_UPGRADE_FOUND: R0/0: auto_upgrade_client:

Found donor RP 0 to auto upgrade RP 1.

*Jun 16 19:52:28.773: %AUTO_UPGRADE-5-AUTO_UPGRADE_START: R0/0: auto_upgrade_client:

Upgrading RP 1 with software from RP 0.

*Jun 16 19:52:39.655: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

*Jun 16 19:52:39.655: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

*Jun 16 19:52:39.642: %AUTO_UPGRADE_MODULAR-5-SMU_AUTO_UPGRADE_INITIATING: R0/0: auto_upgrade_client: In

*Jun 16 19:52:40.832: %AUTO_UPGRADE-5-AUTO_UPGRADE_FINISH: R0/0: auto_upgrade_client: Finished installin

*Jun 16 19:52:40.847: %AUTO_UPGRADE-5-AUTO_UPGRADE_RELOAD: R0/0: auto_upgrade_client: Reloading RP 1 to

*Jun 16 19:52:41.622: %IOSXE_OIR-6-OFFLINECARD: Card (rp) offline in slot R1

** snip **

*Jun 16 19:56:10.356: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

*Jun 16 19:56:10.356: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

** snip **

*Jun 16 19:57:33.582: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEED: Bulk Sync succeeded

*Jun 16 19:57:34.623: %RF-5-RF_TERMINAL_STATE:

Terminal state reached for (SSO)

Verify Post-Replacement

Check the state of the supervisors once SSO is completed

<#root>

C9400#

show module

Chassis Type: C9404R

Mod	Ports	Card Type	Model	Serial No.
2	10	Supervisor 1 Module	C9400-SUP-1	JAE22100647
3	10	Supervisor 1 Module	C9400-SUP-1	

Mod	MAC addresses	Hw	Fw	Sw	Status
2	A8B4.56BF.316C to A8B4.56BF.3175	1.0	16.12.1r	16.09.05	ok
3					

Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
2	Active	sso	sso
3	Standby	sso	sso

Chassis MAC address range: 44 addresses from a8b4.56bf.3140 to a8b4.56bf.316b

<#root>

C9400#

show redundancy

Redundant System Information :

```

-----
Available system uptime = 10 minutes
Switchovers system experienced = 0
Standby failures = 0
Last switchover reason = none
Hardware Mode = Duplex
Configured Redundancy Mode =

```

sso

Operating Redundancy Mode =

SSO

Maintenance Mode = Disabled

Communications = Up

Current Processor Information :

Active Location = slot 2

Current Software state = ACTIVE

Uptime in current state = 10 minutes

Image Version = Cisco IOS Software [Fuji], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.9.5, RE

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2019 by Cisco Systems, Inc.

Compiled Thu 22-Aug-19 18:14 by mcpre

BOOT = bootflash:packages.conf;

CONFIG_FILE =

Configuration register = 0x102

Peer Processor Information :

Standby Location = slot 3

Current Software state =

STANDBY HOT

Uptime in current state =

0 minutes

Image Version = Cisco IOS Software [Fuji], Catalyst L3 Switch Software (CAT9K_IOSXE),

Version 16.9.5

, RELEASE SOFTWARE (fc2)

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2019 by Cisco Systems, Inc.

Compiled Thu 22-Aug-19 18:14 by mcpre


BOOT = bootflash:packages.conf;

CONFIG_FILE =

Configuration register = 0x102

Replace a Supervisor of C9400 Dual-Sup StackWise-Virtual

This example is for a C9400 stackwise-Virtual setup (one supervisor in each chassis), where chassis-1's supervisor (Active switch) has gone bad and needs to be replaced. The SVL is running in "Install" boot mode.



Verify Pre-Replacement

Check the current StackWise-Virtual related configurations and the state of supervisors. Ensure that boot variable on switch is set correctly pointing to correct package file (if boot mode is Install) or bin file (bundle boot mode) and auto-boot is enabled.

```
<#root>
```

```
9400-3#
```

```
show stackwise-virtual
```

```
Stackwise Virtual Configuration:
```

```
-----
```

```
Stackwise Virtual : Enabled
```

```
Domain Number : 100
```

```
Switch Stackwise Virtual Link Ports
```

```
-----
```

```
1          1          TenGigabitEthernet1/5/0/1 <<< switch 1 needs to be replaced here
2          1          TenGigabitEthernet2/5/0/1
```

```
<#root>
```

```
9400-3#
```

```
show bootvar
```

```
BOOT variable =
```

```
flash:packages.conf
```

```
;
```

```
Configuration Register is 0x102
```

```
MANUAL_BOOT variable = no
```

```
BAUD variable = 9600
```

```
ENABLE_BREAK variable = yes
```

```
BOOTMODE variable does not exist
```

```
IPXE_TIMEOUT variable does not exist
```

CONFIG_FILE variable =

Note: If the switch is in "Install" boot mode, verify that software auto-upgrade is enabled. If not, then enable that by configuring "software auto-upgrade enable" from global configuration mode.

```
<#root>
```

```
9400-3#
```

```
show run all | in software auto
```

```
no software auto-upgrade source url
```

```
software auto-upgrade enable
```

Note: If your **active** supervisor is running in "**Bundle**" boot mode, please keep a copy of running software file (.bin file that you are running on active) in an USB stick or local TFTP server which can be accessed from new supervisor, through it's out-of-band (OOB) management port.

If active supervisor needs to be replaced (like in our example), perform a failover to standby supervisor and wait for standby to take over active's role. Skip this step if you are replacing standby supervisor.

```
<#root>
```

```
9400-1#
```

```
redundancy force-switchover
```

```
System configuration has been modified. Save? [yes/no]: yes
```

```
Building configuration...
```

```
Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi
```

Replace

Power off the chassis where supervisor needs to be replaced (In our example, it is chassis-1).

Remove the line cards from the backplane from respective chassis (where supervisor needs to be replaced). There is no need to take the line cards completely out of the chassis, as long as they are not attached to backplane, it is fine. That way, when new supervisor is inserted and being pre-staged, the remote switches of the connections (Multi-chassis etherchannel) do not put their local ports into err-disabled state (LACP and so on).

```
<#root>
```

```
9400-3#
```

```
show module
```



```
domain 100
Switch(config-stackwise-virtual)#
exit
```

Configure SVL and DAD ports. Use the **same ports**, that were used on the faulty supervisor.

```
<#root>
9400-1(config)#
interface tenGigabitEthernet 5/0/1

9400-1(config-if)#
stackwise-virtual link 1
```

WARNING: All the extraneous configurations will be removed for TenGigabitEthernet5/0/1 on reboot
INFO: Upon reboot, the config will be part of running config but not part of start up config.

Check that SVL configuration is applied correctly to the new switch.

```
<#root>
Switch#show stackwise-virtual

Stackwise Virtual Configuration:
-----
Stackwise Virtual : Disabled
Switch   Stackwise Virtual Link   Ports
-----  -----
Stackwise Virtual Configuration After Reboot:
-----
Stackwise Virtual : Enabled
Domain Number :    100
Switch   Stackwise Virtual Link   Ports
-----  -----
1        1                          TenGigabitEthernet5/0/1
```

Check the SVL settings in ROMMON from IOSd CLI (available in versions 16.12.x or higher)

```
<#root>
9400-1#
show romvar

ROMMON variables:
MAC_ADDR="70:0F:6A:DE:54:34"
SWITCH_NUMBER="1"
```

```
MODEL_NUM="C9400-SUP-1"
SYSTEM_SERIAL_NUM=""
MOTHERBOARD_SERIAL_NUM="JAE221703NQ"
TEMPLATE="access"
BAUD="9600"
LICENSE_BOOT_LEVEL="network-advantage+dna-advantage,all:MACALLAN-CHASSIS;"
MCP_STARTUP_TRACEFLAGS="00000000:00000000"
CALL_HOME_DEBUG="00000000000000"
D_STACK_DAD=""
CONFIG_FILE=""
BOOTLDR=""
SWITCH_IGNORE_STARTUP_CFG="0"

MANUAL_BOOT="no"
```

```
AUTOREBOOT_RESTORE="0"
ENABLE_BREAK="yes"
RET_2_RTS=""
AUTO_SWITCH_CONSOLE_DISABLE="0"
BOOT="flash:cat9k_iosxe.16.12.03a.SPA.bin;"
D_STACK_DISTR_STACK_LINK2=""
ABNORMAL_RESET_COUNT="1"
ROMMON_AUTOBOOT_ATTEMPT="3"
BSI="0"
RET_2_RCALTS=""
RANDOM_NUM="421133355"

D_STACK_DISTR_STACK_LINK1="Te5/0/1,"
```

```
D_STACK_MODE="aggregation"
```

```
D_STACK_DOMAIN_NUM="100"
```

Save the configurations and power off chassis where new supervisor is placed into.

Connect StackWise-Virtual links between two chassis and prefer to leave the Dual-active detection link disconnected (if applicable).

Power on the chassis and monitor the boot process through console.

- **If your SVL is running in "Bundle" boot mode**, ensure that new supervisor is coming up with same software version as Active. If not, break into ROMMON again and boot it manually using the correct software version.
- **If the SVL is running in "Install" boot mode**, then "software auto-upgrade" must take care of pushing right software version and boot mode into new supervisor, without any manual intervention.

```
<#root>
```

```
Active supervisor's log
```

```
*Sep 12 07:20:25.457: %ILPOWER-6-SET_ILPOWER: Set power allocated to POE to 4420 for slot 0
*Sep 12 07:20:30.621:
```



```
%BOOT-3-BOOTTIME_INCOMPATIBLE_SW_DETECTED: Chassis 2 R0/0: issu_stack: Incompatible software detected. I

*Sep 12 07:20:40.779: %AUTO_UPGRADE-5-AUTO_UPGRADE_START_CHECK: Chassis 2 R0/0: auto_upgrade_client: Auto

*Sep 12 07:21:00.978: %AUTO_UPGRADE-5-AUTO_UPGRADE_INITIATED: Chassis 2 R0/0: auto_upgrade_client: Auto

*Sep 12 07:21:01.031: %AUTO_UPGRADE-5-AUTO_UPGRADE_SEARCH: Chassis 2 R0/0: auto_upgrade_client: Searchin
*Sep 12 07:21:01.053: %AUTO_UPGRADE-5-AUTO_UPGRADE_FOUND: Chassis 2 R0/0: auto_upgrade_client: Found dor
*Sep 12 07:21:01.074: %AUTO_UPGRADE-5-AUTO_UPGRADE_START: Chassis 2 R0/0: auto_upgrade_client: Upgrading
```

<#root>

Logs from new supervisor's console

```
Waiting for remote chassis to join
#####
Chassis number is 1
All chassis in the stack have been discovered. Accelerating discovery

Chassis 1 reloading, reason - System requested reload <<< reload is instructed by current active as part
Sep 12 07:25:23.306: %PMAN-5-EXITACTION: R0/0: pvp: Process manager is exiting: process exit with reload
```

All the running configurations must be automatically synced from Active supervisor to the new one. Wait for these logs from active supervisor.

```
*Sep 12 07:33:39.803: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEED: Bulk Sync succeeded
*Sep 12 07:33:40.837: %RF-5-RF_TERMINAL_STATE: Terminal state reached for (SSO)
```

- **Once SSO is completed**, proceed with connecting the Dual-active detection (DAD) link and other network uplink ports on new supervisor, as applicable.
- **Push the line cards back inside**, to get them attached to backplane again
- **Verify that all line cards have booted fine**, passed online diagnostic tests and brought up their interfaces, including port-channel binding and so on.

Verify Post-Replacement

Check the StackWise Virtual related configurations and the states of the switch using these commands.

<#root>

9400-3#

sh redundancy

Redundant System Information :

Available system uptime = 1 hour, 31 minutes
Switchovers system experienced = 0
Standby failures = 0
Last switchover reason = none

Hardware Mode = Duplex
Configured Redundancy Mode = sso

Operating Redundancy Mode = sso

Maintenance Mode = Disabled
Communications = Up

Current Processor Information :

Active Location = Switch 2
Current Software state = ACTIVE
Uptime in current state = 31 minutes
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Tue 28-Apr-20 09:37 by mcpre
BOOT = flash:packages.conf;
CONFIG_FILE =
Configuration register = 0x102

Peer Processor Information :

Standby Location = Switch 1

Current Software state = STANDBY HOT

Uptime in current state = 4 minutes
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Tue 28-Apr-20 09:37 by mcpre
BOOT = flash:packages.conf;
CONFIG_FILE =
Configuration register = 0x102
!

<#root>

9400-3#

sh stackwise-virtual

Stackwise Virtual Configuration:

Stackwise Virtual : Enabled

Domain Number : 100

Switch Stackwise Virtual Link Ports

```
-----  
1          1          TenGigabitEthernet1/5/0/1  
2          1          TenGigabitEthernet2/5/0/1
```

<#root>

9400-3#

sh module

Chassis Type: C9410R

Switch Number 1

Mod	Ports	Card Type	Model	Serial No.
1	48	48-Port UPOE w/ 24p mGig 24p RJ-45	C9400-LC-48UX	JAE22360153
2	48	48-Port UPOE w/ 24p mGig 24p RJ-45	C9400-LC-48UX	JAE215103V7
5	10	Supervisor 1 Module	C9400-SUP-1	JAE221703NQ

Mod	MAC addresses	Hw	Fw	Sw	Status
1	00B7.71FA.D878 to 00B7.71FA.D8A7	1.0	16.12.2r	16.12.03a	

ok

2	4C77.6DBF.4A94 to 4C77.6DBF.4AC3	1.0	16.12.2r	16.12.03a	
---	----------------------------------	-----	----------	-----------	--

ok

5	AC3A.675B.E9AC to AC3A.675B.E9B5	1.0	16.12.2r	16.12.03a	
---	----------------------------------	-----	----------	-----------	--

ok

Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
-----	-----------------	---------------------------	----------------------------

```
-----  
5
```


Standby	SSO
---------	-----

SSO

snip

Replace a Member of the C9500 StackWise-Virtual

In this example, you are considering a C9500 Stackwise Virtual setup with Switch-1 (the Active switch) as a faulty switch that needs to be replaced. The SVL is running in INSTALL boot mode.



Verify Pre-Replacement

Check the current StackWise-Virtual related configurations and the state of the switches. Ensure that boot variable is set correctly, points to packages.conf, and config-register is set to 0x2102.

```
<#root>
```

```
C9500-1#
```

```
show stackwise-virtual
```

```
Stackwise Virtual Configuration:
```

```
-----
Stackwise Virtual : Enabled
Domain Number : 100
Switch Stackwise Virtual Link Ports
-----
1          1          TwentyFiveGigE1/0/1
                TwentyFiveGigE1/0/2
2          1          TwentyFiveGigE2/0/1
                TwentyFiveGigE2/0/2
```

```
<#root>
```

```
C9500-1#
```

```
show stackwise-virtual dual-active-detection
```

```
Dual-Active-Detection Configuration:
```

```
-----
Switch    Dad port
-----
1         TwentyFiveGigE1/0/3
2         TwentyFiveGigE2/0/3    <<<<<<<<<< Ports configured for Dual-Active Detection (DAD)
```

Note :

Configs of these DAD ports do not show up in running-config

```
!
interface TwentyFiveGigE 1/0/3
end
!
interface TwentyFiveGigE 2/0/3
end
```

C9500-1#show switch

Switch/Stack Mac Address : f4db.e619.0480 - Local Mac Address

Mac persistency wait time: Indefinite

H/W Current

Switch#	Role	Mac Address	Priority	Version	State
---------	------	-------------	----------	---------	-------

*1	Active	f4db.e619.0480	15	V02	Ready
2	Standby	f4db.e618.fa80	1	V02	Ready

C9500-1#

show redundancy

Redundant System Information :

Available system uptime = 4 minutes

Switchovers system experienced = 0

Standby failures = 0

Last switchover reason = none

Hardware Mode = Duplex

Configured Redundancy Mode = sso

Operating Redundancy Mode = sso

Maintenance Mode = Disabled

Communications = Up

Current Processor Information :

Active Location = slot 1

Current Software state = ACTIVE

Uptime in current state = 4 minutes

Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2019 by Cisco Systems, Inc.

Compiled Tue 19-Nov-19 10:04 by mcpre

BOOT = flash:packages.conf

;

CONFIG_FILE =

Configuration register = 0x102

Peer Processor Information :

Standby Location = slot 2

Current Software state = STANDBY HOT

Uptime in current state = 1 minute

Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2019 by Cisco Systems, Inc.

Compiled Tue 19-Nov-19 10:04 by mcpre

BOOT = flash:packages.conf

;

CONFIG_FILE =

Configuration register = 0x102

Note: If the SVL is running in INSTALL boot mode, verify that software auto-upgrade is enabled. If not, then enable that by configuring "**software auto-upgrade enable**" from global configuration mode. (Skip this step, if SVL is running in Bundle boot mode).

<#root>

C9500-1#

show run all | in software auto

no software auto-upgrade source url

software auto-upgrade enable

If active switch needs to be replaced, perform a failover to Standby switch and wait for standby to take over active's role. (Skip this step if you are replacing Standby unit).

<#root>

C9500-1#

redundancy force-switchover

System configuration has been modified. Save? [yes/no]: yes

Building configuration...

Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi

Replace

Power off the Switch that needs to be replaced. Disconnect all the cables from that switch.

<#root>

C9500-1#

show switch

Switch/Stack Mac Address : f4db.e619.0480 - Foreign Mac Address

Mac persistency wait time: Indefinite

H/W Current

Switch#	Role	Mac Address	Priority	Version	State
---------	------	-------------	----------	---------	-------

1	Member	0000.0000.0000	0	V02	Removed << switch 1 is powered down
*2	Active	f4db.e618.fa80	1	V02	Ready

Power on the new switch. It must boot up in Stand-alone mode (Non-SVL). (Skip this step if the current Active SVL is running in INSTALL boot mode)

Check the software version on new unit. If it does not match with existing member of StackWise-Virtual unit, then pre-stage that to match the software version and license, with existing member of SVL. (You can load the correct software version through TFTP/FTP/SFTP or using an USB stick, and after matching the software version and license on new unit, proceed to next step.

```
<#root>
```

```
Cisco IOS XE Software,
```

```
Version 16.12.02
```

```
Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12.02, RELEASE SOFTWARE  
Technical Support: http://www.cisco.com/techsupport  
Copyright (c) 1986-2019 by Cisco Systems, Inc.  
Compiled Tue 19-Nov-19 10:04 by mcpre
```

Note: If SVL is running in INSTALL boot mode and software-autoupgrade is enabled, then typically the existing active member of SVL must be able to match the code and boot mode of new unit automatically.

Configure StackWise Virtual on the new switch. You must use same SVL domain number to match existing member.

```
<#root>
```

```
Switch#
```

```
conf t
```

```
Enter configuration commands, one per line. End with CNTL/Z.
```

```
Switch(config)#
```

```
stackwise-virtual
```

```
Please reboot the switch for Stackwise Virtual configuration to take effect
```

```
Switch(config-stackwise-virtual)#
```

```
domain 100
```

```
Switch(config-stackwise-virtual)#
```

```
exit
```

Configure SVL and DAD ports. Use **same ports**, that were used on the faulty switch.

```
<#root>
```

```
Switch(config)#
```

```
int range twel/0/1-2
```

```
Switch(config-if-range)#
```

```
stackwise-virtual link 1
```

```
WARNING: All the extraneous configurations will be removed for TwentyFiveGigE1/0/1 on reboot
```

```
WARNING: All the extraneous configurations will be removed for TwentyFiveGigE1/0/2 on reboot
```

```
Switch(config-if-range)#exit
```

```
Switch(config)#
```

```
int twe1/0/3
```

```
Switch(config-if)#
```

```
stackwise-virtual dual-active-detectio
```

```
n
```

```
WARNING: All the extraneous configurations will be removed for TwentyFiveGigE1/0/3 on reboot.
```

Check that SVL configuration is applied correctly to the new switch.

```
<#root>
```

```
Switch#
```

```
show stackwise-virtual
```

```
Stackwise Virtual Configuration:
```

```
-----  
Stackwise Virtual : Disabled  
Switch   Stackwise Virtual Link   Ports  
-----
```

```
Stackwise Virtual Configuration After Reboot:
```

```
-----  
Stackwise Virtual : Enabled  
Domain Number : 100  
Switch   Stackwise Virtual Link   Ports  
-----  
1         1                       TwentyFiveGigE1/0/1  
                                TwentyFiveGigE1/0/2
```

```
Switch#
```

```
show stackwise-virtual dual-active-detection
```

```
Dual-Active-Detection Configuration:
```

```
-----  
Switch   Dad port  
-----
```

```
Distributed Stack DAD Configuration After Reboot:
```

```
-----  
Switch   Dad port  
-----  
1         TwentyFiveGigE1/0/3
```


Save the configurations and power off the new switch.

Connect StackWise-Virtual links between existing SVL member and the new unit. Prefer to leave the Dual-active detection link disconnected.

Power on the new unit. If there is a conflict in switch number, then new unit must be re-numbered automatically.

```
Chassis is reloading, reason: Configured Switch num conflicts with peer, Changing local switch number to  
Sep 10 22:41:50.738: %PMAN-3-PROCHOLDDOWN: R0/0: The process nif_mgr has been helddown (rc 69)
```

Note: If new unit is running an incompatible software or boot mode and existing SVL member is running INSTALL boot mode, then software auto-upgrade kicks in, to bring new unit on INSTALL boot mode, without manual intervention.

```
*Sep 10 22:47:05.996: %AUTO_UPGRADE-5-AUTO_UPGRADE_START_CHECK: Chassis 2 R0/0: auto_upgrade_client: Aut
```

All the running configurations are **automatically synced** from Active switch to the New switch. No additional configurations are needed. Wait for these logs from active switch.

```
*Sep 11 01:02:28.974: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEED: Bulk Sync succeeded
```

```
C9500-1#
```

```
*Sep 11 01:02:30.009: %RF-5-RF_TERMINAL_STATE: Terminal state reached for (SSO)
```

Proceed with connecting the Dual-active detection (DAD) link and other network ports. (Once SSO is completed)

Verify Post-Replacement

Check the StackWise Virtual related configurations and the states of the switch using these commands.

```
<#root>
```

```
C9500-1#
```

```
show stackwise-virtual
```

```
Stackwise Virtual : Enabled
```

```
Domain Number : 100
```

```
Switch Stackwise Virtual Link    Ports
```

```
-----  
1          1          TwentyFiveGigE1/0/1  
                TwentyFiveGigE1/0/2  
2          1          TwentyFiveGigE2/0/1  
                TwentyFiveGigE2/0/2
```

```
C9500-1#
```

show redundancy

Redundant System Information :

Available system uptime = 14 minutes
Switchovers system experienced = 0
Standby failures = 0
Last switchover reason = none

Hardware Mode = Duplex
Configured Redundancy Mode = sso
Operating Redundancy Mode = sso
Maintenance Mode = Disabled
Communications = Up

Current Processor Information :

Active Location = slot 2
Current Software state = ACTIVE
Uptime in current state = 14 minutes
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2019 by Cisco Systems, Inc.
Compiled Tue 19-Nov-19 10:04 by mcpre
BOOT = flash:packages.conf;
CONFIG_FILE =
Configuration register = 0x102

Peer Processor Information :

Standby Location =

slot 1

Current Software state =

STANDBY HOT

Uptime in current state = 1 minute
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2019 by Cisco Systems, Inc.
Compiled Tue 19-Nov-19 10:04 by mcpre
BOOT = flash:packages.conf;
CONFIG_FILE =
Configuration register = 0x102

Replace a Redundant Supervisor of C9600 Dual-Sup Standalone Chassis

In this example, you are considering to replace the active supervisor at slot 3 of a C9606 chassis. (The switch is running in "Install" boot mode.)



Verify Pre-Replacement

Check that boot variable on switch is set correctly pointing to correct package file (if boot mode is Install) or bin file (bundle boot mode) and auto-boot is enabled.

Note: If the switch is running in "Install" boot mode, verify that **software auto-upgrade** is enabled. If not, then enable that by configuring "**software auto-upgrade enable**" from global configuration mode.

```
<#root>
```

```
C9600R-1#
```

```
show run all | in software auto
```

```
no software auto-upgrade source url
```

```
software auto-upgrade enable
```

Note: If your active supervisor is running in "Bundle" boot mode, please keep a copy of running software file (.bin file that you are running on active) in an USB stick or local TFTP server which can be accessed from new supervisor, through it's out-of-band (OOB) management port.

Replace

If active supervisor needs to be replaced (like in this example of ours), perform a failover to standby supervisor and wait for it to take over active's role. (Skip this step if you are going to replace standby supervisor).

```
<#root>
```

```
C9600R-1#
```

```
redundancy force-switchover
```

```
System configuration has been modified. Save? [yes/no]: yes
```

```
Building configuration...
```

```
Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi
```

Remove faulty supervisor from chassis and insert the new one, with a console cable plugged into it.

Note: Initially both supervisors might not be on same software version and you need to match them. For example, active supervisor could be running 16.12.4 and new/standby 16.12.2.

If your active supervisor is running in "Bundle" boot mode, then break into the ROMMON of new supervisor, while it is booting up. With help of an USB stick or OOB TFTP access, manually boot the supervisor with same software version as your active supervisor. Later on, after new standby joins SSO, copy the running software to it's local bootflash.

```
<#root>
```

```
Preparing to autoboot. [Press Ctrl-C to interrupt] 3 (interrupted)
```

```
rommon 1 >
```

```
rommon 2 >
```

```
boot disk0:cat9k_iosxe.16.12.04.SPA.bin
```

If your active supervisor is running in "Install" boot mode, automatic software upgrade must be kicked in by current active supervisor, as soon it detects an incompatible software version or boot mode on new/standby supervisor. Typically, no manual intervention is needed at this stage.

```
<#root>
```

```
*Sep 12 21:32:04.886: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F
```

```
*Sep 12 21:32:04.886: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F
```

```
*Sep 12 21:32:07.773: %REDUNDANCY-2-IPC:
```

```
IOS versions do not match.
```

```
*Sep 12 21:32:07.823: %SMART_LIC-5-EVAL_START: Entering evaluation period
```

```
*Sep 12 21:32:28.980: %AUTO_UPGRADE_MODULAR-5-SMU_AUTO_UPGRADE_INITIATING: R1/0:
```

```
auto_upgrade_client: Initiating SMU autoupgrade for RP 0
```

```
*Sep 12 21:32:30.867: %AUTO_UPGRADE-5-AUTO_UPGRADE_FINISH: R1/0: auto_upgrade_client:
```

```
Finished installing software on RP 0.
```

*Sep 12 21:32:30.908: %AUTO_UPGRADE-5-AUTO_UPGRADE_RELOAD: R1/0: auto_upgrade_client:

Reloading RP 0 to complete the auto upgrade.

** snip **

*Jun 16 19:56:10.356: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

*Jun 16 19:56:10.356: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

** snip **

*Sep 12 21:36:37.786: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

*Sep 12 21:36:37.786: %REDUNDANCY-5-PEER_MONITOR_EVENT: Active detected a standby insertion (raw-event=F

snip

*Sep 12 21:39:24.085: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEED: Bulk Sync succeeded

*Sep 12 21:39:25.124: %RF-5-RF_TERMINAL_STATE:

Terminal state reached for (SSO)

Verify Post-Replacement

Check the state of the supervisors once SSO is completed

<#root>

C9606R-1#

show mod

Chassis Type: C9606R

Mod	Ports	Card Type	Model	Serial No.
1	24	24-Port 40GE/12-Port 100GE	C9600-LC-24C	CAT2313L2WQ
2	48	48-Port 10GE / 25GE	C9600-LC-48YL	CAT2314L36W
3	0	Supervisor 1 Module	C9600-SUP-1	CAT2310L5C1
4	0	Supervisor 1 Module	C9600-SUP-1	CAT2311L4DQ
5	48	48-Port 10GE / 25GE	C9600-LC-48YL	CAT2310L57N

Mod	MAC addresses	Hw	Fw	Sw	Status
1	DC8C.37C9.AC00 to DC8C.37C9.AC7F	1.0	17.1.1[FC2]	16.12.04	ok
2	DC8C.37C9.FD00 to DC8C.37C9.FD7F	1.0	17.1.1[FC2]	16.12.04	ok
3	DC8C.3772.C780 to DC8C.3772.C7FF	1.0	17.1.1[FC2]	16.12.04	ok
4	DC8C.3772.E580 to DC8C.3772.E5FF	1.0	17.1.1[FC2]	16.12.04	ok
5	DC8C.3773.0280 to DC8C.3773.02FF	1.0	17.1.1[FC2]	16.12.04	ok

Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
3	Standby	sso	sso
4	Active	sso	sso

Chassis MAC address range: 64 addresses from 6cb2.ae4a.9680 to 6cb2.ae4a.96bf

<#root>

C9606R-1#

show redundancy

Redundant System Information :

Available system uptime = 1 day, 11 hours, 32 minutes
Switchovers system experienced = 1
Standby failures = 1
Last switchover reason = user forced
Hardware Mode = Duplex
Configured Redundancy Mode = sso
Operating Redundancy Mode = sso
Maintenance Mode = Disabled
Communications = Up

Current Processor Information :

Active Location = slot 4
Current Software state = ACTIVE
Uptime in current state = 35 minutes
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Thu 09-Jul-20 21:49 by mcpre
BOOT =
CONFIG_FILE =

Peer Processor Information :


Standby Location = slot 3
Current Software state =

STANDBY HOT

Uptime in current state = 3 minutes
Image Version = Cisco IOS Software [Gibraltar], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 16.12
Technical Support: <http://www.cisco.com/techsupport>
Copyright (c) 1986-2020 by Cisco Systems, Inc.
Compiled Thu 09-Jul-20 21:49 by mcpre
BOOT =
CONFIG_FILE =

Replace a Supervisor of C9600 Dual-Sup StackWise-Virtual

In this example, you are considering a C9600 stackwise-Virtual setup (one supervisor in each chassis), where chassis-1's supervisor (Active switch) has gone bad and needs to be replaced. The SVL is running in "Install" boot mode.



Verify Pre-Replacement

Check the current StackWise-Virtual related configurations and the state of supervisors. Ensure that boot variable on switch is set correctly pointing to correct package file (if boot mode is Install) or bin file (bundle boot mode) and auto-boot is enabled.

```
<#root>
```

```
C9600_SVL#
```

```
sh stackwise-virtual
```

```
Stackwise Virtual Configuration:
```

```
-----
Stackwise Virtual : Enabled
Domain Number : 100
```

```
Switch Stackwise Virtual Link Ports
```

```
-----
2          1          FortyGigabitEthernet2/1/0/1
                FortyGigabitEthernet2/1/0/2
1          1          FortyGigabitEthernet1/1/0/1  << supervisor of SW1 needs to be replaced
                FortyGigabitEthernet1/1/0/2
```

```
<#root>
```

```
C9600_SVL#
```

```
show bootvar
```

```
BOOT variable =
```

```
bootflash:packages.conf
```

```
;
```

```
MANUAL_BOOT variable = no
```

```
BAUD variable = 9600
```

```
ENABLE_BREAK variable = yes
BOOTMODE variable does not exist
IPXE_TIMEOUT variable does not exist
CONFIG_FILE variable =
```

Note: If the SVL is in "Install" boot mode, verify that software auto-upgrade is enabled. If not, then enable that by configuring "**software auto-upgrade enable**" from global configuration mode.

```
<#root>
```

```
C9600_SVL#
```

```
show run all | in software auto
```

```
no software auto-upgrade source url
```

```
software auto-upgrade enable
```

If your active supervisor is running in "Bundle" boot mode, please keep a copy of running software file (.bin file that you are running on active) in an USB stick or local TFTP server which can be accessed from new supervisor, through it's out-of-band (OOB) management port.

- **If active supervisor needs to be replaced** (like in our example), perform a failover to standby supervisor and wait for standby to take over active's role. Skip this step if you are replacing standby supervisor.

```
<#root>
```

```
C9600_SVL#
```

```
redundancy force-switchover
```

```
System configuration has been modified. Save? [yes/no]: yes
```

```
Building configuration...
```

```
Compressed configuration from 11673 bytes to 4403 bytes[OK]Proceed with switchover to standby RP? [confi
```

Replace

Power off the chassis where supervisor needs to be replaced. In our example, it is chassis-1.

Remove the line cards from the backplane from respective chassis (where supervisor needs to be replaced), except one where StackWise-Virtual links (SVL) are attached to. For those line cards, where SVLs are configured, remove all connections except the SVLs itself. That way, when new supervisor is inserted and being pre-staged, the remote switches of the connections (Multi-chassis etherchannel) do not put their local ports into err-disabled state (LACP and so on).

```
<#root>
```


C9600_SVL#

show module

Chassis Type: C9606R

Switch Number 1

Mod	Ports	Card Type	Model	Serial No.
-----	-------	-----------	-------	------------

Mod	MAC addresses	Hw	Fw	Sw	Status
-----	---------------	----	----	----	--------

Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
-----	-----------------	---------------------------	----------------------------

Switch Number 2

Mod	Ports	Card Type	Model	Serial No.
-----	-------	-----------	-------	------------

1	24	24-Port 40GE/12-Port 100GE	C9600-LC-24C	CAT2310L4DW
2	48	48-Port 10GE / 25GE	C9600-LC-48YL	CAT2310L59S
3	0	Supervisor 1 Module	C9600-SUP-1	CAT2340L40Q
5	24	24-Port 40GE/12-Port 100GE	C9600-LC-24C	CAT2313L2W1

Mod	MAC addresses	Hw	Fw	Sw	Status
-----	---------------	----	----	----	--------

1	DC8C.379F.DB80 to DC8C.379F.DBFF	1.0	17.3.1r[FC2]	17.03.01	ok
2	DC8C.3772.FD80 to DC8C.3772.FDFF	1.0	17.3.1r[FC2]	17.03.01	ok
3	7C21.0E5D.0800 to 7C21.0E5D.087F	1.0	17.3.1r[FC2]	17.03.01	ok
5	DC8C.37A0.D180 to DC8C.37A0.D1FF	1.0	17.3.1r[FC2]	17.03.01	ok

Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
-----	-----------------	---------------------------	----------------------------

3	Active	non-redundant	sso
---	--------	---------------	-----

Chassis 2 MAC address range: 64 addresses from 2c4f.523b.bd00 to 2c4f.523b.bd3f

Insert the new supervisor into same slot where faulty supervisor was present and power it on. It must boot up in Stand-alone mode (Non-SVL), leave the Stackwise-virtual links and DAD links disconnected for now.

If your active supervisor is running in "Bundle" boot mode, then copy the software bin file (same as current active supervisor of SVL) to bootflash of new standby supervisor and change bootstring accordingly.

If your active supervisor is running in "Install" boot mode, then manual software upgrade is not needed. Software and boot mode of new supervisor must be upgraded automatically by current active supervisor, as soon it detects an incompatible software version or boot mode on new/standby supervisor.

Configure the new supervisor with Stackwise-virtual settings. (You must use same SVL domain number to match existing member).

<#root>

Switch#

conf t

Enter configuration commands, one per line. End with CNTL/Z.

```
Switch(config)#
stackwise-virtual
```

Please reboot the switch for Stackwise Virtual configuration to take effect
Switch(config-stackwise-virtual)#

```
domain 100
```

```
Switch(config-stackwise-virtual)#
exit
```

Configure SVL and DAD ports. Use same ports, that were used on the faulty supervisor.

```
<#root>
```

```
Switch(config)#
int range fortyGigabitEthernet 1/0/1 -2
```

```
Switch(config-if-range)#
stackwise-virtual link 1
```

```
Switch(config)#int range twentyFiveGigE 2/0/25 -26
Switch(config-if-range)#
stackwise-virtual dual-active-detection
```

Check that SVL configuration is applied correctly to the new switch.

```
<#root>
```

```
Switch#
show stackwise-virtual
```

```
Stackwise Virtual Configuration:
-----
Stackwise Virtual Configuration After Reboot:
-----
Stackwise Virtual : Enabled
```

```
Domain Number : 100
```

```
Switch Stackwise Virtual Link  Ports
-----
1          1                    FortyGigabitEthernet1/0/1
                                FortyGigabitEthernet1/0/2
```

```
Switch#
show stackwise-virtual dual-active-detection
```

```

In dual-active recovery mode: No
Dual-Active-Detection Configuration:
-----
Switch Dad port Status
-----
Distributed Stack DAD Configuration After Reboot:
-----
Switch      Dad port      Status
-----
1           TwentyFiveGigE2/0/25  down
           TwentyFiveGigE2/0/26  down

```

If software version is 16.12.x or higher, you can check the SVL settings in ROMMON from IOSd CLI.

```
<#root>
```

```
Switch#
```

```
show romvar
```

```

ROMMON variables:
BOARDID="38"
ETHER_PORT="2"
PS1="rommon ! >"
MAC_ADDR="7C:21:0E:5D:04:00"
DOPPLER_E_WA="1"
RETRY="0"
MODEL_NUM="C9600-SUP-1"
SYSTEM_SERIAL_NUM="CAT2340L3Y5"
MOTHERBOARD_SERIAL_NUM="CAT2340L3Y5"
TEMPLATE="core"
BAUD="9600"
AUTO_SWITCH_CONSOLE_DISABLE="0"
PSEUDO_OIR_REMOVE_SET="1"
CALL_HOME_DEBUG="00000000000000"
ENABLE_BREAK="yes"
RET_2_RTS=""
CRASHINFO="bootflash:crashinfo_RP_00_00_20200225-024401-UTC"
MCP_STARTUP_TRACEFLAGS="00000000:00000000"
CONFIG_FILE=""
BOOTLDR=""
RECOVERY_RELOAD_DISABLE=""
SWITCH_PRIORITY="1"
SWITCH_NUMBER="1"
SWITCH_IGNORE_STARTUP_CFG="0"
D_STACK_DISTR_STACK_LINK2=""
MANUAL_BOOT="no"
AUTOREBOOT_RESTORE="0"
ABNORMAL_RESET_COUNT="0"
ROMMON_AUTOBOOT_ATTEMPT="3"
BSI="0"
RET_2_RCALTS=""
RANDOM_NUM="1430571596"
BOOT="bootflash:cat9k_iosxe.16.12.02.SPA.bin;"
D_STACK_DISTR_STACK_LINK1="Fo1/0/1,Fo1/0/2,"

```

```
D_STACK_DAD="Twe2/0/25,Twe2/0/26,"
```

```
D_STACK_MODE="aggregation"
```

```
D_STACK_DOMAIN_NUM="100"
```

Save the configurations and power off chassis where new supervisor is placed into.

Connect StackWise-Virtual links between two chassis and prefer to leave the Dual-active detection link disconnected (if applicable).

Power on the chassis and monitor the boot process through console.

Note: If your SVL is running in "Bundle" boot mode, please ensure that new supervisor is coming up with same software version as Active. If not, break into ROMMON again and boot it manually using the correct software version.

Note: If the SVL is in "Install" boot mode, verify that software auto-upgrade is enabled. If not, then enable that by configuring "**software auto-upgrade enable**" from global configuration mode.

```
<#root>
```

```
Active supervisor's log-
```

```
*Sep 13 00:59:49.367: %STACKMGR-6-CHASSIS_ADDED: Chassis 1 R0/0: stack_mgr: Chassis 1 has been added to
```

```
*Sep 13 00:59:51.988: %STACKMGR-6-CHASSIS_ADDED: Chassis 1 R0/0: stack_mgr: Chassis 1 has been added to
```

```
*Sep 13 00:59:52.135: %BOOT-3-BOOTTIME_INCOMPATIBLE_SW_DETECTED: Chassis 2 R0/0: issu_stack: Incompatibl
```

```
*Sep 13 00:59:52.297: %AUTO_UPGRADE-5-AUTO_UPGRADE_START_CHECK: Chassis 2 R0/0: auto_upgrade_client: Aut
```

```
*Sep 13 00:59:53.311: %AUTO_UPGRADE-5-AUTO_UPGRADE_INITIATED: Chassis 2 R0/0: auto_upgrade_client: Auto
```

```
*Sep 13 00:59:53.368: %AUTO_UPGRADE-5-AUTO_UPGRADE_SEARCH: Chassis 2 R0/0: auto_upgrade_client: Searchin
```

```
*Sep 13 00:59:53.397: %AUTO_UPGRADE-5-AUTO_UPGRADE_FOUND: Chassis 2 R0/0: auto_upgrade_client: Found don
```

```
*Sep 13 00:59:53.423: %AUTO_UPGRADE-5-AUTO_UPGRADE_START: Chassis 2 R0/0: auto_upgrade_client: Upgrading
```

```
Logs from new supervisor's console-
```

```
Waiting for remote chassis to join
```

```
#####
```

```
Chassis number is 1
```

```
All chassis in the stack have been discovered. Accelerating discovery
```

```
Chassis 1 reloading, reason - System requested reload <<< reload is instructed by current active as part
```

All the running configurations are automatically synced from Active supervisor to the new one. Wait for these logs from active supervisor.

```
*Sep 13 01:14:18.552: %HA_CONFIG_SYNC-6-BULK_CFGSYNC_SUCCEED: Bulk Sync succeeded
```

```
*Sep 13 01:14:18.577: %RF-5-RF_TERMINAL_STATE: Terminal state reached for (SSO)
```

Once SSO is completed, proceed with connecting the Dual-active detection (DAD) link as well.

- **Push the line cards back inside** (for chassis where supervisor is replaced), to get those attached to backplane again. Now, reconnect the cables.
- **Verify** that all line cards have booted fine, passed online diagnostic tests and brought up their interfaces, including port-channel binding and so on.

Verify Post-Replacement

Check the StackWise Virtual related configurations and the states of the switch using these commands.

```
<#root>
```

```
C9600_SVL#
```

```
show redundancy
```

```
Redundant System Information :
```

```
-----
```

```
Available system uptime = 1 hour, 27 minutes
```

```
Switchovers system experienced = 0
```

```
Standby failures = 0
```

```
Last switchover reason = none
```

```
Hardware Mode = Duplex
```

```
Configured Redundancy Mode = sso
```

```
Operating Redundancy Mode = sso
```

```
Maintenance Mode = Disabled
```

```
Communications = Up
```

```
Current Processor Information :
```

```
-----
```

```
Active Location = Switch 2
```

```
Current Software state = ACTIVE
```

```
Uptime in current state = 1 hour, 27 minutes
```

```
Image Version = Cisco IOS Software [Amsterdam], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.3
```

```
Technical Support: http://www.cisco.com/techsupport
```

```
Copyright (c) 1986-2020 by Cisco Systems, Inc.
```

```
Compiled Fri 07-Aug-20 21:32 by mcpre
```

```
BOOT = bootflash:packages.conf;
```

```
CONFIG_FILE =
```

Peer Processor Information :

Standby Location = Switch 1

Current Software state = STANDBY HOT

Uptime in current state = 0 minutes

Image Version = Cisco IOS Software [Amsterdam], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.3.

Technical Support: <http://www.cisco.com/techsupport>

Copyright (c) 1986-2020 by Cisco Systems, Inc.

Compiled Fri 07-Aug-20 21:32 by mcpre

BOOT = bootflash:packages.conf;

CONFIG_FILE =

<#root>

C9600_SVL#

show stackwise-virtual

Stackwise Virtual Configuration:

Stackwise Virtual : Enabled

Domain Number : 100

Switch Stackwise Virtual Link Ports

1	1	FortyGigabitEthernet1/1/0/1
		FortyGigabitEthernet1/1/0/2
2	1	FortyGigabitEthernet2/1/0/1
		FortyGigabitEthernet2/1/0/2

C9600_SVL#

show stackwise-virtual dual-active-detection

In dual-active recovery mode: No

Recovery Reload: Enabled

Dual-Active-Detection Configuration:

Switch	Dad port	Status
-----	-----	-----
1	TwentyFiveGigE1/2/0/25	up
	TwentyFiveGigE1/2/0/26	up
2	TwentyFiveGigE2/2/0/25	up
	TwentyFiveGigE2/2/0/26	up

<#root>

C9600_SVL#

show module

Chassis Type: C9606R

Switch Number 1

Mod	Ports	Card Type	Model	Serial No.
1	24	24-Port 40GE/12-Port 100GE	C9600-LC-24C	CAT2252L0PR
2	48	48-Port 10GE / 25GE	C9600-LC-48YL	CAT2334L0BA
3	0	Supervisor 1 Module	C9600-SUP-1	CAT2340L3Y5
5	48	48-Port 10GE / 25GE	C9600-LC-48YL	CAT2337L509

Mod	MAC addresses	Hw	Fw	Sw	Status
1	70B3.175A.8100 to 70B3.175A.817F	1.0	17.3.1r[FC2]	17.03.01	ok
2	10B3.D652.9900 to 10B3.D652.997F	1.0	17.3.1r[FC2]	17.03.01	ok
3	7C21.0E5D.0400 to 7C21.0E5D.047F	1.0	17.3.1r[FC2]	17.03.01	ok
5	4C71.0D7C.8400 to 4C71.0D7C.847F	1.0	17.3.1r[FC2]	17.03.01	ok


Mod	Redundancy Role	Operating Redundancy Mode	Configured Redundancy Mode
3	Standby	SSO	SSO

Switch Number 2

snip

Replace a Supervisor of C9600 Quad-Sup StackWise-Virtual

In this example, you are considering a C9600 Quad Sup stackwise-Virtual setup (two supervisors in each chassis), where a supervisor has gone bad and needs to be replaced. The SVL is running in "Install" boot mode.



Replace and Verify

Pulling out the faulty supervisor

- If the supervisor to be replaced is **Global Active supervisor** (Sw-1 Slot 3 in the image shown), perform a failover so that the Global Standby (Sw-2 Slot 3 in the previous picture) takes over as Active. Wait until there is a new Global Standby and SSO gets completed. (In this case, Sw-1 Slot 4 to become new Global Standby).
- If the supervisor to be replaced is **Global Standby supervisor** (Sw-2 Slot 3 in the image shown), pull the supervisor out. Wait until there is a new Global Standby and SSO gets completed. (In this case, Sw-2 Slot 4 to become new Global Standby)
- If the supervisor to be replaced is **ICS supervisor**(Sw-1 Slot 4 or Sw-2 Slot 4 in the image shown), pull the supervisor out.

Inserting the new supervisor

- **If the new supervisor is running on 17.x code**, the steps are straight forward. Just insert the new supervisor. If ICS supervisors have 17.x image, they automatically boot and become part of Quad-sup. Even if it is running different 17.x code than that of what is running one on the production setup, Software Auto-upgrade to automatically take care of upgrading the ICS supervisor with the same 17.x code in INSTALL mode.
- **If the new supervisor is running on 16.x code**, or if you are unsure of the code it is running on, try to insert the supervisor on a spare chassis and get it upgraded to 17.x code. If there is no spare chassis to upgrade, these steps have to be taken.
- **This step is very important.** Insert the ICS supervisor and use Ctrl+C to **break them to rommon**. If you miss to break into ROMMON and supervisor boots up on 16.x code, this could take down the complete chassis where the supervisor was inserted

Look for any SVL related rommon variables. These variables start with D_STACK. Usually a new supervisor do not have these variables set.

```
D_STACK_DISTR_STACK_LINK2=""
D_STACK_DAD="Fo1/0/13,Fo1/0/15,"
D_STACK_MODE="aggregation"
D_STACK_DOMAIN_NUM="255"
D_STACK_DISTR_STACK_LINK1="Fo1/0/10,Fo1/0/15,Fo1/0/16,Fo1/0/17,Fo1/0/3,Fo1/0/6,"
```

Unset all the previously shown variables

```
<#root>
```

```
rommon 1 >
```

```
unset D_STACK_DAD
```

```
rommon 1 >
```

```
unset D_STACK_DISTR_STACK_LINK1
```

```
rommon 1 >
```

```
unset D_STACK_DOMAIN_NUM
```

```
rommon 1 >
```



```
unset D_STACK_MODE
```

Look for variable "SWITCH_NUMBER=1". If the switch number is 2, set the variable to 1. If it is already 1, move to the next step.

```
<#root>
```

```
rommon 1 >
```

```
SWITCH_NUMBER=1
```

Set to manual boot the supervisor.

```
<#root>
```

```
rommon 1 >
```

```
MANUAL_BOOT=YES
```

Manually boot the ICS supervisor in bundle mode using USB/TFTP on 17.x code. Do not change boot variable in rommon. Just boot it manually from rommon.

- **The supervisor is reset** as it detects an existing ICS in SVL mode, so it gets converted from stand-alone to stackwise virtual mode. It could again fall back into rommon, since auto-boot is disabled.

Unset manual boot to enable auto-boot.

```
<#root>
```

```
rommon 1 >
```

```
unset MANUAL_BOOT
```

Manually boot the ICS supervisor in bundle mode using USB/TFTP on 17.x code. Do not change boot variable in rommon. Just boot it manually from rommon. This step boots the ICS in BUNDLE mode.

Note: Software Auto-upgrade is meant to automatically take care of upgrading the ICS supervisor with 17.x code in INSTALL mode and reloads ICS sups to come up in RPR. If auto-upgrade is disabled, you can also run the command "install autoupgrade" from active supervisor.
