Understand Extended Fast Software Upgrade on Catalyst 9300 Series Switches

Contents

Introduction

Prerequisites

Requirements

Minimum Licencing

Other Requirements

Components Used

Background Information

Why xFSU?

Supported Protocols

Limitations

Standalone and Stacked Devices

Stacked Devices

Other Limitations

Required Configurations

Release Support Matrix

Within EM release / From EM to EM release

Within Same SM or EM version

Procedure

Reload Fast

Verify

Basic Show Commands

xFSU Related Logs

Troubleshoot

Related Information

Introduction

This document describes the Extended Fast Software Upgrade (xFSU) feature available on Catalyst 9300 Series Switches.

Prerequisites

Requirements

Minimum Licencing

- Network Essential licence level on the standalone switch
- Network Advantage licence level on the stacked switches.

Other Requirements

- This feature is supported only on Access switches running in Install mode.
- The device must be configured with either Rapid Spanning Tree Protocol (RSTP) or Multiple Spanning Tree Protocol (MSTP).
- The device must not be a ROOT BRIDGE: For a device, with STP configured and not defined as the root device, xFSU is supported only if the number of ports in the forwarding state connected to an STP peer is less than or equal to 1.
- NSF timers: ex: When "bgp graceful-restart" is configured, the BGP hold time is recommended to be configured to 10 seconds.

Components Used

The information in this document is based on these software and hardware versions:

- Catalyst 9300, Catalyst 9300L and Catalyst 9300X Series switches
- Cisco IOS XE 17.3.2a and later


The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, ensure that you understand the potential impact of any command.

Background Information

The Extended Fast Software Upgrade (xFSU) is a software enhancement process aimed to reduce traffic downtime during software reload or upgrade operations. xFSU is based on principles of graceful restart feature (also known as Cisco NSF).

The general idea behind this feature is to keep the data (forwarding) plane to continue to function, while the control plane is reloading as part of the software upgrade. The role of xFSU is to reconcile the forwarding state in ASIC with the new control plane and restore the forwarding state after a quick reset of forwarding ASIC as shown below.

This image shows the dramatic traffic downtime reduction compared to a normal reload.



xFSU introduces these commands:

install add file <image URL> activate xfsu commit

• available in Cisco IOS XE 17.8 release and above

install add file <image URL> activate reloadfast commit

- available in Cisco IOS XE 17.3 and 17.6 releases
- Upgrades the software version with reduced downtime


reload fast

• Reloads the existing software with reduced downtime.

Why xFSU?

For systems like Catalyst 9300 switches without true redundant control and forwarding plane, down time/traffic loss during the reloads and upgrades are more than 3 to 4min.

- For access networks this downtime is critical for the likes of wifi access points, robots etc.
- xFSU can help minimize the down time however restrictions apply as not all configurations are supported.



Note: For stacked system distributing the uplinks across Active and Standby or Active and Member Switches on a Stack as a best practice to further reduce the downtime


Supported Protocols



Note: For all protocols not listed here, the traffic downtime will be similar to that in a normal reload/upgrade

- Layer 2 Switching
- Per VLAN Spanning Tree (PVST)
- STP with RSTP or MSTP
- Static Port-channels (Mode on)
- UDLD
- Link Aggregation Control Protocol (LACP)
- BGP (IPv4 and IPv6 address families)
- Open Shortest Path First (OSPF) or OSPFv2 or OSPFv3
- IS-IS
- Virtual routing and forwarding (VRF)
- Flexible NetFlow
- QoS
- IEEE 802.1X Port-Based Authentication
- MAC authentication bypass
- Web authentication
- Internet Group Management Protocol (IGMP) snooping
- Multicast Listener Discovery (MLD) snooping

Limitations



Caution: xFSU is not supported in combination with any of these scenarios. Please do not attempt xFSU if any of these are present on the device.

Standalone and Stacked Devices

- For an STP root device, if any of the device ports in the forwarding state are connected to an STP peer (A device with STP configured and directly connected to the root device)
- The device is configured with Bidirectional Forwarding Detection (BFD)
- The device is configured with LISP/VXLAN.
- The device is configured with macsec
- The device is configured in SDA and EVPN Fabric.
- The device is configured as Meraki mode or DNAC
- If a BGP peer sends an unsupported hold timer in the BGP Open message, the proposed hold timer is accepted, but BGP is not supported on an xFSU event.

Stacked Devices

• The stacked device is configured with the half-ring state.


- The stacked device is configured with MACsec Key Agreement (MKA) or Cisco TrustSec (CTS)
- the stacked device is configured with multicast since PIM on stack is not in place yet.

Other Limitations

- Application hosting might not restart automatically after performing Extended Fast Software Upgrade. You might need to disable and re-enable Cisco IOx, configure application hosting, install, activate and start an application again.
- Configured Unidirectional Link Detection (UDLD) message intervals are ignored during xFSU. The intervals are restored to the configured values after xFSU is completed.

Required Configurations

This table lists configurations needed prior to performing xFSU to acheive a traffic downtime less than 30 seconds on respective protocols.




Note: This feature and functionality is not applicable to all configurations. Even if a protocol is listed as supported with xFSU, based on its interaction with other components and time sensitive (stateful protocols) configurations, this could lead to a higher traffic loss. It is recommended to test

the specific configuration before using this feature.

Switch Configuration	Protocol	Additional Configuration	Command		
Standalone device	IPv6	Set the time limit for a remote IPv6 node to be considered reachable after a reachability confirmation event has occurred.	Device(config)# ipv6 nd reachable- time 3600000		
	IPv6 with MLD	Enable IPv6 MLD snooping	Device(config)# ipv6 mld snooping		
	OSPF	Increase more retransmit retries in the stack.	Device(config-router)# ip ospf retransmit-interval 10		
	OSPFv3	Increase more retransmit retries in the stack.	Device(config-router)# ospfv3 retransmit-interval 10		
	OSPFv3	 Enable SNMP ifIndex persistence globally Set a fixed router ID for an OSPFv3 instance. Enable SNMP ifIndex persistence 	Device(config)# snmp ifmib ifindex persist Device(config)# router ospfv3 1 Device(config-router)# router-id 192.0.2.5 Device(config-router)# interface-id snmp-if-index		
	BGP	Enable NSF awareness on a device	Device(config-router)# bgp graceful-restart		
Stacked device	OSPF	Increase more retransmit retries in the stack.	Device(config-router)# ip ospf retransmit-interval 10		
	OSPFv3	Increase more retransmit retries in the stack.	Device(config-router)# ospfv3 retransmit-interval 10		
	BGP	Enable NSF awareness on all devices in the stack.	Device(config-router)# bgp graceful- restart all		

		Device(config-router)# nsf ietf	
IS-IS	Enable NSF operation for IS-IS.	OR	
		Device(config-router)# nsf cisco	

Release Support Matrix



Extended Fast Software Upgrade Support between Releases

Within EM release / From EM to EM release


From/To	17.3.x (EM)*	17.4.x (SM)	17.5.x (SM)	17.6.x (EM)	17.7.x (SM)	17.8.x (SM)	17.9.x (EM)
17.3.x (EM)*	✓	X	X	√	X	X	✓
17.4.x (SM)			X	X	X	X	X
17.5.x (SM)	_	_	_	X	X	X	X
17.6.x (EM)			_	√	X	X	✓
17.7.x (SM)			_	_	_	X	X
17.8.x (SM)	_			_	_	_	X
17.9.x (EM)			_	_	_	_	✓

* On Cisco IOS XE 17.3.x train, xFSU is supported only starting 17.3.2 version.

Within Same SM or EM version

From/To	17.3.x (EM)*	17.4.x (SM)	17.5.x (SM)	17.6.x (EM)	17.7.x (SM)	17.8.x (SM)	17.9.x (EM)
17.3.x (EM)*	✓						_
17.4.x (SM)	_	✓					
17.5.x (SM)	_		✓				
17.6.x (EM)		_		✓			
17.7.x (SM)		_			✓		
17.8.x (SM)						✓	
17.9.x (EM)							✓

^{*} On Cisco IOS XE 17.3.x train, xFSU is supported only starting 17.3.2 version.



Note: There are three releases planned each year – two Standard Maintenance (SM) and one Extended Maintenance (EM). A standard support release has a sustaining support lifetime of 12 months from the first customer shipment (FCS) with two scheduled rebuilds. An extended-support release provides a sustaining support lifetime of 48 months from FCS with ten scheduled rebuilds.

Procedure

install add file <image URL>activate xfsu commit



Note: This CLI is available only in Cisco IOS XE 17.8 release and above. For 17.3 and 17.6 releases, use 'install add file <image URL> activate reloadfast commit'

- This command upgrades the software version with reduced downtime.
- Here are the steps that happen automatically on running the CLI.
 - install add: Download image from TFTP server, copy over to all switches and expand packages on each switch
 - **xFSU check**: Provide xFSU related check including restriction check
 - install activate/commit: Activate and commit installed packages

• **install pre-upgrade:** Pre upgrade MCU, Rommon images • **Fast Reload:** fast reload switches <#root> C9300 Switch# install add file flash:cat9k_iosxe.V178_1A_FC2_2.SSA.bin activate xfsu commit install_add_activate_commit: START Tue Apr 19 21:54:03 UTC 2022 STACK_GR: Inside xFSU check if switch stack Checking STP eligibility: Eligible [1]: Performing xFSU-pre-check 300+0 records in 300+0 records out 307200 bytes (307 kB, 300 KiB) copied, 0.196216 s, 1.6 MB/s SUCCESS: xFSU-pre-check finished [1]: xFSU-pre-check package(s) on switch 1 For all other than the below protocols, the traffic downtime will be longer than 30 seconds. 1) Layer 2 Switching, 2) Per VLAN Spanning Tree (PVST), 3) STP with RSTP or MSTP 4) Static Port-channels (Mode on), 5) UDLD, 6) LACP, 7) BGP (IPv4 and IPv6) Open Shortest Path First (OSPF) or OSPFv2 or OSPFv3, 9) IS-IS, 10) Virtual routing and forwarding (VRF), 11) Flexible NetFlow, 12) QoS SUCCESS: xFSU requirement pre-check Downloading file flash:cat9k_iosxe.V178_1A_FC2_2.SSA.bin Finished downloading file flash:cat9k_iosxe.V178_1A_FC2_2.SSA.bin to flash:cat9k_iosxe.V178_1A_FC2_2.SS install_add_activate_commit: Adding PACKAGE install_add_activate_commit: Checking whether new add is allowed --- Starting initial file syncing ---Info: Finished copying flash:cat9k_iosxe.V178_1A_FC2_2.SSA.bin to the selected switch(es) Finished initial file syncing --- Starting Add ---Performing Add on all members [1] Add package(s) on switch 1 [1] Finished Add on switch 1 Checking status of Add on [1] Add: Passed on [1] Finished Add Image added. Version: 17.08.01.0.1516 install_add_activate_commit: Activating PACKAGE Following packages shall be activated:

/flash/cat9k-wlc.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-webui.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-srdriver.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-sipspa.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-sipbase.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-rpboot.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-rpbase.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-lni.V178_1A_FC2_2.SSA.pkg

/flash/cat9k-guestshell.V178_1A_FC2_2.SSA.pkg
/flash/cat9k-espbase.V178_1A_FC2_2.SSA.pkg

```
/flash/cat9k-cc_srdriver.V178_1A_FC2_2.SSA.pkg
--- Verifying Platform specific xFSU admission criteria ---
SUCCESS: xFSU image pre-check
This operation requires a fast reload of the system.
Do you want to proceed? [y/n]y <-- answer y to continue
--- Starting Activate ---
Performing Activate on all members
[1] Activate package(s) on switch 1
--- Starting list of software package changes ---
Old files list:
Modified cat9k-cc_srdriver.17.08.01a.SPA.pkg
Modified cat9k-espbase.17.08.01a.SPA.pkg
Modified cat9k-guestshell.17.08.01a.SPA.pkg
Modified cat9k-lni.17.08.01a.SPA.pkg
Modified cat9k-rpbase.17.08.01a.SPA.pkg
Modified cat9k-rpboot.17.08.01a.SPA.pkg
Modified cat9k-sipbase.17.08.01a.SPA.pkg
Modified cat9k-sipspa.17.08.01a.SPA.pkg
Modified cat9k-srdriver.17.08.01a.SPA.pkg
Modified cat9k-webui.17.08.01a.SPA.pkg
Modified cat9k-wlc.17.08.01a.SPA.pkg
New files list:
Added cat9k-cc_srdriver.V178_1A_FC2_2.SSA.pkg
Added cat9k-espbase.V178_1A_FC2_2.SSA.pkg
Added cat9k-guestshell.V178_1A_FC2_2.SSA.pkg
Added cat9k-lni.V178_1A_FC2_2.SSA.pkg
Added cat9k-rpbase.V178_1A_FC2_2.SSA.pkg
Added cat9k-rpboot.V178_1A_FC2_2.SSA.pkg
Added cat9k-sipbase.V178_1A_FC2_2.SSA.pkg
Added cat9k-sipspa.V178_1A_FC2_2.SSA.pkg
Added cat9k-srdriver.V178_1A_FC2_2.SSA.pkg
Added cat9k-webui.V178_1A_FC2_2.SSA.pkg
Added cat9k-wlc.V178_1A_FC2_2.SSA.pkg
Finished list of software package changes
[1] Finished Activate on switch 1
Checking status of Activate on [1]
Activate: Passed on [1]
Finished Activate
--- Starting Commit ---
Performing Commit on all members
[1] Commit package(s) on switch 1
[1] Finished Commit on switch 1
Checking status of Commit on [1]
Commit: Passed on [1]
Finished Commit
Send model notification for install_add_activate_commit before reload
Check xFSU support and verification on switch
[1]: xFSU-Verify-Package package(s) on switch 1
Finished preverifying before xFSU
SUCCESS to verify packages
SUCCESS to verify before xFSU
[1]: Finished xFSU-Verify-Package successful on switch 1
(-2) SUCCESS: Finished xFSU-Verify-Package: Success on [1]
[1]: Performing Upgrade_Service
300+0 records in
300+0 records out
```

307200 bytes (307 kB, 300 KiB) copied, 0.196891 s, 1.6 MB/s

SUCCESS: Upgrade_Service finished

PID TTY TIME CMD Starting GR:#

Waiting for UDLD processing: UDLD processing complete

cat: /: Is a directory

Wait for ifm backup: Ifm backup is completeApr 19 22:05:04.843: %PMAN-5-EXITACTION: F0/0: pvp: Process Apr 19 22:05:08.099: %PMAN-5-EXITACTION: R0/0: pvp: Process manager is exiting: rp processes exit with

Initializing Hardware..... Reload Fast Detected

System Bootstrap, Version 17.9.0.4r, DEVELOPMENT SOFTWARE Copyright (c) 1994-2022 by cisco Systems, Inc. Compiled Tue 03/22/2022 10:39:31.69 by mjagatap

Current ROMMON image: Primary
Last reset cause: SoftwareReload
C9300-24T platform with 8388608 Kbytes of main memory

Preparing to autoboot. [Press Ctrl-C to interrupt] 0 boot: attempting to boot from [flash:packages.conf]

boot: reading file packages.conf

#

Loading image in Verbose mode: 0

Both links down, not waiting for other switches Switch number is 1

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc. 170 West Tasman Drive San Jose, California 95134-1706

Cisco IOS Software [Cupertino], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.8.1a, RELEASE SOF Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2022 by Cisco Systems, Inc.
Compiled Sat 16-Apr-22 18:59 by mcpre

This software version supports only Smart Licensing as the software licensing mechanism.

PLEASE READ THE FOLLOWING TERMS CAREFULLY. INSTALLING THE LICENSE OR LICENSE KEY PROVIDED FOR ANY CISCO SOFTWARE PRODUCT, PRODUCT FEATURE, AND/OR SUBSEQUENTLY PROVIDED SOFTWARE FEATURES (COLLECTIVELY, THE "SOFTWARE"), AND/OR USING SUCH SOFTWARE CONSTITUTES YOUR FULL ACCEPTANCE OF THE FOLLOWING TERMS. YOU MUST NOT PROCEED FURTHER IF YOU ARE NOT WILLING TO BE BOUND BY ALL THE TERMS SET FORTH HEREIN.

Your use of the Software is subject to the Cisco End User License Agreement (EULA) and any relevant supplemental terms (SEULA) found at http://www.cisco.com/c/en/us/about/legal/cloud-and-software/software-terms.html.

You hereby acknowledge and agree that certain Software and/or features are licensed for a particular term, that the license to such Software and/or features is valid only for the applicable term and that such Software and/or features may be shut down or otherwise terminated by Cisco after expiration of the applicable license term (e.g., 90-day trial period). Cisco reserves the right to terminate any such Software feature electronically or by any other means available. While Cisco may provide alerts, it is your sole responsibility to monitor your usage of any such term Software feature to ensure that your systems and networks are prepared for a shutdown of the Software feature.

FIPS: Flash Key Check: Key Not Found, FIPS Mode Not Enabled cisco C9300-24T (X86) processor with 1310600K/6147K bytes of memory. Processor board ID FJC2327E0UB 2048K bytes of non-volatile configuration memory. 8388608K bytes of physical memory. 1638400K bytes of Crash Files at crashinfo:. 11264000K bytes of Flash at flash:.

Base Ethernet MAC Address : d4:ad:bd:f0:38:80 Motherboard Assembly Number : 73-18270-03 Motherboard Serial Number : FJZ23271DDG

Model Revision Number : E0 Motherboard Revision Number : B0

Model Number : C9300-24T

System Serial Number : FJC2327E0UB

CLEI Code Number :

WARNING: Command has been added to the configuration using a type 7 password. However, recommended to m

Press RETURN to get started!

Reload Fast

- This command reloads the existing software with reduced downtime.
- Here are the steps that happen automatically on running the CLI.

- **xFSU check**: Provide xFSU related check including restriction check
- **Fast Reload**: fast reload switches

<#root>

C9300 Switch#

reload fast

Reload fast command is being issued on Active unit, this will reload fast the whole stack Proceed with reload fast? [confirm]

STACK_GR: Inside xFSU check if switch stack
Checking STP eligibility: Eligible

[1]: Performing xFSU-pre-check
300+0 records in
300+0 records out
307200 bytes (307 kB, 300 KiB) copied, 0.196405 s, 1.6 MB/s
SUCCESS: xFSU-pre-check finished
[1]: xFSU-pre-check package(s) on switch 1

For all other than the below protocols, the traffic downtime will be longer than 30 seconds.

- 1) Layer 2 Switching, 2) Per VLAN Spanning Tree (PVST), 3) STP with RSTP or MSTP
- 4) Static Port-channels (Mode on), 5) UDLD, 6) LACP, 7) BGP (IPv4 and IPv6)

Open Shortest Path First (OSPF) or OSPFv2 or OSPFv3, 9) IS-IS, 10) Virtual routing and forwarding (VRF), 11) Flexible NetFlow, 12) QoS SUCCESS: xFSU requirement pre-check --- Verifying Platform specific xFSU admission criteria ---SUCCESS: xFSU image pre-check Check xFSU support and verification on switch [1]: xFSU-Verify-Package package(s) on switch 1 Finished preverifying before xFSU SUCCESS to verify packages SUCCESS to verify before xFSU [1]: Finished xFSU-Verify-Package successful on switch 1 (-2) SUCCESS: Finished xFSU-Verify-Package: Success on [1] [1]: Performing Upgrade_Service 300+0 records in 300+0 records out 307200 bytes (307 kB, 300 KiB) copied, 0.196099 s, 1.6 MB/s mount: /tmp/microcode_update/boot_pkg: WARNING: source write-protected, mounted read-only. SUCCESS: Upgrade_Service finished PID TTY TIME CMD Starting GR:# Waiting for UDLD processing: UDLD processing complete cat: /: Is a directory Wait for ifm backup: Ifm backup is completeApr 19 21:43:03.283: %PMAN-5-EXITACTION: F0/0: pvp: Process Apr 19 21:43:05.337: %PMAN-5-EXITACTION: RO/O: pvp: Process ger is exiting: rp processes exit with relo

Initializing Hardware..... Reload Fast Detected System Bootstrap, Version 17.9.0.4r, DEVELOPMENT SOFTWARE Copyright (c) 1994-2022 by cisco Systems, Inc. Compiled Tue 03/22/2022 10:39:31.69 by mjagatap

Current ROMMON image : Primary Last reset cause : SoftwareReload

C9300-24T platform with 8388608 Kbytes of main memory

Preparing to autoboot. [Press Ctrl-C to interrupt] 0 boot: attempting to boot from [flash:packages.conf]

boot: reading file packages.conf

#

Loading image in Verbose mode: 0

Both links down, not waiting for other switches Switch number is 1

Restricted Rights Legend

Use, duplication, or disclosure by the Government is subject to restrictions as set forth in subparagraph (c) of the Commercial Computer Software - Restricted Rights clause at FAR sec. 52.227-19 and subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS sec. 252.227-7013.

Cisco Systems, Inc. 170 West Tasman Drive San Jose, California 95134-1706

Cisco IOS Software [Cupertino], Catalyst L3 Switch Software (CAT9K_IOSXE), Version 17.8.1a, RELEASE SOF Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2022 by Cisco Systems, Inc.
Compiled Sat 16-Apr-22 18:59 by mcpre

This software version supports only Smart Licensing as the software licensing mechanism.

PLEASE READ THE FOLLOWING TERMS CAREFULLY. INSTALLING THE LICENSE OR LICENSE KEY PROVIDED FOR ANY CISCO SOFTWARE PRODUCT, PRODUCT FEATURE, AND/OR SUBSEQUENTLY PROVIDED SOFTWARE FEATURES (COLLECTIVELY, THE "SOFTWARE"), AND/OR USING SUCH SOFTWARE CONSTITUTES YOUR FULL ACCEPTANCE OF THE FOLLOWING TERMS. YOU MUST NOT PROCEED FURTHER IF YOU ARE NOT WILLING TO BE BOUND BY ALL THE TERMS SET FORTH HEREIN.

Your use of the Software is subject to the Cisco End User License Agreement (EULA) and any relevant supplemental terms (SEULA) found at http://www.cisco.com/c/en/us/about/legal/cloud-and-software-terms.html.

You hereby acknowledge and agree that certain Software and/or features are licensed for a particular term, that the license to such Software and/or features is valid only for the applicable term and that such Software and/or features may be shut down or otherwise terminated by Cisco after expiration of the applicable license term (e.g., 90-day trial period). Cisco reserves the right to terminate any such Software feature electronically or by any other means available. While Cisco may provide alerts, it is your sole responsibility to monitor your usage of any such term Software feature to ensure that your systems and networks are prepared for a shutdown of the Software feature.

FIPS: Flash Key Check: Key Not Found, FIPS Mode Not Enabled cisco C9300-24T (X86) processor with 1310600K/6147K bytes of memory. Processor board ID FJC2327E0UB 2048K bytes of non-volatile configuration memory. 8388608K bytes of physical memory. 1638400K bytes of Crash Files at crashinfo:. 11264000K bytes of Flash at flash:.

Base Ethernet MAC Address : d4:ad:bd:f0:38:80 Motherboard Assembly Number : 73-18270-03 Motherboard Serial Number : FJZ23271DDG

Model Revision Number : E0
Motherboard Revision Number : B0

Model Number : C9300-24T

System Serial Number : FJC2327E0UB

CLEI Code Number :

WARNING: Command has been added to the configuration using a type 7 password. However, recommended to m

Press RETURN to get started!

C9300_Switch>
C9300_Switch>en
C9300_Switch#sh log | inc FAST

*Apr 19 21:48:01.667: %FED_IPC_MSG-5-FAST_RELOAD_COMPLETE: Switch 1 F0/0: fed: Fast reload operation co

Verify

Commands/outputs to be collected to validate after xFSU is completed successfully.

Basic Show Commands

- show switch detail To display the switch detail information
- **show version** To display the switch version
- . **show version** | **in reason** display reason as "Image Install with Reloadfast" or "Reload Fast Command "on all switches.

- **show running-config** To display the switch running configuration
- **show logging** To display the switch console log
- **show log | in FAST** (collect this post xFSU) To grep FAST_RELOAD_COMPLETE from the switch console log

xFSU Related Logs

show graceful-reload - To display the xFSU graceful reload log

```
<#root>

C9300_Switch#

show graceful-reload

Graceful Reload Infra Status: Not running
Minimum required system uptime before fast reload can be supported is 10 seconds
Client OSPFV3 : (0x10203008) Status: Up
Client OSPF : (0x10203007) Status: Up
Client GR_CLIENT_BGP : (0x10203006) Status: Up
Client IS-IS : (0x10203005) Status: Up
Client LACP_xFSU : (0x10203004) Status: Up
Client GR_CLIENT_TOPO : (0x10203003) Status: Up
Client GR_CLIENT_VRF : (0x10203002) Status: Up
Client GR_CLIENT_FIB : (0x10203001) Status: Up
Client GR_CLIENT_FIB : (0x10203000) Status: Up
```

show xfsu status - To display the xFSU status (This CLI is available only in Cisco IOS XE 17.8 release and above. For 17.3 and 17.6 releases, use '**show reloadfast status**')

```
<#root>
C9300_Switch#
show xfsu status

Reload Fast PLATFORM Status: Dataplane update done
Graceful Reload Infra Status: Not running
Minimum required system uptime before fast reload can be supported is 10 seconds
Client OSPFV3 : (0x10203008) Status: Up
Client OSPF : (0x10203007) Status: Up
Client GR_CLIENT_BGP : (0x10203006) Status: Up
Client IS-IS : (0x10203005) Status: Up
Client LACP_xFSU : (0x10203004) Status: Up
Client GR_CLIENT_TOPO : (0x10203003) Status: Up
Client GR_CLIENT_TOPO : (0x10203002) Status: Up
Client GR_CLIENT_RIB : (0x10203001) Status: Up
Client GR_CLIENT_RIB : (0x10203000) Status: Up
```

Troubleshoot

Outputs to be collected in case if xFSU fails.

FPGA Version

<#root>
show platform hardware fpga switch <sw_num> | inc Version
 - display FPGA version

Complete Topology Including SKU/FRU/Uplink/Downlink Details

<#root>

show inventory

- display switch inventory

show cdp neighbor

- display switch CDP neighbor

show etherchannel summary

- display switch etherchannel summary

show spanning-tree

- display switch spanning-tree configuration

show romvar switch all | in BOARD

- display switch board ID

Btrace & Crash Related Info

<#root>

show platform software trace message fed switch <sw-num>

- display switch fed trace configuration

request platform software trace rotate all

rotate switch trace logs to archive
 Copy logs from

crashinfo-<sw_num>:/tracelogs/fed_F0*

If crash happens during xFSU, copy

crashinfo-<sw_num>:system-report*

```
If stack SSO not ready or archive trace generated during bootup, copy crashinfo-<sw_num>:*archive*
```

Interface Related Info

```
<#root>
show interface status | inc connected
  - display switch connected interface status.
show ip interface brief | inc up
  - display switch those interfaces which stay up.
show interface <intf-id> status -
display interface status for particular interface.
show interface <intf-id> status err-disabled
  - display interface err-disabled status for particular interface.
```

XCVR/Phy/Uplink Related Info

<#root>

show controllers ethernet-controller <intf-id> phy detail

- To display switch phy detail for particular ethernet-controller interface.

show controllers ethernet-controller <intf-id> mac

- To display switch mac information for particular ethernet-controller interface.

show controllers ethernet-controller <intf-id> link-status

- To display switch link status for particular ethernet-controller interface.

show controllers ethernet-controller <ints-id>


- To display information for particular ethernet-controller interface.

xFSU show tech-support xfsu

<#root>


show tech-support xfsu

- display xFSU technical support information



Note: (This CLI is available only in Cisco IOS XE 17.8 release and above. For 17.3 and 17.6 releases, use 'show tech-support reloadfast')

xFSU eligibility



Note: **show xfsu eligibility** -To display xFSU eligibility information (This CLI is available only in Cisco IOS XE 17.8 release and above)

show xfsu eligibility (standalone switch)

<#root>

C9300_Switch#

show xfsu eligibility

Reload fast supported: Yes

Reload Fast PLATFORM Status: Not started yet

Stack Configuration: No

Eligibility Check Status

----Autoboot Enabled No
Install Mode Yes
Check macsec eligibility Eligible

```
<-- All the status must be Yes or eligible to continue xFSU
Spanning Tree
                          Eligible
<-- For STP status must be eligible to continue xFSU
show xfsu eligibility (stack switches)
<#root>
Switch#
show xfsu eligibility
Reload fast supported: Yes
Reload Fast PLATFORM Status: Not started yet
Stack Configuration: Yes
Eligibility Check
                       Status
==========
                         =====
                        Yes
Autoboot Enabled
Install Mode
                         Yes
Network Advantage License Yes
Full ring stack
Check macsec eligibility Eligible
<--
All the status must be Yes or eligible to continue xFSU
Spanning Tree
                          Eligible
<-- For STP status must be eligible to continue xFSU
SSO Mode
                          Yes
<-- If 'SSO mode' status is 'No', please wait until condition is met, then proceed
```

Related Information

- Technical Support & Documentation Cisco Systems
- List of protocols not supported: refer the link here
- List of protocols supported: refer to the link <u>here</u>