



Release Notes for Cisco 860VAE-W Series Multimode VDSL2/ADSL2/2+ DSL Routers using Firmware Release A2pv6F039t

First Published: 2016-05-30

Last Updated: 2016-05-30

Release: Cisco IOS Release 15.5(3)M

Contents

- [Introduction, page 1](#)
- [System Requirements, page 1](#)
- [Supported Features, page 4](#)
- [New and Changed Information, page 5](#)
- [Related Documentation, page 5](#)
- [Obtaining Documentation and Submitting a Service Request, page 6](#)

Introduction

These release notes describe new enhancements and fixed caveats for the Cisco 860VAE-W Series Multimode VDSL2/ADSL2/2+ DSL routers using firmware release A2pv6F039t. This firmware is used for Cisco CPEs and recommended for Australia's National Broadband Network (NBN).

These release notes are updated as needed.

System Requirements

- [Memory and IOS Software Requirements, page 2](#)
- [Determining the Firmware Version, page 2](#)
- [Upgrading to a New Firmware Release, page 3](#)

System Requirements

Memory and IOS Software Requirements

Table 1 lists the supported Cisco 860VAE Series Multimode VDSL2/ADSL2/2+ DSL routers and also the memory and IOS requirements while using firmware release A2pv6F039t.

Table 1 Supported Cisco 860VAE-W Series Multimode VDSL2/ADSL2/2+ DSL and Memory Requirements

Platform	Flash (MB)	DRAM (MB)	IOS version
C866VAE-W-E-K9			
C867VAE-W-A-K9			
C867VAE-W-E-K9			
C867VAE-POE-W-A-K9	128	512	15.5(3) M or later

Determining the Firmware Version

To determine the version of firmware currently running on your Cisco 860VAE-W series router, issue the following IOS command and look for the output entries shown in bold in this example:

```
C867VAE-K9#show controller vdsl 0

Controller VDSL 0 is UP

Daemon Status:           Up

XTU-R (DS)                XTU-C (US)

Chip Vendor ID:          'BDCM'           'BDCM'
Chip Vendor Specific:    0x0000           0xA450
Chip Vendor Country:    0xB500           0xB500
Modem Vendor ID:        'CSCO'           'BDCM'
Modem Vendor Specific:      0x4602             0x0000
Modem Vendor Country:       0xB500             0xB500
Serial Number Near:         GMK172801HR C867VAE 15.5(3)
Serial Number Far:
Modem Version Near:         15.5(3)
Modem Version Far:          0xa450

Modem Status:               TC Sync (Showtime!)

DSL Config Mode:            VDSL2
Trained Mode:               G.993.2 (VDSL2) Profile 17a
TC Mode:                    PTM
Selftest Result:            0x00
DELT configuration:         disabled
DELT state:                 not running

Full inits:                 1
Failed full inits:          0
Short inits:                0
Failed short inits:         12

Modem FW Version:       4.12L.08
Modem PHY Version:     A2pv6F039t.d24m
Trellis:                    ON                      ON
SRA:                         disabled             disabled
  SRA count:                  0                      0
Bit swap:                     enabled             enabled
  Bit swap count:             8                      1
Line Attenuation:             0.3 dB                 0.0 dB
Signal Attenuation:           0.0 dB                 0.0 dB
Noise Margin:                 18.8 dB                6.8 dB
```

System Requirements

```

Attainable Rate:      150631 kbits/s          60284 kbits/s
Actual Power:        14.5 dBm                - 4.3 dBm
Per Band Status:    D1      D2      D3      U0      U1      U2      U3
Line Attenuation(dB): 0.0    0.4    0.6    N/A    0.0    0.0    N/A
Signal Attenuation(dB): 0.0    0.4    0.6    N/A    0.0    0.0    N/A
Noise Margin(dB):   19.2   18.6   18.6   N/A    7.1    6.6    N/A
Total FECC:         0
Total ES:           0
Total SES:          0
Total LOSS:         0
Total UAS:          1292
Total LPRS:         0
Total LOFS:         0
Total LOLS:         0

```

```

                DS Channel1    DS Channel0    US Channel1    US Channel0
Speed (kbps):    0                100014         0                60015
SRA Previous Speed: 0                0              0                0
Previous Speed:  0                0              0                0
Reed-Solomon EC: 0                0              0                0
CRC Errors:      0                0              0                0
Header Errors:   0                0              0                0
Interleave (ms): 0.00           7.00          0.00            0.00
Actual INP:      0.00           1.01          0.00            0.00

```

```

Training Log : Stopped
Training Log Filename : flash:vdslllog.bin

```

Upgrading to a New Firmware Release

Perform the following steps to upgrade to a new firmware release:

1. Download the new firmware from Cisco.com Software Center at <http://www.cisco.com/cisco/software/navigator.html>.

Choose **Products** -> **Routers** -> **Branch Routers** -> **Cisco 800 Series Routers** -> **Cisco 866VAE-W Integrated Services Router (or Cisco 867 VAE-W Integrated Services Router)** -> **Very High Bitrate DSL (VDSL) Firmware** > **VAEW_A_39f1_B_39d_24g1.SSA.bin**

2. Copy the **VAEW_A_39f1_B_39d_24g1.SSA.bin** firmware to a designated location; for example, router flash or a TFTP server.
3. Configure the router to load the new firmware from a designated location.

```

Router# configure terminal
Enter configuration commands, one per line.  End with CNTL/Z.

```

```

Router(config)# controller vdsl 0
Router(config-controller)# firmware filename ?
archive:  Download fw file name
cns:     Download fw file name
flash:   Download fw file name
ftp:     Download fw file name
http:    Download fw file name
https:   Download fw file name
null:    Download fw file name
nvram:   Download fw file name
rcp:     Download fw file name
scp:     Download fw file name
system:  Download fw file name

```

Supported Features

```
tar:      Download fw file name
tftp:     Download fw file name
tmpsyst:  Download fw file name
xmodem:   Download fw file name
ymodem:   Download fw file name
```

```
Router(config-controller)# firmware filename flash:
```

Note: Controller VDSL 0 should *not* be turned off.

4. Enter the **copy running-config startup-config** command to save your configuration.
5. Enter the reload command to restart the router.

Supported Features

This section contains information about various features supported by firmware release A2pv6F039t:

- G.993.2 (VDSL2) protocol.
- PTM and ATM mode
- Annex A and Annex B band plans
- Profiles supported: 8a/b/c/d, 12a/b, 17a and 30a (BCM6306 required)
- US0
- Diagnostics mode/DELT
- Bitswaps, SRA and SOS/ROC
- FEXT Equalized UPBO
- Dying Gasp
- INM
- PhyR and G.INP (Framing Type 1)
- SRA/SoS+G.INP
- G.vector and G.vector friendly mode (G.993.2 Annex Y)
- Virtual Noise
- Alternate Electrical Length Measurement
- ADSL protocols
- G.992.5 (ADSL2+), G.992.3 (ADSL2), G.992.2 (G.LITE), G.992.1 (G.DMT), ANSI T1.413
- ATM/PTM mode
- Annex A/L/M
- L2 power management
- Diagnostics mode/DELT
- Bitswaps and SRA
- INM

New and Changed Information

- PhyR and G.INP (Framing Type 1)
- SRA+G.INP
- Virtual Noise

New and Changed Information

This section contains changes introduced with firmware release A2pv6F039t.

- Improve G.992.1 Showtime Stability against ALU 7350 [FW-8502]
- Provide driver bit control to use AELEM of 0 in G.993.2 [FW-8509]
- Remove the CPE side work around for US PSD against NVLT-D to avoid no-connects in G.993.2 [FW-8471]

Known Issues and Limitations

- ANSI T1.413 is not supported with AFE A.12.40
- G.INP supports DTU framing type 1 only
- G.993.2 ATM mode testing is limited due to lack of DSLAM support

Related Documentation

- [Release-Specific Documents, page 5](#)
- [Platform-Specific Documents, page 5](#)
- [Other Firmware Code, page 5](#)

Release-Specific Documents

For detailed information about the release-specific platforms, see the following documentations:

- [Cisco Multimode VDSL2 and ADSL2/ADSL2+ High-Speed WAN Interface Card](#)
- [Cisco 800 Series Integrated Services Router Hardware Installation Guide](#)
- [Cisco 800 Series Integrated Services Routers Software Configuration Guide](#)

Platform-Specific Documents

For more information about the supported platforms, see the following documentations:

- [Cisco 800 Series Integrated Services Router Hardware Installation Guide](#)
- [Cisco 800 Series Integrated Services Routers Software Configuration Guide](#)

Other Firmware Code

For information on the firmware used prior to this release, see [Release Notes for Cisco 860VA Series Multimode VDSL2/ADSL2/2+ DSL Router with Firmware Release A2pv6F039d](#).

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2016 Cisco Systems, Inc. All rights reserved.