

Release Notes for VDSL CPE PHY Release B2pvC038u

First Published: December 18, 2015 Release: Cisco IOS Release 15.2(4)M

Contents

- Introduction, page 1
- System Requirements, page 1
- Features, page 5
- New and Changed Information, page 6
- Related Documentation, page 7

Introduction

These release notes describe new enhancements and fixed caveats for the VDSL CPE PHY using firmware release B2pvC038u. This firmware is used for Cisco CPEs and certified by Deutsch Telekom with its Digital Subscriber Line Access Multiplexers (DSLAMs). Cisco does not support any CPE interoperability issues if the CPEs are not tested with the DSLAMs by Deutsch Telekom. In this firmware Annex J mode is enabled.

These release notes are updated as needed.

System Requirements

- Memory and IOS Software Requirements, page 2
- Determining the Firmware Version, page 2
- Upgrading to a New Firmware Release, page 3



Memory and IOS Software Requirements

Table 1 lists the supported Cisco 886VA Series Routers and Cisco 896VA Series Routers with their respective memory and IOS requirements while using firmware release B2pvC038u.



This firmware version is compiled with the SDK version 4.02L.03 and supports IOS release 15.6(2)T and earlier releases up to the supported version mentioned in the firmware release note. This firmware is not supported with Cisco IOS 15.6(3)M and later releases.

Table 1 Supported Cisco 886 Routers and Cisco 896 Routers with Memory Requirements

Platform	Flash	DRAM	IOS version
C886VA-K9	128 MB	256 MB	15.2(4) M or later
C886VAJ-K9			
C886VA-W-E-K9			
C896VA-K9	256 MB	1 GB DRAM	
C896VAG-LTE-GA-K9			

The following EHWIC is supported with B2pvC038u:

C1900/C2900/C3900/C3900e Series router with Cisco EHWIC-VA-DSL-B

Determining the Firmware Version

To determine the version of firmware currently running on your Cisco 886VA Series Router, issue the following IOS command and look for the output entries shown in bold in this example:

```
C886VA# show controller vdsl 0
Controller VDSL 0 is UP
Daemon Status:
                       XTU-R (DS)
                                               XTU-C (US)
Chip Vendor ID:
                                                'BDCM'
                       'BDCM'
Chip Vendor Specific: 0x0000
                                                0x939B
Chip Vendor Country:
                       0 \times B500
                                                0xB500
Modem Vendor ID:
                       'CSCO'
Modem Vendor Specific: 0x4602
                                                0x0000
Modem Vendor Country: 0xB500
                                                0x0000
Serial Number Near: FHK141975T1 886VA-K9 15.5(3)M
Serial Number Far:
                    15.5(3)M
Modem Version Near:
Modem Version Far:
                      0x939b
Modem Status:
                        TC Sync (Showtime!)
DSL Config Mode:
                        AUTO
Trained Mode: G.992.5 (ADSL2+) Annex J
TC Mode:
                       ATM
Selftest Result:
                        0x00
DELT configuration:
                       disabled
DELT state:
                        not running
```

```
Failed full inits:
                          1
Short inits:
Failed short inits:
                                   File Name
Firmware
                Source
VDSL
                user config
                                   flash:VA_A_39m_B_38u_24h.bin
Modem FW Version:
                          151214_0008-4.02L.03.B2pvC038u.d24h
                        B2pvC038u.d24h
Modem PHY Version:
Trellis:
                           ON
                           disabled
                                                      disabled
 SRA count:
                         0
                                                      0
                         enabled
Bit swap:
                                                      enabled
Bit swap: enabled

Bit swap count: 0

Line Attenuation: 0.0 dB

Signal Attenuation: 0.9 dB

Noise Margin: 5.9 dB

Attainable Rate: 27521 kbits/s

Actual Power: 6.9 dBm
                                                      0
                                                      1.2 dB
                                                       0.2 dB
                                                       6.9 dB
                                                     2393 kbits/s
                                                     11.9 dBm
Total FECC:
Total ES:
                        0
                                                      0
                        0
Total SES:
                                                      Ω
                        0
Total LOSS:
                                                      Ω
Total UAS:
                          73
                                                      73
                          0
                                                      0
Total LPRS:
Total LOFS:
                          0
                                                      0
Total LOLS:
                          Ω
                   DS Channell DS Channell US Channell
                                                                        US Channel0
                                                                               2392
```

0 Speed (kbps): 27515 0 SRA Previous Speed: 0
Previous Speed: 0
Total Cells: 0 0 0 0 0 27662 1567 0 0 1562068 0 114878 User Cells: 16 0 0 0 Reed-Solomon EC: 0 0 0 0 0 CRC Errors: 0 4 Header Errors: 0 0 Interleave (ms): 0.00
Actual INP: 0.00 0.00 0.08 7.23 0.00 0.00 0.22

Training Log : Stopped

Training Log Filename : flash:vdsllog.bin

C886VA#

Full inits:

10

Upgrading to a New Firmware Release

Perform the following steps to upgrade to a new firmware release:

- **1.** Download the new firmware from Cisco.com Software Center at: http://www.cisco.com/cisco/software/navigator.html
 - Choose Products > Routers > Branch Routers > 800 Series Routers > Cisco 886VA Integrated Services Router > Very High Bitrate DSL (VDSL) Firmware > B2pvC038u
- 2. Copy the B2pvC038u firmware to a designated location; for example, router flash or a TFTP server.
- 3. Configure the router to load the new firmware from a designated location.

Router# configure terminal

Enter configuration commands, one per line. End with $\mathtt{CNTL}/\mathtt{Z}\text{.}$

```
Router(config) # controller vdsl 0
Router(config-controller) # firmware filename ?
 archive: Download fw file name
           Download fw file name
           Download fw file name
 flash:
  ftp:
          Download fw file name
           Download fw file name
 http:
           Download fw file name
 https:
           Download fw file name
 null:
 nvram:
           Download fw file name
 rcp:
           Download fw file name
           Download fw file name
 scp:
 system: Download fw file name
           Download fw file name
  tar:
           Download fw file name
  tmpsys: Download fw file name
 xmodem: Download fw file name
 ymodem:
          Download fw file name
```

Router(config-controller)# firmware filename flash:



Controller VDSL 0 should not be turned off.

- 4. Enter the **copy running-config startup-config** command to save your configuration.
- **5.** Enter the **reload** command to restart the router.

Features

B2pvC038u supports the following features:

- G.993.2 (VDSL2) protocol
 - PTM and ATM mode
 - Annex B over ISDN band plans
 - Profiles supported: 8a/b/c/d, 12a/b and 17a
 - US0
 - Diagnostics mode/DELT
 - Bitswaps, SRA and SOS/ROC
 - FEXT Equalized UPBO
 - Dying Gasp
 - INM
 - PhyR and G.INP (Framing Type 1)
 - SRA/SoS+G.INP
 - Virtual Noise
 - G.Vector (G.993.5) and G.Vector Friendly (G.993.2 Annex Y)
 - Alternate Electrical Length Measurement

- ADSL protocols
 - G.992.5 (ADSL2+), G.992.3 (ADSL2), G.992.1 (G.DMT)
 - ATM/PTM mode
 - Annex B/J
 - L2 power management
 - Diagnostics mode/DELT
 - Bitswaps and SRA
 - INM
 - PhyR and G.INP (Framing Type 1)
 - SRA+G.INP
 - Virtual Noise

New and Changed Information

This section contains changes introduced with firmware release B2pvC038u.

- Fixed issue with G.993.2 SRA when block interleaver is used in G.INP
- Fixed G.993.2 training issues when ROC tones have low PSD
- Fixed G.993.2 Annex Y negotiation issue
- Fixed G.998.4 LEFTRS threshold update issue after SRA
- Fixed no connect issue in G.993.2 against ADTRAN DSLAM
- Improved ATTNDR computation in G.993.2 Showtime
- Improved G.INP+SRA upshift behavior in G.993.2
- Fixed O-TPS parsing issue in G.993.2 when G.INP is enabled
- Fixed minDelay initialization issue in G.993.2 G.INP
- Fixed issue in disabling DS and US SRA separately in G.993.2 when G.INP is enabled
- Improved LOS detection in G.993.2
- Improved G.993.2 G.INP DS rates when SOS is not negotiated
- Improved ATTNDR computation in G992.[35]
- Fixed false triggering of DS SOS in G.993.2
- Fixed no-connect in certain fixed rate profiles in G.992.[35] when nitro is enabled
- Fixed G.Vector training issue in high cross-talk condition
- Fixed G.993.2 sync issues in long loops
- Fixed connect issue in G.993.2 for low fixed rate profiles when PhyR is enabled
- Adjusted B43 G.HS PSD

Known Issues and Limitations

• G.INP supports DTU framing type 1 only

Related Documentation

- Release-Specific Documents, page 7
- Platform-Specific Documents, page 7
- Other Firmware Code, page 7

Release-Specific Documents

For detailed information about the release-specific platforms, see the following documentations:

- Cisco Multimode VDSL2 and ADSL2/ADSL2+ High-Speed WAN Interface Card
- Cisco 800 Series Integrated Services Router Hardware Installation Guide
- Cisco 800 Series Integrated Services Routers Software Configuration Guide

Platform-Specific Documents

For more information about the supported platforms, see the following documentations:

- Cisco 800 Series Integrated Services Router Hardware Installation Guide
- Cisco 800 Series Integrated Services Routers Software Configuration Guide

Other Firmware Code

For information on the firmware used prior to this release, see the *Release Notes for VDSL CPE PHY Release B2pvC038h3_J*.

Obtain Documentation and Submit a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation*.

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the What's New in Cisco Product Documentation RSS feed. The RSS feeds are a free service.

This document is to be used in conjunction with the documents listed in the "Related Documentation" section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2014-2015 Cisco Systems, Inc. All rights reserved.