



Release Notes for Cisco ASR 920 Series Aggregation Services Router, Cisco IOS XE Cupertino 17.9.x

First Published: 2022-12-04

Last Modified: 2023-10-25

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2022–2023 Cisco Systems, Inc. All rights reserved.



CHAPTER 1

Introduction

This release notes contain information about the Cisco ASR 920 Series Aggregation Services Routers, provides new and changed information for these routers, hardware support, limitations and restrictions, and caveats.



Note Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.

- Use faceted search to locate content that is most relevant to you.
- Create customized PDFs for ready reference.
- Benefit from context-based recommendations.

Get started with the Content Hub at content.cisco.com to craft a personalized documentation experience.

Do provide feedback about your experience with the Content Hub.

This release notes provides information for these variants of the Cisco ASR 920 Series Routers:

- ASR-920-12CZ-A
- ASR-920-12CZ-D
- ASR-920-4SZ-A
- ASR-920-4SZ-D
- ASR-920-10SZ-PD
- ASR-920-24SZ-IM
- ASR-920-24SZ-M
- ASR-920-24TZ-M
- ASR-920-12SZ-IM
- ASR-920-12SZ-A
- ASR-920-12SZ-D
- ASR 920-8S4Z-PD
- [Cisco ASR 920 Series Routers Overview, on page 2](#)

- [Feature Navigator](#), on page 2
- [Feature Matrix](#), on page 2
- [Software Licensing Overview](#), on page 2
- [Determining the Software Version](#), on page 3
- [Upgrading to a New Software Release](#), on page 4
- [Supported HoFPGA and ROMMON Versions](#), on page 4
- [Restrictions and Limitations](#), on page 10
- [Additional References](#), on page 11

Cisco ASR 920 Series Routers Overview

The Cisco ASR 920 Series Aggregation Services Routers provide a comprehensive and scalable set of Layer 2 and Layer 3 VPN services in a compact package. They are temperature-hardened, small form factor, with high throughput and low power consumption ideal for mobile backhaul, business services and residential voice, video, and data ("triple-play") applications.

Feature Navigator

Use the Cisco Feature Navigator to find information about feature, platform, and software image support. To access the Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

Feature Matrix

The feature matrix lists the features supported for each platform. For more information, see the [Cisco ASR 920 Series Aggregation Services Routers Feature Compatibility Matrix](#).

The cumulative [Feature Compatibility Release Matrix](#) is available on Content Hub.

Software Licensing Overview

Starting with Cisco IOS XE Cupertino 17.7.1, PAK licenses are no longer available. When you purchase the Cisco IOS XE Cupertino 17.7.1 release or later, Smart Licensing is enabled by default. We recommend that you move to Smart Licensing before upgrading to Cisco IOS XE Cupertino 17.7.1 or a higher release, for a seamless experience.

If you are using Cisco IOS XE Bengaluru 17.6.1 or an earlier release version, Smart Licensing is not enabled by default. To enable Smart Licensing, see [Software Activation Configuration Guide \(Cisco IOS XE ASR 920 Routers\)](#).

The router offers the following base licenses:

- Metro Services
- Metro IP Services
- Advanced Metro IP access

- SDM Video Template

Table 1: Cisco ASR 920 Software Licenses Feature Set

Metro Services	Metro IP Services	Metro Aggregation Services
—	Includes all features in Metro Services	Includes all features in Metro IP Services
QoS, with deep buffers and hierarchical QoS (HQoS)	IP routing (RIP, OSPF, EIGRP, BGP, IS-IS)	MPLS (LDP and VPN)
Layer 2: 802.1d, 802.1q	PIM (SM, DM, SSM), SSM mapping	MPLS TE and FRR
Ethernet Virtual Circuit (EVC)	BFD	MPLS OAM
Ethernet OAM (802.1ag, 802.3ah)	Multi-VRF CE (VRF lite) with service awareness (ARP, ping, SNMP, syslog, trace-route, FTP, TFTP)	MPLS-TP
Multiple Spanning Tree (MST) and Resilient Ethernet Protocol (REP)	IEEE 1588-2008 Ordinary Slave Clock and Transparent Clock	Pseudowire emulation (EoMPLS, CESoPSN, and SAToP)
Synchronous Ethernet	—	VPLS and HVPLS
IPv4 and IPv6 host connectivity	—	Pseudowire redundancy
—	—	MR-APS and mLACP

The router offers the following additional feature licenses:

- ATM
- IEEE 1588-2008 Boundary Clock/Master Clock
- OC-x Port License

Determining the Software Version

Use the following commands to verify your software version:

- Consolidated Package— **show version**

Table 2: ROMMON Version

PIDs	ROMMON
ASR-920-12SZ-A , ASR-920-12SZ-D	15.6(54r)S
ASR-920-12SZ-IM	15.6(54r)S

PIDs	ROMMON
ASR-920-12CZ-A, ASR-920-12CZ-D, ASR-920-4SZ-A, ASR-920-4SZ-D, ASR-920-10SZ-PD, ASR-920-24SZ-IM, ASR-920-24SZ-M, ASR-920-24TZ-M, and ASR920-8S4Z-PD	15.6(56r)S

Upgrading to a New Software Release

Only the latest consolidated packages can be downloaded from Cisco.com; users who want to run the router using individual subpackages must first download the image from Cisco.com and extract the individual subpackages from the consolidated package.

For information about upgrading to a new software release, see the .

Upgrading the FPD Firmware

FPD Firmware packages are bundled with the software package. FPD upgrade is automatically performed on the router.

If you like to manually change the FPD Firmware software, use the **upgrade hw-module subslot 0/0 fpd bundle** to perform FPD firmware upgrade.

Supported HoFPGA and ROMMON Versions

The tables below list the HoFPGA and ROMMON version of the software releases.

Table 3: HoFPGA and ROMMON Versions for the Cisco ASR-920-12CZ-A, ASR-920-12CZ-D, ASR-920-4SZ-A, ASR-920-4SZ-D, ASR-920-10SZ-PD, and ASR 920-8S4Z-PD

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Amsterdam 17.1.x	0X00040043 (BFD/default template) 0x00020009 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.3.1	0X00020009	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X00020009	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00040044 (BFD/default template)	15.6(44r)S
Cisco IOS XE Bengaluru 17.5.1	0X00040044 (BFD/default template)	15.6(44r)S
Cisco IOS XE Bengaluru 17.6.1	0X00040044	15.6(48r)S

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Bengaluru 17.6.2	0X00040044	15.6(48r)S
Cisco IOS XE Cupertino 17.7.1	0X00040044	15.6(48r)S
Cisco IOS XE Cupertino 17.8.1	0X00040044	15.6(48r)S
Cisco IOS XE Cupertino 17.9.1	0X00040044	15.6(56r)S
Cisco IOS XE Cupertino 17.9.2a	0X00040044	15.6(56r)S
Cisco IOS XE Cupertino 17.9.3	0X00040044	15.6(56r)S
Cisco IOS XE Cupertino 17.9.4	0X00040044	15.6(56r)S
Cisco IOS XE Cupertino 17.9.5a	0X00040044	15.6(56r)S

Table 4: HoFPGA and ROMMON Versions for the Cisco ASR-920-24SZ-IM, ASR-920-24SZ-M, and ASR-920-24TZ-M

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Amsterdam 17.1.x	0x00030014 (BFD/default template) 0x00030014 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.3.1	0X00030014	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X00030014	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00030016	15.6(44r)S
Cisco IOS XE Bengaluru 17.5.1	0X00040019	15.6(44r)S
Cisco IOS XE Bengaluru 17.6.1	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.2	0X0004001b	15.6(48r)S
Cisco IOS XE Cupertino 17.7.1	0X0004001b	15.6(48r)S
Cisco IOS XE Cupertino 17.8.1	0X0004001b	15.6(48r)S
Cisco IOS XE Cupertino 17.9.1	0X0004001b	15.6(56r)S
Cisco IOS XE Cupertino 17.9.2a	0X0004001b	15.6(56r)S
Cisco IOS XE Cupertino 17.9.3	0X0004001b	15.6(56r)S
Cisco IOS XE Cupertino 17.9.4	0X0004001b	15.6(56r)S
Cisco IOS XE Cupertino 17.9.5a	0X0004001b	15.6(56r)S

Table 5: HoFPGA and ROMMON Versions for the Cisco ASR-920-12SZ-IM

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Amsterdam 17.1.x	0x0003001B (BFD/default template) 0x00020008 (Netflow template)	15.6(24r)S
Cisco IOS XE Amsterdam 17.3.1	0X0003001b	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X0003001b	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X0003001e	15.6(43r)S
Cisco IOS XE Bengaluru 17.5.1	0X0003001e	15.6(43r)S
Cisco IOS XE Bengaluru 17.6.1	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.2	0X0003001e	15.6(46r)S
Cisco IOS XE Cupertino 17.7.1	0x0003001e	15.6(46r)S
Cisco IOS XE Cupertino 17.8.1	0x0003001e	15.6(46r)S
Cisco IOS XE Cupertino 17.9.1	0X0003001e	15.6(54r)S
Cisco IOS XE Cupertino 17.9.2a	0X0003001e	15.6(54r)S
Cisco IOS XE Cupertino 17.9.3	0X0003001e	15.6(54r)S
Cisco IOS XE Cupertino 17.9.4	0X0003001e	15.6(54r)S
Cisco IOS XE Cupertino 17.9.5a	0X0003001e	15.6(54r)S

Table 6: HoFPGA and ROMMON Versions for the Cisco ASR-920-12SZ-A and ASR-920-12SZ-D

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Amsterdam 17.1.x	0x00010039 (BFD/default template) 0x10000007 (Netflow template)	15.6(29r)S
Cisco IOS XE Amsterdam 17.3.1	0X10000008	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X10000008	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00010040 (BFD/default template)	15.6(43r)S
Cisco IOS XE Bengaluru 17.5.1	0X10000008	15.6(43r)S
Cisco IOS XE Bengaluru 17.6.1	0X10000008	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.2	0X00020043	15.6(46r)S

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Cupertino 17.7.1	0X00020043	15.6(46r)S
Cisco IOS XE Cupertino 17.8.1	0X00020043	15.6(46r)S
Cisco IOS XE Cupertino 17.9.1	0X10000008	15.6(54r)S
Cisco IOS XE Cupertino 17.9.2a	0X10000008	15.6(54r)S
Cisco IOS XE Cupertino 17.9.3	0X10000008	15.6(54r)S
Cisco IOS XE Cupertino 17.9.4	0X10000008	15.6(54r)S
Cisco IOS XE Cupertino 17.9.5a	0X10000008	15.6(54r)S

Table 7: IM FPGA Versions for the Cisco ASR-920-24SZ-IM

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Amsterdam 17.1.x	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.1	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.2	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.4.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.5.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.6.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.2	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.7.1	0.75	69.24	0.54	0.54	0.46

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Cupertino 17.8.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.2a	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.3	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.4	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.5a	0.75	69.24	0.54	0.54	0.46

Table 8: IM FPGA Versions for the Cisco ASR-920-12SZ-IM

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Amsterdam 17.1.x	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.1	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.2	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.4.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.5.1	0.75	N/A	N/A	0.54	0.46

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Bengaluru 17.6.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.2	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.7.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.8.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.2a	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.3	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.4	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Cupertino 17.9.5a	0.75	69.24	0.54	0.54	0.46

Restrictions and Limitations



Note The error message "PLATFORM-1-NOSPACE: SD bootflash : no space alarm assert" may occur in the following scenarios:

- Any sector of SD Card gets corrupted
- Improper shut down of router
- power outage.

This issue is observed on platforms which use EXT2 file systems.

We recommend performing a reload of the router. As a result, above alarm will not be seen during the next reload due to FSCK(file systems check) execution.

However, If the error persists after a router reload, we recommend to format the bootflash or FSCK manually from IOS.

-
- Embedded Packet Capture (EPC) is not supported on ASR 920 routers.
 - The **default** *command-name* command is used to default the parameters under that interface. However, when speed is configured on the interface, the following error is displayed:

```
Speed is configured. Remove speed configuration before enabling auto-negotiation
```
 - For VCoP, only SFP-T3F-SATOP-I is supported.
 - Adding or deleting the Trunk Ethernet flow points (TEFPs) with scaled bridge-domain, without delay causes the Cisco ASR 920 Series router to crash.
 - Virtual services should be deactivated and uninstalled before performing replace operations.
 - The Cisco ASR920 Series Routers no longer support the controller and nid-controller commands for the Cisco ME1200 switch.
 - The following interface modules (IMs) do not require the activation command for IM boot up, provided no other IM is activated in subslot 0/1 before.

However, if an IM was activated in the system earlier, deactivate the previously-activated IM before inserting a new IM in system.

- 16-Port T1/E1 Interface Module
- 32-Port T1/E1 Interface Module
- 8-Port T1/E1 Interface Module
- 4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module
- 14-Port Serial Interface Module
- 6-Port E and M Interface Module
- 4-Port C37.94 Interface Module

- RS422 works on ports from 0 to 7 only.
- The frame drops may occur for packets with packet size of less than 100 bytes, when there is a line rate of traffic over all 1G or 10G interfaces available in the system. This restriction is applicable only on RSP2 module, and is not applicable for RSP3 module.
- MPLS VC label packet with time-to-live (TTL) value of 2 is dropped at egress MPLS PE device due to ASIC limitations. During PHP process, MPLS TTL value for the VC label is decremented by one with implicit-null. The VC label-related TTL value is set to 255 while imposing the VC label due to multiple VC switching scenarios.

Use the **no mpls ip propagate-ttl** command as the Short Pipe mode for the required label.

- Interface naming is from right to left. For more information, see the Cisco ASR 920 Software Configuration Guide .
- Packet size greater than 1460 is not supported over IPsec Tunnel.
- Minimal traffic drop might be seen for a moment when higher rate traffic is sent through the IPsec tunnels for the first time.
- One Ternary Content-Addressable Memory (TCAM) entry is utilized for Segment Routing Performance Measurement. This is required for the hardware timestamping to function.
- While performing an auto upgrade of ROMMON, only primary partition is upgraded. Use the **upgrade rom-mon filename** command to upgrade the secondary partition of the ROMMON. However, the router can be reloaded during the next planned reload to complete the secondary ROMMON upgrade.
- Some router models are not fully compliant with all IETF guidelines as exemplified by running the pyang tool with the lintflag. The errors and warnings exhibited by running the pyang tool with the lint flag are currently non-critical as they do not impact the semantic of the models or prevent the models from being used as part of the toolchains. A script is provided, **check-models.sh**, which runs pyang with lint validation enabled, but ignoring certain errors. This allows the developer to determine what issues may be present.
- If IPv6 Global IP is configured as the BFD peer, and if the interface goes down, a VRRP flap may occur. This may occur because, VRRP works on the basis of Link-local IP and not global IP. As a result, VRRP flaps on the previously backed up device and prints a DAD message.

Additional References

Product Information

- [Cisco ASR 920 Series Aggregation Services Router Data Sheets](#)

Hardware Installation Guides

- [Cisco ASR 920 Series Aggregation Services Router Hardware Guides](#)

Software Configuration Guides

- [Cisco ASR 920 Series Aggregation Services Router Configuration Guides](#)

Regulatory Compliance and Safety Information

- [Regulatory Compliance and Safety Information for the Cisco ASR 920 Series Aggregation Services Routers](#)

Field Notices and Bulletins

- Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.
- Bulletins—You can find bulletins at http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html.

MIB Support

To view supported MIB, go to <http://tools.cisco.com/ITDIT/MIBS/MainServlet>.

Accessibility Features in the Cisco ASR 920 Series Routers

For a list of accessibility features in Cisco ASR 920 Series Routers, see the [Voluntary Product Accessibility Template \(VPAT\)](#) on the Cisco website, or contact accessibility@cisco.com.

All product documents are accessible except for images, graphics, and some charts. If you would like to receive the product documentation in audio format, braille, or large print, contact accessibility@cisco.com.

End-of-Life and End-of-Sale Notices

For End-of-Life and End-of-Sale Notices for the Cisco ASR 920 Series Routers, see <http://www.cisco.com/c/en/us/products/routers/asr-920-series-aggregation-services-router/eos-eol-notice-listing.html>.



CHAPTER 2

What's New in Cisco IOS XE Cupertino 17.9.x

This chapter describes the new hardware and software features supported on the Cisco ASR 920 Series routers in Cisco IOS XE Cupertino 17.9.x.

For information on features supported for each release, see [Feature Compatibility Matrix](#).

- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.5a, on page 13](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.5a, on page 13](#)
- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.4a, on page 13](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.4a, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.4, on page 14](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.4, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.3, on page 14](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.3, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.2a, on page 14](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.2a, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Cupertino 17.9.1, on page 14](#)
- [What's New in Software for Cisco IOS XE Cupertino 17.9.1, on page 14](#)

What's New in Hardware for Cisco IOS XE Cupertino 17.9.5a

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.5a

There are no new software features in this release.

What's New in Hardware for Cisco IOS XE Cupertino 17.9.4a

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.4a

There are no new features in this release. This release provides a fix for CSCwh87343: Cisco IOS XE Software Web UI Privilege Escalation Vulnerability. For more information, see [cisco-sa-iosxe-webui-privesc-j22SaA4z](#).

What's New in Hardware for Cisco IOS XE Cupertino 17.9.4

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.4

There are no new software features in this release.

What's New in Hardware for Cisco IOS XE Cupertino 17.9.3

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.3

There are no new software features in this release.

What's New in Hardware for Cisco IOS XE Cupertino 17.9.2a

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.2a

There are no new software features in this release.

What's New in Hardware for Cisco IOS XE Cupertino 17.9.1

There are no new hardware features in this release.

What's New in Software for Cisco IOS XE Cupertino 17.9.1

Feature	Description
Cisco ASR 920 Series Aggregation Services Router	

Feature	Description
Custom Idle Pattern	<p>You can configure idle pattern manually on CEM circuits and verify if it's stable and transmitted to the other end in alarm conditions. You can configure on all CEM PWs in a T1/E1 circuit.</p> <p>Supported on the following IMs on CESoPSN circuits with both partial and full time slots.</p> <ul style="list-style-type: none"> • 48-port T1/E1 CEM Interface Module • 48-port T3/E3 CEM Interface Module <p>These idle pattern numbers are used for tracking purposes.</p>
Carrier Ethernet	
Application of QoS Policies on ITU-T Y.1731 Egress Packets	<p>You can now apply QoS policies on Y.1731 egress packets. Operations, Administration, and Maintenance (OAM) functions and mechanisms for Ethernet-based networks are defined in ITU-T Y.1731. With this implementation, you can prioritize OAM traffic; for example, prioritizing operational information used to detect faults and determining network performance.</p>
Layer 2 Control Protocol Enhancements	<p>Layer 2 Control Protocols (L2CP) propagate the MAC address control information to determine which parts of a network the router should forward, tunnel, peer, or discard information.</p> <p>This release supports forward and discard options for the following protocols:</p> <ul style="list-style-type: none"> • MRP Block • Cisco BPDU • Cisco STP UplinkFast • Cisco CFM
MPLS Basic	
Support for Co-routed Inter-area Flex-LSP Tunnels	<p>Flex LSPs (also called Associated Bidirectional LSPs) now support inter-area co-routed tunnels. With this implementation, we meet the specific requirements of network operators to create on-demand tunnels by defining an explicit path across different areas.</p>
System Logging	
No Service Password Recovery	<p>This feature provides additional security by removing all user files from bootflash during factory reset. It prevents the malicious users from accessing configuration files stored in bootflash.</p> <p>This feature is only supported on Cisco ASR 920-10SZ-PD, Cisco ASR-920-12CZ-A/D, Cisco ASR-920-4SZ-A/D, Cisco ASR-920-12SZ-IM, ASR-920U-12SZ-IM, Cisco ASR-920-24SZ-IM, Cisco ASR-920-24SZ-M, and Cisco ASR-920-24TZ-M routers.</p>
Upgrading the Software on the Cisco ASR 920 Series Routers	

Feature	Description
Support for Firmware Upgrade	This release introduces the firmware upgrade support for ASR 920-10SZ-PD and Cisco ASR-920-24SZ-IM, Cisco ASR-920-24SZ-M, and Cisco ASR-920-24TZ-M routers.
YANG Model Support for QoS Service Group	Cisco YANG now supports QoS Service Groups. Service-Groups allow you to add service instances to groups and apply service policies. You can configure the definition of the service-group and apply the service-group to an interface. With this implementation, you can quickly deploy QoS mechanisms, such as creating a class for email traffic.
IPv6: RFC 8200 Compliance	Improvements have been made to the Cisco IOS XE platforms to maintain compliance with IETF standards as specified for the Internet Protocol, Version 6 (IPv6) in RFC 8200 . The enhancements bring in improved security and better handling of IP packets with fragments.
TPoP T1/E1 clock status display update	Starting with release Cisco IOS XE Cupertino 17.9.1, TPoP T1/E1 clock status is accurately displayed in the recovered clock status output.
Show Tech-Support Enhancements	
Show Tech-Support Enhancements	The show tech-support now supports generic commands to provide better debuggability. The show tech-support platform cef command now displays IPv4 address information. For more information, see Cisco IOS Configuration Fundamentals Command Reference .



CHAPTER 3

Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.5a, on page 17](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.5a, on page 18](#)
- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.4a, on page 18](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.4a, on page 18](#)
- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.4, on page 18](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.4, on page 19](#)
- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.3, on page 19](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.3, on page 19](#)
- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.2a, on page 20](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.2a, on page 20](#)
- [Open Caveats – Cisco IOS XE Cupertino 17.9.1, on page 21](#)
- [Resolved Caveats – Cisco IOS XE Cupertino 17.9.1, on page 21](#)
- [Cisco Bug Search Tool, on page 21](#)

Resolved Caveats – Cisco IOS XE Cupertino 17.9.5a

Identifier	Headline
CSCwf07736	cem interface counters momentarily report error when x21 xconnect is cleared and re-established

Identifier	Headline
CSCwi41800	Block end users from removing a GRANDPARENT policy-map if the policy-map is attached to an interface
CSCwb01284	ASR 900 Series PTP Sync degraded on Tester after primary PTP source failover to secondary
CSCwe24919	RJIL ASR-920 issue: both Power Supply is showing fail state while LED is Green

Open Caveats – Cisco IOS XE Cupertino 17.9.5a

Identifier	Headline
CSCwd46121	Time stamp issue on Transparent clock for 1G PORTS
CSCwd23704	ASR920: Warning message seen on enabling scaleipv6 sdm template.
CSCwd89451	ASR920/NCS4202 doesn't forward IPv6 packets with src address 0:0:0:0:0:0:1111

Resolved Caveats – Cisco IOS XE Cupertino 17.9.4a

Identifier	Headline
CSCwh87343	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability

Open Caveats – Cisco IOS XE Cupertino 17.9.4a

There are no open caveats in this release.

Resolved Caveats – Cisco IOS XE Cupertino 17.9.4

Identifier	Headline
CSCwe38959	rs232 ASYNC PW service with full scale seeing packet and byte drops intermittently.
CSCwd90840	mcast data traffic is getting dropped over vpls.
CSCwe54549	ASR-920 - SFP not detected due to checksum error.
CSCvy81362	ASR920: Controllers are down due to LP-LOP alarm After CE reboots.

Identifier	Headline
CSCwe34672	in asr920, High CPU on ptp_uea process.
CSCwd67723	In IMA32D/IMA8D card, sometimes change in E1 controller config (after ctrlr flap) results in IM reboot.
CSCwd85267	FR Port mode - show interface CLI does not display FR PW statistics.
CSCwe10460	Power sensor threshold warning alarms in EPNM.

Open Caveats – Cisco IOS XE Cupertino 17.9.4

Identifier	Headline
CSCwd05362	Performance issue on router platform
CSCwd67723	In IMA32D/IMA8D card, sometimes change in E1 controller config (after ctrlr flap) results in IM reboot
CSCwe13024	All readings for Power supply unit reflect as zero though the unit is functional
CSCwe27155	[920] Seen traffic drop with BDI shut (IP_FRR configs)

Resolved Caveats – Cisco IOS XE Cupertino 17.9.3

Identifier	Headline
CSCwc76004	ASR920: wrong timestamp in TWAMP test packet with PTP active
CSCwd57471	Change in BGP ORF prefix-filter not being advertised from XE to XR node
CSCwb77093	next hop self does changes automatically on VRF lite and ipv4
CSCwd06972	IOS-XE 17.x - user password not saved if user attribute list is configured
CSCwd58396	NETCONF: Failed sync between Running configs and Candidate database
CSCwc55520	Traceback and IDB leak noticed when a RSP3 setup performs a switchover

Open Caveats – Cisco IOS XE Cupertino 17.9.3

Identifier	Headline
CSCwc76004	ASR920: wrong timestamp in TWAMP test packet with PTP active

CSCwc93296	ASR-920-10SZ-PD /16.9.4/port Te0/0/10 went admin down after in successive reload
CSCwd76589	BGP On Change Notification not sent for BGP Dynamic Peers
CSCwc03907	ISIS SRLG to BGPLS export problems
CSCwd90908	NTP packets are sent from global VRF with a source IP configured on service VRF interface

Resolved Caveats – Cisco IOS XE Cupertino 17.9.2a

Identifier	Headline
CSCwc84627	ASR-920-12SZ-IM - reboots continuously for a PCIE bus error
CSCwb77396	G.8032: Ring brief output does not display the Block port flag in Idle state
CSCwc21402	Invalid BGP update when add-paths negotiated only for label (SAFI 4) and not unicast (SAFI1)
CSCwc67367	Seeing traffic issues after clearing ISIS with SRTE_ODN_ISIS_Flex_Algo configs

Open Caveats – Cisco IOS XE Cupertino 17.9.2a

Identifier	Headline
CSCwc93296	ASR-920-10SZ-PD /16.9.4/port Te0/0/10 reports admin down after successive reloads
CSCwc79322	ASR-920: Memory leak on ptpd_uea process
CSCwd46121	Time stamp issue on Trasparanet clock for 1G PORTS process
CSCwc54860	EIGRP down authentication issues after upgrading from 17.3 to 17.6
CSCwc03907	ISIS SRLG to BGPLS export problems
CSCwc23316	Command "show snmp mib ifmib ifindex detail [IntName]" truncated when is more than 32 characters
CSCwc54860	EIGRP down authentication issues after upgrading from 17.3 to 17.6
CSCwc03907	ISIS SRLG to BGPLS export problems
CSCwc23316	Command "show snmp mib ifmib ifindex detail [IntName]" truncated when is more than 32 characters

Open Caveats – Cisco IOS XE Cupertino 17.9.1

Identifier	Headline
CSCwb78907	DS3_RX_RAI is shown in both facility-alarm and facility-condition status commands

Resolved Caveats – Cisco IOS XE Cupertino 17.9.1

Identifier	Headline
CSCwa33548	We observed traffic issue with latest labels and bi-directional traffic is not working and drop is seen
CSCvy78284	Router crashes when zeroised RSA key is regenerated
CSCwa52959	TPOP T1/E1 : Clock status to be corrected for alarm condition
CSCwa16189	SNMP traps are seen continuously in SNMP server with MPLS-TE configuration
CSCvz65726	Post SSO with Qos OHA counters stop works
CSCvv16943	Uea-iomd phase2 IM FPD upgrade commit to polaris_dev
CSCvw17894	Exception for weak algorithm options for SNMP does not work
CSCwb01224	Multihop BFD transit packets getting droppedn on router after upgrade to 17.3.3
CSCwb01940	Router drops L2 multicast traffic upon REP topology change
CSCwa41638	Router MAC Table and L2VPN EVPN Table out of sync

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>

