



Release Notes for Cisco Intersight Infrastructure Firmware, Release 4.2

First Published: 2023-09-26

Last Modified: 2024-04-17

Overview

Introduction

Cisco Intersight Infrastructure Services (IIS) enable the streamlined deployment, monitoring, management, and support of physical and virtual infrastructure. IIS supports Cisco Unified Computing System™ (UCS) servers and third-party devices. In addition, IIS provides the following advanced management and support capabilities along with global visibility of infrastructure health and status.

Intersight Managed Mode (IMM) is a new IIS architecture that manages the UCS Fabric Interconnected systems through a Redfish-based standard model. IMM unifies the capabilities of the UCS Systems and the cloud-based flexibility of Intersight, thus unifying the management experience for the standalone and Fabric Interconnect attached systems.

About the Release Notes

This document contains information on new features, resolved caveats, open caveats, and workarounds for following components:

- FI kernel and system
- Chassis IOM and IFM I/O modules

This document also includes the following:

- Updated information after the documentation was originally published.
- Related firmware and BIOS on blade, rack, and modular servers and other Cisco Unified Computing System (UCS) components associated with the release.

Revision History

The following table shows the online change history for this document.

Revision Date	Description
April 17, 2024	Updated the Cross Version Firmware Support table.
February 22, 2024	Created release notes for Intersight Infrastructure Firmware Release 4.2(3j).

Revision Date	Description
September 29, 2023	Created release notes for Intersight Infrastructure Firmware Release 4.2(3h).
July 24, 2023	Created release notes for Intersight Infrastructure Firmware Release 4.2(3g).
May 17, 2023	Created release notes for Intersight Infrastructure Firmware Release 4.2(3e).
March 27, 2023	Created release notes for Intersight Infrastructure Firmware Release 4.2(3d).
March 16, 2023	Updated release notes to include supported hardware information for every Intersight Infrastructure Firmware release.
January 20, 2023	Updated release notes for Intersight Infrastructure Firmware Release 4.2(2a) and 4.2(1n).
January 12, 2023	Created release notes for Intersight Infrastructure Firmware Release 4.2(3c).
January 10, 2023	Updated release notes for Intersight Infrastructure Firmware Release 4.2(3b).
August 04, 2022	Created release notes for Intersight Infrastructure Firmware Release 4.2(2b).
February 15, 2022	Created release notes for Intersight Infrastructure Firmware Release 4.2(1l).

New Features in Release

New Hardware Features in Infra Firmware Releases

New Hardware Support in 4.2(3j) — None

New Hardware Support in 4.2(3c)

Support for the following IOM in Intersight Managed Mode:

- UCS-IOM-2304
- UCS-IOM-2304V2



Note The above two IOM are supported only with Cisco UCS 6500 series Fabric Interconnect and require CMC Firmware version 4.2(2.30) or above.

For more information, see [Supported Hardware for Intersight Managed Mode](#).

New Hardware Support in 4.2(3b)



- Note**
- Cisco UCS X210c M7 Compute Node requires Server Firmware Version 5.1(0.230096) and Cisco Intersight Infrastructure Firmware version 4.2(3b) or above.
 - Cisco UCS C220 M7 and C240 M7 servers require Server Firmware Version 4.3(1.230097) and Cisco Intersight Infrastructure Firmware version 4.2(3b) or above.

For more information, see [Supported Hardware for Intersight Managed Mode](#).

New Hardware Support in 4.2(2b)

Support for the following:

- Support for Cisco UCS-FI-6536 Fabric Interconnect.
- Support for Cisco UCSX-I-9108-100G Intelligent Fabric Module (IFM).
- Support for Cisco UCSX-440P PCIe Node.

For more information, see [Supported Hardware for Intersight Managed Mode](#).

New Hardware Support in 4.2(1e)

Cisco UCS X9508 Chassis

The Cisco UCS X-Series Modular System begins with the Cisco UCS X9508 Chassis engineered to be adaptable and future ready. With a midplane-free design, I/O connectivity for the X9508 chassis is accomplished with frontloading, vertically oriented compute nodes intersecting with horizontally oriented I/O connectivity modules in the rear of the chassis. A unified Ethernet fabric is supplied with the Cisco UCS 9108 Intelligent Fabric Modules.

- 7-Rack-Unit (7RU) chassis has 8x front-facing flexible slots. These can house a combination of compute nodes and a pool of future I/O resources that may include GPU accelerators, disk storage, and nonvolatile memory.
- 2x Cisco UCS 9108 Intelligent Fabric Modules (IFMs) at the top of the chassis that connect the chassis to upstream Cisco UCS 6400 Series Fabric Interconnects. Each IFM features:
 - Up to 100 Gbps of unified fabric connectivity per compute node
 - 8x 25-Gbps SFP28 uplink ports.
- Six 2800W Power Supply Units (PSUs) provide 54V power to the chassis with N, N+1, and N+N redundancy.
- Efficient, 4x100mm, dual counter-rotating fans deliver industry-leading airflow and power efficiency.

Cross Version Firmware Support

An IMM Server firmware in a domain is supported with a specific IMM Infrastructure firmware version.

The following table shows the supported Server and Infrastructure firmware combinations within an IMM domain. Any additional Infrastructure firmware restrictions are highlighted as a note in the specific [New Hardware Support](#) section.

X-Series Server Firmware Version	Infrastructure Firmware Version		
	4.2(1)	4.2(2)	4.2(3)
5.1(1)	No	No	Yes
5.1(0)	No	No	Yes
5.0(4)	Yes	Yes	Yes
5.0(2)	Yes	Yes	Yes
5.0(1)	Yes	Yes	Yes

C-Series Server Firmware Version	Infrastructure Firmware Version		
	4.2(1)	4.2(2)	4.2(3)
4.3(1)	Yes	Yes	Yes
4.2(3)	Yes	Yes	Yes
4.2(2)	Yes	Yes	Yes
4.2(1)	Yes	Yes	Yes
4.1(3)	Yes	Yes	Yes

B-Series Server Firmware Version	Infrastructure Firmware Version		
	4.2(1)	4.2(2)	4.2(3)
5.1(0)	Yes	Yes	Yes
4.2(3)	Yes	Yes	Yes
4.2(2)	Yes	Yes	Yes
4.2(1)	Yes	Yes	Yes
4.1(3)	Yes	Yes	Yes

Security Fixes

Caveats

The open and resolved bugs for a release are accessible through the [Cisco Bug Search Tool](#). This web-based tool provides you with access to the Cisco bug tracking system, which maintains up-to-date information about bugs and vulnerabilities in this product and other Cisco hardware and software products.

For more information about the Cisco Bug Search Tool, see the [Bug Search Tool Help & FAQ](#).

Resolved Caveats

Resolved Caveats in Release 4.2(3j)

The following table lists the resolved caveats in release 4.2(3j)

Defect ID	Description	First Bundle Affected
CSCwf93621	During the ComputeRackUnitDiscover:OobStorageConfig process on Cisco UCS C240 M5SX servers, the discovery or association often failed with an error message <i>Remote-Invocation-Error: Waiting for storage subsystem to initialize</i> . This issue was observed following the server firmware upgrade to 4.2(3d) and appeared to affect servers using 3.8Tb or 7.6Tb drives.	4.2(3d)C
CSCwe96606	Cisco UCS 6454 Fabric Interconnect displayed <i>svc_sam_samcproxy</i> process failure messages.	4.2(3d)A
CSCwh86319	The Cisco UCS 6400 series and 6500 series Fabric Interconnects operating on 4.3(2.230117) version observed persistent issues of storage space exhaustion and firmware upgrade failures.	4.3(2.230117)
CSCwd15750	In a setup equipped with Cisco UCS 6454 Fabric Interconnects, reboots during auto-install, without user acknowledgement. This issue was observed during the upgrade process of the infrastructure firmware from version 4.1(3e)A to version 4.2(1i)A.	4.1(3e)A
CSCwe95417	After upgrading Cisco UCS 6332-16UP Fabric Interconnects to Infrastructure Firmware 4.2(2c)A, chassis power chart shows abnormal readings.	4.2(2c)A
CSCwe88483	Cisco UCS 6454 Fabric Interconnect crash due to Machine Check Exception (MCE) errors.	4.2(2c)A
CSCwi54393	In a setup with Linux OS, some LUNs do not get mounted when the setup is starting boot time with PXE boot along with lot of SAN LUNs.	4.1(3b)

Resolved Caveats in Release 4.2(3h)

The following caveats are resolved in Release 4.2(3h):

Defect ID	Symptom	First Bundle Affected
CSCwf61835	In a setup equipped with Cisco UCS 15000 Series VIC adapters and ESXi OS, the adapters may become unreachable and be in hung state. Internal PO goes down and the backplane connection link also shows as link down. All the vNICs/vHBAs are also in a down state.	4.2(2a)

Defect ID	Symptom	First Bundle Affected
CSCwf52054	Cisco UCS 2200/2300/2400 IOMs may go offline after upgrading to release 4.2(3d).	4.2(3d)
CSCwe98053	CRC errors are seen in a setup equipped with Cisco UCS 2408 IOM connected to Cisco UCS B-Series server HIF ports.	4.2(2a)
CSCwh15315	Third-party SFP goes into unsupported state after upgrading to release 4.2(2a) or later.	4.2(2a)
CSCwf92065	SNMP configuration does not restore in NXOS after SNMPD restart.	4.2(2c)
CSCwf73403	On a Cisco UCS 6454 Fabric Interconnect, on initial boot or after an erase configuration, the fabric interconnect did not boot to the initial configuration prompt. After finishing boot, the fabric interconnect showed a login prompt with the default hostname of switch.	4.2(3b)

Resolved Caveats in Release 4.2(3g)

The following table lists the resolved caveats in release 4.2(3g)

Defect ID	Description	First Bundle Affected
CSCwe45912	In a cluster setup with Cisco UCS 6400 series FI or 6536 FI, after a server reboot, if the MAC address is learned through the impacted FI, then the ARP is unable to resolve on any OS. This issue does not impact the servers, which are not rebooted.	4.2(1i)
CSCwf05062	Cisco UCS 6454 FI crashes and recovers due to following error: <pre>%SYSMGR-2-SERVICE_CRASHED: Service "mfdm" (PID 15518) hasn't caught signal 6 (core will be saved). %\$ VDC-1 %\$ %SYSMGR-2-HAP_FAILURE_SUP_RESET: Service "mfdm" in vdc 1 has had a hap failure</pre>	4.2(1d)
CSCwf44680	In a setup equipped with Cisco UCS 6454 FI, when IP Unicast/Subnet-broadcast packet destined to Link-Layer broadcast is received over Mgmt port of FI, the packet is routed over Mgmt0 Interface. This results in FI sending back the received packet with the Mgmt0 source MAC address leading to upstream device on the network detecting the same destination IP address with a different source MAC address.	4.2(3e)

Resolved Caveats in Release 4.2(3e)

The following table lists the resolved caveats in release 4.2(3e)

Defect ID	Description	First Bundle Affected
CSCwe07549	<p>iSCSI LUN discovery fails for servers in Intersight Managed Mode with CHAP Authentication enabled.</p> <p>A X210c M6 Compute Node was configured with iSCSI profile with Challenge Handshake Authentication Protocol (CHAP) authentication enabled. On rebooting the server, iSCSI boot LUN in BIOS is not found. Even though CHAP is enabled in iSCSI boot profile of Intersight from BIOS in iSCSI configuration, it is observed that Authentication mode appears as none.</p>	4.2(11)

Resolved Caveats in Release 4.2(3d)

The following table lists the resolved caveats in release 4.2(3d)

Defect ID	Description	First Bundle Affected
CSCwd41247	Multiple instances of hung Samcproxy is observed in a setup equipped with Cisco UCS 6400 FI. There may also be other miscellaneous faults on the domain related to Samcproxy being in a bad state.	4.2(3c)
CSCwe24011	Unexpected reboot is observed during normal operation in Cisco UCS 6536 FI and Cisco UCS 6400 FI series FIs.	4.2(3c)
CSCwd90187	<p>In a setup equipped with Cisco UCS 6536 FI, port goes to Link not connected status when QSFP-100G-DR/FR-S is replaced with QSFP-100G-CUxM under the following conditions:</p> <ul style="list-style-type: none"> • 100G interface <ul style="list-style-type: none"> • Interface is configured with FEC Auto • Interface was using QSFP-100G-FR, QSFP-100G-DR transceivers Interface now uses QSFP-100G-CUxM, where CUxM refers to CU1M, CU2M, and so on. 	4.2(3c)
CSCwe28336	<p>MTS buffer stuck on vsh.bin process.</p> <p>The process crashes and impacts other functionality once the limit is reached.</p>	4.2(3c)
CSCwe28336	In a setup equipped with Cisco UCS 6400 FI, Multicast streams are not accepted by the server.	4.2(3c)

Resolved Caveats in Release 4.2(3c)

The following table lists the resolved caveats in release 4.2(3c)

Defect ID	Description	First Bundle Affected
CSCwd86029	While upgrading the Infrastructure firmware from 4.2(1d) to 4.2(2a), 4.2(3b), or 4.2(3c) release, if there is a time lag between two IFM upgrades, Redfish query fails on one of the IFM during this time interval. It may be seen as a connection failure in IMM.	4.2(2c)

Resolved Caveats in Release 4.2(3b)

The following table lists the resolved caveats in release 4.2(3b)

Defect ID	Description	First Bundle Affected
CSCwd37309	In a UCS X-Series Chassis, using the fan UCSX-9508-FAN, an alert is seen stating "[Chassis fan module] has a critical speed threshold condition". This behavior may be seen on multiple chassis and may occur on different fan modules. A fault gets raised and then gets cleared on its own. The issue is observed during LOW fan speed conditions. If the fault persists and does not clear on its own, physically re-seat the fan. If the fault persists even after re-seating, reach out to Cisco TAC as it could potentially indicate a separate problem.	4.2(11)

Resolved Caveats in Release 4.2(2d)

The following table lists the resolved caveats in release 4.2(2d)

Defect ID	Description	First Bundle Affected
CSCwd37309	In a UCS X-Series Chassis, using the fan UCSX-9508-FAN, an alert is seen stating "[Chassis fan module] has a critical speed threshold condition". This behavior may be seen on multiple chassis and may occur on different fan modules. A fault gets raised and then gets cleared on its own. The issue is observed during LOW fan speed conditions. If the fault persists and does not clear on its own, physically re-seat the fan. If the fault persists even after re-seating, reach out to Cisco TAC as it could potentially indicate a separate problem.	4.2(11)

Resolved Caveats in Release 4.2(1n)

The following table lists the resolved caveats in release 4.2(1n)

Defect ID	Description	First Bundle Affected
CSCwb90201	In Cisco UCS 6500 Series FI, extra member port in uplink port fails to forward the broadcast traffic. This happens because the Fibre Channel over Ethernet (FCoE) member port gets incorrectly included in the uplink port.	4.2(11)

Defect ID	Description	First Bundle Affected
CSCwb00770	In Cisco UCS 6500 Series FI, the fabric port fails to forward the unicast traffic in the UDP port range 100-150	4.2(11)
CSCwb43580	FI switch link with QSFP-40G-LR4 status appears as Up for more than a minute even after shutting the remote end port or pulling the cable. FI switch is connected to C-Series server with Cisco 1400 Series adapter.	4.2(11)
CSCwb07198	For Cisco UCS 6500 Series FI, IGMP 16k limit notification is seen on Syslog even on sending only one igmp join from Appliance server to FI.	4.2(11)
CSCwb73274	A convergence time of more than 100 sec is observed for IP multicast traffic during fabric failover. This is observed when 3K VLAN on FI and N9K with Snoop Enabled are configured on all VLAN. More than 5 querier are configured on N9K on different VLANs. Three groups are joined on different VLAN from different Host/Servers.	4.2(11)
CSCwb78536	Fiber Channel Storage port is stuck at Init after FI reboot. The port is connected to 32G Netapp and FCoE traffic is sent to it before the reboot of Fabric Interconnect B.	4.2(11)
CSCwb64509	snmpd_log core is affected when FI is rebooted after enabling FC uplink port and breakout interfaces.	4.2(11)

Resolved Caveats in Release 4.2(11)

The following table lists the resolved caveats in release 4.2(11)

Defect ID	Description	First Bundle Affected
CSCvz92352	The Intelligent Fabric Management (IFM) experiences reboot loop due to a faulty Power Supply Unit in the chassis. A faulty PSU is indicated by non solid green PSU LED.	4.2(2a)

Open Caveats

Open Caveats for Release 4.2(3j) — None

Open Caveats for Release 4.2(3c)

The following caveats are open in Release 4.2(3c):

Defect ID	Symptom	Workaround	First Bundle Affected
CSCwd52370	<p>After upgrading the firmware of the Fabric Interconnect in UCSB-5108-AC2 chassis with UCS-IOM-2408, connection to Intersight is lost.</p> <p>Port flaps cause the CMC to unset its chassis information, which removes the useful information from /var/isconfig. When chassis info is again set, the CMC DC may not re-read the /var/isconfig file after it is again populated with its data, causing the CMC to be disconnected from Intersight.</p>	Restart CMC DC (/etc/init.d/dc restart)	4.2(2c)

Open Caveats for Release 4.2(2a)

The following caveats are open in Release 4.2(2a):

Defect ID	Symptom	Workaround	First Bundle Affected
CSCwd82136	<p>In a setup equipped with Cisco UCS 6400 series FI connected to Cisco UCS C-Series servers using Cisco VIC 1457/1455/1467, ports on the FI may go to error-disabled state with errDisabledExcessportIn reason after a link flap.</p>	Flap the FI port connected to the Cisco UCS C-Series servers.	4.2(2a)

Defect ID	Symptom	Workaround	First Bundle Affected
CSCwd90187	<p>In a setup equipped with Cisco UCS 6536 FI, port goes to Link not connected status when QSFP-100G-DR/FR-S is replaced with QSFP-100G-CUxM under the following conditions:</p> <ul style="list-style-type: none"> • 100G interface • Interface is configured with FEC Auto • Interface was using QSFP-100G-FR, QSFP-100G-DR transceivers <p>Interface now uses QSFP-100G-CUxM, where CUxM refers to CU1M, CU2M, and so on.</p>	<p>There are two workarounds for this issue:</p> <ul style="list-style-type: none"> • Perform the following steps: <ol style="list-style-type: none"> 1. Insert an optic or AOC transceiver that does not have FEC capability. For example, QSFP-100G-SR or QSFP-100G-AOC3M on the interface. 2. Remove the transceiver in Step 1. 3. Re-insert passive copper cable. • Reboot the FI. 	4.2(2a)

Related Documentation

Release Notes

- [Release Notes and Release Bundles for Cisco Intersight](#)
- [Release Notes for Cisco UCS Manager](#)
- [Release Notes for Cisco Integrated Management Controller](#)