



# Cisco TelePresence Video Communication Server X8.9.1

## Release Notes

**First Published: December 2016**

**Last Updated: February 2017**

## Contents

Preface .....	2
Change History .....	2
Supported Platforms .....	2
Product Documentation .....	4
Changes and Features in X8.9.1 .....	5
Software Enhancements in X8.9.1 .....	5
Documentation Changes in X8.9.1 .....	6
Features in X8.9 .....	7
Edge Traversal Integration with Cisco Meeting Server .....	7
(NOT SUPPORTED) Web Proxy for Cisco Meeting Server .....	7
IM and Presence Service Federation With Skype for Business or Office 365 Organizations ..	8
REST API Expansion .....	9
Allow Jabber on iOS to Use Safari for SSO Over MRA .....	9
Shared Line / Multiple Line Support for MRA Endpoints .....	9
(Preview) Smart Call Home .....	10
Secure Install Wizard .....	10
Improved DiffServ Code Point Marking .....	10
Improved Maintenance Mode .....	11
Other Changes and Enhancements .....	12
Open and Resolved Issues .....	12
Bug Search Tool Links .....	12
Notable Issues in this Version .....	13
Limitations .....	14
Unsupported Features (General) .....	14
Unsupported Endpoint Features When Using MRA .....	14
Unsupported Cisco VCS Features and Limitations When Using MRA .....	15

## Preface

Unsupported Contact Center Features When Using MRA .....	15
Interoperability .....	15
Notable Interoperability Concerns .....	15
Upgrading to X8.9.1 .....	16
Prerequisites and Software Dependencies .....	16
Upgrade Instructions .....	17
Using Collaboration Solutions Analyzer .....	19
Using the Bug Search Tool .....	19
Obtaining Documentation and Submitting a Service Request .....	19
Cisco Legal Information .....	20
Cisco Trademark .....	20

## Preface

## Change History

**Table 1 Release Notes Change History**

Date	Change	Reason
February 2017	Republished with clarification for scope of shared line/ multiple line feature.	Customer found issue.
January 2017	Add summary of X8.9.1 software and documentation enhancements. Update Resolved Issues section. Update Limitations section.	X8.9.1 maintenance release
December 2016	First publication.	X8.9

## Supported Platforms

**Table 2 Cisco VCS Software Versions Supported by Platform**

Platform name	Serial Numbers	Scope of software version support
Small VM (OVA)	(Auto-generated)	X8.1 onwards
Medium VM (OVA)	(Auto-generated)	X8.1 onwards
Large VM (OVA)	(Auto-generated)	X8.1 onwards
CE500* (Cisco VCS pre-installed on UCS C220 M3L)	52C#####	X8.1.1 onwards
CE1000* (Cisco VCS pre-installed on UCS C220 M3L)	52B#####	X8.1.1 onwards
CE1100 (Cisco VCS pre-installed on UCS C220 M4L)	52D#####	X8.6.1 onwards

\* As of 26<sup>th</sup> February 2016, you cannot order the CE500 and CE1000 appliances from Cisco. See the [End-of-sale announcement](#) for other important dates in the lifecycle of these platforms.

Preface

**Some VCS hardware appliances are not supported**

We do not support this Cisco VCS software version on the 1st generation Cisco VCS hardware appliances, serial numbers 52A#####.

## Product Documentation

The following documents provide guidance on installation, initial configuration, and operation of the product:

For installing the Cisco VCS, see:

- *Cisco VCS Virtual Machine Installation Guide* on the [VCS installation guides page](#).
- *Cisco Video Communication Server CE1100 Appliance Installation Guide* on the [VCS installation guides page](#).

For general administration topics, reference, and maintenance, see:

- *Cisco TelePresence VCS Administrator Guide* on the [Cisco TelePresence VCS maintain and operate guides page](#).
- *Cisco TelePresence VCS Serviceability Guide* on the [Cisco TelePresence VCS maintain and operate guides page](#).

Other documents that may be relevant in your environment:

- Registrar:  
See *Cisco Single VCS Control - Basic Configuration Deployment Guide* on the [VCS configuration guides page](#).
- Firewall Traversal:  
See *Cisco TelePresence VCS Basic Configuration (Control with Expressway) Deployment Guide* on the [VCS configuration guides page](#).
- Cisco Spark: [Hybrid services knowledge base](#)
- Clustering:  
See the *Cisco VCS Cluster Creation and Maintenance Deployment Guide*, for your version, on the [Cisco TelePresence Video Communication Server \(VCS\) configuration guides page](#).
- Certificates:  
See *Cisco VCS Certificate Creation and Use Deployment Guide* on the [VCS configuration guides page](#).
- Unified Communications:  
See *Mobile and Remote Access Through Cisco Video Communication Server* on the [VCS configuration guides page](#).
- Cisco Meeting Server:  
*Cisco VCS with Cisco Meeting Server Deployment Guide* on the [VCS configuration guides page](#).  
See *Cisco Meeting Server API Reference Guide* on the [Cisco Meeting Server programming guides page](#).  
Other Cisco Meeting Server configuration guides are available on the [Cisco Meeting Server configuration guides page](#).
- Microsoft Infrastructure:  
See *Cisco VCS and Microsoft Infrastructure Deployment Guide* on the [VCS configuration guides page](#).

## Changes and Features in X8.9.1

## Changes and Features in X8.9.1

X8.9.1 is a maintenance release.

**Important! We strongly recommend that you upgrade to this X8.9.1 software. The software includes a fix for an issue with the Call History table. This issue can in certain circumstances cause severe system problems (CDETS CSCvc58081 refers).**

## Software Enhancements in X8.9.1

**Table 3 Feature History by Release Number**

Feature / change	X8.9	X8.9.1
<a href="#">Apple Push Notifications Service Pass Through to Cisco Jabber for iPhone and iPad</a>	Not supported	Supported
<a href="#">Edge Traversal of Microsoft SIP Traffic for Cisco Meeting Server</a>	Supported	Supported
<a href="#">Web Proxy for Meeting Server</a>	NOT SUPPORTED	NOT SUPPORTED
<a href="#">IM and Presence Service Federation With Skype for Business or Office 365 Organizations</a>	Preview	Supported
<a href="#">REST API Expansion</a>	Supported	Supported
<a href="#">Allow Jabber for iPhone and iPad to Use Safari for SSO Over MRA</a>	Supported	Supported
<a href="#">Shared Line / Multiple Line Support for MRA Endpoints</a>	Preview	Supported
<a href="#">Smart Call Home</a>	Preview	Preview
<a href="#">Secure Install Wizard</a>	Supported	Supported
<a href="#">DiffServ Code Point Marking</a>	Supported	Supported
<a href="#">Maintenance Mode For MRA</a>	Supported	Supported
<a href="#">X8.9 Changes and Enhancements</a>	Supported	Supported

#### Summary of changes

- If you have Cisco Jabber users with iOS devices, Cisco VCS with Mobile and Remote Access now supports the Apple Push Notification Service. (Subject to the dependent systems being available.) See feature description below.
- The Install Wizard has these changes:
  - When deploying an OVA using the Install Wizard, a warning in relation to an RSA key being required has been removed. An RSA public key is only required if you wish to set the root and admin password through SSH – primarily used in automated deployments.
  - The serial number and release key, if available, now appear in the Install Wizard for reference purposes.
- For DCSP marking, traffic type "Video" is now assigned by default if the media type cannot be identified. (For example, if different media types are multiplexed on the same port.) Previously we assigned type "Audio" as the default.
- Miscellaneous security enhancements.
- A new alarm number 20021 exists, to warn about cluster communication failures.

## Changes and Features in X8.9.1

**Apple Push Notification Service Pass Through to Cisco Jabber for iPhone and iPad**

If you have Cisco Jabber users with iOS devices, Cisco VCS with Mobile and Remote Access is able to support the Apple Push Notification Service (APNs). This feature is subject to the dependent systems also being APNs-enabled.


In X8.9.n this feature is used only for IM&P services, and not for video or voice calls.

No extra configuration is needed, assuming Cisco VCS Expressway is already providing Mobile and Remote Access for Jabber iOS devices. The following requirements apply:

- Devices running an APNs-enabled Jabber for iOS software build.
- Cisco Unified Communications Manager IM and Presence Service running an APNs-enabled software version.

For more information, see *Deploying Apple Push Notifications for the IM and Presence Service* on the [Cisco Unified Communications Manager IM and Presence Service Configuration and TechNotes](#) page on Cisco.com

**Figure 1 Example of Apple Push Notifications for CUCM IM&P and Jabber iOS**

**Documentation Changes in X8.9.1**

The following sections in these notes have been updated:

- [Limitations](#)
- [Notable Issues in this Version](#)
- [Resolved Issues list](#)
- [Cisco Expressway as H.323 Gatekeeper](#) (endpoint software requirements corrected)

Changes to other documents include:

- The section "*What's New in this Version*" is now removed from the online help.
- The information about how to make backups and restore the system has been updated.
- We now clarify that we do not support downgrading an existing Cisco VCS system to an earlier version.

## Features in X8.9

- We now clarify that in paired configurations with a Cisco VCS Control and a Cisco VCS Expressway, the Cisco VCS Expressway needs its own, separate public IP address. And if you use static NAT IP addressing, the Cisco VCS Control must not use the same IP address as the Cisco VCS Expressway.
- The *Mobile and Remote Access Deployment Guide* has new information about shared line and multiline support for endpoints connected through MRA. In section " *Unsupported Features When Using Mobile and Remote Access*".

## Features in X8.9

## Edge Traversal Integration with Cisco Meeting Server

The Cisco VCS pair at the edge of the network can now traverse Microsoft-variant SIP traffic to and from the Cisco Meeting Server. This allows your users to collaborate with people from external organizations that use Office 365 or Microsoft Skype for Business infrastructure. Users can meet in Meeting Server spaces, or make point-to-point calls between the organizations.

Two Cisco VCS enhancements help you configure these collaboration scenarios:

- The DNS zone can do SRV lookups for the Microsoft federation service (`._sipfederationtls._tcp.example.com.`)
- Search rules now have the ability to route calls based on which variant of SIP is used on the call

The screenshot shows a configuration interface with several fields and dropdown menus. The 'SIP variant' dropdown menu is open, showing the following options: 'All SIP Variants' (selected), 'Standards-based', 'Microsoft Variants', 'Microsoft AV & Share', and 'Microsoft SIP IM&P'. Other fields include 'Protocol' (SIP), 'Source', 'Request must be authenticated', and 'Mode' (Any alias).


*Cisco VCS with Cisco Meeting Server Deployment Guide* on the [VCS configuration guides page](#).

## (NOT SUPPORTED) Web Proxy for Cisco Meeting Server

**CAUTION: Do not use the Web Proxy for Meeting Server. This feature is not supported with this release of Cisco VCS, due to known issues.**

We've added a reverse https proxy for Cisco Meeting Server, which enables off-premises users to browse to a Meeting Server Web Bridge. Users can manage or join spaces without having any software other than a supported browser.

## Features in X8.9



The proxy requires little extra configuration on the Cisco VCS pair. Simply enter the Meeting Server listening address on the Cisco VCS Control. Then the pair uses the existing traversal connection to proxy external https requests to that address.

You can enable the Web Proxy for Meeting Server on the same Cisco VCS pair as MRA or other traversal features. However, you can't use it if the pair is configured for Jabber Guest.

#### More information

- [List of supported browsers.](#)
- [Cisco VCS with Cisco Meeting Server Deployment Guide](#) on the [VCS configuration guides page.](#)

You need Web Bridge version 2.1.2 or later to support this feature in Cisco VCS.

## IM and Presence Service Federation With Skype for Business or Office 365 Organizations

The Cisco VCS pair at the edge of the network can now traverse messaging and presence traffic between IM and Presence Service and external organizations using Skype for Business or Office 365. For this feature to work, Cisco Unified Communications Manager IM and Presence Service must be running a compatible software version.

[Cisco VCS with Cisco Meeting Server Deployment Guide](#) on the [VCS configuration guides page.](#)



## Features in X8.9

## REST API Expansion

In X8.8, we introduced a new API to simplify remote configuration. Third party systems, such as Cisco Prime Collaboration Provisioning, can now use the API to configure the following features / services on the Cisco VCS:

- Mobile and Remote Access (MRA)
- Business to business (B2B) calls

The API is self-documented using REST API Markup Language (RAML).

See *Cisco Video Communication Server REST API Reference Guide* on the [VCS configuration guides page](#).

## Allow Jabber on iOS to Use Safari for SSO Over MRA

This option applies if you use single sign-on (SSO) and have Cisco Jabber iOS endpoints that access Unified Communications services from outside the network. In this case, by default the identity provider's authentication page is displayed in an embedded web browser (not the Safari browser) on the iOS devices. That default browser is unable to access the iOS trust store, and so cannot use any certificates deployed to the devices. From X8.9, you can optionally configure Cisco VCS Expressway to allow Jabber on iOS devices to use the native Safari browser. Because the Safari browser *is* able to access the device trust store, you can now enable password-less authentication or two-factor authentication in your SSO deployment.

### Caveat

A potential security issue exists for this option. The mechanism to return browser control from Safari to Jabber after the identity provider authentication completes, uses a custom URL scheme that invokes a custom protocol handler. It's possible that another application other than Jabber could intercept the scheme and gain control from iOS. In that case, the application would have access to the OAuth token in the URL.

If you are confident that your iOS devices will not have other applications that register the Jabber custom URL scheme, for example because all mobile devices are managed, then it's safe to enable the option. If you are concerned about the possibility of another app intercepting the custom Jabber URL, then do **not** enable the embedded Safari browser.

**Note:** Make sure that you apply this option consistently in Cisco VCS Expressway and in Unified CM. If you decide to enable or disable it in one application, do the same in the other. The relevant settings are:

- **Allow Jabber iOS clients to use embedded Safari browser** in Cisco VCS Expressway (**Configuration > Unified Communications > Configuration > Single Signon** section)
- **SSO Login Behavior for iOS** in Unified CM (**System > Enterprise Parameters > SSO Configuration** section)

### Supported endpoints

- Cisco Jabber for iOS 11.8 or later, on devices using iOS 9 or later

### Supported Unified Communications services

- Cisco Unified Communications Manager 11.5(1)SU1 or later
- Cisco Unity Connection 11.5(1) or later

## Shared Line / Multiple Line Support for MRA Endpoints

Cisco VCS now supports pass through of Unified CM shared line and multiple line features for endpoints that are connecting by Mobile and Remote Access.

The benefit of this feature is that remote and mobile endpoint users can use features, like barge, conference barge, hold on one device and resume on another, in the same way as they would when they are on the premises.

You need to configure multiple and shared lines for users and their MRA devices on Unified CM.

## Features in X8.9

**Required versions:**

- Unified CM 11.5(1)SU2 or later
- Cisco VCS X8.9 or later
- Cisco IP Phone 7800 Series and Cisco IP Phone 8800 Series phones, with firmware version 11.5(1) or later

**Note:** This feature is disabled by default, because it impacts some features on earlier versions of Unified CM.

If you are using a Unified CM version before 11.5(1)SU2, and you enable SIP Path headers on Cisco VCS Control, the following Unified CM features will *report the MRA devices' IP addresses instead of the Cisco VCS's IP address*:

- Device Mobility
- Real-Time Monitoring Tool (RTMT)
- Cisco Emergency Responder (CER)

Other features may also be affected by this change. The devices' IP addresses are not useful for determining their location, as they are typically from reserved private ranges and could overlap with your organization's internal range.

## (Preview) Smart Call Home

Smart Call Home is a free embedded support capability for Cisco VCS. It offers proactive diagnostics and real-time alerts, enabling higher network availability and increased operational efficiency.

Smart Call Home notifies users of Schedule- and Event-based notifications.

- Schedule-based: inventory, telemetry and configuration messages used to generate a Device Report and improve hardware and software quality by identifying failure trends. You can find these notifications posted on the first day of every month.
- Event-based: asynchronous events already supported by Cisco VCS such as alarms and ACRs. You will find these notifications posted to the Smart Call Home server as and when they occur.

You can opt to keep your organization's details anonymous. In this case Cisco VCS sends reports to the Smart Call Home server as normal, but the server does not send out notifications.

## Secure Install Wizard

The Cisco VCS now includes an Install Wizard that helps make the deployment and configuration of your system easier and more secure.

The Install Wizard guides you through the initial configuration required to get your system up and running securely. Any further configuration is then possible using the web interface or CLI.

Only the person authorized to complete the system installation can access and complete the initial setup on the system console (or VM equivalent). All accounts on the Cisco VCS are disabled upon first boot until the installation is complete. The system is also not accessible over the network interface until the installation has been completed and secured.

In a VM deployment, any preconfigured data gets imported when the VM boots for the first time and you are not required to re-enter data.

The Install Wizard does not affect the upgrade procedure for an existing system, as the system maintains any data that you have already configured.

## Improved DiffServ Code Point Marking

From X8.9, the Cisco VCS supports improved DSCP (Differentiated Service Code Point) packet marking for traffic passing through the firewall, including Mobile and Remote Access. DSCP is a measure of the Quality of Service level of the packet. To provide more granular control of traffic prioritization, DSCP values are set (marked) for these individual traffic types:

## Features in X8.9

Traffic type	Supplied default value	Web UI field
Video	34	QoS Video
Audio	46	QoS Audio
XMPP	24	QoS XMPP
Signaling	24	QoS Signaling

Before X8.9 you had to apply DSCP values to all signaling and media traffic collectively.

You can optionally change the default DSCP values from the **System > Quality of Service** web UI page (or the CLI).

**Notes:**

- DSCP value "0" specifies standard best-effort service.
- DSCP marking is applied to SIP and H.323 traffic.
- DSCP marking is applied to TURN media, providing the TURN traffic is actually handled by the Cisco VCS.
- Traffic type "Video" is assigned by default if the media type cannot be identified. (For example, if different media types are multiplexed on the same port.)

**Existing QoS/DSCP Commands and API are Discontinued**

**From X8.9 we no longer support the previous methods to specify QoS/DSCP values. The former Web UI settings QoS Mode and QoS Value, CLI commands `xConfiguration IP QoS Mode` and `xConfiguration IP QoS Value` and corresponding API are now discontinued.** Do not use these commands.

**What if I currently use these commands?**

When you upgrade the Cisco VCS, any existing QoS value you have defined is automatically applied to the new fields and replaces the supplied defaults. For example, if you had a value of 20 defined, all four DSCP settings (QoS Audio, QoS Video, QoS XMPP, QoS Signaling) are set to 20 also.

We don't support downgrades. If you need to revert to your pre-upgrade software version, the QoS settings are reset to their original supplied defaults. So QoS Mode is set to *None* and QoS Value is set to 0. You will need to manually redefine the values you want to use.

## Improved Maintenance Mode

Maintenance mode on the Cisco VCS has been enhanced so that you can bring an MRA system down in a managed way.


When you engage maintenance mode, the Cisco VCS stops accepting new calls or proxy (MRA) traffic. Existing calls and chat sessions are not affected.

As users end their sessions normally, the system comes to a point when it is not processing any traffic of a certain type, and then it shuts that service down.

If users try to make new calls or start new chat sessions while the Cisco VCS is in maintenance mode, the clients will receive a service unavailable response, and they might then choose to use another peer (if they are capable). This fail-over behavior depends on the client, but restarting the client should resolve any connection issues if there are active peers in the cluster.

The Unified Communications status pages also show (Maintenance Mode) in any places where MRA services are affected.

## Open and Resolved Issues



Status	System	Configuration	Applications	Users	Maintenance
<b>Unified Communications</b>					
Unified Communications (last updated: 13:45:43 EDT)					
Unified Communications status	Enabled				
Unified CM registrations	Configured but with errors				
	HTTP proxy service: Inactive (Maintenance mode)				
	Port forwarding mesh: Inactive (Maintenance mode)				
	Provisioning server: Inactive (Maintenance mode)				
IM and Presence Service	Configured but with errors				
	XMPP router: Inactive (Maintenance mode)				
	HTTP proxy service: Inactive (Maintenance mode)				
	Port forwarding mesh: Inactive (Maintenance mode)				
	Provisioning server: Inactive (Maintenance mode)				
	Service requires an active connection to at least one IM & Presence server (Maintenance mode)				
XMPP Federation	Not configured ( <a href="#">Configure a domain on Expressway-C</a> )				
Single Sign-On support	Not configured (Enable on the <a href="#">Unified Communications</a> page)				

## Other Changes and Enhancements

- You can nominate an administrator account as an emergency account. In case the Cisco VCS disallows local authentication but is unable to connect to a remote authentication service.
- We have removed the limitation that TURN services should not be enabled on a system that is being used for MRA. We did this to allow services that require TURN to coexist with MRA. One example is edge traversal for Cisco Meeting Server.

**Note:** This change does not make Jabber Guest compatible with MRA. It also does not mean that TURN can be used for MRA. The change simply means that MRA is not impacted if you enable TURN services (for other reasons).

- We have discontinued the pre-X8.9 API and CLI commands for defining QoS/DSCP values: `xConfiguration IP QoS Mode` and `xConfiguration IP QoS Value`. They are replaced by new commands / web UI settings.
- The web administration port is now configurable, on the **System > Administration** page. The default port is still 443.
- From X8.9 onwards, automated intrusion protection is enabled, by default, for the following categories:
  - http-ce-auth
  - http-ce-intrusion
  - sshpfd-auth
  - sshpfd-intrusion
  - xmpp-intrusion

This change affects new systems. Upgraded systems keep their existing protection configuration.

## Open and Resolved Issues

## Bug Search Tool Links

Follow the links below to read the most recent information about the open and resolved issues in this release.

- [All open issues, sorted by date modified \(recent first\)](#)
- [Issues resolved by X8.9.1](#)
- [Issues resolved by X8.9](#)

## Notable Issues in this Version

### **CSCva36208: Rich Media Session license is not consumed by Single NIC Cisco VCS Expressway hosting Jabber Guest service**

Changes to the licensing model in X8.8 revealed an issue with licensing of the Jabber Guest service on the Cisco VCS Expressway server. When the Cisco VCS pair is part of the "Single NIC" Jabber Guest deployment, the Cisco VCS Expressway should count one RMS license for each Jabber Guest call, but it does not. This issue may cause confusion about the server's load. Because usage appears low even when the server is processing multiple calls.

We recommend the Dual NIC Jabber Guest deployment.

If you use the single NIC deployment, make sure your Cisco VCS Expressway is correctly licensed to ensure continuity of service with future upgrades.

### **CSCvc47502 and CSCvc34689: Cisco VCS B2BUA drops some RTCP multistreaming Refresh packets during decryption in Cisco WebEx calls**

**Note:** This software version is only vulnerable to this issue if the other end of the call involves a VCS or Expressway running X8.7x or earlier.

This issue affects certain TelePresence configurations with Cisco VCS or Cisco Expressway software versions X8.7x.

#### **Affected components**

- Cisco TelePresence IX5000 Series immersive endpoint (all versions)
- Cisco VCS or Cisco Expressway versions X8.7.x and earlier
- Cisco TelePresence Server versions 4.3, 4.4(1.9), 4.2 or earlier
- Cisco TelePresence Server versions 4.4(1.16) or later
- Cisco TelePresence TX9000 Series
- Cisco TelePresence System (CTS)
- Other video endpoints

#### **Description**

The issue affects calls from immersive TelePresence systems operating in TIP/MUX mode, or other TelePresence systems operating in multistreaming mode. When encrypted/decrypted by VCS or Expressway X8.7.x. The symptoms are pixelated video which gets progressively worse. Then the endpoint terminates the call (because problems with decoding received media lead to perceived packet loss). Other video and quality issues may also occur.

With the TelePresence Server, the following behavior may trigger the issue:

- Versions 4.3 or 4.4(1.9): sharing for more than the session refresh.
- Versions 4.2 or earlier, or 4.4(1.16) or later: starting and stopping sharing multiple times.

**Note:** This issue does not occur if any of the following cases apply:

- Encryption to / from the VCS / Expressway is disabled.
- TIP/MUX is disabled (immersive systems).
- Multistream is disabled.
- If Cisco WebEx is involved, and WebEx video callback (Call My Video System) is used.

#### **Background**

The mechanism for session state maintenance in X8.7.x is susceptible to issues when a high number of SSRC IDs are present in encrypted calls. These include calls from immersive endpoints that use TIP, or from endpoints operating in multistream mode. This issue was resolved by Cisco VCS X8.8.x and later. However, this issue can affect encrypted

## Limitations

calls where one of the VCS / Expressways at either end of the call leg is still on X8.7.x while the other is on X8.8.x or later.

### Recommendation - Upgrade X8.7.x systems

The CMR Cloud infrastructure (Cisco WebEx) was upgraded from X8.7 to resolve the issue for customers that have VCS or Expressway X8.8.x on-premises. This means that other customers using CMR Hybrid, who have VCS / Expressway X8.7.x on-premises, could now see this issue. We strongly recommend that you upgrade your Cisco VCS / Expressway X8.7.x if you are using multistream/immersive endpoints for encrypted calls with other Cisco infrastructure, like CMR Cloud or third-party partners.

## Limitations

### Unsupported Features (General)

- DTLS is not supported through the Cisco VCS Control/Cisco VCS Expressway. SRTP is used to secure calls instead; attempts to make DTLS calls will fail.
- SIP UPDATE method. Features that rely on the SIP UPDATE method ([RFC 3311](#)) will not work as expected because the Cisco VCS does not support this method.
- Audio calls may be licensed as video calls in some circumstances. Calls that are strictly audio-ONLY consume fewer licenses than video calls. However, when audio calls include non-audio channels, such as the iX channel that enables ActiveControl, they are treated as video calls for licensing purposes.

### Unsupported Endpoint Features When Using MRA

**Note:** This list contains known limitations and is not exhaustive. The MRA deployment does not necessarily support pass through of line-side features provided by Cisco Unified Communications Manager. Absence of such items from this list does not imply that they are supported.

- Call recording for Cisco Jabber endpoints connected over Mobile and Remote Access (MRA).
- Cisco IP Phone 88xx and 78xx series support shared line or multiline features when connected through MRA (if Path Header support is enabled). We do not support shared line or multiline over MRA for other endpoints, phones, and soft clients.
- Custom embedded tabs for Cisco Jabber endpoints connected over MRA.
- Directory access mechanisms other than the Cisco User Data Service (UDS).
- Certificate provisioning to remote endpoints. For example, the Certificate Authority Proxy Function (CAPF). If you can do the first-time configuration on premises (inside the firewall) then you can support endpoints that use CAPF. After that you can use them over MRA - but you can't do the initial configuration over MRA.
- Features that rely on the SIP UPDATE method ([RFC 3311](#)) will not work as expected, because the Cisco VCS does not support this method. For example, Unified CM and endpoints use UPDATE to implement blind transfer, which does not work correctly over MRA.
- Peer-to-peer file transfer when using IM and Presence Service and Jabber is unsupported over MRA.
  - Managed File Transfer (MFT) with IM and Presence Service 10.5.2 (and later) and Jabber 10.6 (and later) clients is supported over MRA.
  - File transfer with WebEx Messenger Service and Cisco Jabber is supported over MRA.
- Additional mobility features including GSM handoff and session persistency.
- Hunt group/hunt pilot/hunt list.
- Self-care portal.
- Jabber SDK is not supported over MRA.

## Interoperability

## Unsupported Cisco VCS Features and Limitations When Using MRA

- The Cisco VCS cannot be used for Jabber Guest when it is used for Mobile and Remote Access (MRA).
- The Cisco VCS Control used for MRA cannot also be used for Microsoft gateway service. Microsoft gateway service requires a dedicated Cisco VCS Control.
- MRA is not supported in IPv6 only mode.
- Endpoint management capability (SNMP, SSH/HTTP access).
- Multi-domain and multi-customer support is limited as follows:
  - Prior to X8.5, each Cisco VCS deployment supported only one IM&P domain (even though IM and Presence Service 10.0 or later supports Multiple Presence Domains).
  - As of X8.5, you can create multiple deployments on the Cisco VCS Control, but this feature is still limited to one domain per deployment.
  - As of X8.5.1, a deployment can have Multiple Presence Domains. This feature is in preview, and we currently recommend that you do not exceed 50 domains.
- Deployments on Large VM servers are limited to 2500 proxied registrations to Unified CM (the same limit as Cisco VCS appliances or equivalent VM).
- Not all contact center features are supported by Cisco VCS when connected through MRA.

## Unsupported Contact Center Features When Using MRA

This section applies if you use the Cisco Unified Contact Center Express (Unified CCX) solution through Mobile and Remote Access (MRA).

Cisco VCS does not support some Unified CCX features for contact center agents or other users who connect over MRA. Unsupported features include:

- Deskphone control functions (due to no support for CTI-QBE protocol).
- Built in Bridge (BIB) functions, which means that silent monitoring and recording, and agent greeting are not available.
- Shared line and multiline support for 78xx and 88xx series phones is available from X8.9 but is not in earlier Cisco VCS versions.

**Notes:**

- Jabber for Mac and Jabber for Windows are not capable of deskphone control when they are connected over MRA. This is because the Cisco VCS pair does not traverse the CTI-QBE protocol.
- If these Jabber applications, or other CTI applications, can connect to CUCM CTIManager (directly or through the VPN) they *can* provide deskphone control of clients that are connected over MRA.

## Interoperability

The interoperability test results for this product are posted to <http://www.cisco.com/go/tp-interop>, where you can also find interoperability test results for other Cisco TelePresence products.

## Notable Interoperability Concerns

X8.7.n (and earlier versions) of Cisco VCS are not interoperable with Cisco Unified Communications Manager IM and Presence Service 11.5(1).

This is caused by a deliberate change in that version of IM and Presence Service, and there is a corresponding change in Cisco VCS X8.8 (and later).

To ensure continuous interoperability, you must upgrade your Cisco VCS systems to X8.9 *before* you upgrade your IM and Presence Service systems to 11.5(1).

## Upgrading to X8.9.1

The symptom of the issue is an error on Cisco VCS as follows:

```
Failed Unable to Communicate with <IM&P node address>. AXL query HTTP error "'HTTPError:500'"
```

## Upgrading to X8.9.1

### Prerequisites and Software Dependencies

**Upgrade Caution, PLEASE READ: X8.8 and later versions are more secure than earlier versions. Upgrading could cause your deployments to stop working as expected, so you must check for the following environmental issues before you upgrade to X8.8 or later:**

- Minimum versions of Unified Communications infrastructure: Some versions of Unified CM, IM and Presence Service, and Cisco Unity Connection have been patched with CiscoSSL updates. Check that you're running the minimum versions described in the Mobile and Remote Access deployment guide, before you upgrade Cisco VCS.

See *Mobile and Remote Access Through Cisco Video Communication Server* on the [VCS configuration guides page](#).

IM and Presence Service 11.5 is an exception. You must upgrade Cisco VCS to X8.8 or later before you upgrade IM and Presence Service to 11.5.

- Certificates: Certificate validation was tightened up in X8.8.
  - Try the secure traversal test before and after upgrade (**Maintenance > Security certificates > Secure traversal test**) to validate TLS connections.
  - Are your Unified Communications nodes using valid certificates that were issued by a CA in the Cisco VCS Controls' trust list?
  - If you are using self-signed certificates, are they unique? Does the trusted CA list on Cisco VCS have the self-signed certificates of all the nodes in your deployment?
  - Are all entries in the Cisco VCS's trusted CA list unique? You must remove any duplicates.
  - If you have TLS verify enabled on connections to other infrastructure (always on by default for Unified Communications traversal zone, and optional for zones to Unified Communications nodes) you must ensure that the hostname is present in the CN or SAN field of the host's certificate. We do not recommend disabling TLS verify mode, even though it may be a quick way to resolve a failing deployment.
- DNS entries: Do you have forward and reverse DNS lookups for all infrastructure systems that the Cisco VCS interacts with?

**Important! From version X8.8 onward, you must create forward and reverse DNS entries for all Cisco VCS Expressway systems, so that systems making TLS connections to them can resolve their FQDNs and validate their certificates.**

If the Cisco VCS cannot resolve hostnames and IP addresses of systems, your complex deployments (eg. MRA) could stop working as expected after you upgrade.

- Cluster peers: Do they have valid certificates? If they are using default certificates you should replace them with (at least) internally generated certificates and update the peers' trust lists with the issuing CA.

**Note:** If you are upgrading to X8.8 or later from an earlier version, clustering communications changed in X8.8 to use TLS connections between peers instead of IPSec. TLS verification is not enforced (by default) after you upgrade, and you'll see an alarm reminding you to enforce TLS verification.

#### Downgrading to an Earlier Version is Not Supported

We do not support downgrades. Do not install a previous Cisco VCS version onto a system that is running a newer version. If you do so, the system configuration will not be preserved.

#### Hybrid Services

**Important! Your Management Connector must be up to date before you upgrade your Cisco VCS. You must authorize and accept any Management Connector upgrades advertised by the Cisco Collaboration Cloud before**



## Upgrading to X8.9.1

**attempting to upgrade your Cisco VCS. Failure to do so may cause issues with the connector once you have upgraded your Cisco VCS.**

**Note:** X8.7.1 is now the minimum version required for Hybrid Services. If you are using Hybrid Services with X8.7, you must upgrade to X8.7.1 or later.

### Existing TMS Agent (Legacy Mode) Provisioning Deployments

Cisco VCS X8.1 and later no longer supports TMS Agent (legacy mode) provisioning. **Before you upgrade to X8 or later**, if you are using TMS Agent (legacy mode) for provisioning you must first migrate to Cisco TelePresence Management Suite Provisioning Extension which requires TMS 13.2.x. See *Cisco TMS Provisioning Extension Deployment Guide* for instructions about how to migrate.

### Existing OCS Relay Deployments

Cisco VCS X8.1 and later no longer supports OCS Relay integration with Microsoft Lync 2010 / OCS 2007 R2. If you use OCS Relay you must migrate to using the Microsoft Interoperability B2BUA to route SIP calls between the Cisco VCS and Microsoft infrastructure. See *Cisco VCS and Microsoft Infrastructure Deployment Guide* for information about this deployment.

### Existing Non-AES Build Installations

As of version X8.1, the software uses AES encryption. Prior to this, a version that used weaker encryption was available. If you are upgrading to X8.1 or later (or another version that uses AES) from a version that used the weaker encryption, you **must** perform a factory reset. Proceed as follows to ensure you can upgrade in future:

1. Record all your software configuration details
2. Upgrade the software with the AES-encryption version  
All configuration will be lost
3. Perform a factory reset
4. Manually reconfigure the software

## Upgrade Instructions

### Before You Begin

We recommend that you upgrade Cisco VCS components while the system has low levels of activity.

If you are upgrading a Cisco VCS that uses clustering, device provisioning (Cisco TMSPE) or FindMe (with Cisco TMS managing Cisco VCS), you must follow the directions in *Cisco VCS Cluster Creation and Maintenance Deployment Guide*.

Follow the procedure below for upgrading Cisco VCS to X8.9.1, only if all of the following apply:

- The Cisco VCS is not part of a cluster
- Device provisioning is not in use
- Cisco TMS is not managing the Cisco VCS
- Cisco VCS is currently running X5.1.1 or later

### Process

To upgrade a Cisco VCS:

1. Backup the Cisco VCS (**Maintenance > Backup and restore**).

You should backup your system before upgrading.

If your system was delivered with X6.1 pre-installed, you must make some configuration changes before using the backup process as described in the section below.

## Upgrading to X8.9.1

**2. Enable maintenance mode.**

Log in to the Cisco VCS as admin (SSH or serial), and at a command prompt, type:

```
xConfiguration SystemUnit Maintenance Mode: On
```

Note that from X8.1 you can enable maintenance mode via the web interface (**Maintenance > Maintenance mode**).

**3. Wait for all calls to clear and registrations to timeout.**

- If necessary, manually remove any calls that do not clear automatically (**Status > Calls**, click **Select all** and then click **Disconnect**).
- If necessary, manually remove any registrations that do not clear automatically (**Status > Registrations > By device**, click **Select all** and then click **Unregister**).

**4. Upgrade and restart the Cisco VCS (Maintenance > Upgrade).**

Note that when upgrading to a new major release, for example from X7.n to X8.n you need to supply a valid release key as a part of the upgrade process.

The web browser interface may timeout during the restart process, after the progress bar has reached the end. This may occur if the Cisco VCS carries out a disk file system check – which it does approximately once every 30 restarts.

The upgrade is now complete and all Cisco VCS configuration should be as expected.

**Upgrade Cisco VCS Control and Cisco VCS Expressway systems connected over a traversal zone**

We recommend that Cisco VCS Control (traversal client) and Cisco VCS Expressway (traversal server) systems that are connected over a traversal zone both run the same software version.

However, we do support a traversal zone link from one Cisco VCS system to another that is running the previous major release of Cisco VCS. This means that you do not have to simultaneously upgrade your Cisco VCS Control and Cisco VCS Expressway systems.

Note that certain services (such as Mobile and Remote Access) require both the Cisco VCS Control and Cisco VCS Expressway systems to be running the same software version.

**Back up Cisco VCS units delivered with X6.1 pre-installed**

If your system was delivered with X6.1 pre-installed, you must make some configuration changes before using the backup process. You do not need to follow these additional steps if you do not have X6.1 installed or your installation of X6.1 is the result of an upgrade from a previous release. To ensure that all of your data is backed up:

**1. Log in to the Cisco VCS as root user.****2. Enter the following commands:**

```
mkdir /tandberg/persistent/oti
mkdir /tandberg/persistent/management
```

**3. Exit the root account.****Upgrade from older releases**

- We strongly recommend installing a new server certificate if you are upgrading from any version of Cisco VCS released prior to X8.1.1.
- The certificate signing request storage location changed in X8:
  - When you generate a CSR in X7, the application puts **csr.pem** and **privkey\_csr.pem** into **/tandberg/persistent/certs**.
  - When you generate a CSR in X8, the application puts **csr.pem** and **privkey.pem** into **/tandberg/persistent/certs/generated\_csr**.

If you want to upgrade from X7 and have an unsubmitted CSR, then we recommend discarding the CSR before upgrade, and then regenerating the CSR after upgrade.

## Using Collaboration Solutions Analyzer

- You cannot upgrade to X7.n or later from releases prior to X5.1.  
You must first upgrade to X5.2 and then to X7.n or later. See the X5.2 release notes for details.

## Using Collaboration Solutions Analyzer

*Collaboration Solutions Analyzer* is a tool created by Cisco Technical Assistance Center (TAC) to help you with troubleshooting, by analyzing log files from your Cisco TelePresence Video Communication Server.

To get started:

1. Collect the logs from your Cisco TelePresence Video Communication Server.
2. Sign in to <https://cway.cisco.com/tools/CollaborationSolutionsAnalyzer/>.  
(You need a customer or partner account to sign in).
3. Paste or drag in your log file.
4. Click **Run**.

The tool analyzes the log file and displays the information in a format that is much easier to understand than the raw logs. For example, you can generate ladder diagrams to show SIP calls.

## Using the Bug Search Tool

The Bug Search Tool contains information about open and resolved issues for this release and previous releases, including descriptions of the problems and available workarounds. The identifiers listed in these release notes will take you directly to a description of each issue.

To look for information about a specific problem mentioned in this document:

1. Using a web browser, go to the [Bug Search Tool](#).
2. Sign in with a cisco.com username and password.
3. Enter the bug identifier in the **Search** field and click **Search**.

To look for information when you do not know the identifier:

1. Type the product name in the **Search** field and click **Search**.
2. From the list of bugs that appears, use the **Filter** drop-down list to filter on either *Keyword*, *Modified Date*, *Severity*, *Status*, or *Technology*.

Use **Advanced Search** on the Bug Search Tool home page to search on a specific software version.

The Bug Search Tool help pages have further information on using the Bug Search Tool.

## Obtaining Documentation and Submitting a Service Request

Use the [Cisco Notification Service](#) to create customized flexible notification alerts to be sent to you via email or by RSS feed.

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.

## Cisco Legal Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies are considered un-Controlled copies and the original on-line version should be referred to for latest version.

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

© 2017 Cisco Systems, Inc. All rights reserved.

## Cisco Trademark

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)