cisco.



Release Notes for Cisco NCS 4206 and Cisco NCS 4216 Series, Cisco IOS XE 17.15.x

First Published: 2024-08-14

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA http://www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 527-0883 THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/c/en/us/about/legal/trademarks.html. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2024 Cisco Systems, Inc. All rights reserved.



CONTENTS

CHAPTER 1	Introduction 1
	Overview of Cisco NCS 4206 and NCS 4216 1
	Cisco NCS 4206 1
	Cisco NCS 4216 1
	Feature Navigator 2
	Hardware Supported 2
	Cisco NCS 4206 Supported Interface Modules 2
	Supported Interface Modules 2
	Cisco NCS 4216 Supported Interface Modules 4
	Cisco NCS 4216 F2B Supported Interface Modules 4
	Restrictions and Limitations 4
	Determining the Software Version 7
	Upgrading to a New Software Release 7
	Supported FPGA Versions for NCS 4206 and NCS 4216 8
	Additional References 12
CHAPTER 2	- What's New for Cisco IOS XE 17.15.1 15
	What's New in Hardware for Cisco IOS XE 17.15.1 15
	What's New in Software for Cisco IOS XE 17.15.1 15
CHAPTER 3	- Caveats 17
	Resolved Caveats - Cisco IOS XE 17.15.1 17
	Open Caveats - Cisco IOS XE 17.15.1 18
	Cisco Bug Search Tool 18

Contents



Introduction

This document provides information about the IOS XE software release for the Cisco NCS 4206 and Cisco NCS 4216 beginning with Cisco IOS XE Release 3.18SP.

- Overview of Cisco NCS 4206 and NCS 4216, on page 1
- Feature Navigator, on page 2
- Hardware Supported, on page 2
- Restrictions and Limitations, on page 4
- Determining the Software Version, on page 7
- Upgrading to a New Software Release, on page 7
- Supported FPGA Versions for NCS 4206 and NCS 4216, on page 8
- Additional References, on page 12

Overview of Cisco NCS 4206 and NCS 4216

Cisco NCS 4206

The Cisco NCS 4206 is a fully-featured aggregation platform designed for the cost-effective delivery of converged mobile and business services. With shallow depth, low power consumption, and an extended temperature range, this compact 3-rack-unit (RU) chassis provides high service scale, full redundancy, and flexible hardware configuration.

The Cisco NCS 4206 expands the Cisco service provider product portfolio by providing a rich and scalable feature set of Layer 2 VPN (L2VPN) and Layer 3 VPN (L3VPN) services in a compact package. It also supports a variety of software features, including Carrier Ethernet features, Timing over Packet, and pseudowire.

For more information on the Cisco NCS 4206 Chassis, see the Cisco NCS 4206 Hardware Installation Guide.

Cisco NCS 4216

The Cisco NCS 4216 is a seven-rack (7RU) unit chassis that belongs to the Cisco NCS 4200 family of chassis. This chassis complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE and CDMA. Given it's form-factor, interface types and Gigabit Ethernet density the Cisco NCS 4216 can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco NCS 4216 is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation chassis.

For more information about the Cisco NCS 4216 Chassis, see the Cisco NCS 4216 Hardware Installation Guide.

NCS 4216 14RU

The Cisco NCS 4216 F2B is a 14-rack unit router that belongs to the Cisco NCS 4200 family of routers. This router complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE, and CDMA. Given its form-factor, interface types, and Gigabit Ethernet density the Cisco NCS 4216 14RU can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco NCS 4216 14RU is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation router.

For more information about the Cisco NCS 4216 F2B Chassis, see the Cisco NCS 4216 F2B Hardware Installation Guide.

Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to http://www.cisco.com/go/cfn. An account on cisco.com is not required.

Hardware Supported

The following sections list the hardware supported for Cisco NCS 4206 and Cisco NCS 4216 chassis.

Cisco NCS 4206 Supported Interface Modules

Supported Interface Modules



Note

If the **license feature service-offload enable** command is configured, then the NCS4200-1T8LR-PS IM is not supported in the router for RSP3.

Note

There are certain restrictions in using the interface modules on different slots in the chassis. Contact Cisco Sales/Support for the valid combinations.



Note

FAN OIR is applicable every time the IM based fan speed profile is switched to NCS4200-1H-PK= and NCS4200-2Q-P interface modules. Even though the IMs remain in the Out-of-Service state, they are still considered as present in the chassis.

L

RSP Module	Supported Interface Modules	Part Numbers	Slot
NCS420X-RSP	8-port 10 Gigabit Ethernet Interface Module (8X10GE)	NCS4200-8T-PS	All
	1-port 100 Gigabit Ethernet Interface Module (1X100GE)	NCS4200-1H-PK=	4 and 5
	2-port 40 Gigabit Ethernet QSFP Interface Module (2X40GE)	NCS4200-2Q-P	4 and 5
	8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module	NCS4200-1T16G-PS	0,3,4, and 5
	1-port OC-192 Interface module or 8-port Low Rate Interface Module	NCS4200-1T8S-10CS	2,3,4, and 5
	NCS 4200 1-Port OC-192 or 8-Port Low Rate CEM 20G Bandwidth Interface Module	NCS4200-1T8S-20CS	2,3,4, and 5^{1}
	48-port T1/E1 CEM Interface Module	NCS4200-48T1E1-CE	All
	48-port T3/E3 CEM Interface Module	NCS4200-48T3E3-CE	All
	2-port 100 Gigabit Ethernet (QSFP) Interface Module $(2X100GE)^2$	NCS4200-2H-PQ	4,5
	1-port OC48 ³ / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	2,3,4, and 5

Table 1: NCS420X-RSP Supported Interface Modules and Part Numbers

¹ These slots are supported on 10G or 20G mode.
² IM supports only one port of 100G with RSP3 as QSFP28 on Port 0 in both slots 4 and 5.
³ If OC48 is enabled, then the remaining 3 ports are disabled.

RSP Module	Supported Interface Modules	Part Numbers	Slot
NCS420X-RSP	SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet Interface Module (1X10GE)	NCS4200-1T8LR-PS	All
	8-port T1/E1 CEM Interface Module	NCS4200-8E1T1-CE	All
	1-port OC48 ^{<u>4</u>} / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	2,3,4, and 5

⁴ If OC48 is enabled, then the remaining 3 ports are disabled.

Cisco NCS 4216 Supported Interface Modules

For information on supported interface modules, see Supported Interface Modules.

Cisco NCS 4216 F2B Supported Interface Modules

For information on supported interface modules, see Supported Interface Modules.

Restrictions and Limitations



Note The error message "PLATFORM-1-NOSPACE: SD bootflash : no space alarm assert" may occur in the following scenarios:

- Any sector of SD Card gets corrupted
- Improper shut down of router
- power outage.

This issue is observed on platforms which use EXT2 file systems.

We recommend performing a reload of the router. As a result, above alarm will not be seen during the next reload due to FSCK(file systems check) execution.

However, If the error persists after a router reload, we recommend to format the bootflash or FSCK manually from IOS.

- Embedded Packet Capture (EPC) is not supported on ASR 900 routers.
- From the Cisco IOS XE 16.6.1 releases, In-Service Software Upgrade (ISSU) is not supported on the router to the latest releases. For more information on the compatible release versions, see ISSU Support Matrix.
- ISSU is not supported between a Cisco IOS XE 3S release and the Cisco IOS XE Bengaluru 17.6.x release.
- The port restriction on 1-port OC-192 or 8-port low rate CEM interface module is on port pair groups. If you have OC48 configured on a port, the possible port pair groups are 0–1, 2–3, 4–5, 6–7. If one of the ports within this port group is configured with OC48 rate, the other port cannot be used.
- RS422 pinout works only on ports 0–7.
- The **ip cef accounting** command is *not* supported on the router.
- Configuration sync does *not* happen on the Standby RSP when the active RSP has Cisco Software Licensing configured, and the standby RSP has Smart Licensing configured on the router. If the active RSP has Smart Licensing configured, the state of the standby RSP is undetermined. The state could be pending or authorized as the sync between the RSP modules is not performed.
- Evaluation mode feature licenses may not be available to use after disabling, and enabling the smart licensing on the RSP2 module. A reload of the router is required.

• Ingress counters are not incremented for packets of the below format on the RSP3 module for the 10-Gigabit Ethernet interfaces, 100-Gigabit Ethernet interfaces; and 40-Gigabit Ethernet interfaces.

Packet Format

MAC header---->VLAN header---->Length/Type

When these packets are received on the RSP3 module, the packets are not dropped, but the counters are not incremented.

- T1 SAToP, T3 SAToP, and CT3 are supported on an UPSR ring only with local connect mode. Cross-connect configuration of T1, T3, and CT3 circuits to UPSR are not supported.
- PTP is not supported when 8-port 10-Gigabit Ethernet interface module is in oversubscribed mode.
- Port channel 61–64 is not supported in the 16.11.1a release. The range of configurable port channel interfaces has been limited to 60.
- Effective with Cisco IOS XE Everest 16.6.1, the VPLS over Port-channel (PoCH) scale is reduced from 48 to 24 for Cisco ASR 903 RSP3 module.

Note

The PoCH scale for Cisco ASR 907 routers is 48.

- The frame drops may occur for packets with packet size of less than 100 bytes, when there is a line rate of traffic over all 1G or 10G interfaces available in the system. This restriction is applicable only on RSP2 module, and is not applicable for RSP3 module.
- One Ternary Content-Addressable Memory (TCAM) entry is utilized for Segment Routing Performance Measurement. This is required for the hardware timestamping to function.
- While performing an auto upgrade of ROMMON, only primary partition is upgraded. Use the **upgrade rom-mon filename** command to upgrade the secondary partition of the ROMMON during the auto upgrade. However, the router can be reloaded during the next planned reload to complete the secondary ROMMON upgrade. This is applicable to ASR 903 and ASR 907 routers.
- In the Cisco IOS XE 17.1.1 release, the EVPN EVI type is VLAN-based by default, and while configuring for the EVPN EVI type, it is recommended to configure the EVPN EVI type as VLAN-based, VLAN bundle and VLAN aware model.
- For Cisco IOS XE Gibraltar Release 16.9.5, Cisco IOS XE Gibraltar Release 16.12.3, and Cisco IOS XE Amsterdam 17.1.x, a minimum disk space of 2 MB is required in the boot flash memory file system for a successful ROMMON auto upgrade process. For a disk space lesser than 2 MB, ROMMON auto upgrade fails and the router reboots. This is applicable to Cisco ASR 903 and Cisco ASR 907 routers.
- In the Cisco IOS XE 16.12.1, 17.1.1, and 17.2.1 releases, IPsec is not supported on the Cisco RSP3 module.
- CEM circuit provisioning issues may occur during downgrade from Cisco IOS XE Amsterdam 17.3.1 to any lower versions or during upgrade to Cisco IOS XE Amsterdam 17.3.1 from any lower versions, if the CEM scale values are greater than 10500 APS/UPSR in protected CEM circuits. So, ensure that the CEM scale values are not greater than 10500, during ISSU to or from 17.3.1.
- Some router models are not fully compliant with all IETF guidelines as exemplified by running the pyang tool with the **lint** flag. The errors and warnings that are exhibited by running the pyang tool with the **lint** flag are currently noncritical as they do not impact the semantic of the models or prevent the models

from being used as part of the toolchains. A script has been provided, "check-models.sh", that runs pyang with **lint** validation enabled, but ignoring certain errors. This allows the developer to determine what issues may be present.

As part of model validation for the Cisco IOS XE Amsterdam 17.3.1 release, "LEAFREF_IDENTIFIER_NOT_FOUND" and "STRICT_XPATH_FUNCTIONS" error types are ignored.

- Test Access Port (TAP) is not supported when the iMSG VLAN handoff feature is enabled on the same node.
- Data Communication Channel (DCC) is not supported in the NCS4200-1T8S-20CS interface module for the Cisco IOS XE Cupertino 17.8.1 release.
- In Cisco IOS XE Dublin 17.12.1, for mLDP Partitioned multicast distribution tree (MDT) to work with PIM-Sparse Mode (SM) traffic, configure only a single ingress PE and ensure that the **strict-rpf interface** command is disabled. Configuring multiple PE ingress is not allowed.
- SF and SD alarms are not supported on T1 and T3 ports for the following interface modules:
 - NCS4200-3GMS
 - NCS4200-48T3E3-CE
 - NCS4200-48T1E1-CE
- In RSP2 and RSP3 modules, during In-Service Software Upgrade (ISSU), interface modules undergo FPGA upgrade.

The following table details the IM Cisco IOS XE versions during ISSU with respect to FPGA upgrade and the impact of traffic flow for these IMs:

Table 3: Impact on IM during ISSU and FPGA Upgrade

IM	IM Version During ISSU	Pre-ISSU FPGA Upgrade	Post-ISSU Impact on IM	FPGA Version post ISSU
Phase 1	Cisco IOS XE 17.3.x or earlier version to Cisco IOS XE 17.4.x		Traffic is impacted during upgrade.	0.75

IM	IM Version During ISSU	Pre-ISSU FPGA Upgrade	Post-ISSU Impact on IM	FPGA Version post ISSU
Phases 1 and 2	Version earlier to Cisco IOS XE 17.8.x	FPGA upgrade completes and IM starts after the reload process. • FPGA version (Phase 1)— 0.47 • FPGA version (Phase 2) • NCS4208IFS 6922 • Combo IM: 69.24	Traffic is impacted during upgrade.	FPGA version (Phase 1)—0.75 FPGA version (Phase 2) • NCS420081FS—6924 • Combo IM: 69.32
Phase 1	Cisco IOS XE 17.4.1 or later versions to Cisco IOS XE 17.8.1	IM FPGA already upgraded with the latest version and reload is not required.	Traffic is not impacted.	0.75

For more information on the FPGA versions, see Supported FPGA Versions.

Refer the following table for supported IMs:

Table 4: NCS 4200 Supported Ethernet Interface Module

Phase 1 IM	Phase 2 IM	Phase 3 IM
NCS4200-1T8LR	NCS4200-1T8LR-PS	NCS4200-8T-PS
		NCS4200-2Q-P
		NCS4200-2H-PQ

Determining the Software Version

You can use the following commands to verify your software version:

- Consolidated Package—show version
- Individual sub-packages-show version installed (lists all installed packages)

Upgrading to a New Software Release

Only the latest consolidated packages can be downloaded from Cisco.com; users who want to run the router using individual subpackages must first download the image from Cisco.com and extract the individual subpackages from the consolidated package.

For information about upgrading to a new software release, see the Upgrading the Software on the Cisco NCS 4200 Series Routers .

Upgrading the FPD Firmware

FPD Firmware packages are bundled with the software package. FPD upgrade is automatically performed ont the router.

If you like to manually change the FPD Firmware software, use the **upgrade hw-module subslot 0/0 fpd bundle** to perform FPD frmware upgrade.

Supported FPGA Versions for NCS 4206 and NCS 4216

Use the **show hw-module all fpd** command to display the IM FPGA version on the chassis.

Use the **show platform software agent iomd** [*slot/subslot*] **firmware cem-fpga** command to display the CEM FPGA version on the chassis.

The table below lists the FPGA version for the software releases.



Note During ISSU, TDM interface modules are reset for FPGA upgrade.

Table 5: Supported TDM IM and CEM FPGAs for NCS 4206-RSP3 and NCS 4216

Category	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA (NCS 4200-48T1E1-CE)	48 X T3/E3 CEM Interface Module FPGA (NCS 4200-48T3E3-CE)	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA (NCS4 200-1T8S-10CS)	NCS 4200-1T8S-20CS	NCS4200-3GMS
IM FPGA	17.15.1	1.22	1.22	1.15	0.95	2.0
CEM FPGA		70160070	CAS: 72020072 Non-CAS: 56030056	5G mode: 10090065 10G mode: 10070079	20G mode - CAS: 10330075 10G and 20G - Non-CAS: 12290074	CAS: 10930095 Non-CAS: 11060093
IM FPGA	17.13.1	1.22	1.22	1.15	0.95	2.0
CEM FPGA		70140070	CAS: 72010072 Non-CAS: 56020056	5G mode: 10090065 10G mode: 10070079	20G mode - CAS: 10240075 10G and 20G - Non-CAS: 11160074	CAS: 10810095 Non-CAS: 10950093

Category	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA (NCS 4200-48T1E1-CE)	48 X T3/E3 CEM Interface Module FPGA (NCS 4200-48T3E3-CE)	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA (NCS4 200-1T8S-10CS)	NCS 4200-1T8S-20CS	NCS4200-3GMS
IM FPGA	17.12.1	1.22	1.22	1.15	0.95	2.0
CEM FPGA		7.0	7.2	5G mode:	10G mode:	9.5
				6.5	7.4	
				10G mode:	20G mode:	
				7.9	7.5	
IM FPGA	17.11.1a	1.22	1.22	1.15	0.95	2.0
CEM FPGA		7.0	5.6	5G mode:	10G mode:	9.3
				6.5	7.4	
				10G mode:	20G mode:	
				7.9	7.5	
IM FPGA	17.10.1	1.22	1.22	1.15	0.95	2.0
CEM FPGA		6.0	5.2	5G mode:	10G mode:	9.3
				6.5	7.3	
				10G mode:	20G mode:	
				7.9	7.3	
IM FPGA	17.9.2	1.22	1.22	1.15	0.95	2.0
CEM FPGA		6.0	5.2	5G mode:	10G mode:	9.1
				6.5	7.2	
				10G mode:	20G mode:	
				7.9	7.2	
IM FPGA	17.9.1	1.22	1.22	1.15	0.93	2.0
CEM FPGA		6.0	5.2	5G mode:	10G mode:	9.1
				6.5	7.2	
				10G mode:	20G mode:	
				7.9	7.2	

Category	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA (NCS 4200-48T1E1-CE)	48 X T3/E3 CEM Interface Module FPGA (NCS 4200-48T3E3-CE)	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA (NCS4 200-1T8S-10CS)	NCS 4200-1T8S-20CS	NCS4200-3GMS
IM FPGA	17.8.1	1.22	1.22	1.15	0.93	2.0
CEM FPGA	-	6	5.2	5G mode:	10G mode:	9.0
				6.5	7.0	
				10G mode:	20G mode:	
				7.9	6.0	
IM FPGA	17.7.1	1.22	1.22	1.15	0.93	2.0
CEM FPGA		0x52110052	0x52520052	5G mode:	10G mode:	0x10030076
				0x10090065	0x10290051	
				10G mode:	20G mode:	
				0x10070079	0x10290051	
IM FPGA	17.6.2	1.22	1.22	1.15	0.93	2.0
CEM FPGA		0x52110052	0x52520052	5G mode:	10G mode:	0x10030076
				0x10090065	0x10290051	
				10G mode:	20G mode:	
				0x10070079	0x10290051	
IM FPGA	17.6.1	1.22	1.22	1.15	0.93	2.0
CEM FPGA	-	0x52110052	0x52520052	5G mode:	10G mode:	0x10030076
				0x10090065	0x10290051	
				10G mode:	20G mode:	
				0x10070079	0x10290051	
IM FPGA	17.5.1	1.22	1.22	1.15	0.93	2.0
CEM FPGA		0x52050052	0x52420052	5G mode:	10G mode:	0x10020076
				0x10210063	0x10090051	
				10G mode:	20G mode:	
				0x10530078	0x10090051	

Cisco IOS XE Release	NCS4200-1T16G -PS	NCS4200-1T8LR -PS	NCS4200-8T -PS	NCS4200-2Q -P	NCS4200-1H -PK	NCS4200-2H -PQ	NCS4200 -1T16LR
17.15.1	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.13.1	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.12.1	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.11.1a	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.10.1	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.10.1	1.129	69.32	0.21	0.21	0.20	0.20	69.24
17.9.2	1.129	69.32	0.21	0.21	0.22	0.20	69.24
17.9.1	1.129	69.32	0.21	0.21	0.22	0.20	69.24
17.8.1	1.129	69.32	0.21	0.21	0.22	0.20	69.24
17.7.1	1.129	1.129	0.21	0.21	0.22	0.20	69.24
17.6.1	1.129	1.129	0.21	0.21	0.22	0.20	69.24
17.5.1	1.22	1.22	1.15	0.93	2.0	0.23	0.20
17.4.1	1.129	69.24	0.21	0.22	0.20	3.4	1.129

Table 6: Supported Ethernet IM FPGA/FPD versions for NCS 4206-RSP3 and NCS 4216

Table 7: FPGA, HoFPGA, and ROMMON Versions for Cisco IOS XE 17.15.1 Release

Platform	Interface Module	FPGA Current Version	FPGA Minimum Required Version	RSP HoFPGA Active	RSP HoFPGA Standby	ROMMON
NCS420X-RSP-128	NCS4200-1T8LR-PS	69.32	69.32	69.32	69.32	15.6(57r)S
NCS4206-RSP	NCS4200-1H-PK	0.20	0.20	69.32	69.32	15.6(57r)S
	NCS4200-8T-PS	0.22	0.21			
	NCS4200-1T8LR-PS	69.32	69.32			
NCS4216-RSP	NCS4200-1H-PK	0.20	0.20	20040034	20040034	15.6(57r)S

Additional References

Deferrals

Cisco IOS software images are subject to deferral. We recommend that you view the deferral notices at the following location to determine whether your software release is affected: http://www.cisco.com/en/US/products/products_security_advisories_listing.html.

Field Notices and Bulletins

• Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at http://www.cisco.com/en/US/support/tsd products field notice summary.html.

MIB Support

The below table summarizes the supported MIBs on the Cisco NCS 4206 and Cisco NCS 4216.

Supported MIBs		
BGP4-MIB (RFC 1657)	CISCO-IMAGE-LICENSE-MGMT-MIB	MPLS-LDP-STD-MIB (RFC 3815)
CISCO-BGP-POLICY-ACCOUNTING-MIB	CISCO-IMAGE-MIB	MPLS-LSR-STD-MIB (RFC 3813)
CISCO-BGP4-MIB	CISCO-IPMROUTE-MIB	MPLS-TP-MIB
CISCO-BULK-FILE-MIB	CISCO-LICENSE-MGMT-MIB	MSDP-MIB
CISCO-CBP-TARGET-MIB	CISCO-MVPN-MIB	NOTIFICATION-LOG-MIB (RFC 3014)
CISCO-CDP-MIB	CISCO-NETSYNC-MIB	OSPF-MIB (RFC 1850)
CISCO-CEF-MIB	CISCO-OSPF-MIB (draft-ietf-ospf-mib-update-05)	OSPF-TRAP-MIB (RFC 1850)
CISCO-CLASS-BASED-QOS-MIB	CISCO-OSPF-TRAP-MIB (draft-ietf-ospf-mib-update-05)	PIM-MIB (RFC 2934)
CISCO-CONFIG-COPY-MIB	CISCO-PIM-MIB	RFC1213-MIB
CISCO-CONFIG-MAN-MIB	CISCO-PROCESS-MIB	RFC2982-MIB
CISCO-DATA-COLLECTION-MIB	CISCO-PRODUCTS-MIB	RMON-MIB (RFC 1757)
CISCO-EMBEDDED-EVENT-MGR-MIB	CISCO-PTP-MIB	RSVP-MIB
CISCO-ENHANCED-MEMPOOL-MIB	CISCO-RF-MIB	SNMP-COMMUNITY-MIB (RFC 2576)
CISCO-ENTITY-ALARM-MIB	CISCO-RTTMON-MIB	SNMP-FRAMEWORK-MIB (RFC 2571)
CISCO-ENTITY-EXT-MIB	CISCO-SONET-MIB	SNMP-MPD-MIB (RFC 2572)

[•] Bulletins—You can find bulletins at http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html.

Supported MIBs		
CISCO-ENTITY-FRU-CONTROL- MIB	CISCO-SYSLOG-MIB	SNMP-NOTIFICATION-MIB (RFC 2573)
CISCO-ENTITY-SENSOR-MIB	DS1-MIB (RFC 2495)	SNMP-PROXY-MIB (RFC 2573)
CISCO-ENTITY-VENDORTYPE-OID-MIB	ENTITY-MIB (RFC 4133)	SNMP-TARGET-MIB (RFC 2573)
CISCO-FLASH-MIB	ENTITY-SENSOR-MIB (RFC 3433)	SNMP-USM-MIB (RFC 2574)
CISCO-FTP-CLIENT-MIB	ENTITY-STATE-MIB	SNMPv2-MIB (RFC 1907)
CISCO-IETF-ISIS-MIB	EVENT-MIB (RFC 2981)	SNMPv2-SMI
CISCO-IETF-PW-ATM-MIB	ETHERLIKE-MIB (RFC 3635)	SNMP-VIEW-BASED-ACM-MIB (RFC 2575)
CISCO-IETF-PW-ENET-MIB	IF-MIB (RFC 2863)	SONET-MIB
CISCO-IETF-PW-MIB	IGMP-STD-MIB (RFC 2933)	TCP-MIB (RFC 4022)
CISCO-IETF-PW-MPLS-MIB	IP-FORWARD-MIB	TUNNEL-MIB (RFC 4087)
CISCO-IETF-PW-TDM-MIB	IP-MIB (RFC 4293)	UDP-MIB (RFC 4113)
CISCO-IF-EXTENSION-MIB	IPMROUTE-STD-MIB (RFC 2932)	CISCO-FRAME-RELAY-MIB
CISCO-IGMP-FILTER-MIB	MPLS-LDP-GENERIC-STD-MIB (RFC 3815)	

MIB Documentation

To locate and download MIBs for selected platforms, Cisco IOS and Cisco IOS XE releases, and feature sets, use Cisco MIB Locator found at the following location: http://tools.cisco.com/ITDIT/MIBS/servlet/index. To access Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank e-mail to cco-locksmith@cisco.com. An automatic check will verify that your e-mail address is registered with Cisco.com. If the check is successful, account details with a new random password will be e-mailed to you. Qualified users can establish an account on Cisco.com by following the directions found at the following location: http://tools.cisco.com/RPF/register/register.do

Open Source License Notices

For a listing of the license notices for open source software used in Cisco IOS XE 3S Releases, see the documents accessible from the License Information page at the following location:

http://www.cisco.com/en/US/products/ps11174/products_licensing_information_listing.html

- To receive timely, relevant information from Cisco, sign up at Cisco Profile Manager.
- To get the business impact you're looking for with the technologies that matter, visit Cisco Services.
- To submit a service request, visit Cisco Support.
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit Cisco Marketplace.
- To obtain general networking, training, and certification titles, visit Cisco Press.

• To find warranty information for a specific product or product family, access Cisco Warranty Finder.

Cisco Bug Search Tool

Cisco Bug Search Tool (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.



What's New for Cisco IOS XE 17.15.1

- What's New in Hardware for Cisco IOS XE 17.15.1, on page 15
- What's New in Software for Cisco IOS XE 17.15.1, on page 15

What's New in Hardware for Cisco IOS XE 17.15.1

There are no new hardware features introduced for this release.

What's New in Software for Cisco IOS XE 17.15.1

Feature	Description	
Alarms		
SONET Alarms for APS	• With Automatic Protection Switching (APS), SONET alarms soaking as per the recommendation from GR-253.	
	• Alarm is raised or cleared during APS manual, force, and lock out switch actions.	
	• When traffic is switched to an alternate link in the APS group, the severity of the alarms is affected based on service impact.	
SD-BER and SF -BER Alarms for T1/E1 and T3/E3 services	Signal Failure-Bit Error Rate (SF-BER) and Signal Degrade-BER (SD-BER) alarms are declared when there is a signal failure or signal degradation that happens in the traffic.	
	These alarms may be raised when the error rate of a given entity exceeds the user-configured BER threshold value.	
	This helps the administrator to take corrective actions.	
СЕМ		
DDS DS0 Remote Latching Loopback	DS0 loopback is used for testing and troubleshooting the T1 or E1, T3 or E3, and OCx channel over PSN. You can configure DS0 loopback on these controllers for remote devices.	

Feature	Description
Protection Switching Count for Protected SONET Interface	In SONET with redundancy, an Automatic protection switching (APS) occurs between working and standby protection links due to reasons like a circuit failure. Whenever the switching happens, the switching count is tracked using a Protection Switching Count (PSC) parameter.
	Depending on the PSC count, you can debug the network to identify the reason for extensive switching and work on the corrective actions.
TCAM and NFT Co	ommands
TCAM and NFT Commands	New commands have been introduced for the Ternary Content-Addressable Memory (TCAM) and NFT.
	ТСАМ
	You can now view the Ternary Content-Addressable Memory (TCAM) utilization for each control plane TCAM entry.
	Command: show platform hardware pp active tcam utilization control-plane-sessions
	NFT
	• You can now enable the collection of the packets punted to the CPU from the NFT hash table.
	Command: platform nft-summarization enable
	• Once the above command is enabled, you can use a timer to clean up the NFT hash table.
	Command: platform nft-summarization timer-value
	• You can view a summary of the packets punted to the CPU from the NFT hash table.
	Command: show platform hardware pp active infrastructure pi nft summary



Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The "Open Caveats" sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The "Resolved Caveats" sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Resolved Caveats Cisco IOS XE 17.15.1, on page 17
- Open Caveats Cisco IOS XE 17.15.1, on page 18
- Cisco Bug Search Tool, on page 18

Resolved Caveats - Cisco IOS XE 17.15.1

Identifier	Headline
CSCwi76112	Message to be displayed for M13 framing when configured with clear-channel
CSCwi60730	Speed LED status is not correct when sonet/sdh mode is configured
CSCwi33111	Eomer T1: Sev changes back from major to minor after IM OIR.
CSCwj06370	Serial cease traffic when configuring module other port
CSCwj05647	3GMS Serial interface protocol down with specific Modem
CSCwj12451	Update 2^20-O151 QRSS bert help string with QRSS Keyword in NCS42xx platform
CSCwj44502	DCR clocking fails to get acquired on the with sts1-E mode
CSCwj99522	Need to support dtr not-used CLI in RS232 transparent mode

Identifier	Headline
CSCwi92203	Channelized DS3: RAI is propagating to all DS1's when DS3 RAI is asserted

Open Caveats - Cisco IOS XE 17.15.1

Identifier	Headline
CSCwk58917	L-bit propogation not enabled for LOF alarm after framing change with framed SAToP
CSCwk02087	17.6.3-BFD stuck in INIT state for interface Te0/0/0 & Te0/4/3
CSCwh75614	Increased CPU after upgrading router to 17.6.3 from 16.9.4 when 1000 SLM/DMM sessions are configured
CSCwj60760	Confd process not in Started State in 5 mins after netconf-yang config is done
CSCwk27810	After reconfiguring second synce source the QL-failed for that source interface and ranking also 254
CSCwj38216	BDI ARP is not learning but peer side BDI MAC is learning through VC

Cisco Bug Search Tool

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at http://www.cisco.com/web/applicat/cbsshelp/help.html