



Cisco IP Phone 6800 Series Multiplatform Phones Release Notes for Firmware Release 11.1(1) SR3

First Published: 2018-12-18

Release Notes

Use these release notes with the following Cisco IP Phone 6800 Series Multiplatform Phones running SIP Firmware Release 11.1(1)SR3.

- Cisco IP Phone 6841 Multiplatform Phones
- Cisco IP Phone 6851 Multiplatform Phones

The following table describes the individual phone requirements.

| Phone | Support Requirements |
|---|--|
| Cisco IP Phone 6841 and 6851 Multiplatform Phones | BroadSoft BroadWorks 21.0 MetaSphere CFS version 9.4 Asterisk 13.1 |

Related Documentation

Cisco IP Phone 6800 Documentation

See the publications that are specific to your language, phone model, and multiplatform firmware release. Navigate from the following Uniform Resource Locator (URL):

<https://www.cisco.com/c/en/us/support/collaboration-endpoints/ip-phone-6800-series-multiplatform-firmware/tsd-products-support-series-home.html>

New and Changed Features

Handset on Cisco IP Phone 6841 and 6851 Multiplatform Phones

For Cisco IP Phone 6841 and 6851 Multiplatform Phones, the **WideBand Handset Enable** field enables or disables the phone to use a wideband handset. By default, the system configures this field against the phone's hardware version. The default setting is **No** for hardware version 00 and 01, and **Yes** for hardware version 02.

You can also change the setting as needed. If your phone is using a wideband handset, set this field to **Yes**.

The **WideBand Handset Enable** field is located in the **General** section of the **Voice > Phone** tab on the phone administration web page.

This feature has no user impact.

Upgrade the Firmware

The Cisco IP Phone 6800 Series Multiplatform Phones support a single image upgrade using the TFTP, HTTP, or HTTPS protocols with a URL.

After the firmware upgrade completes, the phone reboots automatically.

Procedure

-
- Step 1** Click the following URL:
<https://software.cisco.com/download/navigator.html?mdfid=286318380&i=rm>
- Step 2** Choose **IP Phone 6800 Series with Multiplatform Firmware** in the middle pane.
- Step 3** Choose your phone model in the right pane.
- Step 4** Choose the **Multiplatform Firmware** software type.
- Step 5** Under **Latest**, choose the **11.1.1 MSR3** folder.
- Step 6** (Optional) Place your mouse pointer on the filename to display the file details and checksum values.
- Step 7** Download the `cp-68xx.11-1-1MSR3-1_REL.zip` file.
- Step 8** Click **Accept License Agreement** when you accept the Cisco End User License.
- Step 9** Unzip the firmware files.
- Step 10** Put the files in the TFTP, HTTP, or HTTPS download directory.
- Step 11** Configure the **Upgrade Rule** on the **Provisioning** tab in the web page with the valid URL.

Use the URL format—`<protocol>://<serv_ip[:port]>/<filepath>/sipxxx.loads`

You can also upgrade the third-party call control by using a URL in the web browser—

`<protocol>://<serv_ip[:port]>/<filepath>/sipxxx.loads`

Example

`https://10.74.10.225/firmware/sip68xx.11-1-1MSR3-1.loads`

Note Use the `*.loads` file in the URL. The `*.zip` file contains other files.

Limitations and Restrictions

Phone Behavior During Times of Network Congestion

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

Caller Identification and Other Phone Functions

Caller identification or other phone functions have not been verified with third-party applications for the visually or hearing impaired.

Caveats

View Caveats

You can search for caveats using the Cisco Bug Search tool.

Known caveats (bugs) are graded according to severity level, and can be either open or resolved.

Before you begin

To view the caveats, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

Procedure

- Step 1** Perform one of the following actions:
- To find all caveats, use this URL:
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1\(1\)&sb=anfr&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1(1)&sb=anfr&bt=custV)
 - To find all open caveats, use this URL:
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1\(1\)&sb=anfr&sts=open&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1(1)&sb=anfr&sts=open&bt=custV)
 - To find all resolved caveats, use this URL:
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1\(1\)&sb=anfr&sts=fd&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286318380&rls=11.1(1)&sb=anfr&sts=fd&bt=custV)
- Step 2** When prompted, log in with your Cisco.com user ID and password.
- Step 3** (Optional) To look for information about a specific problem, enter the bug ID number in the Search for field, and press **Enter**.
-

Open Caveats

The following list contains the severity 1, 2, and 3 defects that are open for the Cisco IP Phone 6800 Series Multiplatform Phones that use Firmware Release 11.1(1)SR3.

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier. You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of the open defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 3](#).

- CSCvg00958 Phone doesn't send 420 Bad Extension when it receives INVITE with unsupported value
- CSCvg10304 Dual Mode and IP Pref is IPv4, Phone does not fallback to IPv4 when IPv4 is up
- CSCvg42260 Sometimes packet capture may not be terminated
- CSCvg59538 No record in reboot reason when the reboot is triggered by vlan change in IPv6 only mode
- CSCvg61600 Geolocation status messages show up in English words with other locale
- CSCvg63918 Phone still uses the old device after changing preferred audio device in ringback status
- CSCvg70042 Wrong LED when DUT is configured call park shared-line ext function with wrong IP as PROXY
- CSCvg75579 Resync failed while using Digest Authentication with valid long password and username
- CSCvg77675 Select line key fail when barge fail
- CSCvg83031 Call center queue states can not show "full", when queue threshold is exceeded.
- CSCvg84786 Provisioning Status shows incorrect while use no <flat-profile> in resync file
- CSCvg96811 Hoteling subscribe will not retry after server unreachable or response error.
- CSCvh02982 Initiate Paging call during upgrade, and the upgrade will fail after the call is terminated
- CSCvh13556 Parameter RTP Packet Size validation does not work
- CSCvh16152 MOS data is all zeroes in first second, phone should not send out this invalid data
- CSCvh17328 Recent call xmpp status is not updated when change xmpp presence to offline
- CSCvh17346 Configuration, "Login Invisible" does not work when user login
- CSCvh19488 Generate PRT will make phone reboot when "PRT Upload Rule" can't be queried by DNS in HK locale
- CSCvh23468 RFC2833 DTMF digits failing with AMR-WB mode
- CSCvh29624 Phone does not preserve the existing call when on secondary SBC and failover to primary SBC
- CSCvh52720 Ignore group paging on active call cannot work
- CSCvh52884 Paging call can be answered when paging service disabled
- CSCvh66529 Phone reboots - Not handling multipart/mixed and multipart/related MIME type properly
- CSCvh69377 The max name length of Auto defined sd is inconsistent with normal sd
- CSCvh71029 Change of Hold Reminder Timer by resync will cause phone reboot
- CSCvh71043 Phone will reboot after received illegal value % for parameter

- CSCvh72506 Phone doesn't use the last DNS cached record if TTL expire and no response from DNS server
- CSCvh76496 Phone cannot get the correct content from HTTP 301 response
- CSCvh76520 Phone will always report download fail when receive 301 after reboot
- CSCvh76689 Phone cannot handle the content from HTTP 302 response
- CSCvh76791 Provisioning Status is wrong when receive 500/501/503
- CSCvh78587 Phone can't accept a long realm in 401 when upgrade

Resolved Caveats

The following list contains the severity 1, 2, and 3 defects that are resolved for the Cisco IP Phone 6800 Series Multiplatform Phones that use Firmware Release 11.1(1)SR3.

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier. You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 3](#).

- CSCvm04387 494 Security Agreement Required: Error not handled

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2018 Cisco Systems, Inc. All rights reserved.