



# Cisco IP Conference Phone 7832 Multiplatform Phones Release Notes for Firmware Release 11.3(1)SR2

---

**First Published:** 2020-06-15

## Release Notes

Use these release notes with the Cisco IP Conference Phone 7832 Multiplatform Phones running SIP Firmware Release 11.3(1)SR2.

The following table describes the individual phone requirements.

Phone	Support Requirements
Cisco IP Conference Phone 7832 Multiplatform Phones	BroadSoft BroadWorks 22.0 MetaSphere CFS version 9.5 Asterisk 11.0

## New and Changed Features

This release is a maintenance release and doesn't contain any new or enhanced features.

To view the resolved and open caveats for this release, see [View Caveats, on page 3](#).

## Cisco IP Conference Phone 7832 Documentation

Refer to publications that are specific to your language and call control system. Navigate from the following documentation URL:

<https://www.cisco.com/c/en/us/support/collaboration-endpoints/ip-phone-7800-series-multiplatform-firmware/tsd-products-support-series-home.html>

## Upgrade the Firmware

The Cisco IP Conference Phone 7832 Multiplatform Phones support a single image upgrade using TFTP, HTTP, or HTTPS protocols with a URL.

After the firmware upgrade completes, the phone reboots automatically.

### Procedure

---

**Step 1** Click the following URL:

<https://software.cisco.com/download/navigator.html?mdfid=286311381>

- Step 2** Select **IP Phone 7800 Series with Multiplatform Firmware** in the center pane.
- Step 3** Select **IP Conference Phone 7832 with Multiplatform Firmware** in the right pane.
- Step 4** Select the **Multiplatform Firmware** software type.
- Step 5** Under **Latest Release**, select the **11.3.1 MSR2-6** folder.
- Step 6** (Optional) Place your mouse pointer on the file name to display the file details and checksum values.
- Step 7** Download the `cmterm-7832.11-3-1MSR2-6_REL.zip` file.
- Step 8** Click **Accept License Agreement** when you accept the software license.
- Step 9** Unzip the firmware files.
- Step 10** Put the files in the TFTP, HTTP, or HTTPS download directory.
- Step 11** Upgrade the phone firmware with one of these methods.

- Upgrade the phone firmware from the phone administration web page:
  - a. On the phone administration web page, go to **Admin Login > Advanced > Voice > Provisioning** tab, **Firmware Upgrade** section. In the **Upgrade Rule** field, enter the load file URL as described below.

Load file URL format:

```
<upgrade protocol>://<server ip address>[:<port>]/<path>/<file name>.loads
```

Examples:

```
http://10.73.10.223/firmware/sip7832.11-3-1MSR2-6.loads
```

```
https://server.domain.com/firmware/sip7832.11-3-1MSR2-6.loads
```

- b. Click **Submit All Changes**.

- Upgrade the phone firmware directly from your web browser:

In the address bar of your web browser, enter the phone upgrade URL as described below.

Phone upgrade URL format:

```
<phone protocol>://<phone ip address[:port]>/admin/upgrade?<load file URL>
```

Load file URL format:

```
<upgrade protocol>://<server ip address>[:<port>]/<path>/<file name>.loads
```

Example:

```
https://10.74.10.225/admin/upgrade?http://10.73.10.223/firmware/sip7832.11-3-1MSR2-6.loads
```

```
https://10.74.10.225/admin/upgrade?https://server.domain.com/firmware/sip7832.11-3-1MSR2-6.loads
```

**Note** Specify the `<file name>.loads` file in the URL. The `<file name>.zip` file contains other files.

## Limitations and Restrictions

### Phone Behavior During Times of Network Congestion

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

## View Caveats

You can search for caveats (bugs) with the Cisco Bug Search tool.

Known caveats are graded according to severity level, and are either open or resolved.

### Before you begin

You have your Cisco.com user ID and password.

### Procedure

- 
- Step 1** Click one of the following links:
- To view all caveats that affect this release:  
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3\(1\)&sb=anfr&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3(1)&sb=anfr&bt=custV)
  - To view open caveats that affect this release:  
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3\(1\)&sb= afr&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3(1)&sb= afr&bt=custV)
  - To view resolved caveats that affect this release:  
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3\(1\)&sb=fr&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=&pf=prdNm&pfVal=286319849&rls=11.3(1)&sb=fr&bt=custV)
- Step 2** When prompted, log in with your Cisco.com user ID and password.
- Step 3** (Optional) For information about a specific caveat, enter the bug ID number (*CSCxxxxxxx*) in the **Search for** field, and press **Enter**.
- 

## Open Caveats

The following list contains the severity 1, 2, and 3 defects that are open for the Cisco IP Phone 7800 Series Multiplatform Phones that use Firmware Release 11.3(1)SR2.

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered `cisco.com` user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of the open defects or to view specific bugs, access the Bug Search Toolkit as described in [View Caveats, on page 3](#).

There are no open caveats in this release.

## Resolved Caveats

The following list contains the severity 1, 2, and 3 defects that are resolved for the Cisco IP Conference Phone 7832 Multiplatform Phones that use Firmware Release 11.3(1)SR2.

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered `cisco.com` user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in [View Caveats, on page 3](#).

- CSCvu20649 MPP phones - unable to activate via device activation code
- CSCvs70834 LDAP reverse lookup not pulling info from LDAP server on incoming INVITE
- CSCvs59424 3pcc-88xx: Phone is not uploading the config when Report To Server is set to On
- CSCvs54502 3pcc-8800: phone restarts when an incoming call arrive at second line
- CSCvs88350 MPP phones Multicast Paging Ended By Itself
- CSCvs54500 Error prompt during Profile Account Setup and default input alphanumeric
- CSCvt25512 MPP phone configuration displays unsupported locales
- CSCvt22995 MPP does not show BLF when NOTIFY has different URI
- CSCvt52122 Transferor hears busy signal during consultative transfer
- CSCvu41656 Skip Valid From date for EDOS and GDS

## Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

---

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2020 Cisco Systems, Inc. All rights reserved.