



## **Release Notes for Cisco cBR Series Converged Broadband Routers for Cisco IOS XE Gibraltar 16.10.x**

**First Published:** 2018-11-27

**Last Modified:** 2019-08-14

### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883





# CONTENTS

---

## CHAPTER 1

### **Introduction 1**

System Requirements 2

Memory Requirements 2

Hardware Supported 3

Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1g 4

Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1f 5

Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1d 6

Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1c 7

Microcode Software 8

Feature Support 8

Cisco cBR Series Converged Broadband Routers and Cisco Remote PHY Devices Version  
Compatibility 8

New and Changed Information 9

New Software Features in Cisco IOS XE Gibraltar 16.10.1g 9

New Software Features in Cisco IOS XE Gibraltar 16.10.1f 9

New Software Features in Cisco IOS XE Gibraltar 16.10.1d 10

New Software Features in Cisco IOS XE Gibraltar 16.10.1c 10

Modified Software Features in Cisco IOS XE Gibraltar 16.10.1g 11

Modified Software Features in Cisco IOS XE Gibraltar 16.10.1f 11

Modified Software Features in Cisco IOS XE Gibraltar 16.10.1d 11

Modified Software Features in Cisco IOS XE Gibraltar 16.10.1c 12

New Hardware Features in Cisco IOS XE Gibraltar 16.10.1g 12

New Hardware Features in Cisco IOS XE Gibraltar 16.10.1f 12

New Hardware Features in Cisco IOS XE Gibraltar 16.10.1d 12

New Hardware Features in Cisco IOS XE Gibraltar 16.10.1c 12

MIBs 12

New and Changed MIB Information in Cisco IOS XE Gibraltar 16.10.1g 12

New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1f 13

New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1d 13

New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1c 14

Best Practice Manual of Procedure for Cisco IOS XE Gibraltar 16.10.x Upgrade 14

Cisco cBR Series Converged Broadband Routers Documentation References 14

Obtaining Documentation and Submitting a Service Request 14

---

**CHAPTER 2**

**Caveat List 15**

Cisco Bug Search 15

Open Caveats Cisco IOS XE Gibraltar 16.10.1g 16

Open Caveats Cisco IOS XE Gibraltar 16.10.1f 17

Open Caveats Cisco IOS XE Gibraltar 16.10.1d 17

Open Caveats Cisco IOS XE Gibraltar 16.10.1c 18

Resolved Caveats Cisco IOS XE Gibraltar 16.10.1g 19

Resolved Caveats Cisco IOS XE Gibraltar 16.10.1f 20

Resolved Caveats Cisco IOS XE Gibraltar 16.10.1d 21

Resolved Caveats Cisco IOS XE Gibraltar 16.10.1c 22



# CHAPTER 1

## Introduction

---



- Note** Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.
- Use faceted search to locate content that is most relevant to you.
  - Create customized PDFs for ready reference.
  - Benefit from context-based recommendations.

Get started with the Content Hub at [content.cisco.com](http://content.cisco.com) to craft a personalized documentation experience. Do provide feedback about your experience with the Content Hub.

---

This release notes contain information about downloading and installing Cisco IOS XE Gibraltar 16.10.x. It also provides new and changed information, hardware support, limitations and restrictions, and caveats for Cisco IOS XE Gibraltar 16.10.x.

We recommend that you view the field notices for this release to see if your software or hardware platforms are affected. If you have an account on Cisco.com, you can find field notices at [http://www.cisco.com/en/US/customer/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/customer/support/tsd_products_field_notice_summary.html) .

If you do not have a Cisco.com login account, you can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html) .



- Note** Cisco IOS XE Gibraltar 16.10.x is generally available for field deployment. However, we recommend that you validate and qualify Cisco IOS XE Gibraltar 16.10.x in a limited field trial with your specific network configuration requirements in order to ensure a smoother, faster, and successful field deployment.
- 



- Note** Due to the performance impact, it is recommended to deploy Cisco IOS XE Gibraltar 16.10.1d or a release later than Cisco IOS XE Gibraltar 16.10.1f for RPHY applications.
- 

This chapter includes the following sections:

- [System Requirements, on page 2](#)
- [New and Changed Information, on page 9](#)

- [MIBs, on page 12](#)
- [Best Practice Manual of Procedure for Cisco IOS XE Gibraltar 16.10.x Upgrade, on page 14](#)
- [Cisco cBR Series Converged Broadband Routers Documentation References, on page 14](#)
- [Obtaining Documentation and Submitting a Service Request, on page 14](#)

## System Requirements

These sections describe the system requirements for Cisco IOS XE Gibraltar 16.10.x:

### Memory Requirements

The following table displays the memory recommendations for the Cisco cBR Series Converged Broadband Routers with Cisco IOS XE Gibraltar 16.10.1g feature sets.

**Table 1: Memory Recommendations for the Cisco cBR Series Converged Broadband Routers**

Feature Set	Cisco cBR Route Processor	Software Image	Recommended Flash Memory	Recommended DRAM Memory	Runs From
CISCO IOS-XE universalk9	Cisco cBR8 (CBR) Processor	cbrsup-universalk9.16.10.01g.SPA.bin	8G	48G	Bootflash:
CISCO IOS-XE CLC K9	Cisco cBR8 (CYLONS) Processor	cbrsup-universalk9.16.10.01g.SPA.bin	8G	16G	Supervisor

The following table displays the memory recommendations for the Cisco cBR Series Converged Broadband Routers with Cisco IOS XE Gibraltar 16.10.1f feature sets.

**Table 2: Memory Recommendations for the Cisco cBR Series Converged Broadband Routers**

Feature Set	Cisco cBR Route Processor	Software Image	Recommended Flash Memory	Recommended DRAM Memory	Runs From
CISCO IOS-XE universalk9	Cisco cBR8 (CBR) Processor	cbrsup-universalk9.16.10.01f.SPA.bin	8G	48G	Bootflash:
CISCO IOS-XE CLC K9	Cisco cBR8 (CYLONS) Processor	cbrsup-universalk9.16.10.01f.SPA.bin	8G	16G	Supervisor

The following table displays the memory recommendations for the Cisco cBR Series Converged Broadband Routers with Cisco IOS XE Gibraltar 16.10.1d feature sets.

**Table 3: Memory Recommendations for the Cisco cBR Series Converged Broadband Routers**

Feature Set	Cisco cBR Route Processor	Software Image	Recommended Flash Memory	Recommended DRAM Memory	Runs From
CISCO IOS-XE universalk9	Cisco cBR8 (CBR) Processor	cbrsup-universalk9.16.10.01d.SPA.bin	8G	48G	Bootflash:
CISCO IOS-XE CLC K9	Cisco cBR8 (CYLONS) Processor	cbrsup-universalk9.16.10.01d.SPA.bin	8G	16G	Supervisor

The following table displays the memory recommendations for the Cisco cBR Series Converged Broadband Routers with Cisco IOS XE Gibraltar 16.10.1c feature sets.

**Table 4: Memory Recommendations for the Cisco cBR Series Converged Broadband Routers**

Feature Set	Cisco cBR Route Processor	Software Image	Recommended Flash Memory	Recommended DRAM Memory	Runs From
CISCO IOS-XE universalk9	Cisco cBR8 (CBR) Processor	cbrsup-universalk9.16.10.01c.SPA.bin	8G	48G	Bootflash:
CISCO IOS-XE CLC K9	Cisco cBR8 (CYLONS) Processor	cbrsup-universalk9.16.10.01c.SPA.bin	8G	16G	Supervisor

## Hardware Supported

For detailed information about the hardware supported in Cisco IOS XE Release 16.10.x and its maintenance releases, see:

[http://www.cisco.com/c/en/us/td/docs/cable/cbr/installation/guide/b\\_cbr\\_how\\_and\\_what\\_to\\_order.html](http://www.cisco.com/c/en/us/td/docs/cable/cbr/installation/guide/b_cbr_how_and_what_to_order.html).



**Note** The Cisco cBR chassis must house line cards with either Downstream DOCSIS 3.0 PHY modules or Downstream DOCSIS 3.1 PHY modules. Mixed configuration is not supported.

## Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1g

To determine the version of the Cisco IOS XE software running on your Cisco cBR Series Converged Broadband Routers, log in and enter the **show version EXEC** command:

```
Router#show version
Load for five secs: 34%/3%; one minute: 83%; five minutes: 82%
Time source is NTP, 19:14:36.345 PDT Wed Aug 14 2019
Cisco IOS XE Software, Version 16.10.01g
Cisco IOS Software [Gibraltar], cBR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version
16.10.1g, RELEASE SOFTWARE (fc2)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2019 by Cisco Systems, Inc.
Compiled Tue 13-Aug-19 15:23 by mcpre
```

```
Cisco IOS-XE software, Copyright (c) 2005-2019 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS-XE software are
licensed under the GNU General Public License ("GPL") Version 2.0. The
software code licensed under GPL Version 2.0 is free software that comes
with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such
GPL code under the terms of GPL Version 2.0. For more details, see the
documentation or "License Notice" file accompanying the IOS-XE software,
or the applicable URL provided on the flyer accompanying the IOS-XE
software.
```

```
ROM: IOS-XE ROMMON
```

```
guam uptime is 13 minutes
Uptime for this control processor is 19 minutes
System returned to ROM by reload at 21:41:37 PDT Tue Aug 13 2019
System restarted at 19:01:06 PDT Wed Aug 14 2019
System image file is "harddisk:cbrsup-universalk9.16.10.01g.SPA.bin"
Last reload reason: Reload Command
```

```
This product contains cryptographic features and is subject to United
States and local country laws governing import, export, transfer and
use. Delivery of Cisco cryptographic products does not imply
third-party authority to import, export, distribute or use encryption.
Importers, exporters, distributors and users are responsible for
compliance with U.S. and local country laws. By using this product you
agree to comply with applicable laws and regulations. If you are unable
to comply with U.S. and local laws, return this product immediately.
```

```
A summary of U.S. laws governing Cisco cryptographic products may be found at:
http://www.cisco.com/wwl/export/crypto/tool/stqrg.html
```

```
If you require further assistance please contact us by sending email to
export@cisco.com.
```

```
Smart Licensing Status: UNREGISTERED/EVAL MODE
```

```
Cisco cBR-8 (cBR) processor (revision CBRVE) with 13312575K/6147K bytes of memory.
Processor board ID FXS1849Q1FE
16 Ten Gigabit Ethernet interfaces
4 Hundred Gigabit Ethernet interfaces
32768K bytes of non-volatile configuration memory.
50331648K bytes of physical memory.
7649279K bytes of eUSB flash at bootflash:.
```



```
234365527K bytes of SATA hard disk at harddisk:.  
60718080K bytes of USB flash at usb1:.  
0K bytes of WebUI ODM Files at webui:.
```

```
Configuration register is 0x2
```

## Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1f

To determine the version of the Cisco IOS XE software running on your Cisco cBR Series Converged Broadband Routers, , log in and enter the **show version EXEC** command:

```
Router#show version  
Load for five secs: 21%/0%; one minute: 17%; five minutes: 18%  
Time source is NTP, 12:46:14.081 PDT Fri May 31 2019  
Cisco IOS XE Software, Version 16.10.01f  
Cisco IOS Software [Gibraltar], cBR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version  
16.10.1f, RELEASE SOFTWARE (fc2)  
Technical Support: http://www.cisco.com/techsupport  
Copyright (c) 1986-2019 by Cisco Systems, Inc.  
Compiled Thu 30-May-19 13:24 by mcpre
```

```
Cisco IOS-XE software, Copyright (c) 2005-2019 by cisco Systems, Inc.  
All rights reserved. Certain components of Cisco IOS-XE software are  
licensed under the GNU General Public License ("GPL") Version 2.0. The  
software code licensed under GPL Version 2.0 is free software that comes  
with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such  
GPL code under the terms of GPL Version 2.0. For more details, see the  
documentation or "License Notice" file accompanying the IOS-XE software,  
or the applicable URL provided on the flyer accompanying the IOS-XE  
software.
```

```
ROM: IOS-XE ROMMON
```

```
guam uptime is 15 hours, 12 minutes  
Uptime for this control processor is 15 hours, 15 minutes  
System returned to ROM by SSO Switchover at 21:27:24 PDT Thu May 30 2019  
System restarted at 21:37:19 PDT Thu May 30 2019  
System image file is "harddisk:cbrsup-universalk9.16.10.01f.SPA.bin"  
Last reload reason: Reload Command
```

```
This product contains cryptographic features and is subject to United  
States and local country laws governing import, export, transfer and  
use. Delivery of Cisco cryptographic products does not imply  
third-party authority to import, export, distribute or use encryption.  
Importers, exporters, distributors and users are responsible for  
compliance with U.S. and local country laws. By using this product you  
agree to comply with applicable laws and regulations. If you are unable  
to comply with U.S. and local laws, return this product immediately.
```

```
A summary of U.S. laws governing Cisco cryptographic products may be found at:  
http://www.cisco.com/wwl/export/crypto/tool/stqrg.html
```

```
If you require further assistance please contact us by sending email to  
export@cisco.com.
```

```
Smart Licensing Status: UNREGISTERED - REGISTRATION FAILED/EVAL MODE
```

```
Cisco cBR-8 (CBR) processor (revision CBRVE) with 12336107K/6147K bytes of memory.
```

```

Processor board ID FXS1849Q1FE
16 Ten Gigabit Ethernet interfaces
4 Hundred Gigabit Ethernet interfaces
32768K bytes of non-volatile configuration memory.
50331648K bytes of physical memory.
7739391K bytes of eUSB flash at bootflash:.
117155287K bytes of SATA hard disk at harddisk:.
3911744K bytes of USB flash at usb0:.
0K bytes of WebUI ODM Files at webui:.

```

```

Configuration register is 0x2102

```

## Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1d

To determine the version of the Cisco IOS XE software running on your Cisco cBR Series Converged Broadband Routers, , log in and enter the **show version EXEC** command:

```

Router#show version
Cisco IOS XE Software, Version 16.10.01d
Cisco IOS Software [Gibraltar], cBR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version
16.10.1d, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2019 by Cisco Systems, Inc.
Compiled Tue 26-Mar-19 22:26 by mcpre

```

Cisco IOS-XE software, Copyright (c) 2005-2019 by cisco Systems, Inc. All rights reserved. Certain components of Cisco IOS-XE software are licensed under the GNU General Public License ("GPL") Version 2.0. The software code licensed under GPL Version 2.0 is free software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such GPL code under the terms of GPL Version 2.0. For more details, see the documentation or "License Notice" file accompanying the IOS-XE software, or the applicable URL provided on the flyer accompanying the IOS-XE software.

```

ROM: IOS-XE ROMMON

```

```

BXB-TB28 uptime is 18 hours, 53 minutes
Uptime for this control processor is 18 hours, 58 minutes
System returned to ROM by reload at 13:51:35 EDT Wed Mar 27 2019
System restarted at 16:49:04 EDT Wed Mar 27 2019
System image file is "harddisk:cbrsup-universalk9.16.10.01d.SPA.bin"
Last reload reason: BootRomUpgrade

```

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: <http://www.cisco.com/wvl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to [export@cisco.com](mailto:export@cisco.com).

```
Smart Licensing Status: UNREGISTERED/EVAL MODE

Cisco cBR-8 (CBR) processor (revision CBR) with 4523766K/6147K bytes of memory.
Processor board ID FXS2038Q3GC
16 Gigabit Ethernet interfaces
32768K bytes of non-volatile configuration memory.
50331648K bytes of physical memory.
7743487K bytes of eUSB flash at bootflash:.
97620247K bytes of SATA hard disk at harddisk:.
0K bytes of WebUI ODM Files at webui:.

Configuration register is 0x2102
```

## Determining the Software Version for Cisco IOS XE Gibraltar 16.10.1c

To determine the version of the Cisco IOS XE software running on your Cisco cBR Series Converged Broadband Routers, log in and enter the **show version EXEC** command:

```
Router#show version
Load for five secs: 6%/0%; one minute: 7%; five minutes: 7%
Time source is NTP, 18:19:34.308 CST Mon Jan 28 2019
Cisco IOS XE Software, Version 16.10.01c
Cisco IOS Software [Gibraltar], cBR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version
16.10.1c, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2019 by Cisco Systems, Inc.
Compiled Fri 25-Jan-19 03:21 by mcpre
```

```
Cisco IOS-XE software, Copyright (c) 2005-2019 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS-XE software are
licensed under the GNU General Public License ("GPL") Version 2.0. The
software code licensed under GPL Version 2.0 is free software that comes
with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such
GPL code under the terms of GPL Version 2.0. For more details, see the
documentation or "License Notice" file accompanying the IOS-XE software,
or the applicable URL provided on the flyer accompanying the IOS-XE
software.
```

```
ROM: IOS-XE ROMMON
```

```
Router uptime is 2 days, 3 hours, 6 minutes
Uptime for this control processor is 2 days, 1 hour, 27 minutes
System returned to ROM by SSO Switchover at 16:48:38 CST Sat Jan 26 2019
System restarted at 16:56:16 CST Sat Jan 26 2019
System image file is "harddisk:cbrsup-universalk9.16.10.01c.SPA.bin"
Last reload reason: 4
```

```
This product contains cryptographic features and is subject to United
States and local country laws governing import, export, transfer and
use. Delivery of Cisco cryptographic products does not imply
third-party authority to import, export, distribute or use encryption.
Importers, exporters, distributors and users are responsible for
compliance with U.S. and local country laws. By using this product you
agree to comply with applicable laws and regulations. If you are unable
to comply with U.S. and local laws, return this product immediately.
```

```
A summary of U.S. laws governing Cisco cryptographic products may be found at:
http://www.cisco.com/wwl/export/crypto/tool/stqrg.html
```

If you require further assistance please contact us by sending email to [export@cisco.com](mailto:export@cisco.com).

Smart Licensing Status: REGISTERED/AUTHORIZED

Cisco cBR-8 (CBR) processor (revision CBR) with 5500542K/6147K bytes of memory.  
Processor board ID FXS175106MQ  
24 Gigabit Ethernet interfaces  
32768K bytes of non-volatile configuration memory.  
50331648K bytes of physical memory.  
7743487K bytes of eUSB flash at bootflash:.  
97620247K bytes of SATA hard disk at harddisk:.  
0K bytes of WebUI ODM Files at webui:.

Configuration register is 0x1822

## Microcode Software

This section describes microcode software that is supported for the Cisco cBR Series Converged Broadband Routers.

For more information, see [Upgrading the Cisco cBR Series Converged Broadband Routers for Cisco IOS XE Gibraltar 16.10.x](#).

## Feature Support

Cisco IOS XE software is packaged in feature sets that consist of software images that support specific platforms. The feature sets available for a specific platform depend on which Cisco IOS XE software images are included in a release. Each feature set contains a specific set of Cisco IOS XE features.



---

**Caution**

Cisco IOS XE images with strong encryption (including, but not limited to 168-bit [3DES] data encryption feature sets) are subject to U.S. government export controls and have limited distribution. Strong encryption images to be installed outside the United States are likely to require an export license. Customer orders may be denied or subject to delay because of U.S. government regulations. When applicable, the purchaser or user must obtain local import and use authorizations for all encryption strengths. Please contact your sales representative or distributor for more information, or send an e-mail to [export@cisco.com](mailto:export@cisco.com).

---

## Cisco cBR Series Converged Broadband Routers and Cisco Remote PHY Devices Version Compatibility

The versions of Cisco cBR Series Converged Broadband Routers (Cisco cBR-8) and Cisco Remote PHY Devices (RPD) must be compatible. If the versions are not compatible, the RPD remains in the init(gcp) state. The following list provides information on the compatible cBR-8 and RPD versions:

- Cisco IOS XE Everest 16.6.x works with RPD 2.x
- Cisco IOS XE Fuji 16.7.x works with RPD 3.x
- Cisco IOS XE Fuji 16.8.x works with RPD 4.x

- Cisco IOS XE Fuji 16.9.x works with RPD 5.x
- Cisco IOS XE Gibraltar 16.10.1c works with RPD 6.1, 6.2 and 6.3
- Cisco IOS XE Gibraltar 16.10.1d works with RPD 6.4, 6.5 and 6.7
- Cisco IOS XE Gibraltar 16.10.1f is not recommended for RPD deployment
- Cisco IOS XE Gibraltar 16.10.1g works with RPD 6.7.1, 7.1 and 7.2

## New and Changed Information

The following section lists the new software and hardware features supported on the Cisco cBR Series Converged Broadband Routers in this release:

### New Software Features in Cisco IOS XE Gibraltar 16.10.1g

#### RPHY ifIndex change

The new feature removes the Cisco private ifIndex for RPHY channels (ifIndex starting from 41,000) and reimplement CoreToRpdMap/RpdToCoreMap tables to keep them aligned with DOCS-RPHY-MIB-2018-07-26 definition.

#### CISCO-ENTITY-ALARM-MIB feature

Introduction of the new **cable snmp trap detailed-alarm** CLI, that is used to add entity name into alarm description text in alarm trap.

#### DS OOB 55-1 VOM Traffic Monitor

Cisco cBR Converged Broadband Router provides the VOM Traffic Monitor, which monitors the OOB 55-1 downstream traffic to the virtual-OM interface that is configured on the Cisco cBR-8 router for traffic loss. You must enable SNMP traps and monitoring in order to use this feature.

### New Software Features in Cisco IOS XE Gibraltar 16.10.1f

#### Service Group Simplification (DSG)

The Cisco IOS XE Gibraltar 16.10.1f release supports Advanced-Mode DOCSIS Set-Top Gateway (A-DSG) configuration under MAC domain interface on a Cisco CMTS router with an OPS MD-profile. The method of configuring A-DSG by OPS MD-profile is in addition to the existing method of using legacy CLI to configure DSG TG.

#### View QAM Utilization Percentage

You can now view the QAM utilization percentage by using the **show controllers downstream-cable counter rf-channel** and the **show controller Integrated-cable counter rf-channel** commands.

**dsgifMIB support per CM-SP-DSG-I12-080626 - dsgiftunnelsStats**

The latest DSG specification defines a new MIB table—dsgIfTunnelDsStats in dsgIfMIB. This is supported from Cisco IOS XE Gibraltar 16.10.1f release.

## New Software Features in Cisco IOS XE Gibraltar 16.10.1d

**Load Balancing Groups with Operational Simplification**

The Cisco IOS XE Gibraltar 16.10.1d release supports simplified Load Balancing configuration in the Operational Simplification service group profile. Currently, CMTS supports auto creation of D30 GLBGs based on the existing configuration. Load Balancing would now support creation of RLBGs and D20 GLBGs.

**Proactive Network Management MAX-HOLD trigger mode**

The Cisco IOS XE Gibraltar 16.10.1d release enables MAX-HOLD trigger mode support in PNM. The non-CCAP defined MAX-HOLD mode offers significant advantages over the existing FREE-RUN mode that was used earlier. With the MAX-HOLD trigger mode, the RPD sends samples much faster—one sample every 2ms, compared to the earlier rate of one sample per 100ms. The RPD also sends the sample to the server, instead of the line card.

**DOM support for DPIC**

To display information with regard to the Digital Physical Interface Card, you can now use the **show platform hardware dpic** command.

**RPHY: 2 OFDM channels per SG**

Starting from Cisco IOS XE Gibraltar 16.10.1d, the OFDM channel support in the remote PHY system includes two OFDM channels for each Remote PHY device (RPD) with a channel bandwidth up to 192 MHz and the modulation up to 4096 QAM.

**Analog Tx/Rx modules alarm threshold adjustment CLI**

Starting from Cisco IOS XE Gibraltar 16.10.1d, a new CLI is supported to adjust the alarm threshold of the analog Tx/Rx module in RPD node.

## New Software Features in Cisco IOS XE Gibraltar 16.10.1c

**Support for Guest Shell**

Guest Shell is a decoupled execution space running within a Linux Container. From within the Guest Shell, the network-admin has these capabilities:

- Access to the network over Linux network interfaces.
- Access to bootflash.
- Access to IOS CLI.
- Ability to install and run python scripts.
- Ability to install and run Linux applications.

### Upstream Triggered Spectrum Capture

The Cisco cBR 16.10.1c release supports Upstream Triggered Spectrum Capture for RPHY Core configurations. The upstream triggered spectrum analysis measurement provides a wideband spectrum analyzer function in the CCAP which can be triggered to examine desired upstream transmissions as well as underlying noise or interference during a quiet period.

### Support for Two DOCSIS Upstream OFDMA Channels Per Controller for ICCAP Configurations

Starting from Cisco IOS XE Gibraltar 16.10.1c release, two OFDMA channels—us-channel 12 and us-channel 13 can be configured per controller.

### OFDMA Line Card Process Restart

Linecard IOSd and linecard US-Scheduler (CDMAN) process restart (LCPR) is supported for modems that are assigned OFDMA upstream channels. If LCPR is enabled, remote phy devices remain active after process restarts.

### OFDMA Line Card High Availability

N+1 Line Card High Availability (LCHA) is supported for modems that are assigned OFDMA upstream channels. If LCHA is enabled, the modems remain active after switchover and revert.

### Support for Narrowband Digital Forward And Narrowband Digital Return

Narrowband Digital Forward (NDF) refers to the digitizing of an analog portion of the downstream spectrum at the headend, sending the digital samples as payload in [DEPI] packets to the RPD, and then re-creating the original analog stream at the RPD. NDF supports services such as FM Broadcast, DAB+ Broadcast, and OOB signals for Forward Sweep, DS Leakage, and Element management.

Narrowband Digital Return (NDR) refers to the digitizing of an analog portion of the upstream spectrum at the RPD, sending the digital samples as payload in [R-UEPI] packets to the CMTS, and then re-creating the original analog stream at the headend. NDR supports legacy OOB signals for Reverse Sweep, Return Path Monitoring, FSK based HMS, and other FSK based telemetry signals.

## Modified Software Features in Cisco IOS XE Gibraltar 16.10.1g

There are no modified software features in Cisco IOS XE Gibraltar 16.10.1g.

## Modified Software Features in Cisco IOS XE Gibraltar 16.10.1f

### Modified the show cable video session logical-edge-device Command Output

Two columns—Encrypt Type and Encrypt Status are added in the **show cable video session logical-edge-device** command output. The Encrypt Type column displays the sessions that are encrypted at source as Pre-encrypted and Encrypt Status displays Encrypted.

## Modified Software Features in Cisco IOS XE Gibraltar 16.10.1d

There are no modified software features in Cisco IOS XE Gibraltar 16.10.1d.

## Modified Software Features in Cisco IOS XE Gibraltar 16.10.1c

### 10GE/100GE Mode Switch Process Update

Online insertion and removal of QSFP transceiver triggers 10GE/100GE mode switch instead of configuring mode switch using commands and then reloading the chassis.

### Configuring max-burst value

Starting from 16.10.1c, you must manually configure the max-burst value in the Service Class Name (SCN) to the minimum required value in the MULPI specification for DOCSIS cable modems (4000) that supports extended packet length. Setting the max-burst value manually avoids the confusion about how the CMTS adjusts the max-burst value.

## New Hardware Features in Cisco IOS XE Gibraltar 16.10.1g

There are no new hardware features in the Cisco IOS XE Gibraltar 16.10.1g release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.10.1f

There are no new hardware features in the Cisco IOS XE Gibraltar 16.10.1f release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.10.1d

### New SFP module

Starting from Cisco IOS XE Gibraltar 16.10.1d, new SFP optical module SFP-10G-AOC3M= is supported on DPIC card cBR-DPIC-8X10G.

## New Hardware Features in Cisco IOS XE Gibraltar 16.10.1c

There are no new hardware features in the Cisco IOS XE Gibraltar 16.10.1c release.

## MIBs

To locate and download MIBs for selected platforms, Cisco IOS XE releases, and feature sets, use Cisco MIB Locator found at the following URL:

<https://mibs.cloudapps.cisco.com/ITDIT/MIBS/servlet/index>

## New and Changed MIB Information in Cisco IOS XE Gibraltar 16.10.1g

The following MIB tables are included in the Cisco IOS XE Gibraltar 16.10.1g release:

- docsRphyRpdDevExtSwImageSupportTable
- docsRphyRpdDevExtSwImageSupportSwImageLastUpdate



- docsRphyRpdDevExtSwImageSupportSwImageName
- docsRphyRpdDevExtSwImageSupportSwImageDescr
- docsRphyRpdDevExtSwImageSupportSwImageServerType
- docsRphyRpdDevExtSwImageSupportSwImageServerAddress
- docsRphyRpdDevCandidateBackupCoresTable
  - docsRphyRpdDevCandidateBackupCoresBackupCoreAddIndex docsRphyRpdDevCandidateBackupCoresBackupCoreAddType
  - docsRphyRpdDevCandidateBackupCoresBackupCoreAddr

The following MIBs are updated in the Cisco IOS XE Gibraltar 16.10.1g release:

- docsRphyRpdDevInfoPrincipalCoreStatus
- docsRphyRpdIfEnetConnectorPresent
- docsRphyRpdIfEnetNetworkAuthStatus
- docsRphyRpdDevCoresConnectedIndex
- docsRphyRpdDevCoresConnectedAuxCoreRpdState
- docsRphyRpdDevCoresConnectedResourceSetIndex
- docsRphyRpdDevCoresConnectedGcpBackupConnConfig
- docsRphyCtrlRpdCrashDataServerCtrlHttpFilenameKeyword

## New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1f

The **DOCS-RPHY-STATS-MIB** is updated to include OFDM and OOB tables in the Cisco IOS XE Gibraltar 16.10.1f release.

## New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1d

The following MIB tables are included in the Cisco IOS XE Gibraltar 16.10.1d release:

- docsRphyStatsRpdDsScQamPerfStatsTable
  - docsRphyStatsRpdDsScQamPerfStatsCoreIfIndex
  - docsRphyStatsRpdDsScQamPerfStatsDsRfPortIndex
  - docsRphyStatsRpdDsScQamPerfStatsOutDiscards
  - docsRphyStatsRpdDsScQamPerfStatsOutErrors
  - docsRphyStatsRpdDsScQamPerfStatsOutPackets
  - docsRphyStatsRpdDsScQamPerfStatsRpdDsCounterDiscTime
- docsRphyStatsRpdUsScQamChanPerfStatsTable

- docsRphyStatsRpdUsScQamChanPerfStatsTable
- docsRphyStatsRpdUsScQamChanPerfStatsUsRfPortIndex
- docsRphyStatsRpdUsScQamChanPerfStatsChanSnr
- docsRphyStatsRpdUsScQamChanPerfStatsHcsErrors
- docsRphyStatsRpdUsScQamChanPerfStatsLateMaps
- docsRphyStatsRpdUsScQamChanPerfStatsIllegalMaps
- docsRphyStatsRpdUsScQamChanPerfStatsDiscardedRequests
- docsRphyStatsRpdUsScQamChanPerfStatsRpdUsCounterDiscTime

## New and Changed MIB Information in Cisco IOS-XE Gibraltar 16.10.1c

In the Cisco IOS-XE Gibraltar 16.10.1c release, the **DOCS-RPHY-MIB** was changed to align with DOCS-RPHY-MIB 07/26/2018 version. Support for three new tables have been added.

For information about DOCS-RPHY-MIB 07/26/2018 version, see the [CableLabs MIB definition](#).

## Best Practice Manual of Procedure for Cisco IOS XE Gibraltar 16.10.x Upgrade

See [Upgrading the Cisco cBR Series Converged Broadband Routers for Cisco IOS XE Gibraltar 16.10.x](#).

## Cisco cBR Series Converged Broadband Routers Documentation References

Go to the following link to access the technical documents:

<http://www.cisco.com/c/en/us/support/video/cbr-series-converged-broadband-routers/tsd-products-support-series-home.html>

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.



## CHAPTER 2

# Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats.

The *Open Caveats* section lists open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



**Note** The *Caveats* section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search, on page 15](#)
- [Open Caveats Cisco IOS XE Gibraltar 16.10.1g, on page 16](#)
- [Open Caveats Cisco IOS XE Gibraltar 16.10.1f, on page 17](#)
- [Open Caveats Cisco IOS XE Gibraltar 16.10.1d, on page 17](#)
- [Open Caveats Cisco IOS XE Gibraltar 16.10.1c, on page 18](#)
- [Resolved Caveats Cisco IOS XE Gibraltar 16.10.1g, on page 19](#)
- [Resolved Caveats Cisco IOS XE Gibraltar 16.10.1f, on page 20](#)
- [Resolved Caveats Cisco IOS XE Gibraltar 16.10.1d, on page 21](#)
- [Resolved Caveats Cisco IOS XE Gibraltar 16.10.1c, on page 22](#)

## Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

Save Search Load Saved Search Clear Search Email Current Search

Search For:  If you have a specific bug ID, enter it here

Product: Series/Model Start typing product name to view suggestions or expand list to choose your product

Releases: Affecting or Fixed in these Releases Enter release number

368025

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

### Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.

## Open Caveats Cisco IOS XE Gibraltar 16.10.1g

Caveat ID Number	Description
<a href="#">CSCvn67318</a>	CLC unable to communicate with SUP
<a href="#">CSCvo15430</a>	PKO_ERROR, QAM oversubscribed on CBR-CCAP-LC-G2-R line card with more than 448 video QAMs
<a href="#">CSCvp68713</a>	AUX core is getting flapped between "offline" and "init(l2tp)" when Aux with static PWs only
<a href="#">CSCvp95298</a>	RPHY D31 - OFDM utilization goes over 100% in CLI output
<a href="#">CSCvq05825</a>	Temperature increase when upgrading from 16.7.3 to 16.10.1d
<a href="#">CSCvq13279</a>	CBR crashes on configuring DPIC interface with port-channel configuration and SUPHA
<a href="#">CSCvq14302</a>	Physic interfaces keep re-adding/leaving to port-channel when sub-interface down
<a href="#">CSCvq38886</a>	RPHY Speed Issues - Intel Based Modems
<a href="#">CSCvq40960</a>	cbr8/VIDEO : ECM cache not flushed after last video session terminates
<a href="#">CSCvq47000</a>	cBR8 - Active CLC Crash Due to CPUHOG and IPC Overload of Protect
<a href="#">CSCvq49963</a>	Mismatch in serial numbers after linecard replacement
<a href="#">CSCvq65204</a>	No traffic on non-primary channels
<a href="#">CSCvq83903</a>	RBG interface missing AC record when using OPS and controller profiles
<a href="#">CSCvq86262</a>	I-CCAP cBR-8 displays incorrect SCQAM utilization
<a href="#">CSCvq86980</a>	Modems are parital online on OFMDMA upstream

Caveat ID Number	Description
<a href="#">CSCvq87493</a>	cBR-8 unexpected reload while execution "subcarrier-spacing" command

## Open Caveats Cisco IOS XE Gibraltar 16.10.1f

Caveat ID Number	Description
<a href="#">CSCvo15430</a>	PKO_ERROR, QAM oversubscribed on CBR-CCAP-LC-G2-R line card heavily loaded with video traffic
<a href="#">CSCvp25270</a>	LCHA BPI isidkey assign incorrect - similar to CSCvh00500 but not fixed in 16.7.3
<a href="#">CSCvp37177</a>	Sup unexpected reload on show interface stats for interface VideoMON
<a href="#">CSCvp46033</a>	docsRphyRpdDevCoresConnectedCoreFunction returns incorrect values
<a href="#">CSCvp95363</a>	QAM oversubscribed message is disabled

## Open Caveats Cisco IOS XE Gibraltar 16.10.1d

Caveat ID Number	Description
<a href="#">CSCvm81484</a>	CRC error observed randomly on uplink router which connect to WAN interface
<a href="#">CSCvm88487</a>	Vidman core immediately after LCPR
<a href="#">CSCvn53588</a>	D31 OFDMA codewords stats is not as expected
<a href="#">CSCvn67318</a>	CLC unable to communicate with SUP
<a href="#">CSCvn72716</a>	LC switch to protect card and corefile generated
<a href="#">CSCvn75830</a>	iomd reload @ iomd_ipc_send
<a href="#">CSCvn83854</a>	D31 CMs fall offline with US traffic and OFDMA and symbols-per-frame 6 configured
<a href="#">CSCvo06478</a>	Voice failure without reserved downstream bandwidth
<a href="#">CSCvo15430</a>	RPHY core PKO_ERROR on CBR-CCAP-LC-G2-R line card with DVB
<a href="#">CSCvo19397</a>	cBR8 - CLC Repeatedly Logging "kernel: set_reg_configuration: write max6654 register at 09 failed"
<a href="#">CSCvo40502</a>	SUP unexpected reload when polling ifEntry
<a href="#">CSCvo41443</a>	cBR8 PTP process causing CPUHOG
<a href="#">CSCvo45684</a>	Unexpected reload when doing a SUPSO after an OIR and SUP replacement
<a href="#">CSCvo66208</a>	SUP unexpected reload with MPLS enabled

Caveat ID Number	Description
<a href="#">CSCvo77695</a>	D3.1 CM offline issue on OFDM primary channel when OFDMA configured
<a href="#">CSCvo85716</a>	multiple RPDs using the same controller the CCAP reports the SNR from only the first RPD
<a href="#">CSCvo88231</a>	Slot 0 crashed after LCSO
<a href="#">CSCvo90369</a>	DBG: modem stuck at initO with created DBG having 2 ofdm and one in down state
<a href="#">CSCvo91298</a>	ISSU from 16.6.1 to 16.10.1d failed at stage 2 due to SUP reload in Standby service handler process
<a href="#">CSCvo94774</a>	'cable util-interval' does not take effect for OFDM util in docsIfCmtsChannelUtUtilization
<a href="#">CSCvp01331</a>	Primary line card crash, but standby card fails to take over because of 'ALL CMTX down'

## Open Caveats Cisco IOS XE Gibraltar 16.10.1c

Caveat ID Number	Description
<a href="#">CSCvg76956</a>	Redundant Line card will be reset due to Transient Standby state Timer timed out
<a href="#">CSCvj20713</a>	PHY43.31(CMTS OFDMA Burst Receiver Input Signal Minislot Parameters) Failed for QPSK and 2K FFT Size
<a href="#">CSCvj40754</a>	there is no packet/bytes or bits/sec increasing for counters in #show interface
<a href="#">CSCvk59521</a>	IPC performance downgrade will increase the voice ctrl pkt latency
<a href="#">CSCvk68830</a>	RPHY modem not back online after re-config FN/MD/WB/profile etc unless reset RPD
<a href="#">CSCvm51131</a>	cBR-8: Accessing standby filesystems is extremely slow.
<a href="#">CSCvm63094</a>	CBR-8: misleading FAN syslog error messages.
<a href="#">CSCvm65242</a>	CBR-8: fan failure in sh plat or sh platf diag did not update show environment
<a href="#">CSCvm69126</a>	CPUHOG in DOCSIS LCHA Process
<a href="#">CSCvm89987</a>	ptpd_mcp_rp process unexpected reload
<a href="#">CSCvm91723</a>	Only one CM with UGS-AD with 20 grants per interval allowed per US when minislot=1
<a href="#">CSCvn00496</a>	cBR-8 standby supervisor fails to take over due to midplane lock failure
<a href="#">CSCvn04305</a>	LC does not reach rfs w pic: state changed to normal

Caveat ID Number	Description
<a href="#">CSCvn24876</a>	docsis-channel-id change failed
<a href="#">CSCvn48630</a>	Active protect LC reload during resource configuration of OFDM channels during ISSU
<a href="#">CSCvn53588</a>	D31-UMP: OFDMA codewords stats is not as expected
<a href="#">CSCvn67318</a>	CLC unable to communicate with SUP
<a href="#">CSCvn72716</a>	LC switch to protect card and corefile generated
<a href="#">CSCvn75830</a>	iomd reload @ iomd_ipc_send
<a href="#">CSCvn83854</a>	D31 CMs fall offline with US traffic and OFDMA and symbols-per-frame 6 configured
<a href="#">CSCvo02514</a>	docsIf31CmtsUsOfdmaChanSubcarrierSpacing returns value in Hz instead of KHz
<a href="#">CSCvo03922</a>	cBR-8 : IGMP Joins Occuring Too Slowly Resulting in Service Impact
<a href="#">CSCvo15430</a>	RPHY core PKO_ERROR on CBR-CCAP-LC-G2-R line card with DVB

## Resolved Caveats Cisco IOS XE Gibraltar 16.10.1g

Caveat ID Number	Description
<a href="#">CSCvn22000</a>	SUP250 backhaul 10GE interface admin down after reload chassis
<a href="#">CSCvn53588</a>	D31 OFDMA codewords stats is not as expected
<a href="#">CSCvn72716</a>	LC switch to protect card and corefile generated
<a href="#">CSCvn79157</a>	cBR-8 Sup reload due to QOS Template handling exception
<a href="#">CSCvo43793</a>	poor US throughput resulting from invalid fragment sizes
<a href="#">CSCvo45684</a>	Unexpected reload when doing a SUPSO after an OIR and SUP replacement
<a href="#">CSCvo68383</a>	Monitor DS OOB 55-1 Traffic and SNMP Trap/alarm on failure
<a href="#">CSCvo72165</a>	After reconfig of IP address of CA on LC, old IP address stays in routing table
<a href="#">CSCvp25270</a>	LCHA BPI isidkey assign incorrect - similar to CSCvh00500 but not fixed in 16.7.3
<a href="#">CSCvp28806</a>	D3.0 JIB chan value is 0 and rlm is set to 0 due to D3.1 channel
<a href="#">CSCvp37177</a>	Sup unexpected reload on show interface stats for interface VideoMON
<a href="#">CSCvp43802</a>	Add "show command" for host resource management TLV 100.21/22/23
<a href="#">CSCvp53181</a>	Observed incorrect packet count in cbr for packets received from RPD.
<a href="#">CSCvp57491</a>	CBR8 SUP/PIC "Failed Identification Test" Error after OIR/Replacement

Caveat ID Number	Description
<a href="#">CSCVp62500</a>	sh cable signal-quality cable x/y/z upstream x cmts can't show CNiR
<a href="#">CSCVp92883</a>	some modem reset automaticly after LCHA
<a href="#">CSCVp93648</a>	US packet counter in CBR8 is not accurate for 55d1
<a href="#">CSCVp95363</a>	Spurious QAM oversubscribed messages, message is disabled in 16.10.1f
<a href="#">CSCVq00557</a>	LCHA revertback to stable state takes longer time with recent v1612 image
<a href="#">CSCVq01053</a>	Wrong qlimit 0/63 causes downstream drops
<a href="#">CSCVq09290</a>	Unexpected cBR-8 line card reload or vidman process restart at pool_alloc
<a href="#">CSCVq11263</a>	CPU HOG crash @ cmts_mcast_get_ds_check_adm_ctrl
<a href="#">CSCVq16616</a>	DPIC link redundancy does not send correct trap when link down for 40GDPIC
<a href="#">CSCVq19754</a>	D31 modem DBC and DSID value 0 behavior after channel impairment
<a href="#">CSCVq23522</a>	multiple RPDs using the same controller the CLI only show the first RPD
<a href="#">CSCVq27809</a>	fix the incorrect handling of DBC partial-service RSP during D31 profile list change in RCC
<a href="#">CSCVq29998</a>	DCD DSG Rule & CFR Encoding lost after LCSO
<a href="#">CSCVq68404</a>	cBR-8 displays incorrect QAM utilization

## Resolved Caveats Cisco IOS XE Gibraltar 16.10.1f

Caveat ID Number	Description
<a href="#">CSCVm81484</a>	CRC error observed randomly on uplink router which connect to WAN interface
<a href="#">CSCVn37237</a>	ASR1002-HX crashed after huge traffic is transmitted over it
<a href="#">CSCVo00664</a>	SUP reload after running the command " show plat hard qfp act infr bqs debug qmrt_dump "
<a href="#">CSCVo15703</a>	CBR8/RPHY: IP address of D31 cable modem unpingnable after shut and no shut ofdma channel
<a href="#">CSCVo41374</a>	cBR-8 Static Load-balance cannot work when the frequency of rf-ch 8 is far away from others
<a href="#">CSCVo65282</a>	EDVT:SUP250 PMAN-3-PROCFAIL: R1/0: pman: The process cmand has failed (rc 134)
<a href="#">CSCVo72542</a>	CBR-CCAP-LC-G2-R cdman process-restart cause iosd reload on both SUPs



Caveat ID Number	Description
<a href="#">CSCvo77695</a>	D3.1 CM Unable to use OFDM Primary DS When OFDMA Configured or with Annex-A SC-QAM Channels
<a href="#">CSCvo83128</a>	Static Passthru sessions deleted when performing an SBSS failover
<a href="#">CSCvo85716</a>	multiple RPDs using the same controller the CCAP reports the SNR from only the first RPD
<a href="#">CSCvo88231</a>	Slot 0 unexpected reload after LCSO - occurred once
<a href="#">CSCvo90369</a>	modem stuck at init(o) with created DBG having 2 ofdm and one in down state
<a href="#">CSCvo91298</a>	ISSU from 16.6.1 to 16.10.1d failed at stage 2 due to SUP reload in Standby service handler process
<a href="#">CSCvp09475</a>	CBR8/RPD: cBR8 returning wrong value of ifType for ofdma channel
<a href="#">CSCvp18310</a>	ENH:For annexC, it still shows as annexB in snmp result
<a href="#">CSCvp21664</a>	SUP reload after configuring dsgr tg in MD and also after 'show derived-config interface' CLI
<a href="#">CSCvp23692</a>	Sessions output bitrate does not drop to zero on input loss
<a href="#">CSCvp31043</a>	SNMP WALK query failed on ob551PerfStats and Oob552PerfStats tables
<a href="#">CSCvp49534</a>	RPHY: inconsistent max-carrier configuration in DS controller profile & RPD shelf

## Resolved Caveats Cisco IOS XE Gibraltar 16.10.1d

Caveat ID Number	Description
<a href="#">CSCvg16863</a>	SUP160 crashes in tdlb_notf_read
<a href="#">CSCvk68830</a>	RPHY modem not back online after re-config FN/MD/WB/profile etc unless reset RPD
<a href="#">CSCvm39860</a>	Standby sup would crash when boot up with reason sync failed to a non-exist rf-pic card
<a href="#">CSCvm63094</a>	CBR-8: misleading FAN syslog error messages.
<a href="#">CSCvm91723</a>	Only one CM with UGS-AD with 20 grants per interval allowed per US when minislot=1
<a href="#">CSCvn00496</a>	cBR-8 standby supervisor fails to take over due to midplane lock failure
<a href="#">CSCvn67294</a>	Modem Flap list missing some US channels if 'upstream ranging-init-technique 2' configured under MD
<a href="#">CSCvn86577</a>	cBR8 Linecard memory leak caused by specsvl_fft_log file

Caveat ID Number	Description
<a href="#">CSCvn98633</a>	EDVT:CBR-CCAP-LC-G2-R CDMAN_ILK_REINIT Failure: FATAL!
<a href="#">CSCvo02514</a>	docsIf31CmtsUsOfdmaChanSubcarrierSpacing returns value in Hz instead of KHz
<a href="#">CSCvo08333</a>	all modems on D-PON enabled MD are on partial, using US0 only
<a href="#">CSCvo09571</a>	Incorrect calculation for docsis DS_D31_License after OIR
<a href="#">CSCvo18098</a>	VPM IPC failed to get BIPC buffer
<a href="#">CSCvo21280</a>	docsPnmCmtsUtscCtrlInitiateTest MIB object expects 0 as false, TruthValue objects expect 2 as false
<a href="#">CSCvo21334</a>	Drop between US-PHY & US-JIB causes all modems on US Ch to be init(rc); no dial tone for NRTPS SF
<a href="#">CSCvo30267</a>	CM offline after LCSO triggered by OIR with scale RPD env
<a href="#">CSCvo35498</a>	Cannot specify preferred PCR-pid for primary-subordinate clock recovery mode
<a href="#">CSCvo58725</a>	show cable rpd config upstream remote shows incorrect information
<a href="#">CSCvo58915</a>	RPD Events 66070201 & 66070221: MAC of VirtualPortGroup used for Core ID instead of stby core intf
<a href="#">CSCvo68977</a>	Admission-Control vacancy table overutilized causing service-flow errors; customer hears "fast busy"
<a href="#">CSCvo72542</a>	CBR-CCAP-LC-G2-R cdman process-restart cause iosd reload on both SUPs

## Resolved Caveats Cisco IOS XE Gibraltar 16.10.1c

Caveat ID Number	Description
<a href="#">CSCvh19284</a>	cBR8/16.6.1 : DS-JIB BG channel errors due to mcast flows after SUP FO
<a href="#">CSCvj06355</a>	DPIC cannot ping outside and peer switch intf went down after 1 hour LCHA
<a href="#">CSCvj10057</a>	CCAP appears to use decimal for the tunnel numbers, while the Cisco RPD uses hex
<a href="#">CSCvk26608</a>	RPHY: OFDM channel status became other after change RPD's controller-profile
<a href="#">CSCvk28501</a>	cBR8 docsIfCmtsDownChnlCtrExtTotalBytes not calculated correctly
<a href="#">CSCvk31941</a>	RPHY: memleak @ cmts_free_id_dat_init
<a href="#">CSCvk32885</a>	Default max-burst is incorrect when TLV 5.48 (Extended packet length) is supported
<a href="#">CSCvk42829</a>	Output truncated for cli "show cable modem wideband phy"

Caveat ID Number	Description
<a href="#">CSCvk43566</a>	MpegMIB SNMP response delay msg on configuration sync and configuration download
<a href="#">CSCvk50046</a>	SUP BH interfaces connected with the Switch hit the link flapping when 1st SUPHA after reload
<a href="#">CSCvk64784</a>	SUP rphyman unexpected reload at rphy_master_get_rphy_inst
<a href="#">CSCvk70883</a>	cBR8 LED Memory Leak:Used Memory critical threshold alarms
<a href="#">CSCvk72878</a>	RPD offline but SNMP walk still return value
<a href="#">CSCvm05254</a>	'cable util-interval' does not take effect for SC-QAM & OFDMA util
<a href="#">CSCvm06904</a>	'cable util-interval' does not take effect for DS util (SC-QAM & OFDM)
<a href="#">CSCvm13710</a>	Multicast join not happened when changing ASM to SSM session using same G
<a href="#">CSCvm13831</a>	Changes to sh cable RPD Identification command
<a href="#">CSCvm42350</a>	Downstream power level increase 3 dB when redundancy linecard take place
<a href="#">CSCvm58342</a>	cBR-8 CLC unexpected reload at 'cmts_print_modem_phy'
<a href="#">CSCvm61788</a>	CBR8 VIDEO (Tier based scrambling) SCS raising error Alarm Set: Scrambler: Scrambling not started
<a href="#">CSCvm62468</a>	cBR-8 Linecard unexpected reload in 'ubr_map_builder'
<a href="#">CSCvm65604</a>	PKO hung issue on RPHY setup
<a href="#">CSCvm71936</a>	Cannot create new video sessions on a cBR-8 line card, missing sessions
<a href="#">CSCvm76573</a>	16.9.1a - when shutting an RPD, the cbr8 keeps sending l2tp traffic on that interface
<a href="#">CSCvm82805</a>	D31 CM with TLV5.48 stuck in reject(c) when cfg file max-burst <2000B & SCN max-burst >=2000B
<a href="#">CSCvm82896</a>	Video LED Management IP address unreachable from VSRM
<a href="#">CSCvn09472</a>	Memory leak observed in cpp_cp_svr
<a href="#">CSCvn18107</a>	high cpu due to cmts_update_adj process
<a href="#">CSCvn27399</a>	CBR: all D3.1 modems p-online( ofdm channel Other state )
<a href="#">CSCvn28261</a>	cBR-8 line card VIDEO_BAD_PRIMARY_ID log messages
<a href="#">CSCvn34867</a>	SUPHA causes rpd controller table corruption and RPD misconfiguration
<a href="#">CSCvn40100</a>	SUP reload because of IPV4 HOST DB
<a href="#">CSCvn49536</a>	cBR-8 : Slot 0 Reloaded During LCHA From Primary to Secondary LC

<b>Caveat ID Number</b>	<b>Description</b>
<a href="#">CSCvn53895</a>	MTC mode incorrectly set to MTC_REQ_ATTR, modems unable to US bond
<a href="#">CSCvn59272</a>	DSG tunnels stuck after SUP SO
<a href="#">CSCvn68931</a>	Supervisor reloads unexpectedly when polling the OID k_qamChannelCommonEntry_get via SNMP
<a href="#">CSCvn73235</a>	Errors on changing RPD D3.1 upstream controller-profile when exclusion band configured
<a href="#">CSCvn90475</a>	cBR8: video interface is disabled in CPP after CLC removal, SUP SO, and CLC insertion
<a href="#">CSCvo01998</a>	Errors on changing RPD D3.1 upstream controller-profile when unused band configured