



# Release Notes for Cisco IOS Release 15.4S

---

**First Published:** November 21, 2013  
**Last Updated:** March 19, 2018  
**Release:** Cisco IOS Release 15.4(3)S9  
**Part Number:** OL-30834-08

## Introduction

These release notes support Cisco IOS Release 15.4S up to and including Cisco IOS Release 15.4(3)S9 and are updated as needed to describe new features, bugs, and related documents. Cisco IOS Release 15.4S supports platforms within the following Cisco series:

- Cisco 7600 series routers
- Cisco ASR 901 router
- Cisco ASR 901 10G router
- Cisco ASR 901 S router
- Cisco ME 3600X switch
- Cisco ME 3600-24CX switch
- Cisco ME 3800X switch



---

**Americas Headquarters:**  
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA



# System Requirements

This document describes the system requirements for Cisco IOS 15.4S releases and includes the following sections:

- [Feature Support, page 3](#)
- [Memory Recommendations, page 5](#)
- [Supported Hardware, page 5](#)
- [Determining the Software Version, page 6](#)
- [Upgrading to a New Software Release, page 6](#)

## Feature Support

Cisco IOS software is packaged in feature sets that consist of software images that support specific platforms. The feature sets available for a specific platform depend on which Cisco IOS software images are included in a release. Each feature set contains specific Cisco IOS features.



### Caution

Cisco IOS images with strong encryption (including, but not limited to 168-bit [3DES] data encryption feature sets) are subject to U.S. government export controls and have limited distribution. Strong encryption images to be installed outside the United States are likely to require an export license. Customer orders may be denied or subject to delay because of U.S. government regulations. When applicable, the purchaser/user must obtain local import and use authorizations for all encryption strengths. Please contact your sales representative or distributor for more information, or send an e-mail to [export@cisco.com](mailto:export@cisco.com).

Feature-to-image mapping is available through Cisco Feature Navigator. Cisco Feature Navigator is a web-based tool that enables you to determine which Cisco IOS software images support a specific set of features and which features are supported in a specific Cisco IOS image. You can search by feature or by feature set (software image). You can compare Cisco IOS software releases side-by-side to display both the features unique to each software release and the features that the releases have in common.

Cisco Feature Navigator is updated regularly when major Cisco IOS software releases and technology releases occur. For the most current information, go to the Cisco Feature Navigator home page at the following URL:

[www.cisco.com/go/cfn](http://www.cisco.com/go/cfn)

For help with Cisco Feature Navigator, see the help information at the following URL:

[http://www.cisco.com/web/applicat/CFNTOOLS/Help\\_Docs/help/cfn\\_support.html](http://www.cisco.com/web/applicat/CFNTOOLS/Help_Docs/help/cfn_support.html)

## Determining the Software Images (Feature Sets) That Support a Specific Feature

To determine which software images (feature sets) in a Cisco IOS release support a specific feature, go to the [Cisco Feature Navigator home page](#) and perform the following steps.

- Step 1** From the Cisco Feature Navigator home page, click **Research Features**.
- Step 2** Select your software type or leave the field as “All”.

- Step 3** To find a feature, you can search by either Feature or Technology (select the appropriate button). If you select Search by Feature, you can further filter your search by using the Filter By text box.
- Step 4** Choose a feature from the Available Features text box, and click the **Add** button to add the feature to the Selected Features text box.




---

**Note** To learn more about a feature in the list, click the **View Desc** button in the Available Features text box.

---

Repeat this step to add features. A maximum of 20 features can be chosen for a single search.

- Step 5** Click **Continue** when you are finished choosing features.
- Step 6** In the Release/Platform Tree area, select either your release (from the Train-Release list) or your platform (from the Platform list).
- Step 7** The “Search Result” table will list all the software images (feature sets) that support the features that you chose.




---

**Note** You can download your results into an Excel spreadsheet by clicking on the Download Excel button.

---

## Determining the Features Supported in a Specific Software Image (Feature Set)

To determine which features are supported in a specific software image (feature set), go to the [Cisco Feature Navigator home page](#) and perform the following steps.

- Step 1** From the Cisco Feature Navigator home page, click **Research Software**.
- Step 2** Select your software type from the drop-down list and chose the **Release** button in the “Search By” area.
- Step 3** From the Major Release drop-down list, chose the appropriate major release.
- Step 4** From the Release drop-down list, choose the appropriate maintenance release.
- Step 5** From the Platform drop-down list, choose the appropriate hardware platform.
- Step 6** From the Feature Set drop-down list, choose the appropriate feature set. The Image Details area will provide details on the specific image. The Available Features area will list all the features that are supported by the feature set (software image) that you chose.




---

**Note** To learn more about a feature in the list, click the **View Desc** button in the Available Features text box.

---

## Memory Recommendations

To determine memory recommendations for software images (feature sets) in your Cisco IOS release, go to the [Cisco Feature Navigator home page](#) and perform the following steps.

- 
- Step 1** From the Cisco Feature Navigator home page, click **Research Software**.
  - Step 2** Select your software type from the drop-down list and choose the **Release** button in the “Search By” area.
  - Step 3** From the Major Release drop-down list, choose the appropriate major release.
  - Step 4** From the Release drop-down list, choose the appropriate maintenance release.
  - Step 5** From the Platform drop-down list, choose the appropriate hardware platform.
  - Step 6** From the Feature Set drop-down list, choose the appropriate feature set.
  - Step 7** The Image Details area will provide details on the specific image including the DRAM and flash memory recommendations for each image. The Available Features area will list all the features that are supported by the feature set (software image) that you chose.
- 

## Supported Hardware

Cisco IOS Release 15.4S supports the following platforms, including the following models and supervisor engines:

- Cisco 7600 series routers
- Cisco ASR 901 router
- Cisco ASR 901 10G router
- Cisco ME 3600X switch
- Cisco ME 3600X-24CX switch
- Cisco ME 3800X switch

### Cisco 7600 Series Routers

For extensive information about all supported hardware for Cisco 7600 series routers, see the *Guide to Supported Hardware for Cisco 7600 Series Routers with Cisco IOS Release 15S*:

[http://www.cisco.com/en/US/docs/routers/7600/Hardware/15\\_0s/7600\\_hwd.html](http://www.cisco.com/en/US/docs/routers/7600/Hardware/15_0s/7600_hwd.html)

### Cisco ASR 901 Router

For detailed information about the Cisco ASR 901 router, see the documents at the following location:

[http://www.cisco.com/en/US/products/ps12077/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps12077/tsd_products_support_series_home.html)

### Cisco ASR 901 10G Router

For detailed information about the Cisco ASR 901 10G router, see the documents at the following location:

[http://www.cisco.com/en/US/partner/products/ps12667/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/partner/products/ps12667/tsd_products_support_series_home.html)

## Cisco ME 3600X Switch and ME 3800X Switch

For detailed information about the Cisco ME 3600X switch, see the documents at the following location:

<http://www.cisco.com/en/US/products/ps10956/index.html>

For detailed information about the Cisco ME 3800X switch, see the documents at the following location:

<http://www.cisco.com/en/US/products/ps10965/index.html>

See the *Cisco ME 3800X and ME 3600X Switch Hardware Installation Guide* at

[http://www.cisco.com/en/US/docs/switches/metro/me3600x\\_3800x/hardware/installation/guide/me3800x\\_hig.html](http://www.cisco.com/en/US/docs/switches/metro/me3600x_3800x/hardware/installation/guide/me3800x_hig.html)

## Cisco ME 3600X-24CX Switch

For detailed information about the Cisco ME 3600X-24CX switch, see the document at the following location:

[http://www.cisco.com/en/US/prod/collateral/switches/ps6568/ps10956/data\\_sheet\\_c78-708663.html](http://www.cisco.com/en/US/prod/collateral/switches/ps6568/ps10956/data_sheet_c78-708663.html)

## Determining the Software Version

To determine the version of Cisco IOS software that is running on your Cisco router, log in to the router and enter the **show version** EXEC command:

```
Router# show version
```

```
Cisco IOS Software, s72033_rp Software (s72033_rp-ADVENTERPRISEK9_WBX_WAN-M), Version  
15.4(1)S, EARLY DEPLOYMENT RELEASE SOFTWARE
```

## Upgrading to a New Software Release

For information about choosing a new Cisco IOS software release, see *How to Choose a Cisco IOS Software Release* at the following location:

[http://www.cisco.com/en/US/products/sw/iosswrel/ps1834/products\\_tech\\_note09186a00800fb9d9.shtml](http://www.cisco.com/en/US/products/sw/iosswrel/ps1834/products_tech_note09186a00800fb9d9.shtml)

For information about upgrading the Cisco 7600 series routers, go to the following location:

[http://www.cisco.com/en/US/products/hw/routers/ps368/tsd\\_products\\_support\\_install\\_and\\_upgrade.html](http://www.cisco.com/en/US/products/hw/routers/ps368/tsd_products_support_install_and_upgrade.html)

For information about upgrading the Cisco ASR 901 router, go to the following location:

[http://www.cisco.com/en/US/products/ps12077/prod\\_installation\\_guides\\_list.html](http://www.cisco.com/en/US/products/ps12077/prod_installation_guides_list.html)

For information about upgrading the Cisco ME 3600X switch, go to the following location:

[http://www.cisco.com/en/US/products/ps10956/tsd\\_products\\_support\\_install\\_and\\_upgrade.html](http://www.cisco.com/en/US/products/ps10956/tsd_products_support_install_and_upgrade.html)

For information about upgrading the Cisco ME 3600X-24CX switch, go to the following location:

[http://www.cisco.com/en/US/products/ps10956/prod\\_installation\\_guides\\_list.html](http://www.cisco.com/en/US/products/ps10956/prod_installation_guides_list.html)

For information about upgrading the Cisco ME 3800X switch, go to the following location:

[http://www.cisco.com/en/US/products/ps10965/tsd\\_products\\_support\\_install\\_and\\_upgrade.html](http://www.cisco.com/en/US/products/ps10965/tsd_products_support_install_and_upgrade.html)

For Cisco IOS upgrade ordering instructions, go to the following location:

[http://www.cisco.com/warp/public/cc/pd/iosw/prodlit/957\\_pp.htm](http://www.cisco.com/warp/public/cc/pd/iosw/prodlit/957_pp.htm)

Use Cisco Feature Navigator to find information about platform support and software image support. Cisco Feature Navigator enables you to determine which Cisco IOS and Catalyst OS software images support a specific software release, feature set, or platform. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on Cisco.com is not required.





# Limitations and Restrictions

This chapter describes limitations and restrictions in Cisco IOS 15.4S releases.

- [Limitations and Restrictions in Cisco IOS Release 15.4\(3\)S, page 9](#)
- [Limitations and Restrictions in Cisco IOS Release 15.4\(2\)S, page 9](#)
- [Limitations and Restrictions in Cisco IOS Release 15.4\(1\)S, page 9](#)

## Limitations and Restrictions in Cisco IOS Release 15.4(3)S

- There are no new limitations and restrictions in Cisco IOS Release 15.4(3)S.

## Limitations and Restrictions in Cisco IOS Release 15.4(2)S

- There are no new limitations and restrictions in Cisco IOS Release 15.4(2)S.

## Limitations and Restrictions in Cisco IOS Release 15.4(1)S

There are no new limitations and restrictions in Cisco IOS Release 15.4(1)S.





## **New Features and Important Notes**



# Features and Important Notes for Cisco IOS Release 15.4(3)S

These release notes describe the following topics:

- [New Hardware Features in Cisco IOS Release 15.4\(3\)S1](#), page 13
- [New Software Features in Cisco IOS Release 15.4\(3\)S1](#), page 13
- [New Hardware Features in Cisco IOS Release 15.4\(3\)S](#), page 13
- [New Software Features in Cisco IOS Release 15.4\(3\)S](#), page 13
- [New Hardware and Software Features supported on Cisco 7600 Series Routers in Cisco IOS Release 15.4\(3\)S](#), page 15
- [New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4\(3\)S](#), page 15
- [New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4\(3\)S](#), page 16
- [New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 2600x Series Ethernet Access Switches in Cisco IOS Release 15.4\(3\)S](#), page 16
- [MIBs](#), page 16
- [Important Notes](#), page 16

## New Hardware Features in Cisco IOS Release 15.4(3)S1

There are no new hardware features in Cisco IOS Release 15.4(3)S1.

## New Software Features in Cisco IOS Release 15.4(3)S1

There are no new software features in Cisco IOS Release 15.4(3)S1.

## New Hardware Features in Cisco IOS Release 15.4(3)S

There are no new hardware features in Cisco IOS Release 15.4(3)S.

## New Software Features in Cisco IOS Release 15.4(3)S

This section describes new and changed features in Cisco IOS Release 15.4(3)S. Some features may be new to Cisco IOS Release 15.4(3)S but were released in earlier Cisco IOS software releases. Some features may have been released in earlier Cisco IOS software releases and have been changed in Cisco IOS Release 15.4(3)S. Links to feature modules are included. If a feature listed does not have a link to a feature module, that feature is documented only in the release notes.

### Autonomic Config Download

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/auto\\_net/configuration/15-s/an-auto-net-15-s-book/an-auto-net-infra.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/auto_net/configuration/15-s/an-auto-net-15-s-book/an-auto-net-infra.html)

## **BFD Support for Multicast(PIM)**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipmulti\\_pim/configuration/15-s/imc-pim-15-s-book/imc\\_bfdpim.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipmulti_pim/configuration/15-s/imc-pim-15-s-book/imc_bfdpim.html)

## **BGP - 4-byte AS RD and RT Support (RFC5668)**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-15-s-book/irg-4byte-asn.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-15-s-book/irg-4byte-asn.html)

## **BGP- Subcodes for BGP Cease Notification**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-15-s-book/irg-max-prefix.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-15-s-book/irg-max-prefix.html)

## **CFM Extension for 1+1 Hot-Standby Support**

For detailed information about this feature, see the following document:

<http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/15-s/ce-15-s-book/ce-cfm-nsnhsby.html>

## **CFM Low Latency**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901/Configuration/Guide/b\\_asr901-scg/b\\_asr901-scg\\_chapter\\_0101111.html](http://www.cisco.com/c/en/us/td/docs/wireless/asr_901/Configuration/Guide/b_asr901-scg/b_asr901-scg_chapter_0101111.html)

## **FHRP - HSRP - Hot Standby Router Protocol V2**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp\\_fhrp/configuration/15-s/fhp-15-s-book/HSRP-Version-2.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp_fhrp/configuration/15-s/fhp-15-s-book/HSRP-Version-2.html)

## **HSRP: Global IPv6 Address**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp\\_fhrp/configuration/15-s/fhp-15-s-book/HSRP-Global-IPv6-Address.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp_fhrp/configuration/15-s/fhp-15-s-book/HSRP-Global-IPv6-Address.html)

## **IPv6 Routing: OSPFv3 Authentication Support with IPsec**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_ospf/configuration/15-s/iro-15-s-book/ip6-route-ospfv3-auth-ipsec.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_ospf/configuration/15-s/iro-15-s-book/ip6-route-ospfv3-auth-ipsec.html)

### **IPv6 Routing: RIP for IPv6 (RIPng)**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_rip/configuration/15-s/irr-15-s-book/ip6-rip.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_rip/configuration/15-s/irr-15-s-book/ip6-rip.html)

### **IPv6 Services: Extended Access Control Lists**

For detailed information about this feature, see the following document:

[https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec\\_data\\_acl/configuration/15-s/sec-data-acl-15-s-book/ip6-acls.html](https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data_acl/configuration/15-s/sec-data-acl-15-s-book/ip6-acls.html)

### **TWAMP RFC Compliance**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipsla/configuration/15-s/sla-15-s-book/sla\\_twamp.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipsla/configuration/15-s/sla-15-s-book/sla_twamp.html)

### **VRF Aware BGP Translate-update**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-15-s-book/vrf-aware-bgp-translate-update.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-15-s-book/vrf-aware-bgp-translate-update.html)

### **VRRPv3 Protocol Support**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp\\_fhrp/configuration/15-s/fhp-15-s-book/VRRPv3-Protocol-Support.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipapp_fhrp/configuration/15-s/fhp-15-s-book/VRRPv3-Protocol-Support.html)

## **New Hardware and Software Features supported on Cisco 7600 Series Routers in Cisco IOS Release 15.4(3)S**

For detailed information about hardware and software features supported on Cisco 7600 Series Routers in Cisco IOS Release 15.4(3)S, see the following document:

<http://www.cisco.com/c/en/us/support/routers/7600-series-routers/products-release-notes-list.html>

## **New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(3)S**

For detailed information about hardware and software features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(3)S, see the following document:

[http://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901/Release/Notes/asr901\\_rn\\_15\\_4\\_3\\_S.html](http://www.cisco.com/c/en/us/td/docs/wireless/asr_901/Release/Notes/asr901_rn_15_4_3_S.html)

## New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(3)S

For detailed information about hardware and software features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(3)S, see the following document:

[http://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901s/rn/b\\_rn\\_for\\_asr901s\\_15\\_4\\_3s.html](http://www.cisco.com/c/en/us/td/docs/wireless/asr_901s/rn/b_rn_for_asr901s_15_4_3s.html)

## New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 2600x Series Ethernet Access Switches in Cisco IOS Release 15.4(3)S

For detailed information about hardware and software features supported on Cisco ME 3600x and Cisco ME 2600x Series Ethernet Switches in Cisco IOS Release 15.4(3)S, see the following document:

<http://www.cisco.com/c/en/us/support/switches/me-3600x-series-ethernet-access-switches/products-release-notes-list.html>

<http://www.cisco.com/c/en/us/support/switches/me-2600x-series-ethernet-access-switches/products-release-notes-list.html>

## MIBs

To locate and download MIBs for selected platforms, Cisco IOS releases, and feature sets, use the Cisco MIB Locator found at the following URL:

<http://tools.cisco.com/ITDIT/MIBS/servlet/index>

If the Cisco MIB Locator does not support the MIB information that you need, you can obtain a list of supported MIBs and download MIBs from the Cisco MIBs page at the following URL:

<http://www.cisco.com/public/sw-center/netmgmt/cmtk/mibs.shtml>

To access the Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank email to [cco-locksmith@cisco.com](mailto:cco-locksmith@cisco.com). An automatic check will verify that your email address is registered with Cisco.com. If the check is successful, account details with a new random password will be emailed to you. Qualified users can establish an account on Cisco.com by following the directions found at this URL:

<http://tools.cisco.com/RPF/register/register.do>

## Important Notes

The following sections contain important notes about Cisco IOS Release 15.4S:

- [Field Notices and Bulletins, page 16](#)

### Field Notices and Bulletins

- Field Notices—Cisco recommends that you view the field notices for this release to see if your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).
- Bulletins—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).



# Features and Important Notes for Cisco IOS Release 15.4(2)S

These release notes describe the following topics:

- [New Hardware Features in Cisco IOS Release 15.4\(2\)S2, page 17](#)
- [New Software Features in Cisco IOS Release 15.4\(2\)S2, page 17](#)
- [New Hardware Features in Cisco IOS Release 15.4\(2\)S1, page 17](#)
- [New Software Features in Cisco IOS Release 15.4\(2\)S1, page 17](#)
- [New Hardware Features in Cisco IOS Release 15.4\(2\)S, page 17](#)
- [New Software Features in Cisco IOS Release 15.4\(2\)S, page 18](#)
- [New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4\(2\)S, page 19](#)
- [New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4\(2\)S, page 19](#)
- [New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4\(2\)S, page 20](#)
- [MIBs, page 20](#)
- [Important Notes, page 20](#)

## New Hardware Features in Cisco IOS Release 15.4(2)S2

There are no new hardware features in Cisco IOS Release 15.4(2)S2.

## New Software Features in Cisco IOS Release 15.4(2)S2

There are no new software features in Cisco IOS Release 15.4(2)S2.

## New Hardware Features in Cisco IOS Release 15.4(2)S1

There are no new hardware features in Cisco IOS Release 15.4(2)S1.

## New Software Features in Cisco IOS Release 15.4(2)S1

There are no new software features in Cisco IOS Release 15.4(2)S1.

## New Hardware Features in Cisco IOS Release 15.4(2)S

This section describes new and changed features in Cisco IOS Release 15.4(2)S. Some features may be new to Cisco IOS Release 15.4(2)S but were released in earlier Cisco IOS software releases. Some features may have been released in earlier Cisco IOS software releases and have been changed in Cisco IOS Release 15.4(2)S. To determine if a feature is new or changed, see the feature information table at the end of the feature module for that feature. Links to feature modules are included. If a feature does not have a link to a feature module, that feature is documented only in the release notes.

**DWDM SFP+ Support on ES+ HD Line Cards for C7600 Platforms.**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/routers/7600/Hardware/15\\_0s/7600\\_hwd.html](http://www.cisco.com/c/en/us/td/docs/routers/7600/Hardware/15_0s/7600_hwd.html)

**SPA-1xCHSTM1/OC3-V2**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/interfaces\\_modules/shared\\_port\\_adapters/configuration/7600series/sipspasw/76cfstm1.html](http://www.cisco.com/c/en/us/td/docs/interfaces_modules/shared_port_adapters/configuration/7600series/sipspasw/76cfstm1.html)

**SPA-2XT3/E3-V2 and SPA-4XT3/E3-V2**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/interfaces\\_modules/shared\\_port\\_adapters/configuration/7600series/sipspasw/76cfgt3.html](http://www.cisco.com/c/en/us/td/docs/interfaces_modules/shared_port_adapters/configuration/7600series/sipspasw/76cfgt3.html)

**SPA-2XCT3/DS0-V2 and SPA-4XCT3/DS0-V2**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/interfaces\\_modules/shared\\_port\\_adapters/configuration/7600series/sipspasw/76cfgct3.html](http://www.cisco.com/c/en/us/td/docs/interfaces_modules/shared_port_adapters/configuration/7600series/sipspasw/76cfgct3.html)

**New Software Features in Cisco IOS Release 15.4(2)S**

This section describes new and changed features in Cisco IOS Release 15.4(2)S. Some features may be new to Cisco IOS Release 15.4(2)S but were released in earlier Cisco IOS software releases. Some features may have been released in earlier Cisco IOS software releases and have been changed in Cisco IOS Release 15.4(2)S. Links to feature modules are included. If a feature listed does not have a link to a feature module, that feature is documented only in the release notes.

**Autoroute announce and forwarding adjacencies for OSPFv3 over IPv4 TE tunnels**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_ospf/configuration/15-s/iro-15-s-book/iro-ospf-autoroute.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_ospf/configuration/15-s/iro-15-s-book/iro-ospf-autoroute.html)

**Auto-IP for SVI, Port-Channel & VRF**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipaddr\\_ipv4/configuration/15-s/ipv4-15-s-book/Auto-IP.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipaddr_ipv4/configuration/15-s/ipv4-15-s-book/Auto-IP.html)

**BGP - Accumulated IGP**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-15-s-book/bgp-accumulated-igp.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-15-s-book/bgp-accumulated-igp.html)

## **BGP PIC Edge for IP/MPLS**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-15-s-book/irg-bgp-mp-pic.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-15-s-book/irg-bgp-mp-pic.html)

## **BGP Signaling - VPLS interAS option B**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp\\_l2\\_vpns/configuration/15-s/mp-l2-vpns-15-s-book/mp-vpls-bgp-sig-inter-as-option-b.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_l2_vpns/configuration/15-s/mp-l2-vpns-15-s-book/mp-vpls-bgp-sig-inter-as-option-b.html)

## **IGMP Snooping**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipmulti\\_igmp/configuration/15-s/imc-igmp-15-s-book/imc\\_igmp\\_snoop.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipmulti_igmp/configuration/15-s/imc-igmp-15-s-book/imc_igmp_snoop.html)

## **ISIS local microloop protection**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute\\_isis/configuration/15-s/irs-15-s-book/irs-uloop-local-avoid.html](http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_isis/configuration/15-s/irs-15-s-book/irs-uloop-local-avoid.html)

## **SLM over PoCH interfaces**

For detailed information about this feature, see the following document:

[http://www.cisco.com/c/en/us/td/docs/routers/7600/ios/15S/configuration/guide/7600\\_15\\_0s\\_book/y-1731PM.html](http://www.cisco.com/c/en/us/td/docs/routers/7600/ios/15S/configuration/guide/7600_15_0s_book/y-1731PM.html)

## **New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(2)S**

For detailed information about hardware and software features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(2)S, see the following document:

[https://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901/Release/Notes/b-901-rn-15-4-2.html](https://www.cisco.com/c/en/us/td/docs/wireless/asr_901/Release/Notes/b-901-rn-15-4-2.html)

## **New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(2)S**

For detailed information about hardware and software features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(2)S, see the following document:

[https://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901s/scg/b\\_scg\\_for\\_asr901s.html](https://www.cisco.com/c/en/us/td/docs/wireless/asr_901s/scg/b_scg_for_asr901s.html)

## New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4(2)S

For detailed information about hardware and software features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4(2)S, see the following document:

<http://www.cisco.com/c/en/us/support/switches/me-3600x-series-ethernet-access-switches/products-release-notes-list.html>

## MIBs

To locate and download MIBs for selected platforms, Cisco IOS releases, and feature sets, use the Cisco MIB Locator found at the following URL:

<http://tools.cisco.com/ITDIT/MIBS/servlet/index>

If the Cisco MIB Locator does not support the MIB information that you need, you can obtain a list of supported MIBs and download MIBs from the Cisco MIBs page at the following URL:

<http://www.cisco.com/public/sw-center/netmgmt/cmtk/mibs.shtml>

To access the Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank email to [cco-locksmith@cisco.com](mailto:cco-locksmith@cisco.com). An automatic check will verify that your email address is registered with Cisco.com. If the check is successful, account details with a new random password will be emailed to you. Qualified users can establish an account on Cisco.com by following the directions found at this URL:

<http://tools.cisco.com/RPF/register/register.do>

## Important Notes

The following sections contain important notes about Cisco IOS Release 15.4S:

- [Field Notices and Bulletins, page 20](#)

### Field Notices and Bulletins

- **Field Notices**—Cisco recommends that you view the field notices for this release to see if your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).
- **Bulletins**—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).

# Features and Important Notes for Cisco IOS Release 15.4(1)S

These release notes describe the following topics:

- [New and Changed Information, page 21](#)
- [MIBs, page 24](#)
- [Important Notes, page 24](#)

## New and Changed Information

This section lists the new hardware and software features supported on different platforms in Cisco IOS Release 15.4(1)S and contains the following subsections:

- [New Hardware Features in Cisco IOS Release 15.4\(1\)S2, page 21](#)
- [New Software Features in Cisco IOS Release 15.4\(1\)S2, page 21](#)
- [New Hardware Features in Cisco IOS Release 15.4\(1\)S1, page 21](#)
- [New Software Features in Cisco IOS Release 15.4\(1\)S1, page 21](#)
- [New Hardware Features in Cisco IOS Release 15.4\(1\)S, page 22](#)
- [New Software Features in Cisco IOS Release 15.4\(1\)S, page 22](#)
- [New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4\(1\)S, page 24](#)
- [New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4\(1\)S, page 24](#)
- [New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4\(1\)S, page 24](#)

### New Hardware Features in Cisco IOS Release 15.4(1)S2

There are no new hardware features in Cisco IOS Release 15.4(1)S2.

### New Software Features in Cisco IOS Release 15.4(1)S2

There are no new software features in Cisco IOS Release 15.4(1)S2.

### New Hardware Features in Cisco IOS Release 15.4(1)S1

There are no new hardware features in Cisco IOS Release 15.4(1)S1.

### New Software Features in Cisco IOS Release 15.4(1)S1

There are no new software features in Cisco IOS Release 15.4(1)S1.

## New Hardware Features in Cisco IOS Release 15.4(1)S

There are no new hardware features in Cisco IOS Release 15.4(1)S.

## New Software Features in Cisco IOS Release 15.4(1)S

This section describes new and changed features in Cisco IOS Release 15.4(1)S. Some features may be new to Cisco IOS Release 15.4(1)S but were released in earlier Cisco IOS software releases. Some features may have been released in earlier Cisco IOS software releases and have been changed in Cisco IOS Release 15.4(1)S. Links to feature modules are included. If a feature listed does not have a link to a feature module, that feature is documented only in the release notes.

### BGP - EVPN / PBB\_EVPN route-reflection

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/bgp-l3vpn-evpn-rr-support.html](http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_bgp/configuration/15-s/bgp-l3vpn-evpn-rr-support.html)

### BGP - IPv6 NSR

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/7600\\_15\\_0s\\_book.html](http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/7600_15_0s_book.html)

### BGP - RTC for legacy PE

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/ios-xml/ios/iproute\\_bgp/configuration/15-s/irg-bgp-rtc-for-legacy-pe.html](http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_bgp/configuration/15-s/irg-bgp-rtc-for-legacy-pe.html)

### BGP GSHUT enhancement

The BGP Graceful Shutdown (GSHUT) Enhancement feature enables graceful shutdown of either all neighbors or only virtual routing and forwarding (VRF) neighbors across BGP sessions. The following command has been introduced in this feature: **bgp graceful-shutdown all**.

### BGP Monitoring Protocol

The BGP Monitoring Protocol (BMP) feature enables configuration and monitoring of BMP servers, establishing connection with the BMP clients, and monitoring and reporting of all configured BGP neighbors. The following commands were added or modified for this feature:

1. The “bmp-activate” keyword was added to the **neighbor** command.
2. The **bmp** command was added.
3. The **bmp server** command was added to enable bmp-server configuration sub-mode under router configuration mode.

### Cisco 8-Port Channelized T1/E1 Shared Port Adapter (SPA-8XCHT1/E1-V2)

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/interfaces\\_modules/shared\\_port\\_adapters/install\\_upgrade/7600series/SIP-SSC-SPA-HW-Install.html](http://www.cisco.com/en/US/docs/interfaces_modules/shared_port_adapters/install_upgrade/7600series/SIP-SSC-SPA-HW-Install.html)

## IOS VRF Multicast Multi-Topology Support

For detailed information about this feature, see the following document:

<http://www.cisco.com/en/US/docs/ios-xml/ios/mtr/configuration/15-s/vrf-support-mtr.html>

## IPV6 VACL (Vlan Access Control List)

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/7600\\_15\\_0s\\_book.html](http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/7600_15_0s_book.html)

## ISIS local microloop protection

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/ios-xml/ios/iproute\\_isis/configuration/15-s/irs-uloop-local-avoid.html](http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_isis/configuration/15-s/irs-uloop-local-avoid.html)

## LMM support over PoCH on 7600

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/routers/7600/install\\_config/ES40\\_config\\_guide/es40\\_chap4.html](http://www.cisco.com/en/US/docs/routers/7600/install_config/ES40_config_guide/es40_chap4.html)

## Multicast MT mode in VRF

For detailed information about this feature, see the following document:

<http://www.cisco.com/en/US/docs/ios-xml/ios/mtr/configuration/15-s/vrf-support-mtr.html>

## Multi-Topology BGP with VRF enhancement

The Multi-Topology BGP with VRF enhancement feature enables multi-topology BGP routing in VRF. There are no new BGP commands introduced or modified for this feature. If multi-topology BGP is configured, the **address-family (ipv4 | ipv6) multicast** command under a specific “vrf definition” is used for configuration; else all multicast VRF activity is configured using the **address-family (ipv4 | ipv6)** command under “vrf definition”.

## OSPFv2 IP FRR Local Microloop Avoidance

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/ios-xml/ios/iproute\\_ospf/configuration/15-s/iro-ospfv2-ip-frr.html](http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_ospf/configuration/15-s/iro-ospfv2-ip-frr.html)

## VPLS over rLFA-FRR on 7600

For detailed information about this feature, see the following document:

[http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/isis\\_lfa\\_ipfrr.html](http://www.cisco.com/en/US/docs/routers/7600/ios/15S/configuration/guide/isis_lfa_ipfrr.html)

## VRF aware BGP translate-update

The VRF aware BGP translate-update feature enables customer devices, that contain an old version of Cisco software that does not support multicast BGP routing, to advertise its routes to multicast VRF-Lite, multicast VPN for VPNv4 and VPNv6 neighbors, as well as through IPv6 over IPv4 tunnel. The “neighbor” command is modified to include the “translate-update” keyword that enables this feature and applies only to the VRF address families.

## New Hardware and Software Features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(1)S

For detailed information about hardware and software features supported on Cisco ASR 901 Series Routers in Cisco IOS Release 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/wireless/asr\\_901/Release/Notes/asr901\\_rn\\_15\\_4\\_1\\_S.html](http://www.cisco.com/en/US/docs/wireless/asr_901/Release/Notes/asr901_rn_15_4_1_S.html)

## New Hardware and Software Features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(1)S

For detailed information about hardware and software features supported on Cisco ASR 901 S Series Routers in Cisco IOS Release 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/wireless/asr\\_901s/rn/b\\_release\\_notes\\_for\\_asr901s.html](http://www.cisco.com/en/US/docs/wireless/asr_901s/rn/b_release_notes_for_asr901s.html)

## New Hardware and Software Features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4(1)S

For detailed information about hardware and software features supported on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/switches/metro/me3600x\\_3800x/software/release/15.4\\_1\\_S/release/notes/o131008.html](http://www.cisco.com/en/US/docs/switches/metro/me3600x_3800x/software/release/15.4_1_S/release/notes/o131008.html)

## MIBs

To locate and download MIBs for selected platforms, Cisco IOS releases, and feature sets, use the Cisco MIB Locator found at the following URL:

<http://tools.cisco.com/ITDIT/MIBS/servlet/index>

If the Cisco MIB Locator does not support the MIB information that you need, you can obtain a list of supported MIBs and download MIBs from the Cisco MIBs page at the following URL:

<http://www.cisco.com/public/sw-center/netmgmt/cmtk/mibs.shtml>

To access the Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank email to [cco-locksmith@cisco.com](mailto:cco-locksmith@cisco.com). An automatic check will verify that your email address is registered with Cisco.com. If the check is successful, account details with a new random password will be emailed to you. Qualified users can establish an account on Cisco.com by following the directions found at this URL:

<http://tools.cisco.com/RPF/register/register.do>

## Important Notes

The following sections contain important notes about Cisco IOS Release 15.4S:

- [Field Notices and Bulletins, page 25](#)



## Field Notices and Bulletins

- Field Notices—Cisco recommends that you view the field notices for this release to see if your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).
- Bulletins—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).





## Bugs





# Bugs for Cisco IOS Release 15.4(3)S

---

## Open and Resolved Bugs

Bugs describe unexpected behavior in Cisco IOS software releases. Severity 1 bugs are the most serious bugs; severity 2 bugs are less serious. Severity 3 bugs are moderate bugs, and only select severity 3 bugs are included in this section.

In this section, the following information is provided for each bug:

- Symptoms—A description of what is observed when the bug occurs.
- Conditions—The conditions under which the bug has been known to occur.
- Workaround—Solutions, if available, to counteract the bug.



### Note

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select bugs of any severity. To reach the Bug Toolkit, log in to [Cisco.com](https://www.cisco.com) and go to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl). (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

---

This section consists of the following subsections:

- [Using the Bug Search Tool, page 30](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S9, page 31](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S8, page 32](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S8, page 34](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S7, page 35](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S7, page 37](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S6a, page 40](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S6, page 40](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S6, page 41](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S5, page 44](#)



- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S5, page 44](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S4, page 45](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S4, page 46](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S3, page 48](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S3, page 49](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S2, page 51](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S1, page 53](#)
- [Open Bugs—Cisco IOS Release 15.4\(3\)S, page 53](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(3\)S, page 55](#)

## Using the Bug Search Tool

The Cisco Bug Search Tool enables you to filter the bugs so that you only see those in which you are interested. In addition to being able to search for a specific bug ID, or for all bugs in a product and release, you can filter the open and/or resolved bugs by one or more of the following criteria:

- Last modified date
- Status, such as fixed (resolved) or open
- Severity
- Support cases

For more information about how to use the Cisco Bug Search Tool, including how to set email alerts for bugs and to save bugs and searches, see [Bug Search Tool Help & FAQ](#).



### Note

---

You must have a Cisco.com account to log in and access the Cisco Bug Search Tool. If you do not have one, you can [register for an account](#).

---

To use the Cisco Bug Search Tool:

1. In your browser, navigate to the [Cisco Bug Search Tool](#).
2. If you are redirected to a **Log In** page, enter your registered Cisco.com username and password and then, click **Log In**.
3. To search for a specific bug, enter the bug ID in the **Search For** field and press Enter.
4. To search for bugs related to a specific software release, do the following:
  - a. In the **Product** field, choose **Series/Model** from the drop-down list and then enter the product name in the text field. If you begin to type the product name, the Cisco Bug Search Tool provides you with a drop-down list of the top ten matches. If you do not see this product listed, continue typing to narrow the search results.
  - b. In the Releases field, enter the release for which you want to see bugs.

The Cisco Bug Search Tool displays a preview of the results of your search below your search criteria. You can mouse over bugs to see more content about a specific bug.

5. To see more content about a specific bug, you can do the following:
  - Mouse over a bug in the preview to display a pop-up with more information about that bug.
  - Click on the hyperlinked bug headline to open a page with the detailed bug information.

6. To restrict the results of a search, choose from one or more of the following filters:

Filter	Description
Modified Date	A predefined date range, such as last week or last six months.
Status	A specific type of bug, such as open or fixed.
Severity	The bug severity level as defined by Cisco. For definitions of the bug severity levels, see <a href="#">Bug Search Tool Help &amp; FAQ</a>
Rating	The rating assigned to the bug by users of the Cisco Bug Search Tool.
Support Cases	Whether a support case has been opened or not.

Your search results update when you choose a filter.

## Resolved Bugs—Cisco IOS Release 15.4(3)S9

*Table 1 Resolved Bugs—Cisco IOS Release 15.4(3)S9*

Caveat ID Number	Description
<a href="#">CSCsv05154</a>	Cisco IOS HTTP server vulnerable to CSRF attacks
<a href="#">CSCui67191</a>	Cisco IOS XE Software Ethernet Virtual Private Network Border Gateway Protocol DOS Vulnerability
<a href="#">CSCun88463</a>	Router reload due to memory corruption with IP SLA
<a href="#">CSCuo87952</a>	Line card FPD upgrade struck, and card FPD status in 'wait' state.
<a href="#">CSCus34406</a>	dmvpn tunnel goes down when removing secondary ip from tunnel source int
<a href="#">CSCus73337</a>	stack stby reloaded by stack-mgr due to active/stdby config out of sync
<a href="#">CSCut45453</a>	icmpv6 reply are blocked
<a href="#">CSCuv80858</a>	byte counters for a port-channel show interface is inaccurate
<a href="#">CSCuw73525</a>	3650 DHCPv6 Guard does not block rogue DHCP server to provide IPv6 addr
<a href="#">CSCux24141</a>	MET mis-programming results in unwanted multicast after switchover
<a href="#">CSCuy14110</a>	CPU Spike seen due to VTEMPLATE BKG OW Process.
<a href="#">CSCuy38144</a>	Protocol Other counted up when executing "show int accounting"
<a href="#">CSCva18762</a>	IGMP packets looping between Active & Standby SP CPU
<a href="#">CSCvb14640</a>	Cisco IOS and Cisco IOS XE Software IPv6 SNMP Message Handling Denial of Service Vulnerability
<a href="#">CSCvc54886</a>	Asr1k(SPA-1XCHSTM1/OC3): Router down after receiving invalid spa ipc-message
<a href="#">CSCvd01613</a>	DSCP value get remarked on the ES+ 10g line cards
<a href="#">CSCvd02153</a>	Router crash due to mpls/ospf config on interface.
<a href="#">CSCvd19860</a>	OSPFv3 AUTH breaks IPv6 traffic intermittently

Caveat ID Number	Description
<a href="#">CSCvd42785</a>	Multicast forwarding when OIF is Null in 7600
<a href="#">CSCve48453</a>	eBGP vrf next-hop setting behaviour is changed by CSCuv07111.
<a href="#">CSCvf12081</a>	Cisco IOS XE Software Verbose Debug Logging Information Disclosure Vulnerability
<a href="#">CSCvf29111</a>	7600 stack low crash
<a href="#">CSCvf74829</a>	CRL download fails due to "failed to create getcacert message"
<a href="#">CSCvf81579</a>	ASR1K: IOSd crash in kmi_initial_check on null map dereference
<a href="#">CSCvg00110</a>	MET table depletion in 7600
<a href="#">CSCvg06443</a>	VPNMAP table depletion in 7600
<a href="#">CSCvg09008</a>	Online Diagnostics detected a Major Error
<a href="#">CSCvg53836</a>	router crashed when MPA with source vlan 1-4094 created
<a href="#">CSCvg84667</a>	Mishandling of udp pkts (that are destined to RP) at 7600 ES+ NP, when BFD is hardware offloaded
<a href="#">CSCvh02536</a>	XE3.16.6B-ES: pmsi_tunnel label value seen as explicit null on downstream PE
<a href="#">CSCvh21686</a>	ES+HD (76-ES+XT-8TG3CXL) LC ports sharing a channel stop forwarding when a port is admin shutdown

## Resolved Bugs—Cisco IOS Release 15.4(3)S8

Table 2 Resolved Bugs—Cisco IOS Release 15.4(3)S8

Caveat ID Number	Description
<a href="#">CSCvb61075</a>	ASR920: Dual-rate EEM errors out when hostname has a dot '.' character
<a href="#">CSCvc89965</a>	After reload route policy processing not re-evaluate with route-map using match RPKI
<a href="#">CSCvc58538</a>	BGP crashes when removing advertise-map
<a href="#">CSCuw35828</a>	crash w/BGP show advertised-routes when route-server is on vrf
<a href="#">CSCvd90251</a>	Duplicate BGP prefixes are not dropped
<a href="#">CSCvd09584</a>	eVPN PMSI VNI decoding / encoding as MPLS label
<a href="#">CSCvd16828</a>	High CPU due to periodic route refresh to VPN peers using rtfiler AF
<a href="#">CSCva86436</a>	no export ipv4 unicast map triggered router to crash
<a href="#">CSCva24325</a>	NSF/SSO feature not honouring TCP MSS
<a href="#">CSCvc31517</a>	Router crashes using BGP commands for long cost extended community string
<a href="#">CSCve51657</a>	Slow convergence with scale after a core link flaps
<a href="#">CSCvd43437</a>	Wrong Source IP Selection for eBGP in EVN/VNET environment
<a href="#">CSCve57697</a>	Crash in Bstun SNMP code
<a href="#">CSCvb30567</a>	C7600 ES+ stuck TOD counters for Y.1731 measurements



<b>Caveat ID Number</b>	<b>Description</b>
<a href="#">CSCva34374</a>	ipv6 traffic over bridge-domain carrying on few ports only
<a href="#">CSCve66601</a>	Crash in CISCO-SLB-EXT-MIB code
<a href="#">CSCCut87808</a>	Crash While Accessing CallManager XML Config
<a href="#">CSCCuz87695</a>	SCCP Phones on CME not forwarding video packets on outbound calls
<a href="#">CSCCux18010</a>	Cisco Networking Services Sensitive Information Disclosure Vulnerability
<a href="#">CSCCuw77959</a>	1801M - %DATACORRUPTION-1-DATAINCONSISTENCY: copy error
<a href="#">CSCva00899</a>	C841M crashes randomly during execution of the reload EEM script.
<a href="#">CSCvb59372</a>	Double-free of VTY context causes a software-forced crash
<a href="#">CSCCux15954</a>	EEM : fatal condition error from operating system
<a href="#">CSCvc98571</a>	EEM applet will not release the Config Session Lock if it ends when CLI is in configuration mode
<a href="#">CSCva42638</a>	Traceback is seen when a EEM script runs
<a href="#">CSCvc44866</a>	3850/3650 - ssh/vty sessions lock up leading to loss of access to device
<a href="#">CSCCut77951</a>	Arp entry changes to an encap type of 802.1Q
<a href="#">CSCvc77378</a>	Glare condition exists for mid call DO INVITE when CUBE receives in-dialogue SIP OPTIONS message
<a href="#">CSCva80218</a>	IOS-XE router crashed due to possible memory leak issue due to CCSIP_SPI_CTRL
<a href="#">CSCvb08960</a>	ezvpn client config disappears from dialer int when pppoe session flaps
<a href="#">CSCve10917</a>	IPSec crash on ASR1k router while processing KMI
<a href="#">CSCvd40880</a>	Modifying crypto ACL leads to a removal of crypto map config
<a href="#">CSCvb94392</a>	Cisco IOS and IOS XE System Software SNMP Subsystem Denial of Service Vulnerability
<a href="#">CSCCuz15131</a>	dqueue not empty prior to destruction crashes ipv4fib_les_switch_wrapper
<a href="#">CSCvd97524</a>	Fixed versions for CSCCuz15131 crash when traffic with maximum size is on wire
<a href="#">CSCvb25357</a>	NHRP registration requests failed after ipv6 tunnel source change
<a href="#">CSCvb65892</a>	ISDN process crashed unexpectedly
<a href="#">CSCve60376</a>	Crash in ADSL DMT SNMP code
<a href="#">CSCvc15923</a>	L2TP Account accuracy: SSS disconnect ACKs are not received for few sessions
<a href="#">CSCvb41889</a>	NTP leap second inserted every day after leap second occurs
<a href="#">CSCCuw97889</a>	Incorrect CLI output after netconf edit-config
<a href="#">CSCCuz95908</a>	Memory leak due to path query with Null outgoing interface
<a href="#">CSCva38391</a>	CVE-2016-1550: NTP security against buffer comparison timing attacks
<a href="#">CSCCuz94245</a>	IGP-LDP sync interoperability for OSPF multi area adj
<a href="#">CSCCuv69650</a>	OSPF Virtual-link using the lowest cost path
<a href="#">CSCCut21950</a>	3560 / RBAC / Unable to exclude enable command.
<a href="#">CSCCuv04247</a>	3850 config-sync failure on standby w/ 'no shut' on wlan
<a href="#">CSCCuw53025</a>	Cat3850 reports "Error, ECI has run out of event blocks" message

Caveat ID Number	Description
<a href="#">CSCus23013</a>	show cmd under "parser view include-exclude" cause standby router to reload
<a href="#">CSCuz22162</a>	Digital certificates does not sync to standby
<a href="#">CSCva66819</a>	Non-Vlan1 did not get initiated with pnp startup-vlan conf after reload
<a href="#">CSCUw60955</a>	non-vlan1 doesn't seem to initiate in Beni-MR3
<a href="#">CSCux52544</a>	PnP Fails to Initiate with Non-VLAN1 Feature Configured
<a href="#">CSCUw15272</a>	PNP: non-vlan 1 zero-touch upgrade does not work
<a href="#">CSCUt25533</a>	PnPA: non-vlan CLI should only apply to newly bootup devices
<a href="#">CSCvc80135</a>	Crash when removing and re-adding bandwidth remaining percent while class-default has fair-queue
<a href="#">CSCvd23034</a>	Multiple Parent Events Per Node lead to a crash
<a href="#">CSCvc56422</a>	XE316:NIM serial interface flaps after soft OIR with traffic
<a href="#">CSCuy08656</a>	SNMP Traps leading a leak in CHUNK functions
<a href="#">CSCve60402</a>	Crash in Voice DNIS SNMP code
<a href="#">CSCve21448</a>	multiple ISR4K VGW's crashed with Segmentation fault(11), Process = DSMP
<a href="#">CSCvb97638</a>	CCSIP_SPI_CONTROL memory usage leads to crash - SIP subscribe messages
<a href="#">CSCvc99971</a>	Cisco Router 2921 sending cisco-rtp payload 121 for RFC2833 (rtp-nte) instead of 101.
<a href="#">CSCvc86595</a>	HTTP 304 response causes mc error and bad magic

## Open Bugs—Cisco IOS Release 15.4(3)S8

Table 3 Open Bugs—Cisco IOS Release 15.4(3)S8

Caveat ID Number	Description
<a href="#">CSCux26195</a>	"aaa accounting suppress null-username" not working as expected
<a href="#">CSCvd69608</a>	Asr1k crashes at PPP process on pushing 4 or more per-user static ipv6 routes
<a href="#">CSCve54313</a>	Crash in ALPS SNMP code
<a href="#">CSCUw97842</a>	Standby RP crash at be_ancp_get_dsl_line_attr
<a href="#">CSCva00765</a>	crash after no ipv4 multicast multitopology command
<a href="#">CSCvf10260</a>	7600 - ACL not programmed upon configuration changes - all incoming packets processed by CPU
<a href="#">CSCts36318</a>	7600: Native Vlan not removed from trunk port
<a href="#">CSCvd86374</a>	ES20 module crash after FRR object is freed then accessed
<a href="#">CSCvc68496</a>	Discrepancy in number of ACEs in active and Standby after CoA
<a href="#">CSCun31438</a>	Abnormal Call Disconnection due under load due to DP errors
<a href="#">CSCux41072</a>	EIGRP sending hello messages with interface in passive mode.

Caveat ID Number	Description
<a href="#">CSCvb86484</a>	wrong EIGRP redistribution statement in startup config breaks BGP settings after router reload
<a href="#">CSCuv74256</a>	IOS: HMAC key miscalculated with DH Group 21 and IPsec PFS enabled
<a href="#">CSCve13491</a>	Router might crash due watchdog when creating a new swidb at if_index_allocate_index
<a href="#">CSCva55916</a>	CUBE crash in resolve_sig_ip_address_to_bind NULL ccb
<a href="#">CSCuv08835</a>	IPSEC key engine process leaks /w dynamic crypto map in scaled scenario
<a href="#">CSCuv14856</a>	WATCHDOG timeout crash during IPSEC phase 2
<a href="#">CSCuv51788</a>	GM Router failed to register after reload.
<a href="#">CSCup84620</a>	"show crypto isakmp stats" should print dropped IKE messages
<a href="#">CSCup90021</a>	IKEv1 periodic DPDs sent per IPsec SA, not per IKE
<a href="#">CSCvc21452</a>	ASR903:ISIS routes are set with Max Metric due to IGP LDP Sync
<a href="#">CSCvc82325</a>	Crash after the MPLS LDP neighbor flap in the NSR scenario
<a href="#">CSCvf21718</a>	ASRIK crash when running 'show ip nhrp vrf ... detail'
<a href="#">CSCvc65670</a>	NTP leap second addition/deletion for consecutive leap months not working properly
<a href="#">CSCuz62898</a>	Crash in BGP due to regular expressions
<a href="#">CSCvf24928</a>	QFP exmem memory leak in cpp_fm_sce_result_chunk
<a href="#">CSCuv02537</a>	ASRIK ESP200 reload in a B2B CGN NAT scenario with PAP+BPA
<a href="#">CSCux93752</a>	SRST Double Ringback heard on blind transfer to PSTN
<a href="#">CSCuv74171</a>	crash on command "show snmp view"
<a href="#">CSCve46273</a>	%TRANSCIEVER-3-RPC_FAILED: Application error (rc = 3)
<a href="#">CSCux86075</a>	Unexpected crash during SSH operation
<a href="#">CSCvb72458</a>	Router repeatedly crashing with "%UTIL-3-TREE: Data structure error"
<a href="#">CSCuu71299</a>	MPLS LDP flap with %TCP-6-BADAUTH: No MD5 digest
<a href="#">CSCve66658</a>	Crash in TN3270E-RT-MIB code
<a href="#">CSCva08142</a>	IOSd crash on LISP enable router
<a href="#">CSCva00551</a>	Cisco Router may crash on SIP MA Process Due to sstrncpy()
<a href="#">CSCuz72665</a>	DATACORRUPTION-1-DATAINCONSISTENCY error when copying from PAI header

## Resolved Bugs—Cisco IOS Release 15.4(3)S7

Table 4 Resolved Bugs—Cisco IOS Release 15.4(3)S7

Caveat ID Number	Description
<a href="#">CSCva47253</a>	AAA crash on multiple username deletions - Part 2
<a href="#">CSCvb64818</a>	ASR1k/ISG : 3.13.6 : Crash due to bad id in id_to_ptr when sending Accounting to non-existing group
<a href="#">CSCvc42499</a>	Function radius_message_authenticator_decode
<a href="#">CSCuy76789</a>	16.2 Throttle: UDP Packets are getting dropped with nat64+ZBFW configs
<a href="#">CSCuw66787</a>	Clear ip nat translation vrf X impacts vrf Y
<a href="#">CSCvb95069</a>	FTP Passive mode: NAT door limit being exceeded
<a href="#">CSCvb62767</a>	NATed packets are dropped by ALG_PROCESS_TOKEN_FAIL due to NAT door limit being exceeded
<a href="#">CSCuz93698</a>	PPTP Traffic issue with Carrier Grade NAT on IOS-XE
<a href="#">CSCva86436</a>	no export ipv4 unicast map triggered router to crash
<a href="#">CSCva24325</a>	NSF/SSO feature not honouring TCP MSS
<a href="#">CSCva25965</a>	Router may crash after multiple show ip bgp sum/neighbor
<a href="#">CSCuv69297</a>	Catalyst 3850: SSH/VTY session hangs on show run or other show commands
<a href="#">CSCvc33619</a>	Major error status seen on card WS-X6748-GE-TX
<a href="#">CSCva61877</a>	IPv6 neighbor discovery packet processing behavior
<a href="#">CSCvb69386</a>	Controller SPA-1CHSTM1 OC3V2 goes into wedge state after excess controller flaps
<a href="#">CSCva94139</a>	IPv6 neighbor discovery packet processing behavior with SIP-400
<a href="#">CSCva91655</a>	FIB recursive loop crash
<a href="#">CSCuz81292</a>	IPv6 neighbor discovery packet processing behavior
<a href="#">CSCuh23818</a>	HTTPS Secure server script crashed iosd and reloads with traceback
<a href="#">CSCuv97379</a>	[ST-P] STBY router crashed on disconnecting call on ACTIVE
<a href="#">CSCuy30957</a>	For IPv6:Activate Under GDOI Fail-Close Disappears on Reboot
<a href="#">CSCva62029</a>	Crash observed on GM when rekey message received from Key server
<a href="#">CSCvb94852</a>	IKEV2 Default Proposal Reset After Reload
<a href="#">CSCva61415</a>	Unable to initiate IKE sessions due to mismatch in CAC counters
<a href="#">CSCvb29204</a>	BenignCertain on IOS and IOS-XE
<a href="#">CSCva44179</a>	IKEv1 DPD delete logic causes stale phase 2
<a href="#">CSCuz42299</a>	Crash when configuring CWS
<a href="#">CSCut45177</a>	CWS HTTPs traffic fails to load on ISR configured with NVI
<a href="#">CSCva18067</a>	CPU HOG and Crash by MFIB_rate
<a href="#">CSCuz28618</a>	sup2t: sup crashed after MFIB errors
<a href="#">CSCva43443</a>	DNA/SA, Upon Quad SUP SSO, Mcast decap traffic black holing for ~50 sec
<a href="#">CSCva59927</a>	UCI, On QuadS6T Second SSO, PIM joins are not encapsulating over VRF LISP
<a href="#">CSCva99279</a>	RSP3: Labels not getting assigned in spite of having free label space
<a href="#">CSCva97469</a>	VA stuck in protocol down state after failing to establish IPsec session

Caveat ID Number	Description
<a href="#">CSCux99025</a>	Evaluation of Cisco IOS and IOS-XEI for NTP January 2016
<a href="#">CSCux46898</a>	NTP associations vulnerability
<a href="#">CSCvb19326</a>	NTP leap second failure to insert after leap second occurs
<a href="#">CSCvb00272</a>	OSPFv3 IPSEC socket session is not coming up after reboot
<a href="#">CSCvb66420</a>	PFR Sync Issues between MC and Border router ,active probes are missing on border router randomly
<a href="#">CSCvb96706</a>	Client auth and enroll to subca fails
<a href="#">CSCuy13701</a>	IOS PKI: Crash while editing a VRF aware TP with enrollment profile
<a href="#">CSCuv44053</a>	PKI Rollover: rollover cert is being added as active id cert
<a href="#">CSCvb73018</a>	PKI: Cannot import RSA SubCA signed by ECDSA
<a href="#">CSCva15013</a>	AAA/RADIUS memory leak on IOS-XE
<a href="#">CSCuz87179</a>	Crash observed while bringing up PTA sessions in SSS Manager
<a href="#">CSCva67564</a>	No V-Cookie in accounting stop due to idle timeout or manual clearing
<a href="#">CSCuz57124</a>	Tracebacks *MSG 00001 TRUNCATED* on standby, after PTA Sess brought up
<a href="#">CSCvb24139</a>	H225 Sanity Check Failure
<a href="#">CSCuz82533</a>	Router crashed when the virtual access interface comes up
<a href="#">CSCuo75126</a>	Ucode crash seen with Firewall configs in B2BHA setup
<a href="#">CSCva65990</a>	'sh police int' hidden command causes RP to crash
<a href="#">CSCuz76821</a>	tableid_ha: Memleak @ eobc_pool_getbuffer
<a href="#">CSCva37519</a>	stale flowmgr entry during ipv6 tacacs transaction leads to crash
<a href="#">CSCuy38157</a>	Router crash during handling L2 and L3 subscribers at the same time
<a href="#">CSCuv41355</a>	Unable to telnet -- No wild listener: port 23
<a href="#">CSCuh09324</a>	udp entries not deleted from flowmgr table
<a href="#">CSCuz03079</a>	ISR-4K Processing Error: H323 Setup parameter "mediaWaitForConnect TRUE"
<a href="#">CSCva22751</a>	Router crashing due to a watchdog in the ISDN process
<a href="#">CSCvb24266</a>	ISR 4K Crashes When Running "Debug Voice Translation"
<a href="#">CSCva00015</a>	STBY SBC router crashing multiple times
<a href="#">CSCvc19209</a>	SIP session between VXML GW and the Nuance server remains active after callback (CCB) is scheduled
<a href="#">CSCvb90483</a>	VXML GW hardening changes for ICBC memory corruption issue

## Open Bugs—Cisco IOS Release 15.4(3)S7

Table 5 Open Bugs—Cisco IOS Release 15.4(3)S7

Caveat ID Number	Description
<a href="#">CSCux26195</a>	"aaa accounting suppress null-username" not working as expected
<a href="#">CSCuu36200</a>	Radius auth fails if ip radius source-interface vrf default in startup
<a href="#">CSCvb05362</a>	RP crashed - UNIX-EXT-SIGNAL: Segmentation fault(11), Process = ANCP HA
<a href="#">CSCuz21435</a>	IOS-XE: 'ACE event' process watchdog crash.
<a href="#">CSCus85112</a>	CGN, QFP: Show cmd display incorrect NAT trans stats for per-host IP add
<a href="#">CSCup57389</a>	Traffic drops while testing VRF Lite coexistence with SP NAT for LNS
<a href="#">CSCuw97842</a>	Standby RP crash at be_ancp_get_dsl_line_attrs
<a href="#">CSCul15273</a>	AN Link local Tunels not deleted after no autonomic is issued
<a href="#">CSCuo97277</a>	iosd crashed at bfd_chkpt_create_and_send_msg
<a href="#">CSCvc12039</a>	ASR903/RSP1B&RSP3C 3sec to 10sec loss on RSP switchover when SSO enabled
<a href="#">CSCut40990</a>	BGP:send-community inheritance when explicit configuration match default
<a href="#">CSCva00765</a>	crash after no ipv4 multicast multitopology command
<a href="#">CSCus04010</a>	dmpvn hub router crashes when clearing bgp peers
<a href="#">CSCus19601</a>	IPV6 RR not changing Next-hop for a IPV6 prefix
<a href="#">CSCuq27095</a>	Memory leak in BGP table if terminate at show bgp af summary auto more
<a href="#">CSCup33405</a>	Prefixes from GR peer not removed from BGP table when peer goes down
<a href="#">CSCvb22903</a>	RP3 fails to clear SA in the large scale IPsec SCM configuration
<a href="#">CSCup01258</a>	sh ipv6 dhcp pool command display wrong output after router reload
<a href="#">CSCva13768</a>	ISR 4KIPPPoE InterfacelNot Forwarding all IP fragments
<a href="#">CSCun31438</a>	Abnormal Call Disconnection due under load due to DP errors
<a href="#">CSCux41072</a>	EIGRP sending hello messages with interface in passive mode.
<a href="#">CSCvb86484</a>	wrong EIGRP redistribution statement in startup config breaks BGP settings after router reload
<a href="#">CSCur72967</a>	43xx/44xx "show platform software cerm-information" not accounting pkts
<a href="#">CSCuv74256</a>	IOS: HMAC key miscalculated with DH Group 21 and IPsec PFS enabled
<a href="#">CSCtw50974</a>	ASR/ISR4K DTMF 2833 to 2833 Not Working with MTP CoLocated and OOB+2833
<a href="#">CSCut79286</a>	ASR1K QoS feature doesn't work fine with RP2/RIs3.x
<a href="#">CSCup26658</a>	Unexpected Process Restart after "no spanning tree", "default interface"
<a href="#">CSCuw43115</a>	CSR1Kv XE 3.13.3S Crashed on clearing ip ospf process
<a href="#">CSCva55916</a>	CUBE crash in resolve_sig_ip_address_to_bind NULL ccb
<a href="#">CSCuq17104</a>	CUBE disconnecting a call after call transfer due to Hold timer
<a href="#">CSCuu12283</a>	CUBE failed to create DP session on STBY for Webex flow
<a href="#">CSCuw39465</a>	During a transfer CUBE doesnt update the media to the Recording server
<a href="#">CSCuq24354</a>	GETVPN KS rekeys without pol changes may cause IOS XE GMs to re-register
<a href="#">CSCuv08835</a>	IPSEC key engine process leaks /w dynamic crypto map in scaled scenario

Caveat ID Number	Description
<a href="#">CSCux16726</a>	ipv6 OSPFv3 crypto session doesnt come UP after reload
<a href="#">CSCuj53943</a>	Multicast packets are dropped after "clear crypto gdoi ks members"
<a href="#">CSCvc78492</a>	Unable to pass traffic if spoke to spoke fails to build in phase 2
<a href="#">CSCuv51788</a>	GM Router failed to register after reload.
<a href="#">CSCuu41857</a>	Incorrect GDOI registration backoff timer calculation after crash/reload
<a href="#">CSCup84620</a>	"show crypto isakmp stats" should print dropped IKE messages
<a href="#">CSCup90021</a>	IKEv1 periodic DPDs sent per IPsec SA, not per IKE
<a href="#">CSCun72450</a>	IPv6 GETVPN traffic dropped after un-configure then re-configure VRF
<a href="#">CSCvb65892</a>	ISDN process crashed unexpectedly
<a href="#">CSCul24766</a>	Core files are corrupt - crc error
<a href="#">CSCuy03680</a>	V3Lite IGMP packets sent instead of V3 when UDP based feature is present
<a href="#">CSCur10311</a>	MAG does not accept PBA without GRE key during de-registration
<a href="#">CSCvc21452</a>	ASR903:ISIS routes are set with Max Metric due to IGP LDP Sync
<a href="#">CSCuv00547</a>	CRASH SEEN AFTER FLAPPING MPLS INTERFACES
<a href="#">CSCuq95663</a>	CENT: small increase in IPC still exists in longevity
<a href="#">CSCuz22260</a>	ISR G2: unexpected byte lost with Pfrv3 and NBAR based QoS integration
<a href="#">CSCvb92697</a>	High CPU due to NHRP when NHRP cache entry for remote spoke's tunnel address is deleted
<a href="#">CSCux80450</a>	%REGISTRY-3-STUB_CHK_OVERWRITE: error seen during boot up
<a href="#">CSCvc65670</a>	NTP leap second inserted every day after leap second occurs
<a href="#">CSCvb48912</a>	SNMP crashes getting ntpAssociationEntry with low/fragmented memory condition
<a href="#">CSCuz62898</a>	Crash in BGP due to regular expressions
<a href="#">CSCuv69650</a>	OSPF Virtual-link using the lowest cost path
<a href="#">CSCum19502</a>	Inconsistent behavior between telnet and ssh in low memory conditions
<a href="#">CSCus23013</a>	show cmd under "parser view include-exclude" cause standby router to reload
<a href="#">CSCva72564</a>	Customer POC- Autoinstall obtained IP overrides USB bootstrap config
<a href="#">CSCuw24373</a>	Called-station-id and NAS-ID via account profile satus query
<a href="#">CSCun96847</a>	IOS-XE : Zone mismatch vulnerability in Zone Based Firewall
<a href="#">CSCux52451</a>	VRF Domain half open counter increments when aggressive aging occurs
<a href="#">CSCuv02537</a>	ASR1K ESP200 reload in a B2B CGN NAT scenario with PAP+BPA
<a href="#">CSCvb77570</a>	ASR1K: Crash after upgrade to 3.16.3 at transmit_pkt_marmot_spa_d
<a href="#">CSCuw95297</a>	ESP200 crash with 550K translations with cablevision config
<a href="#">CSCux68096</a>	ucode crash abort called from ipv4_nat_create_inside_addrport_bind
<a href="#">CSCva95830</a>	HQF not cleaned after invalid policy applied to vlan-manual GEC subintf
<a href="#">CSCtx83808</a>	PPP: Traceback when changing police to shaper on LNS
<a href="#">CSCum03909</a>	mvpnv6 mldp router crash on _be_ipv6_pdb_remove_ipdb_private
<a href="#">CSCux93752</a>	SRST Double Ringback heard on blind transfer to PSTN



Caveat ID Number	Description
<a href="#">CSCup04090</a>	asr920 throws error messages on snmp polling of a couple of MIBs
<a href="#">CSCuv74171</a>	crash on command "show snmp view"
<a href="#">CSCux86075</a>	Unexpected crash during SSH operation
<a href="#">CSCvb72458</a>	Router repeatedly crashing with "%UTIL-3-TREE: Data structure error"
<a href="#">CSCuy74990</a>	BGP not forming neighborhood on ASR1k with dual RP
<a href="#">CSCuu71299</a>	MPLS LDP flap with %TCP-6-BADAUTH: No MD5 digest
<a href="#">CSCva08142</a>	IOSd crash on LISP enable router
<a href="#">CSCvc81332</a>	ASR Cube crashed @ AFW_M_Connection_EventPreProcess
<a href="#">CSCvb97638</a>	CCSIP_SIP_CONTROL memory usage leads to crash
<a href="#">CSCva00551</a>	Cisco Router may crash on SIP MA Process Due to strstrcpy()
<a href="#">CSCuz72665</a>	DATA CORRUPTION-1-DATA INCONSISTENCY error when copying from PAI header
<a href="#">CSCux16650</a>	SHA-2 support on ISR G2

## Resolved Bugs—Cisco IOS Release 15.4(3)S6a

This is a special release in Cisco IOS software that addresses Cisco Product Security Incident Response Team (PSIRT) caveats.

*Table 6 Resolved Bugs—Cisco IOS Release 15.4(3)S6a*

Caveat ID Number	Description
<a href="#">CSCvb29204</a>	BenignCertain on IOS and IOS-XE
<a href="#">CSCuv87976</a>	CLI Knob for handling Leap second Add/delete ignore/ handle
<a href="#">CSCux46898</a>	NTP associations vulnerability
<a href="#">CSCvb19326</a>	NTP leap second addition is not working during leap second event

## Open Bugs—Cisco IOS Release 15.4(3)S6

*Table 7 Open Bugs—Cisco IOS Release 15.4(3)S6*

Caveat ID Number	Description
<a href="#">CSCva15013</a>	AAA/RADIUS memory leak on IOS-XE
<a href="#">CSCva00765</a>	crash after no ipv4 multicast multitopology command
<a href="#">CSCva82501</a>	FNF crash during multiple config



Caveat ID Number	Description
<a href="#">CSCva55916</a>	CUBE crash in resolve_sig_ip_address_to_bind NULL ccb
<a href="#">CSCuu12283</a>	CUBE failed to create DP session on STBY for Webex flow
<a href="#">CSCva71545</a>	Under load crash seen@CCSIP_UDP_SOCKET process in XE3.16 image
<a href="#">CSCva62029</a>	Crash observed on GM when rekey message received from Key server
<a href="#">CSCcuy03680</a>	V3Lite IGMP packets sent instead of V3 when UDP based feature is present
<a href="#">CSCcuy13701</a>	IOS PKI: Crash while editing a VRF aware TP with enrollment profile
<a href="#">CSCcuo75126</a>	Ucode crash seen with Firewall configs in B2BHA setup
<a href="#">CSCcuy74990</a>	BGP not forming neighborhood on ASR1k with dual RP
<a href="#">CSCva08142</a>	IOSd crash on LISP enable router
<a href="#">CSCva00551</a>	ISR 4K Crash on SIP MA Process Due to sstrncpy()
<a href="#">CSCva00015</a>	STBY SBC router crashing multiple times

## Resolved Bugs—Cisco IOS Release 15.4(3)S6

Table 8 Resolved Bugs—Cisco IOS Release 15.4(3)S6

Caveat ID Number	Description
<a href="#">CSCuz48415</a>	"aaa authentication suppress null-username" not working as expected
<a href="#">CSCuw86386</a>	AAA crash when removing TACACS servers
<a href="#">CSCcuy21675</a>	Crash@username_command with service pwd-encryption & common-criteria cfg
<a href="#">CSCcux69225</a>	Mac filtering option "None" sends blank password
<a href="#">CSCcuy01051</a>	MPLS VPN over mGRE Routing issue after reload
<a href="#">CSCuz82218</a>	TACACS Enable authentication fails with null pre shared key
<a href="#">CSCcuy03054</a>	ASR1K IOSd may crash in BGP Acceptor process due to segmentation fault
<a href="#">CSCcux55351</a>	ASR1K router crashed due to running BGP with AIGP
<a href="#">CSCcux70093</a>	BGP RR does not advertise vpnv6 prefixes even all RT filters are learnt
<a href="#">CSCcuy20481</a>	Crash due to stale pointer after removing vrf command export AF map
<a href="#">CSCcux76332</a>	Deleting a statement in export map, removes other statement
<a href="#">CSCcux96029</a>	GR Non-restarting peer does not advertise VPN routes default RT filter
<a href="#">CSCcuy03504</a>	Incorrect prefix count upon clearing bgp peering
<a href="#">CSCuz58682</a>	Incorrect VPN withdraw with overlapping RT on multiple RT Filter
<a href="#">CSCuz21061</a>	router crashes after %BGP-6-BIGCHUNK + SNMP query.
<a href="#">CSCcux62094</a>	Routes are not exported from vrf to global due to incorrect export limit

Caveat ID Number	Description
<a href="#">CSCUw66752</a>	"SSM connection manager" high CPU if VAIs under scale have QOS applied
<a href="#">CSCUy79944</a>	call-home crash because calling XOS API in interrupt level
<a href="#">CSCUw06084</a>	DTMF not getting recognized on ISR G3 when using TCL Script
<a href="#">CSCUx60876</a>	Memory corruption due to DHCP
<a href="#">CSCUx49494</a>	'allow connections' or 'telephony-service' config is required on ISR4k
<a href="#">CSCUz56699</a>	ISR 4k Paging over SIP / FXS phones have no audio
<a href="#">CSCUy38707</a>	After RSP switchover, BFD hangs for up to 10 minutes before converging
<a href="#">CSCUw48118</a>	ASR920 - crash in bcopy called from 'addnew' during reassembly
<a href="#">CSCUx29974</a>	ISR4k:UnconfiguredIpv4Fia drop seen for pkts transit via PPPoE
<a href="#">CSCUz12967</a>	Crash after show ip protocols vrf with RIP enabled
<a href="#">CSCUy48358</a>	Crash during SIP subscribe notify ACK
<a href="#">CSCUz47777</a>	DTMF issue on ISR G3/ASR during the prompt using TCL Script
<a href="#">CSCUy40672</a>	One way audio in a DODO call after transfer with REFER disabled
<a href="#">CSCUz71250</a>	Router crashes when parsing ack for mid call
<a href="#">CSCUz69975</a>	Under load crash is seen in CVP REFER_PASSTHRU scenario
<a href="#">CSCUw23947</a>	For IPv4: Activate Under GDOI Fail-Close Disappears on Reboot
<a href="#">CSCUy43118</a>	XE316: HubBR might be crashed@tunnel_protection_validate_shared_profile
<a href="#">CSCUu44128</a>	GETVPN on ASR with vasi interface fail to install the Rekey
<a href="#">CSCUz14788</a>	New reg invoke PKI function breaks the GETVPN CRL Checking feature
<a href="#">CSCUv31981</a>	ISR Router Crashes When Trying to Delete a Freed SA
<a href="#">CSCUz99865</a>	IPSec MIB queries results in memory leak and shows wrong SNMP value.
<a href="#">CSCUz25240</a>	ISIS not installing back to RIB neighbors loopback when interface flaps
<a href="#">CSCUx29806</a>	ISIS routes are not not installed in the routing table from isisdatabase
<a href="#">CSCUz35203</a>	SSM connection manager crash during VFI pseudowire bind
<a href="#">CSCUq32410</a>	"Seg fault @ mLDP Process"&Crash@nile_mc_handle_prefix_L3_and_not_L2
<a href="#">CSCUy02409</a>	BDI not Passing VRRP Multicast Traffic
<a href="#">CSCUz39721</a>	ASR1K/RP2/SW 15.4(3)S4 crash
<a href="#">CSCUx78294</a>	Crash on router when removing L2VPN
<a href="#">CSCUs72718</a>	L2TPv3 session pending between 2 devices
<a href="#">CSCUx58640</a>	LDP NSR: Label Mapping Messages Not Sent on RP SSO and VCs Re-bind
<a href="#">CSCUw65792</a>	CWS not associating CN with nested groups when "," (comma) is used
<a href="#">CSCUw65059</a>	mfib on the line card stuck in Connecting state
<a href="#">CSCUv02246</a>	With access interface flap, traffic doesnt switch back to data mdt.
<a href="#">CSCUv37022</a>	Extranet MVPN traffic is getting dropped & not switched to data MDT
<a href="#">CSCUy87734</a>	ASR1K RP crashes LCON Main process when heavily loaded
<a href="#">CSCVa17339</a>	LDP session stuck in established with no TCP connection
<a href="#">CSCUy71712</a>	FlexVPN: Spoke spawns a virtual access to connect to the hub

<b>Caveat ID Number</b>	<b>Description</b>
<a href="#">CSCuy04757</a>	Crash@ospfv3_router_process_mgd_timers on shut/no shut of sub-intf
<a href="#">CSCuy32709</a>	R-LFA Tunnels not established on setting DS required attribute
<a href="#">CSCux19034</a>	XE3.16 crashes when conf "distribute-list" under router ospf and sh run
<a href="#">CSCuo61229</a>	ASR1002 Crashed after "show pfr master active running"
<a href="#">CSCux20613</a>	Bus error crash at oer_saa_mc_get_probe_stats_cbk
<a href="#">CSCuw57225</a>	PFRv2 not work well for 10% inbound load-balance
<a href="#">CSCuy22067</a>	PfRv2 stream keep remaining in DEFAULT state
<a href="#">CSCuy85870</a>	Wrong TD next-hop for overlapping prefixes
<a href="#">CSCur10056</a>	Memory leak in SSS Manager
<a href="#">CSCuw79412</a>	%SYS-6-STACKLOW: Stack for process PPP SIP running low, 0/6000
<a href="#">CSCuo76385</a>	Router crashes at ic_dp_classify when Serial link flaps
<a href="#">CSCuz99848</a>	Memory exhaustion traceback due to large and complex configuration
<a href="#">CSCva28875</a>	NAT ALG fails on Multipart SIP Header
<a href="#">CSCuw50415</a>	Crash seen @ hwidb_iftype_unlist while doing unconf of channel-group
<a href="#">CSCuw55717</a>	Memleak @ pak_pool_cache_item_get : Scaled TFEX
<a href="#">CSCuy55849</a>	RTR installs the ISIS(or OSPF) route with Higher Metric in the RIB
<a href="#">CSCuz76295</a>	MPLS-TE FRR packet drops during re optimization.
<a href="#">CSCuy38709</a>	Memory leak with watcher_create_common.
<a href="#">CSCux82377</a>	ASR 1K ISG Router Crashes When Polling "csubSessionEntry" MIB
<a href="#">CSCuy69440</a>	ISG Critical Exception and crashing with SSS-Manager holding memory
<a href="#">CSCuz62915</a>	ISR4451 crash under load due to Segmentation fault(11), Process = DSMP
<a href="#">CSCuy65330</a>	RSVP Reservation Failure Causes Call Drop on Voice to Video Calls
<a href="#">CSCus45019</a>	Media loop detection failure
<a href="#">CSCuj50209</a>	Memory leak @ voip_rtp_recv_fs_input
<a href="#">CSCuy14532</a>	rtp/rtcp media activity timer doesn't trigger when only 1 rtp leg drops
<a href="#">CSCux54794</a>	Configuration under the E&M voice-ports are missing after the reload
<a href="#">CSCuy16501</a>	Static noise introduced on FXO after IOS upgrade
<a href="#">CSCva30483</a>	IOS-XE 4321 Router crash with BRI interface going down
<a href="#">CSCuz52693</a>	ISR 4K Memory Holding in CCSIP_SPI_CONTROL
<a href="#">CSCus03761</a>	Stack overflow crash @ ip_epm_proxy_slow_check.
<a href="#">CSCuy83854</a>	deb voip application vxml with 1 cvp call caused buffer overflow
<a href="#">CSCuz17364</a>	DTMF Type ahead buffer on GW with Nuance not working
<a href="#">CSCuu25704</a>	Memory corruption in the IO pool when a t38 fax gateway receives t37 fax

## Open Bugs—Cisco IOS Release 15.4(3)S5

*Table 9 Open Bugs—Cisco IOS Release 15.4(3)S5*

Identifier	Description
<a href="#">CSCux44606</a>	Name ACL for Multicast Boundary Stops Working Upon Reload
<a href="#">CSCux33568</a>	ESP crash while reconfiguring FR interface to MFR bundle
<a href="#">CSCux07224</a>	ASR1K crash with OTV due to L2BD FIB entry change
<a href="#">CSCux59115</a>	ASR1002-X Crash with dpidb_tableid_params_initialize
<a href="#">CSCux93176</a>	ASR1k:stby RP stuck while bootup
<a href="#">CSCur48133</a>	ATM 3xOC3 SPA failed to program with IFCFG_CMD_TIMEOUT error

## Resolved Bugs—Cisco IOS Release 15.4(3)S5

*Table 10 Resolved Bugs—Cisco IOS Release 15.4(3)S5*

Identifier	Description
<a href="#">CSCUw89522</a>	ASR IOSD crash because of AVC feature
<a href="#">CSCUw13407</a>	PfRV3: transport bytes expected counters overflow and not expected
<a href="#">CSCUv79776</a>	Router with Pfr feature crashed at cpp_free_exmem
<a href="#">CSCUw30599</a>	ISR4331-B: traceback occurred when enabling Ethernet Data Plane Loopback
<a href="#">CSCUv84600</a>	Netflow packets are dropped when EPC is enabled
<a href="#">CSCux29703</a>	ASR1000-2T+20X1GE fails to boot on router reload with SPA-3-NUL_BAY_PTR
<a href="#">CSCUu48458</a>	ASR1k/15.4(3)S QinQ frames are dropped under "TCAM Failure Drops"
<a href="#">CSCux55692</a>	TCAM Errors in NL1k TCAM of Fixed Ethernet Linecards
<a href="#">CSCUw98135</a>	ZBFW HA not replicating sessions when matching based upon L4 proto/port
<a href="#">CSCUw21897</a>	Traceback seen with ip cef accounting
<a href="#">CSCux57066</a>	ASR1K : Lawful Intercept not working as expected for IPv6 traffic
<a href="#">CSCux02656</a>	ASR1K: Crash related to collecting NetFlow data for IPv6 flows
<a href="#">CSCUw36887</a>	Crash with with Flexible Netflow enabled
<a href="#">CSCUw78755</a>	IOS-XE need not require appxk9 license to support per-tunnel DMVPN QoS
<a href="#">CSCUp91567</a>	ASR1001-X boot-loops with CMCC crash and XGM MAC10 block errors
<a href="#">CSCux01133</a>	interface counter stuck on build-in interfaces in ASR1001X
<a href="#">CSCux43951</a>	Packet drops on built-in 1Gig ports of ASR1001-X
<a href="#">CSCUv26762</a>	ASR1001X HMAN generating error msg when reading /proc/cpuinfo
<a href="#">CSCux42411</a>	ASR1001-X Frame Relay with Fortitude NIM fails due to LMI packet padding
<a href="#">CSCUv93130</a>	Cisco IOS-XE 3S platforms Series Root Shell License Bypass Vulnerability
<a href="#">CSCUp70353</a>	IOS-XE router reload due to WebUI log file leak
<a href="#">CSCUw49798</a>	ASR1K: cpp_cp_svr core@cpp_qm_cm_n_delete_queue

Identifier	Description
<a href="#">CSCuw94014</a>	cpp_cp crashes with BB profile #6 48k PTA
<a href="#">CSCut49714</a>	GEC:QoS: pkt buff util high after apply/remove flat policy w/ fair-queue
<a href="#">CSCuw81487</a>	Kahuna RP crash when bringing up PTA sessions with QoS
<a href="#">CSCuw73223</a>	Polaris : cpp_cp_svr crash when the interface goes down
<a href="#">CSCux10321</a>	ASR1000 CLI hangs on executing the "show platform hardware qfp xxx"
<a href="#">CSCud50181</a>	SBC srtp ucode crash doing srtp-rtp interworking
<a href="#">CSCuu45832</a>	STUN packets not handled properly by CPP SBC module in ASR CUBE
<a href="#">CSCuw71226</a>	Call stuck in a deactivating state (CUBE-SP)
<a href="#">CSCut78545</a>	delegate registration failed after password change

## Open Bugs—Cisco IOS Release 15.4(3)S4

Table 11 Open Bugs—Cisco IOS Release 15.4(3)S4

Identifier	Description
<a href="#">CSCuv07111</a>	IOS and IOS-XE devices changing the next-hop on BGP route with own IP
<a href="#">CSCup33405</a>	Prefixes are not removed from BGP table with BDI interface shut
<a href="#">CSCut79286</a>	ASR1K QoS feature doesn't work fine with RP2/RIs3.x
<a href="#">CSCuw09483</a>	Unexpected reload w/"privilege exec level '0-15' show macdb" configured
<a href="#">CSCuu12283</a>	CUBE failed to create DP session on STBY for Webex flow
<a href="#">CSCuu26224</a>	CUBE with SRTP fallback will crash when call hit on incoming dial-peer 0
<a href="#">CSCuv61208</a>	ASR1k EasyVPN server loses RRI for clients behind PAT
<a href="#">CSCuw02157</a>	DMVPN Hub: IOS crash at crypto_ipsec_show_map_info
<a href="#">CSCuq24354</a>	GETVPN KS rekeys without pol changes may cause IOS XE GMs to re-register
<a href="#">CSCuw09323</a>	GETVPN: ASR GM stops decrypting until old SA expires after KS ACL change
<a href="#">CSCuw08567</a>	Ident SM exists without Dynamic Crypto Map leading to rekey failures
<a href="#">CSCuj55363</a>	lispgetVpn traffic is dropped when getvpn profile is applied in wan intf
<a href="#">CSCuj53943</a>	Multicast packets are dropped after "clear crypto gdoi ks members"
<a href="#">CSCus85701</a>	AQoS peer mismatch with NAT
<a href="#">CSCuv66070</a>	Crash on executing "show nhrp group-map" command
<a href="#">CSCuv86821</a>	Router crashed due to Crypto IKMP
<a href="#">CSCuv21051</a>	XE310:Traceback@crypto_isakmp_profile_free after unconfiguration
<a href="#">CSCuv94186</a>	SNMPWALK crash at ipsmIPSec_policyOfTunnel
<a href="#">CSCuv79429</a>	IPSEC: static reverse-route is removed after retransmissions in IKMP
<a href="#">CSCun72450</a>	IPv6 GETVPN traffic dropped after un-configure then re-configure VRF
<a href="#">CSCuv59898</a>	Kernel Watchdog crash at ktime_get
<a href="#">CSCus62778</a>	Stale Data MDT entry

Identifier	Description
<a href="#">CSCuq95663</a>	CENT: small increase in IPC still exists in longevity
<a href="#">CSCuv74171</a>	crash on command "show snmp view"
<a href="#">CSCup31575</a>	HTTPS : Back to Back POST request fails
<a href="#">CSCus06158</a>	ISR4x/ISR3x: Mask IOS-XE SSLVPN syntax from configuration
<a href="#">CSCuw14345</a>	High CPU due to "IP Connected Rou" process and Low Memory .

## Resolved Bugs—Cisco IOS Release 15.4(3)S4

Table 12 Resolved Bugs—Cisco IOS Release 15.4(3)S4

Identifier	Description
<a href="#">CSCus21322</a>	Adding NAS_IPV6_ADDRESS in the Sanet
<a href="#">CSCut27272</a>	CPUHOG and crash due to Auth Manager process
<a href="#">CSCur59242</a>	Crash due to tplus_client_stop_timer
<a href="#">CSCuu59324</a>	router crashes @aaa_memerace
<a href="#">CSCus82903</a>	BGP - %IPV6_ADDRESS-3-NULLIDB: Uninitialized interface pointer
<a href="#">CSCuu85298</a>	FIB/LFIB inconsistency after BGP flap
<a href="#">CSCuv66776</a>	MQC Policy-map counters do not update in T3/E3 SPA
<a href="#">CSCur68351</a>	%COMMON_FIB-4-FIBIDBMISMATCH when configuring sub-int for port-channel
<a href="#">CSCur35098</a>	cmfib line card crash
<a href="#">CSCut42214</a>	High memory & CPU utilization on mfib-const-lc Pr process
<a href="#">CSCuv39005</a>	Supervisor crash after configuring NetFlow on a BGP PIC enabled router
<a href="#">CSCuv15500</a>	TCAM utilization increasing up to 100%
<a href="#">CSCuu50392</a>	aaa attr list leak at dsensor_process_pkt_update_cache
<a href="#">CSCuv39338</a>	ISG: DHCP Server RADIUS Proxy Memory Leak
<a href="#">CSCut10251</a>	Some commands are not in running-config after AUTOINSTALL finishes
<a href="#">CSCus25205</a>	Traceback@eigrp_process_dying during unconfiguration
<a href="#">CSCut12738</a>	[ASR1K HSRP] Physical Link Failure Causes HSRP to Fail
<a href="#">CSCuu68439</a>	Crash after no route-target import command
<a href="#">CSCut28445</a>	CSCur47160 broke load balancing
<a href="#">CSCuu26303</a>	Router crash triggered by service policy and ipv6 traffic
<a href="#">CSCus65125</a>	Router crash with NAT @ ipnat_for_us_feature
<a href="#">CSCut80144</a>	Beni MR1: Debug enabled by default on Mingla
<a href="#">CSCuv19154</a>	After upgrade of IOS-XE software, appnav functionality maybe impacted.
<a href="#">CSCuv83793</a>	AppNav-XE drop packets when traffic from WAAS has wrong ID
<a href="#">CSCuu82763</a>	Evaluation of ciscossl in binos for OpenSSL June 2015 vulnerabilities
<a href="#">CSCur32628</a>	7600 mis-programming causing intermittent packet loss

Identifier	Description
<a href="#">CSCuu80048</a>	interface IP address change cause leaked routes in exported vrfs
<a href="#">CSCuv43978</a>	IPv6 GRE over 6PE does not work properly
<a href="#">CSCuv80943</a>	MCP_DEV:Packet drops@Ipv6NoRoute with ipv6gre configs
<a href="#">CSCut24140</a>	Old active not coming up after first sso also seeing a traceback.
<a href="#">CSCuu28199</a>	[Amur-MR3]IOSD crash reported@spi_iosd_ipc_process_inbound_mts_msg
<a href="#">CSCuu29667</a>	ASR1K crash when snmp setting cipSecTunnelEntry
<a href="#">CSCus92857</a>	Crypto Stateless redundancy causing "IPSEC install failed" after preempt
<a href="#">CSCuu54392</a>	Different Tunnel Protection with shared profile cannot be used
<a href="#">CSCut87217</a>	GETVPN - ASR1K GM deny policy fails when the policy is updated by the KS
<a href="#">CSCur29582</a>	IPSEC-VPN: removal of "crypto-map" kills BFD session forever
<a href="#">CSCus79972</a>	Crash on 'tunnel protection ipsec profile profile-name'
<a href="#">CSCut14502</a>	Address pool leak upon Anyconnect reconnect and subsequent disconnect
<a href="#">CSCuu93699</a>	Crash on IKEv2 cluster hub when anyconnect client tries reconnect
<a href="#">CSCut32445</a>	Crash - IPSec/ISAKMP Timer driven crash.
<a href="#">CSCus30128</a>	RRI dynamic L2L after client change ip address Isec rekey lost routes
<a href="#">CSCuv26780</a>	Memory leak when qos pre-classify is configured with Crypto
<a href="#">CSCuj13127</a>	SSTE: DNS IPv6 traffic fails with IKEv2 and ZBFW configured
<a href="#">CSCut88270</a>	Duplicate hsrp vmac entries after OTV AEDs fail over
<a href="#">CSCut30167</a>	ISIS may crash when reaching LSPFULL condition with IPv6 routes
<a href="#">CSCuu77927</a>	OTV stuck in inactive status when failover due to missing isis vlan tlv
<a href="#">CSCup51000</a>	CEMoUDP: PW interface still being unprovisioned, retry later
<a href="#">CSCuv56754</a>	EoMPLS xconnect remains "RECOVERING" after RP SSO on egress
<a href="#">CSCuv29418</a>	Router is continuously switching between active and standby EoMPLS PW
<a href="#">CSCuu50269</a>	RSP2: MSPW sessions down on S-PE after SSO
<a href="#">CSCuu92194</a>	RSP3:HSPW PW-Group Switchover results in traffic blackhole with no scale
<a href="#">CSCuv34896</a>	VPLS autodiscovery PW failed to comeup when BGP recovers from failure
<a href="#">CSCuu36041</a>	VPLS BGP AD resignalling time takes ~20-40s for multi-homing scenario
<a href="#">CSCuq70725</a>	LDAP Address Error at ldap_clear_transaction_all
<a href="#">CSCuu88964</a>	ASR1K Kernel crash at pidns_get()
<a href="#">CSCtz61014</a>	f Linux kernel NTP leap second handling could cause deadlock
<a href="#">CSCuu12600</a>	SR is not working fine in mk2fc2-sup720 device
<a href="#">CSCuu90695</a>	DM/SM boundary (S,G) are not repopulated: Multicast Missing Registration
<a href="#">CSCur70478</a>	Software crash at ldpx_mem_reallocz_grow due to insufficient memory
<a href="#">CSCuv61750</a>	ASR903 MCP_DEV: Mismatch in VC label programming, EoMPLS scenario
<a href="#">CSCuu76169</a>	PfRV3: Collocated hub MC/BR keep on publish site-prefix with enter-pfx
<a href="#">CSCuv83586</a>	PI25: channel flapping with NBAR based QoS Policy for NTT
<a href="#">CSCut85551</a>	Crash with DMVPN NHS using FQDN



Identifier	Description
<a href="#">CSCut77619</a>	APRIL 2015 NTPd Vulnerabilities
<a href="#">CSCuv65370</a>	Avoid any action on Leap SEcond indictor flag for non-leap second months
<a href="#">CSCup81878</a>	Line by Line Sync fails while deleting dynamic NTP peer
<a href="#">CSCus34757</a>	bgp rpki: crash if bgp default received
<a href="#">CSCus68229</a>	Memory leak in OSPFv3R
<a href="#">CSCut63500</a>	dot1q encapsulation causes vam2+ to crash
<a href="#">CSCut96721</a>	Crash on pfr master router at oer_mc_apc_changed_prefix
<a href="#">CSCuu08872</a>	Crash on pfr master router at pfr_exp_send_tc_config_internal
<a href="#">CSCus13902</a>	Failure seen in OER Border router functionality
<a href="#">CSCuv22992</a>	PFR router crashes due to watchdog when displaying config
<a href="#">CSCuu98524</a>	PFR/OER related IOS crash
<a href="#">CSCuu97977</a>	Pfrv2 load-balance not working with passive mode.
<a href="#">CSCuu18348</a>	IOS PKI HA fails to initialize on standby router after reload or upgrade
<a href="#">CSCuu81737</a>	Router crashes when using crypto
<a href="#">CSCut22660</a>	Session in attempting state on standby when method list is default
<a href="#">CSCur88124</a>	default throttling require other defaults in some cases
<a href="#">CSCut67877</a>	IOS crashes when changing tunnel destination on a Tunnel with QoS
<a href="#">CSCuu46604</a>	Router crashes when a failed primary link comes back up
<a href="#">CSCuq75576</a>	Input queue wedged on outside interface of standby nat-ha router
<a href="#">CSCuo93893</a>	RG-Infra: Add a hook for RG Domain for Reloading peer event:
<a href="#">CSCuu82607</a>	Evaluation of all for OpenSSL June 2015
<a href="#">CSCut46130</a>	MARCH 2015 OpenSSL Vulnerabilities
<a href="#">CSCus06143</a>	CSR1k SSLVPN: Mask unsupported virtual-template type VPN from config
<a href="#">CSCut65242</a>	ISG passing traffic while configured default drop should be used
<a href="#">CSCuu75354</a>	ISG: Dedicated session provisioning failure post lite session conversion
<a href="#">CSCut87425</a>	CPU hog in "EEM TCL Proc" after TCL script termination with long runtime
<a href="#">CSCuv51901</a>	ASR1K BGP send UPDATE don't observe the TCP OPTION
<a href="#">CSCul10482</a>	TFEX: Image auto download fails due to "ip tftp source-interface" config
<a href="#">CSCus46844</a>	802.1x 3650 Radius Response not picked up by AAA code

## Open Bugs—Cisco IOS Release 15.4(3)S3

Table 13 Open Bugs—Cisco IOS Release 15.4(3)S3

Identifier	Description
<a href="#">CSCut04815</a>	LDAP authentication is not working on 5760 or 3850
<a href="#">CSCuu36031</a>	Kernel crash is related to a GPF related to memory corruption.



Identifier	Description
<a href="#">CSCut12738</a>	[ASR1K HSRP] Physical Link Failure Causes HSRP to Fail
<a href="#">CSCur32628</a>	7600 mis-programming causing intermittent packet loss
<a href="#">CSCuu32159</a>	CUBE issue with webex HA
<a href="#">CSCuu00050</a>	CUBE with SRTP fallback is dropping SRTP RTP/SAVP from the 200 OK SDP
<a href="#">CSCur35618</a>	[XE 3.15] FP Crashed for SRTP Video Call + DSP
<a href="#">CSCuu29667</a>	ASR1K crash when snmp setting cipSecTunnelEntry
<a href="#">CSCut14502</a>	Address pool leak upon Anyconnect reconnect and subsequent disconnect
<a href="#">CSCut30167</a>	ISIS may crash when reaching LSPFULL condition with IPv6 routes
<a href="#">CSCue32350</a>	kron crash after deconfiguring the occurrence
<a href="#">CSCus62778</a>	Stale Data MDT entry
<a href="#">CSCur70478</a>	Software crash at ldpx_mem_reallocz_grow due to insufficient memory
<a href="#">CSCuq95663</a>	CENT: small increase in IPC still exists in longevity
<a href="#">CSCut67137</a>	Memory fragmentation on ASR903 due to OSPF
<a href="#">CSCuu24757</a>	ASR1k QFP leak with cpp_sp_svr at module FM CACE
<a href="#">CSCuo51601</a>	ISR4400 - Traffic incorrectly forwarded through class class-default
<a href="#">CSCus06143</a>	CSR1k SSLVPN: Mask unsupported virtual-template type VPN from config
<a href="#">CSCup04062</a>	IOS SSLVPN - Anyconnect Data traffic failure with TLS transport
<a href="#">CSCur10056</a>	Memory leak in SSS Manager
<a href="#">CSCus77343</a>	DSMP crash while doing OIR or module reload when active call exists
<a href="#">CSCut66144</a>	VXML GW fails to handoff call to VXML Application on second VRU leg

## Resolved Bugs—Cisco IOS Release 15.4(3)S3

Table 14 Resolved Bugs—Cisco IOS Release 15.4(3)S3

Identifier	Description
<a href="#">CSCut09164</a>	Memory leak in AAA/EAP code in 3.3.5
<a href="#">CSCut31678</a>	Memory leak in AAA/EAP code in 3.3.5
<a href="#">CSCur57035</a>	ASR 1k crash on __be_bfd_fib_nh_change_cb
<a href="#">CSCuq09320</a>	ASR-1002 crashed with LAN BFD and HSRP with ipv4 and ipv6
<a href="#">CSCus20997</a>	ASR1k: BGP Notification of Admin shutdown triggers Graceful-Restart
<a href="#">CSCur66140</a>	Import of Global routes to VRF will fail
<a href="#">CSCun68322</a>	Support BGP GR for VPN AF in platform without MPLS
<a href="#">CSCus26146</a>	VRF LISP routes not exported to global table with valid next hop
<a href="#">CSCus01544</a>	XE3.13 rejects routes from ebgp peer due to malformed ATTR-SET attribute
<a href="#">CSCus54365</a>	Memory leak in tlv_calloc
<a href="#">CSCur87549</a>	ipv6 traffic over bridge-domain not working

Identifier	Description
<a href="#">CSCur88455</a>	7600 IP FRR: MPLStoMPLS traffic Blackhole after VRF Configuration
<a href="#">CSCut31584</a>	c7600 drops Register-Stop messages resulting into punting ASM stream
<a href="#">CSCut27149</a>	POS FRR issue with traffic loss around 1 sec instead of 50ms
<a href="#">CSCus95226</a>	Compact Flash corruption due to call-home directory being created
<a href="#">CSCus38037</a>	crash with "show voice class ctl-file"
<a href="#">CSCut92745</a>	Crash while placing MLPP calls
<a href="#">CSCur70959</a>	Memory leak @ sipContentObjPvtSetBody
<a href="#">CSCus65095</a>	SSTE: QoS Pre-classify was broken
<a href="#">CSCus34949</a>	DHCP defect - crash due to an invalid access to a freed memory structure
<a href="#">CSCur55365</a>	50% ping failure with IPv6 dual stack and dialer configured
<a href="#">CSCus72257</a>	50% ping failure with IPv6 dual stack and dialer configured
<a href="#">CSCus57583</a>	ASR 1K BGP Process Crash Due to EIGRP Route Redistribution
<a href="#">CSCup52101</a>	EnergyWise Denial of Service vulnerability
<a href="#">CSCut01967</a>	crashed after executed show ethernet cfm errors
<a href="#">CSCus53146</a>	ASR crashes at hal_get_next_packet
<a href="#">CSCur43251</a>	POODLE protocol-side fix: HTTPS Client
<a href="#">CSCur49548</a>	Upgrade from 3.4.6S to 3.13.0S doesn't work with traceback and error log
<a href="#">CSCus86256</a>	uCode crash when MPLS packet received on LAN side of AppNav intercept
<a href="#">CSCut46126</a>	MARCH 2015 OpenSSL Vulnerabilities
<a href="#">CSCut30579</a>	Dynamic PBR policy inconsistent & never update after path failover
<a href="#">CSCus78750</a>	6RD: Knob to disable security check missing.
<a href="#">CSCur96943</a>	CCSIP_SPI_CONTROL leak in sippmh_parse_record_route
<a href="#">CSCus75907</a>	Router crashes when Fax T38 Protocol Configured
<a href="#">CSCur68999</a>	config change on Tunnel int using shared tunnel protection stops traffic
<a href="#">CSCuq15567</a>	Crash with %SYS-3-OVERRUN with crypto_ipsec_clear_peer_sas
<a href="#">CSCup97873</a>	IPSec datapath should not print debug messages without debugs enabled
<a href="#">CSCuq91734</a>	NHRP Packets are dropped after EzVPN decryption
<a href="#">CSCur29861</a>	Traceback seen on c2900 platform for ike_keepalives
<a href="#">CSCur65486</a>	GETVPN: Fail to delete GMs on sec-KS after 3 scheduled rekeys failure
<a href="#">CSCun57148</a>	High CPU in FNF Cache Ager P
<a href="#">CSCus74192</a>	Link down event does not flush the routes correctly with isis
<a href="#">CSCut24465</a>	Static VFI went down after PTF reset
<a href="#">CSCus89274</a>	Crash with nat/reflective acl and TCP session going through that box
<a href="#">CSCus69732</a>	IOS-XE: Evaluation of glibc GHOST vulnerability - CVE-2015-0235
<a href="#">CSCut57290</a>	Egress LER TTL propagation misbehaviour in per-ce label allocation mode
<a href="#">CSCuo67247</a>	High CPU due to NHRP process on ASR in DMVPN ph3 after upgrading IOS-XE
<a href="#">CSCur28336</a>	Memory leak and possible crash when using a logging discriminator

Identifier	Description
<a href="#">CSCus05038</a>	"revocation-check ocp none" does not timeout fast for unreachable server
<a href="#">CSCus77875</a>	List Headers leak verified cert chain Held CCSIP_TLS_SOCKET & Chunk Mgr
<a href="#">CSCus73553</a>	Memory corruption crash in PKI certificate processing
<a href="#">CSCus54238</a>	PKI "revocation check crl none" does not fallback if CRL not available
<a href="#">CSCut17865</a>	ASR1K:13RU IOSd crash @PnP Agent Discovery after router reload
<a href="#">CSCus46259</a>	ASR1k (ISG Radius-Proxy): Memory Leak after excessive client roaming
<a href="#">CSCut26988</a>	Broken bw repartition - traffic is send as w/o configured bw under MQC
<a href="#">CSCut46705</a>	Wrong bandwidth distribution in SIP 200 & 400 causes queue limit of 2
<a href="#">CSCur20444</a>	I/O memory leak due to DHCPv6 packets.
<a href="#">CSCun29420</a>	Crash observed with active IP SLA probes
<a href="#">CSCuq39109</a>	Memory Fragmentation due to IP SLA
<a href="#">CSCus40410</a>	ATM SPA: Incorrect SOM-COM-EOM flag set in packet buffer hdr in Ingress
<a href="#">CSCus88868</a>	IOS openssl leak observed with SSL Anyconnect VPN
<a href="#">CSCuq25323</a>	DLSW peers fail to connect when other DLSw peer sends FIN instead of RST
<a href="#">CSCue88982</a>	MA2b:Supervisor crash seen upon Remote login and the session is idle
<a href="#">CSCut08626</a>	DSMP crash at DSP packet buffer allocation
<a href="#">CSCuu29539</a>	voice statistics CLIs are missing in ISR4k image
<a href="#">CSCut18365</a>	Tracebacks found @ moh_multicast_recv_input
<a href="#">CSCus89791</a>	g722-64 codec crash during dial tone with country code

## Resolved Bugs—Cisco IOS Release 15.4(3)S2

Table 15 Resolved Bugs—Cisco IOS Release 15.4(3)S2

Identifier	Description
<a href="#">CSCur51387</a>	NG3K stack: standby gets reloaded due to reason "configuration mismatch"
<a href="#">CSCur13587</a>	ANCP session terminated due to message len check
<a href="#">CSCuq83441</a>	BGP L2VPN uses default static next-hop instead of outgoing intf-addr
<a href="#">CSCuq99797</a>	BGP Route-Target not advertised when rfilter address family in use
<a href="#">CSCur66140</a>	Import of Global routes to VRF will fail
<a href="#">CSCup48874</a>	IPv6 neighbor link-local address not learnt after RSP Failover
<a href="#">CSCun68322</a>	Support BGP GR for VPN AF in platform without MPLS
<a href="#">CSCus01544</a>	XE3.13 rejects routes from ebgp peer due to malformed ATTR-SET attribute
<a href="#">CSCue87829</a>	Bridge Domain EVC EFPs not mapped to VLAN post Reload/SSO
<a href="#">CSCun80617</a>	Active SP crashes @ mfib_pltf_entry_extract_source followed by RP crash
<a href="#">CSCur94457</a>	AToM traffic is blackholed after RP switchover
<a href="#">CSCur41785</a>	IXP_MAP-3-QOS_CONFIG: ACL is not programmed after reload or RP SSO
<a href="#">CSCur96372</a>	l2protocol forward feature is missing under SIP400

Identifier	Description
<a href="#">CSCum59931</a>	7200 crash with DHCP suspending WCCP
<a href="#">CSCur10249</a>	ASR1006 crash when IPv6 PPPoE sessions increase to several hundred
<a href="#">CSCup99634</a>	IPv6 dhcp database not working on PI25 and Xe3.13
<a href="#">CSCuq78983</a>	RIPv2 key-chain CLI disappears when doing config replace
<a href="#">CSCur11538</a>	ASR1k lldpMIB walk (1.0.8802.1.1.2.1.3.7.1) , but lldpMIB unsupported
<a href="#">CSCur45606</a>	logging discriminator doesn't work
<a href="#">CSCup99438</a>	MK2:tun_decap_tinfo_control subsys missing in DFC
<a href="#">CSCur78068</a>	Quad+fex mk2 (fc):after issu LV - IPC trace back, sw2(ICS) is crashed
<a href="#">CSCuq17828</a>	ASR: Radius Accounting fails when using EDCSA certs
<a href="#">CSCur23619</a>	IKEv2 reconnect radius accounting stop should mention terminate cause
<a href="#">CSCur85771</a>	ISDN Segmentation Fault on ISR 4451
<a href="#">CSCuq51439</a>	ASR903: ISIS LSP generation delayed after receiving BFD down event
<a href="#">CSCur97045</a>	IS-IS Passive-interface default unavailable
<a href="#">CSCum90471</a>	ASR1k: Ping failure b/w CE1 & CE3 after Switchover.
<a href="#">CSCur78744</a>	LISP mobility with HSRP invalid host detection events
<a href="#">CSCuq85667</a>	Crash@mcast_rw_link_dequeue on config replace in MCAST THS
<a href="#">CSCur36464</a>	mVPN: Inter-AS Option B: Different RDs: proxy vector: local RD is picked
<a href="#">CSCur09682</a>	Router crashes in PIM due to infinite recursion at ip_set_mdb_flag
<a href="#">CSCuo81912</a>	SSTE: Unable to remove performance-monitor once the interface is deleted
<a href="#">CSCup67317</a>	max_chunk_size validation incorrect in function chunk_create_inline()
<a href="#">CSCup59760</a>	'sh mpls fwding tabel vrf slot<>' takes longer time & stucks terminal
<a href="#">CSCur92862</a>	TE leaks memory when restarting isis
<a href="#">CSCur07571</a>	Processor memory leak with MRCP_Client at cc_api_get_call_active_entry
<a href="#">CSCur62553</a>	Netconf - Duplicate xml version start tags in hello packet
<a href="#">CSCuq70163</a>	RESTAPI: POST /api/v1/acl/{acl-id}/interfaces does not show in config
<a href="#">CSCus38393</a>	ASR1k:IOSD crash @process_run_degraded_or_crash
<a href="#">CSCur10058</a>	IOS PKI : CRL parsing may fail if HTTP Content-Length is not specified
<a href="#">CSCuq74176</a>	PKI IOS removed valid CA certificate before expiry date
<a href="#">CSCur14783</a>	PnP: ZTD in ISR's blocked due to config wizard
<a href="#">CSCun87941</a>	PPP link interfaces causes SUP to crash
<a href="#">CSCus01735</a>	cbQosTSCfgRate64 is not supported on ASR1k/IOSXE
<a href="#">CSCui23670</a>	Even if show sup-bootdisk is executed, nothing is displayed.
<a href="#">CSCuc68034</a>	IO Memory Leak on FlexWan WS-X6582-2PA exec 'sh cef interface internal'
<a href="#">CSCuo92155</a>	RSVP sync process crash observed with TE NSR configs
<a href="#">CSCup80756</a>	SNMP Engine Crashes in IOS-XE, Segfault When Processing rttMonStats MIB
<a href="#">CSCum87411</a>	software install from tftp get failed fts_client issue
<a href="#">CSCur78381</a>	After a reboot of SPA-4XCT3/DS0, first 4 packet loss in channelized mode

Identifier	Description
<a href="#">CSCuq74492</a>	IOS/IOSd Multiple Vulnerabilities in OpenSSL - August 2014
<a href="#">CSCur44075</a>	AC ICE+ ver <= 4.0 Client unable to connect to XE SSL Headend {CSR1K}
<a href="#">CSCun89616</a>	IOS Does Not Properly Respond to TLS 1.2 Client Hellos
<a href="#">CSCup86552</a>	Issue with qos service installation
<a href="#">CSCuq54260</a>	Session is not syncing to the standby with collect identifier remote-id
<a href="#">CSCuh92882</a>	XE3.11 Seginfo->l2hw_cond_debug is set to "1" when there is no condition
<a href="#">CSCur68259</a>	XE3.13 : Subscribers not pingable after 2nd "clear ip route vrf x *"
<a href="#">CSCur29261</a>	Memory corruption in retrans TCP sanity check causes ISR crash
<a href="#">CSCup41482</a>	TCP snd window stuck with CEF enabled

## Resolved Bugs—Cisco IOS Release 15.4(3)S1

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#) through the [fixed bug search](#).

This search uses the following search criteria and filters:

Field Name	Information
Product	Series/Model Cisco IOS and NX-OS Software => Cisco IOS
Release	15.4(3)S1
Status	Fixed
Severity	2 or higher

## Open Bugs—Cisco IOS Release 15.4(3)S

This section describes possibly unexpected behavior by Cisco IOS Release 15.4(3)S. All the bugs listed in this section are open in Cisco IOS Release 15.4(3)S. This section describes only severity 1, severity 2, and select severity 3 bugs.

- [CSCuo73442](#)  
Symptom: A Cisco switch may crash after issuing the **no ip dhcp pool** command.  
Conditions: This symptom occurs when DHCP is configured.  
Workaround: There is no workaround.
- [CSCup10266](#)  
Symptom: IPv6 default route does not get redistributed into EIGRP without metrics.  
Conditions: This symptom occurs when redistribute static is issued without mentioning metrics.  
Workaround: Mention metrics when issuing the **redistribute static** command under EIGRP.
- [CSCup11348](#)  
Symptom: Incremental memory leaks are observed.  
Conditions: This symptom occurs under the following conditions:

- TFTP server should not be reachable which is mentioned in the DHCP database.
- Remove and add the DHCP pool.

Workaround: There is no workaround.

- CSCup13169

Symptom: The Default static route tag value does not get updated on OSPF.

Conditions: This symptom occurs under the following conditions:

1. Add static default route with tag value.
2. Configure OSPF with redistribute static and default-information originate.

The tag value does not get updated.

Workaround: Create a separate route map for updating the tag value. Route map should be tagged with the **default-information originate** command under OSPF.

- CSCup26658

Symptom: An unexpected process restart occurs after running the following commands in quick succession:

```
no spanning tree mode
default interface <intf>
```

Conditions: This symptom occurs when service instances are configured on the interface with encapsulation and bridge-domain configuration under the interface. Spanning tree must also be configured before running the commands.

Workaround: Leave a 10 second gap between entering the above mentioned commands.

- CSCup48742

Symptom: A Cisco router gets crashed.

Conditions: This symptom occurs under the following conditions:

1. Configure the below CLI and make sure that the SCP server IP is unreachable:

```
ip dhcp database scp://tom:cisco@192.168.50.25/dhcp4 write-delay 60 timeout 5
```

2. Wait for 60 seconds or the following message:

```
%DHCPD-3-WRITE_ERROR: DHCP could not write bindings to
scp://tom:cisco@192.168.50.25/dhcp4
```

3. Make SSH connect from this device to the other device and exit from that connection so as to be back to the original device (optional).
4. Press “Enter”.
5. The following message appears:

```
[Resuming connection 1 to UNKNOWN ... ]
[Connection to UNKNOWN aborted: error status 0]
```

6. The router would hang or crash. If not, run any show command (show ip int br).
7. If all the above conditions are met, wait for the router to crash. Cisco ISR routers take around 5-10 minutes to crash and Cisco ASR routers crash immediately most of the times.

Workaround: Use FTP or TFTP with “ip dhcp database”. Do not use SCP with “ip dhcp database”.

- CSCup54679

Symptom: TE FRR paths are lost after an SSO.

Conditions: This symptom occurs under the following conditions:

1. TE tunnels are configured between PE1 and PE2.
2. TE NSR is configured on PE1 and FRR node protection is configured on PE1.

Before SSO, the FRR database shows the FRR paths and after SSO the FRR paths are lost.

Workaround: There is no workaround.

## Resolved Bugs—Cisco IOS Release 15.4(3)S

- CSCee32792

Symptom: A Cisco router reloads at `snmp_free_variable_element` while using SNMPv3 commands.

Conditions: This symptom occurs while using SNMPv3 commands.

Workaround: There is no workaround.

- CSCte77398

Symptom: A Cisco ATM router configured with ATM PVC Range commands report the following error when attempting to configure a PVC Range:

Unable to configure PVC Range. Possibly multiple users configuring IOS simultaneously.

Conditions: This problem occurs randomly and even if there are no multiple sessions accessing the `pvc-range` at the same time.

Workaround: There is no workaround.

- CSCtq21722

Symptom: A Cisco switch may reload when configured for SNMP.

Conditions: This symptom is observed when SNMP inform hosts are configured.

Workaround: Remove the SNMP host configurations for SNMP informs.

Example: `no snmp-server host x.x.x.x informs version 2c <removed>`

- CSCtx82890

Symptom: After removing the encapsulation on MFR member interface, tracebacks are observed.

Conditions: This symptom is observed when serial interface is configured with FR MLP configuration.

Workaround: There is no workaround.

- CSCty92208

Symptom: Customer faced crash on 6509 after configuring WCCP.

Conditions: Customer configured WCCP with hash assignment and enabled port hashing and it will happen during redirection if packet are software switched.

Workaround: The possible workarounds are:

1. Disable port-hashing if we are using hash-assignment.
2. Use mask-assignment method.

- CSCtz45833

Symptom: A Cisco router crashes with the following message:

Router crash: UNIX-EXT-SIGNAL: Segmentation fault(11), Process = MPLS TE LM

Conditions: This symptom occurs when a router acts as the mid point for MPLS-TE tunnels and performs an ERO expansion. In case the ERO expansion fails (due to IGP race conditions or inter-AS scenario) and backup tunnels are in use (for MPLS-TE FRR feature), the router may crash.

Workaround: Configure the head-ends to perform a full ERO computation to avoid mid points performing any ERO expansion. This can be done using the dynamic path option or by using the explicit path that specifies strict hops for each node along the desired LSP path (using "loose" hops or partial strict hops can lead to this issue).

- CSCuc60868

Symptom: A router randomly crashes either due to memory corruption at `bgp_timer_wheel` or memory chunks near `bgp_timer_wheel` (For example, BFD event chunks if BFD is configured or AtoM Manager chunks if LDP is configured). A crash occurs right after an LDP neighbor is up in the L2VPN setup.

Conditions: This symptom occurs when **vpls bgp signaling** is unconfigured and then reconfigured. Both L2VPN and BGP are unconfigured and reconfigured after all L2VPN and BGP data structures are fully deleted (about 3 minutes for 5 BGP VPLS prefixes). For the repro on file, OSPF (for IGP) is also unconfigured and reconfigured. Both LDP and BGP signalling are affected by this bug.

Workaround: Avoid unconfiguring and reconfiguring BGP L2VPN.

- CSCue00996

Symptom: The Cisco IOS Software implementation of the Network Address Translation (NAT) feature contains two vulnerabilities when translating IP packets that could allow an unauthenticated, remote attacker to cause a denial of service (DoS) condition.

Cisco has released free software updates that address these vulnerabilities.

There are no workarounds to mitigate these vulnerabilities.

This advisory is available at the following link:

<http://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20140326-nat>

Note: The March 26, 2014, Cisco IOS Software Security Advisory bundled publication includes six Cisco Security Advisories. All advisories address vulnerabilities in Cisco IOS Software. Each Cisco IOS Software Security Advisory lists the Cisco IOS Software releases that correct the vulnerability or vulnerabilities detailed in the advisory as well as the Cisco IOS Software releases that correct all Cisco IOS Software vulnerabilities in the March 2014 bundled publication.

Individual publication links are in Cisco Event Response: Semiannual Cisco IOS Software Security Advisory Bundled Publication at the following link:

[http://www.cisco.com/web/about/security/intelligence/Cisco\\_ERP\\_mar14.html](http://www.cisco.com/web/about/security/intelligence/Cisco_ERP_mar14.html)

Conditions: See the published Cisco Security Advisory.

Workaround: See the published Cisco Security Advisory.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 7.1/5.9:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2014-2111 has been assigned to document this issue.

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)



- CSCue84703

Symptom: When a switchover is triggered before the converge of a unicast (and multicast), the MFIB is not in “running state”, and is held in the initializing state forever.

Conditions: This symptom occurs when a switchover is triggered before the converge of the unicast.

Workaround: Switchover after the converge of the unicast.

- CSCuf51357

Symptom: A vulnerability in the Secure Sockets Layer (SSL) VPN subsystem of Cisco IOS Software could allow an unauthenticated, remote attacker to cause a denial of service (DoS) condition.

The vulnerability is due to a failure to process certain types of HTTP requests. To exploit the vulnerability, an attacker could submit crafted requests designed to consume memory to an affected device. An exploit could allow the attacker to consume and fragment memory on the affected device. This may cause reduced performance, a failure of certain processes, or a restart of the affected device.

Cisco has released free software updates that address these vulnerabilities.

There are no workarounds to mitigate this vulnerability.

This advisory is available at the following link:

<http://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20140326-ios-sslvpn>

Note: The March 26, 2014, Cisco IOS Software Security Advisory bundled publication includes six Cisco Security Advisories. All advisories address vulnerabilities in Cisco IOS Software. Each Cisco IOS Software Security Advisory lists the Cisco IOS Software releases that correct the vulnerability or vulnerabilities detailed in the advisory as well as the Cisco IOS Software releases that correct all Cisco IOS Software vulnerabilities in the March 2014 bundled publication.

Individual publication links are in Cisco Event Response: Semiannual Cisco IOS Software Security Advisory Bundled Publication at the following link:

[http://www.cisco.com/web/about/security/intelligence/Cisco\\_ERP\\_mar14.html](http://www.cisco.com/web/about/security/intelligence/Cisco_ERP_mar14.html)

Conditions: See published Cisco Security Advisory.

Workaround: See published Cisco Security Advisory.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 7.8/6.4:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:L/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2014-2112 has been assigned to document this issue.

Additional information on Cisco’s security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCug17485

Symptom: A buffer leak is observed on a Cisco router.

Conditions: This symptom occurs while using SSLVPN.

Workaround: There is no workaround.

- CSCug45421

Symptom: The standby RP crashes.

Conditions: Memory corruption occurs in certain cases when the following commands are executed in quick succession. It leads to a crash later when the memory is accessed. The issue is seen only with on-demand PVCs and when the commands are copied and pasted or executed using a script or tool.

```
configure terminal
interface ATM0/0/0.2 multipoint
range pvc 11/41 11/51
create on-demand
/* Prob commands begin */
pvc-in-range 11/45
exit
no pvc-in-range 11/45
/* Prob commands end */
end
```

Workaround: Do not execute the commands in quick succession.

- CSCuh05259

Symptom: Prompt is provided for configure replace command when **file prompt quiet** is configured.

Conditions: This symptom is observed when “file prompt quiet” has been configured.

Workaround: Use “force” along with the **configure replace** command.

- CSCuh09324

Symptom: UDP based entries are not deleted from the flowmgr table resulting in crash, or poor system response, with CPU hog messages being shown.

Conditions: Affected Platforms - images

- ct5760-ipservicesk9.bin
- cat3k\_caa-universalk9.bin
- cat4500e-universalk9.bin

Device is configured with UDP services that originate from the device. This includes but not limited to the following features:

- TFTP
- Energy Wise
- DNS
- Cisco TrustSec

Workaround: If you suspect that you are affected by this bug, please do the following, for confirmation:

```
Router#config terminal
service internal
end
Router#show flowmgr
```

The output of this command will show many lines entries holding with the same port numbers. Disabling the feature that is being held in the flows until an upgrade can be performed, is a workaround.

A reload is required to clear the held flows.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5.4/4.5:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:H/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2013-6704 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-6704>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCuh49066

Symptom: VSS standby crashes due to LBL sync on issuing the below parser command:

```
parser view li-view
```

Conditions: This symptom occurs in a VSS with parser view configuration.

Workaround: Remove the “parser view” configuration.

- CSCui05000

Symptom: A Cisco router may crash upon importing a prefix into VRF after applying **no ipv4 multicast mult topology** under “vrf definition” for that VRF.

Conditions: This symptom occurs while initially configuring the VRF. **address-family ipv4/6 multicast vrf** must be configured under “router bgp” mode before import route-targets are configured under “vrf definition” mode.

Workaround: There is no workaround.

More Info: If the crash does not occur, it is likely that importing of the prefix will not work.

- CSCui17084

Symptom: Delay between VPN convergence and BGP-based MDT tunnel creation after router reload may cause multicast traffic loss.

Conditions: In a BGP MVPN setup utilizing MDT SAFI, problem is seen upon BGP exiting read-only mode. VPN prefixes will be advertised immediately, whereas MDT prefixes are advertised after a BGP scanner run.

Workaround: There is no workaround.

- CSCui63461

Symptom: The Cisco router crashes when using CCP 2.6 and 2.7 to provision the device.

Conditions: This symptom is observed under normal condition.

Workaround: There is no workaround.

- CSCui64807

Symptom: An active RP crashes during FIB sync because of memory overrun when the standby sup becomes unavailable.

Conditions: This symptom occurs when redundant RPs are configured in SSO mode and the standby RP becomes unavailable (for instance because of crash or physical removal). The issue occurs only on Cisco 7600 RSP 720, Cisco 7600 Series Supervisor Engine 720, and Cisco 7600 platforms where the tableid “ISSU FOF LC” support is enabled. As of 03/17/2014, the tableid “ISSI FOF LC” feature is only supported on SY releases. This issue does not impact Cisco ASR 1000 Series platforms.

Workaround: There is no workaround.

- CSCui79766
 

Symptom: Upgrading hardware platform from Cisco 2811 Integrated Services Router to Cisco 2911 Integrated Services Router introduces periodic, intermittent delay in the delivery of STUN packets to OEM (Motorola) equipment.

Conditions: This symptom occurs while upgrading hardware platform from Cisco 2811 Integrated Services Router to Cisco 2911 Integrated Services Router.

Workaround: There is no workaround.
- CSCui83823
 

Symptom: When CU executes “show tech” or any show commands which gives a long output using putty, the SSH2 putty closes prematurely.

Conditions: This symptom is observed when “term length 0” is enabled. The putty session closes prematurely while executing “show tech show memory”.

Workaround: Redirect the output to a file.
- CSCuj14595
 

Symptom: A Cisco 3945 voice gateway running Cisco IOS Release 15.2(4)M3 or Cisco IOS Release 15.2(4)M4 may have a processor pool memory leak in the CCSIP\_TCP\_SOCKET process.

Conditions: This symptom is seen on slow TCP connections, where the response is slow and frequent transmission errors are observed.

Workaround: There is no workaround.
- CSCuj17827
 

Symptom: CCD unable to unublish hosted DN patterns on forwarders running service-routing code. This can result in stale or duplicate routes in remote cluster’s Learned Pattern table.

Conditions: This symptom is observed during disabling the advertising service, resetting the CCD sip trunk, rebooting a cluster, or a cluster losing connection to all SAF forwarders may trigger this defect.

Workaround: No workaround for preventing duplicate or stale routes, these routes can be purged from a remote cluster by resetting that cluster’s requesting service or configuring a temporary Blocked Learn Pattern that matches the affected patterns.
- CSCuj23293
 

Symptom: A memory leak is seen in the MALLOCLITE process:

```
show processes memory ----- Processor Pool Total: 282793968 Used:
280754252 Free: 2039716 I/O Pool Total: 41943040 Used: 18560544 Free: 23382496
PID TTY Allocated Freed Holding Getbufs Retbufs Process 0 0 268189264 170950536
88785564 1354 634324 *Init* 0 0 0 141933756 0 0 *MallocLite* 409 0 451333208
202702788 40928844 83639 83639 CCSIP_UDP_SOCKET 299003084 Total The memory continues
to increase there.
```

Conditions: This symptom is observed while parsing to header, Gateway gets errors as below:

```
Feb 26 12:07:28 EST: Parse Error: url_parseSipUrl: Received Bad Port Feb 26 12:07:28
EST: //2765/000000000000/SIP/Error/sippmh_cmp_tags: Parse Error in request header
```

The correct response for the above should have been to send 400 Bad Request The request cannot be fulfilled due to bad syntax

The memory associated with the above is not getting released is the side effect of the above.

Workaround: There is no workaround.

Further Problem Description: This issue was not seen on versions earlier than 15.3X

- CSCuj31290

Packet of Disconnect (POD) functionality does not work after upgrading router from Cisco IOS Release 15.1 to 15.2 code. POD fails with following error:

```
*Sep 10 16:51:48.063: RADIUS: Dynamic-Author-Error[101] 6 Missing Attribute [402]
Symptom: Packet of Disconnect (POD) functionality does not work after upgrading router
from Cisco IOS Release 15.1 to 15.2 code.
POD fails with following error:
*Sep 10 16:51:48.063: RADIUS: Dynamic-Author-Error[101] 6 Missing Attribute [402]
```

Conditions: This symptom is observed under the following conditions:

1. When PoD with just username is sent
2. IOS device is configured for packet of disconnect
3. IOS device is running Cisco IOS Release 15.2 Mainline code

Workaround: Downgrade router back to Cisco IOS Release 15.1 release of code.

- CSCuj40804

Symptom:

1. IPDT gets enabled on all bundle ports including RSL port due to which FEX does not come up after a reload, link flap, or SSO. FEX RSL channel members will be in ?u? state, that is unsuitable for a part of the etherchannel.
2. IPDT also gets enabled on the Service module (FWSM) internal port-channel and there is no way to recover them other than removing NMSP (as internal port-channels are non-configurable and non-accessible).

Conditions: This symptom occurs after a reload with “NMSP” protocol.

Workaround: Apply “attachment-suppress” on the port first and bundle the port later. There is no workaround in the case of FWSM internal port-channel.

- CSCuj44818

Symptom: A warning message is displayed.

Conditions: This issue occurs while unconfiguring video monitoring.

Workaround: There is no workaround.

- CSCuj55540

Symptom: Exception is seen on 3945E with whitelisted scansafe traffic.

Conditions: This symptom is observed when there is a lot of whitelisted traffic going through the ISR box.

Workaround: Disable whitelisting.

- CSCuj66067

Symptom: Router running out of memory after an upgrade to Cisco IOS Releases 15.3(1)S, 15.3(3)S, and 15.4(1)S.

Conditions: This symptom is observed when huge number of route server (approximately more than 700) contexts configures in the router.

Workaround: Perform the following workaround:

1. Reduce the number of Route server contexts.
2. Downgrade the IOS version to 15.2(4)S or lower release.

- CSCuj68289  
Symptom: Static SGACL permissions are not updated for authentication server assigned SGT.  
Conditions: This symptom is seen with an authentication server assigned SGT.  
Workaround: Use manual SGT or dynamic SGACL.
- CSCuj89036  
Symptom: IOSd crashes following an OIR of an eToken.  
Conditions: This symptom occurs during OIR activity on either USB port of a single eToken.  
Workaround: Do not OIR an eToken.  
  
More Info: When an eToken is inserted, files on the eToken need to be recursively scanned to build up the master file directory structure. This recursive scanning and building the database can take a very long time depending on the eToken contents. When dual IOSd redundancy mode is enabled, this process appears to take almost twice as long and can easily go over 10 seconds to trip off the IOSd watchdog timeout. Fix is to allow other processes to take over CPU so watchdog timeout will not happen.
- CSCuj89374  
Symptom: CFT was reporting two flows for incoming packets on a dialer interface.  
Conditions: PPPoE on underlying physical interface with ip nat outside configured on the dialer interface.  
Workaround: There is no workaround.
- CSCuj96546  
Symptom: After SSO, egress WCCP stops working in hardware, as netflow does not get installed.  
Conditions: When GRE redirection and hash assignment used for egress redirection and if the tunnel created takes the source address as the WCCP egress interface's IP address.  
Workaround: Create loopback interface and assign highest IP address to it, so that the tunnel created takes this IP address as tunnel source address.
- CSCul10573  
Symptom: On receiving a BGP update from a neighbor, the router will send an illegal network notification and flap the session.  
Conditions: This symptom occurs when the prefix received is a Leaf A-D route (RFC 6514) with an S-PMSI route serving as the Route Key.  
Workaround: There is no workaround.
- CSCul18552  
Symptom: After a switchover, QoS policy map in standby is not synced as in the case of active.  
Conditions: This symptom occurs after a switchover.  
Workaround: There is no workaround.
- CSCul24025  
Symptom: A Cisco ASR 1000 Series router crashes at \_\_be\_slaComponentProcessEvent when **ip sla udp-jitter** is unconfigured.  
Conditions: This symptom occurs when 1000+ IP SLA udp-jitter is configured and then all unconfigured immediately.  
Workaround: There is no workaround.

- CSCul27924

Symptom: Customer experienced crash on ASR-1001 during normal operation.

Conditions: This symptom is not observed under any specific condition.

Workaround: There is no workaround.

- CSCul39964

Symptom: Sessions do not get cleared. They get stuck in WT\_ST state.

Conditions: This symptom occurs when sessions are closed in bulk mode by shutting any trunk link or during a clear all session from DUT.

Workaround: There is no workaround.

More Info: The memory leak issue and WT\_ST are related. Along with memory leak, sessions are not cleared on active RP They get stuck in WT\_ST state.

```

asrlk-1#sh clock
07:18:07.045 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:20:08.295 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:46:34.113 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#s
6557 sessions in FORWARDED (FWDED) State
7908 sessions in WAITING_FOR_STATS (WT_ST) State
14465 sessions totalUniq ID PPPoE RemMAC Port VT

```

```

VA State
SID LocMAC VA-st Type
5978 5978 0000.6ca3.0116 Gi0/0/0.2940148 1 Vi2.3091 WT_ST
b414.8901.8e00 VLAN: 294/148 UP
5979 5979 0000.6ca3.0117 Gi0/0/0.2940149 1 Vi2.3092 WT_ST
b414.8901.8e00 VLAN: 294/149 UP
6460 6514 0000.6ca3.0134 Gi0/0/0.2940178 1 Vi2.3354 WT_ST
b414.8901.8e00 VLAN: 294/178 UP
6454 6508 0000.6ca3.0135 Gi0/0/0.2940179 1 Vi2.3350 WT_ST
b414.8901.8e00 VLAN: 294/179 UP
6453 6507 0000.6ca3.0136 Gi0/0/0.2940180 1 Vi2.3349 WT_ST
b414.8901.8e00 VLAN: 294/180 UP
6518 6572 0000.6ca3.0137 Gi0/0/0.2940181 1 Vi2.3395 WT_ST
b414.8901.8e00 VLAN: 294/181 UP
6514 6568 0000.6ca3.0138 Gi0/0/0.2940182 1 Vi2.3393 WT_ST
b414.8901.8e00 VLAN: 294/182 UP
6516 6570 0000.6ca3.0139 Gi0/0/0.2940183 1 Vi2.3394 WT_ST
b414.8901.8e00 VLAN: 294/183 UP
6560 6614 0000.6ca3.013a Gi0/0/0.2940184 1 Vi2.3413 WT_ST

```

- CSCul40478

**Symptom:** A crash was seen in the periodic accounting process due to the stale reference of the attribute list with AAA accounting DB (this specific attribute list is used by the periodic accounting process for sending the interim accounting records).

**Conditions:** This symptom occurs with Policy Component allocate AAA attribute list handle. This handle reference is shared among multiple components for processing. A component can free the attribute list using this handle. AAA does not validate the handle before usage. The policy will not share the same attribute handle reference with other components. The policy will share a copy of the attribute list to other components so that the component does not refer the same handle.

**Workaround:** There is no workaround.

- CSCul43968

**Symptom:** Mroute states never expire on egress PE without any active downstream receivers.

**Conditions:** This symptom occurs in an IPv6 multicast running in a VRF scenario and during unconfiguration of such a loopback interface that has MLD joins on it.

**Workaround:** There is no workaround.

- CSCul46792

**Symptom:** VCs remain down on ISSU from previous Cisco XE3.12 to Cisco XE3.12 Release.

**Conditions:** This symptom is observed under the following conditions:

1. VPLS BGP Signalling is configured
2. VC's are established in the Active RP

**Workaround:** There is no workaround.

- CSCul49375

**Symptom:** The Cisco ASR 1000 router displays the following messages in the logs:  
 %IDMGR-3-INVALID\_ID: bad id in id\_get (Out of IDs!) (id: 0x0) -Traceback=  
 1#cb40dca901558e45a65b881a8695af4f :400000+8653B3 :400000+893696 :400000+DF330C  
 :400000+DED89B :400000+DF8643 :400000+1F57F36 :400000+1F4BBFB :400000+1F33BA7  
 :400000+1F336C1 :400000+1F34FF9 :400000+1F27763 :400000+1F29B16 :400000+2546FF3  
 :400000+2546EDD :400000+1F2930B

No new PPPoE sessions can be established anymore.



Conditions: The conditions to this symptom are unknown.

Workaround: Reload the device.

- CSCul49852

Symptom: A router might see PPPoE-sessions in the WAITING\_FOR\_STATS (or WT\_ST) status.

Conditions: This symptom was observed by specific users or because of using a specific profile or service like ShellMaps and Radius. The system is configured as BRAS aggregating PPPoEoA or -oE-sessions.

Workaround: There is no workaround.

- CSCul54254

Symptom: Invalid LSAs are not flushed by the router which has their Advertising Router ID. Specifically, Router LSAs which do not have LSID of 0 will not be flushed if the router does not re-originate them, and any LSA with a type that the router does not recognize.

Lingering LSAs could lead to incorrect routing in some very obscure instances. For example, stale Router LSA fragments from two neighboring routers would need to remain in the network. There would not be a routing problem if only one router's stale Router LSA fragment was allowed to linger.

Conditions: There are several possible scenarios that could lead to this symptom. One example is that a router is configured with many interfaces attached to an OSPFv3 instance such that it originates more than one Router LSA fragment. Then the router is reloaded before the configuration is saved, and after the reload it does not reoriginate some of the Router LSA fragments.

Workaround: There is no workaround.

- CSCul55900

Symptom: A FlexVPN Scale rate degradation occurs due to more CPU consumed by static processes.

Conditions: This symptom occurs under the following conditions:

1. Configure UUT to be the flexvpn server which can scale upto 10K sessions.
2. Configure IKEv2 Authorization policy.
3. Try to bring up the flexvpn 10K sessions and monitor the CPU usage.

Workaround: Remove IKEv2 authorization policy. In such a case, IKEv2 routing and mode configuration cannot be verified.

- CSCul72121

Symptom: Continuous trace backs on the PTF console is observed and PTF crashes during a soak.

Conditions: This symptom occurs under the following conditions:

1. Create an MDS profile as attached.
2. Leave the setup for soak for 12 hours.

Workaround: Reload ACT and SBY PTF.

- CSCul75876

Symptom: A router may crash in an OSPF process during reconfiguration.

Conditions: This symptom occurs under the following conditions:

1. Configure the router with "ipfr" in area 0.
2. Connect router to area 0 through two links. For some route one interface is the primary path, and the second is the repair path.

3. Configure router as ABR, that is, have a non-zero area with a neighbor. Do not configure “ipfrr” in the non-zero area. Quickly remove the IP address from both the interfaces in area 0 and router the may crash.

Workaround: Changes to the reconfiguration procedure will avoid the crash.

- Shutdown the interface before removing the IP
- Remove the IP from one interface in area 0, wait for a few seconds and remove the IP address from the second interface in area 0.

- CSCul86211

Symptom: When LNS switches off while the sessions keep on establishing at LAC, LAC finds the l2tp db memory exhausted after sometime. Due to this, it fails to update the session in the database and during this period a crash is observed.

Conditions: This symptom occurs when LAC tries to add l2tp session in the database and fails to do so. In order to handle this error condition, LAC frees the l2tp and l2x session twice. This double free is the reason for crash.

Workaround: There is no workaround.

- CSCul87037

Symptom: An “sg subrte conte” chunk leak occurs while roaming.

Conditions: This symptom occurs after an account-logout and if service permit is configured in control policy. In case of a service permit, the subscriber remains unauth and is redirected to the portal once again. Post successful second account logon and the subscriber session is cleared by timeout or cli, the leak is seen and the same client will not be able to create the session once again. The leak is seen after simulating for the second time account-logon. And if service permit is configured.

In case of service disconnect configured under account-logout, account-logon is not a practical scenario as the portal is not reachable for the client.

Workaround: Use **service disconnect** for **event account-logout**.

```
class type control always event account-logout 1 service disconnect delay 10 !
```

- CSCul88004

Symptom: DPSS packet injects fails to work.

Conditions: This has been observed to occur when the onePK application name contains space characters, for example, white space and tab.

Workaround: Rename the application with no white-spaces.

- CSCul90553

Symptom: Cisco IOS-XE RP2-based platforms are unable to reach 4000 IPsec tunnels with DMVPN EIGRP.

Conditions: This symptom occurs when DMVPN with EIGRP is used on Cisco IOS-XE RP2 platforms.

Workaround: Use previous Cisco IOS XE images (such as Cisco IOS XE Release 3.11).

- CSCul90667

Symptom: Error messages and tracebacks are printed to the console.

Conditions: This symptom occurs when IGP times out while Standby RP becomes NSR Active.

Workaround: Enable NSR under IGP to ensure no timeout occurs.

- CSCu192497
 

Symptom: The Cisco 7600 router providing layer2 EoMPLS services may stop forwarding ingress and egress traffic for an xconnect for which a backup peer config has been applied.

Conditions: This symptom occurs in Cisco 7600 routers running Cisco IOS Release 15.2(4)S4a with ES+ cards (access or core facing) and xconnect configured under a service instance.

Workaround: Clear the xconnect on the Cisco 7600 router side. Clearing on the remote side does not have an effect.
- CSCu196778
 

Symptom: A router may crash and reload with BGP related traceback in an extremely rare timing condition while running “show ip bgp vpnv4 vrf XXXX nei A.A.A.A”.

Conditions: While making BGP related changes such as moving the same neighbor with quick operation of “no neighbor x.x.x.x” and then “neighbor x.x.x.x” across VRFs. Immediately after this if we type a “show ip bgp vpnv4 vrf XXXX nei A.A.A.A” - on a Cisco router running IOS and BGP, then in extremely rare timing condition the router may crash. The possibility of this to happen increases if the configuration and unconfiguration is done from one console and the show operation done from other console.

Workaround: When doing configuration and un-configuration and then show, its better to serialize the operation rather than aggressively use multiple consoles to do all actions at the same time.
- CSCu199015
 

Symptom: In VPLS using BGP signaling with Inter AS, when a PE on another AS is reachable through multiple ASBRs, the PW destination and the next hop PE address of some or all of the PWs in the standby RP remains as the non-preferred ASBR address instead of the preferred ASBR address.

Conditions: This symptom occurs under the following conditions:

  1. BGP L2VPN NLRIs received first from an ASBR becomes a less preferred ASBR on receiving NLRIs for the same VE-IDs from a more preferred ASBR.
  2. NLRI received from the more preferred ASBR has the same values (VEID, VBO, VBS, Label Base, MTU and CW) as the ones received previously from the other ASBR.

Workaround: Bring up the BGP session with the more preferred ASBR first. This would cause no updates to existing NLRIs even if received from other less preferred ASBRs.
- CSCu00056
 

Symptom: ASR IOSd crash occurs with the following error:

```
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = ISG CMD HANDLER
```

Conditions: This symptom occurs when changes are made through RADIUS.

Workaround: There is no workaround.
- CSCu04512
 

Symptom: When an RP switchover is done (which is head end for 500 TE tunnel and tail end for 500 TE tunnels), the RSVP label is assigned to the TE tunnel change and this in turn causes a traffic loss of 45 seconds on the pseudowire which is directed through these tunnels.

Conditions: This symptom occurs under the following conditions:

  - TE RID under the IGP is configured as a loopback other than the first one.
  - SSO is performed.

Workaround: Configure the TE router ID under the IGP to be the first loopback interface.

- CSCum07119

Symptom: Router generates tracebacks or crashes depending on platforms when **show application ip route** command is used concurrently with application route deletion.

Conditions: This symptom is observed when the **show application ip route** command is issued when JAVA onePK SDK is handling route replace operations.

Workaround:

1. Use **show ip route** command to display the application routes and not **show application ip route** command.
2. Use onePK GET ROUTE API to get the status of application added route.
3. Use **show application ip route** only when there is no route delete is in progress.

- CSCum11118

Symptom: A Cisco ISR router crashes due to stack overflow in the “ADJ background” process. The following syslog may be seen just before the crash:

```
000105: Dec 9 04:08:44.447 UTC: SYS-6-STACKLOW Stack for process ADJ background
running low, 20/6000.
```

Can also cause crash due to memory corruption, would show messages like

```
current memory block, bp = 0x3B727044, memorypool type is Processor data check, ptr =
0x3B727074
```

```
next memory block, bp = 0x3B729A60, memorypool type is Processor data check, ptr =
0x3B729A90
```

```
previous memory block, bp = 0x3B725DCC, memorypool type is Processor data check, ptr =
0x3B725DFC
```

Conditions: The conditions to this symptom are unknown.

Workaround: There is no workaround.

- CSCum14830

Symptom: Leaking IPv6 routes is observed from a VRF table into the global table using BGP. These routes consist of the following:

1. BGP routes learned from the VRF IPv6 BGP peer.
2. Redistributed static and connected routes.

The BGP routes leak fine, but the redistributed static and connected routes have an issue. After the redistributed routes leak, the exit interface shows “null0”. Sometimes instead of showing the exit interface as “null0”, it shows a random interface which is a part of VRF and has IPv6 enabled on it.

Conditions: This symptom occurs with IPv6 redistributed connected and static routes into BGP VRF (could also be redistributed from other protocols as well but have not been tested).

Workaround: There is no workaround.

- CSCum15232

Symptom: A Cisco IOS router may crash using LDAP while performing TLS operations.

Conditions: This symptom was observed in Cisco IOS Release 15.3(3)M1.4. Other versions can be affected as well.

Workaround: There is no workaround.

More Info: LDAP is used in IOS SSLVPN deployment to authenticate users.

- CSCum17958  
Symptom: An IOSd crash is observed during a configuration replace.  
Conditions: This symptom occurs on configuration with a port-channel interface.  
Workaround: There is no workaround.
- CSCum22612  
Symptom: Since the ASR fails to send MM6 [being a responder] in the absence of a valid certificate, IKE SAs start leaking and hence get stuck in MM\_KEY\_EXCH state. Multiple MM\_KEY\_EXCH exist for a single Peer on the ASR, however the Peer does not retain any SAs for ASR in this case. Along with CAC for in-negotiation IKE SAs, these stuck SAs block any new SAs or IKE rekeys even after renewing the certificates on the ASR.  
Conditions: This symptom is observed under the following conditions:
  - ASR acting as IKEv1 termination point [sVTI for example] and is a responder.
  - IKE authentication mode is RSA-SIG [Certificates].
  - On the ASR, the ID-Certificate is either Expired or Not-present for a given sVTI tunnel
  - The ASR also has a IKE in-negotiation CAC of a certain value.Example: `crypto call admission limit ike in-negotiation-sa 30`  
Workaround: Perform the following workarounds:
  1. Manually delete stuck SAs by using: **clear crypto isakmp 12345**, where 12345 is conn\_id of a stuck SA. Repeat this for each stuck SA
  2. Temporarily increase CAC to accommodate new SA requests: `crypto call admission limit ike in-negotiation-sa 60`More Info: Found and Tested in Cisco Release XE 3.7.4 or Cisco IOS Release 15.2(4)S4.
- CSCum29064  
Symptom: Syncing dual-stack iWAG session to STANDBY does not occur.  
Conditions: This symptom occurs when IPv4 and IPv6 FSOL is received from same client at ISG together (or very less time gap) for a dual-stack session. In this case, the session does not sync to STANDBY for the previous IPv6 FSOL and ISG gets a new IPv4 FSOL.  
Workaround: There is no workaround.
- CSCum34830  
Symptom: A router crash is observed.  
Conditions: This symptom occurs while performing VRRP and VRRS-related configuration changes.  
Workaround: Unconfigure the **ip pim redundancy <>** command before deleting the subinterface or disabling PIM on an interface.
- CSCum36825  
Symptom: No IPv6 global unicast address is assigned to PPP Virtual access interfaces and to IPv6 over IP/GRE tunnel interfaces.  
Conditions: Virtual access interface is configured using the command “`ipv6 address autoconfig`”.  
Workaround: There are no workarounds.
- CSCum45122  
Symptom: An IPv6 MFIB entry is not removed after the mroute expires.

Conditions: This symptom occurs only with the partitioned MDT profile for mLDP. The PE router could get into a trouble state if it receives traffic first and then almost immediately after that receives an MLD join on the same interface for the same group.

Workaround: Remove VRF context and then reconfigure it.

- CSCum46850

Symptom: Using LISP set tags on routes imported to the RIB when exporting LISP routes from the RIB to BGP fails.

Conditions: This symptom occurs when redistribute list route-map is used under bgp with a route-map that contains match tag.

Workaround: There is no workaround.

- CSCum48221

Symptom: 3560CG box memory is showing as low as 3.15MB.

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.

- CSCum52216

Symptom: After a reload, **ip pim sparse-mode** is gone on interface lisp 0.x (x denoted the LSIP interface number).

Conditions: This symptom occurs after a reload.

Workaround: There is no workaround.

- CSCum61595

Symptom: Alignment errors are observed after upgrading to Cisco IOS Release 15.2(4)M5.

```
Jan 9 19:42:59.623 GMT: %ALIGN-3-CORRECT: Alignment correction made at 0x6477F81Cz
reading 0x6BE87495 Jan 9 19:42:59.623 GMT: %ALIGN-3-TRACE: -Traceback= 0x6477F81Cz
0x647805D0z 0x6478FE70z 0x64751088z 0x64B99F4Cz 0x64B99FD4z 0x64752 284z 0x647525ACz
```

Conditions: This symptom does not occur under specific conditions.

Workaround: There is no workaround.

- CSCum62783

Symptom: The following alignment errors are seen after a PPPoE session establishment for the first time after a reboot:

```
*Jan 14 07:24:40.591: %ALIGN-3-CORRECT: Alignment correction made at 0x32B2DFF4z
reading 0xE7790ED *Jan 14 07:24:40.591: %ALIGN-3-TRACE: -Traceback= 0x32B2DFF4z
0x32B1E274z 0x32B1EECCz 0x32B1EF90z 0x332E550Cz 0x332E54F0z 0xFFFF1A00z 0xFFFF1A00z
```

Conditions: This symptom occurs when **pppoe-client ppp-max-payload** is configured under the Ethernet interface.

Workaround: There is no workaround.

- CSCum63121

Symptom: Localhost not reflected in “show call history voice last 2”.

Conditions: This symptom is observed when UUTs are loaded with c2900-universalk9-mz.SPA.153-3.M1.9.

Workaround: There is no workaround.

- CSCum64565  
Symptom: Router crashes while getting NTP status.  
Conditions: This symptom is not observed under any specific conditions.  
Workaround: There is no workaround.
- CSCum65451  
Symptom: A crash occurs due to multicast stack overflow memory corruption.  
Conditions: This symptom may occur when PIM is enabled on a LISP interface and Auto-RP is also enabled.  
Workaround: Configure **no ip pim autorp** before any other PIM or LISP configuration.
- CSCum67166  
Symptom: The router hangs after loading an image.  
Conditions: This symptom occurs with the latest whales-universal-mz mcp\_dev image.  
Workaround: There is no workaround.
- CSCum71701  
Symptom: This bug can stop traffic from being forwarded by an upstream router when the **ip pim join-prune-interval** command is configured on the downstream router's upstream LISP interface.  
Conditions: This symptom occurs when the **ip pim join-prune-interval** command is configured with a value greater than the default on a LISP interface.  
Workaround: There is no workaround.
- CSCum78363  
Symptom: Local circuit keeps DOWN state.  
Conditions: This symptom is observed when L2TPv3 session is configured.  
Workaround: There is no workaround.
- CSCum85493  
Symptom: Ping fails with tunnel protection applied.  
Conditions: Tunnel protection applied on GRE tunnel interface, using IKEv1 to negotiate IPsec SAs and remote node (IKEv1 responder) behind NAT.  
Workaround: The users can switch to IKEv2.
- CSCum85813  
Symptom: Shut primary static router and secondary static is not installed automatically.  
Conditions: This symptom is seen on the sites where the BFD state of the backup static route is marked as "U" in the output of "show ip static route bfd".  
Workaround: Reinstall the default backup static route.
- CSCum85923  
Symptom: Router-solicitation (RS) messages are dropped on the switch port that have IPv6 RA guard enabled. On removing RA guard, RS messages go through.  
Releases tested:  
Affected releases: 151-2.SG2 and 152-1.E.bin  
Unaffected releases: 150-2.SG.bin

Conditions: This symptom occurs when “ipv6 nd raguard” is enabled.

Workaround: There is no workaround.

- CSCum86841

Symptom: When upgrading from Cisco IOS XE Release 3.2S to Cisco IOS XE Release 3.9S, the DHCP server NACKs the client while sending renew. This worked in Cisco IOS XE Release 3.2S and not in Cisco IOS XE Release 3.9S.

Conditions: This symptom occurs when the DHCP server is provisioned to give out an IP address using a host pool (where the MAC address is tied to IP address). After the client gets the IP address, it downloads the configurations from the TFTP server and update the new MAC address after which when the client sends a renew, the DHCP server NACKs the client till the binding is present.

Workaround: There is no workaround. Downgrade to Cisco IOS XE Release 3.2S.

- CSCum88382

Symptom: BFD session not established upon RP Switchover and back.

Conditions: This symptom is observed during RP switchover and switchback.

Workaround: There is no workaround.

- CSCum89148

Symptom: Map-requests are forwarded to sites whose locators do not match the configured allowed-locator policy.

Conditions: This symptom is observed when the {ipv4 | ipv6} map-resolver allowed-locator registered is configured, and allowed-locator configuration is present under “site”.

Workaround: There is no workaround.

- CSCum93027

Symptom: A Cisco router reloads unexpectedly.

Conditions: This symptom occurs when the following conditions are reproduced:

1. Configure a subinterface with IPv6.
2. Configure OSPFv3 on the subinterface.
3. Configure IPsec authentication for OSPFv3 on the subinterface.
4. Shutdown the subinterface.
5. Remove the subinterface.

Workaround: Unconfigure the OSPFv3 IPsec authentication configuration before removing the subinterface.

- CSCum93078

Symptom: Image installation fails for K10.

Conditions: This symptom occurs after trying to install a tar image on K10. Installation of a bin image fails.

Workaround: Reboot the switch.

- CSCum94228

Symptom: Local CAC displaying all information about each flows. This may impact show output for customer in a set up where we could possibly have large number of flows.

Conditions: This symptom is observed in a scaled configuration.



- Workaround: There is no workaround.
- CSCum95330
 

Symptom: Removing an Ethernet service instance which is a member of a bridge domain may cause the router to reload.

Conditions: This symptom is observed when the last service instance is removed from the bridge domain and there are still members of the bridge domain which are not service instances (such as VFIs).

Workaround: Completely unconfigure the bridge domain and reconfigure it.
  - CSCun00488
 

Symptom: Duplicate records are exported from MMA.

Conditions: This symptom occurs in the following topology:

```
SRC --- UUT --DST | collector
```

Set the configuration at the UUT to export all the records to the collector. At the exporter, duplicate records are noticed.

Workaround: There is no workaround.
  - CSCun04467
 

Symptom: Prior to receiving a label via the Label Distribution Protocol (LDP), the output of **show mpls l2transport vc detailed** and **show l2vpn atom vc detailed** fail to properly indicate the lack of a remote binding.

Conditions: This symptom has been observed in Cisco IOS Release 15.4(02)S.

Workaround: There is no workaround.
  - CSCun07772
 

Symptom: A Cisco router crashes.

Conditions: This symptom occurs on deleting a subscriber's session in attempting state by a COA script as shown below:

```
#!/bin/sh CISCO=$1 # bras SessionID=$2 CoaSecret='secret' #clear ISG session on BRAS
/bin/echo
"User-Name="undef",Acct-Session-Id="$SessionID",cisco-avpair="subscriber:command=account-logout" | /usr/bin/radclient -x $CISCO:1700 coa $CoaSecret
```

Workaround: Do not use the COA script for deleting the subscriber's session.
  - CSCun11782
 

Symptom: Rtfiler prefixes are sent with incorrect next-hop equal to next-hop of the default static route in GRT instead of BGP router-id.

Conditions: This symptom occurs with a default static route present in GRT pointing, for example, to the next-hop known behind the connected interface.

Workaround: Replace the default static route with a more specific static route or remove static and clear BGP.
  - CSCun11927
 

Symptom: Link-OAM breaks after link flap between the Cisco Catalyst 4500-X Series Switch and the Cisco ASR 9000 Series Router. With an interface with LACP + Link-OAM configuration when the connection between the Catalyst 4500-X Series Switch (IOS XE) and Cisco ASR 9000 Series

Router(IOS XR) flaps, the link does not restore due to the following deadlock : LACP PDU does not start unless OAM starts on the Cisco ASR 9000 Series Router side and Link-OAM PDU does not start unless LACP starts on the Catalyst 4500-X Series Switch side.

With the above scenario after a link flap the link gets stuck in (suspended) LACP state on the Catalyst 4500-X Series Switch and non-connected state on Cisco ASR 9000 Series Router. The link has to be restored with manual reconfiguration in a particular sequence to avoid the above dead lock.

Conditions: This symptom occurs due to a combination of Link-OAM and LACP between a Catalyst 4500-X Series Switch and a Cisco ASR 9000 Series Router.

Workaround: Manually restart the link-OAM session and toggle LACP. To restore the link, change the configuration sequence on the Catalyst 4500-X Series Switch side in such a way that the LACP packet goes ahead first and then the Link-OAM PDU.

```
interface x/x
shut
no ethernet oam
no channel-group <x> active
no shut
channel-group <x> active
ethernet oam
```

or

Disable EFD on the Cisco ASR 9000 Series Router side.

or

Toggle OAM on the Cisco ASR 9000 Series Router side.

- CSCun13399

Symptom: Flow-ids are not synced on the standby for some of the IMA VCs on an HA setup.

Conditions: This symptom occurs when an HA router is reloaded with IMA VCs enabled on it.

Workaround: There is no workaround.

- CSCun13688

Symptom: The Cisco Catalyst 6500 Supervisor Engine 2T with CLNS routing configured crashes after **show clnbs route**.

Conditions: This symptom occurs when CLNS routing is configured.

Workaround: There is no workaround.

- CSCun19455

Symptom: When an access-list is applied to an interface using onePK, the “ip access-group” configuration will appear in the running configuration. When the app terminates, this configuration is removed. Additionally, any manually configured access-group for that interface is removed.

Conditions: This occurs when using onePK 1.1.0. The ACL lifetime need not be set to persistent.

Workaround: There is no workaround.

- CSCun25912

Symptom: Configurations dynamically applied to the virtual-access interface might be lost over the reconnection while using the autoreconnect feature on Cisco Anyconnect on the ASR platform.

For example, the interface after initial connection establishment would have a QOS service policy applied:

```
ROUTER#sh derived-config int virtual-access 1
!
```

```
interface Virtual-Access1
ip unnumbered GigabitEthernet0/0/1
tunnel source 10.1.1.1
tunnel mode ipsec ipv4
tunnel destination 10.10.1.100
tunnel protection ipsec profile ipsec-profile
no tunnel protection ipsec initiate
service-policy input INPUT-POLICY
end
```

After reconnection the INPUT-POLICY is missing:

```
ROUTER#sh derived-config int virtual-access 1
!
interface Virtual-Access1
ip unnumbered GigabitEthernet0/0/1
tunnel source 10.1.1.1
tunnel mode ipsec ipv4
tunnel destination 10.10.1.100
tunnel protection ipsec profile ipsec-profile
no tunnel protection ipsec initiate
end
```

Conditions: This symptom is observed with configurations being applied from the user AAA profile over radius authentication. Affected parameters observed are QOS service policies and access-group.

Workaround:

1. Do not use the reconnect feature.

or

2. Apply the configurations directly to the virtual-template (if this is an option).

- CSCun28171

Symptom: An ISG will stop processing CoAs for a subscriber session when CoAs are received in rapid succession. The received CoAs are queued but never processed.

Conditions: This symptom occurs when multiple CoAs for a single subscriber session are received in short time (milliseconds).

Workaround: The subscriber session needs to be reset to recover. There is no workaround known yet to avoid the situation from happening.

- CSCun31021

Symptom: A vulnerability in IKE module of Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to affect already established Security Associations (SA)..

The vulnerability is due to a wrong handling of rogue IKE Main Mode packets. An attacker could exploit this vulnerability by sending a crafted Main Mode packet to an affected device. An exploit could allow the attacker to cause dropping of valid, established IKE Security Associations on an affected device.

Conditions: Device configured to process IKE request that already has a number of established security associations.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C> CVE ID

CVE-2014-2143 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-2143>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun31450

Symptom: CPU hog followed by crash.

Platforms

- ct5760-ipservices.bin
- cat3k\_caa-universalk9.bin
- cat4500e-universalk9.bin

Conditions: This issue occurs while running udp IP SLA applications.

Workaround: There is no workaround.

- CSCun36655

Symptom: If the terminal adjacency of a lisp interface is removed and then re-added, the lisp interface MTU may remain at the invalid value of 65535. This can be seen in the **show cef interface <intf> internal** command output.

IPsec will obtain the MTU value from CEF and LISP, and the incorrect MTU will cause drops of large packets.

IPSEC MTU incorrectly computed - causing packet drops on large packets traversing from "inside" to "outside" are dropped.

Conditions: This symptom is observed in the following Cisco C800 Series: Cisco IOS Software, C890 Software (C890-UNIVERSALK9-M), Version 15.3(3)XB12, RELEASE SOFTWARE (fc2)

Workaround: A workaround is to toggle the IP MTU config on the lisp interface. Use "show run lisp0.1" to determine the MTU. Then use "ip mtu <mtu>" to first set it to a lower value, and then to set it back to the original value.

Example:

```
sh run interface lisp0.1
interface LISP0.1 ip mtu 1398 crypto map CM end
conf t
interface lisp0.1
ip mtu 1200
ip mtu 1398
```

More Info: Originally [Cisco IOS Release 15.3(1)T] the MTU was accurately computed as:  
RTR13-xTR#sh cry ipse sa vrf DeptA | in mtu path mtu 1456, ip mtu 1456, ip mtu idb  
LISP0.1 path mtu 1456, ip mtu 1456, ip mtu idb LISP0.1 path mtu 1456, ipv6 mtu 1456,  
ipv6 mtu idb LISP0.1 path mtu 1456, ipv6 mtu 1456, ipv6 mtu idb LISP0.1 RTR13-xTR#  
In 153-3.XB12, the MTU is as follows:

```
!
RTR#show crypto ipsec sa
| inc mtu ! plaintext mtu 65458, path mtu 65535, ip mtu 65535, ip mtu idb LISP0
```

- CSCun38333

Symptom: Locator ID Separation Protocol (LISP) local EID database locator configured through the "database-mapping <eid-prefix> ipv6-interface <interface> priority <priority> weight <weight>" command uses deprecated IPv6 address on specified interface.

Conditions: Multiple IPv6 addresses available on an interface with the lexicographically first address being deprecated.

Workaround: There is no workaround.

- CSCun40868

Symptom: The following messages are seen continuously on t\_base\_4 image:

```
*Feb 28 00:18:00.359: %CFT_API-3-CFT_ERRMSG_NO_MEMORY: CFT could not allocate memory
for the flow cft_private_insert_pre_flow_tuple, parent_fid: 0
```

Conditions: The issue is seen after configuring the router with Medianet.

Workaround: There is no workaround.

- CSCun41292

Symptom: On a Cisco ASR 1001 router running Cisco IOS Release 15.3(1)S, a crash occurs when the “show ip ei vrf X topo X.X.X.X/X” command is executed. The X.X.X.X/X must be in “FD is infinity” status in EIGRP as CSCtz01338.

```
asr1001_bew_03# show ip ei vrf
```

```
* to all | i Infinity P 174.162.XX.XX/24, 0 successors, FD is Infinity, U, serno 37,
refcount 1 snip P 174.180.XX.XX/29, 0 successors, FD is Infinity, U, serno 46,
refcount 1
```

```
asr1001_bew_03#show ip ei vrf 1 to 174.162.XX.XX/24
```

```
Exception to IOS Thread: Frame pointer 0x7F63DF6602D0, PC = 0x1956C8D
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = Exec -Traceback=
1#980611ad3b9665cd80fe5178bcd6036a :400000+1556C8D :400000+1556B09 :400000+15569D1
:400000+157DE39 :400000+15197A2 :400000+1518659 :400000+156BA5E :400000+15591D1
:400000+1189768 :400000+1188E6D :400000+1186E15 :400000+484F270 :400000+11A1CA0
Fastpath Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
c:7F64154A4000+BE002
Auxiliary Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
pthread:7F640ED43000+A7C9
```

Conditions: This symptom occurs when X.X.X.X/X is in “FD is infinity” status in EIGRP.

Workaround: There is no workaround.

- CSCun45272

Symptom:

1. Standby RP will have out-of-sync entries. With MPLS-TE NSR enabled, the standby RP will have out-of-sync entries which will result in flapping of the path-protected LSP of the tunnel after an SSO.
2. Leaking an LSP. A third LSP will be signaled and leaked (there is no management of the LSP). There are supposed to be two LSPs at steady state (primary and path protected), but with this defect, there will be primary, path protected, and leaked LSP.

Conditions: This symptom occurs with a reoptimization of a tunnel that has failed with path protection enabled.

Workaround: There is no workaround.

- CSCun46486

Symptom: A Cisco device crashes every 2-3 days when the SNMPSET operation is used to create guest users.

Conditions: This symptom occurs when guest users are created through SNMPSET operations at a very high rate.

Workaround: There is no workaround.

- CSCun48344  
Symptom: A config-sync failure occurs due to the **address-family ipv6 unicast vrf** command during the immediate unconfiguration and reconfiguration of VRF definition.  
Conditions: This symptom occurs with attached running configurations.  
Workaround: There is no workaround.
- CSCun52430  
Symptom: Removing explicitly configured queue-limit configuration via “no queue-limit” on a user-defined class may not actually remove the preconfigured queue-limit parameter from PD.  
Conditions: This symptom is observed when an explicitly created queue-limit is removed.  
Workaround: Reconfigure queue-limit with a desired (or default) value.
- CSCun65000  
Symptom: Traffic loss of about 200-500 ms is observed.  
Conditions: This symptom is observed on an RLFA cutover.  
Workaround: There is no workaround.
- CSCun67364  
Symptom: Convergence on Local link failure with rLFA is higher than one second.  
Conditions: Configure rLFA and perform local link failure. The problem is likely seen when configuring a small spf-interval value.  
Workaround: Do not configure too small spf-interval.
- CSCun68542  
Symptom: CSR1000V router running XE3.11 (15.4(1)S) working as Route Reflector.  
The route-reflector is advertising prefixes with incorrect subnet masks to ibgp peers and route-reflector clients. The incorrect prefixes are not present in the bgp table of the route-reflector itself, however they do get installed in the bgp table of the router receiving the update.  
Conditions: This symptom is observed when BGP route reflector uses the additional paths feature.  
Workaround: Disable additional path feature either globally under address-family or per neighbor.
- CSCun71301  
Symptom: A higher layer app such as LISP ends up using a deprecated IPv6 address as returned by the IPv6 service even if a valid address exists for an interface.  
Conditions: This symptom occurs when multiple IPv6 addresses are available on an interface with the lexicographically first address being deprecated.  
Workaround: There is no workaround.
- CSCun72459  
Symptom: High traffic loss is observed with setups having BGP and microloop avoidance combination.  
Conditions: This symptom occurs with the following combination:
  1. IP FRR is turned on.
  2. Cisco IOS XE Release 3.11 code (or newer) that enables microloop avoidance by default.
  3. BGP configurations.

Workaround: Disable the microloop avoidance feature. For example, in ISIS, execute the following commands:

```
router isis <process name>
microloop avoidance disable
!
```

However, there will be some traffic loss due to the lack of microloop avoidance.

- CSCun72939

Symptom: QoS Egress Marking does not work for GRE Tunnels.

Conditions: This symptom is observed under the following conditions:

- The issue happens for fragmented packet.
- The issue is found on Cisco IOS Release 15.3(3)M2.

Workaround: There is no workaround.

- CSCun73515

Symptom: A router crashes due to RMON.

Conditions: This symptom occurs on activation of an RMON event.

Workaround: There is no workaround.

- CSCun73782

Symptom:

A vulnerability in LISP control messages processing on Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

The vulnerability is due to insufficient checking of certain parameters in LISP control messages on ITR. An attacker could exploit this vulnerability by sending malformed LISP control messages to ITR. An exploit could allow the attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

Conditions: Malformed messages can only be generated by a device that is already registered to a LISP system: a valid ETR or ALT.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C>

CVE ID CVE-2014-3262 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-3262>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun75719

Symptom: After a switchover, standby device crashes with traceback.

Conditions: At present, this is observed only on advipservices images in mtrose branches.

Workaround: There is no workaround.

- CSCun76733

Symptom: BFD goes down and remains in Admindown state.

Conditions: This symptom occurs after applying ACL chaining and flapping of the interface.

Workaround: There is no workaround.

More Info: An IPv4 BFD neighbor remains in admindown state on the PE. The ACE configured in ACL for BFD is matched and the receive counters on BFD neighbors are incremented but the BFD is still down.

This issue occurs only after ACL chaining is applied.
- CSCun77010

Symptom: A router may crash after or during the execution of the **show ipv6 ospf rib** command.

Conditions: This symptom occurs when many routes or route paths are present in the OSPFv3 rib. The OSPFv3 rib is significantly recomputed during execution of commands.

Workaround: Limit the use of the **show ipv6 ospf rib** command.
- CSCun78309

Symptom: An Mroute entry on FHR is stuck in a registering state in MVPNv4. `show ip mroute vrf <vpn-name> -->` shows the mroute entry in registering state

Conditions: This symptom occurs when the source address of the encapsulation tunnel for PIM registers on the FHR is one of the interfaces that is not in the same VRF as the register tunnel itself.

Workaround: There is no workaround.

More Info: Output:

```
PE2#show ip mroute vrf vpn1
(215.12.1.2, 229.40.1.1), 00:00:29/00:02:30, flags: FT Incoming interface:
GigabitEthernet3/3.1, RPF nbr 0.0.0.0, Registering Outgoing interface list: Tunnel764,
Forward/Sparse, 00:00:29/00:03:00
```
- CSCun81749

Symptom: MVPN traffic is unexpectedly terminated since the last-hop PIM router does not send an “SG Join” message on the MDT tunnel.

Conditions: This symptom occurs when the same IP address is used for the MDT tunnel IP address on the last-hop PIM router and the source IP address of multicast traffic.

Workaround: There is no workaround.
- CSCun86606

Symptom: An IOSD crash occurs due to “Process = Virtual Exec”.

Conditions: This symptom occurs when the **show ip cef internal** command and routing table is cleared in parallel.

Workaround: When clearing the routing table (for example, `clear ip ospf process`) avoid running ip cef-related show commands in parallel.
- CSCun87557

Symptom: A Cisco router crashes.

Conditions: Set the VTY Service Set maximum response to a small number, for example, 10, and then send multiple commands separated by newline using the same write, for example, “`show ver\nshow ver\n`”.

Workaround: Set Maximum response to a bigger number.



- CSCun88267

Symptom: A Cisco router stops forwarding traffic when an SSLVPN session is established and stops responding.

Conditions: This symptom occurs with SSLVPN and DTLS enabled. Cisco ISR-G2 platforms may experience a Queue Wedge.

Workaround: Disable DTLS by configuring **no svc dtls** under policy group.
- CSCun92081

Symptom: A traceback is seen while removing IPv6 unicast-routing configuration.

Conditions: This symptom occurs when ISIS IPv4 is not enabled and ISIS is runs on IPv6 multitopology mode.

Workaround: There is no workaround.

More Info: The traceback is generated due a warning message that the adjacency database is not empty when ISIS is switching out of the IP mode.
- CSCun92095

Symptom: IOS-XE running router may reload when unconfiguring BGP along with other removal operations in a scaled setup.

Conditions: BGP is configured with 1Million+ nets and 4000 VRFs. Then the bgp instance is removed using “no router bgp <>”

Workaround: Shut down the bgp neighbor sending big scale nets to remove the nets first from BGP and RIB. Then remove the BGP using “no router bgp <>”.
- CSCun99811

Symptom: If a Cisco IOS box does not support Ethernet Y.1731 delay DMM version 1 (DMMv1), but supports DMM version 0 (DMM), it will not respond to a box trying to run a DMMv1 session.

Conditions: This symptom occurs with an initiator box running DMMv1 to a Cisco IOS box that supports DMM but does not support DMMv1. Rather than responding as though it were receiving DMMs version 0, as is the required behavior, the session will be rejected.

Workaround: All boxes that support DMMv1 will also support DMM version 0, so this can be used between two boxes instead. The normal DMM version 0 restrictions apply in this case.
- CSCuo09249

Symptom: An xTR changes its RLOC, map-request packets from that new RLOC are dropped on the MS/MR due to policy violation, for example:

```
*Apr 2 15:29:15 JST: LISP-0: AF IID 100 IPv4, Map resolver filtered incoming map request from 2400:A:A:9999:C267:AFF:FE52:287 because it does not conform to the configured allowed-locator policy.
```

Conditions: This symptom is observed when {ipv4lipv6} map-resolver map-request validate source registered is configured on the MS/MR and the xTR RLOC is updated, for example, by DHCP when the {ipv4lipv6}-interface configuration is used in the database-mapping configuration. Both the new and the old RLOC must have been valid.

Workaround: Remove and re-add database-mapping configuration on xTR, possibly using EEM script on address change Remove “{ipv4lipv6} map-resolver map-request validate source registered” configuration on MS/MR clear lisp site <name> on the MS.

- CSCuo11238
 

Symptom: Router crashes when removing address-family from VRF definition, or when removing the VRF definition.

Conditions: This symptom is observed when PIM is configured for the LISP interface associated with the VRF.

Workaround: Unconfigure LISP for the VRF, or remove PIM configuration from the LISP interface associated with the VRF, before removing VRF configuration.
- CSCuo12245
 

Symptom: The following error message is observed with traceback :  
OCE\_PUNT\_PROCESS-3-LABEL\_CACHE\_INVALID: inlabel pointer was NULL

Conditions: Multicast traffic is label switched in the mpls P2MP tree and replicated at branch bud nodes along the P2MP tree. The error condition is observed at a bud node, where the replicated traffic is dropped with the error.

Workaround: There is no workaround.
- CSCuo15799
 

Symptom: Memory leaks are observed on the node.

Conditions: This symptom occurs with flaps in the REP segment generating TCNs that are being sent into a different REP segment.

Workaround: There is no workaround.
- CSCuo21431
 

Symptom: NTLM may not work properly.

Conditions: This symptom occurs when the LDAP server goes down and comes up.

Workaround: Add a new server as a part of the AAA group server ldap adgroup.
- CSCuo26634
 

Symptom: Crash is observed.

Conditions: This symptom is observed with command “sh frr-manager client client-name <name> det” when the client with the specified name does not exist.

Workaround: There is no workaround.
- CSCuo34395
 

Symptom: BFD OSPF client does not react at interface events on a remote endpoint.

Conditions: This symptom occurs under the following conditions:

  - BFD is enabled - OSPF is enabled
  - One of the devices where BFD is enabled is running Cisco IOS Release 15.3(3)M2

Workaround: There is no workaround.
- CSCuo35867
 

Symptom:

  1. CPOS-based PPP serial interface is UP/DOWN; but HDLC is UP/UP; loopback local for PPP is also UP/DOWN.
  2. From debug, the following output is seen:  
\*Apr 16 20:46:50.330: AAA/ID(00100066): PPP allocated ....



- CSCuo49923
 

Symptom: Performing an ISSU upgrade with the CEF table consistency checkers enabled may result in a crash on “issu runversion”.

Conditions: This symptom occurs with a Cisco Catalyst 6500 Series Switch running Cisco IOS Release 15.1(02)SY.

Workaround: Turn off the CEF table consistency checkers before performing an ISSU upgrade.
- CSCuo51246
 

Symptom: Traffic flow is not as expected when IPv6 policing is enabled on UUT.

Conditions: This symptom is observed on loading the Cisco IOS Release 15.4(2.10)T image.

Workaround: There is no workaround.
- CSCuo53561
 

Symptom: BGP fails to apply an inbound route map on prefixes after a switch over.

Conditions: This symptom occurs when NSR is enabled and RP switchover is performed twice.

Workaround: Enable the knob “bgp sso route-refresh-enable” or manually do a soft refresh to get the routes back from NSR peers on the new active RP.
- CSCuo55180
 

Symptom: A vulnerability in PPPoE processing code of Cisco IOS XE could allow an unauthenticated, adjacent attacker to cause a reload of the affected device and eventually a denial of service (DoS) condition.

The vulnerability is due to improper processing of certain malformed PPPoE packets. An attacker could exploit this vulnerability by sending a malformed PPPoE packet to an IOS XE ASR1000 device, configured with PPPoE termination. An exploit could allow the attacker to cause a reload of the affected device and eventually a denial of service (DoS) condition.

Conditions: Cisco ASR 1000 with IOS XE, configured for PPPoE termination.

Workaround: There is no workaround.

Further Problem Description: A device crashing, may print the following messages on the console:

```
%SYS-3-OVERRUN: Block overrun at 7F7FAE750B58 (red zone 44534C5F00000000)
%SYS-6-MTRACE: mallocfree: addr, pc ? %SYS-6-BLKINFO: Corrupted redzone blk
7F7FAE750B58, words 404, alloc 6374D1B, InUse, dealloc 10001, rfcnt 1 ?
%Software-forced reload
Exception to IOS Thread: Frame pointer 0x7F7FA0AB5AD8, PC = 0x7F80A8469565
UNIX-EXT-SIGNAL: Aborted(6), Process = Check heaps -Traceback=
1#c3a5522ccb47820b036322d6b7226e1c c:7F80A8438000+31565
Fastpath Thread backtrace: -Traceback= 1#c3a5522ccb47820b036322d6b7226e1c
c:7F80A8438000+BDDD2
Auxiliary Thread backtrace: -Traceback= 1#c3a5522ccb47820b036322d6b7226e1c
pthread:7F80A3697000+A7C9
```

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 6.1/5:  
<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:A/AC:L/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2014-3284 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:  
<https://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-3284>

Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCuo56173  
Symptom: When PW's remote peer is ALU, it takes 5 to 10 minutes for the PWs to come up.  
Conditions: This symptom occurs when Provision PW is done first on the ALU and then on the Cisco router.  
Workaround: Provision PW on the Cisco router first.
- CSCuo56871  
Symptom: A Cisco ASR 1001 router running Cisco IOS Release 15.2(4)S4 acting as a route server crashes when **clear bgp ipv4 unicast \*** is executed.  
Conditions: This symptom occurs when a router is configured as as route server and a command executed in an IPv4 table is reset via **clear bgp ipv4 unicast \***.  
Workaround: Do not execute command **clear bgp ipv4 unicast \***. Instead, one could use the **clear ip bgp \*** to hard reset all the BGP tables.
- CSCuo60344  
Symptom: With loss of traffic on primary flow in MoFRR, the secondary flow may not be treated as primary since it is random and the new flow may become the primary.  
Conditions: This symptom occurs in ECMP or TI flow based MoFRR and when there is a loss of primary flow.  
Workaround: There is no workaround.
- CSCuo66491  
Symptom: While using Pfr, traffic classes oscillate from controlled to default to uncontrolled when probe creation fails for alternate external interfaces (due to lack of parent route).  
Conditions: This symptom does not occur under specific conditions.  
Workaround: Configure monitor mode active or monitor mode both instead of monitor mode fast.
- CSCuo72301  
Symptom: Crash occurs when IKEv2 attempts to clean up its contexts when it times-out waiting for received Certificate to be Validated by PKI component.  
Conditions: Authentication with certificates and PKI component's response to certificate validation is delayed.  
Workaround: There is no workaround.
- CSCuo72961  
Symptom: An error message is logged in during QoS configuration during an FPM test.  
Conditions: This symptom occurs due to a policy with FPM class.  
Workaround: There is no workaround.
- CSCuo75681  
Symptom: The RP crashes due to "%SYS-2-CHUNKBADMAGIC" in checkheaps.  
Conditions: This symptom does not occur under specific conditions.  
Workaround: There is no workaround.

- CSCuo83510
 

Symptoms: A stack overflow and boot loop can occur when configuring OSPFv3 for IPv6 using a non-broadcast network type on IOS XE

Conditions: SVI or Layer-3 Interface using the ospf non-broadcast network type.

Workaround: Remove the non-broadcast network configuration.

Further Problem Description: This issue was found during a security audit of the product.

PSIRT Evaluation: The Cisco PSIRT has evaluated this issue and does not meet the criteria for PSIRT ownership or involvement. This issue will be addressed via normal resolution channels.

If you believe that there is new information that would cause a change in the severity of this issue, please contact psirt@cisco.com for another evaluation.

Additional information on Cisco's security vulnerability policy can be found at the following URL:  
[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)
- CSCuo83554
 

Symptom: A vulnerability in the Autonomic Network Discovery Packets of Cisco IOS XE could allow an unauthenticated, adjacent attacker to receive arbitrary data from other traffic passing through the device

The vulnerability is due to uninitialized memory used in packet creation. An attacker could exploit this vulnerability by capturing packets on the segment.

Conditions: Device configured with default configuration.

Workaround: Not applicable or available.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 3.3/3:  
<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:A/AC:L/Au:N/C:P/I:N/A:N/E:POC/RL:U/RC:C>

No CVE ID has been assigned to this issue. Additional information on Cisco's security vulnerability policy can be found at the following URL:  
[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)
- CSCuo84660
 

Symptom: The following error message is seen:

```
*May 15 20:22:43.699: %DATACORRUPTION-1-DATAINCONSISTENCY: copy error, -PC=
:10000000+D90018 -Traceback= 1#10ebf8a777fd9b28d42b106d039edefc :10000000+78F240
:10000000+78F5F0 :10000000+7B9268 :10000000+7548448 :10000000+D90018 :10000000+D8A6D0
:10000000+D9B2C4 :10000000+DA3BEC :10000000+6A6DC4 :10000000+6ADDB0 :10000000+49DBB2C
:10000000+6BF11C
```

Conditions: This symptom occurs while updating the running configuration using any type of remote file transfer (via SNMP or copy command). When the source IP resolves to a DNS hostname longer than 63 bytes, an error message will be seen. There is no impact to the system. The running configuration will update as expected.

Workaround: Copy the file to a local storage first and then copy it from the local storage to the running configuration.
- CSCuo86953
 

Symptom: A Cisco router or switch may crash while issuing the **show logging** command.

Conditions: This symptom occurs while issuing the **show logging** command. Let the output of the **show logging** command remain at the more prompt in the trap logging session. While changing the **logging host** command in a different session, resume the output of the **show logging** command. There is a chance that both actions at the same time will make the device crash.

Workaround: Do not make changes to the **logging host** command while the output of the **show logging** command is still outstanding.

- CSCuo88282

Symptom: A Cisco ASR router crashes.

Conditions: This symptom occurs under the following conditions:

Configure a DHCP database as follows: ip dhcp database tftp://192.168.50.100/dhcp write-delay 60 timeout 30 The router is unable to write the database as TFTP is not installed on 192.168.50.100 or TFTP IP is not reachable (both scenarios leading to crash). After a few seconds the router gets crashed.

Workaround: There is no workaround.

- CSCuo91745

Symptom: The black hole should not drop TC when TC is learnt at the beginning.

Conditions: This symptom occurs when the black hole is added in the class as follows: class http sequence 10 match application http policy custom priority 1 one-way-delay threshold 100 path-preference SP1 fallback blackhole

The HTTP traffic is added. When the TC is learning, it is uncontrolled and hence during this time traffic will be dropped. The dropping will start at the TC learnt and end at the TC controlled. The duration will be a minimum of 30s.

Workaround: There is no workaround.

- CSCuo93299

Symptom: ZTB does not work.

Conditions: This symptom occurs when the image is loaded and left without aborting the setup dialogue box.

Workaround: This issue has been fixed.

- CSCuo93711

Symptom: RSVP HA Services leaks memory on the standby RP. Standby RP eventually hits the “out of memory” condition and will reload. There is no traffic impact as the active RP is not affected.

Conditions: This symptom occurs when the **mpls traffic-eng nsr** command is configured.

Workaround: There is no workaround.

More Info: The leak is specific to MPLS-TE tunnel tails. A small memory block is leaked whenever a tunnel tail is setup or torn.

- CSCuo95313

Symptom: Duplicate cookies are observed in every access request.

Conditions: This symptom occurs when multilogon or logoff is performed on the same session.

Workaround: Tear down the session during the logoff event. Do not configure any delay on the account logoff event.

- CSCuo96504
 

Symptom: A FlexVPN client router may report alignment errors and experience high cpu utilization in IKEv2 FlexVPN process.

Conditions: The tunnel interface in use with the FlexVPN client configuration must flap while the client is processing an IKEv2 redirect. The high cpu utilization is seen only if the client is configured to auto connect.

Workaround: Remove and reconfigure the IKEv2 client configuration block.
- CSCuo97889
 

Symptom: IPv4 and IPv6 traffic will be dropped after performing an SSO.

Conditions: This symptom occurs when you perform an SSO with ISIS as NSR configured, and MPLS-TE as GR configured.

Workaround: Change ISIS to non-NSR.
- CSCuo98907
 

Symptom: Platform-specific images do not build.

Conditions: This symptom occurs when any platform-specific image is built.

Workaround: This issue is fixed.
- CSCup00882
 

Symptom: A router running Cisco IOS experiences an unexpected reload after removing OSPF IPFRR or OSPF Remote LFA from the configuration.

Conditions: This symptom occurs when the router was configured for OSPF IPFRR and, possibly, OSPF Remote LFA and IPFRR and (or) rLFA configuration commands are being removed at the same time when IPFRR SPF is running on the router.

Workaround: There is no workaround.

More Info: This symptom occurs if IPFRR SPF is running at the time the configuration is being removed.
- CSCup01885
 

Symptom: A crash is observed due to a corrupted stack in AAA. This issue was observed on a Cisco ASR 1000 router when an authentication request was sent from IKE (crypto) with a password expiry feature configured.

Conditions: The symptom is seen with the password expiry feature. The configuration needed is:

```
aaa authentication login <method> passwd-expiry group <radius/tacacs>
```

Workaround: Remove the configuration.

More Info: With “aaa authentication login userauthen passwd-expiry group radius” configured, over a period of time, there is AAA stack corruption because of a value read from a wrong offset in the memory. It is not specific to any platform.
- CSCup08772
 

Symptom: A Cisco device hangs.

Conditions: This symptom occurs after a save and reload with intent configured.

Workaround: There is no workaround.

More Info:

  1. Configure registrar.



2. Configure intent.
3. Save and reload the device.

- CSCup09007

Symptom: When a CEM interface is configured, the router crashes when it is unconfigured without logging out of the CEM configuration mode.

Conditions: This symptom occurs when a CEM interface is configured and unconfigured.

Workaround: Exit from the submode before performing **no xconnect**.

- CSCup10447

Symptom: When an Any Transport over MPLS (AToM) xconnect is configured on a dual-RP system, memory leaks may be observed on the standby RP.

```
router-stby#sh memory debug leaks chunks Adding blocks for GD...
kernel memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name
lsmpi_io memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name
Processor memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name NA 3DDDFCB4 180 3DDD06C0 (AToM VC binding) NA
3DDDFE24 180 3DDD06C0 (AToM VC binding) NA 3DDDF94 180 3DDD06C0 (AToM VC binding) NA
3DDE0104 180 3DDD06C0 (AToM VC binding) NA 3DDE0274 180 3DDD06C0 (AToM VC binding) NA
3DDE03E4 180 3DDD06C0 (AToM VC binding) NA 3DDE0554 180 3DDD06C0 (AToM VC binding)
```

Conditions: This symptom is observed when a label advertisement is received from the peer and checkpointed to the standby RP.

Workaround: There is no workaround.

- CSCup21524

Symptom: A crash is observed with the following error messages:

```
Exception to Fastpath Thread: Frame pointer 0x7FEA1735D570, PC = 0x7FEB1F732559
-Traceback= 1#bb8f9a461a7850b52eeefb2d5dc713d87 c:7FEB1F701000+31559
c:7FEB1F701000+32A09 :400000+442C515 :400000+4430C38 iosd_unix:7FEB1FED3000+1B0B6
:400000+6D46665 :400000+7AD419 :400000+2534AFB :400000+4422F8B :400000+70D1E1F
:400000+7117396 :400000+71154E6 :400000+6D6801F :400000+6D6787F :400000+4417B48
:400000+441AE07
IOS Thread backtrace: UNIX-EXT-SIGNAL: User defined signal 2(12), Process = SSM
connection manager -Traceback= 1#bb8f9a461a7850b52eeefb2d5dc713d87
pthread:7FEB1D279000+83BF
Auxiliary Thread backtrace: -Traceback= 1#bb8f9a461a7850b52eeefb2d5dc713d87
pthread:7FEB1D279000+A7C9
```

Conditions: This symptom occurs after a switchover from the active RP to the standby RP and the device has 1000 PPPoA sessions. Call Admission Control (CAC) is also configured.

Workaround: Remove CAC configurations. For example:

```
call admission new-model call admission limit 1000 call admission cpu-limit 80
```

- CSCup23792

Symptom: A loss of service-group configuration under a subinterface is observed.

Conditions: This symptom occurs only when the router is reloaded. It is not seen with a particular LC reload where the interface exists.

Workaround: There is no workaround.

- CSCup33759

Symptom: ISIS IPv6 distribute-list filters of the form:

```
router isis address-family ipv6 distribute-list prefix-list { name } in { interface }
```

should be removed from the configuration when the specified interface is deleted or is no longer enabled for IPv6. In some cases this is not happening, which can cause errors when a saved configuration is used during a subsequent reboot.

On systems with a redundant RP, configuration sync will fail because the distribute-list command will be rejected by the standby RP.

Conditions: This symptom is observed when using ISIS to route IPv6 traffic.

Workaround: Ensure that IPv6 is enabled on any interfaces referenced by ISIS IPv6 distribute-list commands. This can be accomplished either by configuring one or more IPv6 addresses on the interface, or by using the command “ipv6 enable”.

- CSCup39674

Symptom: A traceback is observed consistently during a cleanup.

Conditions: This symptom occurs when MPLS-TP tunnels are configured and unconfigured.

Workaround: There is no workaround.

- CSCup47507

Symptom: In Cisco IOS Release 15.4(3)S or Cisco IOS XE Release 3.13S, the ISIS **summary-address** and **summary-prefix** commands are not synchronized to the standby RP.

Conditions: The symptom is seen on a router with redundant RPs.

Workaround: There is no workaround.

- CSCup49636

Symptom: Estimated Channel Egress Bandwidth gets accounted incorrectly with fast-monitor enabled per DSCP.

For example, with monitor-interval as 1s, all TCs on SP1, Total TC BW: 18Mbps, then Estimated Channel BW: 540Mbps;

Conditions: This symptom occurs when fast-monitor gets enabled for a specific DSCP channel.

Workaround: There is no workaround.



# Bugs for Cisco IOS Release 15.4(2)S

---

## Open and Resolved Bugs

The open and resolved bugs for this release are accessible through the [Cisco Bug Search Tool](#). This web-based tool provides you with access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in this product and other Cisco hardware and software products.

Within the Cisco Bug Search Tool, each bug is given a unique identifier (ID) with a pattern of CSCxxNNNNN, where x is any letter (a-z) and N is any number (0-9). The bug IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices and other Cisco support documents. Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific bug.

You can save searches that you perform frequently. You can also bookmark the URL for a search and email the URL for those search results



### Note

---

If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.

---

This section consists of the following subsections:

- [Using the Bug Search Tool, page 92](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(2\)S4, page 93](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(2\)S3, page 93](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(2\)S2, page 94](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(2\)S1, page 95](#)
- [Open Bugs—Cisco IOS Release 15.4\(2\)S, page 118](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(2\)S, page 119](#)
- [Open and Resolved Bugs - Cisco ASR 901 Series Routers in 15.4\(2\)S, page 139](#)
- [Open and Resolved Bugs - Cisco ASR 901 S Series Routers in 15.4\(2\)S, page 139](#)
- [Open and Resolved Bugs - Cisco ME 3600x and ME 3800x Series Routers in 15.4\(2\)S, page 139](#)



## Using the Bug Search Tool

The Cisco Bug Search Tool enables you to filter the bugs so that you only see those in which you are interested. In addition to being able to search for a specific bug ID, or for all bugs in a product and release, you can filter the open and/or resolved bugs by one or more of the following criteria:

- Last modified date
- Status, such as fixed (resolved) or open
- Severity
- Support cases

For more information about how to use the Cisco Bug Search Tool, including how to set email alerts for bugs and to save bugs and searches, see [Bug Search Tool Help & FAQ](#).



### Note

You must have a Cisco.com account to log in and access the Cisco Bug Search Tool. If you do not have one, you can [register for an account](#).

To use the Cisco Bug Search Tool:

1. In your browser, navigate to the [Cisco Bug Search Tool](#).
2. If you are redirected to a **Log In** page, enter your registered Cisco.com username and password and then, click **Log In**.
3. To search for a specific bug, enter the bug ID in the **Search For** field and press Enter.
4. To search for bugs related to a specific software release, do the following:
  - a. In the **Product** field, choose **Series/Model** from the drop-down list and then enter the product name in the text field. If you begin to type the product name, the Cisco Bug Search Tool provides you with a drop-down list of the top ten matches. If you do not see this product listed, continue typing to narrow the search results.
  - b. In the Releases field, enter the release for which you want to see bugs.

The Cisco Bug Search Tool displays a preview of the results of your search below your search criteria. You can mouse over bugs to see more content about a specific bug.

5. To see more content about a specific bug, you can do the following:
  - Mouse over a bug in the preview to display a pop-up with more information about that bug.
  - Click on the hyperlinked bug headline to open a page with the detailed bug information.
6. To restrict the results of a search, choose from one or more of the following filters:

Filter	Description
Modified Date	A predefined date range, such as last week or last six months.
Status	A specific type of bug, such as open or fixed.
Severity	The bug severity level as defined by Cisco. For definitions of the bug severity levels, see <a href="#">Bug Search Tool Help &amp; FAQ</a>
Rating	The rating assigned to the bug by users of the Cisco Bug Search Tool.
Support Cases	Whether a support case has been opened or not.

Your search results update when you choose a filter.

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#) through the [fixed bug search](#).

This search uses the following search criteria and filters:

Field Name	Information
Product	Series/Model Cisco IOS and NX-OS Software => Cisco IOS
Release	15.4(2)S2
Status	Fixed
Severity	2 or higher

## Resolved Bugs—Cisco IOS Release 15.4(2)S4

*Table 1 Resolved Bugs—Cisco IOS Release 15.4(2)S4*

Identifier	Description
<a href="#">CSCuu93699</a>	Crash on IKEv2 cluster hub when anyconnect client tries reconnect
<a href="#">CSCuq46955</a>	IOS ISR AM IKEv1 doesnt work with rsa-sig
<a href="#">CSCus19794</a>	Cisco IOS and IOS XE IPv6 SEND Denial of Service Vulnerability
<a href="#">CSCuu82607</a>	Evaluation of all for OpenSSL June 2015
<a href="#">CSCuq74492</a>	IOS/IOSd Multiple Vulnerabilities in OpenSSL - August 2014
<a href="#">CSCus61884</a>	JANUARY 2015 OpenSSL Vulnerabilities
<a href="#">CSCut46130</a>	MARCH 2015 OpenSSL Vulnerabilities

## Resolved Bugs—Cisco IOS Release 15.4(2)S3

*Table 2 Resolved Bugs—Cisco IOS Release 15.4(2)S3*

Identifier	Description
<a href="#">CSCug18580</a>	ASR1k crash: UNIX-EXT-SIGNAL SEGFault, Process = AAA ACCT Proc
<a href="#">CSCur51387</a>	NG3K stack: standby gets reloaded due to reason "configuration mismatch"
<a href="#">CSCur27466</a>	WebUI in IOS-XE : evaluation of SSLv3 POODLE vulnerability
<a href="#">CSCup62315</a>	Autonomic Networking Infrastructure Device Reload DoS Vulnerability
<a href="#">CSCup62191</a>	Autonomic Networking Registration Authority Spoofing Vulnerability
<a href="#">CSCuq35209</a>	BGP advertising incorrect Link Local ipv6 address
<a href="#">CSCuq83441</a>	BGP L2VPN uses default static next-hop instead of outgoing intf-addr
<a href="#">CSCuq99797</a>	BGP Route-Target not advertised when rfilter address family in use
<a href="#">CSCuq13985</a>	BGP Router process crash due to received BGP withdraw
<a href="#">CSCur66140</a>	Import of Global routes to VRF will fail
<a href="#">CSCuq24984</a>	In rare high BGP update churn case, sh ip bgp x.x.x.x may crash

Identifier	Description
<a href="#">CSCun68322</a>	Support BGP GR for VPN AF in platform without MPLS
<a href="#">CSCuo66933</a>	Switch sent Failure packet after reboot and caused PC to fail authen
<a href="#">CSCus57583</a>	ASR 1K BGP Process Crash Due to EIGRP Route Redistribution
<a href="#">CSCur13495</a>	Service-data of a service change is not updated by SAF forwarder
<a href="#">CSCuq93406</a>	IOSd crash on Ethernet CFM receiving a malformed CFM frame
<a href="#">CSCur43251</a>	POODLE protocol-side fix: HTTPS Client
<a href="#">CSCuo84660</a>	copy command yields DATACORRUPTION error
<a href="#">CSCuq96691</a>	Utah crash during ezconfig installation.
<a href="#">CSCuq17828</a>	ASR: Radius Accounting fails when using EDCSA certs
<a href="#">CSCum90471</a>	ASR1k: Ping failure b/w CE1 & CE3 after Switchover.
<a href="#">CSCus48386</a>	POODLE related fix : LDAPv3 client REQUIRED to support TLS
<a href="#">CSCur36464</a>	mVPN: Inter-AS Option B: Different RDs: proxy vector: local RD is picked
<a href="#">CSCur09682</a>	Router crashes in PIM due to infinite recursion at ip_set_mdb_flag
<a href="#">CSCuq57261</a>	cBR-8 SUP HA Long M-BGP and LDP Resync Delay
<a href="#">CSCur92862</a>	TE leaks memory when restarting isis
<a href="#">CSCul73513</a>	Clock is not matching between server-client after leap configuration
<a href="#">CSCuo29389</a>	NTP clients of 3900 loses sync sporadically,due to high offsetvariations
<a href="#">CSCun62014</a>	Router crash with %SYS-3-BADFREETRS after reconfiguring pppoe
<a href="#">CSCut14355</a>	GETVPN - IOS-XE using SW-TCAM - Deny policy classification incorrect
<a href="#">CSCus95855</a>	ISR4451 FMAN-FP Crash
<a href="#">CSCus01735</a>	cbQosTSCfgRate64 is not supported on ASR1k/IOSXE
<a href="#">CSCum87411</a>	software install from tftp get failed fts_client issue
<a href="#">CSCuq41114</a>	ENH: SSH configuration option to restrict cipher public key and HMAC
<a href="#">CSCur23656</a>	Cisco IOS and IOSd in IOS-XE : evaluation of SSLv3 POODLE vulnerability
<a href="#">CSCur44075</a>	AC ICE+ ver <= 4.0 Client unable to connect to XE SSL Headend {CSR1K}
<a href="#">CSCup86552</a>	Issue with qos service installation
<a href="#">CSCuh92882</a>	XE3.11 Seginfo->l2hw_cond_debug is set to "1" when there is no condition
<a href="#">CSCup52725</a>	XE3.13: asr1k RP Crash while 72 hour longevity run
<a href="#">CSCum94811</a>	TCP Packet Memory Leak Vulnerability
<a href="#">CSCup41482</a>	TCP snd window stuck with CEF enabled
<a href="#">CSCuh09324</a>	udp entries not deleted from flowmgr table
<a href="#">CSCus47361</a>	DSMP statistic request timeout cause 4 more seconds to disconnect

## Resolved Bugs—Cisco IOS Release 15.4(2)S2

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#) through the [fixed bug search](#).

## Resolved Bugs—Cisco IOS Release 15.4(2)S1

- CSCee32792  
Symptom: A Cisco router reloads at `snmp_free_variable_element` while using SNMPv3 commands.  
Conditions: This symptom occurs while using SNMPv3 commands.  
Workaround: There is no workaround.
- CSCtz45833  
Symptom: A Cisco router crashes with the following message:  

```
Router crash: UNIX-EXT-SIGNAL: Segmentation fault(11), Process = MPLS TE LM
```

  
Conditions: This symptom occurs when a router acts as the mid point for MPLS-TE tunnels and performs an ERO expansion. In case the ERO expansion fails (due to IGP race conditions or inter-AS scenario) and backup tunnels are in use (for MPLS-TE FRR feature), the router may crash.  
Workaround: Configure the head-ends to perform a full ERO computation to avoid mid points performing any ERO expansion. This can be done using the dynamic path option or by using the explicit path that specifies strict hops for each node along the desired LSP path (using “loose” hops or partial strict hops can lead to this issue).
- CSCuc60868  
Symptom: A router randomly crashes either due to memory corruption at `bgp_timer_wheel` or memory chunks near `bgp_timer_wheel` (For example, BFD event chunks if BFD is configured or AtOM Manager chunks if LDP is configured). A crash occurs right after an LDP neighbor is up in the L2VPN setup.  
Conditions: This symptom occurs when **vpls bgp signaling** is unconfigured and then reconfigured. Both L2VPN and BGP are unconfigured and reconfigured after all L2VPN and BGP data structures are fully deleted (about 3 minutes for 5 BGP VPLS prefixes). For the repro on file, OSPF (for IGP) is also unconfigured and reconfigured. Both LDP and BGP signaling are affected by this bug.  
Workaround: Avoid unconfiguring and reconfiguring BGP L2VPN.
- CSCue23898  
Symptom: A Cisco router running Cisco IOS Release 15.3(1)T may crash with a bus error immediately after issuing the **write memory** command.  

```
Example: 14:44:33 CST Thu Feb 14 2013: TLB (load or instruction fetch) exception, CPU signal 10, PC = 0x228B2C70
```

  
Conditions: This symptom occurs while updating the router’s running configuration with the **write memory** command. It has been seen while updating various different commands such as, those under “call-manager-fallback” ip route statements interface sub-commands.  
Workaround: There is no workaround.
- CSCug17485  
Symptom: A buffer leak is observed on a Cisco router.  
Conditions: This symptom occurs while using SSLVPN.  
Workaround: There is no workaround.
- CSCug45421  
Symptom: The standby RP crashes.

Conditions: Memory corruption occurs in certain cases when the following commands are executed in quick succession. It leads to a crash later when the memory is accessed. The issue is seen only with on-demand PVCs and when the commands are copied and pasted or executed using a script or tool.

```
configure terminal
interface ATM0/0/0.2 multipoint
range pvc 11/41 11/51
create on-demand
/* Prob commands begin */
pvc-in-range 11/45
exit
no pvc-in-range 11/45
/* Prob commands end */
end
```

Workaround: Do not execute the commands in quick succession.

- CSCuh09324

Symptom: UDP based entries are not deleted from the flowmgr table resulting in crash, or poor system response, with CPU hog messages being shown.

Conditions: This symptom occurs in the following images

- ct5760-ipservicesk9.bin
- cat3k\_caa-universalk9.bin
- cat4500e-universalk9.bin

The device is configured with UDP services that originate from the device. This includes but not limited to the following features:

- TFTP
- Energy Wise
- DNS
- Cisco TrustSec

Workaround: If you suspect that you are affected by this bug, please do the following, for confirmation:

```
Router#config terminal
service internal
end
Router#show flowmgr
```

The output of this command will show many lines entries holding with the same port numbers. Disabling the feature that is being held in the flows until an upgrade can be performed, is a workaround.

A reload is required to clear the held flows.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5.4/4.5:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:H/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2013-6704 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-6704>



Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCui05000

Symptom: A Cisco router may crash upon importing a prefix into VRF after applying **no ipv4 multicast multitopology** under "vrf definition" for that VRF.

Conditions: This symptom occurs while initially configuring the VRF. **address-family ipv4/6 multicast vrf** must be configured under "router bgp" mode before import route-targets are configured under "vrf definition" mode.

Workaround: There is no workaround.

More Info: If the crash does not occur, it is likely that importing of the prefix will not work.

- CSCui29745

Symptom: Member links under MLPPP go down as the LCP negotiation of those PPP links fails.

Conditions: This symptom occurs after the router reloads and the traffic is flowing through the multilink.

Workaround: Reload SPA/LC on the other end of the link.

- CSCui34165

Symptom: Port-channel QoS features might fail to work after a router reload, followed by QoS configuration modification.

Conditions: This symptom occurs when a vlan load-balanced port-channel is used with policy aggregation configuration where the QoS policy is configured on member links and the port-channel sub-interface, and after a system reload (configuration is from startup configuration).

Workaround: Reload the router without port-channel QoS configuration, and add port-channel QoS configuration to the running configuration after the router boots up.

- CSCui59984

Symptom: REP FLAPs with low LSL timers with the following scale:

1. Scale of MAC address OR
2. Scale of Bridge-domain OR
3. Repeated/multiple REP topology changes OR
4. CPU-intensive activities.

Conditions: This symptom occurs with REP configured with low LSL age timer with scale of configuration or any CPU-intensive activities.

Workaround: Use default LSL timers.

- CSCui64807

Symptom: An active RP crashes during FIB sync because of memory overrun when the standby sup becomes unavailable.

Conditions: This symptom occurs when redundant RPs are configured in SSO mode and the standby RP becomes unavailable (for instance because of crash or physical removal). The issue occurs only on Cisco 7600 RSP 720, Cisco 7600 Series Supervisor Engine 720, and Cisco 7600 platforms where the tableid "ISSU FOF LC" support is enabled. As of 03/17/2014, the tableid "ISSI FOF LC" feature is only supported on SY releases. This issue does not impact Cisco ASR 1000 Series platforms.

Workaround: There is no workaround.

- CSCul22914

Symptom: A Cisco router does not give the necessary failure information if the crypto NIST/KAT tests on boot fail. During test failures, users will not be notified. The logs do not contain information on the failures.

Conditions: This symptom occurs with a crypto NIST/KAT self test. The message below is a generic message and is not specific to a crypto self test failure.

```
*Nov 5 17:48:19.128: %CMRP-3-CHASSIS_MONITOR_READY_TIME_EXCEEDED: cmand: Reloading F0
because it has failed to become ready for packet processing
```

This message does not give enough information for the user to take a proper course of action.

Workaround: There is no workaround.

More Info: A failure in one of the POST Known Answer Test (KAT) test during boot-up triggers this issue. The issue will not occur if all the KAT tests are passes.

- CSCul24443

Symptom: A Cisco router crashes while scaling service instances to 3600 whenever the memory is utilized fully and it throws an error as there is no memory to display the output of the **show running** command.

Conditions: This symptom occurs when the service instance is scaled to 3600.

Workaround: Reload the router.

- CSCul27924

Symptom: Customer experienced crash on ASR-1001 during normal operation.

Conditions: This symptom is not observed under any specific condition.

Workaround: There is no workaround.

- CSCul29918

Symptom: A vulnerability in IPsec tunnel implementation of Cisco IOS Software could allow an unauthenticated, remote attacker to change the tunnel MTU or path MTU and potentially cause IPsec tunnel to drop.

The vulnerability is due to incorrect processing of certain ICMP packets. An attacker could exploit this vulnerability by sending specific ICMP packets to an affected device in order to change the configured MTU value of the tunnel interface. An exploit could allow the attacker to change the tunnel MTU or path MTU and potentially cause IPsec tunnel to drop.

Conditions: This symptom occurs on a device configured for IPsec VTI and with path-mtu-discovery disabled.

Workaround: The issue is caused by ICMP unreachable. Blocking ICMP is a workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/4.1:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:U/RC:C>

CVE ID CVE-2013-6694 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-6694>

Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCul39964

Symptom: Sessions do not get cleared. They get stuck in WT\_ST state.

Conditions: This symptom occurs when sessions are closed in bulk mode by shutting any trunk link or during a clear all session from DUT.

Workaround: There is no workaround.

More Info: The memory leak issue and WT\_ST are related. Along with memory leak, sessions are not cleared on the active RP as they get stuck in WT\_ST state.

```

asrlk-1#sh clock
07:18:07.045 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:20:08.295 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:46:34.113 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#s
6557 sessions in FORWARDED (FWDED) State
7908 sessions in WAITING_FOR_STATS (WT_ST) State
14465 sessions totalUniq ID PPPoE RemMAC Port VT
VA State
SID LocMAC VA-st Type
5978 5978 0000.6ca3.0116 Gi0/0/0.2940148 1 Vi2.3091 WT_ST
b414.8901.8e00 VLAN: 294/148 UP
5979 5979 0000.6ca3.0117 Gi0/0/0.2940149 1 Vi2.3092 WT_ST
b414.8901.8e00 VLAN: 294/149 UP
6460 6514 0000.6ca3.0134 Gi0/0/0.2940178 1 Vi2.3354 WT_ST

```

```

b414.8901.8e00 VLAN: 294/178 UP
6454 6508 0000.6ca3.0135 Gi0/0/0.2940179 1 Vi2.3350 WT_ST
b414.8901.8e00 VLAN: 294/179 UP
6453 6507 0000.6ca3.0136 Gi0/0/0.2940180 1 Vi2.3349 WT_ST
b414.8901.8e00 VLAN: 294/180 UP
6518 6572 0000.6ca3.0137 Gi0/0/0.2940181 1 Vi2.3395 WT_ST
b414.8901.8e00 VLAN: 294/181 UP
6514 6568 0000.6ca3.0138 Gi0/0/0.2940182 1 Vi2.3393 WT_ST
b414.8901.8e00 VLAN: 294/182 UP
6516 6570 0000.6ca3.0139 Gi0/0/0.2940183 1 Vi2.3394 WT_ST
b414.8901.8e00 VLAN: 294/183 UP
6560 6614 0000.6ca3.013a Gi0/0/0.2940184 1 Vi2.3413 WT_ST

```

- CSCul49375

Symptom: The Cisco ASR 1000 router displays the following messages in the logs:

```

%IDMGR-3-INVALID_ID: bad id in id_get (Out of IDs!) (id: 0x0) -Traceback=
1#cb40dca901558e45a65b881a8695af4f :400000+8653B3 :400000+893696 :400000+DF330C
:400000+DED89B :400000+DF8643 :400000+1F57F36 :400000+1F4BBFB :400000+1F33BA7
:400000+1F336C1 :400000+1F34FF9 :400000+1F27763 :400000+1F29B16 :400000+2546FF3
:400000+2546EDD :400000+1F2930B

```

No new PPPoE sessions can be established anymore.

Conditions: The conditions to this symptom are unknown.

Workaround: Reload the device.

- CSCul94606

Symptom: Standby CUBE crashes while handling an agent transfer.

Conditions: This symptom is observed when an agent transfers the call to another agent.

Workaround: There is no workaround.

- CSCum09990

Symptom: Basic mgcp t38-fax call fails between T1/cas endpoints as call not getting confirmed at terminating end.

Conditions: This symptom occurs on Cisco 2900 routers which have been booted with Cisco IOS Release 15.4(1.14)T images.

Workaround: There is no workaround.

- CSCum14830

Symptom: Leaking IPv6 routes is observed from a VRF table into the global table using BGP. These routes consist of the following:

1. BGP routes learned from the VRF IPv6 BGP peer.
2. Redistributed static and connected routes.

The BGP routes leak fine, but the redistributed static and connected routes have an issue. After the redistributed routes leak, the exit interface shows “null0”. Sometimes instead of showing the exit interface as “null0”, it shows a random interface which is a part of VRF and has IPv6 enabled on it.

Conditions: This symptom occurs with IPv6 redistributed connected and static routes into BGP VRF (could also be redistributed from other protocols as well but have not been tested).

Workaround: There is no workaround.

- CSCum20647

Symptom: A traceback is seen in fn\_resiliency\_phase2 Script Cisco XE3.12/PI24 Release.

Conditions: A traceback is seen in fn\_resiliency\_phase2 Script Cisco XE3.12/PI24 Release. Functionality test is going fine but test fail when routers health check is done during cleanup.

Workaround: There is no workaround.

More Info: The issue seen only when GETVPN group is removed.

- CSCum33167

Symptom: When PPPoE-IA is enabled, a Cisco switch forwards PADR/PADT packets to an untrusted port.

Conditions: This symptoms occurs under the following conditions:

- Configure PPPoE IA globally on node 1.
- Configure service instance on interface gig0/1,gig 0/2 and gig 0/3.
- Configure PPPoE IA on the interface and on the service instance.
- Configure gig 0/1 and gig 0/3 as an untrusted port and gig 0/2 as a trusted port.
- Send a PADI Packet from client 1 and send a PADO packet from the server.

The PADO packet is received on client 2, but it should be received only on client 1. Send a PADR packet from client 1, client 2 also receives the packet. But it should not receive the packet. The PADR/PADT packet should be forwarded only to a trusted port.

Workaround: There is no workaround.

- CSCum40306

Symptom: A Cisco router crashes during call transfer in SRST mode.

Conditions: This symptom is observed during call transfer in SRST mode, including SCCP phones.

Workaround: There is no workaround.

- CSCum48221

Symptom: 3560CG box memory is showing as low as 3.15MB.

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.

- CSCum52216

Symptom: After a reload, **ip pim sparse-mode** is gone on interface lisp 0.x (x denoted the LSIP interface number).

Conditions: This symptom occurs after a reload.

Workaround: There is no workaround.

- CSCum60848

Symptom: Under certain conditions, a DSP will hang in certain call scenarios including REFER passthrough.

Conditions: This symptom is observed under heavy load.

Workaround: There is no workaround.

- CSCum61595

Symptom: Alignment errors are observed after upgrading to Cisco IOS Release 15.2(4)M5.

```
Jan 9 19:42:59.623 GMT: %ALIGN-3-CORRECT: Alignment correction made at 0x6477F81Cz
reading 0x6BE87495 Jan 9 19:42:59.623 GMT: %ALIGN-3-TRACE: -Traceback= 0x6477F81Cz
0x647805D0z 0x6478FE70z 0x64751088z 0x64B99F4Cz 0x64B99FD4z 0x64752 284z 0x647525ACz
```

Conditions: This symptom does not occur under specific conditions.

Workaround: There is no workaround.

- CSCum62783

Symptom: The following alignment errors are seen after a PPPoE session establishment for the first time after a reboot:

```
*Jan 14 07:24:40.591: %ALIGN-3-CORRECT: Alignment correction made at 0x32B2DFF4z
reading 0xE7790ED *Jan 14 07:24:40.591: %ALIGN-3-TRACE: -Traceback= 0x32B2DFF4z
0x32B1E274z 0x32B1EECCz 0x32B1EF90z 0x332E550Cz 0x332E54F0z 0xFFFF1A00z 0xFFFF1A00z
```

Conditions: This symptom occurs when **pppoe-client ppp-max-payload** is configured under the Ethernet interface.

Workaround: There is no workaround.

- CSCum66102

Symptom: A Cisco router may crash when the CLI **ip nbar custom <name> <byte-offset> ascii <pattern> tcp <port>** is used. The crash occurs only when the ascii flavor of the **ip nbar custom** command is used.

Conditions: This symptom is not observed under any specific conditions. It occurs on all types of ASR and ISR-G2 routers as well as on 7200.

Workaround: Avoid using the ascii flavor of the **ip nbar custom** command (Example: **ip nbar custom <name> <byte-offset> ascii**)

- CSCum67229

Symptom: Entitymib does not respond for OC3/OC12/T3/E3 controller ports on the Cisco ME3600x-24CX-M platform.

Conditions: This symptom occurs with the Cisco ME 3600X-24CX-M platform running Cisco IOS XE Release 3.10.

Workaround: There is no workaround.

- CSCum81041

Symptom: One way audio incoming calls redirected through CVP.

Conditions: Call flow: -----

```
Caller---G711---TDM GW---SIP---ASR1K---SIP---CUSP---SIP---CVP (Vz0)---IP-IVR
| | ---SIP---CVP (BAMS) | |-----SIP---CUCM---Agent Phone (G729 only)
```

Initially the caller is connected to IP-IVR, both ingress and egress leg of the CUBE is doing G711. Call is connected to the IP-IVR, then CVP sends a refer to the VXML GW for playing prompts and ringback tone etc. When the call is transferred to the agent, CUBE negotiated G729 at the sip level with the CVP, but because of mid-call signaling block on the ingress side, continue with the G711. Hence xcoder is invoked on the CUBE to handle G729 to G711 and vice versa, but CUBE is still sending G711 media to the agent phone side while the agent phone is sending G729 media to the CUBE.

Workaround: There is no workaround.

- CSCum84999

Symptom: SUBSCRIBE received from CVP after BYE and NOTIFY with subscription-state : terminates is send by CUBE.

Conditions: This symptom is observed when SUBSCRIBE IS received after call is terminated with BYE.

- Workaround: There is no workaround.
- CSCum85493
 

Symptom: Ping fails with tunnel protection applied.

Conditions: Tunnel protection applied on GRE tunnel interface, using IKEv1 to negotiate IPsec SAs and remote node (IKEv1 responder) behind NAT.

Workaround: The users can switch to IKEv2.
  - CSCum85813
 

Symptom: Shut primary static router and secondary static is not installed automatically.

Conditions: This symptom is seen on the sites where the BFD state of the backup static route is marked as “U” in the output of **show ip static route bfd**.

Workaround: Reinstall the default backup static route.
  - CSCum94228
 

Symptom: Local CAC displaying all information about each flows. This may impact show output for customer in a set up where we could possibly have large number of flows.

Conditions: This symptom is observed in a scaled configuration.

Workaround: There is no workaround.
  - CSCum95078
 

Symptom: Large IPSEC packets get dropped when fragmentation is done after IPSEC encapsulation.

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.
  - CSCum95330
 

Symptom: Removing an Ethernet service instance which is a member of a bridge domain may cause the router to reload.

Conditions: This symptom is observed when the last service instance is removed from the bridge domain and there are still members of the bridge domain which are not service instances (such as VFIs).

Workaround: Completely unconfigure the bridge domain and reconfigure it.
  - CSCun02605
 

Symptom: ASR crashes with no known trigger in CCSIP\_SPI\_CONTROL process.

Conditions: It is an error scenario where crash occurs when router is not able to send ACK for 200 OK where branch parameters differ.

```
CUBE INVITE | INVITE (Via branch=ABC) ----->|
-----> | 200 OK (Via branch=DEF) |
<----- |
```

Cube fails to send ACK to 200 OK for some reason and causes a crash

Workaround: There is no workaround.
  - CSCun07843
 

Symptom: A critical alarm is observed on the FPGA port 0/5/0.

Conditions: This symptom occurs after performing an SSO.

Workaround: There is no workaround.

- CSCun10381
 

Symptom: A traffic drop was observed because labels do not get programmed.

Conditions: This symptom occurs when scalable EoMPLS with L3VPN is configured. When notifications on atom-imps arrive, they have to get programmed.

Workaround: Clear ip route.

More Info: Traffic was seen to be dropped as the atom-imps could not be programmed because label entry could not be found for the atom-imps.
- CSCun11782
 

Symptom: Rtfiler prefixes are sent with incorrect next-hop equal to next-hop of the default static route in GRT instead of BGP router-id.

Conditions: This symptom occurs with a default static route present in GRT pointing, for example, to the next-hop known behind the connected interface.

Workaround: Replace the default static route with a more specific static route or remove static and clear BGP.
- CSCun13688
 

Symptom: The Cisco Catalyst 6500 Supervisor Engine 2T with CLNS routing configured crashes after **show clnbs route**.

Conditions: This symptom occurs when CLNS routing is configured.

Workaround: There is no workaround.
- CSCun20187
 

Symptom: HSRP communication fails between two PEs (Cisco 7600 Series router) right after removing a neighbor from VFI.

Conditions: Assume that a VPLS circuit is running between more than two PEs say A,B, and C and HSRP is running between A and B. Removing VPLS peer C on either A or B would cause HSRP communication failure between A and B. This failure is not expected as data path is still available between A and B.

Workaround: Perform shut/no shut on the SVI.
- CSCun21602
 

Symptom: Traffic is not forwarded by the router out of any interface.

Conditions: This symptom occurs on toggling of the **ip routing** command in global configuration mode.

Workaround: Perform shut and no shut of the interface which is involved in forwarding or reload the device with **ip routing** enabled.
- CSCun31021
 

Symptom: A vulnerability in IKE module of Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to affect already established Security Associations (SA)..

The vulnerability is due to a wrong handling of rogue IKE Main Mode packets. An attacker could exploit this vulnerability by sending a crafted Main Mode packet to an affected device. An exploit could allow the attacker to cause dropping of valid, established IKE Security Associations on an affected device.

Conditions: This symptom occurs on a device configured to process IKE request that already has a number of established security associations.

Workaround: There is no workaround.



PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C>

CVE ID CVE-2014-2143 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-2143>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun31359

Symptom: Memory corruption crash while processing the sip-profile rule.

Conditions: This symptom occurs on a Cisco 3900 device running Cisco IOS Release 15.3(1)T.

Workaround: Perform the following workaround:

- Using history-info pass-through feature (voice service voip -> sip -> history-info)
- Using header pass-through feature

- CSCun31450

Symptom: CPU hog followed by crash.

Platforms affected are:

- ct5760-ipservices.bin
- cat3k\_caa-universalk9.bin
- cat4500e-universalk9.bin

Conditions: This issue occurs while running udp IP SLA applications.

Workaround: There is no workaround.

- CSCun35055

Symptom: The RPF is not cleared when the internal VLAN is freed by shutting down an interface with RPF configuration. This affects the new interface assigned with this internal VLAN.

Conditions: This symptom occurs when an interface with RPF configuration is shut down.

Workaround: Flap the RPF configuration for the new interface.

- CSCun35070

Symptom: Targeted LDP sessions between Customer Edge devices will flap every 3 minutes. IGP, Interface LDP between CE devices will run fine.

Conditions: This symptom occurs when an MPLS LDP packet is carried over an L2VPN cloud with the control word OFF.

Workaround: Configure the control word ON in an L2VPN cloud.

- CSCun36655

Symptom: If the terminal adjacency of a lisp interface is removed and then re-added, the lisp interface MTU may remain at the invalid value of 65535. This can be seen in the **show cef interface <intf> internal** command output.

IPsec will obtain the MTU value from CEF and LISP, and the incorrect MTU will cause drops of large packets.

IPSEC MTU incorrectly computed - causing packet drops on large packets traversing from “inside” to “outside” are dropped.

Conditions: This symptom is observed in the following Cisco C800 Series:

Cisco IOS Software, C890 Software (C890-UNIVERSALK9-M), Version 15.3(3)XB12, RELEASE SOFTWARE (fc2)

Workaround: A workaround is to toggle the IP MTU config on the lisp interface. Use “show run lisp0.1” to determine the MTU. Then use “ip mtu <mtu>” to first set it to a lower value, and then to set it back to the original value.

```
Example:
sh run interface lisp0.1
interface LISP0.1
ip mtu 1398
crypto map CM
end

conf t
interface lisp0.1
ip mtu 1200
ip mtu 1398
```

More Info: Originally [Cisco IOS Release 15.3(1)T] the MTU was accurately computed as:

```
RTR13-xTR#sh cry ipse sa vrf DeptA | in mtu
  path mtu 1456, ip mtu 1456, ip mtu idb LISP0.1
  path mtu 1456, ip mtu 1456, ip mtu idb LISP0.1
  path mtu 1456, ipv6 mtu 1456, ipv6 mtu idb LISP0.1
  path mtu 1456, ipv6 mtu 1456, ipv6 mtu idb LISP0.1
RTR13-xTR#
```

In 15.3.XB12, the MTU is as follows:

```
!RTR#show crypto ipsec sa | inc mtu
!      plaintext mtu 65458, path mtu 65535, ip mtu 65535, ip mtu idb LISP0
```

- CSCun36866

Symptom: A Cisco router providing Layer 2 EoMPLS services may stop forwarding ingress and egress traffic for an xconnect for which a backup peer configuration has been applied.

Conditions: This symptom occurs in Cisco 7600 Series routers and Cisco ASR 1000 Series routers running Cisco IOS Release 15.3(3)S or 15.4(02)S with xconnect configured under a service instance.

Workaround: Clear the xconnect on the Cisco 7600 router side. Clearing the remote side does not have an effect.

- CSCun41292

Symptom: On a Cisco ASR 1001 router running Cisco IOS Release 15.3(1)S, a crash occurs when the “show ip ei vrf X topo X.X.X.X/X” command is executed. The X.X.X.X/X must be in “FD is infinity” status in EIGRP as CSCtz01338.

```
asr1001_bew_03# show ip ei vrf * to all |
i Infinity P 174.162.XX.XX/24, 0 successors, FD is Infinity, U, serno 37, refcount 1
snip P 174.180.XX.XX/29, 0 successors, FD is Infinity, U, serno 46, refcount 1
asr1001_bew_03#show ip ei vrf 1 to 174.162.XX.XX/24
Exception to IOS Thread: Frame pointer 0x7F63DF6602D0, PC = 0x1956C8D
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = Exec -Traceback=
1#980611ad3b9665cd80fe5178bcd6036a :400000+1556C8D :400000+1556B09 :400000+15569D1
:400000+157DE39 :400000+15197A2 :400000+1518659 :400000+156BA5E :400000+15591D1
:400000+1189768 :400000+1188E6D :400000+1186E15 :400000+484F270 :400000+11A1CA0
```

```
Fastpath Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
c:7F64154A4000+BE002
Auxiliary Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
pthread:7F640ED43000+A7C9
```

Conditions: This symptom occurs when X.X.X.X/X is in “FD is infinity” status in EIGRP.

Workaround: There is no workaround.

- CSCun45272

Symptom:

1. Standby RP will have out-of-sync entries. With MPLS-TE NSR enabled, the standby RP will have out-of-sync entries which will result in flapping of the path-protected LSP of the tunnel after an SSO.
2. Leaking an LSP. A third LSP will be signaled and leaked (there is no management of the LSP). There are supposed to be two LSPs at steady state (primary and path protected), but with this defect, there will be primary, path protected, and leaked LSP.

Conditions: This symptom occurs with a reoptimization of a tunnel that has failed with path protection enabled.

Workaround: There is no workaround.

- CSCun45299

Symptom: IPv6 traffic is dropped for packets with extension headers.

Conditions: This symptom occurs when extension header packets are punted to the CPU.

Workaround: There is no workaround.

- CSCun46486

Symptom: A Cisco device crashes every 2-3 days when the SNMPSET operation is used to create guest users.

Conditions: This symptom occurs when guest users are created through SNMPSET operations at a very high rate.

Workaround: There is no workaround.

- CSCun47357

Symptom: Enabling PBR breaks the EIGRP multicast.

Conditions: This symptom occurs under the following conditions:

1. Create a route map for any random IP address (not necessarily related to multicast/protocol IP).
2. Enable the PBR on an interface with EIGRP peering. It is observed that the EIGRP peering goes down.

Workaround: There is no workaround.

- CSCun47461

Symptom: A crash occurs on issuing the **no switchport** command on an interface applied with a MAC ACL.

Conditions: This symptom occurs on issuing the **no switchport** command on an interface applied with a MAC ACL.

Workaround: There is no workaround.

- CSCun48344
 

Symptom: A config-sync failure occurs due to the **address-family ipv6 unicast vrf** command during the immediate unconfiguration and reconfiguration of VRF definition.

Conditions: This symptom occurs with attached running configurations.

Workaround: There is no workaround.
- CSCun50243
 

Symptom: When CED/ANSam/2100Hz answer tone is detected in the early media phase of the call, the gateway does not switchover and starts sending distorted audio to the originating fax. Fax transmission fails.

Conditions: This symptom is observed when modem passthrough nse codec g711ulaw is used as the fax protocol.

```
Fax -> VG224 --SCCP--> CUCM -SIP--> 3945 GW--ISDN T1 PRI-->PSTN 3945 IOS: 15.1.1.4M5
VG224:15.1.1.4M2
```

Workaround: Perform the following workaround:

  - Use “progress\_ind” to strip PI=8 if the Early Media is opened via an ISDN ALERTING message: (config-dial-peer)#progress\_ind alert strip
  - Check with Carrier if they can avoid opening early media for Fax/Modem calls.
  - More Info: Early media cut-through for fax/modem calls is not supported. The expected flow transition to the Voice Band Data (VBD) mode or modem up-speed as we commonly call it, requires a VoIP call to be first established (call is connected). It is then, when normally a 2100Hz answer tone is detected as the media flows in both direction and triggers Voice Band Data (VBD) upspeed.
- CSCun58030
 

Symptom: A Cisco ME3600-24CX platform does not display time source information while running the PTP dataset time properties show command. Functional issues are not noticed with PTP time sync. The time source field says “Unknown”.

Conditions: This symptom does not occur under specific conditions. A simple Ordinary Clock(OC) Slave- Master connectivity would make the Slave show up as “Time Source Unknown”.

Workaround: There is no workaround.
- CSCun58224
 

Symptom: A memory corruption is observed on scaling NAT sessions.

Conditions: This symptom occurs due to multiple translation entries of NAT with overload.

Workaround: There is no workaround.
- CSCun62420
 

Symptom: Any ingress policy on an EFP affects other EFPs on the same physical port with local-connect configuration.

Conditions: This symptom occurs when an ingress QoS policy is enabled on an EFP and another EFP of the same port is bound to the other port’s EFP by the “connect” statement.

Workaround:

  1. Apply an ingress policy on all EFPs with a local-connect configuration and detach the policy.
  2. Configure an independent service-policy on the erroneously affected EFPs of the same physical interface.

- CSCun65000  
Symptom: Traffic loss of about 200-500 ms is observed.  
Conditions: This symptom is observed on an RLFA cutover.  
Workaround: There is no workaround.
- CSCun65380  
Symptom: CME Crashed while Inbound SIP profile added globally.  
Conditions: This symptom is observed when inbound SIP profile is added.  
Workaround: Do not configure inbound sip profile.
- CSCun67364  
Symptom: Convergence on Local link failure with rLFA is higher than one second.  
Conditions: Configure rLFA and perform local link failure. The problem is likely seen when configuring a small spf-interval value.  
Workaround: Do not configure too small spf-interval.
- CSCun68723  
Symptom: Incorrect information is present on the E1/T1 ports on the Cisco ME 3600X 24CX platform in the IfTable of IF-MIB.  
The incorrect information includes the following:
  1. ifType of the interface is 0 which is not a valid ifType.
  2. ifAdminStatus value is always testing, and does not reflect the actual state.
  3. ifOperStatus value is always unknown and does not reflect the actual state.
  4. ifSpeed value is 0 which is incorrect.Conditions: This symptom occurs on any Cisco ME 3600X 24CX device running Cisco IOS Release 15.3(3)S.  
Workaround: The correct information on the E1/T1 ports is available in CLI.
- CSCun72459  
Symptom: High traffic loss is observed with setups having BGP and microloop avoidance combination.  
Conditions: This symptom occurs with the following combination:
  1. IP FRR is turned on.
  2. Cisco IOS XE Release 3.11 code (or newer) that enables microloop avoidance by default.
  3. BGP configurations.Workaround: Disable the microloop avoidance feature. For example, in ISIS, execute the following commands:

```
router isis <process name>
microloop avoidance disable
!
```

However, there will be some traffic loss due to the lack of microloop avoidance.
- CSCun72939  
Symptom: QoS Egress Marking does not work for GRE Tunnels.

Conditions: This symptom is observed under the following conditions: -The issue happens for fragmented packet. -The issue is found on Cisco IOS Release 15.3(3)M2.

Workaround: There is no workaround.

- CSCun73782

Symptom:

A vulnerability in LISP control messages processing on Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

The vulnerability is due to insufficient checking of certain parameters in LISP control messages on ITR. An attacker could exploit this vulnerability by sending malformed LISP control messages to ITR. An exploit could allow the attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

Conditions: Malformed messages can only be generated by a device that is already registered to a LISP system: a valid ETR or ALT.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C>

CVE ID CVE-2014-3262 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-3262>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun75719

Symptom: After a switchover, standby device crashes with traceback.

Conditions: At present, this is observed only on advipservices images in mtrose branches.

Workaround: There is no workaround.

- CSCun76733

Symptom: BFD goes down and remains in Admindown state.

Conditions: This symptom occurs after applying ACL chaining and flapping of the interface.

Workaround: There is no workaround.

More Info: An IPv4 BFD neighbor remains in admin down state on the PE. The ACE configured in ACL for BFD is matched and the receive counters on BFD neighbors are incremented but the BFD is still down.

This issue occurs only after ACL chaining is applied.

- CSCun77010

Symptom: A router may crash after or during the execution of the **show ipv6 ospf rib** command.

Conditions: This symptom occurs when many routes or route paths are present in the OSPFv3 rib. The OSPFv3 rib is significantly recomputed during execution of commands.

Workaround: Limit the use of the **show ipv6 ospf rib** command.

- CSCun78309

Symptom: An Mroute entry on FHR is stuck in a registering state in MVPNv4.

`show ip mroute vrf <vpn-name> -->` shows the mroute entry in registering state

Conditions: This symptom occurs when the source address of the encapsulation tunnel for PIM registers on the FHR is one of the interfaces that is not in the same VRF as the register tunnel itself.

Workaround: There is no workaround.

More Info: sample Output:

```
-----
PE2#show ip mroute vrf vpn1
(215.12.1.2, 229.40.1.1), 00:00:29/00:02:30, flags: FT Incoming interface:
GigabitEthernet3/3.1, RPF nbr 0.0.0.0, Registering Outgoing interface list: Tunnel764,
Forward/Sparse, 00:00:29/00:03:00
```

- CSCun81754

Symptom: `snmpEngineBoots` integer does not increment on Cisco ME 3800 and Cisco ME 3600 devices once they are reloaded. They get reinitialized.

Conditions: This symptom occurs only when the device gets rebooted. A warm restart increases the value.

Workaround: There is no workaround.

- CSCun85501

Symptom: IPv6 traffic is not forwarded in the hardware for templates other than default and video (like VPNv4-only, VPNv4-v6). However, IPv4 traffic works fine.

Conditions: This symptom occurs when the template is not default or not video

Workaround: There is no workaround.

Further Problem Description: IPv6 traffic is punted to the CPU.

- CSCun87557

Symptom: A Cisco router crashes.

Conditions: This symptom occurs when the VTY Service Set maximum response is set to a small number, for example, 10, and then multiple commands are sent separated by a newline using the same write, for example, “`show ver\nshow ver\n`”.

Workaround: Set the maximum response to a bigger number.

- CSCun91720

Symptom: IPv6 mcast traffic is punted to the host queue (`in3idc_vlan.bridgeBasedMcastIp=1`).

Conditions: This symptom occurs on a Layer 2 device with no multicast configurations.

Workaround: There is no workaround.

More Info: Instead of bridging the IPv6 traffic, the switch punts it to the CPU.

- CSCun91923

Symptom: Router crash observed on CUBE for Carbon2-SIP signaling forking.

Conditions: Crash is seen while you configure CUBE for SIP signaling forking on PI19.

Workaround: There is no workaround.

- CSCun92095
 

Symptom: IOS-XE running router may reload when unconfiguring BGP along with other removal operations in a scaled setup.

Conditions: This symptom occurs when the BGP is configured with 1Million+ nets and 4000 VRFs. Then the BGP instance is removed using “no router bgp <>”

Workaround: Shut down the BGP neighbor sending big scale nets to remove the nets first from BGP and RIB. Then remove the BGP using “no router bgp <>”.
- CSCuo09249
 

Symptom: An xTR changes its RLOC, map-request packets from that new RLOC are dropped on the MS/MR due to policy violation, for example:

```
*Apr 2 15:29:15 JST: LISP-0: AF IID 100 IPv4, Map resolver filtered incoming map request from 2400:A:A:9999:C267:AFFF:FE52:287 because it does not conform to the configured allowed-locator policy.
```

Conditions: This symptom is observed when {ipv4lipv6} map-resolver map-request validate source registered is configured on the MS/MR and the xTR RLOC is updated, for example, by DHCP when the {ipv4lipv6}-interface configuration is used in the database-mapping configuration. Both the new and the old RLOC must have been valid.

Workaround: Remove and re-add database-mapping configuration on xTR, possibly using EEM script on address change Remove “{ipv4lipv6} map-resolver map-request validate source registered” configuration on MS/MR clear lisp site <name> on the MS
- CSCuo11238
 

Symptom: Router crashes when removing address-family from VRF definition, or when removing the VRF definition.

Conditions: This symptom is observed when PIM is configured for the LISP interface associated with the VRF.

Workaround: Unconfigure LISP for the VRF, or remove PIM configuration from the LISP interface associated with the VRF, before removing VRF configuration.
- CSCuo11703
 

Symptom: The **show network-clock synchronization** command flaps between different QL values on the same interface. Depending on the values with which the interface flaps, this could lead to triggering of network-clock selection algorithm and subsequent selection of primary reference clock for the system.

Conditions: This symptom could occur when the network-clock synchronization mode is unprovisioned from automatic selection, and then the monitor interfaces are removed and a new set of interfaces are added for network-clock monitoring with automatic selection reprovisioned.

Workaround: Adding back the older set of interfaces and removing them would resolve the issue.
- CSCuo12245
 

Symptom: The following error message is observed with traceback:

```
OCE_PUNT_PROCESS-3-LABEL_CACHE_INVALID: inlabel pointer was NULL
```

Conditions: Multicast traffic is label switched in the mpls P2MP tree and replicated at branch bud nodes along the P2MP tree. The error condition is observed at a bud node, where the replicated traffic is dropped with the error.

Workaround: There is no workaround.



- CSCuo13314  
Symptom: ES+ crashes while deleting the imposition table from LC.  
Conditions: This symptom occurs while flapping the scalable EoMPLS.  
Workaround: There is no workaround.
- CSCuo16717  
Symptom: PPPoX brings up sessions failure with IPv6 configurations.  
Conditions: This symptom occurs when “vpdn authen-before-forward” is configured.  
Workaround: Do not configure “vpdn authen-before-forward”.
- CSCuo19730  
Symptom: Cisco IOS XE includes a version of OpenSSL that is affected by the vulnerability identified by the Common Vulnerability and Exposures (CVE) ID CVE-2014-0160.  
This bug has been opened to address the potential impact on this product.  
Conditions: Cisco IOS XE devices running release 3.11.0S, 3.11.1S or 3.12.0S and with the WebUI interface over HTTPs enabled. No other versions of Cisco IOS XE are affected.  
Devices with the WebUI interface enabled and using HTTPs as transport protocol will include the following configuration:  
transport-map type persistent webui http-webui secure-server ip http secure-server transport type persistent webui input http-webui  
Devices running IOS XE release 3.11.0S, 3.11.1S or 3.12.0S but WITHOUT the WebUI interface enabled, or with the WebUI interface enabled but NOT using HTTPs as transport protocol are NOT AFFECTED by this vulnerability.  
Devices running IOS XE release 3.11.0S, 3.11.1S or 3.12.0S and with the HTTPs server enabled (by including in their configuration the line “ip http secure-server”) are NOT affected. Both the HTTPs server and the WebUI interface need to be enabled for a device to be vulnerable.  
The WebUI configuration guide is available at  
<http://www.cisco.com/c/en/us/td/docs/routers/asr1000/configuration/guide/chassis/asrswcfg/webui.html>  
Workaround: Not currently available.  
Further Problem Description: Additional details about this vulnerability can be found at  
<http://cve.mitre.org/cve/cve.html>  
Software version and Fixes:  
The first column is the Cisco IOS XE Software Release.  
The second column is the First Fixed Release.  
2.x.x Not Vulnerable  
3.1.xS Not Vulnerable  
3.1.xSG Not Vulnerable  
3.2.xS Not Vulnerable  
3.2xSE Not Vulnerable  
3.2.xSG Not Vulnerable  
3.2.xXO Not Vulnerable  
3.2.xSQ Not Vulnerable

3.3.xS Not Vulnerable  
 3.3.xSE Not Vulnerable  
 3.3xSG Not Vulnerable  
 3.3xXO Not Vulnerable  
 3.3xSQ Not Vulnerable  
 3.4.xS Not Vulnerable  
 3.4.xSG Not Vulnerable  
 3.5.xS Not Vulnerable  
 3.5.xE Not Vulnerable  
 3.6.xS Not Vulnerable  
 3.6.xE Not Vulnerable  
 3.7.xS Not Vulnerable  
 3.8.xS Not Vulnerable  
 3.9.xS Not Vulnerable  
 3.10.xS Not Vulnerable  
 3.11.xS Vulnerable  
 3.12.xS Vulnerable  
 3.12.0aS Not Vulnerable

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/4.3:

<https://intellishield.cisco.com/security/alertmanager/cvss?target=new&version=2.0&vector=AV:N/AC:M/Au:N/C:P/I:N/A:N/E:H/RL:U/RC:C>

The Cisco PSIRT has assigned this score based on information obtained from multiple sources. This includes the CVSS score assigned by the third-party vendor when available. The CVSS score assigned may not reflect the actual impact on the Cisco Product.

CVE-2014-0160 has been assigned to document this issue.

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/web/about/security/psirt/security\\_vulnerability\\_policy.html](http://www.cisco.com/web/about/security/psirt/security_vulnerability_policy.html)

- CSCuo22184

Symptom: The VPLS bit is not set in the flood VLAN LTL index which causes a traffic drop.

Conditions: This symptom occurs under the following conditions:

- Have a port-channel with member links on different NP (say NP2 and NP1) and a physical interface on the same LC and NP (say NP2) to different neighbors, say PE1 and PE2 respectively.
- Shut down the member link of NP1.
- Remote shut the VLAN or access interface on PE2 (reached by physical interface).
- The V-bit is not set and this affects the traffic towards PE1 (reached by port-channel interface).

Workaround:

- Either no-shut the remote VLAN or AC on PE2.



Workaround: There is no workaround at this time.

- CSCuo47380

Symptom: Traffic drops in the MST region during IM-OIR followed by an SSO. When an IM is removed from the router, the MST states are not reflected in the standby RSP. If a switchover happens at this state, it could cause total traffic drop.

Conditions: This symptom is seen in HA routers. If this issue is hit, the IM that was previously removed should not be inserted back, as it could cause a traffic loop.

Workaround: There is no workaround.

- CSCuo47685

Symptom: While evaluating the Cisco IOS Release 15.3(3)S3 early release image, the following error message was observed when using the CoPP configuration given below which matches based on precedence only as shown:

```
class-map match-any coppclass-protocol match precedence 6 7
```

```
"Match precedence in IPv4/IPv6 packets is not supported for this interface error:
failed to install policy map CoPP"
```

Upon occurrence, the entire CoPP policy map is not loaded. There is a concern that some field devices on the current release (Cisco IOS Release 15.0(1)S6) may have the above configuration and as such is prone to this error (CoPP installation failure during upgrade).

Conditions: This symptom occurs while evaluating the Cisco IOS Release 15.3(3)S3 early release image.

Workaround: There is no workaround.

- CSCuo49923

Symptom: Performing an ISSU upgrade with the CEF table consistency checkers enabled may result in a crash on "issu runversion".

Conditions: This symptom occurs with a Cisco Catalyst 6500 Series Switch running Cisco IOS Release 15.1(02)SY.

Workaround: Turn off the CEF table consistency checkers before performing an ISSU upgrade.

- CSCuo55180

Symptom: A vulnerability in PPPoE processing code of Cisco IOS XE could allow an unauthenticated, adjacent attacker to cause a reload of the affected device and eventually a denial of service (DoS) condition.

The vulnerability is due to improper processing of certain malformed PPPoE packets. An attacker could exploit this vulnerability by sending a malformed PPPoE packet to an IOS XE ASR1000 device, configured with PPPoE termination. An exploit could allow the attacker to cause a reload of the affected device and eventually a denial of service (DoS) condition.

Conditions: Cisco ASR 1000 with IOS XE, configured for PPPoE termination.

Workaround: There is no workaround.

Further Problem Description: A device crashing, may print the following messages on the console:

```
%SYS-3-OVERRUN: Block overrun at 7F7FAE750B58 (red zone 44534C5F00000000)
%SYS-6-MTRACE: mallocfree: addr, pc ? %SYS-6-BLKINFO: Corrupted redzone blk
7F7FAE750B58, words 404, alloc 6374D1B, InUse, dealloc 10001, rfcnt 1 ?
%Software-forced reload
Exception to IOS Thread: Frame pointer 0x7F7FA0AB5AD8, PC = 0x7F80A8469565
UNIX-EXT-SIGNAL: Aborted(6), Process = Check heaps -Traceback=
1#c3a5522ccb47820b036322d6b7226e1c c:7F80A8438000+31565
```

```
Fastpath Thread backtrace: -Traceback= 1#c3a5522ccb47820b036322d6b7226e1c
c:7F80A8438000+BDD2
Auxiliary Thread backtrace: -Traceback= 1#c3a5522ccb47820b036322d6b7226e1c
pthread:7F80A3697000+A7C9
```

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 6.1/5:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:A/AC:L/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>

CVE ID CVE-2014-3284 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-3284>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCuo55440

Symptom: The ME3600-24CX device crashes whenever it is reloaded.

Conditions: This symptom occurs when the ME3600-24CX device is reloaded.

Workaround: There is no workaround.

- CSCuo56173

Symptom: When PW's remote peer is ALU, it takes 5 to 10 minutes for the PWs to come up.

Conditions: This symptom occurs when Provision PW is done first on the ALU and then on the Cisco router.

Workaround: Provision PW on the Cisco router first.

- CSCuo72301

Symptom: Crash occurs when IKEv2 attempts to clean up its contexts when it times-out waiting for received Certificate to be Validated by PKI component.

Conditions: Authentication with certificates and PKI component's response to certificate validation is delayed.

Workaround: There is no workaround.

- CSCuo77574

Symptom: An error is seen while enabling "auto negotiation".

Conditions: This symptom is observed when "auto negotiation" is configured on an interface.

Workaround: There is no workaround.

- CSCuo82355

Symptom: A BFD session fails to come up.

Conditions: This symptom occurs when BFD is running on Cisco IOS Release 15.4(1)S to any other lower release.

Workaround: Upgrade the device.

- CSCuo86424

Symptom: An ESP crashes while using packet-trace to debug packets.

Conditions: This symptom occurs when a ping is initiated while using packet-trace to debug packets on Cisco IOS XE Release 3.11.2 or Cisco IOS Release 15.4(2)S2. This issue is only visible in the Cisco IOS Release 15.4(1)S2 maintenance release.

Workaround: Use packet-trace in a circular mode and choose a large number of packets.

Example: `debug platform packet-trace packet 8192 circular`

This will only reduce the chances of seeing the crash but will not eliminate it completely.

- CSCup22590

Symptom: Some Cisco Internetwork Operating System (IOS) releases may be affected by the following vulnerabilities:

These products include a version of openssl that is affected by the vulnerabilities identified by the Common Vulnerability and Exposures (CVE) IDs:

CVE-2014-0195 - DTLS invalid fragment vulnerability  
 CVE-2014-0221 - DTLS recursion flaw  
 CVE-2014-0224 - SSL/TLS MITM vulnerability

This bug has been opened to address the potential impact on this product.

Conditions: This symptom occurs in devices running an affected version of Cisco IOS and utilizing an affected configuration.

One of more of these vulnerabilities affect all versions of IOS prior to the versions listed in the Integrated In field of this defect.

Workaround: None currently available.

Further Problem Description: CVE-2014-0224: All Cisco IOS services that provide a form of TLS or SSL encryption are affected by this vulnerability. This includes features such as the HTTPS Web Management interface.

CVE-2014-0195: Cisco IOS devices that support SSLVPN (AnyConnect) and have the feature configured and enabled are affected by this vulnerability.

CVE-2014-0221: Cisco IOS devices that support SSLVPN (AnyConnect) and have the feature configured and enabled are affected by this vulnerability.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 10/9.5:

<https://intellishield.cisco.com/security/alertmanager/cvss?target=new&version=2.0&vector=AV:N/AC:L/Au:N/C:C/I:C/A:C/E:F/RL:U/RC:C>

The Cisco PSIRT has assigned this score based on information obtained from multiple sources. This includes the CVSS score assigned by the third-party vendor when available. The CVSS score assigned may not reflect the actual impact on the Cisco Product.

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/web/about/security/psirt/security\\_vulnerability\\_policy.html](http://www.cisco.com/web/about/security/psirt/security_vulnerability_policy.html)

## Open Bugs—Cisco IOS Release 15.4(2)S

This section describes possibly unexpected behavior by Cisco IOS Release 15.4(2)S. All the bugs listed in this section are open in Cisco IOS Release 15.4(2)S. This section describes only severity 1, severity 2, and select severity 3 bugs.

- CSCum90044

Symptom: FRR database value does not exist.

Conditions: This symptom occurs on tunnelling intf with Auto-Tunnel\_Primary\_SSO\_Configuration.

Workaround: There is no workaround.

## Resolved Bugs—Cisco IOS Release 15.4(2)S

- CSCtb34814

Symptom: The %DATACORRUPTION-1-DATAINCONSISTENCY: copy error is observed without any traceback just before the system crashes.

Conditions: This issue occurs under normal conditions.

Workaround: There is no workaround.

- CSCte77398

Symptom: A Cisco ATM router configured with ATM PVC Range commands report the following error when attempting to configure a PVC Range:

Unable to configure PVC Range. Possibly multiple users configuring IOS simultaneously.

Conditions: This problem occurs randomly and even if there are no multiple sessions accessing the pvc-range at the same time.

Workaround: There is no workaround.

- CSCts14036

Symptom: Memory “Holding” continues to increase on process “IP SNMP”. This could lead to an out of memory crash.

Conditions: This symptom only affects Cisco IOS release 12.2(53)SG5, under the following conditions:

1. Switch is configured to receive informs and/or
2. Traps received and consumed by switch (traps broadcast)

Use “show proc memory | inc IP SNMP” and compare outputs across several collections of this command.

Workaround: Upgrade to Cisco IOS release 12.2(53)SG8.

- CSCty92208

Symptom: A crash is seen on the Cisco Catalyst 6509 Switch after configuring WCCP.

Conditions: This symptom occurs when WCCP is configured with a hash assignment and port hashing is enabled. It will occur during redirection if packets are software switched.

Workaround:

1. Disable port-hashing if hash-assignment is used.
2. Use the mask-assignment method.

- CSCtz66347

Symptom: Router crashes on executing **show tech-support** from the linux client to the IOS server over an SSH session with the rekey enabled.

Conditions: This symptom occurs when the rekey value “ip ssh rekey volume 400” is configured.

Workaround: Disable the rekey feature by configuring the **no ip ssh rekey** command.

- CSCuc24927
 

Symptom: A segmentation fault is seen when IMA, CEM and Serial are configured on different controllers and an image is loaded.

Conditions: This symptom is seen when IMA, CEM, and Serial are configured on different controllers. and try to load image. The issue is consistently reproduced and is sometimes seen when CEM on TDM and MLPPP QoS on OC3 IM is configured and multiple reloads are done. When there is a segmentation fault, the RSP will not come up and will go to the ROMmon mode.

Workaround: Do not combine IMA, CEM and Serial configurations. Test each feature individually.
- CSCuc60868
 

Symptom: A router randomly crashes either due to memory corruption at `bgp_timer_wheel` or memory chunks near `bgp_timer_wheel` (For example, BFD event chunks if BFD is configured or AtoM Manager chunks if LDP is configured). A crash occurs right after an LDP neighbor is up in the L2VPN setup.

Conditions: This symptom occurs when **vpls bgp signaling** is unconfigured and then reconfigured. Both L2VPN and BGP are unconfigured and reconfigured after all L2VPN and BGP data structures are fully deleted (about 3 minutes for 5 BGP VPLS prefixes). For the repro on file, OSPF (for IGP) is also unconfigured and reconfigured. Both LDP and BGP signalling are affected by this bug.

Workaround: Avoid unconfiguring and reconfiguring BGP L2VPN.
- CSCue59450
 

Symptom: IOS XE Watchdog message seen along with RP and SIP crash.

Conditions: This symptom is observed in an ARP request on the interface having VRF receive configured on it.

Workaround: There is no workaround.
- CSCuf53543
 

Symptom: MPLS-TP L2 VCs are down after an SIP reload and RP switchover.

Conditions: This symptom occurs when VCs are configured through an MPLS-TP tunnel in a hardware redundant platform.

Workaround: There is no workaround.
- CSCug08561
 

Symptom: After a web-logon, users do not get the web-logon response page sent by the portal. If the web-logon is successful, users are not redirected to the web address which they have entered initially but are redirected to the portal for authentication.

Conditions: This symptom occurs under the following conditions:

  1. Walkby feature is enabled with L4R & PBHK features applied to the lite session.
  2. User initiated the web-logon request.

Workaround: There is no workaround.

More Info: When a user does a web-logon, an account-logon coa request is triggered from the portal to ISG. In ISG, the account-logon request triggers a lite session conversion to a dedicated session. During the conversion, lite session and its associated resources (L4R and PBHK mappings) are removed from PD and a dedicated session gets provisioned. Once the conversion is done, ISG replies back with COA ACK/NACK to the portal. Based on the response from ISG, the portal generates a weblogon response (SUCCESS/FAILURE) page and sends it back to the client. But when it reaches ISG, the response packet does not get classified to session in the downstream direction and gets dropped in ISG because PBHK & L4R mapping are deleted.



- CSCug43009
 

Symptom: SYS-SP-2-MALLOCFAIL memory allocation fails due to I/O buffer memory leak in process\_online\_diag\_pak.

Conditions: This symptom occurs when some diag packets get en-queued to a queue which is not being watched. Hence, there is no dequeuing on that queue which leads to I/O memory leak.

Workaround: Reload the box to clear the I/O pool when it is full.
- CSCuh44420
 

Symptom: When a Cisco IOS router with one or more mpls ldp neighbors undergoes an **mpls ldp router-id** configuration change and non-stop routing had been previously enabled and disabled prior to the router-id configuration change, sessions fail to become NSR-ready once **mpls ldp nsr** is reconfigured.

Conditions: This symptom occurs when the **mpls ldp router-id** command is reconfigured after **mpls ldp nsr** has been enabled and then disabled. After the router-id change, **mpls ldp nsr** must be reconfigured in order to encounter this issue.

Workaround: Reload the standby RP.
- CSCuh45042
 

Symptom: Traffic on some GIG subinterfaces are seen to be dropped at the SPA. The SPA TCAM is seen to have two entries sharing the same logical address as a result of which one entry is seen to overwrite the other.

Conditions: This symptom was observed after a router/LC/SPA reload. The exact condition that triggers this symptom is not known.

Workaround: There is no workaround.
- CSCuh89168
 

Symptom: The standby resets in a continuous loop.

Conditions: This symptom occurs on insertion of a new standby RSP with a different license than the one on the active RSP.

Workaround: There is no workaround.
- CSCuh91645
 

Symptom: WS-SUP720-3B crashes while receiving DHCP packets.

Conditions: This symptom occurs with the **ip dhcp relay information policy-action encapsulate** command.

Workaround 1. Use the **ip dhcp relay information policy-action replace** command.

Workaround 2. Use the **no ip dhcp relay information trusted** command.
- CSCui04530
 

Symptom: Upon FPD upgrade, you get this error on Cisco IOS c7600 switch:

```
! %FPD_MGMT-3-BUNDLE_EXTRACT_ERROR: Cannot extract the ssc-600-fpd.bndl bundle from
sup-bootdisk:c7600-fpd-pkg.151kg - The required bundle is not in the package file.
Please make sure that you have the right FPD image package file. % Cannot get the
required data from the indicated file, please verify that you have a valid file and
entered a valid URL. !
```

Conditions: This symptom is observed under the following conditions:

```
IOS: c7600s72033-advipservicesk9-mz.122-33.SRB3
CARDS: WS-SSC-600 WS-IPSEC-3
```

CLI: upgrade hw-module slot x fpd file sup-bootdisk:c7600-fpd-pkg.151-3.S2.pkg

Workaround: Upgrade to FPD image that includes corresponding \*.bndl image.

- CSCui11998
 

Symptom: A CEM-SSO Standby crash occurs with 576 CEMoMPLS configured on the mobile profile testbed after defaulting the CEM interface configuration and during reconfiguration.

Conditions: This symptom occurs during dynamic syncing of cem-xconnect configurations to the standby.

Workaround: Apply reconfiguration CLIs through TFTP. If the reconfiguration CLIs are done in the router, the crash is observed.
- CSCui24744
 

Symptom: An iosd crash is seen.

Conditions: This symptom occurs on removing **bfd-template single-hop sw-no-echo-sha1** configuration.

Workaround: There is no workaround.
- CSCui32105
 

Symptom: In rare occasions the standby RP on a dual RP system may crash after performing a switchover.

Conditions: This symptom occurs when an invalid message is sent from the RP to the RRP.

Workaround: There is no workaround.
- CSCui34165
 

Symptom: Port-channel QoS features might fail to work after a router reload, followed by QoS configuration modification.

Conditions: This symptom occurs when a vlan load-balanced port-channel is used with policy aggregation configuration where the QoS policy is configured on member links and the port-channel sub-interface, and after a system reload (configuration is from startup config).

Workaround: Reload the router without port-channel QoS configuration, and add port-channel QoS configuration to the running configuration after the router boots up.
- CSCui47602
 

Symptom: Traces at IDMGR-3-INVALID\_ID when queried for mplsTunnelTable MIB.

Conditions: This symptom occurs when there is a GETONE SNMP query for non-existing mplsTunnelTable entries.

Workaround: Avoid using GETONE SNMP query for non-existing objects. Use GETNEXT queries instead of GETONE whenever possible.
- CSCui49185
 

Symptom: On a Cisco IOS ASR 1002x series router running Cisco IOS Release 15.4(01)S, a crash occurs.

Conditions: This symptom occurs when MLDP over GRE is configured, with paths being added and removed. The counter of the number of paths in a CEF path list is not updated correctly. When they wrap at 256 this may cause a crash. The problem occurs when a path is removed without decrementing the counter properly. The problem is observed when a path is added/removed from a path list 256 times.

Workaround: Do not modify paths using the method described.

- CSCui51363  
Symptom: The multilink does not pass traffic even though it is in an up/up state.  
Conditions: This symptom occurs when the auto DNR status is set and the sip400 ucode crashes.  
Workaround: Perform a shut/no shut in the multilink.
- CSCui53213  
Symptom: Traffic forwards through the VC even when the EVC is in a shut state.  
Conditions: This symptom occurs in scalable EoMPLS.  
Workaround: There is no workaround.
- CSCui56771  
Symptom: When **shutdown** and **no shutdown** are executed at an external interface on a router acting as a PfR border, the router may unexpectedly reload.  
Conditions: This symptom occurs on a Cisco router when heavy traffic is going through an external interface.  
Workaround: There is no workaround.
- CSCui62441  
Symptom: Complete traffic drop for few seconds is seen after few minutes of performing SSO switchover.  
Conditions: This symptom occurs only after a few minutes of performing an SSO switchover.  
Workaround: There is no workaround.
- CSCui65914  
Symptom: Minor or major temperature alarms are reported in the syslog along with the following DATACORRUPTION logs:  

```
Aug 5 15:54:30.972 Buc: DATACORRUPTION-SP-1-DATAINCONSISTENCY copy error, -PC=
0x414DEED4z -Traceback= 4027C4F4 419551C0 414DEED4 414E5BC4 414E0CA0 414E0F00 Aug 5
15:54:30.972 Buc: C6KENV-SP-4-MINORTEMPALARM interface 10/0 outlet temperature crossed
threshold #1(=60C). It has exceeded normal operating temperature range.
```

  
Conditions: The symptom is observed on ES+ series linecards of Cisco 7600 Series Routers.  
Workaround: There is no workaround.
- CSCui67308  
Symptom: Cisco IOS Router constantly crashes after enabling TE tunnel over BDI interface.  
Conditions: This symptom is observed when TE tunnel is exits a BDI interface. This is not a supported design.  
Workaround: Use physical interface for TE tunnels.
- CSCui71298  
Symptom: A router crash is observed.  
Conditions: This symptom occurs when the configuration is replaced with CEM circuit.  
Workaround: There is no workaround.
- CSCui72518  
Symptom: A tunnel down (times out) occurs when the primary link is used again following FRR.

Conditions: This symptom occurs with FRR and reoptimizing the path back to the primary link with RSVP authentication enabled globally.

Workaround: Use interface CFG for RSVP authentication, as it has least impact on data traffic. The only fall out would be that the reopt may fail leaving FRR active LSP to timeout which will then impact traffic. The global CFG model can be used if you always use multi-hop backup tunnels.

- CSCui74609

Symptom: After an RSP switchover the backup pseudowire state is down and never recovers to standby state.

Conditions: This symptom occurs on CEM circuits in an SAToP environment after an SSO switchover.

Workaround: There is no workaround.

- CSCui76564

Symptom: A roaming mobile customer (example: iPASS, Boingo etc.) logs on via a Web-Portal-Page and the ISG doesn't send in the radius accounting-request packet from the V-Cookie to the Radius Server.

Conditions: This symptom occurs depending on the ISG setup. In this case L & V Cookie must be sent in accounting-request from the ISG to the AAA Server.

Workaround: There is no workaround.

- CSCui82757

Symptom: Session query responses in lite sessions have inconsistent calling-station-ID behavior.

Conditions: This symptom occurs under the following conditions:

1. Walkby feature is enabled with L4R & PBHK features applied to lite session.
2. Session query is sent to ISG.

Workaround: Do not use calling-station-ID.

- CSCui83823

Symptom: When CU executes show tech or any show commands which gives a long output using putty the SSH2 putty closes prematurely.

Conditions: This symptom is observed when "term length 0" is enabled, the putty session closes prematurely while executing show tech show memory.

Workaround: Redirect the output to a file.

- CSCui85019

Symptom: When the command **show xconnect** is entered, it may result in a memory leak. This can be observed by entering the command **show memory debug leaks chunks** and seeing entries like this:

```
router#show memory debug leaks chunks
Adding blocks for GD...
I/O memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name
Processor memory
Address Size Alloc_pc PID Alloc-Proc Name AA3F8B4 2348 6D0B528 97 Exec
PW/UDP VC event trace
```

Conditions: This symptom is observed when one or more xconnects are configured with UDP encapsulation.

Workaround: There is no workaround.

- CSCui90811

Symptom: While running the Cisco IOS 15.3S release and Cisco IOS 15.4S release software for the L2VPN pseudowire redundancy feature on a Cisco router, the traffic is dropped when the primary pseudowire becomes active.

Conditions: Initially the primary pseudowire is down due to either a local or a remote core-facing interface being shutdown. The backup pseudowire is active and traffic flows through the backup pseudowire. Later, when the backup pseudowire is down, the primary pseudowire is brought up and becomes active and traffic is not able to flow through primary pseudowire and is dropped.

Workaround: There is no workaround.

- CSCui95398

Symptom: Config CLI to enable and disable the diag gives a false alarm detection and fails.

Conditions: This symptom occurs when sprp\_inband ping test fails.

Workaround: There is no workaround.

- CSCui95880

Symptom: HSRP for IPv6 flaps when there is a loop in the network, but IPv4 HSRP state remains stable for the same vlan.

```
%HSRP-5-STATECHANGE: Vlan154 Grp 154 state Speak -> Standby %HSRP-5-STATECHANGE:
Vlan154 Grp 154 state Standby -> Listen %HSRP-5-STATECHANGE: Vlan154 Grp 154 state
Standby -> Listen %HSRP-5-STATECHANGE: Vlan154 Grp 154 state Speak -> Standby
%HSRP-5-STATECHANGE: Vlan154 Grp 154 state Standby -> Active
```

Conditions: This symptom is observed when a Layer 2 loop is in the network.

Workaround: Create an IPv6 access-list, denying udp traffic sourced from device own Ipv6 link local address to any address & permit all other traffic. Apply that access-list to svi interface in inbound direction on the respective HSRP cores running IPv6 HSRP, then the HSRP group will not flap.

- CSCui99031

Symptom: In a pair of Cisco 7609-S routers running c7600rsp72043-adviservicesk9-mz.151-3.S5.bin IOS, phase 1 fails to establish due to a “signature invalid!” error when rsa-sig is used for phase 1 authentication.

Conditions: This symptom occurs under the following conditions:

- rsa-sig is used for phase 1 authentication
- site to site tunnel

Workaround: Use PSK instead of PKI.

- CSCuj00746

Symptom: On performing an upgrade from 9.512 to 9.523, there is a label allocation failure in VPWS circuits as they are trying to utilize the labels that are already used by the VPLS circuits that are present in the database.

Conditions: This symptom occurs when both VPWS and VPLS circuits are configured on the same node before upgrading.

Workaround: Removing the VPLS circuit brings up the VPWS circuits. Re-configuring the VPLS circuit is also successful with a different local label assigned.

- CSCuj04178  
Symptom: A crash occurs at `vpdn_apply_vpdn_template_pptp`.  
Conditions: The conditions for this symptom are unknown.  
Workaround: There is no workaround.
- CSCuj11232  
Symptom: Changing the local label on an existing static (no signaling) Any Transport over MPLS (AToM) pseudowire, or changing the static pseudowire to a dynamic one (with LDP signaling) may cause traffic to fail to traverse the pseudowire.  
Conditions: This symptom is observed when either the configured value of the static local label is changed, or if the pseudowire is changed to a dynamic one.  
Workaround: Completely unconfigure the existing xconnect or pseudowire before entering the new configuration.
- CSCuj16367  
Symptom: Traffic does not flow on a few multilinks.  
Conditions: This symptom occurs during a microcode reload (due to any exception) during a multilink flap in Prowler SPA in SIP-400. This sometimes results in the DNR getting stuck.  
Workaround: Reload the SPA.
- CSCuj16742  
Symptom: In a pseudowire redundancy configuration, packets may fail to flow even though the xconnect virtual circuit appears to be up.  
Conditions: This symptom has been observed when the xconnect is re-provisioned while the primary pseudowire is down and the backup pseudowire is up. The issue has only been observed on Circuit Emulation (CEM) attachment circuits, but it is possible other attachment circuit types may be affected as well.  
Workaround: Completely unconfigure the xconnect and then reconfigure it.
- CSCuj22189  
Symptom: On a Cisco ASR series router, a crash occurs when **mpls ip** is added under the interface.  
Conditions: This symptom occurs when the hidden command **snmp-server hc poll** is already configured.  
Workaround: Ensure that the hidden command **snmp-server hc poll** has not been configured.
- CSCuj26593  
Symptom: Simple IP Dual stack and IPv6 sessions failed to survive an RP switchover.  
Conditions: This symptom occurs when the dual stack session exists.  
Workaround: Do not use the dual stack session.
- CSCuj30702  
Symptom: This bug is specific to port channel sub interface configuration in ES+ card. This bug is not relevant to any other port channel configuration in ES+, that is, EVC/Bridge-Domain over PoCH sub-int etc, and other card types, such as ES20/ LAN cards are free from this bug. Any type of IP communication on port channel sub interfaces in ES+ cards fail. Such an issue is seen only with port channel sub interfaces on ES+ and not seen with port channel main interfaces.  
Conditions: This symptom will only be seen with images where the fix of CSCuh40617 is integrated.

Workaround: The connections will work fine if it is moved to the main interface or by using EVC BD configurations.

- CSCuj31090

Symptom: When L2TPv3-based pseudowire is configured between two PE routers and different VLAN ids are used on the ACs on both sides, ES+ on egress PE does not rewrite a dot1q VLAN tag when sending a frame toward CE.

Conditions: This symptom occurs under the following conditions:

1. Both ACs are Ethernet VLAN type.
2. Different dot1q tag is used on both ACs.

Workaround: Configure the same dot1q tag for the ACs on both PEs.

- CSCuj47238

Symptom: There is a difference in the Y1731 probe within **show ip sla statistics**.

Conditions: This symptom is seen in the Cisco 7600 series routers.

```
service instance 400 ethernet evc1000 description -- EVC Cliente BUSINESS--
encapsulation dot1q 400 second-dot1q 100 <==HERE rewrite ingress tag pop 2 symmetric
<==HERE xconnect 172.16.12.6 1000 encapsulation mpls cfm mep domain OPM mpid 2
mdr-rm01#sh ip sla statistics 1 IPSLAs Latest Operation Statistics
IPSLA operation id: 1 Delay Statistics for Y1731 Operation 1 Type of operation: Y1731
Delay Measurement Latest operation start time: 12:06:21.041 CET Wed Sep 11 2013 Latest
operation return code: OK Distribution Statistics:
Interval Start time: 12:06:21.041 CET Wed Sep 11 2013 Elapsed time: 50 seconds Number
of measurements initiated: 44 <== HERE Number of measurements completed: 32 <== HERE
Flag: OK
```

Workaround: There is no workaround.

- CSCuj47554

Symptom: PBHK bundles are not released even after the session is cleared.

Conditions: This symptom occurs after the session is cleared and the port-bundle status is not shown correctly with **show ip portbundle status** command.

Workaround: There is no workaround.

- CSCuj52396

Symptom: In a VPLS Inter-Autonomous System Option B configuration, the virtual circuits between the Autonomous System Border Router (ASBR) and the PE may fail to come up.

Conditions: This symptom is observed while initially establishing VCs after the ASBR has reloaded.

Workaround: The **clear xconnect** exec command can be used to clear the VCs that are down.

- CSCuj55914

Symptom: The MPLS label of the labeled route is missing. This causes a traffic loss as only one path (non-labeled path) takes on the full load of the shared traffic setup.

Conditions: This symptom occurs when there are two routes to a network and one of them is a sham-link, and the routes are learned via OSPF and redistributed by BGP, and one of the routes is labeled and the other is not, and the unlabeled route gets installed after the labeled route (for example, flapping). And both of the routes have the same metrics (that is, **show ip route vrf <> x.x.x.x** and **show ip cef vrf <> x.x.x.x** will have both entries).

Workaround: Flap the unlabeled route and then the labeled route.

- CSCuj57367

Symptom: A 10 gig line card crashes on a Cisco 7600 platform with the following or similar errors:

```
%SYS-DFC3-3-MGDTIMER: Uninitialized timer, timer stop, timer = 30CCCFB0. -Process= "RO
Notify Timers", ipl= 0, pid= 7 -Traceback= 2060E1BCz 2060E8E4z %SYS-DFC3-3-MGDTIMER:
Uninitialized timer, timer stop, timer = 30CCD154. -Process= "RO Notify Timers", ipl=
0, pid= 7 -Traceback= 2060E1BCz 2060E8E4z %SYS-DFC3-3-MGDTIMER: Uninitialized timer,
timer stop, timer = 30CCCFB0. -Process= "RO Notify Timers", ipl= 0, pid= 7 -Traceback=
2060E1BCz 2060E8E4z
08:54:43 Central Tue Oct 1 2013: Address Error (load or instruction fetch) exception,
CPU signal 10, PC = 0x20642A08
```

Conditions: This symptom occurs when a large number of IPC messages are used.

Workaround: There is no workaround.

More Info: On mac-scaling, the L2-DRV application sends more ICC messages(though not always). But periodically( approximately 2-3 minutes), some burst of around 150 ICC messages are sent by the SP towards the RP. This means that mac-scaling has a direct correlation with the number of IPC messages being sent.

- CSCuj60533

Symptom: Repeated CPUHOG messages may be seen along with a crash when “reload” is issued just after a bootup.

Conditions: This symptom occurs when the line cards are still booting up and are in other states.

Workaround: Issue “reload” after the line cards have booted.

- CSCuj64806

Symptom: VRRPv2 priority may be incorrectly calculated when tracking tunnel interfaces. After reloading the router, the track decrement value is decremented twice. As a result, VRRPv2 with tracking does not work as expected.

Conditions: This symptom is observed when you use tracking tunnel for VRRP priority.

Workaround: Use VRRPv3.

- CSCuj65057

Symptom: The **ip vrf forwarding** command under “aaa” is deleted after reloading the stack master.

Conditions: This symptom occurs after reloading the stack master switch.

```
aaa new-model ! aaa group server tacacs+ TACACS+ ip vrf forwarding VRF01 ! ip vrf
VRF01 rd x.x.x.x
```

Workaround: Use the **vrf definition** command instead of the **ip vrf command to define vrf**. (This command is supported on Cisco IOS Release 12.2(58)SE or later releases.)

- CSCuj66352

Symptom: A system crash is observed in the SNMP engine.

Conditions: This symptom occurs under the following conditions:

- ?show subscriber session?
- polling the ISG-MIB
- clearing the subscriber

Workaround: Do not use SNMP polling.

- CSCuj68109

Symptom: The Cisco 7600-SIP-400 router crashes.



Conditions: This symptom occurs when there is an Egress ESF Engine: ME Breakpoint error.

Workaround: There is no workaround.

- CSCuj68932

Symptom: L2TPv3 tunnel with digest fails to establish. Cisco IOS device gives the following messages when “debug l2tp all” and “debug l2tp packet detail” are enabled:

```
L2TP _____:_____ : ERROR: SCCRQ AVP 59, vendor 0: unknown L2TP _____:_____ :
Unknown IETF AVP 59 in CM SCCRQ
```

Conditions: This issue is observed when IOS device peers with non-IOS device that sends IETF L2TPv3 digest AVP (IETF AVP 59) in L2TP control message. This issue is present in S images starting from Cisco IOS Release 12.2(33)XNC and in T train from Cisco IOS Release 15.3(2)T.

Workaround: There is no workaround.

- CSCuj75952

Symptom: The Cisco ASR 1000 route processor reloads.

Conditions: This symptom occurs during PPPoA session establishment if CAC determines that resources are low and HW-assisted CAC needs to be enabled. The router is used to terminate PPPoA sessions and Call Admission Control (CAC) is enabled.

Workaround: Disable Call Admission Control.

- CSCuj78636

Symptom: A memory leak is observed in the IP Switching segment.

Conditions: This symptom occurs if a subscriber roams with the same MAC address but a different IP address. This happens only for L2 roaming and not for L3 roaming.

Workaround: There is no workaround.

- CSCuj82897

Symptom: The “control-word” length is not set properly for small HDLC packets running over HDLC AToM VC with SIP-200. For example: SPA-8XCHT1/E1.

Conditions: This symptom occurs when HDLC AToM VC with SIP-200 is deployed, for example, SPA-8XCHT1/E1, will result in a packet length mismatch issue or dropping by the remote PE router when HDLCoverMPLS runs over the Ethernet link adding an additional padding which cannot be classified at all.

Workaround: Use SIP-400.

- CSCuj87734

Symptom: NVRAM startup configuration fails to load.

Conditions: This symptom occurs on enabling the service compress configuration.

Workaround: Disable the compress configuration CLI and save the configuration and reload the chassis. The chassis comes up with the NVRAM configuration.

- CSCuj88523

Symptom: In a pseudowire redundancy configuration, traffic may fail to flow after a switchover to a backup pseudowire.

Conditions: This symptom occurs on the Cisco 7600 series routers.

Workaround: Execute the following commands on the attachment circuit interface:

- **shutdown**

- **no shutdown**
- CSCuj89036
 

Symptom: IOSd crashes following an OIR of an eToken..

Conditions: This symptom occurs during OIR activity on either USB port of a single eToken.

Workaround: Do not OIR an eToken.

More Info: When an eToken is inserted, files on the eToken need to be recursively scanned to build up the master file directory structure. This recursive scanning and building the database can take a very long time depending on the eToken contents. When dual IOSd redundancy mode is enabled, this process appears to take almost twice as long and can easily go over 10 seconds to trip off the IOSd watchdog timeout. Fix is to allow other processes to take over CPU so watchdog timeout will not happen.
- CSCuj94571
 

Symptom: To run the BERT test, remove **keepalive** from the interface. After completing the BERT test, adding **keepalive** causes the standby RSP to reset.

Conditions: This symptom is consistent and affects 15.1(3)S1.

Workaround: After the completion of the BERT test, remove the BERT test with "**no bert pattern qrss interval interval**" and then add **keepalive**. This will avoid standby RSP reset.
- CSCuj96186
 

Symptom: When auto-tunnel and RSVP graceful restart are configured, the standby crashes after an SSO (NSR is not configured).

Conditions: This symptom occurs under the following conditions:

  - Configure auto-tunnel
  - Configure RSVP graceful restart without NSR
  - Perform an SSO

Workaround: Disable RSVP graceful restart or remove the auto-tunnel configuration.
- CSCuj99537
 

Symptom: Not all LI streams that are properly configured via SNMPv3 and appropriate ACLs and are programmed in TCAM, are intercepted and forwarded towards MD.

Conditions: This symptom occurs in an SIP-400 based LI.

Workaround: Remove and reapply the problematic tap but it doesn't prevent the problem from reoccurring if new LI taps are applied via SNMPv3
- CSCul04006
 

Symptom: The c7600rsp72043 router crashes while booting from the bootdisk with the following error message:

```
Unable to open file to add LC tar
bootdisk:c7600rsp72043-advipservicesk9-mz.152-4.S3a.bin
```

Conditions: This symptom occurs while booting from the "bootdisk" on a c7600rsp72043 router.

Workaround:

  1. After the new image file or the image file which is to be upgraded is copied to "sup-bootdisk", run the verify command to check that the new image file is copied properly. "verify /md5 sup-bootdisk:/<new-image-file> <expected-checksum>". The expected checksum can be found from the CCO site. If "verify" succeeds, then the new image can be booted.

2. Format “sup-bootdisk” and copy the new image to “sup-bootdisk” and run the “verify” command as mentioned above. If “verify” succeeds, then the boot can be tried.
- CSCul04692  
Symptom: A T1 controller flaps in CHT1/ET1 SPA.  
Conditions: This symptom is seen in T1 mode with “cablelength short 100ft” or “cablelength long 0db” when connected with a PURA box.  
Workaround: Configure “cablelength long -7.5db”.
  - CSCul11738  
Symptom: Scaling to maximum number of TE tunnels fails.  
Conditions: This symptom occurs when there are sufficient tail-end tunnels on the node.  
Workaround: There is no workaround.
  - CSCul11961  
Symptom: While performing an ISSU super-pkg downgrade with broadband IP-based session features from Cisco IOS XE Release 3.12.0 to Cisco IOS XE Release 3.11.0, standby FP gets stuck in an “init” state after run version. There are Standby FP pending issues.  
Conditions: This symptom occurs while performing an ISSU super-pkg downgrade with broadband IP-based session features from Cisco IOS XE Release 3.12.0 to Cisco IOS XE Release 3.11.0.  
Workaround: There is no workaround.  
More Info: The issue will not occur in the following cases:
    1. ISSU sub-pkg upgrade or downgrade between XE311 and XE312.
    2. ISSU sup-pkg upgrade from XE311 to XE312.
    3. PPP-session features in ISSU super-pkg upgrade or downgrade between XE311 and XE312.
 The upgrade from 3.11.0(without the fix for CSCul11961) to 3.12(with the fix of CSCul11961) works fine.  
The downgrade from 3.12(with the fix of CSCul11961) to 3.11.0(without the fix for CSCul11961) fails with IP-based sessions. With this downgrade bug for 3.11.0, the fix will go out in 3.11.1 and 3.12.0.
  - CSCul11995  
Symptom: An L2TPv3 session fails to establish and Cisco IOS receives a StopCCN message from the peer with the following message in response to its ICRP message:  

```
"No handler for attr 68 (68)"
```

  
Conditions: This symptom occurs when IOS device peers with non-IOS devices send IETF L2TPv3 Pseudowire Type AVP (IETF AVP 68) in an ICRP message.  
Workaround: There is no workaround.
  - CSCul12583  
Symptom: L4R is not removed after an account logon when DRL is present.  
Conditions: This symptom occurs if per user merge is present.  
Workaround: There is no workaround.
  - CSCul24025  
Symptom: A Cisco ASR 1000 Series router crashes when the **ip sla udp-jitter** command is unconfigured.

Conditions: This symptom occurs when 1000+ IP SLA udp-jitter is configured and then all unconfigured immediately.

Workaround: There is no workaround.

- CSCu124682

Symptom: L2TP LNS puts a non-negotiated magic number to LCP packets. The PPPoE client may terminate the session prematurely due to the unknown magic number.

Conditions: This symptom occurs when L2TP LAC does not negotiate the magic number with the PPPoE client and L2TP LNS does not renegotiate options with the PPPoE client.

Workaround: Configure **lcp renegotiation always** on L2TP LNS.

- CSCu127327

Symptom: On the Cisco c7600 router, if PIM is configured on the port-channel and on the port members, any failure on one of the port members will disable the FE CAM.

Conditions: This symptom occurs when PIM is configured on the port members.

Workaround:

1. Do not configure PIM sparse-mode on the port members even though the CLI is accepted.
2. In case the PIM sparse-mode is configured on the port members, remove it from the port members and the port-channel and then reapply the PIM configuration on the port-channel only.

Further Problem Description: A similar issue (CSCt75608) is seen on the Cisco Catalyst 6500 Series Switches, but the workaround is to configure PIM on the port-channel and the port members to avert the FE CAM to be disabled in the event of one of the port members failing.

- CSCu131953

Symptom: The wrong value is fetched for plaintext mtu of IPsec SA.

Conditions: This symptom occurs while configuring Cisco Group Encrypted Transport VPN(GETVPN) within LISP network.

Workaround: There is no known workaround.

- CSCu138081

Symptom: In a scaled environment, when a preferred path configuration is removed and is followed by a RP switchover the pseudowire interfaces goes down. The pseudowire interface comes up if we add the preferred path or just remove and add the neighbor statement.

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.

- CSCu140176

Symptom: PBR next-hop verify availability for global does not work after a reload.

Conditions: This symptom occurs in **show run** after a reload.

Workaround: There is no workaround.

- CSCu140898

Symptom: After reloading the router or fresh service-instance configuration, traffic received from the access is sent to the core without a dummy VLAN header. This traffic is received by a remote PE2 and sent to switch with a missing VLAN header. Therefore CE2 drops received packets. When the issue is removed, captured traffic in the core contains a dummy VLAN header.

Conditions: This symptom is occasionally observed when the router is reloaded and is consistently observed when a new service instance is configured as an xconnect member.

Workaround: Perform **shutdown** followed by **no shutdown** on the service instance.

- CSCul42480

Symptom: A router crashes upon booting due to lack of memory for the image.

Conditions: There are no specific conditions for this symptom.

Workaround: There is no workaround.

- CSCul47135

Symptom: On Cisco ASR 1000 routers, services are not removed or applied from the active subscriber sessions when CoA is sent from the radius server. The router sends wrong values in response to the CoA request packet.

Conditions: This symptom occurs when 15.2(20130918:081157) is run.

Workaround: There is no workaround.

- CSCul49852

Symptom: A router might see PPPoE-sessions in the WAITING\_FOR\_STATS (or WT\_ST) status.

Conditions: This symptom was observed by specific users or because of using a specific profile or service like ShellMaps and Radius. The system is configured as BRAS aggregating PPPoEoA or -oE-sessions.

Workaround: There is no workaround.

- CSCul50910

Symptom: After a random reload of chassis or SPA Gig on SPA-5X1GE-V2 loses L3 connectivity and ARP protocol failing.

Conditions: This symptom is observed in the Cisco 7600 router with SPA-5X1GE-V2.

Workaround: Reload SIP with SPA loaded in it.

- CSCul52239

Symptom: Multicast traffic might get affected after an interface delete and reconfiguration. This is more likely to happen in dot1q sub-interfaces in ES+ and specifically only if the delete and reconfiguration of the interface is done within 30 seconds.

Conditions: This symptom occurs in Cisco IOS Release 12.2SREx and Cisco IOS 15S based releases.

Workaround: Perform interface delete and reconfiguration with a time gap of one minute.

More Info: How to check whether the issue is hit:

Note down the interface's internal vlan:

```
PE2#sh vlan int usage | i GigabitEthernet2/24.904 2000 GigabitEthernet2/24.904
Get to SP console and do "sh fid start <internal vlan> end <internal vlan>
PE2-sp#sh fid start 2000 end 2000 FID Id Protocol Bkt Enabled FE CAM Enabled Vlan
Don't Learn Age group -----
----- 2000 no no 2000 yes 0x00
```

The issue is hit if "FE CAM Enabled" bit is set to "no".

- CSCul56207

Symptom: A standby RP crashes.

Conditions: This symptom is seen on a Cisco ASR 1000 router used for PPPoEoA-aggregation when configuring a range/pvc. It was seen together with the following error message:

```
asr(config-if-atm-range)pvc-in-range 10/45 %ERROR: Standby doesn't support this
command ^ % Invalid input detected at '^' marker.
```

Workaround: There is no workaround.

- CSCul65614

Symptom: The FAN-MOD-6SHS module consumes more power than expected (should be around 180W).

```
#sh power <SNIP> Fan Type Watts A @42V State ----
----- 1 FAN-MOD-6SHS 427.14 10.17 OK
```

Conditions: This symptom occurs when the ES+ Combo card is placed in slot-1 of 7600 chassis.

Workaround: Place ES+ Combo cards in any other slot other than slot-1 of 7600 chassis.

- CSCul72121

Symptom: Continuous trace backs on the PTF console is observed and PTF crashes during a soak.

Conditions: This symptom occurs under the following conditions:

1. Create an MDS profile as attached.
2. Leave the setup for soak for 12 hours.

Workaround: Reload ACT and SBY PTF.

- CSCul86211

Symptom: When LNS switches off while the sessions keep on establishing at LAC, LAC finds the l2tp db memory exhausted after sometime. Due to this, it fails to update the session in the database and during this period a crash is observed.

Conditions: This symptom occurs when LAC tries to add l2tp session in the database and fails to do so. In order to handle this error condition, LAC frees the l2tp and l2x session twice. This double free is the reason for crash.

Workaround: There is no workaround.

- CSCul87037

Symptom: An “sg subrte conte” chunk leak occurs while roaming.

Conditions: This symptom occurs after an account-logout and if service permit is configured in control policy. In case of a service permit, the subscriber remains unauth and is redirected to the portal once again. Post successful second account logon and the subscriber session is cleared by timeout or cli, the leak is seen and the same client will not be able to create the session once again. The leak is seen after simulating for the second time account-logon. And if service permit is configured.

In case of service disconnect configured under account-logout, account-logon is not a practical scenario as the portal is not reachable for the client.

Workaround: Use **service disconnect** for **event account-logout**.

```
class type control always event account-logout
1 service disconnect delay 10
!
```

- CSCul92497

Symptom: The Cisco 7600 router providing layer2 EoMPLS services may stop forwarding ingress and egress traffic for an xconnect for which a backup peer config has been applied.

Conditions: This symptom occurs in Cisco 7600 routers running Cisco IOS Release 15.2(4)S4a with ES+ cards (access/core facing) and xconnect configured under a service instance.

Workaround: Clear the xconnect on the Cisco 7600 router side. Clearing on the remote side does not have an effect.

- CSCul94087

Symptom: Output Packet drops is observed on the ATM IMA interface even when there is no live traffic and only signaling exchange between non-Cisco devices. Although output drops in most cases means low bandwidth issues but in this case, an entire site was down due to these drops.

Conditions: This symptom occurs under the following conditions:

1. Layer 2 cross connect is configured on Cisco device and Non-Cisco device at other end.
2. Only signaling traffic flows through the devices.
3. IMA group is created for the ATM connectivity.
4. SPA-24CHT1-CE-ATM card is to be used for the ATM connection.

Workaround: Reload the SPA.

- CSCul99015

Symptom: In VPLS using BGP signaling with Inter AS, when a PE on another AS is reachable through multiple ASBRs, the PW destination and the next hop PE address of some or all of the PWs in the standby RP remains as the non-preferred ASBR address instead of the preferred ASBR address.

Conditions: This symptom occurs under the following conditions: 1. BGP L2VPN NLRIs received first from an ASBR becomes a less preferred ASBR on receiving NLRIs for the same VE-IDs from a more preferred ASBR. 2. NLRI received from the more preferred ASBR has the same values (VEID, VBO, VBS, Label Base, MTU and CW) as the ones received previously from the other ASBR.

Workaround: Bring up the BGP session with the more preferred ASBR first. This would cause no updates to existing NLRIs even if received from other less preferred ASBRs.

- CSCum00056

Symptom: ASR IOSd crash occurs with the following error:

```
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = ISG CMD HANDLER
```

Conditions: This symptom occurs when changes are made through RADIUS.

Workaround: There is no workaround.

- CSCum04512

Symptom: When an RP switchover is done (which is head end for 500 TE tunnel and tail end for 500 TE tunnels), the RSVP label is assigned to the TE tunnel change and this in turn causes a traffic loss of 45 seconds on the pseudowire which is directed through these tunnels.

Conditions: This symptom occurs under the following conditions:

- TE RID under the IGP is configured as a loopback other than the first one.
- SSO is performed.

Workaround: Configure the TE router ID under the IGP to be the first loopback interface.

- CSCum11118

Symptom: A Cisco ISR router crashes due to stack overflow in the “ADJ background” process. The following syslog may be seen just before the crash:

000105: Dec 9 04:08:44.447 UTC: SYS-6-STACKLOW Stack for process ADJ background running low, 20/6000

Conditions: The conditions to this symptom are unknown.

Workaround: There is no workaround.

- CSCum16315

Symptom: Upon reload of a Cisco 7600 router configured with a CoPP policy containing IPv6 ACLs and DSCP matching, the CoPP is only applied to the active RSP as shown below.

After reload:

```
lab-7609-rsp-02#sh mod power Mod Card Type Admin Status Oper Status ---
----- 1 CEF720 48 port
10/100/1000mb Ethernet on on 5 Route Switch Processor 720 (Active) on on 6 Route
Switch Processor 720 (Hot) on on 7 CEF720 8 port 10GE with DFC on on 8 CEF720 8 port
10GE with DFC on on
```

CoPP is applied to only the active RSP/SUP after reload:

```
lab-7609-rsp-02#sh policy-map control-plane in | inc class|Earl class-map:
COPPCLASS_MCAST (match-any) Earl in slot 5 : class-map: COPPCLASS_MGMT (match-any)
Earl in slot 5 : class-map: COPPCLASS_ALLOW_ICMP (match-any) Earl in slot 5 :
class-map: COPPCLASS_MONITORING (match-any) Earl in slot 5 : class-map:
COPPCLASS_FILEXFER (match-any) Earl in slot 5 : class-map: COPPCLASS_REMOTEACCESS
(match-any) Earl in slot 5 : class-map: COPPCLASS_OSPF (match-any) class-map:
COPPCLASS_LDP (match-any) Earl in slot 5 : class-map: COPPCLASS_BGP (match-any)
class-map: COPPCLASS_MISC (match-any) class-map: COPPCLASS_UNDESIRABLE (match-any)
Earl in slot 5 : class-map: COPPCLASS_IPV4_CATCHALL (match-any) Earl in slot 5 :
class-map: COPPCLASS_IPV6_CATCHALL (match-any) class-map: class-default (match-any)
Earl in slot 5 :
```

When this issue is triggered, the following error will be seen in the logs:

```
*Dec 14 02:33:14.579: %QM-2-TCAM_BAD_LOU: Bad TCAM LOU operation in ACL
```

This issue potentially exposes the device to a DoS vulnerability.

Conditions: This symptom occurs under the following conditions:

1. 7600 HA Environment.
2. CoPP IPV6 ACL with DSCP match.
3. Reload or Switchover.

Workaround: There are two workarounds for this issue.

1. Modify the CoPP Policy to remove IPV6 ACL/DSCP matching.
2. Remove and reapply the CoPP configuration as shown below:

```
lab-7609-rsp-02(config)#control-plane
lab-7609-rsp-02(config-cp)#no service-policy in COPP
lab-7609-rsp-02(config-cp)#service-policy in COPP
lab-7609-rsp-02(config-cp)#end
```

CoPP is applied to all modules as required:

```
lab-7609-rsp-02#sh policy-map control-plane in | inc class|Earl class-map:
COPPCLASS_MCAST (match-any) Earl in slot 1 : Earl in slot 5 : Earl in slot 7 : Earl in
slot 8 : class-map: COPPCLASS_MGMT (match-any) Earl in slot 1 : Earl in slot 5 : Earl
in slot 7 : Earl in slot 8 : class-map: COPPCLASS_ALLOW_ICMP (match-any) Earl in slot
1 : Earl in slot 5 : Earl in slot 7 : Earl in slot 8 : class-map: COPPCLASS_MONITORING
(match-any) Earl in slot 1 : Earl in slot 5 : Earl in slot 7 : Earl in slot 8 :
class-map: COPPCLASS_FILEXFER (match-any) Earl in slot 1 : Earl in slot 5 : Earl in
```





Conditions: This symptom occurs when port-channel member links are on the same NP.

Workaround: There is no workaround.

- CSCum46850

Symptom: Using LISP set tags on routes imported to the RIB when exporting LISP routes from the RIB to BGP fails.

Conditions: This symptom occurs when redistribute list route-map is used under bgp with a route-map that contains match tag.

Workaround: There is no workaround.

- CSCum62783

Symptom: The following alignment errors are seen after a PPPoE session establishment for the first time after a reboot:

```
*Jan 14 07:24:40.591: %ALIGN-3-CORRECT: Alignment correction made at 0x32B2DFF4z
reading 0xE7790ED *Jan 14 07:24:40.591: %ALIGN-3-TRACE: -Traceback= 0x32B2DFF4z
0x32B1E274z 0x32B1EECCz 0x32B1EF90z 0x332E550Cz 0x332E54F0z 0xFFFF1A00z 0xFFFF1A00z
```

Conditions: This symptom occurs when **pppoe-client ppp-max-payload** is configured under the Ethernet interface.

Workaround: There is no workaround.

- CSCum65501

Symptom: IPv6 CoPP ACL in PI matches traffic incorrectly for sw-switched paks. Packets are not hit against IPv6 ACE matching on L4 protocol. This causes traffic to be classified incorrectly.

Conditions: This symptom occurs with recent Cisco IOS images. Results are as expected on Cisco IOS Release 12.2(33)SRE9a. However, it is broken in Cisco IOS Release 15.2(4)S4a onwards.

Workaround: There is no workaround.

- CSCum67166

Symptom: The router hangs after loading an image.

Conditions: This symptom occurs with the latest whales-universal-mz mcp\_dev image.

Workaround: There is no workaround.

- CSCum85813

Symptom: Shut primary static router and secondary static is not installed automatically.

Conditions: This symptom is seen on the sites where the BFD state of the backup static route is marked as “U” in the output of “show ip static route bfd”.

Workaround: Reinstall the default backup static route.

- CSCun38333

Symptom: Locator ID Separation Protocol (LISP) local EID database locator configured through the "**database-mapping <eid-prefix> ipv6-interface <interface> priority <priority> weight <weight>**" command uses deprecated IPv6 address on specified interface.

Conditions: Multiple IPv6 addresses available on an interface with the lexicographically first address being deprecated.

Workaround: There is no workaround.

- CSCun57668

Symptom: LISP local EID database locator configured through the **database-mapping** *<eid-prefix>* **ipv6-interface** *<interface>* **priority** *<priority>* **weight** *<weight>* command can be a deprecated IPv6 address on a specified interface.

Conditions: This symptom is observed in multiple IPv6 addresses available on an interface with the lexicographically first address being deprecated.

Workaround: There is no workaround.

## Open and Resolved Bugs - Cisco ASR 901 Series Routers in 15.4(2)S

For detailed information on Open and Resolved bugs on Cisco ASR 901 Series Routers in 15.4(2)S, see the following document:

[https://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901/Release/Notes/b-901-rn-15-4-2.html](https://www.cisco.com/c/en/us/td/docs/wireless/asr_901/Release/Notes/b-901-rn-15-4-2.html)

## Open and Resolved Bugs - Cisco ASR 901 S Series Routers in 15.4(2)S

For detailed information on Open and Resolved bugs on Cisco ASR 901 S Series Routers in 15.4(2)S, see the following document:

[https://www.cisco.com/c/en/us/td/docs/wireless/asr\\_901s/scg/b\\_scg\\_for\\_asr901s.html](https://www.cisco.com/c/en/us/td/docs/wireless/asr_901s/scg/b_scg_for_asr901s.html)

## Open and Resolved Bugs - Cisco ME 3600x and ME 3800x Series Routers in 15.4(2)S

For detailed information on Open and Resolved bugs on Cisco ME 3600x and Cisco ME 3800x Series Routers in Cisco IOS Release 15.4(2)S, see the following document:

<http://www.cisco.com/c/en/us/support/switches/me-3600x-series-ethernet-access-switches/products-release-notes-list.html>



# Bugs for Cisco IOS Release 15.4(1)S

## Open and Resolved Bugs

Bugs describe unexpected behavior in Cisco IOS software releases. Severity 1 bugs are the most serious bugs; severity 2 bugs are less serious. Severity 3 bugs are moderate bugs, and only select severity 3 bugs are included in this section.

In this section, the following information is provided for each bug:

- Symptoms—A description of what is observed when the bug occurs.
- Conditions—The conditions under which the bug has been known to occur.
- Workaround—Solutions, if available, to counteract the bug.



### Note

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select bugs of any severity. To reach the Bug Toolkit, log in to [Cisco.com](http://www.cisco.com) and go to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl). (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

This section consists of the following subsections:

- [Open Bugs—Cisco IOS Release 15.4\(1\)S3, page 141](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(1\)S3, page 142](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(1\)S2, page 144](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(1\)S1, page 168](#)
- [Open Bugs—Cisco IOS Release 15.4\(1\)S, page 181](#)
- [Resolved Bugs—Cisco IOS Release 15.4\(1\)S, page 181](#)
- [Open and Resolved Bugs - Cisco ASR 901 Series Routers in 15.4\(1\)S, page 227](#)
- [Open and Resolved Bugs - Cisco ASR 901 S Series Routers in 15.4\(1\)S, page 227](#)
- [Open and Resolved Bugs - Cisco ME 3600x and ME 3800x Series Routers in 15.4\(1\)S, page 227](#)

## Open Bugs—Cisco IOS Release 15.4(1)S3

*Table 1 Open Bugs—Cisco IOS Release 15.4(1)S3*

Identifier	Description
<a href="#">CSCur32628</a>	7600 mis-programming causing intermittent packet loss
<a href="#">CSCur70478</a>	Software crash at <code>ldpx_mem_reallocz_grow</code> due to insufficient memory
<a href="#">CSCur77750</a>	CSCtc51539 happening again on SRE6 onwards
<a href="#">CSCur53326</a>	ASR crash at "IP Inband Session Initiator"

Identifier	Description
<a href="#">CSCUh92882</a>	XE3.11 Seginfo->l2hw_cond_debug is set to "1" when there is no condition
<a href="#">CSCur68259</a>	XE3.13 : Subscribers not pingable after 2nd "clear ip route vrf x *"
<a href="#">CSCua76379</a>	%SYS-3-DUP_TIMER: Same tty1 in linewatch_timers errors in log.

## Resolved Bugs—Cisco IOS Release 15.4(1)S3

*Table 2 Resolved Bugs—Cisco IOS Release 15.4(1)T3*

Identifier	Description
<a href="#">CSCup01885</a>	ASR Reboots Once A week
<a href="#">CSCug18580</a>	ASR1k crash: UNIX-EXT-SIGNAL SEGFAULT, Process = AAA ACCT Proc
<a href="#">CSCup42385</a>	HA fails due to Bulk synch failure with encrypted password
<a href="#">CSCup98776</a>	ASR1K outbund SA creation failure & ESP not processing further requests
<a href="#">CSCup53658</a>	ASR1k qinq subinterface stats do not work on Port Channel
<a href="#">CSCuo56871</a>	ASR route server crashes due in BGP task
<a href="#">CSCun92095</a>	asr1001x crashes when unconfiguring MPLS LDP scale config
<a href="#">CSCug08566</a>	BGP does not advertize a global static route pointing to a vrf intf
<a href="#">CSCuo53561</a>	BGP failed to apply inbound route-map on prefixes after switch over
<a href="#">CSCuo76187</a>	BGP sends out VPN invalid update without label in MP_REACH
<a href="#">CSCuq24984</a>	In rare high BGP update churn case, sh ip bgp x.x.x.x may crash
<a href="#">CSCup52988</a>	InterAS OptionB ASBR does not allocate label for VPNv4 prefix
<a href="#">CSCun68542</a>	invalid prefixes learned from RR with bgp add-path feature enabled
<a href="#">CSCun58072</a>	ifOutOctets go backwards when output drop happens on FR subintf
<a href="#">CSCuq17550</a>	ISRG2-GETVPN-IPv6 Egress IPv6 Interface ACL checked before encryption
<a href="#">CSCup70579</a>	Malformed mDNS packet may cause a reload
<a href="#">CSCuj31290</a>	Packet of Disconnect is Broke after upgrade from 15.1 to 15.2
<a href="#">CSCup89513</a>	Router crash at dual_routeupdate
<a href="#">CSCul70788</a>	Router crashes when calculating the best cost successor in EIGRP DUAL
<a href="#">CSCup06433</a>	Selection of wrong LFA leads to crash during deletion of LFA
<a href="#">CSCul22914</a>	ISR4451-X FIPS: Crypto Device power-up KAT selftests broken
<a href="#">CSCuq93406</a>	IOSd crash on Ethernet CFM receiving a malformed CFM frame
<a href="#">CSCul11486</a>	isrg2 reloaded while quering the objects of ieee8021CfmStackTable
<a href="#">CSCuo49923</a>	c4mk13:Device crash with Unexpected exception to CPU after RV.
<a href="#">CSCun88267</a>	need particle version of reg_invoke_fast_ipwrite() to avoid Q wedge

Identifier	Description
<a href="#">CSCuo84660</a>	copy command yields DATACORRPUTION error
<a href="#">CSCuq96691</a>	Utah crash during ezconfig installation.
<a href="#">CSCup22487</a>	Multiple Vulnerabilities in BinOS OpenSSL - June 2014
<a href="#">CSCun75719</a>	c4mk2: Device getting crashed after rpr and sso.
<a href="#">CSCuj96546</a>	c4mk2:Packet drop with egress WCCP GRE red/L2 ret/Hash assign after sso
<a href="#">CSCuo48507</a>	ISSU:XE310<->XE311 Packet drops seen with ikev2_dvtn after switchover
<a href="#">CSCuh07579</a>	IPSec fails to delete/create SAs due to IPSec background process stuck
<a href="#">CSCup51813</a>	XR Control Packets and Data packets getting dropped on rekeying
<a href="#">CSCuq46955</a>	IOS ISR AM IKEv1 doesnt work with rsa-sig
<a href="#">CSCup94123</a>	ISSU:XE311->XE312 pseudo_wire VC status and LDP are down after RP SWO
<a href="#">CSCum45122</a>	mvpn6: ipv6 mfib stale entry on PE after toggling address-family
<a href="#">CSCum01661</a>	MPLS Traffic drop after SSO, Label is NONE with IPFRR config
<a href="#">CSCuo97889</a>	Traffic is getting drop after TE-SSO
<a href="#">CSCui85237</a>	C3900 router crashed with MQC mode with mix of protocols
<a href="#">CSCuj40124</a>	crash@stile_mtp_dp_post_cls_run when sending the specific pcap file
<a href="#">CSCum45864</a>	MTP signatures failed due to addition on new custom MTP fields
<a href="#">CSCum66102</a>	Router crashes @ stile_free_cnbar_protocols
<a href="#">CSCui05056</a>	SYS-6-STACKLOW due to NBAR config
<a href="#">CSCup49206</a>	Conditional Default route getting flushed on peer performing SSO on UUT.
<a href="#">CSCup04305</a>	Router Crash seen @ __be_ospf_schedule_rtr_lsa
<a href="#">CSCuo83510</a>	Stack overflow detected at ospfv3_router_process upon boot with NBMA cfg
<a href="#">CSCuo37123</a>	PIM process sends out huge Hello bursts after SSO switchover on 7600
<a href="#">CSCuq64710</a>	Large memory leak on RP SSS/SSM processes during pppoe churn
<a href="#">CSCui45885</a>	NAT SIP ALG is translating SIP headers when the service is disabled.
<a href="#">CSCun52430</a>	FFM: Queue-limit not getting updated during unconfig
<a href="#">CSCui23670</a>	Even if show sup-bootdisk is executed, nothing is displayed.
<a href="#">CSCuc68034</a>	IO Memory Leak on FlexWan WS-X6582-2PA exec 'sh cef interface internal'
<a href="#">CSCuo93711</a>	ASR Standby RP - RSVP severely leaking memory
<a href="#">CSCup22590</a>	Multiple Vulnerabilities in IOS/IOSd OpenSSL - June 2014
<a href="#">CSCup86552</a>	Issue with qos service installation

Identifier	Description
<a href="#">CSCup52725</a>	XE3.13: asr1k RP Crash while 72 hour longevity run
<a href="#">CSCup98776</a>	ASR1K outbund SA creation failure & ESP not processing further requests
<a href="#">CSCuq17550</a>	ISRG2-GETVPN-IPv6 Egress IPv6 Interface ACL checked before encryption
<a href="#">CSCul22914</a>	ISR4451-X FIPS: Crypto Device power-up KAT selftests broken
<a href="#">CSCuj96546</a>	c4mk2:Packet drop with egress WCCP GRE red/L2 ret/Hash assign after sso
<a href="#">CSCuo48507</a>	ISSU:XE310<->XE311 Packet drops seen with ikev2_dvti after switchover
<a href="#">CSCuh07579</a>	IPSec fails to delete/create SAs due to IPSec background process stuck
<a href="#">CSCup51813</a>	XR Control Packets and Data packets getting dropped on rekeying
<a href="#">CSCuq46955</a>	IOS ISR AM IKEv1 doesnt work with rsa-sig
<a href="#">CSCup22590</a>	Multiple Vulnerabilities in IOS/IOSd OpenSSL - June 2014

## Resolved Bugs—Cisco IOS Release 15.4(1)S2

- [CSCee32792](#)

Symptom: A Cisco router reloads at `snmp_free_variable_element` while using SNMPv3 commands.

Conditions: This symptom occurs while using SNMPv3 commands.

Workaround: There is no workaround.
- [CSCtq21722](#)

Symptom: A Cisco switch may reload when configured for SNMP.

Conditions: This symptom is observed when SNMP inform hosts are configured.

Workaround: Remove the SNMP host configurations for SNMP informs.

Example: `no snmp-server host x.x.x.x informs version 2c <removed>`
- [CSCtx82890](#)

Symptom: After removing the encapsulation on MFR member interface, tracebacks are observed.

Conditions: This symptom is observed when serial interface is configured with FR MLP configuration.

Workaround: There is no workaround.
- [CSCtz45833](#)

Symptom: A Cisco router crashes with the following message:

```
Router crash: UNIX-EXT-SIGNAL: Segmentation fault(11), Process = MPLS TE LM
```

Conditions: This symptom occurs when a router acts as the mid point for MPLS-TE tunnels and performs an ERO expansion. In case the ERO expansion fails (due to IGP race conditions or inter-AS scenario) and backup tunnels are in use (for MPLS-TE FRR feature), the router may crash.



Workaround: Configure the head-ends to perform a full ERO computation to avoid mid points performing any ERO expansion. This can be done using the dynamic path option or by using the explicit path that specifies strict hops for each node along the desired LSP path (using “loose” hops or partial strict hops can lead to this issue).

- CSCtz97771

Symptom: During regular operations, a Cisco router running Cisco IOS release 12.4(24)T and possibly other releases experiences a crash. The crash info will report the following:

```
%SYS-2-FREEFREE: Attempted to free unassigned memory at 4A001C2C, alloc 4180794C,
dealloc 417616B0,
%SYS-6-BLKINFO: Attempt to free a block that is in use blk 4A001BFC, words 134, alloc
4180794C, Free, dealloc 417616B0, rfcnt 0,
```

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.

- CSCuc21859

Symptom: Memory leak is seen at `ssf_owner_get_feature_sb`.

Conditions: This symptom occurs when the discriminator configuration is with logging, as given in the below examples:

```
logging discriminator <NAME>
logging host x.x.x.x discriminator DEBUG
logging discriminator SysLog mnemonics drops NAME
```

Workaround: Remove the discriminator configuration from the logging configuration.

- CSCuc60868

Symptom: A router randomly crashes either due to memory corruption at `bgp_timer_wheel` or memory chunks near `bgp_timer_wheel` (for example, BFD event chunks if BFD is configured or AtoM Manager chunks if LDP is configured). A crash occurs right after an LDP neighbor is up in the L2VPN setup.

Conditions: This symptom occurs when **vpls bgp signaling** is unconfigured and then reconfigured. Both L2VPN and BGP are unconfigured and reconfigured after all L2VPN and BGP data structures are fully deleted (about 3 minutes for 5 BGP VPLS prefixes). For the repro on file, OSPF (for IGP) is also unconfigured and reconfigured. Both LDP and BGP signaling are affected by this bug.

Workaround: Avoid unconfiguring and reconfiguring BGP L2VPN.

- CSCue23898

Symptom: A Cisco router running Cisco IOS Release 15.3(1)T may crash with a bus error immediately after issuing the **write memory** command.

```
Example: 14:44:33 CST Thu Feb 14 2013: TLB (load or instruction fetch) exception, CPU
signal 10, PC = 0x228B2C70
```

Conditions: This symptom occurs while updating the router’s running configuration with the **write memory** command.

It has been seen while updating various different commands such as, those under “call-manager-fallback” ip route statements interface subcommands

Workaround: There is no workaround.

- CSCuh45042
 

Symptom: Traffic on some GIG subinterfaces are seen to be dropped at the SPA. The SPA TCAM is seen to have two entries sharing the same logical address as a result of which one entry is seen to overwrite the other.

Conditions: This symptom was observed after a router/LC/SPA reload. The exact condition that triggers this symptom is not known.

Workaround: There is no workaround.
- CSCuh87195
 

Symptom: A crash is seen on a Cisco router.

Conditions: The device crashes with gw-accounting and call-history configured. The exact conditions are still being investigated.

Workaround: Perform the following workaround:

  1. Completely remove gw-accounting
  2. Disable call-history using the following commands:

```
gw-accounting file
no acct-template callhistory-detail
```
- CSCui05000
 

Symptom: A Cisco router may crash upon importing a prefix into VRF after applying **no ipv4 multicast multipotology** under “vrf definition” for that VRF.

Conditions: This symptom occurs while initially configuring the VRF. **address-family ipv4/6 multicast vrf** must be configured under “router bgp” mode before import route-targets are configured under “vrf definition” mode.

Workaround: There is no workaround.

More Info: If the crash does not occur, it is likely that importing of the prefix will not work.
- CSCui12822
 

Symptom: The version of the GCC compiler (tool) used for builds in CEL 5.50 needs to be updated to a version that can work on CEL 5.50.

Conditions: This symptom does not occur under specific conditions.

Workaround: Update the version of the GCC compiler to a version that can work on CEL 5.50
- CSCui23099
 

Symptom: A Cisco router with an etherswitch module installed may have the internal interface from the router to the switch become wedged. This will cause any traffic which needs to be process switched to not work. In addition further traffic will throttle the interface.

This example is from a router in the lab. It is a 2811 with a NME-16ES-1G-P installed. This adds a new interface on the router which allows traffic from the etherswitch to the router. When specific traffic is send the interface becomes wedged. The telltale sign of the interface being wedged is having the input queue report more traffic than the size of the queue itself. For example:

```
GigabitEthernet1/0 is up, line protocol is up
Input queue: 76/75/585/0 (size/max/drops/flushes);
Total output drops: 0 0 runts, 0 giants, 585 throttles
```

Conditions: The exact conditions which cause this are unknown, but this has been seen with Wake On LAN (WOL) traffic being sent from a device connected to the etherswitch.

Workaround: Currently there is no work around other than to block the traffic.

- CSCui29745  
Symptom: Member links under MLPPP go down as the LCP negotiation of those PPP links fails.  
Conditions: This symptom occurs after the router reloads and the traffic is flowing through the multilink.  
Workaround: Reload SPA/LC on the other end of the link.
- CSCui34165  
Symptom: Port-channel QoS features might fail to work after a router reload, followed by QoS configuration modification.  
Conditions: This symptom occurs when a VLAN load-balanced port-channel is used with policy aggregation configuration where the QoS policy is configured on member links and the port-channel subinterface, and after a system reload (configuration is from startup configuration).  
Workaround: Reload the router without port-channel QoS configuration, and add port-channel QoS configuration to the running configuration after the router boots up.
- CSCui64807  
Symptom: An active RP crashes during FIB sync because of memory overrun when the standby sup becomes unavailable.  
Conditions: This symptom occurs when redundant RPs are configured in SSO mode and the standby RP becomes unavailable (for instance because of crash or physical removal). The issue occurs only on Cisco 7600 RSP 720, Cisco 7600 Series Supervisor Engine 720, and Cisco 7600 platforms where the tableid “ISSU FOF LC” support is enabled. As of 03/17/2014, the tableid “ISSI FOF LC” feature is only supported on SY releases. This issue does not impact Cisco ASR 1000 Series platforms.  
Workaround: There is no workaround.
- CSCui83823  
Symptom: When CU executes “show tech” or any show commands which gives a long output using putty, the SSH2 putty closes prematurely.  
Conditions: This symptom is observed when “term length 0” is enabled. The putty session closes prematurely while executing “show tech show memory”.  
Workaround: Redirect the output to a file.
- CSCuj19201  
Symptom: Reregistration time is recalculated on GM nodes upon receiving a TBAR rekey, based on the remaining TEK lifetime at the time of the TBAR rekey.  
This effectively causes a much-shorter re-registration window compared to the one obtained at the GM registration, even if the original TEK lifetime was configured with a long value.  
Conditions: This symptom is observed when TBAR is configured and long TEK lifetime used (more than 7200 seconds).  
Workaround: There is no workaround.
- CSCuj27424  
Symptom: Licensing auto update process CPUHogs/Tracebacks seen while running regression suites.  
Conditions: The CPUHOG will occur when memory traceback CLI are configured, which is as expected. Also a warning is displayed when memory CLI configuration is applied.  
Workaround: There is no workaround.

- CSCuj82897

Symptom: The “control-word” length is not set properly for small HDLC packets running over HDLC AToM VC with SIP-200.

For example: SPA-8XCHT1/E1.

Conditions: This symptom occurs when HDLC AToM VC with SIP-200 is deployed, for example, SPA-8XCHT1/E1, will result in a packet length mismatch issue or dropping by the remote PE router when HDLCoverMPLS runs over the Ethernet link adding an additional padding which cannot be classified at all.

Workaround: Use SIP-400.
- CSCul01067

Symptom: Memory leak occurs in process and I/O memory.

Conditions: This symptom is observed when NTPv6 is configured, for example, “ntp server ipv6 2001::1”

Workaround: Remove the NTPv6 configuration.
- CSCul18552

Symptom: After a switchover, QoS policy map in standby is not synced as in the case of active.

Conditions: This symptom occurs after a switchover.

Workaround: There is no workaround.
- CSCul27924

Symptom: Customer experienced crash on ASR-1001 during normal operation.

Conditions: This symptom is not observed under any specific condition.

Workaround: There is no workaround.
- CSCul32547

Symptom: During NTT EFT customers performed COA with parent session id as key and when it was attempted the Cisco ASR 1000 router reloads with the following trace code:

```
% 0x7fba0ee : __be__doprint % 0x83e8bd4 : __be_vsnprintf % 0x83e8b7a : __be_snprintf %
0x3429013 : __be_encode_cisco_vsa % 0x3428909 : __be_encode_rad_vsa % 0x342b79c :
__be_attrib_op_encode % 0x34451d4 : __be_build_radius_packet_from_list % 0x3444b3b :
__be_build_radius_packet % 0x34432fd : __be_send_radius_pkt % 0x6d629d :
__be_process_response_req % 0x6da280 : __be_process_aaa_request % 0x6d48e6 :
__be_aaa_acct_proc
```

Conditions: This symptom occurs due to continuous printing.

Workaround: There is no workaround.
- CSCul39964

Symptom: Sessions do not get cleared. They get stuck in WT\_ST state.

Conditions: This symptom occurs when sessions are closed in bulk mode by shutting any trunk link or during a clear all session from DUT.

Workaround: There is no workaround.

More Info: The memory leak issue and WT\_ST are related. Along with memory leak, sessions are not cleared on the active RP as they get stuck in WT\_ST state.

```
asr1k-1#sh clock
07:18:07.045 CET Thu Nov 14 2013
asr1k-1#su
```

```

PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:20:08.295 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#
asrlk-1#sh clock
07:46:34.113 CET Thu Nov 14 2013
asrlk-1#su
PTA : Locally terminated sessions
FWDED: Forwarded sessions
TRANS: All other sessions (in transient state)
TOTAL PTA FWDED TRANS
TOTAL 14465 0 6557 7908
GigabitEthernet0/0/0 3024 0 0 3024
GigabitEthernet0/0/1 2587 0 0 2587
GigabitEthernet0/1/0 2297 0 0 2297
GigabitEthernet0/1/1 6557 0 6557 0
asrlk-1#
asrlk-1#s
6557 sessions in FORWARDED (FWDED) State
7908 sessions in WAITING_FOR_STATS (WT_ST) State
14465 sessions totalUniq ID PPPoE RemMAC Port VT
VA State
SID LocMAC VA-st Type
5978 5978 0000.6ca3.0116 Gi0/0/0.2940148 1 Vi2.3091 WT_ST
b414.8901.8e00 VLAN: 294/148 UP
5979 5979 0000.6ca3.0117 Gi0/0/0.2940149 1 Vi2.3092 WT_ST
b414.8901.8e00 VLAN: 294/149 UP
6460 6514 0000.6ca3.0134 Gi0/0/0.2940178 1 Vi2.3354 WT_ST
b414.8901.8e00 VLAN: 294/178 UP
6454 6508 0000.6ca3.0135 Gi0/0/0.2940179 1 Vi2.3350 WT_ST
b414.8901.8e00 VLAN: 294/179 UP
6453 6507 0000.6ca3.0136 Gi0/0/0.2940180 1 Vi2.3349 WT_ST
b414.8901.8e00 VLAN: 294/180 UP
6518 6572 0000.6ca3.0137 Gi0/0/0.2940181 1 Vi2.3395 WT_ST
b414.8901.8e00 VLAN: 294/181 UP
6514 6568 0000.6ca3.0138 Gi0/0/0.2940182 1 Vi2.3393 WT_ST
b414.8901.8e00 VLAN: 294/182 UP
6516 6570 0000.6ca3.0139 Gi0/0/0.2940183 1 Vi2.3394 WT_ST
b414.8901.8e00 VLAN: 294/183 UP
6560 6614 0000.6ca3.013a Gi0/0/0.2940184 1 Vi2.3413 WT_ST

```

- CSCul41442
 

Symptom: In the M train of IOS and the S train of IOS-XE the “media anti-trombone” feature added in Cisco IOS Release 15.1(3)T, CUBE does not appear as an option when configuring “voice class media” groups. It is not present as an option at the dial-peer level as well.

Conditions: This symptom is observed in any non “T” train of IOS and IOS-XE.

IOS Tested 15.2(3)T - Available as media option Tested 15.3(3)M - not there

IOS-XE Tested 15.1(3)T - Available as media option Tested 15.3(3)S1 - not there

Workaround: Customer has to have a “T” train IOS of Cisco IOS Release 15.1(3)T or higher.

More Info: Impacts customers ability to deploy Cube Enterprise solutions.
- CSCul49375
 

Symptom: The Cisco ASR 1000 router displays the following messages in the logs:

```
%IDMGR-3-INVALID_ID: bad id in id_get (Out of IDs!) (id: 0x0) -Traceback=
1#cb40dca901558e45a65b881a8695af4f :400000+8653B3 :400000+893696 :400000+DF330C
:400000+DED89B :400000+DF8643 :400000+1F57F36 :400000+1F4BBFB :400000+1F33BA7
:400000+1F336C1 :400000+1F34FF9 :400000+1F27763 :400000+1F29B16 :400000+2546FF3
:400000+2546EDD :400000+1F2930B
```

No new PPPoE sessions can be established anymore.

Conditions: The conditions to this symptom are unknown.

Workaround: Reload the device.
- CSCul49852
 

Symptom: A router might see PPPoE-sessions in the WAITING\_FOR\_STATS (or WT\_ST) status.

Conditions: This symptom was observed by specific users or because of using a specific profile or service like ShellMaps and Radius. The system is configured as BRAS aggregating PPPoEoA or -oE-sessions.

Workaround: There is no workaround.
- CSCul50910
 

Symptom: After a random reload of chassis or SPA Gig on SPA-5X1GE-V2 loses L3 connectivity and ARP protocol failing.

Conditions: This symptom is observed in the Cisco 7600 router with SPA-5X1GE-V2.

Workaround: Reload SIP with SPA loaded in it.
- CSCul59525
 

Symptom: A Cisco ASR 1000 cube running Cisco IOS Release XE3.8S, many hung calls are seen over a period of one week. There are three different symptoms of hung call legs.

Example 1: One of the call leg is in stuck state

Example 2: Both the call legs are active and connected and stuck for more than week

Example 3: Both call legs are stuck in disconnect state but one of the call is connecting and other leg is in active state.

Topology:

```
VzB ---sip----CUBE-----sip-----SME Cluster-----sip-----Admin04 cluster-----IP
Phones | | | -----sip trunk to fax server | | -----SIP trunk
to Unity connection vm
```

Conditions: Though the reason for this issue is unknown, it is very random in nature. Hung calls are seen for a normal sip to sip calls going to IP phone, or calls that routes to unity connection voicemail and also stuck fax calls.

Workaround: There is no workaround. However, reboot the box to clear the stuck calls.

More Info: Examples of single leg stuck calls:

```
----- 1E95 : 82689 40831920ms.1 (11:56:22.410 EST
Tue Nov 12 2013) +4130 pid:200 Answer 14178002600 active dur 1w2d tx:0/0 rx:0/0 dscp:0
media:0 audio tos:0xB8 video tos:0x0 IP 172.31.133.132:23322 SRTP: off rtt:0ms
pl:0/0ms lost:0/0/0 delay:0/0/0ms g729r8 TextRelay: off Transcoded: No media inactive
detected:n media contrl rcvd:n/a timestamp:n/a long duration call detected:n long
duration call duration:n/a timestamp:n/a
```

Example of two leg stuck calls:

```
----- 1E : 288165 141617380ms.1 (15:56:07.871
EST Wed Nov 13 2013) +-1 pid:220 Answer 8039058000 connected dur 00:00:00 tx:0/0
rx:0/0 dscp:0 media:0 audio tos:0xB8 video tos:0x0 IP 10.190.204.107:22476 SRTP: off
rtt:0ms pl:0/0ms lost:0/0/0 delay:0/0/0ms g729r8 TextRelay: off Transcoded: Yes media
inactive detected:n media contrl rcvd:n/a timestamp:n/a long duration call detected:n
long duration call duration:n/a timestamp:n/a
1E : 288177 141625940ms.1 (15:56:16.431 EST Wed Nov 13 2013) +3060 pid:245 Originate
8778074646 active dur 1w0d tx:0/0 rx:1/160 dscp:0 media:0 audio tos:0xB8 video tos:0x0
IP 172.31.122.164:23688 SRTP: off rtt:0ms pl:0/0ms lost:0/0/0 delay:0/0/0ms g711ulaw
TextRelay: off Transcoded: Yes media inactive detected:n media contrl rcvd:n/a
timestamp:n/a long duration call detected:n long duration call duration:n/a
timestamp:n/a
```

Examples of two leg stuck calls and one leg

```
----- 3D41 : 447386
220196650ms.1 (13:45:47.147 EST Thu Nov 14 2013) +-1 pid:200 Answer 3186810693
connecting dur 00:00:00 tx:0/0 rx:0/0 dscp:0 media:0 audio tos:0xB8 video tos:0x0 IP
172.31.133.132:25856 SRTP: off rtt:0ms pl:0/0ms lost:0/0/0 delay:0/0/0ms g711ulaw
TextRelay: off Transcoded: No media inactive detected:n media contrl rcvd:n/a
timestamp:n/a long duration call detected:n long duration call duration:n/a
timestamp:n/a
3D41 : 447387 220196650ms.2 (13:45:47.147 EST Thu Nov 14 2013) +20380 pid:20003
Originate 9724445770 active dur 6d23h tx:0/0 rx:0/0 dscp:0 media:0 audio tos:0xB8
video tos:0x0 IP 10.144.132.72:20062 SRTP: off rtt:0ms pl:0/0ms lost:0/0/0
delay:0/0/0ms g711ulaw TextRelay: off Transcoded: No media inactive detected:n media
contrl rcvd:n/a timestamp:n/a long duration call detected:n long duration call
duration:n/a timestamp:n/a
```

- CSCul73789

Symptom: In an IPv6 IPsec scenario, code crashes occur with traffic flowing. This is seen even with a single tunnel with traffic flowing.

Conditions: This symptom does not occur under specific conditions.

Workaround: There is no workaround.

More Info: The crash is seen because a structure that may not be available is accessed.

- CSCul81353

Symptom: Cisco ASR 1006 with RP2 running ES version based of Cisco IOS Release 15.3(1)S crash with Segmentation Fault.

```
---snip-- UNIX-EXT-SIGNAL: Segmentation fault(11), Process = CCSIP_SPI_CONTROL
-Traceback= 1#9821b08208133f5124c039ddeb8173b :400000+347A664 :400000+7B14A0F
:400000+7B0F5E7 :400000+8F6C8A :400000+9A8C4C :400000+9B6951 :400000+95F2A4
:400000+962772 :400000+BE9018 :400000+BE8E4F ---snip--
```

After the RP Switch over all the new calls were rejected with the following errors as well, which may be unrelated to the crash:

```
--snip-- Dec 2 15:11:47: %VOICE_IEC-3-GW: SIP: Internal Error (INVITE, codec
mismatch): IEC=1.1.278.7.110.0 on callID 17334189 Dec 2 15:11:49: %VOICE_IEC-3-GW:
SIP: Internal Error (INVITE, codec mismatch): IEC=1.1.278.7.110.0 on callID 17334212
Dec 2 15:11:49: %VOICE_IEC-3-GW: SIP: Internal Error (INVITE, codec mismatch):
IEC=1.1.278.7.110.0 on callID 17334218 ---snip---
```

Conditions: This symptom is observed after two weeks of uptime and during normal load condition.

Workaround: Workaround is to reboot the box to recover from the situation.

More Info: The core file writing is incomplete as TEMP\_IN\_PROGRESS

```
---- show stby-harddisk: all-----
142 2406627691 Dec 02 2013 14:11:14 +00:00
/harddisk/core/kernel.rp_20131202191114.core.gz
149 79237120 Dec 02 2013 14:03:52 +00:00
/harddisk/core/nyorbgdnesbc-dr_RP_0_linux_iosd-imag_6335.core.gz.TEMP_IN_PROGRESS
-----
```

- CSCul87037

Symptom: An “sg subrte conte” chunk leak occurs while roaming.

Conditions: This symptom occurs after an account-logout and if service permit is configured in control policy. In case of a service permit, the subscriber remains unauth and is redirected to the portal once again. Post successful second account logon and the subscriber session is cleared by timeout or cli, the leak is seen and the same client will not be able to create the session once again. The leak is seen after simulating for the second time account-logon. And if service permit is configured.

In case of service disconnect configured under account-logout, account-logon is not a practical scenario as the portal is not reachable for the client.

Workaround: Use **service disconnect** for **event account-logout**.

```
class type control always event account-logout
  1 service disconnect delay 10
!
```

- CSCul90667

Symptom: Error messages and tracebacks are printed to the console.

Conditions: This symptom occurs when IGP times out while Standby RP becomes NSR Active.

Workaround: Enable NSR under IGP to ensure no timeout occurs.

- CSCul94087

Symptom: Output Packet drops is observed on the ATM IMA interface even when there is no live traffic and only signalling exchange between non-Cisco devices. Although output drops in most cases means low bandwidth issues but in this case, an entire site was down due to these drops.

Conditions: This symptom occurs under the following conditions:

1. Layer 2 cross connect is configured on Cisco device and Non - Cisco device at other end
2. Only signalling traffic flows through the devices
3. IMA group is created for the ATM connectivity
4. SPA-24CHT1-CE-ATM card is to be used for the ATM connection.

Workaround: Reload the SPA.

- CSCul96421

Symptom: Outbound calls over SIP trunk to provider fails.





More Info: While running ISIS it is possible for BFD to attempt to register before IP ARP has completed (but the ISIS CLNS neighbor has been established). When this happens, BFD may send packets with source MAC and destination MAC addresses of all 0s. This causes the neighbor to ignore them and a BFD neighbor never establishes. This is a rare condition within the ISIS, ARP and BFD components and may not always be encountered.

- CSCum14438

Symptom: “nh\_l2m\_handle\_t” memory leaks are observed while configuring service instances on an access interface of the Cisco ME 3600 platform.

Conditions: This symptom occurs when a new service instance is created on an access interface.

Workaround: There is no workaround.

- CSCum14830

Symptom: Leaking IPv6 routes is observed from a VRF table into the global table using BGP. These routes consist of the following:

1. BGP routes learned from the VRF IPv6 BGP peer.
2. Redistributed static and connected routes.

The BGP routes leak fine, but the redistributed static and connected routes have an issue. After the redistributed routes leak, the exit interface shows “null0”. Sometimes instead of showing the exit interface as “null0”, it shows a random interface which is a part of VRF and has IPv6 enabled on it.

Conditions: This symptom occurs with IPv6 redistributed connected and static routes into BGP VRF (could also be redistributed from other protocols as well but have not been tested).

Workaround: There is no workaround.

- CSCum15232

Symptom: A Cisco IOS router may crash using LDAP while performing TLS operations.

Conditions: This symptom was observed in Cisco IOS Release 15.3(3)M1.4. Other versions can be affected as well.

Workaround: There is no workaround.

More Info: LDAP is used in IOS SSLVPN deployment to authenticate users.

- CSCum16315

Symptom: Upon reload of a Cisco 7600 router configured with a CoPP policy containing IPv6 ACLs and DSCP matching, the CoPP is only applied to the active RSP as shown below.

After reload:

```
lab-7609-rsp-02#sh mod power
Mod Card Type Admin Status Oper Status --- -----
----- 1 CEF720 48 port 10/100/1000mb Ethernet on on
5 Route Switch Processor 720 (Active) on on
6 Route Switch Processor 720 (Hot) on on
7 CEF720 8 port 10GE with DFC on on
8 CEF720 8 port 10GE with DFC on on
CoPP is applied to only the active RSP/SUP after reload:
lab-7609-rsp-02#sh policy-map control-plane in | inc class|Earl
class-map: COPPCCLASS_MCAST (match-any)
Earl in slot 5 :
class-map: COPPCCLASS_MGMT (match-any)
Earl in slot 5 :
class-map: COPPCCLASS_ALLOW_ICMP (match-any)
Earl in slot 5 :
class-map: COPPCCLASS_MONITORING (match-any)
```

```

Earl in slot 5 :
class-map: COPPCLASS_FILEXFER (match-any)
Earl in slot 5 :
class-map: COPPCLASS_REMOTEACCESS (match-any)
Earl in slot 5 :
class-map: COPPCLASS_OSPF (match-any)
class-map: COPPCLASS_LDP (match-any)
Earl in slot 5 :
class-map: COPPCLASS_BGP (match-any)
class-map: COPPCLASS_MISC (match-any)
class-map: COPPCLASS_UNDESIRABLE (match-any)
Earl in slot 5 :
class-map: COPPCLASS_IPV4_CATCHALL (match-any)
Earl in slot 5 :
class-map: COPPCLASS_IPV6_CATCHALL (match-any)
class-map: class-default (match-any)
Earl in slot 5 :

```

When this issue is triggered, the following error will be seen in the logs:

```
*Dec 14 02:33:14.579: %QM-2-TCAM_BAD_LOU: Bad TCAM LOU operation in ACL
```

This issue potentially exposes the device to a DoS vulnerability.

Conditions: This symptom occurs under the following conditions:

- 7600 HA Environment.
- CoPP IPV6 ACL with DSCP match.
- Reload or Switchover.

Workaround: There are two workarounds for this issue.

Modify the CoPP Policy to remove IPV6 ACL/DSCP matching.

Remove and reapply the CoPP configuration as shown below:

```

lab-7609-rsp-02(config)#control-plane
lab-7609-rsp-02(config-cp)#no service-policy in COPP
lab-7609-rsp-02(config-cp)#service-policy in COPP
lab-7609-rsp-02(config-cp)#end

```

CoPP is applied to all modules as required:

```

lab-7609-rsp-02#sh policy-map control-plane in | inc class|Earl
class-map: COPPCLASS_MCAST (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCLASS_MGMT (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCLASS_ALLOW_ICMP (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCLASS_MONITORING (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCLASS_FILEXFER (match-any)

```

```

Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_REMOTEACCESS (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_OSPF (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_LDP (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_BGP (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_MISC (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_UNDESIRABLE (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_IPV4_CATCHALL (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: COPPCCLASS_IPV6_CATCHALL (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :
class-map: class-default (match-any)
Earl in slot 1 :
Earl in slot 5 :
Earl in slot 7 :
Earl in slot 8 :

```

PSIRT Evaluation: The Cisco PSIRT has evaluated this issue and does not meet the criteria for PSIRT ownership or involvement. This issue will be addressed via normal resolution channels.

If you believe that there is new information that would cause a change in the severity of this issue, please contact [psirt@cisco.com](mailto:psirt@cisco.com) for another evaluation.

Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCum18012

Symptom: System crashes on defaulting an interface with 64 EFPs.



```
000175: Oct 30 11:05:09.413 KSA: ASSERTION FAILED : ../voip/ccvtsp/vtsp.c:
vtsp_cdb_assert: 1518: unkn -Traceback= 000176: Oct 30 11:05:09.481 KSA: ASSERTION
FAILED : ../voip/ccvtsp/vtsp.c: vtsp_cdb_assert: 1518: unkn -Traceback= 000177: Oct 30
11:05:09.485 KSA: %SYS-3-MGDTIMER: Uninitialized timer, timer stop, timer = 49595828.
-Process= "DSMP", ipl= 0, pid= 304, -Traceback=
11:05:09 KSA Wed Oct 30 2013: TLB (load or instruction fetch) exception, CPU signal
10, PC = 0x4110CA2C
```

Conditions: Cisco IOS VoIP gateway experiences an unexpected reload while processing voice calls. This happens when the caller Id is enabled on the FXO port with the voice-port subcommand **caller-id alerting dsp-pre-allocate** enabled.

Workaround:

1. Disable the **caller-id alerting dsp-pre-allocate** command. This will, however, not support caller Id on Old FXO cards where the Caller Id Type is set to Type I ( i.e. caller Id reception before connect).
  2. Disable the **caller-id enable** command. This again will not provide the Caller Id feature, but prevent the router from unexpected reloads.
- CSCum52216  
Symptom: After a reload, **ip pim sparse-mode** is gone on interface lisp 0.x (x denoted the LSIP interface number).  
Conditions: This symptom occurs after a reload.  
Workaround: There is no workaround.
  - CSCum55357  
Symptom: CUBE crashes for SIP-H323 Transcoding call.  
Conditions: The issue is seen while running regression for Cisco IOS Release 15.3(3)M1.9.  
Workaround: There is no workaround.
  - CSCum60848  
Symptom: Under certain conditions, a DSP will hang in certain call scenarios including REFER passthrough.  
Conditions: This symptom is observed under heavy load.  
Workaround: There is no workaround.
  - CSCum61595  
Symptom: Alignment errors are observed after upgrading to Cisco IOS Release 15.2(4)M5.  
Jan 9 19:42:59.623 GMT: %ALIGN-3-CORRECT: Alignment correction made at 0x6477F81Cz reading 0x6BE87495 Jan 9 19:42:59.623 GMT: %ALIGN-3-TRACE: -Traceback= 0x6477F81Cz 0x647805D0z 0x6478FE70z 0x64751088z 0x64B99F4Cz 0x64B99FD4z 0x64752 284z 0x647525ACz  
Conditions: This symptom does not occur under specific conditions.  
Workaround: There is no workaround.
  - CSCum62783  
Symptom: The following alignment errors are seen after a PPPoE session establishment for the first time after a reboot:  
\*Jan 14 07:24:40.591: %ALIGN-3-CORRECT: Alignment correction made at 0x32B2DF4z reading 0xE7790ED \*Jan 14 07:24:40.591: %ALIGN-3-TRACE: -Traceback= 0x32B2DF4z 0x32B1E274z 0x32B1EECCz 0x32B1EF90z 0x332E550Cz 0x332E54F0z 0xFFFF1A00z 0xFFFF1A00z

Conditions: This symptom occurs when **pppoe-client ppp-max-payload** is configured under the Ethernet interface.

Workaround: There is no workaround.

- CSCum65451

Symptom: A crash occurs due to multicast stack overflow memory corruption.

Conditions: This symptom may occur when PIM is enabled on a LISP interface and Auto-RP is also enabled.

Workaround: Configure **no ip pim autorp** before any other PIM or LISP configuration.

- CSCum67229

Symptom: Entitymib does not respond for OC3/OC12/T3/E3 controller ports on the Cisco ME3600x-24CX-M platform.

Conditions: This symptom occurs with the Cisco ME 3600X-24CX-M platform running Cisco IOS XE Release 3.10.

Workaround: There is no workaround.

- CSCum70579

Symptom: CISCO-EVC-MIB is not available with MetroIPAccess license on Cisco ME 3600X platforms.

Conditions: This symptom is observed only with MetroIPAccess license.

Workaround: Upgrade the license to AdvancedMetroIP license.

- CSCum71701

Symptom: This bug can stop traffic from being forwarded by an upstream router when the **ip pim join-prune-interval** command is configured on the downstream router's upstream LISP interface.

Conditions: This symptom occurs when the **ip pim join-prune-interval** command is configured with a value greater than the default on a LISP interface.

Workaround: There is no workaround.

- CSCum78613

Symptom: A crash is observed with QoS Egress classification policies in trunk mode configuration.

Conditions: This symptom occurs with a random sequence of steps involving changing of interface configurations by attaching the policy beforehand.

Workaround: Reload with the final configurations needed.

- CSCum81041

Symptom: One way audio incoming calls redirected through CVP.

Conditions: Call flow: -----

```
Caller----G711----TDM GW----SIP-----ASR1K----SIP-----CUSP----SIP----CVP (Vz0) ----IP-IVR
| | ----SIP---CVP (BAMS) | |-----SIP---CUCM---Agent Phone (G729 only)
```

Initially the caller is connected to IP-IVR, both ingress and egress leg of the CUBE is doing G711. Call is connected to the IP-IVR, then CVP sends a refer to the VXML GW for playing prompts and ringback tone etc. When the call is transferred to the agent, CUBE negotiated G729 at the sip level with the CVP, but because of mid-call signalling block on the ingress side, continue with the G711. Hence xcoder is invoked on the CUBE to handle G729 to G711 and vice versa, but CUBE is still sending G711 media to the agent phone side while the agent phone is sending G729 media to the CUBE.

- Workaround: There is no workaround.
- CSCum83829
 

Symptom: Cisco ME 3600 and ME 3800 platforms crash when shut and no shut is performed on an interface.

Conditions: This symptom occurs prior to shut and no shut when the VLAN of the that particular port is removed and added back. The VLAN must have static configurations like static join or static mrouter.

Workaround: There is no workaround.
  - CSCum84999
 

Symptom: SUBSCRIBE received from CVP after BYE and NOTIFY with subscription-state: terminates is send by CUBE.

Conditions: This symptom is observed when SUBSCRIBE IS recieved after call is terminated with BYE.

Workaround: There is no workaround.
  - CSCum85813
 

Symptom: Shut primary static router and secondary static is not installed automatically.

Conditions: This symptom is seen on the sites where the BFD state of the backup static route is marked as “U” in the output of **show ip static route bfd**.

Workaround: Reinstall the default backup static route.
  - CSCum95330
 

Symptom: Removing an Ethernet service instance which is a member of a bridge domain may cause the router to reload.

Conditions: This symptom is observed when the last service instance is removed from the bridge domain and there are still members of the bridge domain which are not service instances (such as VFI).

Workaround: Completely unconfigure the bridge domain and reconfigure it.
  - CSCun07772
 

Symptom: A Cisco router crashes.

Conditions: This symptom occurs on deleting a subscriber’s session in attempting state by a COA script as shown below:

```
#!/bin/sh CISCO=$1 # bras SessionID=$2 CoaSecret='secret'
#clear ISG session on BRAS /bin/echo
"User-Name="undef",Acct-Session-Id="$SessionID",cisco-avpair="subscriber:command=account-logoff" | /usr/bin/radclient -x $CISCO:1700 coa $CoaSecret
```

Workaround: Do not use the COA script for deleting the subscriber’s session.
  - CSCun10381
 

Symptom: A traffic drop was observed because labels do not get programmed.

Conditions: This symptom occurs when scalable EoMPLS with L3VPN is configured. When notifications on atom-imps arrive, they have to get programmed.

Workaround: Clear ip route.

More Info: Traffic was seen to be dropped as the atom-imps could not be programmed because label entry could not be found for the atom-imps.



- CSCun11782  
Symptom: Rtfiler prefixes are sent with incorrect next-hop equal to next-hop of the default static route in GRT instead of BGP router-id.  
Conditions: This symptom occurs with a default static route present in GRT pointing, for example, to the next-hop known behind the connected interface.  
Workaround: Replace the default static route with a more specific static route or remove static and clear BGP.
- CSCun13688  
Symptom: The Cisco Catalyst 6500 Supervisor Engine 2T with CLNS routing configured crashes after **show clnbs route**.  
Conditions: This symptom occurs when CLNS routing is configured.  
Workaround: There is no workaround.
- CSCun18738  
Symptom: A “aspdma\_rx\_n\_pkt\_handler” memory leak is observed in Cisco ME 3600 and ME 3800 platforms.  
Conditions: This symptom occurs randomly with the Cisco Discovery Protocol configured in the device.  
Workaround: There is no workaround.
- CSCun20187  
Symptom: HSRP communication fails between two PEs (Cisco 7600 Series router) right after removing a neighbor from VFI.  
Conditions: Assume that a VPLS circuit is running between more than two PEs say A,B, and C and HSRP is running between A and B. Removing VPLS peer C on either A or B would cause HSRP communication failure between A and B. This failure is not expected as data path is still available between A and B.  
Workaround: Perform shut/no shut on the SVI.
- CSCun21602  
Symptom: Traffic is not forwarded by the router out of any interface.  
Conditions: This symptom occurs on toggling of the **ip routing** command in global configuration mode.  
Workaround: Perform shut and no shut of the interface which is involved in forwarding or reload the device with **ip routing** enabled.
- CSCun25316  
Symptom: Cisco ME 3600 packets in routing protocol queue results in an ISIS Flap.  
Conditions: This symptom occurs when more than 1000 packets get punted to the routing protocol queue.  
Workaround: Increase the queue size.  
**platform qos policer cpu queue <qid><rate>**
- CSCun30040  
Symptom: AN neighbor ship goes down after enabling SD.  
Conditions: This symptom occurs when IPv6 packets get dropped because interface input queue is full after enabling mDNS.

Workaround: There is no workaround.

- CSCun31021

Symptom: A vulnerability in IKE module of Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to affect already established Security Associations (SA)..

The vulnerability is due to a wrong handling of rogue IKE Main Mode packets. An attacker could exploit this vulnerability by sending a crafted Main Mode packet to an affected device. An exploit could allow the attacker to cause dropping of valid, established IKE Security Associations on an affected device.

Conditions: Device configured to process IKE request that already has a number of established security associations.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C>

CVE ID CVE-2014-2143 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-2143>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun41292

Symptom: On a Cisco ASR 1001 router running Cisco IOS Release 15.3(1)S, a crash occurs when the “show ip ei vrf X topo X.X.X.X/X” command is executed. The X.X.X.X/X must be in “FD is infinity” status in EIGRP as CSCtz01338.

```
asr1001_bew_03# show ip ei vrf * to all | i Infinity P 174.162.XX.XX/24, 0 successors,
FD is Infinity, U, serno 37, refcount 1 snip P 174.180.XX.XX/29, 0 successors, FD is
Infinity, U, serno 46, refcount 1 asr1001_bew_03# asr1001_bew_03# asr1001_bew_03#
asr1001_bew_03# asr1001_bew_03# asr1001_bew_03#show ip ei vrf 1 to 174.162.XX.XX/24
Exception to IOS Thread: Frame pointer 0x7F63DF6602D0, PC = 0x1956C8D
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = Exec -Traceback=
1#980611ad3b9665cd80fe5178bcd6036a :400000+1556C8D :400000+1556B09 :400000+15569D1
:400000+157DE39 :400000+15197A2 :400000+1518659 :400000+156BA5E :400000+15591D1
:400000+1189768 :400000+1188E6D :400000+1186E15 :400000+484F270 :400000+11A1CA0
Fastpath Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
c:7F64154A4000+BE002
Auxiliary Thread backtrace: -Traceback= 1#980611ad3b9665cd80fe5178bcd6036a
pthread:7F640ED43000+A7C9
```

Conditions: This symptom occurs when X.X.X.X/X is in “FD is infinity” status in EIGRP.

Workaround: There is no workaround.

- CSCun45272

Symptom:

1. Standby RP will have out-of-sync entries. With MPLS-TE NSR enabled, the standby RP will have out-of-sync entries which will result in flapping of the path-protected LSP of the tunnel after an SSO.
2. Leaking an LSP. A third LSP will be signaled and leaked (there is no management of the LSP). There are supposed to be two LSPs at steady state (primary and path protected), but with this defect, there will be primary, path protected, and leaked LSP.

Conditions: This symptom occurs with a reoptimization of a tunnel that has failed with path protection enabled.

Workaround: There is no workaround.

- CSCun45299

Symptom: IPv6 traffic is dropped for packets with extension headers.

Conditions: This symptom occurs when extension header packets are punted to the CPU.

Workaround: There is no workaround.

- CSCun46486

Symptom: A Cisco device crashes every 2-3 days when the SNMPSET operation is used to create guest users.

Conditions: This symptom occurs when guest users are created through SNMPSET operations at a very high rate.

Workaround: There is no workaround.

- CSCun48344

Symptom: A config-sync failure occurs due to the **address-family ipv6 unicast vrf** command during the immediate unconfiguration and reconfiguration of VRF definition.

Conditions: This symptom occurs with attached running configurations.

Workaround: There is no workaround.

- CSCun58030

Symptom: A Cisco ME-3600X platform does not display time source information while running the PTP dataset time properties show command. Functional issues are not noticed with PTP time sync. The time source field says "Unknown".

Conditions: This symptom does not occur under specific conditions. A simple Ordinary Clock(OC) Slave- Master connectivity would make the Slave show up as "Time Source Unknown".

Workaround: There is no workaround.

- CSCun65000

Symptom: Traffic loss of about 200-500 ms is observed.

Conditions: This symptom is observed on an RLFA cutover.

Workaround: There is no workaround.

- CSCun68723

Symptom: Incorrect information is present on the E1/T1 ports on the Cisco ME 3600X 24CX platform in the IfTable of IF-MIB.

The incorrect information includes the following:

1. ifType of the interface is 0 which is not a valid ifType.
2. ifAdminStatus value is always testing, and does not reflect the actual state.
3. ifOperStatus value is always unknown and does not reflect the actual state.
4. ifSpeed value is 0 which is incorrect.

Conditions: This symptom occurs on any Cisco ME 3600X 24CX device running Cisco IOS Release 15.3(3)S.

Workaround: The correct information on the E1/T1 ports is available in CLI.

- CSCun72459

Symptom: High traffic loss is observed with setups having BGP and microloop avoidance combination.

Conditions: This symptom occurs with the following combination:

1. IP FRR is turned on.
2. Cisco IOS XE Release 3.11 code (or newer) that enables microloop avoidance by default.
3. BGP configurations.

Workaround: Disable the microloop avoidance feature. For example, in ISIS, execute the following commands:

```
router isis <process name>
microloop avoidance disable
!
```

However, there will be some traffic loss due to the lack of microloop avoidance.

- CSCun73463

Symptom: A Cisco ME 3600 device crashes.

Conditions: This symptom occurs on configuring a card type t1/e1 without a t1/e1 license on the device.

Workaround: Configure the card type after obtaining a t1/e1 license.

- CSCun73515

Symptom: A router crashes due to RMON.

Conditions: This symptom occurs on activation of an RMON event.

Workaround: There is no workaround.

- CSCun73782

Symptom: A vulnerability in LISP control messages processing on Cisco IOS and Cisco IOS XE could allow an unauthenticated, remote attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

The vulnerability is due to insufficient checking of certain parameters in LISP control messages on ITR. An attacker could exploit this vulnerability by sending malformed LISP control messages to ITR. An exploit could allow the attacker to cause a vulnerable device to disable CEF forwarding and eventually drop traffic passing through.

Conditions: Malformed messages can only be generated by a device that is already registered to a LISP system: a valid ETR or ALT.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/3.6:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:N/A:P/E:F/RL:OF/RC:C>

CVE ID CVE-2014-3262 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2014-3262>

Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCun76733  
Symptom: BFD goes down and remains in admin-down state.  
Conditions: This symptom occurs after applying ACL chaining and flapping of the interface.  
Workaround: There is no workaround.  
More Info: An IPv4 BFD neighbor remains in admin-down state on the PE. The ACE configured in ACL for BFD is matched and the receive counters on BFD neighbors are incremented but the BFD is still down.  
This issue occurs only after ACL chaining is applied.
- CSCun77010  
Symptom: A router may crash after or during the execution of the **show ipv6 ospf rib** command.  
Conditions: This symptom occurs when many routes or route paths are present in the OSPFv3 rib. The OSPFv3 rib is significantly recomputed during execution of commands.  
Workaround: Limit the use of the **show ipv6 ospf rib** command.
- CSCun85501  
Symptom: IPv6 traffic is not forwarded by the device for templates other than the default (like VPNv4-only, VPNv4-v6). However, IPv4 traffic works fine.  
Conditions: This symptom occurs when the template is changed to anything other than the default.  
Workaround: There is no workaround.
- CSCun86087  
Symptom: In a VPLS environment, packets of some VCs are blocked in an imposition direction.  
Conditions: This symptom occurs with port channels and LAG as MPLS core-facing interface on ES+.  
Workaround: There is no workaround.
- CSCun91720  
Symptom: IPv6 mcast traffic is punted to the host queue (in3idc\_vlan.bridgeBasedMcastIp=1).  
Conditions: This symptom occurs on a Layer 2 device with no multicast configurations.  
Workaround: There is no workaround.  
More Info: Instead of bridging the IPv6 traffic, the switch punts it to the CPU.
- CSCuo08759  
Symptom: With IP-FRR, VPLS traffic is dropped on a core-facing port-channel after a link flap.  
Conditions: This symptom occurs when a core-facing interface is a portchannel configured on a Cisco 7600 ES+ card.  
Workaround: Perform shut and no shut on the port channel interface.
- CSCuo11703  
Symptom: The **show network-clock synchronization** command flaps between different QL values on the same interface. Depending on the values with which the interface flaps, this could lead to triggering of network-clock selection algorithm and subsequent selection of primary reference clock for the system.  
Conditions: This symptom could occur when the network-clock synchronization mode is unprovisioned from automatic selection, and then the monitor interfaces are removed and a new set of interfaces are added for network-clock monitoring with automatic selection reprovisioned.

Workaround: Adding back the older set of interfaces and removing them would resolve the issue.

- CSCuo16717

Symptom: PPPoX brings up sessions failure with IPv6 configurations.

Conditions: This symptom occurs when “vpdn authen-before-forward” is configured.

Workaround: Do not configure “vpdn authen-before-forward”.

- CSCuo19730

Symptom: Cisco IOS XE includes a version of OpenSSL that is affected by the vulnerability identified by the Common Vulnerability and Exposures (CVE) ID CVE-2014-0160.

This bug has been opened to address the potential impact on this product.

Conditions: Cisco IOS XE devices running release 3.11.0S, 3.11.1S or 3.12.0S and with the WebUI interface over HTTPs enabled. No other versions of Cisco IOS XE are affected.

Devices with the WebUI interface enabled and using HTTPs as transport protocol will include the following configuration:

```
transport-map type persistent webui http-webui secure-server ip http secure-server transport type
persistent webui input http-webui
```

Devices running IOS XE release 3.11.0S, 3.11.1S or 3.12.0S but WITHOUT the WebUI interface enabled, or with the WebUI interface enabled but NOT using HTTPs as transport protocol are NOT AFFECTED by this vulnerability.

Devices running IOS XE release 3.11.0S, 3.11.1S or 3.12.0S and with the HTTPs server enabled (by including in their configuration the line “ip http secure-server”) are NOT affected. Both the HTTPs server and the WebUI interface need to be enabled for a device to be vulnerable.

The WebUI configuration guide is available at

<http://www.cisco.com/c/en/us/td/docs/routers/asr1000/configuration/guide/chassis/asrswcfg/webui.html>

Workaround: There is no workaround.

Further Problem Description: Additional details about this vulnerability can be found at

<http://cve.mitre.org/cve/cve.html>

Software version and Fixes

The first column is the Cisco IOS XE Software Release The second column is the First Fixed Release.

2.x.x	Not Vulnerable	3.1.xS	Not Vulnerable	3.1.xSG	Not Vulnerable	3.2.xS	Not Vulnerable	3.2xSE	Not Vulnerable	3.2.xSG	Not Vulnerable	3.2.xSQ	Not Vulnerable	3.3.xS	Not Vulnerable	3.3.xSE	Not Vulnerable	3.3xSG	Not Vulnerable	3.3xXO	Not Vulnerable	3.3xSQ	Not Vulnerable	3.4.xS	Not Vulnerable	3.4.xSG	Not Vulnerable	3.5.xS	Not Vulnerable	3.5.xE	Not Vulnerable	3.6.xS	Not Vulnerable	3.6.xE	Not Vulnerable	3.7.xS	Not Vulnerable	3.8.xS	Not Vulnerable	3.9.xS	Not Vulnerable	3.10.xS	Not Vulnerable	3.11.xS	Vulnerable	3.12.xS	Vulnerable	3.12.0aS	Not Vulnerable
-------	----------------	--------	----------------	---------	----------------	--------	----------------	--------	----------------	---------	----------------	---------	----------------	--------	----------------	---------	----------------	--------	----------------	--------	----------------	--------	----------------	--------	----------------	---------	----------------	--------	----------------	--------	----------------	--------	----------------	--------	----------------	--------	----------------	--------	----------------	--------	----------------	---------	----------------	---------	------------	---------	------------	----------	----------------

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 4.3/4.3:

<https://intellishield.cisco.com/security/alertmanager/cvss?target=new&version=2.0&vector=AV:N/AC:M/Au:N/C:P/I:N/A:N/E:H/RL:U/RC:C>

The Cisco PSIRT has assigned this score based on information obtained from multiple sources. This includes the CVSS score assigned by the third-party vendor when available. The CVSS score assigned may not reflect the actual impact on the Cisco Product.



Workaround: There is no workaround.

## Resolved Bugs—Cisco IOS Release 15.4(1)S1

- CSCte77398

Symptom: A Cisco ATM router configured with ATM PVC Range commands report the following error when attempting to configure a PVC Range:

Unable to configure PVC Range. Possibly multiple users configuring IOS simultaneously.

Conditions: This problem occurs randomly and even if there are no multiple sessions accessing the pvc-range at the same time.

Workaround: There is no workaround.

- CSCtz73473

Symptom: In a rare multipath import configuration on IOS router, the following traceback is seen:

```
SW0: *May 4 12:08:40.175 PDT: %IPRT-3-INVALID_NEXTHOP: Duplicate ID 0x3 113.1.1.0/24
from bgp decode: 0x6770760 ---> ip_route_update+37C 0x59F7B20 --->
bgp_ipv4_rib_install+578 0x59F87C8 ---> bgp_ipv4_rib_update+108 0x5A8C524 --->
bgp_vpnv4_update_iprib+2C 0x59F8C24 ---> bgp_v4class_update_fwhtable_walker+60 ...
```

Though there is no operational impact, it disturbs the console with the above traceback.

Conditions: This symptom is observed when you configure the following in the VRF address family:

```
router bgp 200000
!
address-family ipv4 vrf 5
import path selection multipaths
maximum-paths eibgp 8
```

Workaround: Do not log output on console but make it buffered to keep console clean.

- CSCuc53853

Symptom: A vulnerability exists in Cisco IOS switches where the remote, non-authenticated attacker can cause Denial of Service (DoS) by reloading an affected device. An attacker can exploit this vulnerability by sending a special combination of crafted packets.

Conditions: This symptom occurs when the HTTP server is enabled on the affected device.

Workaround: There is no workaround.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5.4/4.2:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:H/Au:N/C:N/I:N/A:C/E:POC/RL:OF/RC:C>

CVE ID CVE-2013-1100 has been assigned to document this issue.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-1100>

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)



- CSCue68714

Symptom: Newer released IOS-XE BGP, post Cisco IOS Release 15.2(4)S/XE3.7 not forming BFD session with the older implementations. This happens when using eBGP multi-hop to peer between two loopback interfaces on directly connected routers.

Conditions: This ddt adds a couple of options “[single-hop | multi-hop]” to the existing BGP-BFD knob “neighbor x.x.x.x fall-over [bfd] [check-control-plane-failure]”.

So, after the change the knob would be: “neighbor x.x.x.x fall-over [bfd] [single-hop | multi-hop] [check-control-plane-failure]”

\*\*Note: Existing: “neighbor x.x.x.x fall-over [bfd]” --- This behavior would not be disturbed; so that we do not change the behavior that has been released as part of all the releases for more than three years now.

Add-on in this ddt:

1) “neighbor x.x.x.x fall-over [bfd] [single-hop] -- NEW-option “single-hop”; would force BGP to open a single-hop bfd session. Even in case of back-to-back ebgp update-source loopback with 2 hop BGP peering.

2) “neighbor x.x.x.x fall-over [bfd] [multi-hop] -- NEW-option “multi-hop”; would force BGP to open a multi-hop bfd session.

Workaround: There is no work around. ISR G2 should support BFD multi-hop feature.

More Info: ISR-G2 does not support multi-hop BFD, while ISR4400 supports multi-hop BFD. BFD multi-hop support for ISR-G2 needs to be provided, so that they can interop with ISR4400 and ASRs.

- CSCuh15049

Symptom: EIGRP internal error log message appears along with tracebacks when EIGRP neighbors go down. The device might crash during the peer cleanup.

Conditions: This symptom is not observed under any specific conditions.

Workaround: There is no workaround.

- CSCuh69292

Symptom: LDAP moves in the stuck state.

Conditions: This issue is seen if the LDAP server becomes unavailable during LDAP transactions.

Workaround: There is no workaround.

- CSCui17084

Symptom: Delay between VPN convergence and BGP-based MDT tunnel creation after router reload may cause multicast traffic loss.

Conditions: In a BGP MVPN setup utilizing MDT SAFI, problem is seen upon BGP exiting read-only mode. VPN prefixes will be advertised immediately, whereas MDT prefixes are advertised after a BGP scanner run.

Workaround: There is no workaround.

- CSCui51363

Symptom: The multilink does not pass traffic even though it is in an up/up state.

Conditions: This symptom occurs when the auto DNR status is set and the sip400 ucode crashes.

Workaround: Perform a shut/no shut in the multilink.

- CSCui53428
 

Symptom: Forwarding state is not preserved on the Cisco ASR 9000 series router after an SSO in the Cisco ASR 903 router.

Conditions: This symptom occurs when an SSO is performed on the Cisco ASR 903 router.

Workaround: There is no workaround.
- CSCui59185
 

Symptom: ASR901 crashes while booting up with memory lite disabled.

Conditions: This symptom is observed when RFLA is enabled with memory lite disabled.

Workaround: Enable memory lite.
- CSCui63462
 

Symptom: High CPU usage is observed in an mDNS process with redistribution enabled.

Conditions: This symptom occurs when redistribution is enabled in a loop scenario.

Workaround: Enable redistribution accurately. This CLI should not be enabled when the setup contains loops.
- CSCui82519
 

Symptom: The receiver has a remote alarm after configuring “framing no-crc4” on the controller.

Conditions: This symptom occurs after configuring “framing no-crc4” on the controller.

Workaround: There is no workaround.
- CSCui82817
 

Symptom: A tunnel with lower absolute metric is not advertised properly.

Conditions: This symptom occurs under the following conditions:

  1. When there are multiple tunnels to a destination.
  2. The tunnel with a better metric comes up.
  3. When ISIS is used as IGP and both L1 and L2 are present and configured for TE.

Workaround: Clear the ISIS sessions.
- CSCuj11232
 

Symptom: Changing the local label on an existing static (no signaling) Any Transport over MPLS (AToM) pseudowire, or changing the static pseudowire to a dynamic one (with LDP signaling) may cause traffic to fail to traverse the pseudowire.

Conditions: This symptom is observed when either the configured value of the static local label is changed, or if the pseudowire is changed to a dynamic one.

Workaround: Completely unconfigure the existing xconnect or pseudowire before entering the new configuration.
- CSCuj30572
 

Symptom: With EIGRP and PFR configured, a router crashes after giving the following EIGRP messages.

```
000111: Sep 17 09:08:33.331: %DUAL-5-NBRCHANGE: EIGRP-IPv4 1: Neighbor 10.50.2.1
(Tunnel1502) is down: Peer Termination received 000112: Sep 17 09:08:33.347:
%DUAL-3-INTERNAL: EIGRP-IPv4 1: Internal Error -Traceback= 319D4CB4z 319EC5E4z
319EC7C8z 319E4950z 319EA760z 31A25008z 32C23084z 32C23068z
```

Conditions: This symptom occurs when PFR, OER and EIGRP are configured.

Say RouterUnderTest has two EIGRP Peers HUB1 and HUB2. (Given metrics are only for illustration) When EIGRP has a Prefix with 3 different Paths installed in following Order DRDB1 NH - HUB1, Metric 36571392 / 0 (Installed by PFR) DRDB2 NH - HUB2, Metric 58322432 / 409600 ( x Hops away learnt from RouterX) DRDB3 NH - HUB1, Metric 538004992/500409600 (y Hops away learnt from Router Y)

With these initial conditions, if Neighbor ship with Router Y goes down, Both PFR and EIGRP try to delete DRDB3 Which results in inconsistent data structures with Memory corruption. Any further access to memory will result in crash.

Workaround: Use other load sharing methods instead of PFR.

More Info: The crash is usually seen during execution of an EIGRP Route lookup function similar to the following:

```
0x33841E10:eigrp_pfr_get_drdb(0x33841ddc)+0x34
0x33842014:eigrp_pfr_route_lookup(0x33841e88)+0x18c
```

- CSCuj39400

Symptom: A Cisco 3945 series router running Cisco IOS Release 15.2(2)T2 may crash with a bus error. This relates to VOIP\_RTCP.

Conditions: Initial assessment shows that this appears to happen most often while running sip debugs. However at least one identical crash happened after SIP debugs were disabled three days before.

Workaround: There is no known workaround.

- CSCuj41494

Symptom: Memory leak is observed when the Cloud Web Security (formerly know as Scansafe) functionality is used on IOS versions containing the fix for CSCuh33843. Versions prior to 15.3(3)M are unaffected since they did not get the fix for CSCuh33843.

Conditions: This symptom occurs when Scansafe traffic is handled by TCP.

Workaround: Disable Scansafe.

- CSCuj42031

Symptom: Router may crash due to bus error - voip\_rtp\_dispose\_media\_service\_pak

This new bug is similar to CSCtx54882 and is impacting the IOS image : c3900-universalk9\_npe-mz.SPA.152-4.M2.bin.

Conditions: This symptom has been observed on a Cisco router running Cisco IOS Release 152-4.M2.

Workaround: There is no workaround.

- CSCuj44818

Symptom: A warning message is displayed.

Conditions: This issue occurs while unconfiguring video monitoring.

Workaround: There is no workaround.

- CSCuj50396

Symptom: The flow exporter status becomes inactive.

Conditions: This symptom occurs after an RP switchover while checking flow monitor information.

Workaround: There is no workaround.

- CSCuj52396  
Symptom: In a VPLS Inter-Autonomous System Option B configuration, the virtual circuits between the Autonomous System Border Router (ASBR) and the PE may fail to come up.  
Conditions: This symptom is observed while initially establishing VCs after the ASBR has reloaded.  
Workaround: The **clear xconnect** exec command can be used to clear the VCs that are down.
- CSCuj52699  
Symptom: A Cisco router crashes.  
Conditions: This symptom is observed in a load or stress condition.  
Workaround: There is no workaround.
- CSCuj54036  
Symptom: A Cisco c3900e router crashes during stress conditions.  
Conditions: This symptom is observed when content-scan is enabled and the router is at stress conditions.  
Workaround: There is no workaround.
- CSCuj55540  
Symptom: An exception is seen on a Cisco ISR 3945E router with whitelisted scansafe traffic.  
Conditions: This symptom is observed when there is a lot of whitelisted traffic going through the ISR box.  
Workaround: Disable whitelisting.
- CSCuj58950  
Symptom: A Cisco Catalyst 6500 Series switch may leak memory in the I/O pool due to mDNS traffic. The pool in which the leak is seen is dependent on the size of the incoming packet.  
Conditions: This symptom occurs when mDNS traffic is sent to the switch.  
Workaround: Apply an ACL to the inbound interface. This will drop the traffic and buffers will not leak.
- CSCuj64691  
Symptom: When configuring redistribute connected under eigrp, a host route/32 on SVI is installed unexpectedly.  
Conditions: This symptom is observed under the following conditions:
  - Configure a prefix to be in the routing table with EIGRP as the owner.
  - Redistribute connected interface to EIGRP so that the local entry is same as the prefix.Workaround: Disable STP for the VLAN of SVI (in this particular case).
- CSCuj64806  
Symptom: VRRPv2 priority may be incorrectly calculated when tracking tunnel interfaces. After reloading the router, the track decrement value is decremented twice. As a result, VRRPv2 with tracking does not work as expected.  
Conditions: This symptom is observed when you use tracking tunnel for VRRP priority.  
Workaround: Use VRRPv3.
- CSCuj65057  
Symptom: The **ip vrf forwarding** command under "aaa" is deleted after reloading the stack master.

Conditions: This symptom occurs after reloading the stack master switch.

```
----- aaa new-model ! aaa group server tacacs+ TACACS+ ip vrf forwarding VRF01 !
ip vrf VRF01 rd x.x.x.x -----
```

Workaround: Use the **vrf definition** command instead of the **ip vrf command to define vrf**. (This command is supported on Cisco IOS Release 12.2(58)SE or later releases.)

- CSCuj65601

Symptom: Logging into a Cisco router through SSH and telnet with AAA fails.

Conditions: This symptom occurs when the TACACS server group contains IPv6 source interface. The IPv6 source interface needs to be removed and added. After this process the SSH and telnet stops working.

Workaround 1: On entering the **no ipv6 tacacs source-interface GigabitEthernet0/0/0** command, enter **end** and wait for around 2 minutes. Enter the **ipv6 tacacs source-interface GigabitEthernet0/0/0** command and wait for around 5 minutes. Login to the router through SSH or telnet.

Workaround 2. Enter the above commands in succession and then wait for 7 to 9 minutes to login into the router.

- CSCuj66067

Symptom: Router running out of memory after an upgrade to Cisco IOS Releases 15.3(1)S, 15.3(3)S, and 15.4(1)S.

Conditions: This symptom is observed when huge number of route server (approximately more than 700) contexts configures in the router.

Workaround: Perform the following workaround:

1. Reduce the number of Route server contexts
2. Downgrade the IOS version to 15.2(4)S or lower release

- CSCuj72553

Symptom: The OSPF router may stay without a router LSA after NSF restarts which means that routing in the OSPF domain is seriously affected.

Conditions: This symptom occurs under the following conditions: -OSPF NSF is terminated for some reason. -**mpls traffic-eng nsr** is configured.

Workaround: Remove **mpls traffic-eng nsr**.

More Info: Example of **show ip ospf nsf** after a failed NSF:

```
Router#sh ip ospf 1 nsf
Routing Process "ospf 1" IETF Non-Stop Forwarding enabled restart-interval limit: 120
sec Last IETF NSF restart 03:33:06 ago terminated after 5 secs, reason: Event nbr
1-way IETF NSF helper support enabled Cisco NSF helper support enabled Restart resync
LSA state: TE has requested data Restart resync Adj state: TE has requested data OSPF
restart state is NO_RESTART Handle 140515696469576, Router ID 10.1.1.1, checkpoint
Router ID 0.0.0.0 Config wait timer interval 10, timer not running Dbase wait timer
interval 120, timer not running
Router#
Router LSA generation is prevented by flag described on lines:
Restart resync LSA state: TE has requested data Restart resync Adj state: TE has
requested data
```

Note: TE resync is not completed, although NSF is completed.

- CSCuj72631
 

Symptom: The Cisco Catalyst 6500 Series Switch crashes due to mdns configuration running Cisco IOS Release 15.1(2)SY.

Conditions: This symptom occurs while configuring the following:

```
CMD: "service-routing mdns-sd" 09:05:29 EDT Thu Sep 26 2013
CMD: "service-policy permit-all in" 09:05:52 EDT Thu Sep 26 2013
CMD: "service-policy permit-all out" 09:06:14 EDT Thu Sep 26 2013
Early Notification of crash condition..
09:06:18 EDT Thu Sep 26 2013: Floating Point exception, CPU signal 8, PC = 0x406F71BC
```

Workaround: There is no workaround.
- CSCuj75952
 

Symptom: The Cisco ASR 1000 route processor reloads.

Conditions: This symptom occurs during PPPoA session establishment if CAC determines that resources are low and HW-assisted CAC needs to be enabled. The router is used to terminate PPPoA sessions and Call Admission Control (CAC) is enabled.

Workaround: Disable Call Admission Control.
- CSCuj78636
 

Symptom: A memory leak is observed in the IP Switching segment.

Conditions: This symptom occurs if a subscriber roams with the same MAC address but a different IP address. This happens only for L2 roaming and not for L3 roaming.

Workaround: There is no workaround.
- CSCuj81681
 

Symptom: Mediamon fails working after the number of records pushed from the producers exceeds the cache entries set.

Conditions: This symptom is observed when the number of records or the flows generated by the traffic has to be more than the number of cache entries.

Workaround: There is no workaround.
- CSCuj83764
 

Symptom: Router crashes when a two-level ZBFW policy with attribute configured is attached to the zone pair.

Conditions: This symptom is observed when the ZBFW policy has two levels and the attribute is used in the policy.

Workaround: There is no workaround.
- CSCuj87667
 

Symptom: When the value "xxx" of MPLS exp bits is copied to the outer IP/GRE header TOS, the new TOS value should be "xxx00000". Instead, it shows "00000xxx", and the QoS information is broken.

Conditions: This symptom is observed in MPLS over GRE case.

Workaround: There is no workaround.
- CSCuj94571
 

Symptom: To run the BERT test, remove **keepalive** from the interface. After completing the BERT test, adding **keepalive** causes the standby RSP to reset.

Conditions: This symptom is consistent and affects Cisco IOS Release 15.1(3)S1.

Workaround: After the completion of the BERT test, remove the BERT test with **no bert pattern grss interval interval** and then add **keepalive**. This will avoid standby RSP reset.

- CSCuj94804

Symptom: On selecting a new clock source with the same QL value as the previous clock source, the clock class will not be updated.

Conditions: This symptom occurs under the following conditions:

1. Configure a PTP ordinary clock as master. The unit will select the internal clock source (QL-SEC) and will send clock class 58.
2. Configure a network source with the same QL as the internal clock (that is, QL-sec). The new clock source will be selected, but the clock class does not change accordingly. The same issue does not occur when the network source is configured with a different QL value.

Workaround: Reload the router.

- CSCuj99819

Symptom: MVPN GRE tunnels are not established.

Conditions: BGP has a VPN peer configured using an update-source that does not have PIM enabled.

Workaround: There is no workaround.

- CSCul04692

Symptom: A T1 controller flaps in CHT1/ET1 SPA.

Conditions: This symptom is seen in T1 mode with “cablelength short 100ft” or “cablelength long 0db” when connected with a PURA box.

Workaround: Configure “cablelength long -7.5db”.

- CSCul10573

Symptom: On receiving a BGP update from a neighbor, the router will send an illegal network notification and flap the session.

Conditions: This symptom occurs when the prefix received is a Leaf A-D route (RFC 6514) with an S-PMSI route serving as the Route Key.

Workaround: There is no workaround.

- CSCul11961

Symptom: While performing an ISSU super-pkg downgrade with broadband IP-based session features from Cisco IOS XE Release 3.12.0 to Cisco IOS XE Release 3.11.0, standby FP gets stuck in an "init" state after run version. There are Standby FP pending issues.

Conditions: This symptom occurs while performing an ISSU super-pkg downgrade with broadband IP-based session features from Cisco IOS XE Release 3.12.0 to Cisco IOS XE Release 3.11.0.

Workaround: There is no workaround.

More Info: The issue will not occur in the following cases:

1. ISSU sub-pkg upgrade or downgrade between XE311 and XE312.
2. ISSU sup-pkg upgrade from XE311 to XE312.
3. PPP-session features in ISSU super-pkg upgrade or downgrade between XE311 and XE312.

The upgrade from 3.11.0(without the fix for CSCul11961) to 3.12(with the fix of CSCul11961) works fine.

The downgrade from 3.12(with the fix of CSCul11961) to 3.11.0(without the fix for CSCul11961) fails with IP-based sessions. With this downgrade bug for 3.11.0, the fix will go out in 3.11.1 and 3.12.0.

- CSCul12583

Symptom: L4R is not removed after an account logon when DRL is present.

Conditions: This symptom occurs if per user merge is present.

Workaround: There is no workaround.

- CSCul14571

Symptom: Cisco router can crash after OSPFv3 is unconfigured from an interface.

Conditions: This symptom is observed when NSR is enabled.

Workaround: Unconfigure NSR before unconfiguring OSPFv3 from an interface.

More Info: This is extremely rare issue; the OSPFv3 should be in a process of checkpointing LSA from primary RP to standby while an interface from which the LSA was received is unconfigured.

- CSCul19814

Symptom: After collecting "raw netflow" data, the active switch crashes. The **show flow monitor v4 cache** command causes the reboot of the switch with the following message: %SCHED-3-TRASHING: Process thrashing on watched message event.

Conditions: This symptom occurs due to the **show flow monitor** command.

Workaround: There is no workaround.

- CSCul19906

Symptom: A crash is seen on the Cisco ASR router with crashinfo and core with following messages:

```
Exception to IOS Thread:
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = EIGRP-IPv4
```

Conditions: This symptom occurs with a Cisco ASR router routing EIGRP.

Workaround: There is no workaround.

- CSCul24682

Symptom: L2TP LNS puts a non-negotiated magic number to LCP packets. The PPPoE client may terminate the session prematurely due to the unknown magic number.

Conditions: This symptom occurs when L2TP LAC does not negotiate the magic number with the PPPoE client and L2TP LNS does not renegotiate options with the PPPoE client.

Workaround: Configure **lcp renegotiation always** on L2TP LNS.

- CSCul31953

Symptom: Wrong value is fetched for plaintext mtu of IPsec SA.

Conditions: Configuring Cisco Group Encrypted Transport VPN(GETVPN) within LISP network.

Workaround: There is no workaround.

- CSCul38081

Symptom: In a scaled environment, when a preferred path configuration is removed and is followed by a RP switchover the pseudowire interfaces goes down. The pseudowire interface comes up if we add the preferred path or just remove and add the neighbor statement.

Conditions: This symptom is not observed under any specific conditions.



Workaround: There is no workaround.

- CSCul40898

Symptom: After reloading the router or fresh service-instance configuration, traffic received from the access is sent to the core without a dummy VLAN header. This traffic is received by a remote PE2 and sent to switch with a missing VLAN header. Therefore CE2 drops received packets. When the issue is removed, captured traffic in the core contains a dummy VLAN header.

Conditions: This symptom is occasionally observed when the router is reloaded and is consistently observed when a new service instance is configured as an xconnect member.

Workaround: Perform **shutdown** followed by **no shutdown** on the service instance.

- CSCul43968

Symptom: Mroute states never expire on egress PE without any active downstream receivers.

Conditions: This symptom occurs in an IPv6 multicast running in a VRF scenario and during unconfiguration of such a loopback interface that has MLD joins on it.

Workaround: There is no workaround.

- CSCul47135

Symptom: On Cisco ASR 1000 routers, services are not removed or applied from the active subscriber sessions when CoA is sent from the radius server. The router sends wrong values in response to the CoA request packet.

Conditions: This symptom occurs when 15.2(20130918:081157) is run.

Workaround: There is no workaround.

- CSCul54254

Symptom: Invalid LSAs are not flushed by the router which has their Advertising Router ID. Specifically, Router LSAs which do not have LSID of 0 will not be flushed if the router does not re-originate them, and any LSA with a type that the router does not recognize.

Lingering LSAs could lead to incorrect routing in some very obscure instances. For example, stale Router LSA fragments from two neighboring routers would need to remain in the network. There would not be a routing problem if only one router's stale Router LSA fragment was allowed to linger.

Conditions: There are several possible scenarios that could lead to this symptom. One example is that a router is configured with many interfaces attached to an OSPFv3 instance such that it originates more than one Router LSA fragment. Then the router is reloaded before the configuration is saved, and after the reload it does not reoriginate some of the Router LSA fragments.

Workaround: There is no workaround.

- CSCul55900

Symptom: A FlexVPN Scale rate degradation occurs due to more CPU consumed by static processes.

Conditions: This symptom occurs under the following conditions:

1. Configure UUT to be the flexvpn server which can scale upto 10K sessions.
2. Configure IKEv2 Authorization policy.
3. Try to bring up the flexvpn 10K sessions and monitor the CPU usage.

Workaround: Remove IKEv2 authorization policy. In such a case, IKEv2 routing and mode configuration cannot be verified.

- CSCul56207
 

Symptom: A standby RP crashes.

Conditions: This symptom is seen on a Cisco ASR 1000 router used for PPPoEoA-aggregation when configuring a range/pvc. It was seen together with the following error message:

```
asr(config-if-atm-range)pvc-in-range 10/45 %ERROR: Standby doesn't support this
command ^ % Invalid input detected at '^' marker.
```

Workaround: There is no workaround.
- CSCul72121
 

Symptom: Continuous trace backs on the PTF console is observed and PTF crashes during a soak.

Conditions: This symptom occurs under the following conditions:

  1. Create an MDS profile as attached.
  2. Leave the setup for soak for 12 hours.

Workaround: Reload ACT and SBY PTF.
- CSCul75876
 

Symptom: A router may crash in an OSPF process during reconfiguration.

Conditions: This symptom occurs under the following conditions:

  1. Configure the router with “ipfrr” in area 0.
  2. Connect router to area 0 through two links. For some route one interface is the primary path, and the second is the repair path.
  3. Configure router as ABR, that is, have a non-zero area with a neighbor. Do not configure “ipfrr” in the non-zero area. Quickly remove the IP address from both the interfaces in area 0 and router the may crash.

Workaround: Changes to the reconfiguration procedure will avoid the crash.

  - Shutdown the interface before removing the IP
  - Remove the IP from one interface in area 0, wait for a few seconds and remove the IP address from the second interface in area 0.
- CSCul86211
 

Symptom: When LNS switches off while the sessions keep on establishing at LAC, LAC finds the l2tp db memory exhausted after sometime. Due to this, it fails to update the session in the database and during this period a crash is observed.

Conditions: This symptom occurs when LAC tries to add l2tp session in the database and fails to do so. In order to handle this error condition, LAC frees the l2tp and l2x session twice. This double free is the reason for crash.

Workaround: There is no workaround.
- CSCul92497
 

Symptom: The Cisco 7600 router providing layer2 EoMPLS services may stop forwarding ingress and egress traffic for an xconnect for which a backup peer config has been applied.

Conditions: This symptom occurs in Cisco 7600 routers running Cisco IOS Release 15.2(4)S4a with ES+ cards (access/core facing) and xconnect configured under a service instance.

Workaround: Clear the xconnect on the Cisco 7600 router side. Clearing on the remote side does not have an effect.

- CSCu196778

Symptom: A router may crash and reload with BGP related traceback in an extremely rare timing condition while running “show ip bgp vpnv4 vrf XXXX nei A.A.A.A”.

Conditions: This symptom occurs while making BGP-related changes such as moving the same neighbor with quick operation of “no neighbor x.x.x.x” and then “neighbor x.x.x.x across VRFs. Immediately after this if we type a “show ip bgp vpnv4 vrf XXXX nei A.A.A.A” - on a Cisco router running IOS and BGP, then in extremely rare timing condition the router may crash. The possibility of this to happen increases if there config and unconfig is done from one console and the show operation done from other console.

Workaround: When doing configuration and unconfiguration and then show, it is better to serialize the operation rather than aggressively use multiple consoles to do all actions at the same time.

- CSCu199015

Symptom: In VPLS using BGP Signaling with Inter AS, when a PE on another AS is reachable through multiple ASBRs, the PW destination & Next hop PE address of some or all of the PW's in Standby RP remains as the non-preferred ASBR address instead of the preferred ASBR address.

Conditions: This issue would be encountered when the following conditions occur:

1. BGP L2VPN NLRI's received first from a ASBR becomes a less preferred ASBR on receiving NLRI's for the same VE-ID's from a more preferred ASBR.
2. NLRI received from the more preferred ASBR has the same values (VEID, VBO, VBS, Label Base, MTU & CW) as the ones received previously from the other ASBR.

Workaround: Bring up BGP session with the more preferred ASBR first. This would cause no updates to existing NLRIs even if received from other less preferred ASBR.

- CSCum00056

Symptom: ASR IOSd crash occurs with the following error:

```
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = ISG CMD HANDLER
```

Conditions: This symptom occurs when changes are made through RADIUS.

Workaround: There is no workaround.

- CSCum02221

Symptom: Memory Corruption crash: chunk from bgp\_attrlist\_chunks accessed past redzone. With BGP debug update turned on there will be messages about wrong attributes, etc. by BGP Error Handling shortly before the crash.

Conditions: This symptom is observed while running BGPv4 codenomicon suite; BGP receives an update with repeating valid attributes with flag lengths bigger than data in the packet. Crash will happen every time with a generic BGP session if update as described above is received, however under normal working conditions crash will not occur as above update is not valid.

Workaround: There is no workaround.

- CSCum04512

Symptom: When an RP switchover is done (which is head end for 500 TE tunnel and tail end for 500 TE tunnels), the RSVP label is assigned to the TE tunnel change and this in turn causes a traffic loss of 45 seconds on the pseudowire which is directed through these tunnels.

Conditions: This symptom occurs under the following conditions: -TE RID under the IGP is configured as a loopback other than the first one. -SSO is performed.

Workaround: Configure the TE router ID under the IGP to be the first loopback interface.

- CSCum07119

Symptom: A router generates tracebacks or crashes depending on platforms when **show application ip route** command is used concurrently with application route deletion.

Conditions: This symptom is observed when the **show application ip route** command is issued when JAVA onePK SDK is handling route replace operations.

Workaround:

1. Use **show ip route** command to display the application routes and not **show application ip route** command.
2. Use onePK GET ROUTE API to get the status of application added route.
3. Use **show application ip route** only when there is no route delete is in progress.

- CSCum11118

Symptom: A Cisco ISR router crashes due to stack overflow in the “ADJ background” process. The following syslog may be seen just before the crash:

```
000105: Dec 9 04:08:44.447 UTC: SYS-6-STACKLOW Stack for process ADJ background
running low, 20/6000
```

Conditions: The conditions to this symptom are unknown.

Workaround: There is no workaround.

- CSCum34830

Symptom: A router crash is observed.

Conditions: This symptom occurs while performing VRRP and VRRS-related configuration changes.

Workaround: Unconfigure the **ip pim redundancy <>** command before deleting the subinterface or disabling PIM on an interface.

- CSCum42586

Symptom: SLM does not work over the port-channel evc xconnect up mep.

Conditions: This symptom occurs when port-channel member links are on the same NP.

Workaround: There is no workaround.

- CSCum78363

Symptom: Local circuit keeps DOWN state.

Conditions: This symptom is observed when L2TPv3 session is configured.

Workaround: There is no workaround.

- CSCum88382

Symptom: BFD session not established upon RP Switchover and back.

Conditions: This symptom is observed during RP switchover and switchback.

Workaround: There is no workaround.

- CSCun00488

Symptom: Duplicate records are exported from MMA.

Conditions: This symptom occurs in the following topology:

```
SRC --- UUT --DST | collector
```

Set the configuration at the UUT to export all the records to the collector. At the exporter, duplicate records are noticed.

Workaround: There is no workaround.

## Open Bugs—Cisco IOS Release 15.4(1)S

This section describes possibly unexpected behavior by Cisco IOS Release 15.4(1)S. All the bugs listed in this section are open in Cisco IOS Release 15.4(1)S. This section describes only severity 1, severity 2, and select severity 3 bugs.

- CSCuh85588

Symptoms: VRF-related CLIs are not executed under “view nw-gp”.

Conditions: This symptom occurs in VRF-related CLIs.

Workaround: Include the definition in the view rather than using all for vrf.

```
MCP-1RU(config-view)#commands configure
MCP-1RU(config-view)#commands configure incl
MCP-1RU(config-view)#commands configure include ?
  LINE  Keywords of the command
        all  wild card support
MCP-1RU(config-view)#commands configure include vrf def
MCP-1RU(config-view)#commands configure include vrf definition
```

## Resolved Bugs—Cisco IOS Release 15.4(1)S

- CSCtb34814

Symptoms: The following error message is reported just before a crash:

```
%DATACORRUPTION-1-DATAINCONSISTENCY: copy error
```

There may not be any tracebacks given for the crash.

Conditions: This symptom is observed under normal conditions.

Workaround: There is no workaround.

- CSCtd45679

Symptom: The standby supervisor reloads after removing an IPSLA probe via CLI:

```
R7600(config)#no ip sla 1
R7600(config)# 06:53:31: Config Sync: Line-by-Line sync verifying failure on command:
no ip sla 1 due to parser return error
06:53:31: rf_reload_peer_stub: RP sending reload request to Standby. User:
Config-Sync, Reason: Configuration mismatch
R7600(config)# 06:53:31: %RF-SP-5-RF_RELOAD: Peer reload. Reason: Proxy request to
reload peer
R7600(config)# 06:53:31: %OIR-SP-3-PWRCYCLE: Card in module 6, is being power-cycled
(RF request)
R7600(config)# 06:53:32: %PFREDUN-SP-6-ACTIVE: Standby processor removed or reloaded,
changing to Simplex mode
```

Conditions: This symptom only occurs if the probe is configured via SNMP.

Workaround: Remove the probe via SNMP.

More Info: This issue is applicable to a Cisco Catalyst 6500 platform running Cisco IOS 12.2SX releases. It may also affect other high availability (HA) platforms running Cisco IOS 12.2 or 15.X releases.

- CSCtq23960

Symptoms: A Cisco ISRG2 3900 series platform using PPC architecture crashes and generates empty crashinfo files:

```
show flash: all
-#- --length-- -----date/time----- path <<snip>> 2 0 Mar 13 2011 09:40:36
crashinfo_<date> 3 0 Mar 13 2011 12:35:56 crashinfo_<date> 4 0 Mar 17 2011 16:14:04
crashinfo_<date> 5 0 Mar 21 2011 05:50:58 crashinfo_<date>
```

Conditions: The symptom is observed with a Cisco ISRG2 3900 series platform using PPC architecture.

Workaround: There is no workaround.

- CSCtx20903

Symptom: TACACS authentication fallback does not work.

Conditions: This symptom occurs in single connection TACACS host.

Workaround: Disable the single connection.

- CSCty13747

Symptoms: Cisco Network Based Application Recognition (NBAR) applications with “engine-id=13” not shown or exported.

Conditions: This symptom is observed while executing the **show flow exporter option application table** command.

Workaround: The issue has been fixed.

- CSCty57970

Symptoms: A crash occurs when “content-scan out” is unconfigured from the egress interface.

Conditions: This symptom occurs when “content-scan out” is unconfigured after router runs continuously for around two days.

Workaround: There is no known workaround.

- CSCtz19192

Symptom: Router crashes with the following message:

```
Unexpected exception to CPU: vector 120.
```

Conditions: This symptom occurs due to a change in the bandwidth or policing rate of the dialer interface.

Workaround: Downgrade to Cisco IOS Release 15.1(4)M4.

- CSCtz66347

Symptom: Router crashes on executing **show tech-support** from the linux client to the IOS server over an SSH session with the rekey enabled.

Conditions: This symptom occurs when the rekey value “ip ssh rekey volume 400” is configured.

Workaround: Disable the rekey feature by configuring the **no ip ssh rekey** command.

- CSCtz98228

Symptom: On the Cisco 3900e platform, a crash and router reload occurs without generating any crashinfo and traceback.

Conditions: This symptom could be seen with HTTP traffic intercepted by the content-scan feature. It is mostly seen during the content-scan session creation.

Workaround: Disable the content-scan feature.

- CSCua64100

Symptom: SCTP receive message fails when the socktest tool is used.

Conditions: This symptom is seen only when the socktest tool is used.

Workaround: Another test tool can be used.

- CSCub95285

Symptoms: No logging messages are seen when configuring the syslog server in CLI mode until configuration mode is exited. However when unconfiguring the syslog server, syslog messages will appear within configuration mode.

Conditions: The symptom is observed when, in CLI configuration mode, you enter the following command:

```
Router(config)#logging host 1.2.3.4 transport tcp
```

Workaround: There is no workaround.

- CSCuc11958

Symptom: 7600-SIP-400 linecard crash seen with SPA reload.

Conditions: The symptom is observed with a SPA reload.

Workaround: There is no workaround.

- CSCuc41531

Symptoms: Forwarding loop is observed for some PfR-controlled traffic.

Conditions: This symptom is observed with the following conditions:

- Traffic Classes (TCs) are controlled via PBR.
- The parent route is withdrawn on selected BR/exit.

Workaround: This issue does not affect configured or statically defined applications, but only affects learned applications so this can be used as one workaround. Another option is to issue shut/no shut on PfR master or clear the related TCs with the **clear pfr master traffic-class ...** command (this fixes the issue until the next occurrence).

- CSCuc49364

Symptoms: A discrepancy is seen between show profile flow and show metadata table.

Conditions: This symptom is observed on SIP Re-invite.

Workaround: There is no workaround.

- CSCuc51879

Symptom: Traffic loss occurs on the Cisco ASR 1000 Series Routers during an RP SSO switchover.

Conditions: This symptom occurs during an RP SSO switchover on the Cisco ASR 1000 Series Routers.

Workaround: There is no workaround.

- CSCuc57360

Symptom: Adjacencies in the stats region get exhausted.

Conditions: This symptom occurs while reloading the router with mldp inband v4 and v6 data. When the control traffic is on and when other features are configured (scaled configuration), the adjacency leak happens. Adjacency allocation failure happens for the adjacencies allocated during this time.

Workaround: There is no workaround.

- CSCuc65662

Symptom: Router crashes while configuring xconnect after traffic over SAToP over UDP.

Conditions: The symptom is observed when you send traffic using SAToP over UDP. After that try to configure SAToP over MPLS and router crashes.

Workaround: There is no workaround.

- CSCuc83061

Symptoms: In a SAF setup with EIGRP, the EIGRP peers are seen flapping continuously when there are mixed TLV version neighbors on a single interface.

Conditions: This symptom occurs when EIGRP Service-family neighbor-ship flaps are seen at random intervals. There is no definite pattern to these flaps, and they are not restricted to any one peer in the network. This issue is seen when there are two different TLV versions and they are on the same interface, and if service data is greater than 8KB.

Workaround: There is no workaround. If one of the mixed peers is removed from the interface, the issue will not be seen.

- CSCuc85638

Symptom: Ethernet CFM and ELMI interworking. If CFM is configured on xconnect and interworking with ELMI, incorrect EVC state may be reported to ELMI on MPLS configuration changes.

Conditions: The symptom is observed with the following conditions:

- CFM configured on xconnect EFP.
- ELMI configured on same interface.
- CFM-ELMI interworking enabled.

Workaround: There is no workaround.

- CSCud32155

Symptom: When the **license revoke** command is used, the license count does not reduce or change on the Cisco uBR10012 router with the Cisco uBR-MC3GX60V line card running Cisco IOS Release 12.2(33)SCF4.

Conditions: This symptom occurs when the license is revoked without installing the actual license file.

Workaround: A notification message will be displayed to user stating that the evaluation license will be installed on the device on revoke success.

- CSCud49546

Symptom: The Cisco ASR 1000 Router Processor crashes with punted fragment-bit set multicast packets.

Conditions: This symptom occurs when the fragment bit is set in the multicast packets and when the same fragment gets punted to the Router Processor more than once.

Workaround: There is no workaround.



- CSCud58457

Symptom: Standby interface stays UP/UP after a reload:

```
BGL.S.15-ASR1004-1#sh int des Interface Status Protocol Description Te0/0/0 down down
Te0/1/0 up up Te0/2/0 down down Te0/3/0 up up Gi0 admin down down
```

It should be like this :

```
BGL.S.15-ASR1004-1#sh int des
Interface Status Protocol Description
Te0/0/0 down down
Te0/1/0 up up
Te0/2/0 down down
Te0/3/0 standby mode down
Gi0 admin down down
```

Conditions: The symptom is observed when “backup interface” and “carrier-delay” are configured under the interface:

```
interface TenGigabitEthernet0/1/0
backup interface TenGigabitEthernet0/3/0
ip address 10.163.137.29 255.255.255.224
logging event link-status
carrier-delay up 1
carrier-delay down msec 0
cdp enable
hold-queue 4096 in
hold-queue 4096 out
!
interface TenGigabitEthernet0/3/0
mac-address d867.d9dd.ff10
no ip address
logging event link-status
carrier-delay up 1
carrier-delay down msec 0
cdp enable
hold-queue 4096 in
hold-queue 4096 out
!
```

Workaround: Flap the standby interface.

- CSCud86954

Symptom: Some flows are not added to the Flexible Netflow cache, as indicated by the “Flows not added” counter increasing in the **show flow monitor statistics** command output. “Debug flow monitor packets” shows “FNF\_BUILD: Lost cache entry” messages, and after some time, all cache entries are lost. At that moment, debug starts showing “FLOW MON: ip input feature builder failed on interface couldn’t get free cache entry”, and no new entries are created and exported (“Current entries” counter remains at 0).

The following is sample output when all cache entries are lost:

```
Router#sh flow monitor
FNF-MON stat Cache type: Normal Cache size: 4096 Current entries: 0 High Watermark:
882
Flows added: 15969 Flows not added: 32668 Flows aged: 15969 - Active timeout ( 1800
secs) 0 - Inactive timeout ( 15 secs) 15969 - Event aged 0 - Watermark aged 0 -
Emergency aged 0
```

Conditions: This symptom occurs when all of the following are true:

- Flexible Netflow is enabled on a DMVPN tunnel interface.
- Local policy-based routing is also enabled on the router.

- Local PBR references an ACL that does not exist or an ACL that matches IPsec packets.

Workaround:

1. Make sure that the ACL used in the local PBR route-map exists and does not match IPsec packets sent over the DMVPN tunnel interface.
  2. Disabling encryption on the tunnel interface, or changing tunnel mode from mGRE to GRE also removes this bug.
  3. The issue will not be seen if FNF is not configured, or if FNF is configured but is not monitoring VPN traffic.
- CSCud96854  
Symptom: Standby RSP crashes while unconfiguring interfaces on ACR controller.  
Conditions: The symptom is observed when using a TCLSH script to teardown 450 CEM CKTs.  
Workaround: There is no workaround.
  - CSCue05186  
Symptom: FRR LFA will wrongly switch to the alternate path if BFD is unconfigured on the peer router.  
Conditions: The symptom is observed if BFD is unconfigured on the peer router.  
Workaround: Shut the interfaces with BFD configured, remove the BFD configuration on both routers, then re-enable the interfaces.
  - CSCue09385  
Symptom: Active RP crash during sessions bring up after clearing PDP.  
Conditions: The symptom is observed after clearing PDP.  
Workaround: There is no workaround.  
More Info: This is a negative test where DHCP IP under APN on IWAG is the access interface IP. In real world, we do not configure access interface IP as a DHCP IP for an APN.
  - CSCue14596  
Symptom: The mib cfmFlowMetadataAppName value in the SNMP query should not include vendor information.  
Conditions: This symptom occurs when the SNMP query is run for mib cfmFlowMetadataAppName and the following value is obtained:  

```
cfmFlowMetadataAppName.2.1 = cisco telepresence-control
```

  
The vendor information “cisco” should be removed. The expected mib value should be as following:  

```
cfmFlowMetadataAppName.2.1 = telepresence-control
```

  
Workaround: There is no workaround.
  - CSCue18999  
Symptom: The CEF adjacency becomes incomplete after the subinterface is up in the Cisco ASR 1000 series router.  

```
Router#show ip cef vrf <vrf_name> detail | include incomplete  
Adj source: IP adj out of <subinterface>, addr <IP Address> (incomplete)
```

  
Conditions: This symptom occurs when too many subinterfaces are used and a shut/no shut is performed using an interface range on the physical interface.

Workaround 1. Execute shutdown/no shutdown on subinterfaces.

Workaround 2. Configure **no ip arp incomplete enable**.

- CSCue25754

Symptom: During reconvergence after flapping of an MVPNv6 PE/CE interface in upstream PE, SG and SG RPT Prune state for the same source, a group will be created in the Upstream PE. SG RPT Prune state will be deleted after about 60 seconds. The outgoing MVPN tunnel interface will exist in both the SG state (with OIF state as Joined) and SG RPT Prune state (with OIF state as Pruned).

Conditions: This symptom occurs only when data MDT configuration for the VRF containing the affected flow is deleted and then reconfigured while the PE/CE link is in “shutdown” state. The path to the source for the affected flow and also the Rendezvous Point for the affected flow are via the CE router attached to the link that has flapped.

Workaround: The **clear ipv6 pim topology** command will clear the states, after which only the SG state will be recreated.

- CSCue50101

Symptom: ATM OAM packets are not being sent on the L2TPv3 tunnel when configured in transparent mode.

Conditions: This symptom is observed when you enable oam-pvc manage on the CE.

Workaround: There is no workaround.

- CSCue68714

Symptom: Newer released IOS-XE BGP, post Cisco IOS Release 15.2(4)S/XE3.7 not forming BFD session with the older implementations. This happens when using eBGP multi-hop to peer between two loopback interfaces on directly connected routers.

Conditions: This ddts adds a couple of options “[single-hop | multi-hop]” to the existing BGP-BFD knob “neighbor x.x.x.x fall-over [bfd] [check-control-plane-failure]”.

So, after the change the knob would be: “neighbor x.x.x.x fall-over [bfd] [single-hop | multi-hop] [check-control-plane-failure]”

\*\*Note: Existing: “neighbor x.x.x.x fall-over [bfd]” --- This behavior would not be disturbed; so that we do not change the behavior that has been released as part of all the releases for more than three years now.

Add-on in this ddts:

1) neighbor x.x.x.x fall-over [bfd] [single-hop] -- NEW-option “single-hop”; would force BGP to open a single-hop bfd session. Even in case of back-to-back ebgp update-source loopback with 2 hop BGP peering.

2) neighbor x.x.x.x fall-over [bfd] [multi-hop] -- NEW-option “multi-hop”; would force BGP to open a multi-hop bfd session.

Workaround: There is no work around. ISR G2 should support BFD multi-hop feature.

More Info: ISR-G2 does not support multi-hop BFD, while ISR4400 supports multi-hop BFD. BFD multi-hop support for ISR-G2 needs to be provided, so that they can interop with ISR4400 and ASRs.

- CSCue68761

Symptom: A leak in small buffer is seen at ip\_mforward in Cisco IOS Release 15.1(4)M3.

```
Device: Cisco 2911 Cisco IOS: c2900-universalk9-mz .SPA.151-4.M3.bin
----- show buffers -----
```

```

Buffer elements: 156 in free list (500 max allowed) 11839912 hits, 0 misses, 617
created
Public buffer pools: Small buffers, 104 bytes (total 45187, permanent 50, peak 45187 @
10:04:00): 0 in free list (20 min, 150 max allowed) 7968057 hits, 202704 misses, 2128
trims, 47265 created 71869 failures (680277 no memory)
----- show buffers usage -----
Statistics for the Small pool Input IDB : Mu1 count: 45180 Caller pc : 0x22CF95C4
count: 45180 Resource User: IP Input count: 45180 Caller pc : 0x22381654 count: 2
Resource User: Init count: 2 Output IDB : Mu1 count: 4 Caller pc : 0x2380114C count: 4
Resource User: PIM regist count: 4 Number of Buffers used by packets generated by
system: 45187 Number of Buffers used by incoming packets:
+++++small buffer packet+++++
<snip>
Buffer information for Small buffer at 0x2A815220 data_area 0xD9DEB04, refcount 1,
next 0x0, flags 0x2080 linktype 7 (IP), enctype 16 (PPP), encsize 2, rxtype 1 if_input
0x30F21520 (Multilink1), if_output 0x0 (None) inputtime 00:02:46.212 (elapsed
05:55:11.464) outputtime 00:01:22.632 (elapsed 05:56:35.044), oqnumber 65535
datagramstart 0xD9DEB56, datagramsize 38, maximum size 260 mac_start 0xD9DEB56,
addr_start 0x0, info_start 0xD9DEB58 network_start 0xD9DEB58, transport_start
0xD9DEB6C, caller_pc 0x22CF0044
source: 10.131.124.33, destination: 224.0.1.40, id: 0x55F0, ttl: 11, TOS: 192 prot:
17, source port 496, destination port 496
Enter hex value: 0x22CF95C4 0x22CF95C4:ip_mforward(0x22ce9448)+0x51c Enter hex value:
0x22CF0044 0x22CF0044:ip_mforward(0x22ce9448)+0x51c

```

Conditions: This symptom is observed with the Cisco 2911 running Cisco IOS Release 15.1(4)M3. When IP Multicast is used with NAT, in certain scenarios when NAT functionality returns error, multicast code does not free duplicate packet buffers eventually leading to exhaustion of packet buffer pool in the router.

Workaround: There is no real workaround except to disable NAT.

- CSCue76057

Symptom: On a SIP 400 with gigeV2 SPA, when EVC is configured with “encap default”, it is seen that sometimes the FUGU TCAM is not programmed with correct VVID for the EVC. This results in incoming traffic reaching the linecard with wrong VVID. This can impact traffic incoming on the EVC.

Conditions: The symptom is observed with an “encap default” configuration under EVC, or removal and re-application of “encap default” under EVC.

Workaround: There is no workaround.

- CSCue85804

Symptom: A memory allocation error occurs in the standby log after a switchover.

Conditions: This symptom occurs after an RP switchover on a router configured with the Locator ID Separation Protocol (LISP).

Workaround: There is no workaround.

- CSCue91919

Symptom: When “ip mtu 17892” or “ipv6 mtu 17892” is configured on tunnel interfaces, a Config-Sync failure is seen after a Stateful Switch Over (SSO) and the CLI is rejected on reload.

Conditions: The tunnel modes affected are “tunnel mode ipsec ipv4” or “tunnel mode mpls traffic-engineering”. The CLI “ip mtu 17892” is accepted for the “ipsec ipv4” tunnel mode or the “mpls traffic-engineering” tunnel mode, but is nvgennd in a different order causing a Config-Sync failure on SSO.

Workaround: There is no workaround.

More Info: Since the CLI (ipv4 /ipv6 mtu 17892) is rejected on every reload, it has to be reentered to take effect.

- CSCue92027

Symptom: The RP crashes due to redzone corruption.

Conditions: This symptom occurs due to improper memory management

Workaround: There is no workaround.

- CSCue92733

Symptom: An open routing application cannot install a route into the router.

Conditions: This symptom is observed when the application sets up the route with Null0 as a next-hop interface.

Workaround: There is no workaround.

- CSCue95644

A limited number of Cisco IOS and Cisco IOS XE releases based on the Cisco IOS 15 code base include support for a new algorithm to hash user-provided plaintext passwords. This algorithm is called Type 4, and a password hashed using this algorithm is referred to as a Type 4 password. The Type 4 algorithm was designed to be a stronger alternative to the existing Type 5 and Type 7 algorithms to increase the resiliency of passwords used for the “enable secret password” and “username username secret password” commands against brute-force attacks.

For additional information please see the full Cisco Security Response at the link below.

This Cisco Security Response is available at:

<http://tools.cisco.com/security/center/content/CiscoSecurityResponse/cisco-sr-20130318-type4>

- CSCuf06108

Symptom: Memory leaks from “IPC RTTYC Message Handler” might be detected by the “show memory debug leak” tool.

Conditions: This symptom occurs when commands which involve remote TTY interactions and which are filter-specified (include or search) are executed. The memory leaks will occur on the RTTY client side.

For example: Execute this command on PRE B (Active RP):

```
sh licen all sub 0/0 | i Activeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeee
```

The memory leak will be detected on PRE A (Standby RP): Address Size Alloc\_pc PID Alloc-Proc Name 87252944 272 10F1E858 22 IPC RTTYC Messa IPC RTTYC Message Handler

Workaround: There is no workaround.

- CSCuf09198

Symptom: After deleting a VRF, you are unable to reconfigure the VRF.

Conditions: The symptom is observed when BGP SAFI 129 address-family is not configured, but unicast routes are installed into multicast RIB to serve as upstream multicast hop, as described in RFC 6513. This applies to VRFs configured before BGP is configured.

Workaround: Beyond unconfiguring BGP, there is no workaround once the issue occurs.

Configuring a dummy VRF multicast address-family under BGP before the issue occurs can prevent the problem from occurring.

- CSCuf53543

Symptom: MPLS-TP L2 VCs are down after an SIP reload and RP switchover.

Conditions: This symptom occurs when VCs are configured through an MPLS-TP tunnel in a hardware redundant platform.

Workaround: There is no workaround.

- CSCuf56776

Symptom: After a linecard is removed and reinserted (OIR), traffic may fail to pass through some virtual circuits which have been configured for pseudowire redundancy.

Conditions: This symptom is observed when the first segment ID in the redundancy group is numerically greater than the second segment.

```
PE1#show ssm id | inc 1st 1stMem: 16394 2ndMem: 12301 ActMem: 12301 1stMem: 16394
2ndMem: 12301 ActMem: 12301
```

After the OIR is performed, it can be seen that the segments are reversed on the linecard.

```
ESM-20G-12#sh ssm id | inc 1st 1stMem: 12301 2ndMem: 16394 ActMem: 12301 1stMem: 12301
2ndMem: 16394 ActMem: 12301
```

Workaround: There is no workaround.

- CSCuf56842

Symptom: A reload may occur while using **show oer** and **show pfr** commands via SSH.

Conditions: This symptom is observed when the **show pfr master application detail** command is used via SSH.

Workaround: There is no workaround.

- CSCuf60830

Symptom: The standby-RP occasionally crashes on the process SSS Manager after an RP failover when the new standby-RP attempts to sync.

Conditions: This symptom occurs during an RP Failover, at high scale, with a high churn of sessions and ISG services.

Workaround: In case the standby-RP does not recover itself after the crash, manually reload the router.

- CSCuf62756

Symptom: If **bandwidth qos-reference value** is configured on an interface which bandwidth can change, then the actual interface bandwidth will be used for QoS service-policy validation when the interface bandwidth changes. This can result in a service-policy being removed if the interface bandwidth is insufficient to meet the requirements of the service-policy, such as bandwidth guarantees.

Conditions: Affects variable-bandwidth interfaces such as EFM interfaces or PPP multilink bundles.

Workaround 1: Use proportional actions in the QoS service-policy, such as “police rate percent...”, “bandwidth remaining ratio...”, “bandwidth remaining percent...”, and “priority percent”.

Workaround 2: You can configure **bandwidth qos-reference** with maximum bandwidth of the interface:

```
interface Ethernet0 bandwidth qos-reference <max bandwidth of interface>
```

This can prevent policy-map detached due to interface bandwidth change.

- CSCuf65255

Symptom: A CPU hog is caused by unnecessary requests to calculate the dynamic MPLS label range for each of the service instances configured (especially for L3VPN services).

Conditions: This symptom will occur if there is any MPLS ip-propagate-ttl, label range, or per-interface MPLS MTU configuration on the switch/router. When this configuration is present, and there are a large number of interfaces, any operation that involves generating the configuration will be slow (for example, show run, copy run, write mem, etc).

This can result in the copy operation taking more than 300 seconds (for an average configuration size of 1000kB). Note that it will complete in due course, and the generated configuration will be correct (it takes longer than it should).

Workaround: Reducing the number of BGP routes injected for L3VPN sessions causes the CPU hog to last for a smaller duration as it reduces the number of MPLS labels assigned and thus the amount of unnecessary work being done.

- CSCuf65371

Symptom: On LAC, with “l2tp hidden” configured under VPDN template, L2TP sessions are failing to establish on existing L2TP tunnels after RP failover.

Conditions: The symptom is observed with “l2tp hidden” configured under VPDN template.

Workaround: Tear down L2TP tunnels after RP failover, or unconfigure “l2tp hidden”. Disabling L2TP redundancy with “no l2tp sso enable” will fix issue as well.

- CSCuf68995

Symptom: Ping failures are observed and traffic gets dropped.

Conditions: The symptom is observed when you configure MPLSoMGRE tunnel on PE1 and PE2. Initiate ping from CE1 to CE2. Packets reach the CE2 and replay is coming back but these packets are getting dropped on PE2. After PE2 switchover, ping fails from CE1 to CE2. PE2 is configured with MPLSoMGRE on an HA system. Topology:

```
CE1---- PE1 ----PE2----CE2
```

Workaround: There is no workaround.

- CSCuf73798

Symptom: Tracebacks are seen when Lc/Sp is comes up.

```
May 15 10:14:22.145 IST: %MFIB_PLTF-SP-3-ENTRY_HANDLE_BAD: Space. 0x291E5D04 -Process=
"mfib-const-lc Process", ipl= 0, pid= 303 -Traceback= 81D35D8z 8B13630z 8B0C434z
8A86784z 8A3F588z 8A434A8z 8A65C64z 8A68ED0z 8A86EA8z 83ECFF0z 83E82D0
```

Conditions: This symptom occurs in Cisco IOS Release 15.3(3)S.

Workaround: There is no workaround.

More Info: This issue was not reproducible. So a code walk-through and some safe checks and code strengthening was done to avoid such an error.

- CSCuf81275

Symptom: Some ISG sessions do not pass traffic.

Conditions: This symptom is observed when you have more than one Line Card for the ISG sessions.

Workaround: There is no workaround.

- CSCuf86171

Symptom: The DHCP snooping database agent can get stuck while using FTP as the transfer protocol.

The following is the output of “show ip dhcp snooping database”:

```
Agent URL : <FTP URL> Write delay Timer : 300 seconds Abort Timer : 300 seconds
```

```

Agent Running : Yes Delay Timer Expiry : 0 (00:00:00) <<<<< Delay timer is at zero,
but process will never re-start Abort Timer Expiry : Not Running
Last Succeeded Time : 02:09:53 PDT Thu Jun 6 2013 <<<<< Time will never update Last
Failed Time : None Last Failed Reason : No failure recorded.
Total Attempts : 12 Startup Failures : 0 Successful Transfers : 11 Failed Transfers :
0 Successful Reads : 1 Failed Reads : 0 Successful Writes : 10 Failed Writes : 0 Media
Failures : 0

```

Conditions: This symptom occurs while using FTP as the protocol to transfer the DHCP snooping binding database to an external server.

Workaround: Use another file transport mechanism like SCP or TFTP. Once the issue occurs, the only known workaround is to reload the affected device.

- CSCug04187

Symptom: A build breakage is observed.

Conditions: This symptom occurs due to CSCuf62756.

Workaround: There is no workaround.

- CSCug08561

Symptom: After a web-logon, users do not get the web-logon response page sent by the portal. If the web-logon is successful, users are not redirected to the web address which they have entered initially but are redirected to the portal for authentication.

Conditions: This symptom occurs under the following conditions:

1. Walkby feature is enabled with L4R & PBHK features applied to the lite session.
2. User initiated the web-logon request.

Workaround: There is no workaround.

More Info: When a user does a web-logon, an account-logon coa request is triggered from the portal to ISG. In ISG, the account-logon request triggers a lite session conversion to a dedicated session. During the conversion, lite session and its associated resources (L4R and PBHK mappings) are removed from PD and a dedicated session gets provisioned. Once the conversion is done, ISG replies back with COA ACK/NACK to the portal. Based on the response from ISG, the portal generates a weblogon response (SUCCESS/FAILURE) page and sends it back to the client. But when it reaches ISG, the response packet does not get classified to session in the downstream direction and gets dropped in ISG because PBHK & L4R mapping are deleted.

- CSCug08663

Symptom: Traffic drops on the edge device and traffic looping may occur after a shut and no shut of the overlay interface.

Conditions: This symptom may occur in an OTV multihoming setup when the overlay interface on one of the edge devices is shut and no shut in quick succession.

Workaround: There is no workaround.

- CSCug15952

Symptom: %QOS-3-INDEX\_EXISTS error message is shown and router crashes.

Conditions: The symptom is observed when sessions are brought up and the collision IDs with dynamic policy names are synced to standby from active. When the sessions time out and restart, the same dynamic policy names are synced to HA tree on standby again without cleaning up the tree earlier and the crash will happen.

Workaround: Avoid the same session reestablishment before rebooting the router.



- CSCug17724

Symptom: When using session protection and graceful restart for LDP, LDP neighbor goes down immediately after filtering LDP hello between routers. The LDP neighbor should go down after 10 minutes (default value of forwarding state holding time for GR).

Conditions: The symptom is observed when you enable session protection and graceful restart for LDP

Workaround: There is no workaround.

- CSCug17808

Symptom: In certain scenarios, EIGRP routes are advertised only to stub peers and are not advertised to non-stub peers.

EIGRP routes are routes in the EIGRP Topo table. They can be routes learnt by EIGRP peer or can be redistributed.

Conditions: This symptom is observed when a Cisco ASR router is rebooted or the route is cleared via the **clear ip route** command and the route disappears from the spokes. This bug is not restricted to Cisco ASR routers. It can happen to any kind of routers if the following conditions are met:

1. Peers must be a mixture of stubs and non-stubs.
2. When a route is lost, send a query to non-stubs and wait for a reply from non-stubs about the query.
3. A new update needs to be sent to all peers.

Workaround: Upgrade to an image with the fix for this bug. Clearing the EIGRP neighborship restores the route on the spokes.

Further Problem Description: In an ideal scenario, the sequence is as follows:

1. When a route is lost, a query to non-stubs is sent.
2. After receiving a reply from non-stubs, infinite metric to stub peers is sent.
3. The route is learnt again.
4. The route is advertised to both stub and non-stub peers properly.

In a defective scenario (for example clear route), as a new route is learnt before getting a reply from non stubs, especially when non-stub neighbors or networks beyond non-stubs are more, sequence (3) comes before (2). In such cases routes are sent only to stubs.

- CSCug17820

Symptoms: Random crashes are seen pointing to managed timer in L4F component.

Conditions: The symptom is observed during scansafe traffic.

Workaround: Disable the scansafe feature.

- CSCug18797

Symptom: Router crashes when it checks whether the interface is configured as DHCP SIP session initiator.

Conditions: The symptom is observed DHCP and ISG are configured.

Workaround: There is no workaround.

- CSCug21879

Symptom: After a link flap, ATM PVC does not come up due to PPP negotiation failure.

Conditions: This symptom occurs due to LCP timeout. The output queue of the Virtual Access Interface mapped to the dialer interface will be stuck or will be full with continual increment of output drops under the Virtual Access Interface.

Workaround: The two possible ways to recover from the Virtual Access Interface being stuck are:

1. Reconfiguring the ATM PVC.
2. Unbinding and rebinding the dialer to the ATM PVC using **no dialer pool-member <> & dialer pool-member <>** commands under the interface configuration mode.

- CSCug24114

Symptom: CTS environment-data download fails from ISE.

Conditions: The symptom is observed if there is less PAC and environment-data refresh timer is configured in ISE. After multiple refreshes of PAC and environment data and the switch is reloaded, sometimes a CTS environment-data download fails from ISE on the switch.

Workaround: Unconfigure **pac key CLI** and configure it again as below:

```
no pac key pac key <key-id>
```

- CSCug25258

Symptom: Router crashes while running the **show interface rate-limit** command. When entries down the list of the output disappear for reasons such as interfaces going down or PPPoE clients disconnecting, the router may crash when you hit the space bar to get to these invalid entries.

Conditions: This symptom occurs when rate limiting is configured.

Workaround: Configure **term length 0** before running the show output.

- CSCug31561

A vulnerability in the DHCP implementation of Cisco IOS Software and Cisco IOS XE Software could allow an unauthenticated, remote attacker to cause a denial of service (DoS) condition.

The vulnerability occurs during the parsing of crafted DHCP packets. An attacker could exploit this vulnerability by sending crafted DHCP packets to an affected device that has the DHCP server or DHCP relay feature enabled. An exploit could allow the attacker to cause a reload of an affected device.

Cisco has released free software updates that address this vulnerability. There are no workarounds to this vulnerability.

This advisory is available at the following link:

<http://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20130925-dhcp>

Note: The September 25, 2013, Cisco IOS Software Security Advisory bundled publication includes eight Cisco Security Advisories. All advisories address vulnerabilities in Cisco IOS Software. Each Cisco IOS Software Security Advisory lists the Cisco IOS Software releases that correct the vulnerability or vulnerabilities detailed in the advisory as well as the Cisco IOS Software releases that correct all Cisco IOS Software vulnerabilities in the September 2013 bundled publication.

Individual publication links are in “Cisco Event Response: Semiannual Cisco IOS Software Security Advisory Bundled Publication” at the following link:

[http://www.cisco.com/web/about/security/intelligence/Cisco\\_ERP\\_sep13.html](http://www.cisco.com/web/about/security/intelligence/Cisco_ERP_sep13.html)

- CSCug31579

Symptom: In an OTV scenario, when a multicast source (site) is connected via dual OTV routers and if the AED node’s L3 interface flaps and comes up within around 30 seconds, the multicast stream stops flowing due to an RPF failure on the data group.

Conditions: This symptom occurs only when an AED node's L3 interface (join interface) flaps and comes up within around 30-50 seconds.

Workaround: Clear the mroute table on an AED using **clear ip mroute <data-group>**. This issue is not seen if the flapped interface comes up after around 150 seconds.

- CSCug33084

Symptom: An SP/DFC crash is seen when a churn on the multicast is done either through provisioning/unprovisioning or through other network events.

Conditions: This symptom occurs when a pointer to an already freed hal\_context is still present in a replicate queue. Later during the churn the same pointer is accessed which leads to the crash.

Workaround: There is no workaround.

- CSCug34485

Multiple Cisco products are affected by a vulnerability involving the Open Shortest Path First (OSPF) Routing Protocol Link State Advertisement (LSA) database. This vulnerability could allow an unauthenticated attacker to take full control of the OSPF Autonomous System (AS) domain routing table, blackhole traffic, and intercept traffic.

The attacker could trigger this vulnerability by injecting crafted OSPF packets. Successful exploitation could cause flushing of the routing table on a targeted router, as well as propagation of the crafted OSPF LSA type 1 update throughout the OSPF AS domain.

To exploit this vulnerability, an attacker must accurately determine certain parameters within the LSA database on the target router. This vulnerability can only be triggered by sending crafted unicast or multicast LSA type 1 packets. No other LSA type packets can trigger this vulnerability.

OSPFv3 is not affected by this vulnerability. Fabric Shortest Path First (FSPF) protocol is not affected by this vulnerability.

Cisco has released free software updates that address this vulnerability. Workarounds that mitigate this vulnerability are available. This advisory is available at the following link:

<http://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20130801-lsaospf>.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5.8/5.8:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:M/Au:N/C:N/I:P/A:P/E:H/RL:U/RC:C>

CVE ID CVE-2013-0149 has been assigned to document this issue. Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCug34503

Symptom: LLDP packets with destination MAC: 01:80:C2:00:00:0E are dropped.

Conditions: This symptom occurs with the fix of CSCue41216.

Workaround: There is no workaround.

More Info: Regression because of CSCue41216 causes LLDP packets which have a MAC address of 01.80.c2.00.00.0e to get dropped according to MEF standard. But the packets should get dropped for SUNI and NNI port, while for CUNI they should get passed.

- CSCug34877

Symptom: Switch crashes with the following message:

```
%SYS-2-LINKED: Bad enqueue of 901E0D40 in queue 1AABE690 -Process= "SSH Process", ipl= 0, pid= 392
```

Conditions: This symptom occurs during an SSH connection to a remote device from the switch while having multiple SSH connections to the same switch.

Workaround: There is no workaround.

- CSCug37196

Symptom: Execution of “no bfd interval” under an interface results in a router crash.

Conditions: Basic usage of the BFD template on an interface followed by the execution of the “no bfd interval” results in a router crash.

Workaround: There is no workaround.

- CSCug37333

Symptom: An error occurs while attaching a non-queue based service policy in the input direction.

Conditions: This symptom occurs while attaching a service policy map in the input direction.

Workaround: There is no workaround.

- CSCug38011

Symptom: Device crashes with CPU hog messages.

Conditions: The symptom is observed when the device is reloaded after configuring NTP peer:

```
ntp server pool.ntp.org source cell0
```

Workaround: There is no workaround.

- CSCug38248

Symptom: Watchdog crash is observed on “Common Flow Table” timer process. For example:

```
%SYS-2-WATCHDOG: Process aborted on watchdog timeout, process = CFT Timer Process.
```

Conditions: Error is raised due to a CPU loop while attempting to unbind and delete a child flow in the “CFT Timer” process.

Workaround: There is no workaround.

- CSCug39278

Symptom: L3 QoS policy not working in EVC L3 VPN.

Conditions: The symptom is observed when CFM is enabled globally.

Workaround: Disable CFM.

- CSCug41888

This is by design currently. Logging persistent uses the software forced crash unexpected restart reason to handle various errors including misconfigurations and running out of space on the flash device in certain circumstances. CSCts03251 addressed one circumstance where running out of space on a flash device would lead to a software forced crash unexpected restart when trying to write to the persistent log, but if the flash is out of space and the oldest file is being deleted, the same issue can occur still.

One known misconfiguration to lead to a software forced crash is to configure the protected option with a url that points to a file rather than a directory. When the next logging message is attempted to be written to the persistent log, the persistent logging feature determines that it can not write to the url provided and invokes a software forced crash. To avoid this, ensure that the url provided in the logging persistent command points to a directory or do not use the protected option.

PSIRT Evaluation:

The Cisco PSIRT has evaluated this issue and does not meet the criteria for PSIRT ownership or involvement. This issue will be addressed via normal resolution channels.

If you believe that there is new information that would cause a change in the severity of this issue, please contact [psirt@cisco.com](mailto:psirt@cisco.com) for another evaluation.

Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCug44641

Symptom: The **clear xconnect all** command causes xconnect related CFM configuration to be removed permanently.

Conditions: This symptom is observed only when using xconnect related CFM configuration.

Workaround: Avoid issuing the **clear xconnect all** command.

- CSCug48702

Symptom: When no **ipv6 unicast-routing** is configured, a crash occurs in the router in the ART code.

Conditions: This symptom occurs under the following conditions:

1. Configure **ipv6 unicast-routing**.
2. Add a few application routes.
3. Configure **no ipv6 unicast-routing**.

Workaround: There is no workaround.

- CSCug50208

Symptom: A crash is seen due to double free of memory.

Conditions: The symptom is seen when the accept interface VLAN goes down.

Workaround: There is no workaround.

- CSCug50340

Symptom: PW traffic is not flowing after SSO/card reset the active PTF card.

Conditions: The symptom is observed with the following conditions:

1. Create a unprotected tunnel between the active PTF card and create a PW.
2. Apply the table map. Bi-directional traffic is flowing fine.
3. SSO/reset the active PTF card in node 106 (4/1).
4. Now tunnel core port is in standby card.
5. Observed bi-directional traffic is not flowing once the card becomes up.
6. Again reset the active PTF card (5/4).
7. Observe uni-directional traffic only is flowing.

Workaround: Delete the PW and recreate it again. However, note that if you do an SSO/card reset, the issue reappears.

- CSCug50606

Symptom: Sometimes, IPCP assigns an different address for clients from wrong address pool.

Conditions: This symptom is observed under the following conditions:

- **peer default ip address** command is configured on dialers.

- There are some dialers on the Cisco router.
- The issue could happen on Cisco IOS Release 15.2(4)M3.

Workaround: There is no workaround.

- CSCug52119

Symptom: A RIB route is present for a prefix, but the router continues to LISP encapsulate.

Conditions: The symptom is observed when a LISP map-cache existed for a prefix and then the RIB route was added later.

Workaround: Use the following command:

```
clear ip/ipv6 lisp map-cache <prefix>
```

- CSCug58977

Symptom: 2.6Gbp/s traffic is observed on both of the VPN SPA interfaces. Traffic direction: Rx on outside interface, Tx on inside interface.

Conditions: This symptom occurs when fragmented IPSec packet arrives on clear side. The issue is observed only in VRF mode.

Workaround: Reload the IPSec card.

- CSCug59746

Symptom: A crash is seen on the RP in the SS manager process:

```
Exception to IOS Thread: Frame pointer 0x7F58BB22FE80, PC = 0x7C505FB
UNIX-EXT-SIGNAL: Segmentation fault(11), Process = SSS Manager -Traceback=
1#980611ad3b9665cd80fe5178bcd6036a :400000+78505FB :400000+7C68774 :400000+7C6871A
:400000+1C13522 :400000+7852194 :400000+78512C8 :400000+7C68774 :400000+7C6871A
:400000+33A8AC1 :400000+77DD92F :400000+33C3E4C :400000+33AFE89 :400000+33B2564
:400000+7824301 :400000+7823F37 :400000+77FA27F
```

Conditions: The issue appears to be related to NAS port. It looks like a key is being set when the issue occurred. The exact conditions are still being investigated.

Workaround: Possibly remove radius or more specifically, NAS port configurations. This still needs to be verified.

- CSCug61252

Symptoms: The potential exists for an unauthenticated user to read the contents of an uninitialized memory of a WebEx node.

Conditions: This symptom occurs in the default installation of an affected version of the WebEx node software.

Workaround: There is no workaround.

Additional details about the vulnerability described here can be found at:

<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-1232>

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5/5:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:L/Au:N/C:P/I:N/A:N/E:H/RL:U/RC:C>

CVE ID CVE-2013-1232 has been assigned to document this issue. Additional information on Cisco's security vulnerability policy can be found at the following URL:

[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCug61485

Symptom: The Cisco ASR 1000 RP crashes in RSVP.

Conditions: This symptom occurs when “mpls traffic-eng tunnels” is configured on an interface and “ip rsvp bandwidth” is not configured and the bandwidth on the physical interface is changed.

Workaround: There is no workaround.

- CSCug62154

Symptom: CPU shoots to 100% with TACACS configuration. VTY to the device does not work due to this.

Conditions: This symptom is observed when the router or switch is booted up with TACACS configurations and the CPU shoots up to 100%. Telnet to the router is not possible. Any command issued on the console would take lot of time.

Workaround: Remove the TACACS configurations and then reboot the router.

- CSCug64059

Symptom: In a rare case when the VPN core RR advertises paths that contain the ibgp-CE attribute ATTR\_SET to the PE and does a graceful start, the PE router crashes.

Conditions: This symptom occurs in a rare case when the VPN core RR advertises paths that contain the ibgp-CE attribute ATTR\_SET to the PE and the peering RR to PE does a graceful restart. In case the RR switches over then the stale paths in the PE containing ATTR\_SET cause the PE to crash.

Workaround: This problem will not occur if the RR that sends paths to the PE with ATTR\_SET does not enable graceful restart.

- CSCug64957

Symptom: An error occurs on changing the grandchild class rate.

Conditions: This symptom occurs when 1x1000x8 policy maps are configured.

Workaround: There is no workaround.

- CSCug68193

Symptom: Multicast traffic across ES+ cards stop flowing across subinterfaces.

Conditions: The symptom is observed after a linecard OIR. After the linecard comes up, multicast traffic stops flowing across subinterfaces.

Workaround: Shut/no shut the subinterface.

- CSCug70151

Symptom: The box crashes on removing the oneP datapath transport CLI configuration.

Conditions: This symptom occurs only on Cisco c3945e, Cisco c3925e and Cisco IOL platforms.

Workaround: There is no workaround.

- CSCug71297

Symptom: An SP crash is observed at the below RPC call block during an ISSU upgrade after commit version.

```
SP: Frames of RPC pf_issu_sp2rp process (pid 579) on 16 (proc|slot) after blocking rpc call failed: 42342B84
```

Conditions: This symptom occurs during ISSU commit version while saving the configuration.

Workaround: There is no workaround.

- CSCug72891
 

Symptom: EIGRP neighbor flaps due to EIGRP SIA. Troubleshooting shows that a race condition causes EIGRP successor loop first and it leads to EIGRP QUERY loop resulting in the neighbor flaps.

Conditions: The issue is observed when a worse metric update is received from the successor, once the route is already in active state, in a partially peered multiaccess network.

Workaround: There is no workaround.
- CSCug75194
 

Symptom: A latency issue is observed. The order of packets changes.

Conditions: This symptom occurs on EVC xconnect for MACsec packets and data packets.

Workaround: Stop the control traffic from the peer side and send only data traffic.
- CSCug77784
 

Symptom: When **wr mem** is executed, the following error message is seen:

```
private-config file open failed (File table overflow)
```

Conditions: This symptom occurs when the standby is reloaded continuously. Due to this, the client, that is, the active side is not able to reach the standby side and while returning an error, the FD is not released and exhausts FDs. The maximum number of open FDs allowed is 128. Once this limit is reached, no more files can be opened.

Workaround: Reload is a possible workaround to free the FDs.
- CSCug78098
 

Symptom: Supervisor engine crashes and the Cisco IOS software is forced to reload due to the PIM process.

Conditions: This symptom is observed when using the **show ip pim rp-hash** command right after the BSR RP times out and causes the crash.

Workaround: Perform these steps in the following order:

  1. Wait for a minute after BSR RP times out before using this command.
  2. Configuring **no ip domain lookup** will make the time taken to execute **show ip pim rp-hash** to a few milliseconds. This will prevent the crash from being reproduced manually.
- CSCug78929
 

Symptom: Packets of a certain protocol are dropped due to v6 PACL applied on a switch port.

Conditions: This symptom occurs when v6 PACL contains explicit protocol entries such as “permit 89 any any”.

Workaround: There is no workaround.
- CSCug79199
 

Symptom: When the Gigabit Ethernet SPA interface configured with vlan0, that is, “encapsulation priority-tagged native tx-tagged” undergoes MDR, MDR will fail with a “:%ETH\_SPA\_GILA\_FUGU-3-HW\_SW\_MISMATCH” message. MDR will be aborted and the SPA will undergo a reboot thereby causing interface flaps and traffic loss.

Conditions: This symptom occurs when the Gigabit Ethernet interface is configured with vlan0 configuration as follows:

```
interface GigabitEthernet0/1/0.9
encapsulation priority-tagged native tx-tagged
```



```
ip address 21.0.0.1 255.255.255.0 !
```

Workaround: There is no workaround.

- CSCug79561

Symptom: Memory leaks are observed when accessing certain parts of the PTP MIB.

Conditions: This symptom occurs when the following OIDs are accessed:

```
cPtpClockInput1ppsInterface : 1.3.6.1.4.1.9.9.760.1.1.3.1.11
cPtpClockOutput1ppsInterface : 1.3.6.1.4.1.9.9.760.1.1.3.1.12 cPtpClockTODInterface :
1.3.6.1.4.1.9.9.760.1.1.3.1.13 cPtpClockCurrentDSOffsetFromMaster :
1.3.6.1.4.1.9.9.760.1.2.1.1.5 cPtpClockCurrentDSMeanPathDelay :
1.3.6.1.4.1.9.9.760.1.2.1.1.6 cPtpClockParentDSParentPortIdentity :
1.3.6.1.4.1.9.9.760.1.2.2.1.4 cPtpClockParentDSGMClockIdentity :
1.3.6.1.4.1.9.9.760.1.2.2.1.8 cPtpClockDefaultDSClockIdentity :
1.3.6.1.4.1.9.9.760.1.2.3.1.5 cPtpClockTransDefaultDSClockIdentity :
1.3.6.1.4.1.9.9.760.1.2.6.1.3 cPtpClockPortName : 1.3.6.1.4.1.9.9.760.1.2.7.1.5
cPtpClockPortCurrentPeerAddress : 1.3.6.1.4.1.9.9.760.1.2.7.1.9 cPtpClockPortDSName :
1.3.6.1.4.1.9.9.760.1.2.8.1.5 cPtpClockPortDSPortIdentity :
1.3.6.1.4.1.9.9.760.1.2.8.1.6 cPtpClockPortDSPeerMeanPathDelay :
1.3.6.1.4.1.9.9.760.1.2.8.1.13 cPtpClockPortRunningName :
1.3.6.1.4.1.9.9.760.1.2.9.1.5 cPtpClockPortTransDSPortIdentity :
1.3.6.1.4.1.9.9.760.1.2.10.1.4 cPtpClockPortTransDSPeerMeanPathDelay :
1.3.6.1.4.1.9.9.760.1.2.10.1.7 cPtpClockPortAssociateAddress :
1.3.6.1.4.1.9.9.760.1.2.11.1.7
```

Workaround: Exclude the above OIDs.

- CSCug79857

Symptom: Router crash is seen.

Conditions: The symptom is observed when you issue the following command:

```
show ip subscriber mac e01d.3b70.108e
```

Workaround: Do **show ip subscriber mac e01d.3b70.108e** only for the sessions in connected state, that is, sessions should not be in “Attempting” state in **sh sss sess | i mac address**.

- CSCug83238

Symptom: TE Tunnel constantly performs signalling attempts instead of holding down the path option, which causes CPU to become very busy.

Conditions: The symptom is observed with the following conditions:

- Configuration of multiple verbatim explicit path options.
- Path error during LSP signalling.

Workaround: There is no workaround.

- CSCug85947

Symptom: OSPFv3 routes go missing after an NSR switchover.

Conditions: This symptom occurs after an SSO.

Workaround: Clear the IPv6 OSPF process.

- CSCug86298

Symptom: The “14f mgt task” process takes up memory and does not release it.

Conditions: This symptom occurs with scansafe configuration.

Workaround: There is no workaround.

- CSCug87772
 

Symptom: On a receiver PE router with a scaled receiver MVRF, stale entries are left behind in the MFIB table after a shut/unshut of the subinterfaces.

Conditions: This symptom occurs when 200 receiver MVRFs are configured on the receiver PE router and the subinterfaces are shut/unshut.

Workaround: There is no workaround.
- CSCug92091
 

Symptom: When an IPv6 host is performing DAD and it is not yet present in the binding table it might log the following message:

```
%SISF-4-PAK_DROP: Message dropped A=:: G=FE80::84D2:B20F:7041:433D V=7 I=Gi1/0/13
P=NDP::NS Reason=Advertise while TENTATIVE
```

This packet is seen on other ports in the same VLAN without an impact to DAD. Hence the message is misleading.

Conditions: This symptom occurs when DAD packets are received on the switch and they can be logged as drops.

Workaround: There is no workaround.
- CSCug92748
 

Symptom: Pathtrace (Mediatrace) Service Set APIs can crash the network element when the source-ip or destination-ip in the path specifier is null.

Conditions: This symptom occurs when Pathtrace (Mediatrace) Service Set APIs is used with a path-specifier with a destination ip or source ip set to null.

Workaround: Do not use source ip and destination ip as null for path specifier while using the Pathtrace (Mediatrace) Service Set APIs.
- CSCug94275
 

Symptom: ES+ card crashes with an unexpected exception to CPU: vector 200, PC = 0x0.

Conditions: The symptom is observed on the ES+ series linecards on a Cisco 7600 series router. Symptom is reported on the ES+ console and in the crashinfo file on the ES+ flash disk. It is not reported in the syslog.

Workaround: There is no workaround.
- CSCug97383
 

Symptom: Switch crashes with EOAM and IP SLA Ethernet-monitor configurations.

Conditions: This issue occurs infrequently when EOAM configuration include VLANs. Does not occur if all EOAM configurations are configured with only Ethernet Virtual Circuits (EVC).

Workaround: There is no workaround.
- CSCug99771
 

Symptom: OSPF N2 default route missing from Spoke upon reloading Hub. Hub has a static default route configured and sends that route over DMVPN tunnel running OSPF to spoke. When hub is reloaded, the default route is missing on Spoke. NSSA-External LSA is there on Spoke after reload, but the routing bit is not set. Hence, it is not installed in RIB on Spoke.

Conditions: Default originated using command **area X nssa default-information-originate**.

Workaround: Removing & re adding **area X nssa default-information-originate** on Hub resolves the issue.

- CSCuh01533  
Symptom: Memory leaks are seen at SADB index list.  
Conditions: This symptom is observed in ISR-G2 and ASR platforms when the configurations are loaded.  
Workaround: There is no workaround.
- CSCuh03718  
Symptom: When configuring a fail-close policy for GETVPN, an exemption for locally terminated VPN on the GM (deny esp any any) does not work. The traffic will still be blocked until the GETVPN policy is downloaded via a registration to the KS.  
One scenario is where the GM is terminating a GETVPN domain as well as GRE/IPSEC tunnels encrypted by tunnel-protection.  
Conditions: This symptom is observed under no specific conditions.  
Workaround: There is no workaround.
- CSCuh06821  
Symptom: Traffic drop occurs after the SSO.  
Conditions: This symptom is observed with RSP10g.  
Workaround: There is no workaround.
- CSCuh07349  
Symptom: A Cisco 7600 Sup may crash due to SP memory corruption.  
Conditions: This issue is observed on an REP enabled router, which is part of an REP segment. The exact trigger for this issue is not clear.  
Workaround: There is no workaround.
- CSCuh07404  
Symptom: VFI and PWs remain down.  
Conditions: This symptom is observed after removing and re-adding VLAN.  
Workaround: Configure **member vfi <>** command again under VLAN configuration.
- CSCuh07657  
Symptom: VRF Aggregate label is not re-originated after a directly connected CE facing interface (in VRF) is shut down.  
Conditions: This symptom occurs in an MPLS VPN set-up with Cisco 7600(PE) Router running on Cisco IOS Release 12.2(33)SRE4 with per VRF aggregation.  
For example:  

```
mpls label mode vrf TEST protocol all-afs per-vrf
```

  
Workaround: Downgrade to Cisco IOS Release 12.2(33)SRE3 or earlier.
- CSCuh09412  
Symptom: A Cisco ASR 1000 running ISG with “radius-proxy session-restart” crashes when WiFi clients are roaming between hotspots.  
Conditions: The symptom is observed if a client roams between WiFi access points and the accounting-stop message from the initial access point does not reach the ISG where the subscriber session is active as can sometimes be the case of roaming between access points on a wireless LAN controller.

Workaround: Disable “radius-proxy session-restart” and reload the chassis to clear the session-cache.

- CSCuh16115

Symptom: With VPLS configuration with IP-FRR, on doing multiple churns SP/LC may crash.

Conditions: The issue occurs when xconnect internal data structure is to be freed up and IP FRR is still pointing to it.

Workaround: Remove IP-FRR configuration before unprovisioning xconnect.

- CSCuh16927

Symptom: Mac entries learned on a trunk link are flushed after removing VLANs.

Conditions: The symptom is observed when some allowed VLANs are removed on a trunk link, all mac address entries learned on this link are flushed. This issue is specific to extended VLAN IDs.

Workaround: Executing ping to destination IP after removing VLANs will recover this condition.

- CSCuh20027

Symptom: Cisco router configured with Locator ID Separation Protocol (LISP) configuration may crash when LISP debug is enabled.

Conditions: This symptom is observed when LISP debug output is enabled through “debug lisp control ...”.

Workaround: Disable LISP debugging.

- CSCuh21740

Symptom: There is a deletion and addition of VRFs with MVPNV6 configurations.

Conditions: This symptom occurs when PIM VRF neighbors are not up.

Workaround: Reload the router.

- CSCuh24040

Symptom: BGP routes are not marked Stale and considered best routes even though the BGP session with the peer is torn down. A hard or soft reset of the BGP peering session does not help.

For BFD-related triggering, the following messages are normally produced with the BGP-5-ADJCHANGE message first, and the BGP\_SESSION-5-ADJCHANGE message second. Under normal conditions, the two messages will have identical timestamps. When this problem is seen, the order of the messages will be reversed, with the BGP\_SESSION-5-ADJCHANGE message appearing first, and with a slightly different timestamp from the BGP-5-ADJCHANGE message. In the problem case, the BGP\_SESSION-5-ADJCHANGE message will also include the string “NSF peer closed the session”

For example when encountering this bug, you would see:

```
May 29 18:16:24.414: %BGP_SESSION-5-ADJCHANGE: neighbor x.x.x.x IPv4 Unicast vpn vrf
VRFNAME topology base removed from session NSF peer closed the session May 29
18:16:24.526: %BGP-5-ADJCHANGE: neighbor x.x.x.x vpn vrf VRFNAME Down BFD adjacency
down
Instead of: May 29 18:16:24.354: %BGP-5-ADJCHANGE: neighbor x.x.x.x vpn vrf VRFNAME
Down BFD adjacency down May 29 18:16:24.354: %BGP_SESSION-5-ADJCHANGE: neighbor
x.x.x.x IPv4 Unicast vpn vrf VRFNAME topology base removed from session BFD adjacency
down
```

Log messages associated for non-BFD triggers are not documented.

Conditions: This symptom is observed when BGP graceful restart is used in conjunction with BFD, but it is possible (but very low probability) for it to happen when BGP graceful restart processing happens when any other type of BGP reset (Example: clear command) is in progress.

Affected configurations all include:

```
router bgp ASN
...
bgp graceful-restart
...
```

The trigger is that BGP exceeds its CPU quantum during the processing of a reset, and gives up the CPU, and then BGP Graceful Restart processing runs before BGP can complete its reset processing. This is a very low probability event, and triggering it is going to be highly dependent on the configuration of the router, and on BGP's CPU requirements.

It is not possible to trigger this bug unless BGP graceful-restart is configured.

Workaround: If you are engaged in active monitoring of router logs, and the bug is being triggered by a BFD-induced reset, you can detect this situation by watching for the reversal of log message order described in the Symptoms section, and then take manual steps to remedy this problem when it occurs.

On the problematic router, issue **no neighbor <xxx> activate** command under the proper address-family will clear the stale routes.

The other option is to manually shutdown the outgoing interface which marks the routes as “inaccessible” and hence not been used anymore. This prevents the traffic blackhole but the routes will stay in the BGP table.

More Info: This bug affects all releases where CSCsk79641 or CSCtn58128 is integrated. Releases where neither of those fixes is integrated are not affected.

- CSCUh27770

Symptom: On a dual-RP system which is configured for stateful switchover (SSO), some VPLS virtual circuits may fail to be provisioned on the standby route processor.

Conditions: This symptom is observed when the VFI consists of VLAN interfaces that are also configured for IP.

Workaround: Reload the standby RP.

- CSCUh32177

Symptom: The “no passive-interface <if-name>” command will be added automatically after configuring the “ipv6 enable” command on the interface even though the “passive-interface default” command is configured for OSPFv3.

```
(config)#interface FastEthernet0/2/0
(config-if)#ipv6 enable
(config-if)#end
#sh run | sec ipv6 router ospf
ipv6 router ospf 100 router-id 10.1.1.1
passive-interface default
no passive-interface FastEthernet0/2/0 <<< Added automatically. ---
```

Conditions: This symptom occurs when the “passive-interface default” command is configured for OSPFv3.

Workaround: Adjust the configuration manually. In this example it would be “passive-interface FastEthernet0/2/0”.

- CSCuh32439

Symptom: A linktrace targeted at the MAC address of a remote MIP fails with no response seen from the router with the target MIP despite the fact that a linktrace targeted at a MEP or MIP beyond that MIP fully succeeds (including recording the existence of the MIP that cannot be targeted directly).

Conditions: This symptom is seen only when all of the following conditions are true:

- The router on which the target MIP is on uses the 'Bridgeport' model of assigning MAC addresses to MPs (currently, this is just Cisco ASR 901 router).
- The target MIP is on a port channel interface.
- The target MIP is not on the port that the linktrace will ingress on.

Workaround: Linktraces to MIPs or MEPs beyond the failing MIP will succeed and return the relevant information for the untargetable MIP.

- CSCuh36124

Symptom: Service Routing/SAF in Cisco IOS Release 15.2 experiences HIGH cpu during a failover condition where the active SAF forwarder loses connection to the network causing the clients to switch to the secondary forwarder. This problem only happens if the forwarder that becomes active still has an active neighbor that it needs to send an updated registration data to ( so more than 2 forwarders are required to observe this defect ). Due to the high CPU condition during this failover, clients can experience longer registration times increasing the outage window.

Conditions: This symptom occurs when more than 2 forwarders are involved and all the forwarders are peered to each other via direct configured peers or network-based EIGRP peers. The HIGH CPU is caused directly by the connection that exists between SAF forwarders to exchange data across the network, and not due to the client towards SAF forwarder data exchange.

Workaround: There is no workaround.

- CSCuh37664

Symptom: Prefixes and TCs stay "INPOLICY" although some configured resolvers are above the threshold.

Conditions: This symptom occurs when a policy uses non-default resolvers.

Workaround: Reload the MC.

More Info: Non-default resolvers are not checked (only unreachable is checked).

Output of "debug pfr master prefix detail" should normally show a similar line for each of the configured resolvers

```
OER MC PFX 10.2.1.0/24: Check ACT ABS unreachable: unreachable 0, policy 400000,
notify FALSE
```

When the problem is seen, only this line is observed for the unreachable.

- CSCuh39624

Symptom: PMIPv6 crashes when "no ipv6 mobile pmipv6-lma lma1" is configured.

Conditions: This symptom occurs when "no ipv6 mobile pmipv6-lma lma1" is configured.

Workaround: There is no workaround.

- CSCuh40275

Symptom: SNMP occupies more than 90% of the CPU.

Conditions: This symptom is observed when polling the cefFESelectionTable MIB.

Workaround: Execute the following commands:

```
snmp-server view cutover iso included
snmp-server view cutover cefFESelectionEntry excluded
snmp-server community public view cutover ro
snmp-server community private view cutover rw
```

- CSCuh40329

Symptom: OSPFV3 runs as PE-CE, but used to learn IPv4 prefixes. Core facing interface is GRE tunnel where OSPF and LDP runs. OSPFV3 based Shamlinks are created between PEs. When tunnel flaps, OSPF and LDP recovers, but in a few seconds tunnel locks up. In locked up condition, all traffic fails on the tunnel, even directly connected pings. The only way to recover is to reconfigure the tunnel from scratch. It happens fairly consistently after every re-convergence, not every time though.

Conditions: This issue is seen only on ISR G2s that are configured as PEs. They are so far seen with 3925 running Cisco IOS Release 15.3(2)T and 2911 running Cisco IOS Release 15.2(4)M3.

Workaround: Use OSPF V2 based shamlinks.

- CSCuh40617

Symptom: Ping fails when “encap dot1q” is configured on an FE SPA inserted in bay 1 of flexwan.

Conditions: This symptom is observed when FE SPA is inserted in bay 1 of flexwan.

Workaround: Move the SPA to bay 0 of flexwan.

- CSCuh41290

Symptom: After the unavailability of the LDAP CRL, no new CRL fetches can be done because LDAP waits for a reply infinitely and never times out.

Conditions: This symptom was first seen on Cisco IOS Release 15.1(4)M6 but not exclusive to it.

Workaround: Set “revocation-check none” under affected trustpoint. Reload router.

- CSCuh43027

Symptom: Prefixes withdrawn from BGP are not removed from the RIB although they are removed from the BGP table.

Conditions: A withdraw message contains more than one NLRI, one of which is for a route that is not chosen as best. If deterministic med is enabled, then the other NLRI in the withdraw message might not eventually be removed from the RIB.

Workaround: Forcibly clear the RIB.

Further Problem Description: This issue may also occur if BGP PIC is enabled and the withdraw message contains a route that is currently serving as a backup path.

- CSCuh43252

Symptom: After upgrading to Cisco IOS Release 15.0(2)SE3, you can no longer authenticate using TACACS. The TPLUS process on the switch will be pushing the CPU up to 99%.

Conditions: The symptom is observed when you use TACACS for authentication.

Workaround: Downgrade the switch to a version prior to 15.0(2)SE3.

- CSCuh43255

Symptom: The BGP task update-generation process may cause the router to reload, in a rare timing condition when there is prefix flap and there is high scale of prefixes going through update-generation, including the flapping prefix.

Conditions: The symptom is observed when the Cisco ASR router is acting as a route server for BGP along with having various route-server contexts. The router does not do any forwarding. It merely processes control plane traffic.

Workaround: There is no workaround.

More Info: The setup is the same as mentioned in this doc:

[http://www.cisco.com/en/US/docs/ios/ios\\_xe/iproute\\_bgp/configuration/guide/irg\\_route\\_server\\_xe.html](http://www.cisco.com/en/US/docs/ios/ios_xe/iproute_bgp/configuration/guide/irg_route_server_xe.html).

- CSCuh44420

Symptom: When a Cisco IOS router with one or more mpls ldp neighbors undergoes an mpls ldp router-id configuration change and non-stop routing had been previously enabled and disabled prior to the router-id configuration change, sessions fail to become NSR-ready once mpls ldp nsr is reconfigured.

Conditions: This symptom occurs when the mpls ldp router-id is reconfigured after mpls ldp nsr has been enabled and then disabled. After the router-id change, mpls ldp nsr must be reconfigured in order to encounter this issue.

Workaround: Reload the standby RP.

- CSCuh44476

Symptom: After an SSO, some VCs are not displayed for certain neighbors.

Conditions: This symptom occurs after an SSO on a box which has VFIs with autodiscovery BGP and BGP signalling with more than two remote PEs.

Workaround: There is no workaround.

- CSCuh46849

Symptom: A Cisco ASR 1000 router may display the following log with a traceback:

```
SCHED-3-UNEXPECTEDEVENT Process received unknown event (maj 80, min 0).
```

Conditions: The conditions are unknown.

Workaround: Reload the router.

- CSCuh47183

Symptom: This message will be seen followed by a “%Software forced reload”:

```
%SYS-6-STACKLOW: Stack for process EEM Callback Thread running low, 0/9000
```

Conditions: EEM (Embedded Event Manager) configuration necessary.

Workaround: Avoid using EEM applet.

- CSCuh48666

Symptom: Router crashes and reloads with dynamic EID scaling.

Conditions: The symptom is observed with dynamic EID scaling.

Workaround: There is no workaround.

- CSCuh48840

Symptom: A Cisco router crashes.

Conditions: This symptom is observed under the following conditions:

- a. The sup-bootdisk is formatted and copied with a big size file (example: copy a Cisco 7600 image file of an approximate size of 180M).



- b. Reload the box and during bootup try to write the file onto the sup-bootdisk (SEA write sea\_log.dat 32M bytes).
- c. The issue is reproduced.
- d. When the issue seen, check the sea\_log.dat always with 0 byte
- e. No matter where (disk0 or bootdisk) to load image.
- f. No matter sea log disk to sup-bootdisk or disk0:. I reproduced the issue with “logg sys disk disk0:” configuration.

SEA is calling IFS API to create sea\_log.dat, looks like IFS creating file hungs SP.

```
sea_log.c : sea_log_init_file() -> ifs_open() -> sea_zero_log() -> ifs_lseek() ->
ifs_write()
```

Workaround: There is no workaround.

- CSCuh51367

Symptom: An alignment traceback is seen in the L4F code.

Conditions: This symptom occurs when traffic from HTTP/HTTPS goes through Scansafe+14f.

Workaround: There is no workaround.

- CSCuh51897

Symptom: LC crashes with following error messages:

```
Jun 11 03:55:05.641: %SYS-DFC2-2-NOBLOCK: printf with blocking disabled. -Process=
''NDE - IPV6'', ip1= 7, pid= 165 Jun 11 03:55:44.165: %CPU_MONITOR-SP-6-NOT_HEARD:
CPU_MONITOR messages have not been heard for 31 seconds [2/0] Jun 11 03:56:44.761:
%CPU_MONITOR-SP-6-NOT_HEARD: CPU_MONITOR messages have not been heard for 91 seconds
[2/0] Jun 11 03:57:02.441: %XDR-6-XDRIPCNOTIFY: Message not sent to slot 2/0 (2)
because of IPC error timeout. Disabling linecard. (Expected during linecard OIR) Jun
11 03:57:14.761: %CPU_MONITOR-SP-6-NOT_HEARD: CPU_MONITOR messages have not been heard
for 121 seconds [2/0] Jun 11 03:58:14.762: %CPU_MONITOR-SP-3-TIMED_OUT: CPU_MONITOR
messages have failed, resetting module [2/0] Jun 11 03:58:14.826:
%C7600_PWR-SP-4-DISABLED: power to module in slot 2 set off (Heartbeat Messages Not
Received From Module)
```

Conditions: This symptom occurs when IPv6 NetFlow is enabled on the device.

Workaround: Disable IPv6 NetFlow.

- CSCuh53544

Symptom: OSPF ABR router does not flush type-4 ASBR summary LSA after NSR switchover if the connection to ASBR is lost during NSR switchover.

Conditions: This symptom is occurs when the VSS system acts as ABR and loses connection to an ASBR during NSR switchover. This configuration is not recommended and Layer 3 topology should not change during the switchover.

Workaround: Clear “ip ospf proc”.

- CSCuh56327

Symptom: IP SLA responder crash occurs on Cisco ASR 1002 router in Cisco IOS Release 15.2(4)S, Cisco IOS Release 15.2(4)S1, and Cisco IOS Release 15.2(4)S2.

Conditions: This symptom occurs when ip sla udp jitter with precision microseconds, udp jitter with milliseconds and udp echo are configured on the sender device with the same destination port on Cisco ASR 1002 router.

Workaround: Use different destination ports for udp-echo and udp jitter with millisecond precision than udp jitter with microsecond and optimize timestamp.

- CSCuh56385

Symptom: Very slow propagation of data across a network of SAF forwarders after a fail over condition is observed. More than two SAF forwarders are required to observe this defect.

Conditions: This symptom occurs when there are more than two SAF forwarders in the network. After a fail over condition and the clients initiate advertising patterns into the standby forwarder, the propagation of these advertisements via update messages to the SAF peers can experience a 5 second inter-service advertisement delay.

Workaround: There is no workaround. Once the forwarder that suffered the fail over condition returns and establishes its neighbor relationships with its peers, the forwarders will update quickly.

- CSCuh57839

Symptom: Clock quality level stuck and QL-DNU and not synchronized with the quality level of the clock source.

Conditions: This occurs when a synchronization interface that was previously down comes back up.

Workaround: There is no workaround.

- CSCuh59070

Symptom: Tunnel or Vtemplate interface type becomes P2P or Traffic Engineering type, so the class is different, so some of the operation can not be perform because of the wrong type.

Conditions: This symptom is observed when Restful API uses Onep python SDK.

Workaround: There is no workaround.

- CSCuh62266

Symptom: During normal operation, the Cisco ASR 1000 router may crash after repeated SNMP related watchdog errors.

```
Jun 15 2013 10:43:30.325: %SCHED-0-WATCHDOG: Scheduler running for a long time, more
than the maximum configured (120) secs. -Traceback= 1#6d024ee43b83b4f5539a076aa2e8d467
:10000000+56A5348 :10000000+20F7D54 :10000000+2513910 :10000000+20F807C
:10000000+20EBE84 :10000000+2119BA8 :10000000+20EBE84 :10000000+2106C24
:10000000+20EBE84 :10000000+213C9E8 :10000000+213CC34 :10000000+225B748
:10000000+222941C :10000000+2214314 :10000000+224812C -Traceback=
1#6d024ee43b83b4f5539a076aa2e8d467 :10000000+21416F0 :10000000+2513910
:10000000+20F807C :10000000+20EBE84 :10000000+2119BA8 :10000000+20EBE84
:10000000+2106C24 :10000000+20EBE84 :10000000+213C9E8 :10000000+213CC34
:10000000+225B748 :10000000+222941C :10000000+2214314 :10000000+224812C
```

Conditions: This symptom occurs while trying to obtain data from IP SLAs Path-Echo (rttMonStatsCollectTable) by SNMP polling operation.

Workaround: There is no workaround other than to disable SNMP configuration from the router.

More Info: This crash occurred in a customer environment and device with a particular version of the software (Cisco IOS Release 15.1(2)S2). No other similar issue has been identified so far.

- CSCuh63997

Symptom: Router crashes when service-policy is installed on the interface.

Conditions: The symptom is observed with service-policies having random-detect aggregate configuration.

Workaround: Use non-aggregate random-detect for WRED configurations. If the platform supports only aggregate random-detect, then there cannot be a workaround other than not using the WRED configuration altogether.

- CSCuh68693

Symptom: RP crashes [active RP, in the case of a dual RP setup] when the **show otv isis database standard detail** command is used to check details related to MAC addresses.

Conditions: This symptom occurs in valid OTV configurations (OTV state is UP and AED State is Yes).

Workaround: There is no workaround.

- CSCuh70868

Symptom: VPN prefixes are not advertised to more than one eBGP ASBRs even though the filters are received from them.

Conditions: This symptom occurs when an RT filter is configured between the eBGP ASBRs and the filter allows the VPN prefixes to be sent only to the neighbor from where the best path is received. All the other ASBRs do not receive the VPN prefixes even though maximum-path <> is configured.

Workaround: There is no workaround.

More Info: Remove route-target filtering between the eBGP ASBRs.

- CSCuh72031

Symptom: System might crash while trying to enter into exec mode through VTU.

Conditions: IPv4 TACACS server configured for login authentication with send-nat-address option.

Workaround: Remove send-nat-address option.

- CSCuh74735

Symptom: Intra mag roaming via DHCP request.

Conditions: This symptom is observed under no specific conditions.

Workaround: There is no workaround.

- CSCuh74822

Symptom: Config or unconfig causes MAG configuration to fail with MCSA.

Conditions: The conditions for this symptom are unknown.

Workaround: Perform a reload.

- CSCuh75315

Symptom: RP crash occurs while removing NAT configurations.

Conditions: This symptom occurs while removing 4k NAT session configurations from UUT.

Workaround: There is no workaround.

- CSCuh76617

Symptom: With MVPN BGP C-route signalling, some multicast states in the VRF might remain even when C-route state is withdrawn from BGP.

Conditions: This symptom occurs when all the BGP sessions on the PE go down (for example, manual clearing of BGP by using the **clear ip bgp** command).

Workaround: There is no workaround.

- CSCuh78003
 

Symptom: Complete loss of network traffic.

Conditions: This symptom occurs when all xconnects are cleared on a device where pseudowire redundancy is configured and no other network event occurred before this trigger.

Workaround: Remove and reconfigure the xconnects.
- CSCuh78173
 

Symptom: The EVC value shows as I state after a change from MPLS IP to PC MPLS IP.

Conditions: This symptom occurs when mpls ip is changed from interface to PC.

Workaround: Remove EVC configuration.
- CSCuh80492
 

Symptom: The system crashes and it causes a reload. Messages that can be seen on the console indicate there is a “NULL pointer dereference”. For example:

```
BUG: unable to handle kernel NULL pointer dereference
```

This is followed by a stack trace.

Conditions: This symptom occurs due to lack of proper locking semantics on the variables controlling the IPC namespace. This crash is unlikely to occur in normal situations. The user will need to have shell access and then access a task file under /proc (for example: /proc/29208/ns/ipc) which gives stats on the IPC namespace.

Workaround: There is no workaround.
- CSCuh86464
 

Symptom: SSS message chunk memory leak.

Conditions: This symptom occurs when the **clear subscriber session all** command is used while scale sessions are being initiated.

Workaround: There is no workaround.
- CSCuh89168
 

Symptom: The standby resets in a continuous loop.

Conditions: This symptom occurs on insertion of a new standby RSP with a different license than the one on the active RSP.

Workaround: There is no workaround.
- CSCuh90094
 

Symptom: %MEDIATRACE-3-R\_SNMP\_COMM\_STR\_MISSING message is displayed, which suggests that the **snmp-server community public ro** command should be executed. But this command has already been executed on the configuration.

Conditions: This symptom occurs when there is some access-limit mechanism in place on the SNMP configuration, such as the **snmp mib community-map** command.

Workaround: Ensure that the first community to appear in the configuration has no access-limit mechanism, or it has one that allows the router to query itself using SNMP.
- CSCuh91225
 

Symptom: A router crashes at pki\_import\_trustpool\_bundle.

Conditions: The call-home reporting command will enable smart callhome using HTTPS and send an inventory message to register for smart callhome. If the certificate which is required by HTTPS does not exist in the device, it will try to download it which causes the crash.

Workaround: There is no workaround.

- CSCUh91645

Symptom: WS-SUP720-3B crashes while receiving DHCP packets.

Conditions: This symptom occurs with the **ip dhcp relay information policy-action encapsulate** command.

Workaround 1. Use the **ip dhcp relay information policy-action replace** command.

Workaround 2. Use the **no ip dhcp relay information trusted** command.

- CSCUh92051

Symptom: Per user v4ACL HA replication broken in mcpdev.

Conditions: This symptom occurs when IPv4 and IPv6 profiles for single users are applied and the v4 profile per user data is not synchronized to the standby.

Workaround: There is no workaround.

- CSCUh94035

Symptom: A watchdog timeout crash occurs.

Conditions: This symptom occurs when DMVPN and IPv4/IPv6 EIGRP are configured. A crash occurs while DUAL is updating the EIGRP topology table.

Workaround: There is no workaround.

- CSCUh94799

Symptom: When a Port-channel interface with a carrier delay of 0 milliseconds and one or more service instances configured is removed, an unexpected process termination occurs.

Conditions: The issue will be seen only when there is both carrier delay of ms 0 configuration and service instance configuration under a Port channel interface, and that Port-channel interface is removed.

Workaround: There are several work arounds:

1. Remove the service instance(s) from the Port-channel interface before deleting the interface.
2. Remove the carrier delay from the Port-channel before deleting the interface.
3. Configure a non-zero carrier delay instead of a 0 carrier delay.
4. Don't use carrier-delay on port-channel interfaces in conjunction with service instances. Instead use carrier-delay on port-channel member interfaces. The use of "lacp fast-switchover" on the port-channel interface can also help to avoid the need for carrier-delay in cases where redundant LACP member links are in use.

- CSCUh94879

Symptom: Cisco IOS crashes after configuring the MHBFD template and map.

Conditions: This symptom occurs when the following are configured:

1. bfd-template multi-hop New-Temp
2. no authentication sha keychain mhop-key-abc
3. bfd map ipv4 4.4.4.4/32 1.1.1.1/32 New-Temp

Workaround: There is no workaround.

- CSCuh95503  
Symptom: Iosd crashes while removing match criteria from class map.  
Conditions: This symptom occurs when multiple filters are matched in the same statement and any one of them is deleted.  
Workaround: There is no workaround.
- CSCuh97129  
Symptom: Losing EIGRP Extended communities on BGP L3VPN route.  
Conditions: This symptom is observed when Remote PE-CE connection is brought down and only backup EIGRP path remains in the BGP table.  
Workaround: Clearing the problem route in the VRF will resolve the issue.
- CSCuh97838  
Symptom: Increased CPU Interrupt utilization due to process switching of packets.  
Conditions: This symptom occurs when CESoUDP is configured on the remote PE but is not configured on the local 901.  
Workaround: There are two workarounds:
  1. Configure the CESoUDP on the local 901 before configuring it on the remote PE.
 Or
  2. Remove the CESoUDP from the remote PE.
- CSCuh98997  
Symptom: L2VPN for Route reflector client in peer-policy or peer-group configuration does not work to reflect RFC 6074 update or RFC 4761 updates.  
Conditions: This symptom occurs in the following scenarios:
  1. Template peer-policy is configured with route-reflector-client, or peer-group is configured with route-reflector-client.
  2. Together with prefix-length-size 2 are configured for one or more neighbors.
  3. With no neighbor in bgp l2vpn vpls address-family configuring route-reflector-client explicitly.
 Workaround: Configure a neighbor in bgp l2vpn vpls address-family to have route-reflector-client explicitly.
- CSCui03965  
Symptom: Standby RP keeps on booting after an ISSU upgrade of the standby RP.  
Conditions: The symptom is observed after an ISSU upgrade of the standby RP.  
Workaround: There is no workaround.
- CSCui04262  
Symptom: An error syslog is seen on ASR1K BRAS running XE352.P3 Standby-RP, showing QOS service-policy installation failures:
 

```

1. Jun 13 14:43:55.323 CEST: %QOS-6-POLICY_INST_FAILED: Service policy installation failed
2. Jun 13 14:47:10.725 CEST: %QOS-3-INDEX_DELETE: class-group unable to remove index 00B6AA60
3. Jun 13 14:47:10.726 CEST: %QOS-3-UNASSIGNED: A CLASS_REMOVE event resulted in an (un)assigned index for class-group
target-input-parent$class-default$IPBSA>ci=3#qu=3#qd=4#co=4#pu=policy#ru=200K#pd=polic
e#rd=300K<_IN$class-default 4. Jun 13 14:47:10.727 CEST: %QOS-6-RELOAD: Index removal

```

```
failed, reloading self Symptom: An error syslog is seen on ASR1K BRAS running XE352.P3
Standby-RP, showing QOS service-policy installation failures: 1. Jun 13 14:43:55.323
CEST: %QOS-6-POLICY_INST_FAILED: Service policy installation failed 2. Jun 13
14:47:10.725 CEST: %QOS-3-INDEX_DELETE: class-group unable to remove index 00B6AA60 3.
Jun 13 14:47:10.726 CEST: %QOS-3-UNASSIGNED: A CLASS_REMOVE event resulted in an
(un)assigned index for class-group
target-input-parent$class-default$IPBSA>ci=3#qu=3#qd=4#co=4#pu=policy#ru=200K#pd=polic
e#rd=300K<_IN$class-default 4. Jun 13 14:47:10.727 CEST: %QOS-6-RELOAD: Index removal
failed, reloading self
```

Conditions: This symptom is observed when on Cisco ASR1000 BRAS, running Cisco IOS Release XE352.P3, Version 15.2(1)S2, CUST-SPECIAL:V152\_1\_S2\_CSCUA32331\_4. When churning PPPoE sessions with 2 unique ISG/Shell map services per session, and after a manual RP Failover is done, after a while the error will be seen.

Workaround: There is no workaround.

- CSCui04530

Symptom: Upon FPD upgrade, you get this error on Cisco IOS c7600 switch:

```
! %FPD_MGMT-3-BUNDLE_EXTRACT_ERROR: Cannot extract the ssc-600-fpd.bndl bundle from
sup-bootdisk:c7600-fpd-pkg.151kg - The required bundle is not in the package file.
Please make sure that you have the right FPD image package file. % Cannot get the
required data from the indicated file, please verify that you have a valid file and
entered a valid URL. !
```

Conditions: This symptom is observed under the following conditions:

```
IOS: c7600s72033-advipservicesk9-mz.122-33.SRB3
CARDS: WS-SSC-600 WS-IPSEC-3
CLI: upgrade hw-module slot x fpd file sup-bootdisk:c7600-fpd-pkg.151-3.S2.pkg
```

Workaround: Upgrade to FPD image that includes corresponding \*.bndl image.

- CSCui06930

Symptom: Some VLAN VCs which are associated with Service Instance configuration via a bridge domain may not be brought up under some timing conditions.

Conditions: Upon startup with saved configuration where a VC is associated with an EFP via bridge domain configuration, it is possible that the VC may not be brought up even where the EFP (service Instance) is itself up.

Workaround: Perform a shut/no shut of the VLAN interface.

- CSCui07997

Symptom: Route over OSPFv2 sham-link shows two next hop.

Conditions: This symptom is observed when the route entry is ECMP route between the sham-link and another path.

Workaround: Break ECMP by adjusting the OSPF cost.

- CSCui09196

Symptom: During smoke testing using the latest mcp\_dev image on a Cisco IOS 7600 series router running Cisco IOS Release 15.4(00.01)S, the router crashes during configuration.

Conditions: This symptom occurs when a crash occurs in RSP.

Workaround: There is no workaround.

- CSCui14692  
Symptom: Crash on C819G running 152-4.M1 due to memory corruption at `vm_xif_malloc_bounded_stub`.  
Conditions: This condition is seen due to recursive function call of fib code, NHRP, IP SLA etc. However, these might not be the only trigger.  
Workaround: There is no workaround.
- CSCui21030  
Symptom: A vulnerability in OSPF implementation of Cisco IOS and Cisco IOS XE could allow an unauthenticated, adjacent attacker to cause a reload of the affected device.  
The vulnerability is due to improper parsing of certain options in OSPF LSA type 11 packets. An attacker could exploit this vulnerability by sending LSA type 11 OSPF packet with unusual options set. An exploit could allow the attacker to cause a reload of the affected device.  
Conditions: This symptom occurs while receiving a bad RI opaque LSA with some unusual options.  
Workaround: There is no workaround.  
PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5.7/4.7:  
<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:A/AC:M/Au:N/C:N/I:N/A:C/E:F/RL:OF/RC:C>  
CVE ID CVE-2013-5527 has been assigned to document this issue.  
Additional details about the vulnerability described here can be found at:  
<http://tools.cisco.com/security/center/content/CiscoSecurityNotice/CVE-2013-5527>  
Additional information on Cisco's security vulnerability policy can be found at the following URL:  
[http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)
- CSCui21061  
Symptom: Multicast stops working when CDP is disabled on a physical interface that is part of a port-channel.  
Conditions: This issue is seen when "no cdp enable" is issued on the physical interface. It is not seen if CDP is disabled globally, or if there is no port-channel configured.  
Workaround: Disable CDP globally or use a configuration that does not involve a port-channel.
- CSCui24744  
Symptom: An iosd crash is seen.  
Conditions: This symptom occurs on removing **bfd-template single-hop sw-no-echo-sha1** configuration.  
Workaround: There is no workaround.
- CSCui25696  
Symptom: A Cisco ASR 1002-X router experiences a watchdog reset due to a kernel core dump triggered by a possible divide-by-zero condition.  
Conditions: This symptom can occur under any condition.  
Workaround: There is no workaround.
- CSCui26581  
Symptom: A small memory leak is seen when accessing certain parts of PTP MIB.  
Conditions: This symptom occurs when the following OIDs in the PTP MIB are accessed:



```

cPtpClockRunningPacketsSent: 1.3.6.1.4.1.9.9.760.1.2.4.1.5
cPtpClockRunningPacketsReceived: 1.3.6.1.4.1.9.9.760.1.2.4.1.6
cPtpClockPortRunningPacketsReceived: 1.3.6.1.4.1.9.9.760.1.2.9.1.13
cPtpClockPortRunningPacketsSent: 1.3.6.1.4.1.9.9.760.1.2.9.1.14
cPtpClockPortAssociatePacketsSent: 1.3.6.1.4.1.9.9.760.1.2.11.1.8
cPtpClockPortAssociatePacketsReceived: 1.3.6.1.4.1.9.9.760.1.2.11.1.9
cPtpClockPortAssociateInErrors: 1.3.6.1.4.1.9.9.760.1.2.11.1.10,
cPtpClockPortAssociateOutErrors: 1.3.6.1.4.1.9.9.760.1.2.11.1.11

```

Workaround: Exclude the above OIDs

- CSCui28312

Symptom: A Cisco IOS router crashes.

Conditions: This symptom occurs in rare cases on images supporting HA with IPv6 BSR configured, when C-RPs are configured, and then unconfigured shortly after.

Workaround: There is no workaround.

- CSCui29499

Symptom: ISIS goes into INIT state.

Conditions: BFD flap leads to ISIS adjacency not coming up if the following conditions are true:

1. In P2P mode only
2. When local node supports RFC6213 and its remote neighbor does not support RFC6213
3. The P2P link is down and adjacency is deleted on the remote neighbor and up again before the adjacency hold down timer expires on the local node that has the RFC6213 support

Workaround: Any of the following work arounds will work.

- Remove BFD on 903, wait for ISIS to come up and configure BFD again
- Shut and no shut the interface on the local node with RFC6213
- Not to use P2P link at all

More Info: Deviation not experienced when EIGRP or OSPF routing protocols were running over the same link as ISIS in testing.

- CSCui30036

Symptom: Cisco ASR 1001 IDC maverick SPA(ASR1001-IDC-8XT1E1) will not bootup.

Conditions: This issue is observed with latest Cisco IOS Release XE3.10 and mcp\_dev image.

Workaround: There is no workaround. Use image prior to Cisco IOS Release XE3.10.

- CSCui32105

Symptom: In rare occasions the standby RP on a dual RP system may crash after performing a switchover.

Conditions: This symptom occurs when an invalid message is sent from the RP to the RRP.

Workaround: There is no workaround.

- CSCui33454

Symptom: Unidirectional traffic flow is observed for PFC based EoMPLS PW due to lost FIB entries in hardware. Receive counter under VC statistics does not increment on one side of PW.

Counter for VC statistics in “receive” direction does not increment, only send counter increases.

Conditions: This symptom is observed under the following conditions:

- EoMPLS PW provisioned on PFC/DFC based linecard

- The issue is triggered with FIB changes toward the xconnect neighbor peer
- Workaround 1. “Soft” workaround - Remove and configure back the affected xconnect.  
or “hard” WA in case soft does not help
- Workaround 2. “Hard” workaround - Linecard reload in case of DFC based AC linecard - Supervisor reload in case of non-DFC based AC linecard.
- CSCui39527
  - Symptom: Standby RP crashes during VRF transfer.
  - Conditions: This symptom occurs on a standby RP with EoGRE tunnel+HA configuration.
  - Workaround: There is no workaround.
- CSCui43534
  - Symptom: 5760 Wireless LAN crashes during CWA client association when ISE is unreachable.
  - Conditions: This symptom is observed when ISE becomes unreachable. Client associates to WLAN with CWA support.
  - Workaround:
    1. Configure backup radius.
    2. Remove the MAC filter.
- CSCui44972
  - Symptom: A small memory leak is observed while accessing certain parts of the PTP MIB .
  - Conditions: This symptom occurs while accessing cPtpClockPortDSName when a boundary clock is configured and there is no license for the boundary clock.
  - Workaround: Avoid accessing cPtpClockPortDSName (OID: 1.3.6.1.4.1.9.9.760.1.2.8.1.5).
- CSCui46390
  - Symptom: Multiple paths with different VBS or LB for an RFC 4761 prefix is not considered as the same prefix. This causes an interop issue with Cisco IOS XR software and BGP routers of other vendors.
  - Conditions: This symptom occurs when:
    1. The **neighbor suppress-signaling-protocol ldp** option is enabled.
    2. Multiple paths exist with different VBS/LB but same RD/VEID/VBO.
  - Workaround: There is no workaround.
- CSCui46593
  - Symptom: CPU hog crash due to Mwheel Process.
  - Conditions: This symptom is observed in a normal operation.
  - Workaround: There is no workaround.
- CSCui47248
  - Symptom: A traceback is observed.
  - Conditions: This symptom occurs when **config replace <clean file>** is done and the replaced configuration file has disabled IP routing but has IPv4 static routes configured.
  - Workaround: There is no workaround.

- CSCui47602  
Symptom: Traces at IDMGR-3-INVALID\_ID when queried for mplsTunnelTable MIB.  
Conditions: This symptom occurs when there is a GETONE SNMP query for non-existing mplsTunnelTable entries.  
Workaround: Avoid using GETONE SNMP query for non-existing objects. Use GETNEXT queries instead of GETONE whenever possible.
- CSCui47732  
Symptom: When Router 1 and Router 2 have full OSPF adjacency, and interface loopback 0 on Router 2 is not an OSPF interface, Router 1 cannot reach Router 2's loopback 0. MPLS LDP is configured using both Router 1 and Router 2 loopback 0 as router-id, so LDP neighbor cannot be formed between them. When **mpls ldp sync** is configured under **router ospf**, Router 2 is generating max-metric router LSAs to Router 1, which is expected. However, when **no mpls ldp sync** is configured, OSPF doesn't rebuild router LSA and still sends router LSA with metric 65535.  
Conditions: This symptom occurs when **mpls ldp sync** cannot be configured due to LDP being in down state.  
Workaround: Use the **flap interface** or **clear ospf process** command, followed by a router LSA refresh.
- CSCui49185  
Symptom: On a Cisco IOS ASR 1002x series router running Cisco IOS Release 15.4(01)S, a crash occurs.  
Conditions: This symptom occurs when MLDP over GRE is configured, with paths being added and removed. The counter of the number of paths in a CEF path list is not updated correctly. When they wrap at 256 this may cause a crash. The problem occurs when a path is removed without decrementing the counter properly. The problem is observed when a path is added/removed from a path list 256 times.  
Workaround: Do not modify paths using the method described.
- CSCui53213  
Symptom: Traffic forwards through the VC even when the EVC is in a shut state.  
Conditions: This symptom occurs in scalable EoMPLS.  
Workaround: There is no workaround.
- CSCui53428  
Symptom: Forwarding state is not preserved on the Cisco ASR 9000 series router after an SSO in the Cisco ASR 903 router.  
Conditions: This symptom occurs when an SSO is performed on the Cisco ASR 903 router.  
Workaround: There is no workaround.
- CSCui61928  
Symptom: The chunk mgr process consumes a lot of memory and does not free it up. This may lead to insufficient processor memory.  
Conditions: This symptom occurs when a static BFD session constantly flaps. Dynamic BFD sessions are not affected.  
Workaround: This situation can be avoided by:
  1. Preventing a constantly flapping static BFD session.
  2. Removing the BFD configuration.

3. Configuring BFD dampening (in the BFD template mode).
- CSCui62441

Symptom: Complete traffic drop for few seconds is seen after few minutes of performing SSO switchover.

Conditions: This symptom occurs only after a few minutes of performing an SSO switchover.

Workaround: There is no workaround.
  - CSCui67308

Symptom: Cisco IOS Router constantly crashes after enabling TE tunnel over BDI interface.

Conditions: This symptom is observed when TE tunnel is exits a BDI interface. This is not a supported design.

Workaround: Use physical interface for TE tunnels.
  - CSCui69873

Symptom: A crash occurs in ospfv3\_db\_scope\_str().

Conditions: This symptom is observed when you enable **debug ospfv3 lsdb**.

Workaround: There is no workaround.
  - CSCui74609

Symptom: After a RSP switchover the backup pseudowire state is down and never recovers to standby state.

Conditions: This symptom occurs on CEM circuits in a SAToP environment after a SSO switchover.

Workaround: There is no workaround.
  - CSCui76564

Symptom: A roaming mobile customer (example: iPASS, Boingo etc.) logs on via a Web-Portal-Page and the ISG doesn't send in the radius accounting-request packet from the V-Cookie to the Radius Server.

Conditions: This symptom occurs depending on the ISG setup. In this case L & V Cookie must be sent in accounting-request from the ISG to the AAA Server.

Workaround: There is no workaround.
  - CSCui82259

Symptom: Cisco IOS router reloads, giving a traceback.

Conditions: This symptom occurs when the failover is initiated from the primary link (GX) to the secondary link (BGAN) or from BGAN to GX for multiple VRFs at the same time, using an EEM script.

Workaround: There is no workaround.
  - CSCui82757

Symptom: Session query responses in lite sessions have inconsistent calling-station-ID behavior.

Conditions: This symptom occurs when:

    1. Walkby feature is enabled with L4R & PBHK features applied to lite session.
    2. Session query is sent to ISG.

Workaround: Do not use calling-station-ID.

- CSCui85019

Symptom: When the command **show xconnect** is entered, it may result in a memory leak. This can be observed by entering the command **show memory debug leaks chunks** and seeing entries like this:

```
router#show memory debug leaks chunks Adding blocks for GD...
I/O memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name
Processor memory
Address Size Alloc_pc PID Alloc-Proc Name AA3F8B4 2348 6D0B528 97 Exec
PW/UDP VC event trace
```

Conditions: This symptom is observed when one or more xconnects are configured with UDP encapsulation.

Workaround: There is no workaround.

- CSCui87915

Symptom: The VC is not going down after the access interface is down.

Conditions: This symptom occurs in scalable eompls under port-channel and the member link is shut down.

Workaround: The EFPs under the member link can be reconfigured once the member link is down.

- CSCui89069

Symptom: An ISIS flap is observed on performing SSO.

Conditions: This symptom occurs when **nsf ietf** is configured and one or more loopbacks are configured as passive interfaces.

Workaround 1. Use **nsf cisco**.

Workaround 2. Continue to use **nsf ietf** but configure **ip router isis <process\_name>** on the loopback interfaces.

- CSCui90811

Symptom: While running the Cisco IOS 15.3S release and Cisco IOS 15.4S release software for the L2VPN pseudowire redundancy feature on a Cisco router, the traffic is dropped when the primary pseudowire becomes active.

Conditions: Initially the primary pseudowire is down due to either a local or a remote core-facing interface being shutdown. The backup pseudowire is active and traffic flows through the backup pseudowire. Later, when the backup pseudowire is down, the primary pseudowire is brought up and becomes active and traffic is not able to flow through primary pseudowire and is dropped.

Workaround: There is no workaround.

- CSCui95398

Symptom: Configuration CLI to enable/disable “diag false alarm detection”.

Conditions: As of now this can be used to control the result of sprp\_inband ping failure.

Workaround: Nil

More Info: “platform diagnostic false-alarm-detection” is the CLI.

- CSCui99031
 

Symptom: In a pair of Cisco 7609-S routers running c7600rsp72043-advipservicesk9-mz.151-3.S5.bin IOS, phase 1 fails to establish due to a “signature invalid!” error when rsa-sig is used for phase 1 authentication.

Conditions: This symptom occurs under the following conditions:

  - rsa-sig is used for phase 1 authentication
  - site to site tunnel

Workaround: Use PSK instead of PKI.
- CSCuj00746
 

Symptom: On performing an upgrade from 9.512 to 9.523, there is a label allocation failure in VPWS circuits as they are trying to utilize the labels that are already used by the VPLS circuits that are present in the database.

Conditions: This symptom occurs when both VPWS and VPLS circuits are configured on the same node before upgrading.

Workaround: Removing the VPLS circuit brings up the VPWS circuits. Re-configuring the VPLS circuit is also successful with a different local label assigned.
- CSCuj04178
 

Symptom: A crash occurs at vpdn\_apply\_vpdn\_template\_pptp.

Conditions: The conditions for this symptom are unknown.

Workaround: There is no workaround.
- CSCuj06347
 

Symptom: Cisco IOS and Cisco NX-OS software contain a vulnerability that could allow an authenticated, local attacker to poison the LISP map cache on the router configured as an Ingress Tunnel Router (ITR).

Conditions: This symptom occurs when an attacker has a privilege 0 local access to the ITR and executes **lig** commands.

Workaround:

  1. Configure **privilege exec level 1 lig<nCmdBold>, to prevent privilege level 0 users from executing the lig** command.
  2. Use separate VRFs for the EID and RLOC spaces, assuming the attacker does not have access to the RLOC case.
  3. Using GETVPN or other crypto in the RLOC space may mitigate against this, but not in the common deployment scenario, where crypto maps are applied to the LISP0 interface.

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 1.5/1.4:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:L/AC:M/Au:S/C:N/I:P/A:N/E:F/RL:W/RC:C>

No CVE ID has been assigned to this issue.

Additional information on Cisco's security vulnerability policy can be found at the following URL: [http://www.cisco.com/en/US/products/products\\_security\\_vulnerability\\_policy.html](http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html)

- CSCuj16742

Symptom: In a pseudowire redundancy configuration, packets may fail to flow even though the xconnect virtual circuit appears to be up.

Conditions: This symptom has been observed when the xconnect is re-provisioned while the primary pseudowire is down and the backup pseudowire is up. The issue has only been observed on Circuit Emulation (CEM) attachment circuits, but it is possible other attachment circuit types may be affected as well.

Workaround: Completely unconfigure the xconnect and then reconfigure it.
- CSCuj17482

Symptom: On a device running low on memory, an EFP is attempted to be deleted, but fails due to lack of memory. The second attempt at removing that same EFP causes the router to restart.

Conditions: This symptom occurs when the a lot of configuration has been applied to the device, causing high memory usage.

Workaround: Do not over-configure the device.
- CSCuj22189

Symptom: On a Cisco ASR series router, a crash occurs when **mpls ip** is added under the interface.

Conditions: This symptom occurs when the hidden command **snmp-server hc poll** is already configured.

Workaround: Ensure that the hidden command **snmp-server hc poll** has not been configured.
- CSCuj23896

Symptom: The Cisco Catalyst 4500-X Series Switches crash while running wireshark.

Conditions: This symptom occurs when the following conditions are met:

  1. Capture is started with ipv4/ipv6/mac filter (using match keyword).
  2. Capture is stopped and modified to use different filter.
  3. Capture is started again.

Workaround: Avoid using **monitor capture <name> match <ipv4/ipv6/mac>**. Use an ACL/class-map which is created from the configuration mode.
- CSCuj30702

Symptom: This bug is specific to port channel sub interface configuration in ES+ card. This bug is not relevant to any other port channel configuration in ES+, that is, EVC/Bridge-Domain over PoCH sub-int etc, and other card types, such as ES20/ LAN cards are free from this bug. Any type of IP communication on port channel sub interfaces in ES+ cards fail. Such an issue is seen only with port channel sub interfaces on ES+ and not seen with port channel main interfaces.

Conditions: This symptom will only be seen with images where the fix of CSCuh40617 is integrated.

Workaround: The connections will work fine if it is moved to the main interface or by using EVC BD configurations.
- CSCuj31090

Symptom: When L2TPv3-based pseudowire is configured between two PE routers and different VLAN ids are used on the ACs on both sides, ES+ on egress PE does not rewrite a dot1q VLAN tag when sending a frame toward CE.

Conditions: This symptom occurs when: 1. Both ACs are Ethernet VLAN type. 2. Different dot1q tag is used on both ACs.

Workaround: Configure the same dot1q tag for the ACs on both PEs.

- CSCuj31151

Symptom: If an impedance option is specified for an external clock in the **network-clock input-source** configuration, other configuration (such as hold-off or wait-to-restore) may fail to be applied.

Conditions: This symptom is seen when using external clock inputs with an impedance option specified.

Workaround: It may be possible to achieve the desired behaviour using global configuration (for example global hold-off or wait-to-restore configuration), if not, there is no workaround.

- CSCuj44262

Symptom: The 10GigE port is not up even though the XFP transmits laser.

Conditions: This symptom occurs under the following conditions:

- Using SPA-1X10GE-L-V2 and XFP-10G-MM-SR.
- Leaving the interface in shutdown state for a long time (over 6hrs).

Workaround: Reload the SPA.

- CSCuj47238

Symptom: There is a difference in the Y1731 probe within **show ip sla statistics**.

Conditions: This symptom is seen in the Cisco 7600 series routers.

```
service instance 400 ethernet evc1000 description -- EVC Cliente BUSINESS---
encapsulation dot1q 400 second-dot1q 100 <==HERE rewrite ingress tag pop 2 symmetric
<==HERE xconnect 172.16.12.6 1000 encapsulation mpls cfm mep domain OPM mpid 2
mdr-rm01#sh ip sla statistics 1 IPSLAs Latest Operation Statistics
IPSLA operation id: 1 Delay Statistics for Y1731 Operation 1 Type of operation: Y1731
Delay Measurement Latest operation start time: 12:06:21.041 CET Wed Sep 11 2013 Latest
operation return code: OK Distribution Statistics:
Interval Start time: 12:06:21.041 CET Wed Sep 11 2013 Elapsed time: 50 seconds Number
of measurements initiated: 44 <== HERE Number of measurements completed: 32 <== HERE
Flag: OK
```

Workaround: There is no workaround.

- CSCuj48676

Symptom: Following MIBs have wrong values reported:

```
cfmConditionsProfile cfmAlarmHistoryConditionsProfile cfmFlowMetricConditionsProfile
cfmFlowMonitorConditionsProfile
```

Conditions: This symptom is observed when Performance Monitor feature is configured with threshold-crossing-alarms.

Workaround: There is no workaround.

- CSCuj50401

Symptom: An ND cache entry is not created for an ISIS IPv6 neighbour when an ISIS adjacency is established.

Conditions: This symptom occurs when ISIS IPv6 is configured and has an established adjacency with the neighboring node.

Workaround: There is no workaround.



Further Problem Description: The impact is negligible because the fix is an optimization. As an optimization a new entry is created in the ND cache when a new ISIS adjacency is established. The defect means that an ND cache entry is not created when an adjacency is established, causing slight delays when data starts flowing. An entry will be created normally when data flows to the neighbor.

- CSCuj57367

Symptom: A 10 gig line card crashes on a Cisco 7600 platform with the following or similar errors:

```
%SYS-DFC3-3-MGDTIMER: Uninitialized timer, timer stop, timer = 30CCCFB0. -Process= "RO
Notify Timers", ipl= 0, pid= 7 -Traceback= 2060E1BCz 2060E8E4z %SYS-DFC3-3-MGDTIMER:
Uninitialized timer, timer stop, timer = 30CCD154. -Process= "RO Notify Timers", ipl=
0, pid= 7 -Traceback= 2060E1BCz 2060E8E4z %SYS-DFC3-3-MGDTIMER: Uninitialized timer,
timer stop, timer = 30CCCFB0. -Process= "RO Notify Timers", ipl= 0, pid= 7 -Traceback=
2060E1BCz 2060E8E4z
08:54:43 Central Tue Oct 1 2013: Address Error (load or instruction fetch) exception,
CPU signal 10, PC = 0x20642A08
```

Conditions: This symptom occurs when a large number of IPC messages are used.

Workaround: There is no workaround.

More Info: On mac-scaling, the L2-DRV application sends more ICC messages(though not always). But periodically( approximately 2-3 minutes), some burst of around 150 ICC messages are sent by the SP towards the RP. This means that mac-scaling has a direct correlation with the number of IPC messages being sent.

- CSCuj66352

Symptom: A system crash is observed in the SNMP engine.

Conditions: This symptom occurs under the following conditions:

- ?show subscriber session?
- polling the ISG-MIB -clearing the subscriber

Workaround: Do not use SNMP polling.

- CSCuj68932

Symptom: L2TPv3 tunnel with digest fails to establish. Cisco IOS device gives the following messages when "debug l2tp all" and "debug l2tp packet detail" are enabled:

```
L2TP ____:____: ERROR: SCCRQ AVP 59, vendor 0: unknown L2TP ____:____:
Unknown IETF AVP 59 in CM SCCRQ
```

Conditions: This issue is observed when IOS device peers with non-IOS device that sends IETF L2TPv3 digest AVP (IETF AVP 59) in L2TP control message. This issue is present in S images starting from Cisco IOS Release 12.2(33)XNC and in T train from Cisco IOS Release 15.3(2)T.

Workaround: There is no workaround.

- CSCuj72553

Symptom: The OSPF router may stay without a router LSA after NSF restarts which means that routing in the OSPF domain is seriously affected.

Conditions: This symptom occurs under the following conditions:

- OSPF NSF is terminated for some reason.
- **mpls traffic-eng nsr** is configured.

Workaround: Remove **mpls traffic-eng nsr**.

More Info: Example of **show ip ospf nsf** after a failed NSF:

```
Router#sh ip ospf 1 nsf
```

```

Routing Process "ospf 1"
  IETF Non-Stop Forwarding enabled
  restart-interval limit: 120 sec
  Last IETF NSF restart 03:33:06 ago terminated after 5 secs, reason: Event
  nbr 1-way
  IETF NSF helper support enabled
  Cisco NSF helper support enabled
  Restart resync LSA state: TE has requested data
  Restart resync Adj state: TE has requested data
  OSPF restart state is NO_RESTART
  Handle 140515696469576, Router ID 10.1.1.1, checkpoint Router ID 0.0.0.0
  Config wait timer interval 10, timer not running
  Dbase wait timer interval 120, timer not running

```

Router LSA generation is prevented by flag described on lines:

```

Restart resync LSA state: TE has requested data
Restart resync Adj state: TE has requested

```

Note: TE resync is not completed, although NSF is completed.

- CSCuj73822

Symptom: A router crashes while removing the Locator ID Separation Protocol configuration **router lisp <id>** or **site <site-name>** sub-modes.

Conditions: This symptom occurs when “allowed-locator list {ipv4 | ipv6} <prefix-list>” is present under the lisp site being deconfigured.

Workaround: Remove the “allowed-locator list {ipv4 | ipv6} <prefix-list>” configuration from all the map-server sites before removing the “site <site-name>” sub-mode configuration (or removing the “router lisp <id>” sub-mode).

- CSCuj88523

Symptom: In a pseudowire redundancy configuration, traffic may fail to flow after a switchover to a backup pseudowire.

Conditions: This symptom occurs on the Cisco 7600 series routers.

Workaround: Execute the following commands on the attachment circuit interface: **-shutdown -no shutdown**

- CSCuj96186

Symptom: When auto-tunnel and RSVP graceful restart are configured, the standby crashes after an SSO (NSR is not configured).

Conditions: This symptom occurs under the following conditions:

- Configure auto-tunnel
- Configure RSVP graceful restart without NSR
- Perform an SSO

Workaround: Disable RSVP graceful restart or remove the auto-tunnel configuration.

- CSCuj99537

Symptom: Not all LI streams that are properly configured via SNMPv3 and appropriate ACLs and are programmed in TCAM, are intercepted and forwarded towards MD.

Conditions: This symptom occurs in an SIP-400 based LI.

Workaround: Remove and reapply the problematic tap but it doesn't prevent the problem from reoccurring if new LI taps are applied via SNMPv3

- CSCul11995

Symptom: An L2TPv3 session fails to establish and Cisco IOS receives a StopCCN message from the peer with the following message in response to its ICRP message: "No handler for attr 68 (68)"

Conditions: This symptom occurs when IOS device peers with non-IOS devices send IETF L2TPv3 Pseudowire Type AVP (IETF AVP 68) in an ICRP message.

Workaround: There is no workaround.

## Open and Resolved Bugs - Cisco ASR 901 Series Routers in 15.4(1)S

For detailed information on Open and Resolved bugs on Cisco ASR 901 Series Routers in 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/wireless/asr\\_901/Release/Notes/asr901\\_rn\\_15\\_4\\_1\\_S.html](http://www.cisco.com/en/US/docs/wireless/asr_901/Release/Notes/asr901_rn_15_4_1_S.html)

## Open and Resolved Bugs - Cisco ASR 901 S Series Routers in 15.4(1)S

For detailed information on Open and Resolved bugs on Cisco ASR 901 S Series Routers in 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/wireless/asr\\_901s/rn/b\\_release\\_notes\\_for\\_asr901s.html](http://www.cisco.com/en/US/docs/wireless/asr_901s/rn/b_release_notes_for_asr901s.html)

## Open and Resolved Bugs - Cisco ME 3600x and ME 3800x Series Routers in 15.4(1)S

For detailed information on Open and Resolved bugs on Cisco ME 3600x and Cisco ME 3800x Series Routers in 15.4(1)S, see the following document:

[http://www.cisco.com/en/US/docs/switches/metro/me3600x\\_3800x/software/release/15.4\\_1\\_S/release/notes/ol31008.html](http://www.cisco.com/en/US/docs/switches/metro/me3600x_3800x/software/release/15.4_1_S/release/notes/ol31008.html)



## Related Documentation

The following sections describe the documentation available for Cisco IOS Release 15.4S. These documents include hardware and software installation guides, Cisco IOS configuration and command reference publications, system error messages, and feature modules.

Documentation is available online on Cisco.com.

Use these release notes with the resources described in the following sections:

- [Platform-Specific Documents, page 229](#)
- [Cisco Feature Navigator, page 229](#)
- [Cisco IOS Software Documentation Set, page 230](#)
- [Notices, page 230](#)
- [Obtaining Documentation and Submitting a Service Request, page 232](#)

## Platform-Specific Documents

Cisco 7600 Series Routers

[http://www.cisco.com/en/US/products/hw/routers/ps368/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/hw/routers/ps368/tsd_products_support_series_home.html)

Cisco ASR 901 Router

<http://www.cisco.com/en/US/products/ps12077/index.html>

Cisco ME 3600X Switch

<http://www.cisco.com/en/US/products/ps10956/index.html>

Cisco ME 3600X-24CX Switch

[http://www.cisco.com/en/US/prod/collateral/switches/ps6568/ps10956/data\\_sheet\\_c78-708663.html](http://www.cisco.com/en/US/prod/collateral/switches/ps6568/ps10956/data_sheet_c78-708663.html)

Cisco ME 3800X Switch

<http://www.cisco.com/en/US/products/ps10965/index.html>

## Cisco Feature Navigator

Cisco IOS software is packaged in feature sets that are supported on specific platforms. To get updated information regarding platform support for this feature, access Cisco Feature Navigator. Cisco Feature Navigator dynamically updates the list of supported platforms as new platform support is added for the feature.

Cisco Feature Navigator is a web-based tool that enables you to quickly determine which Cisco IOS and Catalyst OS software images support a specific set of features and which features are supported in a specific Cisco IOS image. You can search by feature or release. Under the release section, you can compare releases side by side to display both the features unique to each software release and the features in common.

Cisco Feature Navigator is updated regularly and when major Cisco IOS software releases and technology releases occur. For the most current information, go to the Cisco Feature Navigator home page at the following URL:

<http://www.cisco.com/go/cfn>

## Cisco IOS Software Documentation Set

The Cisco IOS Release 15.4S documentation set consists of configuration guides, command references, and other supporting documents and resources. For the most current documentation, go to the following URL:

[http://www.cisco.com/en/US/products/ps13594/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps13594/tsd_products_support_series_home.html)

## Notices

The following notices pertain to this software license.

### OpenSSL/Open SSL Project

This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org/>).

This product includes cryptographic software written by Eric Young (eay@cryptsoft.com).

This product includes software written by Tim Hudson (tjh@cryptsoft.com).

### License Issues

The OpenSSL toolkit stays under a dual license, i.e. both the conditions of the OpenSSL License and the original SSLeay license apply to the toolkit. See below for the actual license texts. Actually both licenses are BSD-style Open Source licenses. In case of any license issues related to OpenSSL please contact [openssl-core@openssl.org](mailto:openssl-core@openssl.org).

#### OpenSSL License:

Copyright © 1998-2007 The OpenSSL Project. All rights reserved.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

1. Redistributions of source code must retain the copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions, and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgment: “This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org/>)”.
4. The names “OpenSSL Toolkit” and “OpenSSL Project” must not be used to endorse or promote products derived from this software without prior written permission. For written permission, please contact [openssl-core@openssl.org](mailto:openssl-core@openssl.org).
5. Products derived from this software may not be called “OpenSSL” nor may “OpenSSL” appear in their names without prior written permission of the OpenSSL Project.
6. Redistributions of any form whatsoever must retain the following acknowledgment:  
“This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org/>)”.

THIS SOFTWARE IS PROVIDED BY THE OpenSSL PROJECT “AS IS” AND ANY EXPRESSED OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE OpenSSL PROJECT OR ITS CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

This product includes cryptographic software written by Eric Young (eay@cryptsoft.com). This product includes software written by Tim Hudson (tjh@cryptsoft.com).

**Original SSLeay License:**

Copyright © 1995-1998 Eric Young (eay@cryptsoft.com). All rights reserved.

This package is an SSL implementation written by Eric Young (eay@cryptsoft.com).

The implementation was written so as to conform with Netscapes SSL.

This library is free for commercial and non-commercial use as long as the following conditions are adhered to. The following conditions apply to all code found in this distribution, be it the RC4, RSA, lhash, DES, etc., code; not just the SSL code. The SSL documentation included with this distribution is covered by the same copyright terms except that the holder is Tim Hudson (tjh@cryptsoft.com).

Copyright remains Eric Young’s, and as such any Copyright notices in the code are not to be removed. If this package is used in a product, Eric Young should be given attribution as the author of the parts of the library used. This can be in the form of a textual message at program startup or in documentation (online or textual) provided with the package.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

1. Redistributions of source code must retain the copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgement:

“This product includes cryptographic software written by Eric Young (eay@cryptsoft.com)”.

The word ‘cryptographic’ can be left out if the routines from the library being used are not cryptography-related.

4. If you include any Windows specific code (or a derivative thereof) from the apps directory (application code) you must include an acknowledgement: “This product includes software written by Tim Hudson (tjh@cryptsoft.com)”.

THIS SOFTWARE IS PROVIDED BY ERIC YOUNG “AS IS” AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE AUTHOR OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY

THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

The license and distribution terms for any publicly available version or derivative of this code cannot be changed. i.e. this code cannot simply be copied and put under another distribution license [including the GNU Public License].

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.

---

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses used in this document are not intended to be actual addresses. Any examples, command display output, and figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses in illustrative content is unintentional and coincidental.

Copyright © 2012–2013 Cisco Systems, Inc. All rights reserved.

---