



Release Notes for the Cisco ASR 900 Series Routers, Cisco IOS XE Release 3S

First Published: March 3, 2015

Last Updated: April 23, 2021

Cisco Systems, Inc.

www.cisco.com

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco website at www.cisco.com/go/offices.

Text Part Number: NA

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

Cisco IOS XE 3S Release Notes for the Cisco ASR 903 Router
© 2012-2017 Cisco Systems, Inc. All rights reserved.

CHAPTER 1**Release Notes for the Cisco ASR 900 Series Routers 1-1**

Overview of Cisco ASR 900 Series Routers	1-2
Cisco ASR 900 Router Series	1-2
Cisco ASR 902 Router	1-2
Cisco ASR 907 Router	1-2
Feature Navigator	1-2
Hardware Supported	1-2
Supported RSP and Interface Modules on the Cisco ASR 903 Router	1-3
Supported RSP and Interface Modules on the Cisco ASR 902 Router	1-5
Supported RSP and Interface Modules on ASR 907 Router	1-7
Feature Set Table	1-8
Software Licensing Overview	1-16
Documentation Roadmap	1-17
Restrictions and Limitations for ASR 900 Series Routers	1-17
Limitations	1-18
Determining the Software Version	1-18
Upgrading to a New Software Release	1-19
Supported FPGA Versions	1-19
Deferrals	1-22
Field Notices and Bulletins	1-22
MIB Support	1-22
MIB Documentation	1-24
Open Source License Notices	1-25

CHAPTER 2**New Features in Cisco IOS XE 3.6S Releases 2-1**

New Hardware Features in Cisco IOS XE Release 3.6(2)S	2-1
New Hardware Features in Cisco IOS XE Release 3.6(1)S	2-1
New Hardware Features in Cisco IOS XE Release 3.6S	2-1
New Software Features in Cisco IOS XE Release 3.6(2)S	2-2
New Software Features in Cisco IOS XE Release 3.6(1)S	2-2
New Software Features in Cisco IOS XE Release 3.6S	2-4

CHAPTER 3**New Features in Cisco IOS XE 3.7S Releases 3-1**

New Hardware Features in Cisco IOS XE Release 3.7(5)S	3-1
New Hardware Features in Cisco IOS XE Release 3.7(4)S	3-1
New Hardware Features in Cisco IOS XE Release 3.7(3)S	3-2

New Hardware Features in Cisco IOS XE Release 3.7(2)S	3-2
New Hardware Features in Cisco IOS XE Release 3.7(1)aS	3-2
New Hardware Features in Cisco IOS XE Release 3.7(0)S	3-2
New Software Features in Cisco IOS XE Release 3.7(5)S	3-2
New Software Features in Cisco IOS XE Release 3.7(4)S	3-2
New Software Features in Cisco IOS XE Release 3.7(3)S	3-2
New Software Features in Cisco IOS XE Release 3.7(2)S	3-2
New Software Features in Cisco IOS XE Release 3.7(1)aS	3-3
New Software Features in Cisco IOS XE Release 3.7(0)S	3-3

CHAPTER 4

New Features in Cisco IOS XE 3.8S Releases 4-1

New Hardware Features in Cisco IOS XE Release 3.8(2)S	4-1
New Hardware Features in Cisco IOS XE Release 3.8(1)S	4-1
New Hardware Features in Cisco IOS XE Release 3.8(0)S	4-1
New Software Features in Cisco IOS XE Release 3.8(2)S	4-2
New Software Features in Cisco IOS XE Release 3.8(1)S	4-2
New Software Features in Cisco IOS XE Release 3.8(0)S	4-2

CHAPTER 5

New Features in Cisco IOS XE 3.9S Releases 5-1

New Hardware Features in Cisco IOS XE Release 3.9(2)S	5-1
New Software Features in Cisco IOS XE Release 3.9(2)S	5-1
New Hardware Features in Cisco IOS XE Release 3.9(1a)S	5-1
New Software Features in Cisco IOS XE Release 3.9(1a)S	5-2
New Hardware Features in Cisco IOS XE Release 3.9(0)S	5-2
New Software Features in Cisco IOS XE Release 3.9(0)S	5-3

CHAPTER 6

New Features in Cisco IOS XE 3.10S Releases 6-1

New Hardware Features in Cisco IOS XE Release 3.10.5S	6-1
New Hardware Features in Cisco IOS XE Release 3.10.4S	6-1
New Hardware Features in Cisco IOS XE Release 3.10.2S	6-1
New Hardware Features in Cisco IOS XE Release 3.10.1S	6-2
DC PEM Module (A900-PWR550-D-E)	6-2
Fan Tray (A903-FAN-E)	6-2
Cable Bracket (A903-CAB-BRACKET)	6-2
Air Plenum	6-2
New Hardware Features in Cisco IOS XE Release 3.10S	6-3

	Serial Interface Module	6-3
	CWDM SFP	6-3
	New Software Features in Cisco IOS XE Release 3.10.5S	6-4
	New Software Features in Cisco IOS XE Release 3.10.4S	6-4
	New Software Features in Cisco IOS XE Release 3.10.2S	6-4
	New Software Features in Cisco IOS XE Release 3.10.1S	6-4
	New Software Features in Cisco IOS XE Release 3.10S	6-4
CHAPTER 7	New Features in Cisco IOS XE 3.11S Releases	7-1
	New Hardware Features in Cisco IOS XE Release 3.11.1S	7-1
	New Software Features in Cisco IOS XE Release 3.11.1S	7-1
	New Hardware Features in Cisco IOS XE Release 3.11S	7-1
	New Software Features in Cisco IOS XE Release 3.11S	7-1
CHAPTER 8	New Features in Cisco IOS XE 3.12S Releases	8-1
	New Hardware Features in Cisco IOS XE Release 3.12S	8-1
	New Software Features in Cisco IOS XE Release 3.12S	8-1
CHAPTER 9	New Features in Cisco IOS XE 3.13S Releases	9-1
	New Hardware Features in Cisco IOS XE Release 3.13.2S	9-1
	New Hardware Features in Cisco IOS XE Release 3.13S	9-1
	New Software Features in Cisco IOS XE Release 3.13.2S	9-2
	New Software Features in Cisco IOS XE Release 3.13S	9-2
CHAPTER 10	New Features in Cisco IOS XE 3.14S Releases	10-1
	New Hardware Features in Cisco IOS XE Release 3.14.2S	10-1
	New Hardware Features in Cisco IOS XE Release 3.14S	10-1
	New Software Features in Cisco IOS XE Release 3.14.2S	10-2
	New Software Features in Cisco IOS XE Release 3.14S	10-2
CHAPTER 11	New Features in Cisco IOS XE 3.15S Releases	11-1
	New Hardware Features in Cisco IOS XE Release 3.15S	11-1
	New Software Features in Cisco IOS XE Release 3.15S	11-2
CHAPTER 12	New Features in Cisco IOS XE 3.16S Releases	12-1
	New Hardware Features in Cisco IOS XE Release 3.16.9S	12-1

New Software Features in Cisco IOS XE Release 3.16.9S	12-1
New Hardware Features in Cisco IOS XE Release 3.16.8S	12-1
New Software Features in Cisco IOS XE Release 3.16.8S	12-1
New Hardware Features in Cisco IOS XE Release 3.16.1aS	12-2
New Software Features in Cisco IOS XE Release 3.16.1aS	12-3
New Hardware Features in Cisco IOS XE Release 3.16S	12-3
New Software Features in Cisco IOS XE Release 3.16S	12-4

CHAPTER 13

New Features in Cisco IOS XE 3.17 Releases 13-1

New Hardware Features in Cisco IOS XE Release 3.17	13-1
New Software Features in Cisco IOS XE Release 3.17	13-2

CHAPTER 14

New Features in Cisco IOS XE 3.18S Releases 14-1

New Hardware Features in Cisco IOS XE Release 3.18.3S	14-1
New Software Features in Cisco IOS XE Release 3.18.3S	14-1
New Hardware Features in Cisco IOS XE Release 3.18.2S	14-1
New Software Features in Cisco IOS XE Release 3.18.2S	14-1
New Hardware Features in Cisco IOS XE Release 3.18.1S	14-2
New Software Features in Cisco IOS XE Release 3.18.1S	14-2
New Hardware Features in Cisco IOS XE Release 3.18S	14-2
New Software Features in Cisco IOS XE Release 3.18S	14-4

CHAPTER 15

New Features in Cisco IOS XE 3.18SP Releases 15-1

New Hardware Features in Cisco IOS XE Release 3.18.8aSP	15-1
New Software Features in Cisco IOS XE Release 3.18.8aSP	15-2
New Hardware Features in Cisco IOS XE Release 3.18.7SP	15-2
New Software Features in Cisco IOS XE Release 3.18.7SP	15-2
New Hardware Features in Cisco IOS XE Release 3.18.6SP	15-2
New Software Features in Cisco IOS XE Release 3.18.6SP	15-2
New Hardware Features in Cisco IOS XE Release 3.18.5SP	15-2
New Software Features in Cisco IOS XE Release 3.18.5SP	15-2
New Hardware Features in Cisco IOS XE Release 3.18.4SP	15-2
New Software Features in Cisco IOS XE Release 3.18.4SP	15-2
New Hardware Features in Cisco IOS XE Release 3.18.3SP	15-3
New Software Features in Cisco IOS XE Release 3.18.3SP	15-3
New Hardware Features in Cisco IOS XE Release 3.18.2SP	15-3

New Software Features in Cisco IOS XE Release 3.18.2SP	15-3
New Hardware Features in Cisco IOS XE Release 3.18.1SP	15-3
New Hardware Features in Cisco IOS XE Release 3.18.1bSP	15-5
New Software Features in Cisco IOS XE Release 3.18.1SP	15-6
New Software Features in Cisco IOS XE Release 3.18.1bSP	15-9
New Hardware Features in Cisco IOS XE Release 3.18SP	15-9
New Software Features in Cisco IOS XE Release 3.18SP	15-9

CHAPTER 16**Restrictions and Caveats in Cisco IOS XE 3.6S Releases 16-1**

Limitations and Restrictions	16-1
Limitations and Restrictions in Cisco IOS XE Release 3.6(2)S	16-1
Limitations and Restrictions in Cisco IOS XE Release 3.6(1)S	16-2
Limitations and Restrictions in Cisco IOS XE Release 3.6S	16-4
Caveats in Cisco IOS XE 3.6S Releases	16-6
Open Caveats—Cisco IOS XE Release 3.6(2)S	16-6
Resolved Caveats—Cisco IOS XE Release 3.6(2)S	16-9
Open Caveats—Cisco IOS XE Release 3.6(1)S	16-11
Resolved Caveats—Cisco IOS XE Release 3.6(1)S	16-13
Open Caveats—Cisco IOS XE Release 3.6(0)S	16-17
Resolved Caveats—Cisco IOS XE Release 3.6(0)S	16-28

CHAPTER 17**Restrictions and Caveats in Cisco IOS XE 3.7S Releases 17-1**

Limitations and Restrictions	17-1
Limitations and Restrictions in Cisco IOS XE Release 3.7(6)S	17-2
Limitations and Restrictions in Cisco IOS XE Release 3.7(5)S	17-2
Limitations and Restrictions in Cisco IOS XE Release 3.7(4)S	17-2
Limitations and Restrictions in Cisco IOS XE Release 3.7(3)S	17-2
Limitations and Restrictions in Cisco IOS XE Release 3.7(2)S	17-2
Limitations and Restrictions in Cisco IOS XE Release 3.7(1)aS	17-3
Limitations and Restrictions in Cisco IOS XE Release 3.7(0)S	17-3
Caveats in Cisco IOS XE 3.7S Releases	17-5
Open Caveats—Cisco IOS XE Release 3.7(6)S	17-6
Resolved Caveats—Cisco IOS XE Release 3.7(6)S	17-6
Open Caveats—Cisco IOS XE Release 3.7(5)S	17-7
Resolved Caveats—Cisco IOS XE Release 3.7(5)S	17-8
Open Caveats—Cisco IOS XE Release 3.7(4)S	17-10
Resolved Caveats—Cisco IOS XE Release 3.7(4)S	17-13
Open Caveats—Cisco IOS XE Release 3.7(3)S	17-20
Resolved Caveats—Cisco IOS XE Release 3.7(3)S	17-23

Open Caveats—Cisco IOS XE Release 3.7(2)S	17-37
Resolved Caveats—Cisco IOS XE Release 3.7(2)S	17-46
Open Caveats—Cisco IOS XE Release 3.7(1)aS	17-48
Resolved Caveats—Cisco IOS XE Release 3.7(1)aS	17-52
Open Caveats—Cisco IOS XE Release 3.7(0)S	17-54
Resolved Caveats—Cisco IOS XE Release 3.7(0)S	17-61

CHAPTER 18

Restrictions and Caveats in Cisco IOS XE 3.8S Releases 18-1

Limitations and Restrictions	18-1
Limitations and Restrictions in Cisco IOS XE Release 3.8(2)S	18-1
Limitations and Restrictions in Cisco IOS XE Release 3.8(1)S	18-1
Limitations and Restrictions in Cisco IOS XE Release 3.8(0)S	18-2
Caveats in Cisco IOS XE 3.8S Releases	18-6
Open Caveats—Cisco IOS XE Release 3.8(2)S	18-7
Resolved Caveats—Cisco IOS XE Release 3.8(2)S	18-12
Open Caveats—Cisco IOS XE Release 3.8(1)S	18-20
Resolved Caveats—Cisco IOS XE Release 3.8(1)S	18-23
Open Caveats—Cisco IOS XE Release 3.8(0)S	18-36
Resolved Caveats—Cisco IOS XE Release 3.8(0)S	18-43

CHAPTER 19

Restrictions and Caveats in Cisco IOS XE 3.9S Releases 19-1

Limitations and Restrictions	19-1
Caveats in Cisco IOS XE 3.9S Releases	19-5
Open Caveats—Cisco IOS XE Release 3.9(2)S	19-6
Resolved Caveats—Cisco IOS XE Release 3.9(2)S	19-6
Open Caveats—Cisco IOS XE Release 3.9(1)aS	19-14
Resolved Caveats—Cisco IOS XE Release 3.9(1)aS	19-18
Open Caveats—Cisco IOS XE Release 3.9(0)S	19-27
Resolved Caveats—Cisco IOS XE Release 3.9(0)S	19-31

CHAPTER 20

Restrictions and Caveats in Cisco IOS XE 3.10S Releases 20-1

Limitations and Restrictions	20-1
Caveats in Cisco IOS XE 3.10S Releases	20-2
Open Caveats—Cisco IOS XE Release 3.10.9S	20-3
Resolved Caveats—Cisco IOS XE Release 3.10.9S	20-3
Open Caveats—Cisco IOS XE Release 3.10.7S	20-3
Resolved Caveats—Cisco IOS XE Release 3.10.7S	20-3
Open Caveats—Cisco IOS XE Release 3.10.6S	20-3
Resolved Caveats—Cisco IOS XE Release 3.10.6S	20-4

Open Caveats—Cisco IOS XE Release 3.10.5S	20-4
Resolved Caveats—Cisco IOS XE Release 3.10.5S	20-4
Open Caveats—Cisco IOS XE Release 3.10.4S	20-5
Resolved Caveats—Cisco IOS XE Release 3.10.4S	20-5
Open Caveats—Cisco IOS XE Release 3.10.3S	20-5
Resolved Caveats—Cisco IOS XE Release 3.10.3S	20-6
Resolved Caveats—Cisco IOS XE Release 3.10.(2)aS	20-8
Open Caveats—Cisco IOS XE Release 3.10.2S	20-8
Resolved Caveats—Cisco IOS XE Release 3.10.2S	20-9
Open Caveats—Cisco IOS XE Release 3.10.1S	20-14
Resolved Caveats—Cisco IOS XE Release 3.10.1S	20-16
Open Caveats—Cisco IOS XE Release 3.10S	20-20
Resolved Caveats—Cisco IOS XE Release 3.10S	20-23

CHAPTER 21**Restrictions and Caveats in Cisco IOS XE 3.11S Releases 21-1**

Caveats in Cisco IOS XE 3.11S Releases	21-1
Open Caveats—Cisco IOS XE Release 3.11.4S	21-2
Resolved Caveats—Cisco IOS XE Release 3.11.4S	21-2
Open Caveats—Cisco IOS XE Release 3.11.3S	21-2
Resolved Caveats—Cisco IOS XE Release 3.11.3S	21-3
Open Caveats—Cisco IOS XE Release 3.11.2S	21-3
Resolved Caveats—Cisco IOS XE Release 3.11.2S	21-4
Open Caveats—Cisco IOS XE Release 3.11.1S	21-5
Resolved Caveats—Cisco IOS XE Release 3.11.1S	21-6
Open Caveats—Cisco IOS XE Release 3.11S	21-8
Resolved Caveats—Cisco IOS XE Release 3.11S	21-9

CHAPTER 22**Restrictions and Caveats in Cisco IOS XE 3.12S Releases 22-1**

Caveats in Cisco IOS XE 3.12S Releases	22-1
Bug Search Tool	22-1
Caveats	22-2
Open Caveats—Cisco IOS XE Release 3.12.4S	22-3
Resolved Caveats—Cisco IOS XE Release 3.12.4S	22-3
Open Caveats—Cisco IOS XE Release 3.12.3S	22-3
Resolved Caveats—Cisco IOS XE Release 3.12.3S	22-3
Open Caveats—Cisco IOS XE Release 3.12.2S	22-3
Resolved Caveats—Cisco IOS XE Release 3.12.2S	22-5
Open Caveats—Cisco IOS XE Release 3.12.1S	22-7
Resolved Caveats—Cisco IOS XE Release 3.12.1S	22-7

Open Caveats—Cisco IOS XE Release 3.12S 22-9
 Resolved Caveats—Cisco IOS XE Release 3.12S 22-9

CHAPTER 23

Restrictions and Caveats in Cisco IOS XE 3.13S Releases 23-1

Caveats in Cisco IOS XE 3.13S Releases 23-1
 Bug Search Tool 23-1
 Caveats 23-2
 Open Caveats—Cisco IOS XE Release 3.13.7S 23-2
 Resolved Caveats—Cisco IOS XE Release 3.13.7S 23-2
 Open Caveats—Cisco IOS XE Release 3.13.6S 23-3
 Resolved Caveats—Cisco IOS XE Release 3.13.6S 23-3
 Open Caveats—Cisco IOS XE Release 3.13.5S 23-3
 Resolved Caveats—Cisco IOS XE Release 3.13.5S 23-4
 Open Caveats—Cisco IOS XE Release 3.13.4S 23-4
 Resolved Caveats—Cisco IOS XE Release 3.13.4S 23-4
 Open Caveats—Cisco IOS XE Release 3.13.3S 23-5
 Resolved Caveats—Cisco IOS XE Release 3.13.3S 23-5
 Open Caveats—Cisco IOS XE Release 3.13.2S 23-6
 Resolved Caveats—Cisco IOS XE Release 3.13.2S 23-6
 Open Caveats—Cisco IOS XE Release 3.13.1S 23-7
 Resolved Caveats—Cisco IOS XE Release 3.13.1S 23-7
 Open Caveats—Cisco IOS XE Release 3.13S 23-8
 Resolved Caveats—Cisco IOS XE Release 3.13S 23-10

CHAPTER 24

Restrictions and Caveats in Cisco IOS XE 3.14S Releases 24-1

Caveats in Cisco IOS XE 3.14S Releases 24-1
 Open Caveats—Cisco IOS XE Release 3.14.3S 24-2
 Resolved Caveats—Cisco IOS XE Release 3.14.3S 24-2
 Open Caveats—Cisco IOS XE Release 3.14.2S 24-3
 Resolved Caveats—Cisco IOS XE Release 3.14.2S 24-3
 Open Caveats—Cisco IOS XE Release 3.14.1S 24-3
 Resolved Caveats—Cisco IOS XE Release 3.14.1S 24-4
 Open Caveats—Cisco IOS XE Release 3.14S 24-5
 Resolved Caveats—Cisco IOS XE Release 3.14S 24-7

CHAPTER 25

Restrictions and Caveats in Cisco IOS XE 3.15S Releases 25-1

Caveats in Cisco IOS XE 3.15S Releases 25-1
 Open Caveats—Cisco IOS XE Release 3.15.2S 25-2
 Resolved Caveats—Cisco IOS XE Release 3.15.2S 25-2

Open Caveats—Cisco IOS XE Release 3.15.1S	25-4
Resolved Caveats—Cisco IOS XE Release 3.15.1S	25-4
Open Caveats—Cisco IOS XE Release 3.15S	25-5
Resolved Caveats—Cisco IOS XE Release 3.15S	25-5

CHAPTER 26**Restrictions and Caveats in Cisco IOS XE 3.16S Releases 26-1**

Limitations and Restrictions in IOS XE Release 3.16.1aS	26-1
Limitations and Restrictions in IOS XE Release 3.16.2	26-2
Caveats in Cisco IOS XE 3.16S Releases	26-2
Open Caveats—Cisco IOS XE Release 3.16.10S (Cisco IOS Release 15.5(3)S10)	26-3
Resolved Caveats—Cisco IOS XE Release 3.16.10S (Cisco IOS Release 15.5(3)S10)	26-3
Resolved Caveats—Cisco IOS XE Release 3.18.10S (Cisco IOS Release 15.5(3)S10 Platform Independent)	26-3
Open Caveats—Cisco IOS XE Release 3.16.9S (Cisco IOS Release 15.5(3)S9)	26-4
Resolved Caveats—Cisco IOS XE Release 3.16.9S (Cisco IOS Release 15.5(3)S9)	26-4
Open Caveats—Cisco IOS XE Release 3.16.8S (Cisco IOS Release 15.5(3)S8)	26-4
Resolved Caveats—Cisco IOS XE Release 3.16.8S (Cisco IOS Release 15.5(3)S8)	26-4
Open Caveats—Cisco IOS XE Release 3.16.6S (Cisco IOS Release 15.5(3)S6)	26-5
Resolved Caveats—Cisco IOS XE Release 3.16.6S (Cisco IOS Release 15.5(3)S6)	26-5
Open Caveats—Cisco IOS XE Release 3.16.5S (Cisco IOS Release 15.5(3)S5)	26-6
Resolved Caveats—Cisco IOS XE Release 3.16.5S (Cisco IOS Release 15.5(3)S5)	26-6
Open Caveats—Cisco IOS XE Release 3.16.4S (Cisco IOS Release 15.5(3)S4)	26-7
Resolved Caveats—Cisco IOS XE Release 3.16.4S (Cisco IOS Release 15.5(3)S4)	26-7
Open Caveats—Cisco IOS XE Release 3.16.3aS (Cisco IOS Release 15.5(3)S3a)	26-8
Resolved Caveats—Cisco IOS XE Release 3.16.3aS (Cisco IOS Release 15.5(3)S3a)	26-9
Open Caveats—Cisco IOS XE Release 3.16.2 (Cisco IOS Release 15.5(3)S2a)	26-9
Resolved Caveats—Cisco IOS XE Release 3.16.2 (Cisco IOS Release 15.5(3)S2a)	26-10
Open Caveats—Cisco IOS XE Release 3.16.1aS (Cisco IOS Release 15.5(3)S1a)	26-12
Resolved Caveats—Cisco IOS XE Release 3.16.1aS (Cisco IOS Release 15.5(3)S1a)	26-13
Open Caveats—Cisco IOS XE Release 3.16S (Cisco IOS Release 15.5(3)S)	26-14
Resolved Caveats—Cisco IOS XE Release 3.16S (Cisco IOS Release 15.5(3)S)	26-14

CHAPTER 27**Restrictions and Caveats in Cisco IOS XE 3.17 Releases 27-1**

Limitations and Restrictions in IOS XE Release 3.17	27-1
Caveats in Cisco IOS XE 3.17 Releases	27-1
Open Caveats—Cisco IOS XE Release 3.17.3S	27-2
Resolved Caveats—Cisco IOS XE Release 3.17.3S	27-3
Open Caveats—Cisco IOS XE Release 3.17.2S	27-3
Closed Caveats—Cisco IOS XE Release 3.17.2S	27-4

Open Caveats—Cisco IOS XE Release 3.17.1S 27-5
 Resolved Caveats—Cisco IOS XE Release 3.17.1S 27-6
 Open Caveats—Cisco IOS XE Release 3.17 27-7
 Resolved Caveats—Cisco IOS XE Release 3.17 27-8

CHAPTER 28

Restrictions and Caveats in Cisco IOS XE 3.18S Releases 28-1

Restrictions in Cisco IOS XE 3.18S Releases 28-1
 Caveats in Cisco IOS XE 3.18S Releases 28-1
 Open Caveats—Cisco IOS XE Release 3.18.3S (Cisco IOS Release 15.6(2)S3) 28-2
 Resolved Caveats—Cisco IOS XE Release 3.18.3S (Cisco IOS Release 15.6(2)S3) 28-3
 Open Caveats—Cisco IOS XE Release 3.18.2S (Cisco IOS Release 15.6(2)S2) 28-3
 Resolved Caveats—Cisco IOS XE Release 3.18.2S (Cisco IOS Release 15.6(2)S2) 28-4
 Open Caveats—Cisco IOS XE Release 3.18.1S (Cisco IOS Release 15.6(2)S1) 28-4
 Resolved Caveats—Cisco IOS XE Release 3.18.1S (Cisco IOS Release 15.6(2)S1) 28-4
 Open Caveats—Cisco IOS XE Release 3.18S (Cisco IOS Release 15.6(2)S) 28-5
 Resolved Caveats—Cisco IOS XE Release 3.18S (Cisco IOS Release 15.6(2)S) 28-5

CHAPTER 29

Restrictions and Caveats in Cisco IOS XE 3.18SP Releases 29-1

Restrictions in Cisco IOS XE 3.18.1SP 29-1
 Caveats in Cisco IOS XE 3.18SP Releases 29-2
 Bug Search Tool 29-2
 Caveats 29-2
 Open Caveats—Cisco IOS XE Release 3.18.9SP (Cisco IOS Release 15.6(2)SP9) 29-3
 Resolved Caveats—Cisco IOS XE Release 3.18.9SP (Cisco IOS Release 15.6(2)SP9) 29-3
 Open Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8) 29-3
 Resolved Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8) 29-4
 Resolved Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8) Platform Independent 29-4
 Open Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7) 29-4
 Resolved Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7) 29-4
 Resolved Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7) Platform Independent 29-5
 Open Caveats—Cisco IOS XE Release 3.18.6SP (Cisco IOS Release 15.6(2)SP6) 29-6
 Resolved Caveats—Cisco IOS XE Release 3.18.6SP (Cisco IOS Release 15.6(2)SP6) 29-6
 Open Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5) 29-7
 Resolved Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5) 29-8
 Open Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4) 29-11
 Resolved Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4) 29-12
 Open Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3) 29-15
 Resolved Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3) 29-16

Open Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2)	29-19
Resolved Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2)	29-19
Open Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1)	29-20
Resolved Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1)	29-21
Open Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP)	29-24
Resolved Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP)	29-24



Release Notes for the Cisco ASR 900 Series Routers

The Cisco ASR 900 Series Routers are full-featured, modular aggregation platforms designed for the cost-effective delivery of converged mobile, residential, and business services.

The Cisco ASR 900 Router Series runs the Cisco IOS XE software beginning with Release 3.5.0S. This document provides information about the IOS XE software release for the Cisco ASR 900 Router Series beginning with Release 3.6(0)S.



Note

For information about Cisco IOS Release 3.5, see the [Release Notes for Cisco IOS XE Release 3S](#).

- [Overview of Cisco ASR 900 Series Routers, page 2](#)
- [Feature Navigator, page 2](#)
- [Hardware Supported, page 2](#)
- [Feature Set Table, page 8](#)
- [Software Licensing Overview, page 16](#)
- [Documentation Roadmap, page 17](#)
- [Restrictions and Limitations for ASR 900 Series Routers, page 17](#)
- [Determining the Software Version, page 18](#)
- [Upgrading to a New Software Release, page 19](#)
- [Deferrals, page 22](#)
- [Supported FPGA Versions, page 19](#)
- [MIB Support, page 22](#)
- [Open Source License Notices, page 24](#)

Text Part Number:

Overview of Cisco ASR 900 Series Routers

Cisco ASR 900 Router Series

The Cisco ASR 900 Router Series is a fully-featured routing platform designed for the cost-effective delivery of converged mobile and business services. With full redundancy, shallow depth, low power consumption and high service scale, this 3-rack-unit (3RU) router is optimized for small aggregation and remote point-of-presence (POP) applications. The Cisco ASR 900 Router Series provides a rich and scalable feature set of Legacy, Timing, Carrier Ethernet, Layer 2 VPN (L2VPN) and Layer 3 VPN (L3VPN) services in a compact package.

The Cisco ASR 900 Router Series is a fully modular platform with support for 6-Interface Modules (IMs), two Route Switch Processor (RSP) slots, two power supplies and redundant fans. Cisco offers a wide choice of LAN and WAN interfaces available in speeds ranging from nxDS0 to 10 Gigabit Ethernet. The design of the Cisco ASR 900 Router Series delivers in-box hardware redundancy for all hardware components and supports software redundancy with In Service Software Upgrade (ISSU) and Non-Stop Forwarding (NSF) support.

Cisco ASR 902 Router

The Cisco ASR 902 Router is a full-featured aggregation platform designed for cost-effective delivery of converged mobile and business services. With shallow depth, low power consumption, and an extended temperature range, this compact 2-rack unit (2RU) router provides high service scale and flexible hardware configuration.

Cisco ASR 907 Router

The Cisco ASR 907 Router seven-rack (7RU) unit router that belongs to the Cisco ASR90x family of routers. This router complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE and CDMA. Given its form-factor, interface types and GigabitEthernet density the Cisco ASR 907 Router can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco ASR 907 Router is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation router.

Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

Hardware Supported

- [Supported RSP and Interface Modules on the Cisco ASR 903 Router, page 3](#)
- [Supported RSP and Interface Modules on the Cisco ASR 902 Router, page 5](#)

- [Supported RSP and Interface Modules on ASR 907 Router, page 7](#)

Supported RSP and Interface Modules on the Cisco ASR 903 Router

Table 1 Supported RSP2 Modules and Interface Modules on Cisco ASR 903 Router

RSP Module	Interface Modules	Part Number	Slot
A900-RSP2A-128	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	All
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	
	16-port T1/E1 Interface Module	A900-IMA16D	
	8-port T1/E1 Interface Module	A900-IMA8D	
	32-port T1/E1 Interface Module	A900-IMA32D	
	4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module	A900-IMA4OS	
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module (1x10GE)	A900-IMA8T1Z	
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z	
	14-port Serial Interface Module	A900-IMASER14A/S	
	6-port E & M Interface Module	A900-IMA6EM	
	4-port C37.94 Interface Module	A900-IMA4C3794	
A900-RSP2A-64	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	0-2
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z	
	4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module	A900-IMA4OS	
	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	3-5
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	16-port T1/E1 Interface Module	A900-IMA16D	
	8-port T1/E1 Interface Module	A900-IMA8D	
	32-port T1/E1 Interface Module	A900-IMA32D	
	14-port Serial Interface Module	A900-IMASER14A/S	
	6-port E & M Interface Module	A900-IMA6EM	
	4-port C37.94 Interface Module	A900-IMA4C3794	

**Note**

The combination IMs (A900-IMA8S1Z, A900-IMA8T1Z) are *not* supported on the A900-RSP2-64 RSP module on the Cisco ASR 900 Router Series.

A900-RSP3 Modules Supported Interface Modules

Table 2 A900-RSP3 Supported Interface Modules on the Cisco ASR 903 Router

RSP Module	Supported Interface Modules	Part Numbers	Slot
A900-RSP3C-400-S	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	All ¹
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module (1x10GE)	A900-IMA8T1Z	
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z	
	8-port 10 Gigabit Ethernet Interface Module (8x10GE)	A900-IMA8Z	
	1-port 100 Gigabit Ethernet Interface Module (1x100GE)	A900-IMA1C	4 and 5
	2-port 40 Gigabit Ethernet QSFP Interface Module (2x40GE)	A900-IMA2F	4 and 5
	1-port OC-192 Interface module or 8-port Low Rate Interface Module	A900-IMA1Z8S-CX	2,3, 4 and 5
	48-port T1/E1 CEM Interface Module	A900-IMA48D-C	All
48-port T3/E3 CEM Interface Module	A900-IMA48T-C		
A900-RSP3C-200-S	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	All ²
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	0, 2 and 4
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	0-4
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module (1x10GE)	A900-IMA8T1Z	
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z	4
	8-port 10 Gigabit Ethernet Interface Module (8x10GE)	A900-IMA8Z	
	2-port 40 Gigabit Ethernet QSFP Interface Module (2x40GE)	A900-IMA2F	

1. There are restrictions using the interface modules in different slots with RSP3 module. Contact Cisco Sales/Support for the valid combinations.
2. There are restrictions using the interface modules in different slots with RSP3 module. Contact Cisco Sales/Support for the valid combinations.

Supported RSP and Interface Modules on the Cisco ASR 902 Router

Table 3 Supported RSP2 and Interface Modules on Cisco ASR 902 Router

RSP Module	Interface Modules	Part Number	Slot
A900-RSP2A-128	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	All
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module(1x10GE)	A900-IMA8T1Z	
	2-port 10 Gigabit Ethernet Interface Module(2x10GE)	A900-IMA2Z	
	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	
	16-port T1/E1 Interface Module	A900-IMA16D	
	8-port T1/E1 Interface Module	A900-IMA8D	
	4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module	A900-IMA4OS	
	14-port Serial Interface Module	A900-IMASER14 A/S	
	6-port E & M Interface Module	A900-IMA6EM	
4-port C37.94 Interface Module	A900-IMA4C379 4		

RSP Module	Interface Modules	Part Number	Slot	
A900-RSP2A-64	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	0 and 2	
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module(1x10GE)	A900-IMA8T1Z		
	2-port 10 Gigabit Ethernet Interface Module(2x10GE)	A900-IMA2Z		
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	1	
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z		
	4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module	A900-IMA4OS	3	
	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S		
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T		
	16-port T1/E1 Interface Module	A900-IMA16D		
	8-port T1/E1 Interface Module	A900-IMA8D		
	14-port Serial Interface Module	A900-IMASER14 A/S		0, 2 and 3
	6-port E & M Interface Module	A900-IMA6EM		
	4-port C37.94 Interface Module	A900-IMA4C379 4		

A900-RSP3C-200-S Supported Interface Modules

Table 4 Supported RSP and Interface Modules on Cisco ASR 902 Router

RSP Module	Supported Interface Modules	Part Numbers	Slot
A900-RSP3C-200-S	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	All ¹
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	
	1-port 10 Gigabit Ethernet XFP Interface Module (1x10GE)	A900-IMA1X	0 and 1
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	A900-IMA8S1Z	All
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module (1x10GE)	A900-IMA8T1Z	
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	A900-IMA2Z	
	8-port 10 Gigabit Ethernet Interface Module (8x10GE)	A900-IMA8Z	0
	2-port 40 Gigabit Ethernet QSFP Interface Module (2x40GE)	A900-IMA2F	

1. There are restrictions using the interface modules in different slots with RSP3 module. Contact Cisco Sales/Support for the valid combinations..

Supported RSP and Interface Modules on ASR 907 Router

Table 5 Supported RSP and Interface Modules on Cisco ASR 907 Router

RSP Module	Interface Modules	Part Number	Slot
A900-RSP3C-400-W	8-port Gigabit Ethernet SFP Interface Module (8x1GE)	A900-IMA8S	0,1,2,5,6,9,10,13,14,15
	8-port Gigabit Ethernet RJ45 (Copper) Interface Module (8x1GE)	A900-IMA8T	0,1,2,5,6,9,10,13,14,15
	SFP Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet (1x10GE)	ASR900-IMA8S1Z	2,5,6,9,10,13,14,15
	Copper Combo IM—8-port Gigabit Ethernet (8x1GE) + 1-port 10 Gigabit Ethernet Interface Module (1x10GE)	ASR900-IMA8T1Z	2,5,6,9,10,13,14,15
	2-port 10 Gigabit Ethernet Interface Module (2x10GE)	ASR900-IMA2Z	3,4,7,8,11,12
	1-port 100 Gigabit Ethernet Interface Module (1x100GE)	A900-IMA1C	7,8
	2-port 40 Gigabit Ethernet QSFP Interface Module (2x40GE)	A900-IMA2F	3,4,7,8,11,12
	8-port 10 Gigabit Ethernet Interface Module (8x10GE)	A900-IMA8Z	3,4,7,8,11,12

Feature Set Table

The following is the list of supported features per Cisco IOS Release for A900-RSP2 Module.

Table 6 *Supported Software Features for A900-RSP2*

Cisco IOS XE Release	Technology	Supported Features
3.13	Ethernet OAM	<ul style="list-style-type: none"> • 802.1ad • CFM Extension for 1+1 Hot-Standby Support • CFM over EFP interface configured with Cross connect • CFM Support on Trunk EFP • CFM enhancements • CFM CCM Hardware Offload • EtherChannel Mini-Links • Ethernet Local Management Interface (LMI) at Provider Edge (PE) • Ethernet Operations, Administration, and Maintenance (OAM) • Microwave ACM Signaling and EEM integration Synthetic Frame Loss Measurement (ETH-SLM) • Trunk EFP Support on Ether-Channel Interfaces • Y.1731 enhancements (On-demand & Concurrent support) • Y.1731 Performance Monitoring

Cisco IOS XE Release	Technology	Supported Features
3.13	Ethernet	<ul style="list-style-type: none"> • 802.1ad • G.8032 and CFM support for Microwave Adaptive Bandwidth • IEEE 802.1ab LLDP (Link Layer Discovery Protocol) • IEEE 802.3ad Link Aggregation (LACP) • LACP 1-1 redundancy with fast switchover) • L2 ACL on Service Instance on Port-channel • MAC Address Limiting on Service Instance / Bridge Domain • MAC Address Security for EVC Bridge-Domain • MAC Limiting per VFI and BD • MST on EVC Bridge-Domain • Static MAC binding to EVCs and Pseudowires • Trunk EFP support • Unicast Reverse Path Forwarding (uRPF) • Unicast Reverse Path Forwarding (uRPF) Loose mode • UniDirectional Link Detection (UDLD) • Egress default queue limit improvement and percent bandwidth support • Switch Port Analyzer (SPAN)
	IP Addressing	<ul style="list-style-type: none"> • DAI (Dynamic ARP Inspection) • DHCP - DHCPv6 Relay Agent notification for Prefix Delegation • DHCP Option 82 Configurable Circuit ID and Remote ID • DHCP Snooping • DHCPv6 - Relay chaining for Prefix Delegation
	IP Multicast	<ul style="list-style-type: none"> • IGMP State Limit • Multicast Source Discovery Protocol (MSDP) • PIM Version 2 • Source Specific Multicast (SSM) • Source Specific Multicast (SSM) Mapping

Cisco IOS XE Release	Technology	Supported Features
3.13	IP Routing	<ul style="list-style-type: none"> • BFD - Static Route Support • BFD Echo Mode • BFD IPv6 Encapsulation Support • BFD Support for HSRP • BFD: BGP multihop client Support (IPv4/IPv6) • BFD - BFD Hardware Offload Support • SSO - BFD • OSPF Support for BFD over IPv4 • BGP - iBGP NSR • BGP Support for BFD • BGP Support for TCP Path MTU Discovery per Session • BGP: Graceful Shutdown (GSHUT) • BGP PIC (edge & core) - for RFC-3107 labeled iBGP • BGP Support for 4-byte ASN • Cisco-BGP-MIBv2 • IP 16-way Equal-Cost Multipath • IP FRR • IP FRR/Remote LFA FRR with L2VPN • IS-IS - MPLS LDP Autoconfiguration • IS-IS Support for BFD over IPv4 • Multi-protocol BGP (MP-BGP) - MPLS VPN • VPLS BGP Signaling
	IP Tunneling	<ul style="list-style-type: none"> • L2PT - Layer 2 Protocol Tunneling • L2PT - Layer 2 Protocol Tunneling on Trunk Ports
	IP Routing- Version 6	<ul style="list-style-type: none"> • IPv6 ACL • IPv6 QoS: MQC Packet Classification • IPv6 Routing: Static Routing IPv6 Switching: CEF/dCEF Support • IPv6 Switching: Provider Edge Router over MPLS (6PE) • IPv6 Routing: IS-IS Support for IPv6 • IPv6 Routing: OSPF for IPv6 (OSPFv3) • IPv6 VPN over MPLS (6VPE) • Static Route Support for BFD over IPv6

Cisco IOS XE Release	Technology	Supported Features
3.13	MPLS	<ul style="list-style-type: none"> • Any Transport over MPLS (AToM): Ethernet over MPLS (EoMPLS) • BGP PIC Edge for IP/MPLS • Bidirectional MPLS-TP LSP • H-VPLS N-PE Redundancy for MPLS Access • Hot Standby Pseudowire Support for ATM and TDM Access Circuits • L2VPN Protocol Based CLI • Link Path Through • MFI -Extended LFA • MPLS (Multiprotocol Label Switching) • MPLS -TP: IP Less trace support (NodeId, LinkId) • MPLS -TP: Linear Protection/PSC support • MPLS Forwarding Infrastructure Scalability • MPLS LDP - IGP Synchronization • MPLS OAM Support for Multisegment Pseudowires • MPLS TE - Bundled Interface Support (EtherChannel and MLP) • MPLS TP: IP-less configuration of MPLS TP tunnels • MPLS Traffic Engineering (TE) - Fast Reroute (FRR) Link and Node Protection • MPLS Virtual Private Networks (VPN) • MPLS VPN - Inter-Autonomous System Support • MPLS-TP OAM: Continuity Check via BFD • MPLS-TP OAM: Fault Management • MPLS-TP OAM: GACH • MPLS-TP OAM: Ping/Trace • MPLS-TP Path Protection • Static VPLS over MPLS-TP • Support sending PW Grouping ID TLV • Virtual Private LAN Services (VPLS) • VPLS Autodiscovery, BGP-based • VPLS MAC Address Withdrawal • VPLS over MPLS-TP • MPLS-TP: MS-PW with Static and Dynamic PW Support • MPLS-TP: PW Redundancy for Static PWs • L2VPN Static to Dynamic PW Interconnection & PW Preferred Path for MPLS-TP Tunnels • L2VPN: PW Status for Static PWs

Cisco IOS XE Release	Technology	Supported Features
3.13	Network Management	<ul style="list-style-type: none"> • IPSLA Y1731 SLM Feature Enhancements
	OS Infrastructure	<ul style="list-style-type: none"> • Access Switch Device Manager (SDM) Template • Cisco Secure Licensing Support) • Field Programmable Device Upgrade Tool • Punt Policing and Monitoring • Digital Code Signing • Embedded Event Manager (EEM) 4.0
	QoS	<ul style="list-style-type: none"> • Class based policing • Class Based Weighted Fair Queuing (CBWFQ) • Class-based QoS MIB • Diffserv Compliant WRED • EFP aware QoS • Egress policing and marking • match any classification • Modular QoS CLI (MQC) • MQC - Multi-Level Priority Queue • Port-Shaper and LLQ in the presence of EFPs • QoS ACLs for ASR900 • QoS Classification based on EFP • QoS EXP matching • QoS Packet Marking • RSVP - Resource Reservation Protocol

Cisco IOS XE Release	Technology	Supported Features
3.13	Security	<ul style="list-style-type: none"> • ACL - Access Control List Source and Destination Address Matching • ACL - DSCP Matching • ACL - ICMP Code • ACL - IP Protocol • Secure Shell SSH Version 2 Client Support
	Timing and Clocking	<ul style="list-style-type: none"> • 1588 BC over MPLS • 1588 PTP Best Master Clock Algorithm (BMCA) or PTP Redundancy • 1588-2008 Boundary Clock • E2E Transparent Clocking • Hybrid Clocking Support • ITU-T Telecom Profile G.8265.1 • Support for IEEE 1588-2008 Precision Clock Synchronization Protocol • Time of Day Selection • PTP over Native Ethernet

Cisco IOS XE Release	Technology	Supported Features
3.14	TDM	<ul style="list-style-type: none"> • 1+1 APS on OC-3 • ATM IMA support • Circuit Emulation SAToP over MPLS • AToM AAL5 over MPLS • STM1 support • SONET mode support for OC-3 • POS Concatenation mode on STM 1 and STM 4 • Access Circuit Redundancy • AAL5 termination for QoS • Circuit Emulation over Packet Switched Network (CESoPSN) • T1/E1 support • Channelization support for OC-3 • QoS support on POS for OC-3 • CEM with 32 T1/E1 • TDM over serial MLPPP, PPP for serial support
	Carrier Ethernet	<ul style="list-style-type: none"> • Ethernet Loopback
	Multicast	<ul style="list-style-type: none"> • IGMP Snooping on EFP and Trunk EFP • PIM BFD Support
	MPLS	<ul style="list-style-type: none"> • Async R232 over MPLS
	OS Infrastructure	<ul style="list-style-type: none"> • Dying Gasp
	Security	<ul style="list-style-type: none"> • Storm Control
	Layer 2	<ul style="list-style-type: none"> • 802.1ad • Ethernet Dataplane Loopback • Remote SPAN
	Lan Switching	<ul style="list-style-type: none"> • UDLD
	IP	<ul style="list-style-type: none"> • VRRP3 Protocol

Cisco IOS XE Release	Technology	Supported Features
3.15	TDM	<ul style="list-style-type: none"> • HDLC, PPP and MLPPP • Circuit Emulation over Packet Switched Network • SAToP over MPLS • T1/E1 support • STM1 support on ASR900 • MPLS-TP: ATM and TDM Pseudowires • POS Concatenation mode on STM-1 and STM-4 Interface Modules • Sonet Framing Support on OC3 IM • Channelization support for OC3 IM • ACFC and PFC support on Multilink interface • MPLS - Multilink PPP support • PPP MLP MRRU negotiation configuration • MLP and Serial support with 8 T1/E1 • MLP and Serial support with 32 T1/E1 • Hot Standby Pseudowire Support for ATM and TDM Access Circuits • MR-APS integration with hot standby Pseudowire • POS over OC-12
	ATM	<ul style="list-style-type: none"> • Inverse Multiplexing over ATM (IMA) • Any Transport over MPLS (AToM): ATM AAL5 over MPLS (AAL5oMPLS) • N:1 PVC mapping to PWE with non-unique VPI • ATM IMA, PPP, MLPP support on OC-3 • Any Transport over MPLS (AToM): ATM Cell Relay over MPLS: Packed Cell Relay
	MPLS	<ul style="list-style-type: none"> • Routed Pseudowire and VPLS • LDP NSR • MPLS - Multilink PPP support
	Multicast	<ul style="list-style-type: none"> • IPv6 Multicast: Multicast Listener Discovery (MLD) • MLDP based MVPN • Label Switched Multicast Point-to-Multipoint Traffic Engineering
	IP	<ul style="list-style-type: none"> • BGP PIC Edge for IPv6 • VRRPv3 High Scale
	QoS	<ul style="list-style-type: none"> • Hierarchical Color-aware policing • EVC push rewrite with CoS
	IP Routing	<ul style="list-style-type: none"> • DHCP Server for IPv6 • DHCP Client for IPv6
	Clocking	<ul style="list-style-type: none"> • Hop-By-Hop Redundancy in PTP Ring
	Licensing	<ul style="list-style-type: none"> • Smart License with HA Support

Cisco IOS XE Release	Technology	Supported Features
3.16.1a	IP Routing	<ul style="list-style-type: none"> Policy Based Routing (PBR)
	Multicast	<ul style="list-style-type: none"> IGMP Snooping over Port-Channel
	IPv6	<ul style="list-style-type: none"> uRPF for IPv6 Strict and Loose mode
	MPLS	<ul style="list-style-type: none"> Circuit Emulation Service over UDP (CESoUDP) Priority Shaper MPLS MTU on GRE Tunnels
	Network Management	<ul style="list-style-type: none"> Service Activation
	Carrier Ethernet	<ul style="list-style-type: none"> Microwave ACM Enhancements
	QoS	<ul style="list-style-type: none"> EMCP load balancing with Ingress and Egress linksPri
	ATM	<ul style="list-style-type: none"> Pseudowire Group Message Generation
	System Management	<ul style="list-style-type: none"> IOS XE Image Signing Segment Routing
3.17S and Later	All	http://www.cisco.com/c/dam/en/us/td/docs/wireless/asr_900/compatibility/matrix/Compatibility-Matrix-ASR900.pdf

Table 7 Supported Software Features for A900-RSP3 Modules

Cisco IOS XE Release	Technology	Supported Features
3.16.1a and Later	All	http://www.cisco.com/c/dam/en/us/td/docs/wireless/asr_900/compatibility/matrix/Compatibility-Matrix-ASR900.pdf

Software Licensing Overview

The router offers the following base licenses:

- Metro Services
- Metro IP Services
- Metro Aggregation Services

Table 8 Cisco ASR 900 Software Licenses Feature Set

Metro Services	Metro IP Services	Metro Aggregation Services
	Includes all features in Metro Services	Includes all features in Metro IP Services
QoS, with deep buffers and hierarchical QoS (HQoS)	IP routing (RIP, OSPF, EIGRP, BGP, IS-IS)	MPLS (LDP and VPN)
Layer 2: 802.1d, 802.1q	PIM (SM, DM, SSM), SSM mapping	MPLS TE and FRR

Metro Services	Metro IP Services	Metro Aggregation Services
Ethernet Virtual Circuit (EVC)	BFD	MPLS OAM
Ethernet OAM (802.1ag, 802.3ah)	Multi-VRF CE (VRF lite) with service awareness (ARP, ping, SNMP, syslog, trace-route, FTP, TFTP)	MPLS-TP
Multiple Spanning Tree (MST) and Resilient Ethernet Protocol (REP)	IEEE 1588-2008 Ordinary Clock and Transparent Clock	Pseudowire emulation (EoMPLS, CESoPSN, and SAToP)
Synchronous Ethernet		VPLS and HVPLS
IPv4 and IPv6 host connectivity		Pseudowire redundancy
		MR-APS and mLACP

The router offers the following additional feature licenses:

- ATM
- IEEE 1588-2008 Boundary Clock/Master Clock
- OC-3 Port License



Note

These features require a software license to use.

For more information about each software license including part numbers, see the [Cisco ASR 900 Router Series Datasheet](#). For instructions on how to install licenses on the Cisco ASR 900 Router Series, see the [Software Activation Configuration Guide, Cisco IOS XE Release 3S](#).

Documentation Roadmap

To view other documents for the Cisco ASR 900 Router Series, see the [Cisco ASR 903 Router Documentation Roadmap](#).

Restrictions and Limitations for ASR 900 Series Routers

- The **ip cef accounting** command is *not* supported on the router.
- Crash may be observed on the router when:
 - EoMPLS, CEM, ATM and IMA Pseudowire Redundancy (PW-redundancy) configurations exist while switchover and fail-back of the pseudowires are being triggered, and the **show platform hardware pp active pw eompls** command is executed.
- Configuration sync does *not* happen on the Standby RSP when the active RSP has Cisco Software Licensing configured, and the standby RSP has Smart Licensing configured on the router. If the active RSP has Smart Licensing configured, the state of the standby RSP is undetermined. The state could be pending or authorized as the sync between the RSP modules is not performed.
- Evaluation mode feature licenses may *not* be available to use after disabling, and enabling the smart licensing on the ASR 903 RSP2 module. A reload of the router is required.

- Ingress counters are *not* incremented for packets of the below format on the RSP3 module for the 10 Gigabit Ethernet interfaces, 100 Gigabit Ethernet interfaces, and 40 Gigabit Ethernet interfaces:

Packet format

MAC header---->Vlan header---->Length/Type

When these packets are received on the RSP3 module, the packets are not dropped, but the counters are not incremented.

Limitations

Identifier	Description
CSCux81166	MPLS MTU getting set even without IP address being configured in RSP2
CSCux40620	Only 15 offloaded cfmovpls sessions are coming up
CSCuy04343	RSP3:Port not getting added to vlan when encap is untagged+dot1q
CSCuw59663	Flex-LSP:OAM packets are punted in TTL Q instead of OAM Q
CSCux74365	SR:microloop due to flushing of SR tunnel, RIB-Update-Delay not honoured
CSCux55104	TBC stopped sending packet after adding netsync command
CSCuw64751	Lower BRP/BRR values with very high queue-limit doesnt work
CSCux33281	RSP3: Minimum supported priority shaper is 1Mbps
CSCuy06751	RSP3: COS marking does not work for single tag traffic in specific case.
CSCux18679	RSP3:stby keep booting with config-sync, ISSU from XE3.18 to XE3.16
CSCus61902	UT issues post L4 filtering support for IP ACL
CSCuw75087	Y1731 is not working with MEP on TEPF
CSCut38237	[RSP3-SPAN]: poch span doesn't work in case traffic flows through second
CSCuw57701	RSP3: IP MTU fragmentation limitations on BDI
CSCuw79466	RSP3:PoCH ECMP loadbalancing fails with RFC3107
CSCuw60217	RSP3 : Match efp egress classification does not work on PC member link
CSCuw89069	RSP3 QoS: Conditional Marking On BD during Flood doesn't work

Determining the Software Version

You can use the following commands to verify your software version:

- Consolidated Package—**show version**
- Individual sub-packages—**show version installed (lists all installed packages)**

Upgrading to a New Software Release

Only Cisco IOS XE 3S consolidated packages can be downloaded from Cisco.com; users who want to run the router using individual subpackages must first download the image from Cisco.com and extract the individual subpackages from the consolidated package.

For information about upgrading to a new software release, see the [Cisco ASR 900 Router Series Configuration Guide](#).

Supported FPGA Versions

Use the `show hw-module all fpd` command to display the FPGA version on the router.

Table 9 lists the FPGA version for the software releases.


Note

If there is an FPGA upgrade during ISSU, it will cause traffic disruption. TDM interface modules get reset irrespective of FPGA upgrade during the ISSU.

Table 9 **FPGA Versions**

Cisco IOS XE Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	TDM Interface Module FPGA	RSP2 Module HoFPGA
3.5	0.28	—	—	—
3.6	0.35 (0.23 H)	—	—	—
3.7 - 3.7a	0.35 (0.23 H)	—	—	—
3.7.2 - 3.7.3	0.35 (0.23 H)	—	—	—
3.7.4 and rebuilds	0.40 (0.28 H)	—	—	—
3.8 and rebuilds	0.35 (0.23 H)	—	—	—
3.9 and rebuilds	0.35 (0.23 H)	—	0.48 (0.30 H)	—
3.10 and rebuilds	0.40 (0.28 H)	—	0.48 (0.31 H)	—
3.10.1	0.42 (0.2A H)	—	0.49 (0.31 H)	—
3.10.2 to 3.10.4	0.44 (0.2C H)	—	0.49 (0.31 H)	—
3.11	0.42 (0.2A H)	—	0.49 (0.31 H)	—
3.11.1 and rebuilds	0.44 (0.2C H)	—	0.49 (0.31 H)	—
3.12	0.44 (0.2C H)	—	0.49 (0.31 H)	—

Cisco IOS XE Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	TDM Interface Module FPGA	RSP2 Module HoFPGA	
3.13	0.44 (0.2C H)	<ul style="list-style-type: none"> 2x10 Gigabit Ethernet IM-69.20 (0x45_14 H) Combo IM-69.22 (0x45_16 H) 	0.49 (0.31 H)	0x42	
3.13.1	0.44 (0.2C H)		0.49 (0.31 H)	0x43	
3.14	0.44 (0.2C H)		0.49 (0.31 H)	0x44	
3.15	0.47 (0.2C H)				
3.16					0x51
3.16.1					0x4B
3.16.3					
3.16.4					
3.17					0x52
3.18					0x60
3.18.1					
3.18SP				0x3_0004 (with BFD_SAD T & NETFLOW)	
3.18.1SP				0x3_0005	

Table 10 FPGA for ASR 903 RSP3 and ASR 907

Cisco IOS XE Release	10 FGPA	8 x10 FGPA	2x40 FGPA	1x100 FGPA
3.16.0.S	2.3	0.17 (0x1100H)	0.17 (0x1100H)	0.17 (0x1100H)
3.16.1a.S	2.5			
3.16.2.S				
3.16.3a.S				
3.16.4				
3.17.S				
3.17.1.S				
3.17.2				
3.18.S			0.19 (0x1300H)	0.19 (0x1300H)
3.18.1				
3.18SP	2.7		0.22 (0x1600 H)	
3.18.1SP				

Table 11 Cisco IOS XE Release 3.18.7SP FPGA for ASR 903 RSP3 and ASR 907

Platform	Interface Module	FPGA (Current Version)	FPGA (Minimum Version)	RSP Module HoFPGA	ROMMON
RSP-128	A900-IMA2Z	69.22	69.22	0X0003000 ^e	15.6(30r)S
	A900-IMA8S	0.49	0.49		
	A900-IMA8T1Z	69.24	69.24		
RSP3-200S	A900-IMA8T	0.49	0.49	4000d	15.6(33r)S
	A900-IMA8Z	0.21	0.17		
	A900-IMA8S	0.49	0.49		
RSP3-400S	A900-IMA1C	0.2	0.19	4000d	15.6(33r)S
	A900-IMA8Z	0.22	0.17		
	A900-IMA8S1Z	69.24	69.24		
RSP3-400W	A900-IMA1C	0.2	0.19	2004000d	15.6(33r)S
	A900-IMA2Z	69.22	69.22		

Table 12 Cisco IOS XE Release 3.18.8aSP and 3.18.9SP FPGA for ASR 903 RSP3 and ASR 907

Platform	Interface Module	FPGA Version	RSP Module HoFPGA	ROMMON
RSP-128	A900-IMA2Z	69.22	0X0003000 ^e	15.6(43r)S
	A900-IMA8S	0.49		
	A900-IMA8T1Z	69.24		
RSP3-200S	A900-IMA8T	0.49	4000d	15.6(42r)S
	A900-IMA8Z	0.17		
	A900-IMA8S	0.49		
RSP3-400S	A900-IMA1C	0.19	4000d	15.6(42r)S
	A900-IMA8Z	0.17		
	A900-IMA8S1Z	69.22		
RSP3-400W	A900-IMA1C	0.19	2004000d	15.6(42r)S
	A900-IMA2Z	69.22		

Table 13 Cisco IOS XE Release 3.18.8aSP FPGA for ASR 900

RSP2	A900-IMA40S	A900-IMA8S1Z	A900-IMA32D	A900-IMA16D	A900-IMA1X
FPGA	0.54	69.24	0.46	0.54	0.49
CEM	NA	NA	NA	NA	NA

Table 14 Cisco IOS XE Release 3.18.9SP FPGA for ASR 900

RSP2	A900-IMA40S	A900-IMA8S1Z	A900-IMA32D	A900-IMA16D	A900-IMA1X
FPGA	0.54	0.54	0.46	0.54	0.54
CEM	NA	NA	NA	NA	NA

Deferrals

Cisco IOS software images are subject to deferral. We recommend that you view the deferral notices at the following location to determine whether your software release is affected:

http://www.cisco.com/en/US/products/products_security_advisories_listing.html

Field Notices and Bulletins

- Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.
- Bulletins—You can find bulletins at http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html.

MIB Support

Table 15 summarizes the supported MIBs on the Cisco ASR 900 Router Series:

Table 15 Supported MIBs

Supported MIBs		
BGP4-MIB (RFC 1657)	CISCO-IMAGE-LICENSE-MGMT-MIB	MPLS-LDP-STD-MIB (RFC 3815)
CISCO-BGP-POLICY-ACCOUNTING-MIB	CISCO-IMAGE-MIB	MPLS-LSR-STD-MIB (RFC 3813)
CISCO-BGP4-MIB	CISCO-IPMROUTE-MIB	MPLS-TP-MIB
CISCO-BULK-FILE-MIB	CISCO-LICENSE-MGMT-MIB	MSDP-MIB
CISCO-CBP-TARGET-MIB	CISCO-MVPN-MIB	NOTIFICATION-LOG-MIB (RFC 3014)
CISCO-CDP-MIB	CISCO-NETSYNC-MIB	OSPF-MIB (RFC 1850)
CISCO-CEF-MIB	CISCO-OSPF-MIB (draft-ietf-ospf-mib-update-05)	OSPF-TRAP-MIB (RFC 1850)
CISCO-CLASS-BASED-QOS-MIB	CISCO-OSPF-TRAP-MIB (draft-ietf-ospf-mib-update-05)	PIM-MIB (RFC 2934)
CISCO-CONFIG-COPY-MIB	CISCO-PIM-MIB	RFC1213-MIB
CISCO-CONFIG-MAN-MIB	CISCO-PROCESS-MIB	RFC2982-MIB

Table 15 **Supported MIBs**

Supported MIBs		
CISCO-DATA-COLLECTION-MIB	CISCO-PRODUCTS-MIB	RMON-MIB (RFC 1757)
CISCO-EMBEDDED-EVENT-MGR-MIB	CISCO-PTP-MIB	RSVP-MIB
CISCO-ENHANCED-MEMPOOL-MIB	CISCO-RF-MIB	SNMP-COMMUNITY-MIB (RFC 2576)
CISCO-ENTITY-ALARM-MIB	CISCO-RTTMON-MIB	SNMP-FRAMEWORK-MIB (RFC 2571)
CISCO-ENTITY-EXT-MIB	CISCO-SONET-MIB	SNMP-MPD-MIB (RFC 2572)
CISCO-ENTITY-FRU-CONTROL-MIB	CISCO-SYSLOG-MIB	SNMP-NOTIFICATION-MIB (RFC 2573)
CISCO-ENTITY-SENSOR-MIB	DS1-MIB (RFC 2495)	SNMP-PROXY-MIB (RFC 2573)
CISCO-ENTITY-VENDORTYPE-OID-MIB	ENTITY-MIB (RFC 4133)	SNMP-TARGET-MIB (RFC 2573)
CISCO-FLASH-MIB	ENTITY-SENSOR-MIB (RFC 3433)	SNMP-USM-MIB (RFC 2574)
CISCO-FTP-CLIENT-MIB	ENTITY-STATE-MIB	SNMPv2-MIB (RFC 1907)
CISCO-IETF-ISIS-MIB	EVENT-MIB (RFC 2981)	SNMPv2-SMI
CISCO-IETF-PW-ATM-MIB	ETHERLIKE-MIB (RFC 3635)	SNMP-VIEW-BASED-ACM-MIB (RFC 2575)
CISCO-IETF-PW-ENET-MIB	IF-MIB (RFC 2863)	SONET-MIB
CISCO-IETF-PW-MIB	IGMP-STD-MIB (RFC 2933)	TCP-MIB (RFC 4022)
CISCO-IETF-PW-MPLS-MIB	IP-FORWARD-MIB	TUNNEL-MIB (RFC 4087)
CISCO-IETF-PW-TDM-MIB	IP-MIB (RFC 4293)	UDP-MIB (RFC 4113)
CISCO-IF-EXTENSION-MIB	IPROUTE-STD-MIB (RFC 2932)	CISCO-FRAME-RELAY-MIB
CISCO-IGMP-FILTER-MIB	MPLS-LDP-GENERIC-STD-MIB (RFC 3815)	IF-MIB

Table 16 summarizes the unverified and supported MIBs on the Cisco ASR 900 Router Series.

Table 16 **Unverified and Supported MIBs**

Unverified MIBs		
ATM-MIB	CISCO-IETF-DHCP-SERVER-EXT-MIB	EXPRESSION-MIB
CISCO-ATM-EXT-MIB		HC-ALARM-MIB
CISCO-ATM-IF-MIB	CISCO-IETF-PPVPN-MPLS-VPN-MIB	HC-RMON-MIB
CISCO-ATM-PVC-MIB	CISCO-IP-STAT-MIB	IEEE8021-CFM-MIB
CISCO-ATM-PVCTRAP-EXTN-MIB	CISCO-IPSLA-ETHERNET-MIB	IEEE8021-CFM-V2-MIB
CISCO-BCP-MIB	CISCO-L2-CONTROL-MIB	IEEE8023-LAG-MIB
CISCO-CALLHOME-MIB	CISCO-LAG-MIB	INT-SERV-GUARANTEED-MIB
CISCO-CIRCUIT-INTERFACE-MIB	CISCO-MAC-NOTIFICATION-MIB	INTEGRATED-SERVICES-MIB

Table 16 Unverified and Supported MIBs

Unverified MIBs		
CISCO-CONTEXT-MAPPING-MIB	CISCO-MEMORY-POOL-MIB	MPLS-L3VPN-STD-MIB (RFC 4382)
CISCO-EIGRP-MIB	CISCO-NHRP-EXT-MIB	MPLS-LDP-ATM-STD-MIB (RFC 3815)
CISCO-ERM-MIB	CISCO-NTP-MIB	MPLS-LDP-MIB
CISCO-ETHER-CFM-MIB	CISCO-PING-MIB	MPLS-TE-STD-MIB
CISCO-ETHERLIKE-EXT-MIB	CISCO-RESILIENT-ETHERNET-PROTOCOL-MIB	MPLS-VPN-MIB
CISCO-EVC-MIB	CISCO-RTTMON-ICMP-MIB	NHRP-MIB
CISCO-HSRP-EXT-MIB	CISCO-RTTMON-IP-EXT-MIB	RFC2006-MIB (MIP)
CISCO-HSRP-MIB	CISCO-RTTMON-RTP-MIB	RMON2-MIB (RFC 2021)
CISCO-IETF-ATM2-PVCTRAP-MIB	CISCO-SNMP-TARGET-EXT-MIB	SMON-MIB
CISCO-IETF-ATM2-PVCTRAP-MIB-EXTN	CISCO-TCP-MIB	VRRP-MIB
CISCO-IETF-BFD-MIB	CISCO-VRF-MIB	
CISCO-IETF-DHCP-SERVER-MIB	ETHER-WIS (RFC 3637)	

MIB Documentation

The following resources provide more detail about MIBs on the Cisco ASR 900 Router Series:

- Cisco ASR 900 Router Series MIB Guide—For information about the Cisco ASR 903 Series Router product implementation of the MIB protocol, see *Cisco ASR 903 Series Aggregation Services Router MIB Specifications Guide* at the following location:

http://www.cisco.com/en/US/docs/wireless/asr_900/mib/guide/asr903mib.html

- MIB Locator—To locate and download MIBs for selected platforms, Cisco IOS and Cisco IOS XE releases, and feature sets, use Cisco MIB Locator found at the following location:

<http://tools.cisco.com/ITDIT/MIBS/servlet/index>

To access Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank e-mail to cco-locksmith@cisco.com. An automatic check will verify that your e-mail address is registered with Cisco.com. If the check is successful, account details with a new random password will be e-mailed to you. Qualified users can establish an account on Cisco.com by following the directions found at the following location:

<http://tools.cisco.com/RPF/register/register.do>

Open Source License Notices

For a listing of the license notices for open source software used in Cisco IOS XE 3S Releases, see the documents accessible from the License Information page at the following location:

http://www.cisco.com/en/US/products/ps11174/products_licensing_information_listing.html

Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2011-2016 Cisco Systems, Inc. All rights reserved.



New Features in Cisco IOS XE 3.6S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.6S.



Note

Cisco IOS XE 3.6S inherits all supported features from Cisco IOS Release 3.5, which is not described in this document. For more information about Cisco IOS Release 3.5, see the [Release Notes for Cisco IOS XE Release 3S](#).

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.6\(2\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.6\(1\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.6S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.6\(2\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.6\(1\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.6S, page 4](#)

New Hardware Features in Cisco IOS XE Release 3.6(2)S

The IOS XE 3.6(2)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.6(1)S

The IOS XE 3.6(1)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.6S

The IOS XE 3.6(0)S Release for the Cisco ASR 903 Router introduces support for the following hardware features:

- New SFP modules—This release introduces support for the following SFP modules:
 - 1000M SFP-DWDM-SFP

- 1000M SFP-CWDM
 - 1000M SFP - GLC-ZX-SMD
 - 1000M SFP - GLC-SX-MMD
 - 1000M SFP - GLC-LH-SMD
 - ONS-SI-155-SR-MM
 - ONS-SI-155-I1
 - ONS-SI-155-L1
 - ONS-SI-155-L2
- 4-Port OC3/STM-1 or 1-Port OC12/STM-4 Interface Module—This release introduces support for the A900-IMA4OS interface module. This combo module supports one of four modes: 4xOC3, 4xSTM-1, 1xOC12, and 1xSTM-4. The module supports SDH framing and HDLC encapsulation.

**Note**

The A900-IMA4OS Interface Module requires a license for use. For more information about supported licenses, see [Software Licensing Overview, page 16](#).

**Note**

IOS XE Release 3.6 for the offers a limited set of software features for the A900-IMA4OS Interface Module. For more information, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html

New Software Features in Cisco IOS XE Release 3.6(2)S

The IOS XE 3.6(2)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.6(1)S

The following are the new software features introduced in Cisco IOS XE Release 3.6(1)S:

- OC-3 Interface Module Software Features—Release 3.6(1) introduces support for PPP and MLPPP the OC-3 interface module. For details about this feature, see:
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/OC_Ifc_Module.html
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/pseudowire.html
 - <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/atm/configuration/xe-3s/asr903/atm-xe-3s-asr903-book.html>
 - http://www.cisco.com/en/US/docs/ios/dial/configuration/guide/dia_media-ind_multi_ppp.html
 - http://www.cisco.com/en/US/docs/ios/dial/configuration/guide/dia_async_slip_ppp.html

- PPP MRRU Negotiation Configuration—Introduces support for the **ppp multilink mrru** command, which allows you to specify a Maximum-Receive-Reconstructed-Unit (MRRU) value on MLP interfaces and member links after a change in the MTU value on the interface. For details about this feature, see http://www.cisco.com/en/US/docs/ios/dial/configuration/guide/dia_pppmlp_mrru_neg.html.
- ACFC and PFC Support on Multilink Interfaces—Using the Address and Control Field Compression (ACFC) and PPP Protocol Field Compression (PFC) Support on Multilink Interfaces feature, you can control the negotiation and application of the Link Control Protocol (LCP) configuration options for ACFC and PFC.

This release introduces support for ACFC and PFC support on serial interfaces on the T1/E1 and optical interface modules. This feature includes support for the following commands:

- **ppp acfc local {request | forbid}**
- **ppp acfc remote {apply | reject | ignore}**
- **ppp pfc local {request | forbid}**
- **ppp pfc remote {apply | reject | ignore}**

For more information about configuring ACFC and PFC, see the following documents

- http://www.cisco.com/en/US/partner/docs/interfaces_modules/shared_port_adapters/configuration/7600series/76cfsip.html#wp1372108
- http://www.cisco.com/en/US/partner/docs/routers/7600/install_config/flexwan_config/features.html#wp256581
- [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- Egress QoS policies on main physical interface for port shaping + H-policies on EFP—Previous releases did not support QoS policies on interfaces configured with an Ethernet Flow Point (EFP) or port-channel member links with EFPs. This release introduces support for hierarchical QoS policies on EFP interfaces. For more information about how to configure QoS on EFP interfaces, see
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
 - [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#).
- Switch Port Analyzer—Release 3.6.1 introduces support for Switch Port Analyzer (SPAN) on physical interfaces. The following commands are supported:
 - **monitor session {session_number} {source {interface slot/port}} [, | - | rx | tx | both]**
 - **monitor session {session_number} {destination {interface type/num}} [, | -]**

For more information about SPAN, see

[Layer 2 Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

- Support for MPLS Labels with PTP traffic- This release introduces support for MPLS labels with PTP Delay-Request packets. The following encapsulation types are supported:
 - VPN
 - BGP IPv4
 - LDP
 - FRR

The router adds time stamps to MPLS-encapsulated PTP packets by default.

For more information see,

- [MPLS Label Distribution Protocol Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)
- [MPLS Traffic Engineering Path Link and Node Protection Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)
- Reverse Path Forwarding failure handling—This release introduces support for the **platform multicast rpf_fail_handling enable** command. The Cisco ASR 903 Router hardware does *not* handle RPF fail packets default; you can use this command to enable RPF fail packets handling.

New Software Features in Cisco IOS XE Release 3.6S

The following are the new software features introduced in Cisco IOS XE Release 3.6S:



Note

Many of the features supported on the Cisco ASR 903 Router require a license for use. For more information about supported licenses, see [Software Licensing Overview, page 16](#).

- Any Transport over MPLS (AToM)—ATM AAL5 over MPLS (AAL5oMPLS)—The AAL5 Transport over MPLS feature provides an ATM permanent virtual circuit (PVC) transport service for transporting AAL5 PDUs across an IP/MPLS backbone with rate-limit policing and configurable PVC priority value. A dynamic MPLS tunnel is configured to enable label imposition and disposition of encapsulated ATM PDUs transported between two edge routers having a Label Distribution Protocol (LDP) neighbor relationship. For details about this feature, see:
 - [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- BFD IPv6 Encapsulation—This feature introduces support for IPv6 addresses with the BFD protocol. For details about this feature, see
 - [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- BGP PIC Edge for IP/MPLS—This feature introduces support for BGP PIC Edge for IP/MPLS for sub-second convergence for IP and MPLS-VPN. For details about this feature, see:
 - [IP Routing: BGP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- CFM over EFP interface with xconnect—This feature provides support for IEEE 802.1ag draft 8.1-compliant CFM functionality on pseudowire & VFI interfaces. For details about this feature, see:
 - [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
 - http://www.cisco.com/en/US/docs/routers/7600/install_config/ES40_config_guide/es40_chap4.html
- CFM on Port-Channel Interfaces—This feature provides support for IEEE 802.1ag (CFM) on port-channel interfaces for end-to-end connectivity fault management on Ethernet networks. For details about this feature, see:
 - <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipsla/configuration/xe-3s/asr903/sla-xe-3s-asr903-book.html>
 - <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/ce-xe-3s-asr903-book/ce-cfm-fm.html>

- Class-based QoS MIB—This feature introduces support for the class-based QoS MIB. For details about this feature, see http://www.cisco.com/en/US/docs/wireless/asr_900/mib/guide/asr903mib.html
- Egress QoS Marking—This feature introduces support for QoS marking on egress interfaces. For details about this feature, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- Egress QoS Policing—This feature introduces support for QoS policing on egress interfaces. For details about this feature, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- E-OAM-CFM CCM Hardware Offload—The router automatically offloads processing of Continuity Check (CC) messages if the CC interval is less than 1 second.
- H-VPLS N-PE Redundancy for MPLS Access—This feature allows user provider (U-PE) devices to be dual-homed to network provider edge (N-PE) devices in a loop-free topology with MPLS as the access/aggregation domain. For details about this feature, see:
 - http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_12_vpns/configuration/xs/asr903/mp-12-vpns-xe-3s-asr903-book/mp-hvpls-npe-red-mpls-access.html
- IPv6 Quality of Service Classification—This feature allows you to define traffic classes, create and configure traffic policies (policy maps), and attach those traffic policies to interfaces. The Cisco ASR 903 Router supports classification of IPv6 traffic based on DSCP or Precedence values on ingress and egress interfaces. For details about this feature, see
 - http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_classn/configuration/xs/asr903/qos-classn-xe-3s-asr903-book.html
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- IPv6 Quality of Service Marking—This feature introduces support for marking IPv6 traffic with DSCP or Precedence values. IPv6 QoS is supported on ingress and egress interfaces. For details about this feature, see
 - http://www.cisco.com/en/US/docs/ios/ios_xe/ipv6/configuration/guide/ip6-qos_xe.html
 - <http://www.cisco.com/en/US/docs/ios/ipv6/configuration/guide/ip6-qos.html>
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- ISIS IPv4 Loop Free Alternate Fast ReRoute (LFA FRR) for VPLS Core—IPFRR (IP Fast ReRoute) is a set of technologies used in order to rapidly converge traffic flows around link and/or node failures. For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_pi/configuration/xs/asr903/iri-xe-3s-asr903-book/iri-lfa-frr.html
- ITU-T G.8032 Ethernet Ring Protection Switching—This feature implements protection switching mechanisms for Ethernet layer ring topologies. This feature uses the G.8032 Ethernet Ring Protection (ERP) protocol, defined in ITU-T G.8032, to provide protection for Ethernet traffic in a ring topology, while ensuring that there are no loops within the ring at the Ethernet layer. The loops are prevented by blocking either a pre-determined link or a failed link. For details about this feature, see <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/lanswitch/configuration/xs/asr903/lanswitch-ethernet-channel-xe-3s-asr903-book/lsw-cfg-rep.html>

- L2 ACL on Service Instance—This is a security feature which customers can apply to an EVC interface to filter packets based on their MAC address. For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/b_layer2_AS903/ly2-acl-evc.html
- L2PT - Layer 2 Protocol Tunneling on Trunk Ports—Layer 2 protocol tunneling makes control protocol PDUs such as STP, CDP, and VTP, transparent to the service provider cloud when passing traffic through trunk ports. For details about this feature, see http://www.cisco.com/en/US/docs/ios-xml/ios/wan_lserv/configuration/xe-3s/wan-lserv-xe-3s-book.html
- MLPPP - Multilink PPP—Multilink PPP (also referred to as MP, MPPP, MLP, or Multilink) provides a method for spreading traffic across multiple physical WAN links and is described in RFC1990. For details about this feature, see:
 - http://www.cisco.com/en/US/docs/ios/dial/configuration/guide/dia_media-ind_multi_ppp.html
 - http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_basic/configuration/xe-3s/asr903/mp-basic-xe-3s-asr903-book.html



Note Limitations apply when configuring MLPPP.

- MPLS Traffic Engineering (TE) - Fast Reroute (FRR) Link and Node Protection—This feature introduces support for MPLS Traffic Engineering (TE) - Fast Reroute (FRR) Link and Node Protection. For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_te_path_protect/configuration/xe-3s/asr903/mp-te-path-protect-xe-3s-asr903-book.html
- Multiple Matching Commands—This feature introduces support for multiple **match** or **match-any** commands in a given QoS class-map. For details about this feature, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- Port-Shaper and LLQ in the presence of EFPs—This feature allows you to create a QoS policy to shape traffic across all EFPs on a given physical port. —For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_plcshp/configuration/xe-3s/asr903/qos-plcshp-xe-3s-asr903-book/qos-plcshp-ehqos-pshape.html
- PPP—This feature introduces support for PPP, which provides a method for transmitting datagrams over serial point-to-point links. For details about this feature, see http://www.cisco.com/en/US/docs/ios/dial/configuration/guide/dia_async_slip_ppp.html
- Static Route Support for BFD over IPv6—This feature introduces support for static routes for BFD using IPv6 addressing. For details about this feature, see:
 - http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_bfd/configuration/xe-3s/asr903/irb-xe-3s-asr903-book/ip6-bfd-static-xe.html
 - <http://www.cisco.com/en/US/docs/ios/ipv6/configuration/guide/ip6-bfd.html>
- Static VPLS over MPLS-TP—This feature introduces support for static VPLS over MPLS-TP. For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/mp_basic/configuration/xe-3s/asr903/mp-basic-xe-3s-asr903-book.html
- STM-1 support—This feature adds support for STM1 mode on Cisco ASR 903 Router in concatenated and channelized mode to the DS1 level. For details about this feature, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html

- Support for Low Latency Queuing on Multiple EFPs—This feature allows you to apply a QoS policy for Low Latency Queuing to multiple EFP interfaces. For details about this feature, see http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_plcshp/configuration/xs-asr903/qos-plcshp-xe-3s-asr903-book/qos-plcshp-ehqos-pshape.html
- Support for Weighted Random Early Detection—This feature introduces support for Weighted Random Early Detection (WRED) for congestion avoidance on egress interfaces. For details about this feature, see:
 - http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_conavd/configuration/xs-asr903/qos-con-avd-xe-3s-asr903-book.html
 - http://www.cisco.com/en/US/products/hw/routers/ps133/products_configuration_guide_book09186a00805b9497.html
 - http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html
- Y.1731 Performance Monitoring—Y.1731-PM provides a standards-based Ethernet performance monitoring function, which encompasses measurement of Ethernet frame delay, frame delay variation, frame loss, and frame throughput as outlined in the ITU-T Y-1731 specification and interpreted by the Metro Ethernet Forum (MEF) standards group. For details about this feature, see:
 - <http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/xs-asr903/ce-xe-3s-asr903-book/ce-perf-mon.html>



New Features in Cisco IOS XE 3.7S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.7S.



Note

Cisco IOS XE 3.7S inherits all supported features from Cisco IOS Release 3.5, which is not described in this document. For more information about Cisco IOS Release 3.5, see the [Release Notes for Cisco IOS XE Release 3S](#).

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.7\(5\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.7\(4\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.7\(3\)S, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.7\(2\)S, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.7\(1\)aS, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.7\(0\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.7\(5\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.7\(4\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.7\(3\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.7\(2\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.7\(1\)aS, page 3](#)
- [New Software Features in Cisco IOS XE Release 3.7\(0\)S, page 3](#)

New Hardware Features in Cisco IOS XE Release 3.7(5)S

The IOS XE 3.7(5)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.7(4)S

The IOS XE 3.7(4)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.7(3)S

The IOS XE 3.7(3)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.7(2)S

The IOS XE 3.7(2)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.7(1)aS

The IOS XE 3.7(1)aS Release for the Cisco ASR 903 Router introduces the following hardware features:

- AC Power Supply—Release 3.7(1)aS3.7(1)aS introduces support for the AC power supply. For more information about the AC power supply, see the [Cisco ASR 903 Hardware Guide](#).

New Hardware Features in Cisco IOS XE Release 3.7(0)S

Release 3.7 introduces support for the ONS-SC-155-EL SFP module.

New Software Features in Cisco IOS XE Release 3.7(5)S

The IOS XE 3.7(5)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.7(4)S

The IOS XE 3.7(4)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.7(3)S

The IOS XE 3.7(3)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.7(2)S

The IOS XE 3.7(2)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.7(1)aS

Release 3.7(1) introduces support for QoS policies on egress MLPPP interfaces on the T1/E1 interface module. For more information about how to configure QoS policies on MLPPP interfaces, see the *Cisco ASR 903 Router Chassis Configuration Guide, Release 3.7*.

New Software Features in Cisco IOS XE Release 3.7(0)S

The following are the new software features introduced in Cisco IOS XE Release 3.7(0)S:

- BGP Graceful Shutdown—The BGP Graceful Shutdown feature reduces or eliminates the loss of traffic along a link being shut down for maintenance. Routers always have a valid route available during the convergence process. This feature is used primarily for maintenance on a link between a PE and CE. For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_bgp/configuration/xs-3s/irg-grace-shut.html.
- Channelization Support—This release introduces support for channelization on the OC-3 interface module using the **channel-group** command. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>
- DHCP Option 82—In residential, metropolitan Ethernet-access environments, DHCP can centrally manage the IP address assignments for a large number of subscribers. When the DHCP option-82 feature is enabled on a switch, a subscriber device is identified by the switch port through which it connects to the network in addition to its MAC address. Multiple hosts on the subscriber LAN can be connected to the same port on the access switch and are uniquely identified. For more information, see
 - IP Addressing: [DHCP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- DHCP Snooping—DHCP snooping is a DHCP security feature that provides network security by filtering untrusted DHCP messages and by building and maintaining a DHCP snooping binding database, also referred to as a DHCP snooping binding table. DHCP snooping acts like a firewall between untrusted hosts and DHCP servers. You use DHCP snooping to differentiate between untrusted interfaces connected to the end user and trusted interfaces connected to the DHCP server or another switch. For more information, see
 - IP Addressing: [DHCP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- Dynamic ARP Inspection—Dynamic ARP inspection determines the validity of an ARP packet based on valid IP-to-MAC address bindings stored in a trusted database, the DHCP snooping binding database. This database is built by DHCP snooping if DHCP snooping is enabled on the bridge-domains and on the router. If the ARP packet is received on a trusted interface, the router forwards the packet without any checks. On untrusted interfaces, the switch forwards the packet only if it is valid. For more information, see
 - IP Addressing: [DHCP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- E2E Transparent Clocking—A transparent clock is a network device such as a switch that calculates the time it requires to forward traffic and updates the PTP time correction field to account for the delay, making the device transparent in terms of timing calculations. The transparent clock ports have no state because the transparent clock does not need to synchronize to the grandmaster clock. An end-to-end transparent clock measures the residence time of a PTP message and accumulates the

times in the correction field of the PTP message or an follow-up message. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>

- GOLD—Generic Online Diagnostic (GOLD) is a health monitoring feature implemented on the Cisco ASR 903 Router. The GOLD functionality is developed to provide online diagnostic capabilities that run at bootup, in the background on a periodic basis, or based on demand from the CLI. For more information, see http://www.cisco.com/en/US/docs/wireless/asr_900/feature/guides/GOLD.html.
- Hot Standby Pseudowire Support—The Hot Standby Pseudowire feature provides faster failover of a backup pseudowire and reduced traffic loss during failover by setting the backup pseudowire to a hot standby state, such that it can immediately take over if the primary pseudowire fails. This feature is supported for Ethernet only; TDM and ATM interfaces are not supported. For more information, see:
 - http://www.cisco.com/en/US/docs/routers/7600/install_config/ES40_config_guide/es40_chap6.html.
 - http://www.cisco.com/en/US/docs/ios/12_0s/feature/guide/fspseudo.html
 - http://www.cisco.com/en/US/partner/docs/ios/mps/configuration/guide/mp_hspw_for_atm.html#wp1054150
 - [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- Hybrid Clocking Support—Hybrid clocking mode that uses clock frequency obtained from the synchronous Ethernet port while using phase (ToD or 1PPS) obtained using PTP. The combination of multiple time and phase sources for the same master clock improves performance over using PTP alone. The router can act as a hybrid clock in both master ordinary clock and slave ordinary clock. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>
- IPv6 ACL—IPv6 Access Control Lists (ACLs) determine what traffic is blocked and what traffic is forwarded at device interfaces. ACLs allow filtering based on source and destination addresses, inbound and outbound to a specific interface. For more information, see
 - [Security Configuration Guide: Access Control Lists, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)
- Layer 2 QoS for ATM—This feature introduces support for support cbr and vbr on ATM interfaces. For more information, see http://www.cisco.com/en/US/partner/docs/ios-xml/ios/mp_12_vpns/configuration/xe-3s/qos-atm-vp-support-xe.html
- Link Path Through—This feature enables a local EoMPLS PE router to detect a failure in the path between the remote PE and CE routers. The local PE router propagates the failure to the local CE router such that it brings down the pseudowire connection and can more quickly reestablish the connection when the remote CE-PE connection is restored. This feature is enabled automatically and does not introduce any new CLI commands.
- MAC Address Security for EVC Bridge-Domain—MAC address security for EVCs. Provides the capability to control and filter the MAC address learning behavior at the granularity of a single EVC service instance. For more information, see:
 - [Layer 2 Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
 - <http://www.cisco.com/en/US/docs/ios-xml/ios/cether/configuration/xe-3s/ce-mac-addlmt-bdsin.html>

- **MAC Limiting**—Mac address limiting per bridge-domain restricts the number of MAC addresses that the router learns in bridge-domain on an EFP, pseudowire or switch port. For more information, see
 - [Layer 2 Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- **MPLS VPN**—The MPLS VPN Inter-AS with ASBRs Exchanging VPN-IPv4 Addresses feature allows a Multiprotocol Label Switching (MPLS) Virtual Private Network (VPN) to span service providers and autonomous systems. For more information, see
 - [MPLS Layer 3 VPNs Inter-AS and CSC Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#).
- **Multicast Static MAC Addresses**—Static MAC addresses allow you to enable multicast at the layer 2 level. You can use multicast static MAC addresses to forward multicast packets to specific EFPs on a network. For more information, see
 - [Layer 2 Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- **Multi-Level Priority Queues (MPQ)**—This feature allows you to configure multiple priority queues for multiple traffic classes by specifying a different priority level for each of the traffic classes in a single service policy map. You can configure multiple service policy maps per router. Having multiple priority queues enables the router to place delay-sensitive traffic (for example, voice) on the outbound link before delay-insensitive traffic. As a result, high-priority traffic receives the lowest latency possible on the router. For more information, see:
 - http://www.cisco.com/en/US/docs/ios-xml/ios/qos_conmgt/configuration/xe-3s/asr903/qos-conmgt-multilevel-pq.html
 - http://www.cisco.com/en/US/docs/ios-xml/ios/qos_conmgt/configuration/xe-3s/qos-conmgt-multilevel-pq.html
- **N:1 PVC mapping to PWE with non-unique VPI**—This feature allows you to map one or more ATM permanent virtual circuits (PVCs) to a single pseudowire. For more information, see
 - [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#).
- **Onboard Failure Logging**—The Onboard Failure Logging (OBFL) feature collects data such as operating temperatures, hardware uptime, interrupts, and other important events and messages from system hardware installed in a Cisco router or switch. The data is stored in nonvolatile memory and helps technical personnel diagnose hardware problems. For more information, see
 - [Network Management Systems Configuration Guide, Cisco IOS XE Release \(Cisco ASR 900 Series\)](#)
- **PTP Redundancy**—PTP redundancy allows a PTP slave clock to select the best master from multiple available master clocks based on clock quality and availability. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>.
- **Time of Day Selection**—You can use the time of day (ToD) and 1PPS ports on the Cisco ASR 903 Series Router to exchange ToD clocking. In master mode, the router can receive time of day (ToD) clocking from an external GPS unit; the router requires a ToD, 1PPS, and 10Mhz connection to the GPS unit. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>



New Features in Cisco IOS XE 3.8S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.8S.

This chapter includes the following sections:

- [New HardwareFeatures in Cisco IOS XE Release 3.8\(2\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.8\(1\)S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.8\(0\)S, page 1](#)
- [New SoftwareFeatures in Cisco IOS XE Release 3.8\(2\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.8\(1\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.8\(0\)S, page 2](#)

New HardwareFeatures in Cisco IOS XE Release 3.8(2)S

The IOS XE 3.8(2)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.8(1)S

The IOS XE 3.8(1)S Release for the Cisco ASR 903 Router does not introduce any new hardware features.

New Hardware Features in Cisco IOS XE Release 3.8(0)S

The IOS XE 3.8(0)S Release for the Cisco ASR 903 Router introduces the following hardware features:

Release 3.8(0)S introduces support for the following SFPs:

- GLC-FE-100BX-U
- GLC-FE-100BX-D
- GLC-FE-100LX
- GLC-FE-100FX
- ONS-XC-10G-EP30.33

- XFP10GER-192IR-L
- XFP10GLR-192SR-L
- XFP-10GZR-OC192LR

For more information about how to configure these SFPs, see:

http://www.cisco.com/en/US/partner/docs/interfaces_modules/transceiver_modules/installation/note/OL_24246.html

http://www.cisco.com/en/US/partner/products/hw/modules/ps5455/tsd_products_support_series_home.html

New Software Features in Cisco IOS XE Release 3.8(2)S

The IOS XE 3.8(2)S Release for the Cisco ASR 903 Router does not introduce any new software features.

New Software Features in Cisco IOS XE Release 3.8(1)S

Release 3.8(1) introduces support for the following software features:

- uRPF Loose Mode—This release introduces support for Unicast Reverse Path Forwarding (uRPF) Loose mode. For more information about this feature, see http://www.cisco.com/en/US/docs/ios-xml/ios/sec_data_urpf/configuration/xe-3s/sec-unicast-rpf-loose-mode.html

New Software Features in Cisco IOS XE Release 3.8(0)S

Release 3.8(0) introduces support for the following software features:

- Automatic Protection Switching—This release introduces support for Automatic protection switching (APS) for link failure protection on SONET networks. For more information, see
 - [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- ATM IMA on OC-3 Interfaces—This release introduces support for ATM IMA on the OC-3 interface module. For more information about this feature, see
 - [Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8.](#)
- BFD Support on TDM interfaces—Release 3.8 introduces support for BFD on TDM interfaces. This feature does not introduce any new CLI. For more information, see
 - [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
 - [Cisco ASR 900 Router Series Configuration Guide](#)
- BFD Support for HSRP—This release extends Bidirectional Forwarding Detection support in order to send failure notifications using the Hot Standby Router Protocol (HSRP). For more information about this feature, see http://www.cisco.com/en/US/products/ps11610/products_installation_and_configuration_guides_list.html
 - [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

- Cisco ASR 900 Router Series Configuration Guide
- BFD Timer Improvements—Release 3.8 introduces support for 3.3ms timers for offloaded IPv4 BFD traffic.
 - IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)
- BGP PIC—This release introduces support for BGP Prefix-Independent Convergence (PIC). This feature improves BGP convergence after a network failure. This convergence is applicable to both core and edge failures and can be used in both IP and MPLS networks. The BGP PIC Edge for IP and MPLS-VPN feature creates and stores a backup/alternate path in the routing information base (RIB), forwarding information base (FIB), and Cisco Express Forwarding so that when a failure is detected, the backup/alternate path can immediately take over, thus enabling fast failover. For more information, see http://www.cisco.com/en/US/partner/docs/ios-xml/ios/iproute_bgp/configuration/xe-3s/asr903/irg-xe-3s-asr903-book.html
- VPLS BGP Signaling—This release introduces support for VPLS BGP Signaling. The two primary functions of the Virtual Private LAN Service (VPLS) control plane are autodiscovery and signaling. The VPLS BGP Signaling feature enables you to use BGP as both an autodiscovery and a signaling protocol for VPLS. For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_bgp/configuration/xe-3s/asr903/irg-vpls-bgp-sig.html
- E-LMI PE Support—This release introduces support for Ethernet Local Management Interface (LMI) at the Provider Edge (PE). For more information about this feature, see <http://www.cisco.com/en/US/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/ce-elmi-pe.html>
- IP SLA Y.1731 SLM Feature Enhancements—This release introduces support for IP SLA SLM enhancements as described in the Y.1731 standard. For more information about this feature, see http://www.cisco.com/en/US/docs/ios-xml/ios/ipsla/configuration/xe-3s/asr903/sla_y1731_demand.html
- IS-IS Support for BFD over IPv6—This release introduces support for BFD on IS-IS IPv6 connections. For more information about this feature, see
 - IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)
- LACP Min-Links—This release introduces support for Etherchannel Min-Links, a minimum threshold for the number of links in an Etherchannel before the it becomes active. For more information about this feature, see <http://www.cisco.com/en/US/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/ce-ieee-link-bndl-xe.html>
- Microwave Adaptive Bandwidth—This release introduces support for Microwave Adaptive Bandwidth with G.8032 and CFM. For more information about this feature, see <http://www.cisco.com/en/US/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/ce-cfm-adapt-bandwidth.html>
- MPLS on PoS Interfaces—Release 3.8 introduces support for MPLS on Packet over SONET (PoS) interfaces. For more information about this feature, see
 - Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8.
- MPLS-TP MIB—This release introduces support for the MPLS-TP MIB. For more information about using MIBs, see [MIB Support, page 1-22](#).
- MPLS-TP Pseudowire Support—This release introduces support for MPLS-TP on ATM and TDM pseudowires. For more information, see
 - Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8.

- http://www.cisco.com/en/US/docs/ios-xml/ios/mp_basic/configuration/xr-3s/mp-mpls-tp.html
- OC-3 MLPPP QoS Support—Release 3.8 introduces support for QoS policies on egress MLPPP interfaces on the optical interface module.
 - [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#)
- Multicast on T1/E1 and Optical Interfaces—Release 3.8 introduces support for multicast on T1/E1 and OC-3 interface modules. For more information about multicast, see
 - [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- Network Virtualization Service—This Release introduces support for the Satellite Network Virtualization (nV) service or the Satellite Switching System, which enables you to configure a topology in which satellite devices complement one or more Cisco ASR 9000 Series routers in order to collectively realize a single virtual switching system. In this system, the satellite switches act under the management control of the Cisco ASR 9000 Series Aggregation Services Routers. The complete configuration and management of the satellite chassis and features is performed through the control plane and management plane of the Cisco ASR 9000 Series Router. For more information about how to configure nV on the ASR 9000 and the satellite devices, see
 - http://www.cisco.com/en/US/partner/docs/routers/asr9000/software/asr9k_r4.2/interfaces/configuration/guide/hc42satl.html
 - [Network Virtualization Configuration Guide, Cisco IOS XE Release \(Cisco ASR 900 Series\)](#)
- Packet over SONET—This release introduces support for Packet over SONET (PoS) interfaces on the OC-3 interface module. For more information on how to configure PoS interfaces, see
 - [Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8](#).
- QoS on PoS Interfaces—Release 3.8 introduces support for QoS features on egress PoS interfaces using MLPPP bundles. For more information about configuring QoS on MLPPP interfaces, see
 - [Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8](#).
- QoS Features—Release 3.8 introduces support for the following QoS features:
 - **queue-limit percent** command— Allows you to specify the queue limit (size) for a class in as a percentage value.
 - Higher Queue Limit Size— Release 3.8 extends the maximum byte value *queue-limit-size* argument used with the **queue-limit** command. The previous maximum value was 491520 bytes; the new value is 2 MB.
 - Release 3.8 enhances the **show policy-map interface** command to display the default queue-limit.

For more information about the Release 3.8 QoS features, see

- [Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8](#).
- SONET Mode—This release introduces support for SONET mode on the OC-3 interface module. For more information on how to configure PoS interfaces, see the *Cisco ASR 903 Chassis Configuration Guide, Release 3.8*.
- Synthetic Frame Loss Measurement—This release introduces support for Synthetic Frame Loss Measurement for Ethernet OAM. For more information about this feature, see http://www.cisco.com/en/US/docs/ios-xml/ios/ipsla/configuration/xr-3s/asr903/sla_mether3_y1731.html
- TCP path MTU Support—This release introduces support for BGP TCP Path MTU Discovery. For more information about this feature, see http://www.cisco.com/en/US/docs/ios/iproute_bgp/configuration/guide/irg_neighbor.html

- Telecom Profile Support—Release 3.8 introduces support for telecom profiles, which allow you to configure a network clock to use the G.8265.1 recommendations for establishing PTP sessions, determining the best master clock, handling SSM, and mapping PTP classes. For information about how to configure telecom profiles, see
 - [Cisco ASR 903 Router Chassis Configuration Guide, Release 3.8](#).
- Trunk EFPs on Port-Channel Interfaces—This release adds support for trunk EFPs on port-channel interfaces, as shown in the following configuration:

```
!  
interface port-channel 4  
  service instance 1 ethernet  
    encapsulation untagged  
    l2protocol peer lacp  
    bridge-domain 1  
  !  
  service instance trunk 10 ethernet  
    encapsulation dot1q <>  
    rewrite ingress tag pop 1 symmetric  
    bridge-domain from-encapsulation  
  !
```

For more information about configuring EFP interfaces, see

- [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- Y.1731 enhancements—This release introduces support for Y.1731 on-demand and concurrent features. For more information about this feature, see <http://www.cisco.com/en/US/partner/docs/ios-xml/ios/cether/configuration/xe-3s/asr903/ce-y1731-perfmon.html>



New Features in Cisco IOS XE 3.9S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.9S and includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.9\(2\)S, page 5-1](#)
- [New Software Features in Cisco IOS XE Release 3.9\(2\)S, page 5-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.9\(1a\)S, page 5-1](#)
- [New Software Features in Cisco IOS XE Release 3.9\(1a\)S, page 5-2](#)
- [New Hardware Features in Cisco IOS XE Release 3.9\(0\)S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.9\(0\)S, page 3](#)

New Hardware Features in Cisco IOS XE Release 3.9(2)S

There are no new hardware features introduced in Cisco IOS XE Release 3.9(2)S.

New Software Features in Cisco IOS XE Release 3.9(2)S

There are no new software features introduced in Cisco IOS XE Release 3.9(2)S.

New Hardware Features in Cisco IOS XE Release 3.9(1a)S

Release 3.9(1) introduces support for the following hardware features:

- GLC-FE-100EX
- GLC-FE-100ZX
- SFP-GE-L
- SFP-GE-S
- SFP-GE-Z

New Software Features in Cisco IOS XE Release 3.9(1a)S

There are no new software features introduced in Cisco IOS XE Release 3.9(1)S.

New Hardware Features in Cisco IOS XE Release 3.9(0)S

Release 3.9(0) introduces support for the following hardware features:

- DWDM-XFP-30.33
- DWDM-XFP-31.12
- DWDM-XFP-31.90
- DWDM-XFP-32.68
- DWDM-XFP-34.25
- DWDM-XFP-35.04
- DWDM-XFP-35.82
- DWDM-XFP-36.61
- DWDM-XFP-38.19
- DWDM-XFP-38.98v
- DWDM-XFP-39.77
- DWDM-XFP-40.56
- DWDM-XFP-42.14
- DWDM-XFP-42.94
- DWDM-XFP-43.73
- DWDM-XFP-44.53
- DWDM-XFP-46.12
- DWDM-XFP-46.92
- DWDM-XFP-47.72
- DWDM-XFP-48.51
- DWDM-XFP-50.12
- DWDM-XFP-50.92
- DWDM-XFP-51.72v
- DWDM-XFP-52.52
- DWDM-XFP-54.13
- DWDM-XFP-54.94
- DWDM-XFP-55.75
- DWDM-XFP-56.55
- DWDM-XFP-58.17
- DWDM-XFP-58.98
- DWDM-XFP-59.79

- DWDM-XFP-60.61
- DWDM-XFP-C
- DWDM-XFP-1560.61

New Software Features in Cisco IOS XE Release 3.9(0)S

Release 3.9(0) introduces support for the following software features:

- BFD Echo Mode Hardware Offloading—BFD echo mode detects forwarding path failures on the remote system using echo packets; this release introduces support for hardware offloading of BFD echo mode packets for up to 255 sessions. The minimum supported timer value for offloaded BFD echo mode sessions is 3.3 ms. BFD echo offloading directs BFD echo packets to the high priority queue instead of the default queue. For more information about how to configure BFD, see
 - [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#).
- BGP Support for 4-byte ASN —This release introduces support for 4-byte autonomous system numbers in both the asplain format and the asdot format as described in RFC 5396. For more information, see
 - http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_bgp/configuration/xe-3s/asr903/irg-4byte-asn.html
- CFM Support for Trunk EFP—This release introduces support for CFM on trunk EFP interfaces. For more information about configuring EFPs, see
 - [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- CLNS Routing Support—This release introduces support for CLNS routing on the router.
 - [ISO CLNS Configuration Guide, Cisco IOS XE Release 3S](#)
- Enhanced Object Tracking—The Enhanced Object Tracking feature separates the tracking mechanism from Hot Standby Router Protocol (HSRP) in order to create a separate standalone tracking process. The tracking process is available to other IOS processes and allows tracking of other objects in addition to the interface line-protocol state. For more information, see
 - http://www.cisco.com/en/US/docs/ios/ios_xe/ipapp/configuration/guide/ipapp_eot_xe.html.
- Embedded Event Manager (EEM) 4.0—Embedded Event Manager (EEM) is a distributed and customized approach to event detection and recovery offered directly in a Cisco IOS device. EEM offers the ability to monitor events and take informational, corrective, or any desired EEM action when the monitored events occur or when a threshold is reached. For more information, see
 - <http://www.cisco.com/en/US/docs/ios-xml/ios/eem/configuration/xe-3s/eem-overview.html>.
- IP FRR/Remote LFA FRR with L2VPN—The Loop-Free Alternate (LFA) Fast Reroute (FRR) with Layer 2 Virtual Private Network (L2VPN) feature minimizes packet loss due to link or node failure. For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/mp_l2_vpns/configuration/xe-3s/asr903/mp-l2vpn-lfa-frr.html.
- IS-IS topology of 3000 nodes—This release extends IS-IS capacity to include support for 3000 nodes. For more information about configuring IS-IS routing, see
 - [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#).
- ISO OSI Routing—This release introduces support for ISO OSI routing.

- Link Layer Discovery Protocol—Link Layer Discovery Protocol (LLDP) is defined in the IEEE 802.1ab standard and allows a non-Cisco device to interact with a Cisco device that uses Cisco Discovery Protocol (CDP) for topology discovery. For more information, see
 - [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- L2VPN Protocol Support—This release introduces support for additional L2VPN protocols including L2TP and UDP. For more information, see
 - [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- Microwave Adaptive Bandwidth Modulation Enhancement—This release introduces support for Adaptive Bandwidth Modulation on G.8032 and E-OAM microwave connections, which allow Ethernet switches to optimize traffic forwarding rules based on microwave link capacity. For more information, see
 - [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- MPLS on MLPPP Interfaces—This release introduces support for MPLS on MLPPP interfaces. For more information about configuring MPLS, see
 - [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
 - <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.
- MPLS -TP Linear Protection/PSC support—Linear Protection on MPLS-TP based transport networks using the RFC 6378 standard. For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/mp_basic/configuration/xs/asr903/mp-basic-xe-3s-asr903-book.html.
- MVPN—The Multicast VPN (MVPN) feature provides the ability to support multicast over a Layer 3 Virtual Private Network (VPN). For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/ipmulti_mvnpn/configuration/xs/asr903/imc_cfg_mc_vpn.html.
- On-Demand Y.1731PM Probe Execution—This release introduces support for IPSLA Y1731 SLM enhancements that enable real-time Ethernet service troubleshooting for users without configuration privileges. This feature supports on-demand Synthetic Loss Measurement (SLM) operations that can be run by issuing a single command in privileged EXEC mode. For more information, see http://www.cisco.com/en/US/docs/ios-xml/ios/ipsla/configuration/xs/sla_y1731_demand.html
- OC-12 HDLC, PPP, and MLPPP support—This release introduces support for HDLC, PPP, and MLPPP on OC-12 interfaces. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.
- POS (Packet over SONET/SDH) on OC12 IM card—This release introduces support for Packet over SONET (POS) and SDH on OC-12 interfaces. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>
- PTP over Native Ethernet—This release introduces support for IEEE 1588-2008 Precision Time Protocol (PTP) on native Ethernet interfaces; this allows the router to deliver the PTP payload within an Ethernet packet. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.
- QoS Ingress Exp Bit Marking—This release introduces support for ingress QoS marking of MPLS Exp bits on TDM and ATM pseudowires. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.

- QoS Match on EFP—This release introduces support for QoS matching on EFP interfaces. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.
- QoS on OC-3 and OC-12 Interfaces—This release introduces support for two-level QoS policies on OC-3/OC-12 serial, MLPPP, and PoS interfaces. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.
- QoS Support for Ether Channels—This release introduces support for QoS policies on Etherchannel interfaces. For more information, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>.



New Features in Cisco IOS XE 3.10S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.10S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.10.5S, page 6-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.10.4S, page 6-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.10.2S, page 6-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.10.1S, page 6-2](#)
- [New Hardware Features in Cisco IOS XE Release 3.10S, page 6-3](#)
- [New Software Features in Cisco IOS XE Release 3.10.5S, page 6-4](#)
- [New Software Features in Cisco IOS XE Release 3.10.4S, page 6-4](#)
- [New Software Features in Cisco IOS XE Release 3.10.2S, page 6-4](#)
- [New Software Features in Cisco IOS XE Release 3.10.1S, page 6-4](#)
- [New Software Features in Cisco IOS XE Release 3.10S, page 6-4](#)

New Hardware Features in Cisco IOS XE Release 3.10.5S

There are no new hardware features introduced for Cisco IOS XE Release 3.10.5S.

New Hardware Features in Cisco IOS XE Release 3.10.4S

There are no new hardware features introduced for Cisco IOS XE Release 3.10.4S.

New Hardware Features in Cisco IOS XE Release 3.10.2S

There are no new hardware features introduced for Cisco IOS XE Release 3.10.2S.

New Hardware Features in Cisco IOS XE Release 3.10.1S

The IOS XE 3.10S Release for the Cisco ASR 903 Router introduces the following hardware features:

DC PEM Module (A900-PWR550-D-E)

The power supply provides 550 W output power for system 12 V power. The power supply is field replaceable, hot-swappable, and operates separately from the fan tray. The power supply contains a front panel with mounting screws, a handle for insertion and removal, and two status LEDs. No ON/OFF switch is provided.

The A900-PWR550-D-E DC PEM module has a T-shaped power input terminal connector. For information on DC PEM module specifications, see [Cisco ASR 903 router Overview](#). For information on installing the connector, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

Fan Tray (A903-FAN-E)

The A903-FAN-E is a fan tray containing twelve (40 x 40 x 20 mm) fans and provides sufficient capacity to maintain operation indefinitely in the event of an individual fan failure. For information on installing the fan tray, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

Dust Filter (A903-FAN-F)

The dust filter on the fan tray is a quadrafoam 45PPI filter which is 85 percent dust resistant. For information on installing the dust filter, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

Dummy Cover (A903-FAN-F-B)

A dummy cover (A903-FAN-F-B) secures the dust filter in the chassis. For installing the fan filter, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

Cable Bracket (A903-CAB-BRACKET)

The cable management bracket helps in routing the cables from the interface modules; therefore enabling a proper cable bending radius. For installing the bracket, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

Air Plenum

Air Plenum or air baffle assembly is used change the air flow pattern of the unit. When the router is installed with the plenum, the air flow pattern is changed from side-side to front-back. For information on ordering the air plenum, see [Installing the Cisco ASR 903 Series Aggregation Services Router](#).

New Hardware Features in Cisco IOS XE Release 3.10S

The IOS XE 3.10S Release for the Cisco ASR 903 Router introduces the following hardware features:

Serial Interface Module

IOS XE Release 3.10(0)S introduces support for the serial interface module, which is designed to provide a low-latency communication platform for legacy interfaces. Designed for utilities, the module is hardened to accommodate the wide operating temperature swings, EMI and surge spikes, and dust found in substation environments.

The combination of the Cisco ASR 903 Router and the serial interface module enables migration from TDM and serial networks to an IP-based network that can control latency and jitter across the network and enable multiple Smart Grid applications.

The Cisco ASR 903 Serial Interface Module supports the following standards:

- IEEE 1613 2009—IEEE Standard for Environmental and Testing Requirements for Communications Networking Devices in Electric Power Substations
- EC 61850-3—IEC standard specifying general requirements for substation automation systems (SAS) communications and related system requirements.
- EC 60870-2-1:1995—IEC standard for substation environmental conditions
- EC 60870-2-2:1996—IEC standard for substation environmental conditions
- EC 61000-6-5:2001—IEC standard defining immunity for power station and substation environments

For information on how to install the serial interface module, see the [Cisco ASR 903 Hardware Installation Guide](#).

For information on how to configure the serial interface module, see [Configuring Raw Socket Transport on the Cisco ASR 903 Router](#).

**Note**

We recommend the installation of the Metro IP Services and Metro Aggregation Services licenses with serial interface module. For more information about obtaining and installing licenses, see [Software Licensing Overview](#).

CWDM SFP

Cisco IOS XE Release 3.10S introduces support for the following SFPs on the 10 Gigabit Ethernet XFP Interface Module:

- ONS-XC-10G-EP
- ONS-XC-10G-1470
- ONS-XC-10G-1490
- ONS-XC-10G-1510
- ONS-XC-10G-1530
- ONS-XC-10G-1550
- ONS-XC-10G-1570

- ONS-XC-10G-1590
- ONS-XC-10G-1610

For more information about how to configure these SFPs, see:

http://www.cisco.com/en/US/partner/docs/interfaces_modules/transceiver_modules/installation/note/OL_24246.html

http://www.cisco.com/en/US/partner/products/hw/modules/ps5455/tsd_products_support_series_home.html

New Software Features in Cisco IOS XE Release 3.10.5S

There are no new software features introduced for Cisco IOS XE Release 3.10.5S.

New Software Features in Cisco IOS XE Release 3.10.4S

There are no new software features introduced for Cisco IOS XE Release 3.10.4S.

New Software Features in Cisco IOS XE Release 3.10.2S

There are no new software features introduced for Cisco IOS XE Release 3.10.2S.

New Software Features in Cisco IOS XE Release 3.10.1S

There are no new software features introduced for Cisco IOS XE Release 3.10.1S.

New Software Features in Cisco IOS XE Release 3.10S

The following features are introduced in Cisco IOS Release 3.10S.

- [Access Circuit Redundancy, page 6-5](#)
- [Access Switch Device Manager Template, page 6-5](#)
- [Auto-IP, page 6-5](#)
- [BFD Debug Enhancement, page 6-5](#)
- [Bidirectional Forwarding Detection Deterministic Hardware Offload, page 6-6](#)
- [Broadcast and Multicast Suppression, page 6-6](#)
- [IGMP Snooping, page 6-6](#)
- [Licensing the OC-3 and OC-12 Interface Modules, page 6-6](#)
- [Multichassis LACP, page 6-7](#)
- [Pseudowire Group Switchover, page 6-7](#)
- [Remote LFA FRR Protection for TDM and ATM Pseudowires, page 6-8](#)

- [Remote LFA FRR and Labeled BGP PIC FRR Integration](#), page 6-8
- [VPLS over Remote LFA](#), page 6-9

Access Circuit Redundancy

Access Circuit Redundancy (ACR) enables local switching for circuit emulation (CEM) interfaces by creating a virtual CEM-ACR interface. All configuration changes made on the virtual CEM-ACR interface are applied automatically on both the Working and Protect interfaces.

For more information see, [Configuring Access Circuit Redundancy on the Cisco ASR 903 Router](#).

Access Switch Device Manager Template

The Switch Device Manager (SDM) templates are used to optimize system resources in the router to support specific features, depending on how the router is used in the network. The SDM templates allocate Ternary Content Addressable Memory (TCAM) resources to support different features.



Note

SDM templates are supported only by the Metro Aggregation Services license.

For more information see, [Configuring Access Switch Device Manager Template on the Cisco ASR 903 Router](#).

Auto-IP

The Auto-IP feature addresses the problem of manually reconfiguring nodes during insertion, deletion, and movement of nodes within an auto-IP ring. The auto-IP feature automatically provides IP addresses to the node interfaces inserted into an auto-IP ring.

For more information, see [Auto-IP](#).

BFD Debug Enhancement

The Bidirectional Forwarding Detection (BFD) Debug Enhancement feature enhances the BFD debug messages and the show command output and enables logs and history for critical BFD events. This feature helps network engineers and operators to easily identify any issues with BFD sessions or events.

The following commands were introduced for this feature: monitor event-trace bfd, monitor event-trace bfd event, monitor event-trace bfd packet, and show monitor event-trace bfd.

For more information, refer to the

- [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)
- [IP Routing Protocol-Independent Commands A through R](#)
- [IP Routing Protocol-Independent Commands S through T](#)

Bidirectional Forwarding Detection Deterministic Hardware Offload

The Bidirectional Forwarding Detection (BFD) deterministic hardware offload feature allows you to define the BFD transmission timer value. Any BFD sessions below or equal to the set value are sent to hardware. For more information see

- [IP Routing: BFD Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Broadcast and Multicast Suppression

A traffic storm occurs when packets flood the LAN, creating excessive traffic and degrading network performance. The traffic broadcast and multicast suppression (or storm control) feature prevents LAN ports from being disrupted by a broadcast, multicast and unicast traffic storm on physical interfaces.

Storm control prevents traffic on a LAN from being disrupted by a broadcast, multicast, or unicast storm on a port. Storm control is applicable for physical interfaces and is used to restrict the unicast, broadcast and multicast ingress traffic on the Layer2 interfaces. The feature is disabled by default on the Cisco ASR 903 router. For more information see

- [Security Configuration Guide: Broadcast and Multicast Suppression, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)

IGMP Snooping

IP Multicast Internet Group Management Protocol (IGMP), which runs at Layer 3 on a multicast device, generates Layer 3 IGMP queries in subnets where the multicast traffic must be routed. IGMP (on a device) sends out periodic general IGMP queries.

IGMP Snooping is an Ethernet Virtual Circuit (EVC)-based feature set. When IGMP snooping is enabled on a bridge domain, the bridge domain interface responds at Layer 2 to the IGMP queries with only one IGMP join request per Layer 2 multicast group. Each bridge domain represents a Layer 2 broadcast domain. For more information see

- [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Licensing the OC-3 and OC-12 Interface Modules

The optical modules 4-Port OC3/STM-1 or 1-Port OC12/STM-4 delivers four active ports of OC-3 interface module (IM) or Synchronous Transport Module level 1 (STM-1) connectivity, or one active port of OC-12 IM or STM-4 connectivity, on the Cisco ASR 903 Router. Licensing is applicable to these ports on the interface modules.

The benefits of licensing these ports are:

- Facilitate the pay-as-you-grow model to enhance the ports by purchasing licenses as required.
- Provide the ability to shift license from one port to another.
- Provide the ability to release a license when the interface module is removed from a slot and reinstall the license when inserted again.
- Support for high availability and OIR of interface modules.

[Table 6-1](#) lists the license supported on the OC-3 and OC-12 interface modules.

Table 6-1 OC-3 and OC-12 Port Licenses

License Type	Description	Usability
1 OC3 port license	Single OC3/STM-1 port	STM-1 on OC-3 port
1 OC12 port license	Single OC12/STM-4 port	STM-1 on OC-3 port

For more information see, [Licensing the Cisco ASR 900 Series Routers](#).

Multichassis LACP

Cisco's Multichassis EtherChannel (MCEC) solution addresses the need for interchassis redundancy mechanisms, where a carrier wants to "dual home" a device to two upstream points of attachment (PoAs) for redundancy. Some carriers either cannot or will not run loop prevention control protocols in their access networks, making an alternative redundancy scheme necessary. MCEC addresses this issue with enhancements to the 802.3ad Link Aggregation Control Protocol (LACP) implementation. These enhancements are provided in the Multichassis LACP (mLACP) feature. For more information, see

- [Ethernet Channel Configuration Guide IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Pseudowire Group Switchover

Currently, pseudowire switchovers to the backup pseudowires occur one by one from IOS to platform dataplane and can take up to four seconds for 1000 pseudowires. The group switchover feature reduces this switchover time by efficiently grouping status messages in both Label Distribution Protocol (LDP) and internal Inter-Process Communications (IPCs).



Note

The Pseudowire Group Switchover feature is enabled by default and cannot be disabled.

For more information, see

- [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#)

Raw Socket

Raw Socket Transport is a method for transporting serial data through an IP network. Raw Socket transports Supervisory Control and Data Acquisition (SCADA) data from Remote Terminal Units (RTUs). This method is an alternative to the Block Serial Tunnel (BSTUN) protocol. Raw Socket supports point-to-point and point-to-multipoint connections. For instructions on how to configure Raw Socket, see [Configuring Raw Socket Transport on the Cisco ASR 903 Router](#).

Raw Socket is supported on the serial interface module. For instructions on how to install the serial interface module, see the [Cisco ASR 903 Hardware Installation Guide](#).

For information on how to configure the serial interface module, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

**Note**

We recommend the installation of the Metro IP Services and Metro Aggregation Services licenses with serial interface module. For more information about obtaining and installing licenses, see [Software Licensing Overview](#).

Hardware Limitations

Serial Interface Module Limitations—The following limitations apply to the serial interface module:

- A maximum of 2 serial interface modules are supported on the Cisco ASR 903 Router.
- The serial interface module hardware supports a 230.4 Kbps traffic rate in asynchronous mode. The actual speed is dependent on cable quality and length. The serial interface module hardware supports an 8 Mbps traffic rate in synchronous mode. The actual speed is dependent on cable quality and length.

Software Limitations

Raw Socket limitations—The following software limitations apply to the serial interface module:

- Raw Socket encapsulation is supported on up to 28 serial ports.
- Asynchronous EIA/TIA-232 serial traffic is supported with DB-25, DB-9, and RJ-45 connectors.
- The X.21, V.35, RS-485, EIA-449, EIA-530, and IRIG-B standards are not currently supported by software.
- Synchronous traffic is not currently supported.

Remote LFA FRR Protection for TDM and ATM Pseudowires

Starting with Cisco IOS XE Release 3.10S, the Loop-Free Alternate (LFA) Fast Reroute (FRR) feature is supported for Time-division multiplexing (TDM) pseudowires.

- Circuit Emulation Service over Packet Switched Network (CESoPSN) over MPLS, and Structure-Agnostic Time Division Multiplexing over Packet (SAToP) over MPLS networks for T1, E1, SDH and SONET framing is supported.
- Inverse Multiplexing over ATM (IMA) over MPLS; PVC and PVC sessions are supported for the ATM (IMA).

For more information see, [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Remote LFA FRR and Labeled BGP PIC FRR Integration

Starting with Cisco IOS XE Release 3.10S, Both the Labeled Border Gateway Protocol (BGP) Prefix-Independent Convergence (PIC) feature and the Loop-Free Alternate (LFA) Fast Reroute (FRR) feature can be configured together on the Cisco ASR 903 router.

For more information see, [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

VPLS over Remote LFA

Starting with Cisco IOS XE Release 3.10, Virtual Private LAN Services (VPLS) is supported on the Cisco ASR 903 router.

For more information see, [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).



New Features in Cisco IOS XE 3.11S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.11S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.11.1S, page 7-1](#)
- [New Software Features in Cisco IOS XE Release 3.11.1S, page 7-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.11S, page 7-1](#)
- [New Software Features in Cisco IOS XE Release 3.11S, page 7-1](#)

New Hardware Features in Cisco IOS XE Release 3.11.1S

There are no new hardware features for Cisco IOS XE Release 3.11.1 S.

New Software Features in Cisco IOS XE Release 3.11.1S

There are no new hardware features for Cisco IOS XE Release 3.11.1 S.

New Hardware Features in Cisco IOS XE Release 3.11S

There are no new hardware features for Cisco IOS XE Release 3.11 S.

New Software Features in Cisco IOS XE Release 3.11S

The following features are introduced in Cisco IOS Release 3.11S.

- [AAL5 termination, page 7-2](#)
- [Access Switch Device Manager Template, page 7-2](#)
- [Data Plane Ethernet Loopback with QoS, page 7-2](#)
- [Dissimilar PHB Match at Ingress and Egress, page 7-2](#)
- [Dying Gasp, page 7-3](#)

- DS3 Framing on OC-3 and OC-12, page 7-3
- Fast Reroute Support for Bridge Domain Interface, page 7-3
- BGP PIC Support for Bridge Domain Interface with FRR, page 7-3
- IPv6 Multicast: Multicast Listener Discovery (MLD), page 7-3
- IPv6 Multicast: PIM v6, page 7-3
- ISIS and OSPF Local Microloop Protection, page 7-4
- Remote SPAN, page 7-4
- Service Groups, page 7-4
- TCAM Threshold Based Alarms, page 7-4

AAL5 termination

This feature enables the Asynchronous Transfer Mode Adaptation Layer 5 (AAL5) layer 3 termination on the interface module (IM) (T1/E1 and OC-3) cards on the Cisco ASR 903 Router. For more information see

- *Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S (ASR 900 Series Routers)*

Access Switch Device Manager Template

This feature can be used to configure system resources on the router to optimize support for specific features, depending on how the router is used in the network.

For more information see,

http://www.cisco.com/en/US/docs/routers/asr903/software/guide/b_SDM_ASR903.html

Data Plane Ethernet Loopback with QoS

The Ethernet data plane loopback feature provides a means for remotely testing the throughput of an Ethernet port. For more information see

- *Layer 2 Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)*

Dissimilar PHB Match at Ingress and Egress

The dissimilar per-hop behavior (PHB) **match** on exp is supported for Ingress and Egress on MPLS and VPLS interfaces.

In earlier releases prior to Cisco IOS XE Release 3.11S, when **qos-group** or **discard-class** based on exp classification was configured, Egress based classification was *not* allowed on any other classification except Ingress **set qos-group** or **discard-class**. This was due to the PHB security model.

With Cisco IOS XE Release 3.11, only EVC based tunnel type configuration with either Layer2 VPN or Layer3 VPN is supported. For more information see

- *Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series*

Dying Gasp

This feature generates an alert when the Cisco ASR 903 Router encounters any of the following conditions:

- Interface error-disable
- Reload
- Power failure or removal of power supply cable

For more information see, [Cisco ASR 900 Router Series Configuration Guide](#).

DS3 Framing on OC-3 and OC-12

This feature introduces support for the DS3 clear channel for OC-3 and OC-12 interface modules. For more information, see [Cisco ASR 900 Router Series Configuration Guide](#)

Fast Reroute Support for Bridge Domain Interface

Fast Reroute is supported on bridge domain interfaces on the Cisco ASR 903 router. For more information, see

- [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

BGP PIC Support for Bridge Domain Interface with FRR

BGP PIC is supported on bridge domain interfaces with FRR on the Cisco ASR 903 router. For more information on configuring BGP PIC, see

- [IP Routing: BGP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).
- [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

IPv6 Multicast: Multicast Listener Discovery (MLD)

This feature is used by IPv6 devices to discover multicast listeners (nodes that want to receive multicast packets destined for specific multicast addresses) on directly attached links.

For more information see, [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

IPv6 Multicast: PIM v6

This feature supports the following:

- PIM Source-Specific Multicast—The PIM source-specific multicast (SSM) routing protocol supports SSM implementation and is derived from PIM-SM.
- PIM Sparse Mode (PIM-SM)—IPv6 multicast provides support for intra domain multicast routing using PIM sparse mode (PIM-SM).
- PIM Embedded RP Support—Embedded RP support allows the device to learn RP information using the multicast group destination address instead of the statically configured RP.

- PIM Accept Register—supports the PIM accept register feature to perform PIM-SM register message filtering at the RP.

For more information see, *IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)*

ISIS and OSPF Local Microloop Protection

For ISIS Microloop Protection, see

http://www.cisco.com/en/US/docs/ios-xml/ios/iproute_isis/configuration/xs-3s/irs-uloop-local-avoid.html

For OSPF Microloop Protections, see

http://www.cisco.com/en/US/partner/docs/ios-xml/ios/iproute_ospf/configuration/xs-3s/iro-ospfv2-ip-frr.html

MR-APS Integration with Hotstandby Pseudowire

This feature is a protection mechanism for Synchronous Optical Network (SONET) networks that enables SONET connections to switch to another SONET circuit when a circuit failure occurs. For more information see

- *Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)*

Remote SPAN

This feature is used for remote monitoring of multiple devices at source port, source Vlan levels in the Layer2 network. For more information, see

- *Layer 2 Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)*

Service Groups

The Service groups feature allows you to create service groups and apply aggregate features to those service groups.

For more information, see *Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series*

TCAM Threshold Based Alarms

This feature generates syslog and consequently a Simple Network Management Protocol (SNMP) trap when an application reaches the preset threshold for its allotted TCAM size. For more information, see

- *Network Management Systems Configuration Guide, Cisco IOS XE Release (Cisco ASR 900 Series)*



New Features in Cisco IOS XE 3.12S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.12S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.12S, page 8-1](#)
- [New Software Features in Cisco IOS XE Release 3.12S, page 1](#)

New Hardware Features in Cisco IOS XE Release 3.12S

The following features are introduced in Cisco IOS XE Release 3.12S.

Cisco ASR 902 Router Chassis

The compact 2-rack-unit (RU) routers provides high service scale and flexible hardware configuration. The routers support up to four interface modules. The router supports both AC and DC redundant power supplies. For installation information, see the [Cisco ASR 902 Hardware Installation Guide](#).

New Software Features in Cisco IOS XE Release 3.12S

The following features are introduced in Cisco IOS Release 3.12S.

- [IP SLAs TWAMP Responder](#)
- [Network Time Protocol \(NTP\) Timestamping](#)
- [Auto-IP for SVI, Port Channel and VRF](#)
- [Autonomic Networking](#)
- [BGP Accumulated IGP](#)
- [TWAMP Responder with RFC Compliance](#)

IP SLAs TWAMP Responder

The IETF Two-Way Active Measurement Protocol (TWAMP) defines a standard for measuring round-trip network performance between any two devices that support the TWAMP protocols. The TWAMP-Control protocol is used to set up performance measurement sessions. The TWAMP-Test protocol is used to send and receive performance-measurement probes.

For more information, see [IP SLAs TWAMP Responder](#).

Network Time Protocol (NTP) Timestamping

Starting with Cisco IOS XE Release 3.12S, additional NTP Time of Day synchronization configuration is supported when NTP is chosen for time synchronization for one-way delay or delay-variation measurements on source and destination devices.

For more information, see [Enabling NTP Time of Day Synchronization](#).

Auto-IP for SVI, Port Channel and VRF

The Auto-IP feature addresses the problem of manually reconfiguring nodes during insertion, deletion, and movement of nodes within an auto-IP ring. The auto-IP feature automatically provides IP addresses to the node interfaces inserted into an auto-IP ring.

For more information, see [Auto-IP](#).

Autonomic Networking

Autonomic networking makes network devices intelligent by introducing self-management concepts that simplify network management for the network operator.

For more information, see [Autonomic Networking](#).

BGP Accumulated IGP

The BGP Accumulated IGP feature is an optional nontransitive Border Gateway Protocol (BGP) path attribute. The attribute type code for the accumulated interior gateway protocol (AIGP) attribute is assigned by the Internet Assigned Numbers Authority (IANA). The value field of the AIGP attribute is defined as a set of type, length, value (TLV) elements. The AIGP TLV contains the AIGP metric.

For more information see, [IP Routing: BGP Configuration Guide, Cisco IOS XE Release 3S](#)

Right To Use Licensing

The RTU license is an evaluation license with a 60-day trial period and changes into a perpetual “Right-To-Use” license after the expiry of the trial period. For more information, see [Licensing the Cisco ASR 900 Series Routers](#).

TWAMP Responder with RFC Compliance

See [IP SLAs TWAMP Responder](#).



New Features in Cisco IOS XE 3.13S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.13S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.13.2S, page 9-1](#)
- [New Software Features in Cisco IOS XE Release 3.13.2S, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.13S, page 9-1](#)
- [New Software Features in Cisco IOS XE Release 3.13S, page 2](#)

New Hardware Features in Cisco IOS XE Release 3.13.2S

There are no new hardware features introduced for Cisco IOS XE Release 3.13.2S.

New Hardware Features in Cisco IOS XE Release 3.13S

The following features are introduced in Cisco IOS XE Release 3.13S.

A900-RSP2 Modules and Interface Modules

The A900-RSP2A-64 and A900-RSP2A-128 RSP modules are introduced on the ASR 900 Series Routers.

The following interface modules are introduced on the Cisco ASR 900 Series Routers

- SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet (1X10GE)
- Copper Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet Interface Module(1X10GE)
- 2-port 10 Gigabit Ethernet Interface Module(2X10GE)

For information on supported interface modules, part numbers and slot restrictions, see [Hardware Supported, page 1-2](#).

For information on installation, see

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

For information on migrating from ASR 900 RSP1 to ASR RSP2 modules, see [Cisco ASR 900 RSP1 to ASR 900 RSP2 Migration and Upgrade Guide](#).

Swapping of Interface Modules

Swapping of interface modules is supported on the A900-RSP2 Module. For more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

The **hw-module subslot default** command is introduced before performing a swap of the modules. to default the interfaces on the interface module. For more information, see [Cisco IOS Interface and Hardware Component Command Reference](#).

Support External Alarms and Traps

Starting with Cisco IOS XE Release 3.13, external alarms and traps are supported on the Cisco 900 Series Routers.

For information on alarms, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

Support for Syslog and Trigger for External Alarm

Starting with Cisco IOS XE Release 3.13, syslog and trigger support is introduced for the external alarms on the Cisco 900 Series Routers.

For information on alarms, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

New Software Features in Cisco IOS XE Release 3.13.2S

There are no new software features introduced for Cisco IOS XE Release 3.13.2S.

New Software Features in Cisco IOS XE Release 3.13S

The following features are introduced in Cisco IOS Release 3.13S.

- [RSP2 Module Features](#)
- [Clear-Channel ATM](#)
- [PTP-SYNCE on 10G interface in WANPHY mode](#)
- [Digital Code Signing](#)
- [802.1ad](#)
- [UniDirectional Link Detection \(UDLD\)](#)
- [REP Access Gateway](#)
- [Smart Call Home](#)
- [Autonomic Networking](#)
- [PIM DR Loadbalancing](#)

RSP2 Module Features

See [Feature Set Table, page 1-8](#) for the list of supported software features in Cisco IOS XE Release 3.13S.

Clear-Channel ATM

When the clear channel ATM feature is enabled, the entire payload rate over Synchronous Optical Network (SONET) or the Synchronous Digital Hierarchy (SDH) line is used as a single flow of cells or packets.

For more information, see [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#).

PTP-SYNCE on 10G interface in WANPHY mode

Starting with Cisco IOS XE Release 3.13, PTP and SyncE in WANPHY mode is supported for RSP2 and 10G interface modules.

For more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

Digital Code Signing

The digital code signing functionality validates the integrity and authenticity of the ROMMON image before booting it.

For more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

802.1ad

IEEE 802.1ad enables the service providers to use the architecture and protocols of IEEE 802.1Q to offer separate LANs, bridged local area networks, or virtual bridged local area networks to a number of customers, with minimal cooperation or no cooperation between each customer and the service provider.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

UniDirectional Link Detection (UDLD)

The UniDirectional Link Detection protocol is a Layer 2 protocol that detects and disables one-way connections before they create undesired situation such as Spanning Tree loops.

For more information, see [LAN Switching Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

REP Access Gateway

Resilient Ethernet Protocol (REP) is a ring protection protocol designed to provide fast failure detection and recovery.

For more information, see [LAN Switching Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Smart Call Home

The Call Home feature provides e-mail-based and web-based notification of critical system events. A versatile range of message formats are available for optimal compatibility with pager services, standard e-mail, or XML-based automated parsing applications.

For more information, see [Software Activation Configuration Guide, Cisco IOS XE Release 3S](#).

Autonomic Networking

See, [Autonomic Networking Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

PIM DR Loadbalancing

See, [IP Multicast: PIM Configuration Guide, Cisco IOS XE Release 3S](#).

Ingress QoS Serial Interface

Ingress Qos is supported on MLPPP bundle and serial interfaces. For more information, see

- [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#)



New Features in Cisco IOS XE 3.14S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.14S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.14.2S, page 10-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.14S, page 10-1](#)
- [New Software Features in Cisco IOS XE Release 3.14.2S, page 10-2](#)
- [New Software Features in Cisco IOS XE Release 3.14S, page 10-2](#)

New Hardware Features in Cisco IOS XE Release 3.14.2S

There are no new features introduced for Cisco IOS XE Release 3.14.2.

New Hardware Features in Cisco IOS XE Release 3.14S

The following features are introduced in Cisco IOS XE Release 3.14S.

32-port T1/E1 Interface Modules

The 32-port T1/E1 interface module (32 x T1/E1) is introduced on the ASR900-RSP2A modules on Cisco ASR 900 Series Routers

For information on supported interface modules, part numbers and slot restrictions, see [Hardware Supported, page 1-2](#).

For information on installation, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

Supported Optics

The following optics are introduced on the 8-port 1 Gigabit Ethernet SFP interface module with the 1-port 10 Gigabit Ethernet interface module in Cisco IOS XE Release 3.14S.

- GLC-BX40-U-I
- GLC-BX40-D-I

- GLC-BX40-DA-I
- GLC-BX80-U-I
- GLC-BX80-D-I
- CWDM-SFP-xxxx=
- CWDM-SFP10G-xxxx

The following optics are supported on the RSP2 module for the 8-port 1 Gigabit Ethernet SFP interface module with the 1-port 10 Gigabit Ethernet interface module :

- SFP-10G-BXD-I
- SFP-10G-BXU-I
- SFP-10G-BX40D-I
- SFP-10G-BX40U-I

New Software Features in Cisco IOS XE Release 3.14.2S

VRRPv3 Protocol Support

This feature is supported on the ASR-900 RSP1 modules with release Cisco IOS XE Release 3.14.2.

For more information, see [First Hop Redundancy Protocols Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

New Software Features in Cisco IOS XE Release 3.14S

The following features are introduced in Cisco IOS Release 3.14S.

- [RSP2 Module Features](#)
- [CEM over UDP](#)
- [Async RS232 over MPLS](#)
- [TSoP Smart SFP](#)

RSP2 Module Features

See [Feature Set Table, page 1-8](#) for the list of supported software features in Cisco IOS XE Release 3.14S.

CEM over UDP

The Circuit Emulation Service over UDP feature extends the implementation of Cisco IOS Circuit Emulation Service (CES) by supporting pseudowire emulation (PWE) function to be performed over an Internet Protocol (IP) network directly.

For more information, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#).

Async RS232 over MPLS

The Cisco ASR 903 Series Router Serial interface module supports pseudowire types that utilize Async RS232 traffic over MPLS. The Serial IM interfaces monitor and detect cable connections, cable types and also monitors modem control signals periodically.

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

TSoP Smart SFP

TSoP Smart SFP is a special type of optical transceiver which provides solution to transparently encapsulate SDH or SONET bit streams into packet format, suitable for pseudowire transport over an ethernet network.

For more information, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

BFD Support for Multicast (PIM)

[IP Multicast: PIM Configuration Guide, Cisco IOS XE Release 3S](#)



New Features in Cisco IOS XE 3.15S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.15S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.15S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.15S, page 2](#)

New Hardware Features in Cisco IOS XE Release 3.15S

The following features are introduced in Cisco IOS XE Release 3.15S.

8-port T1/E1 Interface Modules

The 8-port T1/E1 interface module (8 x T1/E1) is introduced on the A900-RSP2A modules on Cisco ASR 900 Series Routers.

For information on supported interface modules, part numbers and slot restrictions, see [Hardware Supported, page 1-2](#).

For information on installation, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

32-port T1/E1 Interface Modules

The 32-port T1/E1 interface module (8 x T1/E1) is introduced on the A900-RSP2A modules on Cisco ASR 900 Series Routers.

For information on supported interface modules, part numbers and slot restrictions, see [Hardware Supported, page 1-2](#).

For information on installation, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

New Software Features in Cisco IOS XE Release 3.15S

The following features are introduced in Cisco IOS Release 3.15S.

- [RSP2 Module Features](#)
- [QoS EVC Push Rewrite](#)
- [Label Switched Multicast Point-to-Multipoint Traffic Engineering](#)
- [Hop-By-Hop PTP Redundancy](#)
- [Label Switched Multicast Point-to-Multipoint Traffic Engineering](#)
- [Label Distribution Protocol \(LDP\) Non Stop Routing \(NSR\)](#)
- [DHCP Server v6](#)
- [DHCP Client v6](#)
- [Hierarchical Color-Aware Policing](#)
- [Routed Pseudowire and Routed VPLS](#)
- [Smart Licensing with HA Support](#)
- [VRRPv3 High Scale](#)
- [EIGRP OTP VRF Support](#)
- [Support DIKE as a Security Mechanism for AN ACP](#)
- [Zero Touch Auto-IP](#)
- [EVC Priority Propagation](#)
- [Hybrid BMCA](#)

RSP2 Module Features

See [Feature Set Table](#) for the list of supported software features in Cisco IOS XE Release 3.15S.

QoS EVC Push Rewrite

Starting with Cisco IOS XE Release 3.15S, **rewrite push** with **cos** marking is supported on the EVCs on the router.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Label Switched Multicast Point-to-Multipoint Traffic Engineering

The MPLS Point-to-Multipoint Traffic Engineering feature enables you to forward Multiprotocol Label Switching (MPLS) traffic from one source to multiple destinations.

For more information, see [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Hop-By-Hop PTP Redundancy

PTP Ring topology is designed by using Hop-By-Hop configuration of PTP boundary clocks. In this topology, each BC selects its adjacent nodes as PTP masters, instead of using the same GM as the PTP master.

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

Label Switched Multicast Point-to-Multipoint Traffic Engineering

Starting Cisco IOS XE Release 3.15S, Point-to-Multipoint Traffic Engineering is supported on the A900-RSP2A module.

For more information, see [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Label Distribution Protocol (LDP) Non Stop Routing (NSR)

The NSR LDP feature allows the Label Distribution Protocol (LDP) to continue to operate across a node failure without losing peer sessions.

For more information, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#).

DHCP Server v6

Starting with Cisco IOS XE Release, DHCP for IPv6 is supported.

For more information, see [IP Addressing: DHCP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

DHCP Client v6

Starting with Cisco IOS XE Release, DHCP for IPv6 is supported.

For more information, see [IP Addressing: DHCP Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Hierarchical Color-Aware Policing

Starting with Cisco IOS XE Release 3.15S, hierarchical color-aware policing is supported on the A900-RSP2A module.

For more information, see [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#).

Routed Pseudowire and Routed VPLS

Routed Pseudowire and VPLS feature routes Layer 3 traffic and Layer 2 frames for pseudowire connections between provider edge (PE) devices using Virtual Private LAN Services (VPLS) multipoint PE.

For more information, see [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Smart Licensing with HA Support

Starting with Cisco IOS XE Release 3.15S, smart licensing with high availability is supported on the A900-RSP2A module.

For more information, see *Software Activation Configuration Guide, Cisco IOS XE Release 3S*

VRRPv3 High Scale

First Hop Redundancy Protocols Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)

EIGRP OTP VRF Support

http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/iproute_eigrp/configuration/xe-3s/ire-xe-3s-book/ire-otp-vrf.html

Support DIKE as a Security Mechanism for AN ACP

http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/auto_net/configuration/xe-3s/an-auto-net-xe-3s-book/an-auto-net-infra.html

Zero Touch Auto-IP

http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/ipaddr_ipv4/configuration/15-s/ipv4-15-s-book/Zero-touch-Auto-IP.html

EVC Priority Propagation

http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_conmgt/configuration/xe-3s/asr903/qos-con-mgt-xe-3s-asr903-book.html

Hybrid BMCA

<http://www.cisco.com/c/en/us/td/docs/routers/asr903/software/guide/chassis/xe-3s/asr900-router-cfg-book/Clocking-Timing-SynchE.html#pgfId-1278724>



New Features in Cisco IOS XE 3.16S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.16S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.16.9S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.16.9S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.16.8S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.16.8S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.16.8S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.16.1aS, page 3](#)
- [New Hardware Features in Cisco IOS XE Release 3.16S, page 3](#)
- [New Software Features in Cisco IOS XE Release 3.16S, page 4](#)

New Hardware Features in Cisco IOS XE Release 3.16.9S

There are no new features introduced for Cisco IOS XE Release 3.16.9S.

New Software Features in Cisco IOS XE Release 3.16.9S

There are no new features introduced for Cisco IOS XE Release 3.16.9S.

New Hardware Features in Cisco IOS XE Release 3.16.8S

There are no new features introduced for Cisco IOS XE Release 3.16.8S.

New Software Features in Cisco IOS XE Release 3.16.8S

There are no new features introduced for Cisco IOS XE Release 3.16.8S.

New Hardware Features in Cisco IOS XE Release 3.16.1aS

The following features are introduced in Cisco IOS Release 3.16.1aS

- [A900-RSP3 Modules and Interface Modules](#)
- [DC Power Supply](#)
- [AC Power Supply](#)
- [Cisco ASR 907 Series Aggregation Services Router](#)

A900-RSP3 Modules and Interface Modules

The A900-RSP3C-400-S RSP module is introduced on the ASR 900 Series Routers.

The following interface modules are introduced on the Cisco ASR 900 Series Routers:

- 8-port 10 Gigabit Ethernet Interface Module (8X10GE)
- 1-port 100 Gigabit Ethernet Interface Module (1X100GE)
- 2-port 40 Gigabit Ethernet QSFP Interface Module (2X40GE)

For information on supported interface modules, part numbers and slot restrictions, see [Hardware Supported](#).

For information on installation, see

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

DC Power Supply

The A900-PWR1200-D power supply is introduced on the ASR 900 Series Router.

For information on installation, see

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

AC Power Supply

The A900-PWR1200-A power supply is introduced on the ASR 900 Series Router.

For information on installation, see

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

Cisco ASR 907 Series Aggregation Services Router

For more information, see the Hardware Installation Guide at:

<http://www.cisco.com/c/en/us/support/routers/asr-903-series-aggregation-services-routers/products-installation-guides-list.html>

New Software Features in Cisco IOS XE Release 3.16.1aS

There are no new features introduced for Cisco IOS XE Release 3.16.1aS.

New Hardware Features in Cisco IOS XE Release 3.16S

There are no new features introduced for Cisco IOS XE Release 3.16S.

New Software Features in Cisco IOS XE Release 3.16S

The following features are introduced in Cisco IOS Release 3.16S.

- [Policy-Based Routing](#)
- [Segment Routing \(IS-IS\)](#)
- [MPLS MTU over GRE](#)
- [Circuit Emulation Service over UDP](#)
- [IP SLA - Service Performance Testing](#)
- [SLM over VPLS](#)
- [Microwave ACM Extensions](#)
- [Pseudowire Group Status Generation](#)

Policy-Based Routing

This feature provides a way for a device to put packets through a route map before routing them.

The route map determines which packets are routed to which device. You might enable policy-based routing (PBR) if you want some packets to be routed a way other than the obvious shortest path. PBR provides control over routing by extending and complementing the existing mechanisms provided by routing protocols. Possible applications for PBR are to provide equal access, protocol-sensitive routing, source-sensitive routing, routing based on interactive versus batch traffic, and routing based on dedicated links.

For more information, see [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Segment Routing (IS-IS)

The Segment Routing—ISIS v4 node SID feature provides support for segment routing on IS-IS networks.

For more information, see [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

MPLS MTU over GRE

This feature allows you to set the MPLS MTU size in GRE tunnels to the maximum size besides the current default size.

For more information, see [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Circuit Emulation Service over UDP

Circuit Emulation Service over Packet-Switched Network (CESoPSN) and Structure-agnostic TDM over Packet (SAToP) are supported as a part of Circuit Emulation Service over UDP (CEMoUDP).

The feature is supported on 8T1/E1 interface module, 16T1/E1 interface module, and OC3 interface module on the router. Circuit Emulation Service over UDP is not supported for 32-port E1/T1 interface module (A900-IMA32D).

For more information, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900\)](#).

IP SLA - Service Performance Testing

This feature, Y.1564, is an Ethernet service activation test methodology, and is the standard for turning up, installing, and troubleshooting Ethernet and IP based services. Y.1564 is the only standard test methodology that allows a complete validation of Ethernet service-level agreements (SLAs) in a single test. Service performance testing is designed to measure the ability of a Device Under Test (DUT) or a network under test to properly forward traffic in different states.

For more information, see [IP SLAs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#).

SLM over VPLS

Synthetic loss measurement (SLM) is part of the ITU-T Y.1731 standard used to periodically measure Frame Loss and Forward Loss Ratio (FLR) between a pair of point to point MEPs. This feature enables the configuration of SLM over VPLS.

For more information, see [IP SLAs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#).

Microwave ACM Extensions

Starting with Cisco IOS Release 3.16, adaptive bandwidth with multi-hop extensions are supported on the ASR 903 RSP2 module. Multi-hop extensions help identify the degraded links in the topology.

The following command is modified: **event ethernet microwave sd interface**.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Pseudowire Group Status Generation

This release introduces support for pseudowire group status generation.

The Pseudowire Group Message Generation feature assigns pseudowire group id for a group of pseudowires and sends wildcard status notifications or label withdrawal messages for a group.

For more information, see [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#).



New Features in Cisco IOS XE 3.17 Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.17.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.17, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.17, page 2](#)

New Hardware Features in Cisco IOS XE Release 3.17

The following features are introduced in Cisco IOS Release 3.17

- [GPS Support](#)

GPS Support

Effective Cisco IOS-XE Release 3.17, the Cisco ASR 903 (with RSP3 module) and Cisco ASR907 routers use a satellite receiver, also called the global navigation satellite system (GNSS), as a new timing interface. With the GNSS available on the router itself, the access networks can now directly estimate time measurements and clock errors from the satellites. In other words, the Cisco ASR 903 and ASR907 routers can now act as a grandmaster clock.

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

New Software Features in Cisco IOS XE Release 3.17

The following features are introduced in Cisco IOS Release 3.17.

- [Configuring Multicast VPN](#)
- [Multicast VPN Extranet Support](#)
- [E&M Signals over MPLS](#)
- [VLAN Scale with Convergence](#)
- [Layer 3 Access Control Lists on EVCs](#)
- [VLAN Translation with QoS](#)
- [Transparent CFM on C-VLAN](#)
- [Ethernet Fault Detection](#)

Configuring Multicast VPN

The Multicast VPN (MVPN) feature provides the ability to support multicast over a Layer 3 VPN. IP multicast is used to stream video, voice, and data to an MPLS VPN network core.

For more information, see [IP Multicast: PIM Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

Multicast VPN Extranet Support

The Multicast VPN Extranet Support feature enables service providers to distribute IP multicast content originated from one enterprise site to other enterprise sites.

This feature enables service providers to offer the next generation of flexible extranet services, helping to enable business partnerships between different enterprise VPN customers.

For more information, see [IP Multicast: PIM Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

E&M Signals over MPLS

E and M signaling defines a trunk circuit side and a signaling unit side for each connection similar to the data circuit-terminating equipment (DCE) and data terminal equipment (DTE) reference type. The analog E and M interface functions as the signaling unit side and it expects the other side to be a trunk circuit.

For more information, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

VLAN Scale with Convergence

The convergence value is improved from Cisco IOS XE 3.17 release.

For more information, see [LAN Switching Configuration Guide](#).

Layer 3 Access Control Lists on EVCs

Access Control Lists (ACLs) provide the capability to filter packets at a fine granularity. In Metro Ethernet networks, ACLs are directly applied on Ethernet virtual circuits (EVCs). Earlier, the layer 3 ACLs were only supported on the routed ports (physical ports or BDIs). Effective Cisco IOS-XE Release 3.17, the support of layer 3 ACLs on EVCs provides the capability to filter the layer 3 packets on layer 2 bridges that support Ethernet services.

For more information, see [MPLS: Layer 3 VPNs Configuration Guide](#).

VLAN Translation with QoS

Effective Cisco IOS-XE Release 3.17, VLAN translation provides flexibility in managing VLANs and Metro Ethernet-related services. The current implementation of the feature allows one or more 802.1Q tags to be replaced with other 802.1Q tags and thus the desired tag manipulation can be achieved. In a scenario with two EFPs egressing the same interface, each EFP can have a different VLAN rewrite operation, which is more flexible.

For more information, see [Carrier Ethernet Configuration Guide](#).

Transparent CFM on C-VLAN

Transparent CFM is a mechanism to provide transparency on CFM frames between customer ends. Transparency helps the service provider network to pass the entire maintenance levels (0-7) of CFM frames from one customer end to another customer end by UP MEP that is configured on UNI-N port at any level.

For more information, see [Carrier Ethernet Configuration Guide](#).

Ethernet Fault Detection

Ethernet Fault Detection (EFD) is a mechanism that allows Ethernet OAM protocols, such as CFM, to control the “line protocol” state of an interface. Unlike many other interface types, Ethernet interfaces do not have a line protocol, whose state is independent from that of the interface. For Ethernet interfaces, this role is handled by the physical-layer Ethernet protocol itself, and therefore if the interface is physically up, then it is available and traffic can flow.

EFD changes this to allow CFM to act as the line protocol for Ethernet interfaces. This allows CFM to control the interface state so that if a CFM defect (such as AIS or loss of continuity) is detected with an expected peer MEP, the interface can be shut down. This not only stops any traffic flowing, but also triggers actions in any higher-level protocols to route around the problem.

For more information, see [Carrier Ethernet Configuration Guide](#).

PoS MR-APS

Packet-over-SONET (POS) is a standardized way for mapping IP packets into SONET/SDH frames. This feature enables the configuration of MR-APS over Pos.

For more information, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

SLM/DMM over VPLS

Synthetic loss measurement (SLM) and Delay Measurement Message (DMM) are part of the ITU-T Y.1731 standard. SLM is used to periodically measure Frame Loss and Forward Loss Ratio (FLR) between a pair of point to point MEPs. DMM is used to periodically measure Frame Delay and Frame Delay Variation between a pair of point to point MEPs. This feature enables the configuration of SLM/DMM over VPLS.

For more information, see *IP SLAs Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900)*.

BGP PIC Support for TDM Pseudowires

Starting Cisco IOS XE Release 3.17, BGP PIC is supported for TDM pseudowires on the ASR 900 RSP1 module.

For information, see

- *Cisco ASR 900 Router Series Configuration Guide*
- *BGP Configuration Guide, Cisco IOS XE Release 3S (Cisco ASR 900 Series)*

MPLS TE over BDI

Effective Cisco IOS-XE Release 3.17, the Cisco ASR 903 (with RSP2 module) router provides the option for enabling the MPLS TE tunnels over Bridge Domain Interfaces.

For more information, see *MPLS Traffic Engineering Path Link and Node Protection Configuration Guide, Cisco IOS XE Release 3S (ASR 900 Series)*.



New Features in Cisco IOS XE 3.18S Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.18S.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.18.3S, page 14-1](#)
- [New Software Features in Cisco IOS XE Release 3.18.3S, page 14-1](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.2S, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.18.2S, page 1](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.1S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18.1S, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18S, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18S, page 4](#)

New Hardware Features in Cisco IOS XE Release 3.18.3S

There are no new features introduced for Cisco IOS XE Release 3.18.3S.

New Software Features in Cisco IOS XE Release 3.18.3S

There are no new features introduced for Cisco IOS XE Release 3.18.3S.

New Hardware Features in Cisco IOS XE Release 3.18.2S

There are no new features introduced for Cisco IOS XE Release 3.18.2S.

New Software Features in Cisco IOS XE Release 3.18.2S

There are no new features introduced for Cisco IOS XE Release 3.18.2S.

New Hardware Features in Cisco IOS XE Release 3.18.1S

There are no new features introduced for Cisco IOS XE Release 3.18.1S.

New Software Features in Cisco IOS XE Release 3.18.1S

The following features are introduced in Cisco IOS Release 3.18.1S.

X21 Circuit Emulation Service

The X21 Circuit Emulation feature enables transporting x21 traffic over MPLS core.

For more information, see [X21 CESoPSN Configuration Guide for Cisco ASR 900 Router Series](#)

New Hardware Features in Cisco IOS XE Release 3.18S

The following features are introduced in Cisco IOS Release 3.18S:

- [A900-RSP3 Modules](#)
- [DC Power Supply](#)
- [AC Power Supply](#)
- [Blank Deflector \(A900-IMA-BLNK-DEF\)](#)
- [GNSS Module \(A900-CM-GNSS\)](#)

A900-RSP3 Modules

The A900-RSP3C-200 RSP module is introduced on the ASR 902 and the ASR 903 Series Routers.



Note The 2-port 40 Gigabit Ethernet QSFP Interface Module (2X40 GE) is *not* supported on ASR 902 Series Router in Cisco IOS XE 3.18 Release.

For information on installation, see:

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

DC Power Supply

The A900-PWR1200-D power supply is introduced on the ASR 902 Series Router.

- For information on installation, see [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

AC Power Supply

The A900-PWR1200-A power supply is introduced on the ASR 902 Series Router.

For information on installation, see [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

Blank Deflector (A900-IMA-BLNK-DEF)

The A900-IMA-BLNK-DEF is a special type of blank used for empty interface module slots. Starting with Cisco IOS XE Release, this module is supported on the ASR 903 and ASR 902 routers.

For information on installation, see

- [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)
- [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

GNSS Module (A900-CM-GNSS)

Starting with Cisco IOS XE Release, this module is supported on the ASR 902 router with the A900-RSP3C-200 RSP module.

For information on installation, see [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#)

New Software Features in Cisco IOS XE Release 3.18S

The following features are introduced in Cisco IOS Release 3.18S.

- [BGP PIC Support for TDM Pseudowires](#)
- [EtherChannel Min-Links Feature](#)
- [LACP 1:1 Fast Switchover Support](#)
- [Phase Profile G8275.1](#)
- [L3-ATM](#)
- [Simultaneous Support of QOS Policy at Port and EFP Level](#)
- [mLDP IPv6](#)
- [STM-4 TSoPL3-ATM](#)
- [CEMoUDP for 32T1E1](#)
- [Clear Channel ATM \(on OC3/STM1\)L3-ATM](#)
- [Larger String for EVC VLAN Encapsulation](#)
- [Point-to-Point Protocol over Ethernet Intermediate Agent](#)
- [Ethernet Loopback with Other Types of Encapsulation](#)
- [Asymmetric Rewrite Rules](#)
- [EVPN VPWS Single Homed](#)
- [Synthetic Frame Loss Measurement \(ETH-SLM\)](#)
- [Delay and Jitter Support for SADT](#)

BGP PIC Support for TDM Pseudowires

Starting Cisco IOS XE Release 3.18S, BGP PIC is supported for all pseudowires on the Cisco ASR 900 RSP2 module.

Starting Cisco IOS XE Release 3.18S, BGP PIC is supported with MPLS Traffic-engineering in the core on the Cisco ASR 900 RSP1 and RSP2 modules.

For information, see [Configuring Pseudowire](#).

Egress Marking based on Color of Traffic

Effective with Cisco IOS XE Release 3.18S, egress marking based on color of traffic is introduced on the RSP3 module. With this feature, the packets are marked such that the policer passes or drops the packets accordingly.

For more information, see [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#)

EtherChannel Min-Links Feature

Effective with Cisco IOS XE Release 3.18S, the EtherChannel Min-Links feature is supported on LACP EtherChannels. This feature allows you to configure the minimum number of member ports that must be in the link-up state and bundled in the EtherChannel for the port channel interface to transition to the link-up state.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

LACP 1:1 Fast Switchover Support

Effective with Cisco IOS XE Release 3.18S, the LACP 1:1 redundancy feature provides an EtherChannel configuration with one active link and fast switchover to a hot standby link.

For this feature, the LACP EtherChannel must contain exactly two links, of which only one is active.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Phase Profile G8275.1

With upcoming technologies like LTE-TDD, LTE-A CoMP, LTE-MBSFN and Location-based services, eNodeBs (base station devices) are required to be accurately synchronized in time and phase. Having GNSS systems at each node is not only expensive, but also introduces vulnerabilities.

Effective with Cisco IOS XE Release 3.18S, Cisco ASR 903 routers with RSP2 module support the G.8275.1 telecom profile. This profile targets accurate time and phase distribution and requires boundary clocks at every node in the network.

For more information, see the G.8275.1 Telecom Profile document at [Cisco ASR 900 Router Series Configuration Guide](#)

L3-ATM

This feature enables the Asynchronous Transfer Mode Adaptation Layer 5 (AAL5) layer 3 termination on the interface module (IM) (T1/E1 and OC-3) cards on the Cisco ASR 903 Router.

For more information, see [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#)

Simultaneous Support of QoS Policy at Port and EFP Level

Effective with Cisco IOS XE Release 3.18S, this feature provides the flexibility to apply EFP based classification on port and PHB based classification on EFP simultaneously.

For more information, see [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#)

mLDP IPv6

Effective with Cisco IOS XE Release 3.18S, the MLDPv6 based MVPN configuration enables IPv6 multicast packet delivery using MPLS. This feature enables the configuration of MLDPv6 based MVPN.

For more information, see [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

STM-4 TSoP

Effective with Cisco IOS XE Release 3.18S, STM-4 TSoP is supported on ASR 900 RSP2 Module.

STM-4 TSoP is compatible with the below SFPs supported on the OC-12 interface module:

- ONS-SI-622-L2—For 40km cable length, use 2 dB attenuator; short distance use 10 dB attenuator to avoid receiver overload.
- ONS-SI-622-L1—For 40km cable length, no attenuator; short distance use 10 dB attenuator to avoid receiver overload.
- ONS-SI-622-I1—For 15km cable length, use 2 dB attenuator; short distance use 8 dB attenuator to avoid receiver overload.

For more information, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

CEMoUDP for 32T1E1

Effective with Cisco IOS XE Release 3.18S, CEMoUDP is supported on 32 T1/E1 interface module.

For more information, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)

Clear Channel ATM (on OC3/STM1)

Effective with Cisco IOS XE Release 3.18S, Clear Channel ATM is supported on Cisco ASR 900 RSP2 Module.

For more information, see [Asynchronous Transfer Mode Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series Routers\)](#)

Larger String for EVC VLAN Encapsulation

Effective with Cisco IOS XE Release 3.18S, you can add or remove one or more VLAN tag values for matching criteria. You can use the **encapsulation dot1q add** command with **show run** command when the encapsulation configuration command is more than the terminal width and **ethernet service multi-line** command is configured or if the encapsulation command is more than 255 characters.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Point-to-Point Protocol over Ethernet Intermediate Agent

Effective Cisco IOS-XE Release 3.18S, Point-to-Point protocol over Ethernet Intermediate Agent (PPPoE IA) is supported.

PPPoE IA helps the service provider Broadband Remote Access Server (BRAS) to distinguish between end hosts connected over Ethernet to an access switch.

For more information, see [IP Routing: Protocol-Independent Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Ethernet Local Connect

Effective Cisco IOS XE Release 3.18S, you can connect two end points (service instances) using the Local connect (Layer 2 point to point service), which is a point to point connection.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Ethernet Loopback with Other Types of Encapsulation

Effective with Cisco IOS XE Release 3.18S, Ethernet loopback for default and untagged EFPS is available.

For more information, see [Layer 2 Configuration Guide, Cisco IOS XE Release \(ASR 900 Series\)](#)

Asymmetric Rewrite Rules

Effective with Cisco IOS XE Release 3.18S, this feature introduces new rewrite rules for the egress direction in the EFP. You can configure asymmetric rewrite rules in both ingress and egress directions of the EFP.

For more information, see [Carrier Ethernet Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

EVPN VPWS Single Homed

Effective with Cisco IOS XE Release 3.18S, this feature is a BGP control plane solution for point-to-point services. It has the ability to forward traffic from or to one network to another using the Ethernet Segment without MAC lookup.

For more information, see [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

Synthetic Frame Loss Measurement (ETH-SLM)

Effective with Cisco IOS XE Release 3.18S, SLM is not supported with TEF in access mode.

For more information, see [IP SLAs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#)

Delay and Jitter Support for SADT

Effective with Cisco IOS XE Release 3.18S, the delay and jitter are supported in service performance test.

For more information, see [IP SLAs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900\)](#)



New Features in Cisco IOS XE 3.18SP Releases

This chapter provides information about the new features introduced in the Cisco IOS XE Release 3.18SP.

This chapter includes the following sections:

- [New Hardware Features in Cisco IOS XE Release 3.18.9SP, page 1](#)
- [New Software Features in Cisco IOS XE Release 3.18.9SP, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.8aSP, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18.8aSP, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.7SP, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18.7SP, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.6SP, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18.6SP, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.5SP, page 2](#)
- [New Software Features in Cisco IOS XE Release 3.18.5SP, page 2](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.4SP, page 3](#)
- [New Software Features in Cisco IOS XE Release 3.18.4SP, page 3](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.3SP, page 3](#)
- [New Software Features in Cisco IOS XE Release 3.18.3SP, page 3](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.2SP, page 3](#)
- [New Software Features in Cisco IOS XE Release 3.18.2SP, page 3](#)
- [New Hardware Features in Cisco IOS XE Release 3.18.1SP, page 4](#)
- [New Software Features in Cisco IOS XE Release 3.18.1SP, page 6](#)
- [New Hardware Features in Cisco IOS XE Release 3.18SP, page 9](#)
- [New Software Features in Cisco IOS XE Release 3.18SP, page 9](#)

New Hardware Features in Cisco IOS XE Release 3.18.9SP

There are no new features introduced for Cisco IOS XE Release 3.18.9SP.

New Software Features in Cisco IOS XE Release 3.18.9SP

There are no new features introduced for Cisco IOS XE Release 3.18.9SP.

New Hardware Features in Cisco IOS XE Release 3.18.8aSP

There are no new features introduced for Cisco IOS XE Release 3.18.8aSP.

New Software Features in Cisco IOS XE Release 3.18.8aSP

There are no new features introduced for Cisco IOS XE Release 3.18.8aSP.

New Hardware Features in Cisco IOS XE Release 3.18.7SP

There are no new features introduced for Cisco IOS XE Release 3.18.7SP.

New Software Features in Cisco IOS XE Release 3.18.7SP

There are no new features introduced for Cisco IOS XE Release 3.18.7SP.

New Hardware Features in Cisco IOS XE Release 3.18.6SP

There are no new features introduced for Cisco IOS XE Release 3.18.6SP.

New Software Features in Cisco IOS XE Release 3.18.6SP

There are no new features introduced for Cisco IOS XE Release 3.18.6SP.

New Hardware Features in Cisco IOS XE Release 3.18.5SP

There are no new features introduced for Cisco IOS XE Release 3.18.5SP.

New Software Features in Cisco IOS XE Release 3.18.5SP

There are no new features introduced for Cisco IOS XE Release 3.18.5SP.

New Hardware Features in Cisco IOS XE Release 3.18.4SP

There are no new features introduced for Cisco IOS XE Release 3.18.4SP.

New Software Features in Cisco IOS XE Release 3.18.4SP

Multi EFPs for Single BDI Support on Cisco RSP3 Module

The Cisco RSP3 module now supports multiple EFPs with a single BDI.

New Hardware Features in Cisco IOS XE Release 3.18.3SP

There are no new features introduced for Cisco IOS XE Release 3.18.3SP.

New Software Features in Cisco IOS XE Release 3.18.3SP

The following feature is introduced for Cisco IOS XE Release 3.18.3SP.

- [MPLS-TE over PoCH](#)

MPLS-TE over PoCH

MPLS-TE over port channel (PoCH) is now supported. For more information see [MPLS Traffic Engineering Path Link and Node Protection Configuration Guide, Cisco ASR 900 Series](#).

New Hardware Features in Cisco IOS XE Release 3.18.2SP

There are no new features introduced for Cisco IOS XE Release 3.18.2SP.

New Software Features in Cisco IOS XE Release 3.18.2SP

The following features are introduced for Cisco IOS XE Release 3.18.2SP.

- [VPLS over Port-channel and BDI](#)
- [PTP over MPLS Support](#)

VPLS over Port-channel and BDI

Effective with Cisco IOS XE Release 3.18.2SP, Cisco ASR 900 RSP3 Module supports VPLS over Port-channel (PoCH) and bridge domain interfaces (BDI), VPLS over Fast Reroute (VPLSoFRR), VPLS with BGP PIC-Edge, and VPLS with RFC3107.

For information more information, see [MPLS Layer 2 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

PTP over MPLS Support

In the Cisco IOS XE Release 3.18.2SP, PTP packets carrying MPLS labels are supported in the ingress or egress direction on the Cisco RSP3 module.

New Hardware Features in Cisco IOS XE Release 3.18.1SP

The following features are introduced in Cisco IOS Release 3.18.1SP:

- [4-Port C37.94 Interface Module](#)
- [48-Port T1/E1 CEM Interface Module](#)
- [48-Port T3/E3 CEM Interface Module](#)
- [1-Port OC-192 or 8-Port Low Rate CEM Interface Module Support](#)
- [Serial Interface Module](#)

4-Port C37.94 Interface Module

The Cisco (A900-IMA4C3794) is a 4-port interface module that provides IEEE C37.94-2002 compliant Nx64 kbps optical interface ports to the router.

This interface module is supported on the RSP2 module on the ASR 903 and ASR 902 routers.

For information more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

For information more information, see [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#).

48-Port T1/E1 CEM Interface Module

The 48 x T1/E1 interface module provides connectivity for up to 48 x T1/E1 ports through 3 high-density connectors on the front panel. Each port supports 16 TX and RX ports.

This is supported on the RSP3 module on the ASR 903 router.

For information more information, see [Cisco ASR 907 Router Hardware Installation Guide](#).

For information more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#)

48-Port T3/E3 CEM Interface Module

The 48 X T3/E3 interface module provides connectivity for up to 48 x T3/E3 ports through 3 high-density connectors on the front panel. Each port supports 16 TX and RX ports.

This is supported on the RSP3 module on the ASR 903 router.

For information more information, see [Cisco ASR 907 Router Hardware Installation Guide](#).

For information more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

1-Port OC-192 or 8-Port Low Rate CEM Interface Module Support

The 1-Port OC-192 interface module with 8-port low rate CEM interface module is a high density combination interface module. This module supports 1-Port OC-192 and 8 low rate CEM or 1 Gigabit Ethernet port.

This is supported on the RSP3 module on the ASR 903 router.

For information more information, see [Cisco ASR 907 Router Hardware Installation Guide](#).

For information more information, see [Cisco ASR 903 Series Aggregation Services Router Hardware Installation Guide](#).

Serial Interface Module

The serial interface module, which is designed to provide a low-latency communication platform for legacy interfaces. Designed for utilities, the module is hardened to accommodate the wide operating temperature swings, EMI and surge spikes, and dust found in substation environments.

This is supported on the RSP2 module on the ASR 902 router.

For more information, see [Cisco ASR 902 Aggregation Services Router Hardware Installation Guide](#).

New Hardware Features in Cisco IOS XE Release 3.18.1bSP

There are no new features introduced for Cisco IOS XE Release 3.18.1bSP.



Note

The Cisco IOS XE 3.18.1bSP release is applicable only on the Cisco ASR900 RSP3 module.

New Software Features in Cisco IOS XE Release 3.18.1SP

The following features are introduced in Cisco IOS Release 3.18.1SP

- [1-Port OC-192 or 8-Port Low Rate CEM Interface Module Support](#)
- [4-Port C37.94 Interface Module](#)
- [48-Port T1 CEM Interface Module Support](#)
- [48-Port T3 CEM Interface Module Support](#)
- [FlexLSP Inter-area Support on Non-corouted Mode](#)
- [WAN-PHY Support](#)
- [Leap Second](#)
- [Port Licensing](#)
- [Pseudowire Redundancy with Uni-directional Active-Active](#)

1-Port OC-192 or 8-Port Low Rate CEM Interface Module Support

The 1-Port OC-192 or 8-Port Low Rate CEM Interface Module (10G HO / 10G LO) is supported.

The following features are supported on the interface module:

- ACR and DCR Support

Adaptive Clock Recovery (ACR) is an averaging process that negates the effect of random packet delay variation and captures the average rate of transmission of the original bit stream. ACR recovers the original clock for a synchronous data stream from the actual payload of the data stream.

Differential Clock Recovery (DCR) is a technique used for Circuit Emulation (CES) to recover clocks based on the difference between PE clocks. TDM clock frequency is tuned to receive differential timing messages from sending end to the receiving end.

- Alarm History Support

Alarm history or alarm persistence feature enables the maintenance of the history of the port and the path alarms. History of the port-level and path-level alarms are saved into a file and is retained for monitoring network events.

- APS Support

Automatic protection switching (APS) is a protection mechanism for SONET networks that enables SONET connections to switch to another SONET circuit when a circuit failure occurs. A protection interface serves as the backup interface for the working interface. When the working interface fails, the protection interface quickly assumes its traffic load.

1-Port OC-192 and 8-Port OC-48 Interface Modules supports the following SONET protection switching schemes:

- Linear Bidirectional 1+1 APS
- Linear Unidirectional 1+1 APS
- Circuit Emulation Support

Circuit Emulation (CEM) is a technology that provides a protocol-independent transport over a packet-based backhaul technology such as MPLS or IP Networks. CEM provides a bridge between a time-division multiplexing (TDM) network and MPLS network. L2VPN over IP/MPLS is also supported on the interface modules.

- ONS Pluggable Optics Support

A comprehensive range of pluggable optical modules is supported.

- OTN Wrapper Support

Optical Transport Network (OTN) Wrapper feature provides robust transport services that leverage many of the benefits such as resiliency and performance monitoring, while adding enhanced multi-rate capabilities in support of packet traffic, plus the transparency required by Dense Wavelength Division Multiplexing (DWDM) networks. Cisco NCS 4200 acts as an aggregator for ethernet, TDM, and SONET traffic to connect to an OTN network and vice versa. The ports on the interface modules are capable of OTN functionality.

- OTN Wrapper feature is supported on the following interface modules:
 - 8-port 10 Gigabit Ethernet Interface Module (8x10GE) (A900-IMA8Z) - The encapsulation type is OTU1e and OTU2e
 - 2-port 40 Gigabit Ethernet QSFP Interface Module (2x40GE) (A900-IMA2F) - The encapsulation type is OTU3

- Performance Monitoring Support

Performance monitoring (PM) parameters are used by service providers to gather, store, and set thresholds, and to report performance data for early detection of problems.

- QoS Support on CEMoMPLS

The QoS EXP Matching feature allows you to classify and mark network traffic by modifying the Multiprotocol Label Switching (MPLS) experimental bits (EXP) field in IP packets. This feature allows you to organize network traffic by setting values for the MPLS EXP field in MPLS packets. By choosing different values for the MPLS EXP field, you can mark packets so that packets have the priority that they require during periods of congestion.

- SONET Support

Synchronous Optical NETWORK (SONET) defines optical signals and a synchronous frame structure for multiplexed digital traffic. SONET is supported on 1-Port OC-192 and 8-Port Low Rate CEM Interface Modules. The transport network using SONET provides much more powerful networking capabilities than existing asynchronous systems. SONET is a set of standards that define the rates and formats for optical networks specified in GR-253-CORE.

For more information, see [1-Port OC-192 or 8-Port Low Rate CEM Interface Module Configuration Guide \(Cisco ASR 900 Series\)](#).

4-Port C37.94 Interface Module

Starting with Cisco IOS XE 3.18.1SP, 4-port C37.94 interface module is supported on the RSP2 module on the ASR 903 and ASR 902 routers. C37.94 is an IEEE Standard for Nx64 kbps optical fiber interfaces between tele-protection and multiplexer equipment.

For more information, see [Configuring IOT Serial Controller Configuration Guide, \(Cisco ASR 900 Series\)](#).

48-Port T1 CEM Interface Module Support

The 48-port T1 Interface Module is supported on the RSP3 module on the ASR 903 and ASR 907 routers. The 48-port T1/E1 with circuit emulation line card supports generic single or dual-port T1 trunk interfaces for voice, data, and integrated voice or data applications.

The following features are supported on this interface module:

- ACR and DCR Support
- Alarm History Support
- Loopback and BERT Support
- Performance Monitoring

For more information, see [48-Port T1/E1 CEM Interface Module Configuration Guide \(Cisco ASR 900 Series\)](#).

48-Port T3 CEM Interface Module Support

The 48-port T3 Interface Module is supported on the RSP3 module on the ASR 903 and ASR 907 routers. The 48-port T3/E3 with circuit emulation line card supports 48 ports. The channels on the T3 interfaces can be configured as either clear channel mode or channelized mode.

The following features are supported on this interface module:

- ACR and DCR Support
- Alarm History Support
- Loopback and BERT Support
- DS3 Channelization
- MDL Support
- Performance Monitoring

For more information, see [48-Port T3/E3 CEM Interface Module Configuration Guide \(Cisco ASR 900 Series\)](#).

FlexLSP Inter-area Support on Non-co-routed Mode

Flex LSP supports inter-area tunnels with non co-routed mode. For more information on the restrictions for this feature and its configuration details, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900\)](#).

WAN-PHY Support

Effective Cisco IOS XE 3.18.1SP, A900-IMA8Z Interface Modules support LAN/WAN-PHY mode on the ASR 900 RSP3 Module.

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

Leap Second

Starting with Cisco IOS-XE Release 3.18.1SP, you can configure the leap second event date and Offset value (+1 or -1) on master ordinary clock, hybrid boundary clock, dynamic ports, and virtual ports.

The following two new keywords are added to the `utc-offset` command:

- **leap-second**
- **offset**

You can also configure time properties holdover time on boundary clock, hybrid boundary clock, and dynamic ports. The following new command is introduced:

- **time-properties persist**

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

For more information, see [G.8275.1 Telecom Profile](#).

For more information, see [Cisco IOS Interface and Hardware Component Command Reference](#).

Port Licensing

Port Licensing is supported on the 1-Port OC-192 or 8-Port Low Rate CEM Interface Module. For more information, see [Software Activation Configuration Guide, Cisco IOS XE Release 3S \(ASR 903\)](#).

Pseudowire Redundancy with Uni-directional Active-Active

Pseudowire redundancy with uni-directional active-active feature configuration allows, pseudowires (PW) on both the working and protect circuits to remain in UP state to allow traffic to flow from the upstream. The **aps l2vpn-state detach** command and **redundancy all-active replicate** command is introduced to configure uni-directional active-active pseudo wire redundancy.

This feature is introduced on the ASR 900 RSP1 module.

For more information, see [Time Division Multiplexing Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

For more information, see [Cisco IOS Interface and Hardware Component Command Reference](#).

For more information, see [Cisco IOS Wide-Area Networking Command Reference](#).

New Software Features in Cisco IOS XE Release 3.18.1bSP

There are no new features introduced for Cisco IOS XE Release 3.18.1bSP.



Note

The Cisco IOS XE 3.18.1bSP release is applicable only on the Cisco ASR900 RSP3 module.

New Hardware Features in Cisco IOS XE Release 3.18SP

There are no new features introduced for Cisco IOS XE Release 3.18SP.

New Software Features in Cisco IOS XE Release 3.18SP

The following features are introduced in Cisco IOS Release 3.18SP

- [802.1ad](#)
- [DHCPv4 Snooping and DHCPv6](#)
- [EPL and EVPL using Local Connect](#)
- [Legacy Ethertypes](#)
- [Flex LSP](#)
- [Flexible Netflow Support](#)

- [G8275.1 Support](#)
- [IPsec](#)
- [IPV6 Multicast PIM](#)
- [IPV6 Access Control Lists](#)
- [IPv6 VPN4 & VPNv6](#)
- [MPLS TE FRR](#)
- [OTN Wrapper](#)
- [PTP Interoperability Improvements](#)
- [QoS Support on Ether Channel LACP Active Standby \(1:1\)](#)
- [VRRPv3 Support](#)
- [QoS Support on Ether Channel LACP Active Standby \(1:1\)](#)
- [SSM Support on Cisco ASR 900 Series 4-Port OC3/STM1 or 1-Port OC12/STM4 Module](#)
- [SSM Support on Cisco ASR 900 Series 4-Port OC3/STM1 or 1-Port OC12/STM4 Module](#)
- [Support for G.8273.2 Telecom Recommendation](#)
- [X21 Circuit Emulation Service](#)
- [VRRPv3 Support](#)

802.1ad

Configuring IEEE 802.1ad is supported on ASR900 RSP3 Module. IEEE 802.1ad enables the service providers to use the architecture and protocols of IEEE 802.1Q to offer separate LANs, bridged local area networks, or virtual bridged local area networks to a number of customers, with minimal cooperation or no cooperation between each customer and the service provider.

For more information, see [Carrier Ethernet Configuration Guide \(Cisco ASR 900 Series\)](#)

DHCPv4 Snooping and DHCPv6

DHCP v4 Snooping and DHCP are supported on ASR900 RSP3 Module. DHCP is widely used in LAN environments to dynamically assign host IP addresses from a centralized server, which significantly reduces the overhead of administration of IP addresses. DHCP also helps conserve the limited IP address space because IP addresses no longer need to be permanently assigned to hosts; only those hosts that are connected to the network consume IP addresses.

For more information, see [Configuring DHCP Features on the Cisco ASR 903 Router](#)

EPL and EVPL using Local Connect

EPL and EVPL using Local connect are supported on ASR900 RSP3 Module. Local connect (Layer 2 point to point service) is a point to point connection. It transparently transmits packet between two service instances which are configured on the same box. Local connect only connects two end points (service instances). This is different from the traditional L2 bridging.

For more information, see [Carrier Ethernet Configuration Guide \(Cisco ASR 900 Series\)](#)

Legacy Ethertypes

Legacy Ethertype is supported on ASR900 RSP3 Module. With the custom dot1q ethertype, you can select a non-standard (0x9100 and 0x9200) 2-byte ethertype in order to identify 802.1Q tagged frames. The router is allowed to interoperate with third party vendors' switches that do not use the standard 0x8100 ethertype to identify 802.1Q-tagged frames. For instance, if 0x9100 ethertype is used as the custom dot1q ethertype on a particular port, incoming frames containing the ethertype are assigned to the VLAN contained in the tag, immediately following the ethertype. Frames that arrive on that same port containing ethertypes other than 0x9100 are forwarded to service instance with default encapsulation, if present.

The interface can be configured with the following ethertypes:

- 0x9100
- 0x9200

For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#)

Flex LSP

Effective IOS-XE 3.18SP, Cisco ASR 900 Series Routers (RSP3 Module) support Flex Label Switched Paths (Flex LSPs).

Flex LSPs are LSP instances where the forward and the reverse direction paths are setup, monitored and protected independently and associated together during signaling. You use a RSVP Association object to bind the two forward and reverse LSPs together to form either a co-routed or non co-routed associated bidirectional TE tunnel.

For more information, see [MPLS Basic Configuration Guide, Cisco IOS XE Release 3S \(ASR 900\)](#)

Flexible Netflow Support

Netflow Monitoring is supported on RSP2 module. NetFlow provides data to enable network and security monitoring, network planning, traffic analysis, and IP accounting.

The following features are supported for Netflow:

- Netflow—IPv4 and IPv6 unicast flows
- Netflow Export over IPv4 and IPv6 addresses
- ISSU and SSO

For more information, see [Flexible Netflow Configuration Guide \(Cisco ASR 900 Series\)](#).

G8275.1 Support

G8275.1 feature is supported on ASR 900 RSP3 module.

For more information, see [Compatibility Matrix Cisco ASR 900 Series](#).

IPsec

Starting with Cisco IOS-XE Release 3.18SP, IPsec tunnel is supported only on the Cisco ASR903 and ASR907 routers with payload encryption (PE) images.

**Note**

IPsec license must be acquired and installed on the router for IPsec to work.

**Note**

NPE images shipped for Cisco ASR 900 routers do not support data plane encryptions. However, control plane encryption is supported with NPE images, with processing done in software, without the crypto engine.

The following features are supported for IPsec:

- Internet Key Exchange (IKE) for IPsec
- IKEv1 and IKEv2 Transform sets
- IPsec Virtual Tunnel Interfaces
- Encrypted Preshared Key
- IPsec Dead Peer Detection
- IPsec Anti-replay Window
- Public Key Infrastructure (PKI) support for IPsec

For more information, see [IPsec Configuration Guide, \(Cisco ASR 900 Series\)](#).

Starting with Cisco IOS-XE Release 3.18SP, Public Key Infrastructure (PKI) is supported on Cisco ASR 903 and Cisco ASR 907 routers.

The following features are supported for PKI:

- Deploying RSA Keys for PKI
- Authorization and Enrollment of Certificates
- CRL Support for PKI
- Certificate Enrollment for PKI
- OCSP

For more information on understanding and configuring PKI, see [Public Key Infrastructure Configuration Guide](#).

IPv6 Multicast PIM

IPv6 Multicast PIM is supported on ASR 900 RSP3 module. Protocol Independent Multicast (PIM) is used between devices so that they can track which multicast packets to forward to each other and to their directly connected LANs. PIM works independently of the unicast routing protocol to perform send or receive multicast route updates like other protocols. Regardless of which unicast routing protocols are being used in the LAN to populate the unicast routing table, Cisco IOS PIM uses the existing unicast table content to perform the Reverse Path Forwarding (RPF) check instead of building and maintaining its own separate routing table.

For more information, see [IP Multicast: Multicast Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#)

IPv6 Access Control Lists

IPv6 Access Control Lists is supported on ASR 900 RSP3 Module. Access lists determine what traffic is blocked and what traffic is forwarded at device interfaces and allow filtering of traffic based on source and destination addresses, and inbound and outbound traffic to a specific interface. Standard IPv6 ACL functionality was extended to support traffic filtering based on IPv6 option headers and optional, upper-layer protocol type information for finer granularity of control. Standard IPv6 ACL functionality was extended to support traffic filtering based on IPv6 option headers and optional, upper-layer protocol type information for finer granularity of control.

For more information, see [Security Configuration Guide: Access Control Lists, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)

IPv6 VPN4 & VPNv6

Starting with release 3.18SP, this feature is supported on the ASR 900 RSP3 module.

For more information, see [Layer 3 VPNs Configuration Guide, Cisco IOS XE Release 3S \(Cisco ASR 900 Series\)](#).

MPLS TE FRR

Effective XE 3.18SP, this feature is supported on the ASR 900 RSP3 module.

For more information, see [MPLS Traffic Engineering Path Link and Node Protection Configuration Guide, Cisco IOS XE Release 3S \(ASR 900 Series\)](#).

OTN Wrapper

Optical Transport Network (OTN) Wrapper feature provides robust transport services that leverage many of the benefits such as resiliency and performance monitoring, while adding enhanced multi-rate capabilities in support of packet traffic, plus the transparency required by Dense Wavelength Division Multiplexing (DWDM) networks. Cisco ASR 900 Series Routers acts as an aggregator for ethernet, TDM, and SONET traffic to connect to an OTN network and vice versa. The ports on the interface modules are capable of OTN functionality.

OTN Wrapper feature is supported on the following interface modules:

- 8x10GE (A900-IMA8Z) - The encapsulation type is OTU1e and OTU2e.
- 2x40GE (A900-IMA2F) - The encapsulation type is OTU3

For more information, see [Cisco ASR 900 Router Series Configuration Guide](#).

PTP Interoperability Improvements

- Threshold Clock-Class
- Threshold QL for NetSync Algorithm
- UTC Offset

Threshold Clock-Class

This release introduces support to set the threshold clock-class value. This allows the PTP algorithm to use the time stamps from an upstream master clock, only if the clock-class sent by the master clock is less than or equal to the configured threshold clock-class.

The following command is supported: **min-clock-class**

For more information, see [Configuring a Hybrid Boundary Clock](#)

Threshold QL for NetSync Algorithm

This release introduces support to set the threshold QL value for the input frequency source. The input frequency source, which is better than or equal to the configured threshold QL value, is selected to recover the frequency. Otherwise, the internal clock is selected.

The following command is supported: **network-clock synchronization input-threshold**

For more information, see [Configuring a Hybrid Boundary Clock](#)

UTC Offset

This release introduces support to set the UTC Offset value.

The following command is supported: **utc-offset**

For more information, see [Configuring a Master Ordinary Clock](#)

QoS Support on Ether Channel LACP Active Standby (1:1)

Link Aggregation Control Protocol (LACP) supports the automatic creation of ether channels by exchanging LACP packets between LAN ports. LACP packets are exchanged only between ports in passive and active modes. The support of Aggregate QoS method with single member link is introduced with the introduction of LACP 1:1 Active/Standby Etherchannel QoS support.

To use the hot standby or active standby or 1:1 feature in the event an ether channel fails, both ends of the LACP bundle must support the **lacp max-bundle** command.

For more information, see [QoS Support on Ether Channel LACP Active Standby \(1:1\)](#).

8K EFP with 4 Queue Model

In Cisco IOS XE Release 3.18SP, the 8K EFP (4 Queue Model) support allows up to 8000 EFPs at the system level. This feature is enabled with a specific sdm template, **enable_8k_efp**.

For more information, see [Quality of Service Configuration Guidelines for Cisco ASR 900 Router Series](#)

SSM Support on Cisco ASR 900 Series 4-Port OC3/STM1 or 1-Port OC12/STM4 Module

SSM is carried over OC-3 and OC-12 optical links. The SSM is transported in the S1 byte when it is carried over an optical line for SONET and SDH. The SSM messages enable SONET and SDH devices to select the highest quality timing reference automatically and avoid the timing loops.

SSM is supported on Cisco ASR 900 Series 4-Port OC3/STM1 or 1-Port OC12/STM4 Module. It has four ports and the default rate is OC-3. OC-3 rate is supported on all the four ports and OC-12 rate is supported on first port only.

For more information, see [Configuring Synchronous Ethernet ESMC and SSM](#).

Storm Control

Storm Control is supported on ASR 900 RSP3 Module. A traffic storm occurs when packets flood the LAN, creating excessive traffic and degrading network performance. The traffic broadcast and multicast suppression (or storm control) feature prevents LAN ports from being disrupted by a broadcast, multicast and unicast traffic storm on physical interfaces.

For more information, see [Security Configuration Guide: Broadcast and Multicast Suppression, Cisco IOS XE Release 3S \(ASR 900 Series\)](#)

Support for G.8273.2 Telecom Recommendation

Effective with Cisco IOS-XE Release 3.18SP, Cisco ASR 900 routers with RSP2 and RSP3 module support the G.8273.2 telecom recommendation.

For more information, see [G.8275.1 Telecom Profile](#)

X21 Circuit Emulation Service

The X21 Circuit Emulation feature enables transporting x21 traffic over MPLS core.

For more information, see [X21 CESoPSN Configuration Guide for Cisco ASR 900 Router Series](#)

VRRPv3 Support

VRRPv3 feature is supported on ASR 900 RSP3 Module.

Increase in VRRP Group Scale on the RSP3 module

The supported VRRP group scale is increased to 256 VRRPv3 groups (both IPv4 and IPv6) based on VRRP virtual MAC address.

- The group numbers for either IPv4 or IPv6 can be configured only from 1 to 255. VRRPv3 groups can be scaled up to 255, only if either IPv4 or IPv6 configured individually. If both IPv4 and IPv6 groups are scaled together, up to 256 groups can be scaled in any combination (for example, 128 IPv4 + 128 IPv6 groups)
- VRRPv3 group numbers can be reused multiple times. If VRRPv3 groups are repeated, the virtual MAC address scale should not exceed 256. If the assigned virtual MAC address crosses 256, then unpredictable behavior may be expected.

For more information, see [VRRPv3 Protocol Support](#)

For more information, see [Compatibility Matrix Cisco ASR 900 Series](#).



Restrictions and Caveats in Cisco IOS XE 3.6S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.6S releases.



Note

Because Cisco IOS XE 3.6S is based on Cisco IOS XE 3.5 inherited releases, some caveats that apply to Cisco IOS XE 3.5 releases also apply to Cisco IOS XE 3.6S. Release 3.5 is not described in this document; for a list of the software caveats that apply to Cisco IOS XE 3.5, see the [Release Notes for Cisco IOS XE Release 3.5](#).



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions](#), page 16-1
- [Caveats in Cisco IOS XE 3.6S Releases](#), page 16-6

Limitations and Restrictions

The following sections describe the Cisco ASR 903 Router limitations:

- [Limitations and Restrictions in Cisco IOS XE Release 3.6\(2\)S](#), page 16-1
- [Limitations and Restrictions in Cisco IOS XE Release 3.6\(1\)S](#), page 16-2
- [Limitations and Restrictions in Cisco IOS XE Release 3.6S](#), page 16-4

Limitations and Restrictions in Cisco IOS XE Release 3.6(2)S



Note

For a summary of limitations in Release 3.5S, see the [IOS XE 3.5 Release Notes](#).

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.6(2)S:

- SAToP and CESoPSN pseudowire traffic has a default MPLS Exp priority setting of 5 (high).

The limitations for this release are otherwise the same as those for IOS XE Release 3.6(2)S. For more information, see the [Limitations and Restrictions in Cisco IOS XE Release 3.6\(1\)S, page 2](#).

Limitations and Restrictions in Cisco IOS XE Release 3.6(1)S

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.6(1)S:



Note

For a summary of limitations in Release 3.5S, see the [IOS XE 3.5 Release Notes](#).

ATM IMA Limitation

- You can create a maximum of 16 IMA groups on each T1/E1 interface module.

Bridge Domain Interface Limitation

- The **mtu** command is not supported on BDI interfaces; however the **ip mtu** command is supported.

Clocking and Timing Limitation

- Only a single clocking input source can be configured within each group of eight ports (0-7 and 8-15) on the T1/E1 interface module using the network-clock input-source command.

EFP Limitation

- QinQ is not supported on trunk EFP interfaces.

Ethernet IM Limitations

- The Cisco ASR 903 Router does not support the Facilities Data Link (FDL) on Ethernet interfaces.
- The Cisco ASR 903 Router does not support the **mac-address** command on Gigabit Ethernet interface modules.
- 10 Gigabit Ethernet interface modules are not supported in slots 4 and 5.

When you install a Gigabit Ethernet IM in the topmost interface module slot (slot 5), the last interface (interface GigabitEthernet0/5/0) is not operational; the port is reserved for internal communication.

MLPPP Limitations

The following limitations apply when using MLPPP in IOS XE Release 3.6 on the Cisco ASR 903 Router:

- All links in an MLPPP bundle must be on the same interface module.
- All links in an MLPPP bundle must be of the same bandwidth.
- The Cisco ASR 903 Router supports a maximum of 8 links per bundle
- To change the MLPPP bundle fragmentation mode between enabled and disabled, perform a **shutdown/no shutdown** on the bundle.
- LFI is not supported
- Multiclass MLP is not supported
- The Cisco ASR 903 Router supports MLPPP statistics with the following limitations:

- Packet counters on the bundle display the number of fragments rather than packets.
- Control packets are accounted on the bundle.
- If you increase the maximum transmission unit (MTU) size on an MLPPP interface to a value higher than the maximum received reconstructed unit (MRRU) value on the peer interface, this can bring the MLPPP tunnel down. To restore the tunnel, perform a shutdown/no shutdown on the interface.

MPLS VPN Limitation

- MPLS VPN (L3VPN) Fragmentation does not function properly if an access interface has a higher MTU value than a core interface. To ensure that fragmentation functions correctly, configure the core interface MTU with a value that exceeds the access interface MTU and relevant headers.

OC-3 IM Limitations

- SDH framing mode is supported; SONET is not supported.
- Channelization is not supported.
- The optical interface module is designed for OC-3 and OC-12 traffic, but OC-12 functionality is not currently supported.

Pseudowire/AToM Limitation

- The Cisco ASR 903 Router supports ATM over MPLS N-to-one cell mode for a single ATM Virtual Channel Connections (VCCs) or Permanent Virtual Circuits (PVCs) to a pseudowire, but does not support mapping to multiple VCCs or PVCs.
- The Cisco ASR 903 Router does not support ATM over MPLS one-to-one cell mode.
- The Cisco ASR 903 Router supports pseudowire ping using the CW method; pseudowire ping using the TTL method is not supported.
- The Cisco ASR 903 Router supports a maximum of 2000 pseudowires in any combination.

QoS Limitations

For a description of QoS features and limitations on the Cisco ASR 903 Router in release 3.6S, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html.

Software Upgrade Limitation

- We recommend you set the **interface-module-delay** value to 150 or greater in order to ensure sufficient time for IM software upgrades.

Subinterfaces Limitation

- The Cisco ASR 903 router does not support subinterface configurations except on ATM interfaces.



Note You can configure similar functionality using multiple Ethernet Virtual Connections on an interface. For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#).

T1/E1 IM Limitations

- Inverting data on the T1/E1 interface is not supported—Inverting the data stream using the invert data interface command is not supported.

- Bit error rate test (BERT) patterns have limited support—Currently, only the 2¹¹, 2¹⁵, 2²⁰-O153, and 2²⁰-QRSS patterns are supported for BERT.

Limitations and Restrictions in Cisco IOS XE Release 3.6S

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.6S:



Note

For a summary of limitations in Release 3.5S, see the [IOS XE 3.5 Release Notes](#).

TDM Limitation

- The **configure replace** command is not supported for TDM interfaces.

EFP Limitation

- QinQ is not supported on trunk EFP interfaces.

QoS Limitations

For a description of QoS features and limitations on the Cisco ASR 903 Router in release 3.6S, see http://www.cisco.com/en/US/docs/wireless/asr_900/software/guide/chassis/Release3.6.0S/ASR903-Chassis-SW-36.html.

MLPPP Limitations

The following limitations apply when using MLPPP in IOS XE Release 3.6 on the Cisco ASR 903 Router:

- All links in an MLPPP bundle must be on the same interface module.
- All links in an MLPPP bundle must be of the same bandwidth.
- The Cisco ASR 903 Router supports a maximum of 8 links per bundle
- To change the MLPPP bundle fragmentation mode between enabled and disabled, perform a **shutdown/no shutdown** on the bundle.
- LFI is not supported
- Multiclass MLP is not supported
- The Cisco ASR 903 Router supports MLPPP statistics with the following limitations:
 - Packet counters on the bundle display the number of fragments rather than packets.
 - Control packets are accounted on the bundle.
- If you increase the maximum transmission unit (MTU) size on an MLPPP interface to a value higher than the maximum received reconstructed unit (MRRU) value on the peer interface, this can bring the MLPPP tunnel down. To restore the tunnel, perform a shutdown/no shutdown on the interface.

ATM IMA Limitation

- You can create a maximum of 16 IMA groups on each T1/E1 interface module.

Clocking and Timing Limitation

- Only a single clocking input source can be configured within each group of eight ports (0-7 and 8-15) on the T1/E1 interface module using the network-clock input-source command.

Ethernet IM Restrictions

- The Cisco ASR 903 Router does not support the Facilities Data Link (FDL) on Ethernet interfaces.
- The Cisco ASR 903 Router does not support the mac-address command on Gigabit Ethernet interface modules.
- On the Cisco ASR 903 Router, 10 Gigabit Ethernet interface modules are not supported in slots 4 and 5.
- When you install a Gigabit Ethernet IM in the topmost interface module slot (slot 5), the last interface (interface GigabitEthernet0/5/0) is not operational; the port is reserved for internal communication.

OC-3 IM Restrictions

- The **configure replace** command is not supported on the OC-3 IMs.
- SDH framing mode is supported; SONET is not supported.
- HDLC encapsulation is supported; other encapsulation types are not supported.
- Channelization is not supported.
- The optical interface module is designed for OC-3 and OC-12 traffic, but OC-12 functionality is not currently supported.

Pseudowire/AToM Limitation

- The Cisco ASR 903 Router supports ATM over MPLS N-to-one cell mode for a single ATM Virtual Channel Connections (VCCs) or Permanent Virtual Circuits (PVCs) to a pseudowire, but does not support mapping to multiple VCCs or PVCs.
- The Cisco ASR 903 Router does not support ATM over MPLS one-to-one cell mode.
- The Cisco ASR 903 Router supports pseudowire ping using the CW method; pseudowire ping using the TTL method is not supported.
- The Cisco ASR 903 Router supports a maximum of 2000 pseudowires in any combination.

Subinterfaces Limitation

- The Cisco ASR 903 router does not support subinterface configurations except on ATM interfaces.



Note You can configure similar functionality using multiple Ethernet Virtual Connections on an interface. For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#).

T1/E1 IM Limitations

- IP addresses are not supported—The current software release does not support specifying an IP address on a T1/E1 interface. You can specify an address on the interface by configuring it as a part of a CEM group using the **cem-group** command or as a part of an ATM IMA ima-group command. For more details, see the Cisco ASR 903 Series Aggregation Services Router Chassis Software Configuration Guide.
- Inverting data on the T1/E1 interface is not supported—Inverting the data stream using the invert data interface command is not supported.
- Bit error rate test (BERT) patterns have limited support—Currently, only the 2¹¹, 2¹⁵, 2²⁰-O153, and 2²⁰-QRSS patterns are supported for BERT.

Caveats in Cisco IOS XE 3.6S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.6S releases. The following information is provided for each caveat:

- **Symptom**—A description of what is observed when the caveat occurs.
- **Conditions**—The conditions under which the caveat has been known to occur.
- **Workaround**—Solutions, if available, to counteract the caveat.



Note

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select caveats of any severity. To reach the Bug Toolkit, log in to Cisco.com and go to http://www.cisco.com/pcgi-bin/Support/Bugtool/launch_bugtool.pl. (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.6S Releases:

- [Open Caveats—Cisco IOS XE Release 3.6\(2\)S, page 16-6](#)
- [Resolved Caveats—Cisco IOS XE Release 3.6\(2\)S, page 16-9](#)
- [Open Caveats—Cisco IOS XE Release 3.6\(1\)S, page 16-11](#)
- [Resolved Caveats—Cisco IOS XE Release 3.6\(1\)S, page 16-13](#)
- [Open Caveats—Cisco IOS XE Release 3.6\(0\)S, page 16-17](#)
- [Resolved Caveats—Cisco IOS XE Release 3.6\(0\)S, page 16-28](#)

Open Caveats—Cisco IOS XE Release 3.6(2)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.6(2)S.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtw72855

Symptoms: The router does not pass traffic towards the access side on virtual circuits (VCs) configured with QoS shaping output policy.

- Conditions:** Occurs when shaping is configured on class-default
- Workaround:** Configure shaping on user defined class
- CSCtw76473

Symptoms: The router displays packet drops on some VPLS pseudowire virtual circuits (VCs) on the disposition side.

Conditions: Occurs under the following conditions: -The core network is running MPLS-TP tunnels
-There is an SSO switchover on the remote end or an LDP neighbor reset on the peer end.

Workaround: There is no workaround.
 - CSCty45463

Symptoms: The router stops passing VPLS unicast traffic.

Conditions: Occurs after you reload the router while it is passing VPLS unicast traffic.

Workaround: Perform one of the following actions:

 - Clear the mac-address table on the affected virtual circuit (VC)
 - Stop VPLS traffic until the MAC address table is cleared, then resume VPLS traffic.
 - CSCty51990

Symptoms: The router may crash or restart; the console displays a SW_WDOG: expired message.

Conditions: Occurs under the following conditions:

 - The router is configured with 63 or more instances of a unique EVC configured with a unique bridge domain interface (BDI).
 - The router is sending IGMP joins to one multicast group.
 - You perform a shutdown/no shutdown on the interface sending IGMP join messages.
 - You perform an OIR on the router.

Workaround: There is no workaround.
 - CSCty70119

Symptoms: Port shaper rate changes do not take effect.

Conditions: Occurs when QoS policies attached to EVCs on an interface do not include a shaper configuration; the issue does not occur on EFP policies that include a shaper in a class.

Workaround: Include a shaper in one class of the EFP policy.
 - CSCtz20087

Symptoms: The router applies the class-default QoS policy to all outgoing traffic.

Conditions: Occurs under the following conditions: -You configure multiple egress QoS policies on a Gigabit Ethernet interface. -You configure a multilink interface with no ingress QoS policy

Workaround: There is no workaround.
 - CSCua10683

Symptoms: The router performs an RSP switchover instead of a thermal shutdown.

Conditions: Occurs when the **facility-alarm critical exceed-action shutdown** command is in the running configuration and some sensors go into a critical condition as indicated by the **show environment all** or **show facility-alarm status** commands.

Workaround: There is no workaround.

- CSCua13924

Symptoms: The convergence time for IS-IS IPv4 Loop Free Alternate Fast Reroute (LFA FRR) is greater than 50 milliseconds.

Conditions: Occurs when IS-IS LFA FRR reconverges following an interface shutdown while maintaining a large number of routes.

Workaround: There is no workaround.
- CSCua14704

Symptoms: The router stops passing traffic on a bridge-domain interface (BDI).

Conditions: Occurs when you apply the **ip mtu** command to a BDI interface for the first time.

Workaround: Remove and re-apply the **ip mtu** command.
- CSCua73104

Symptoms: The router does not increment QoS port shaper policy counters displayed by the show policy interface command.

Conditions: Occurs when you configure

 - A class-default policy on a physical interface
 - A class-based policy on an EVC interface

Workaround: There is no workaround; however, the router applies the QoS policy normally.
- CSCua95777

Symptoms: The router drops SAToP pseudowire traffic for 10 seconds following a core link failure.

Conditions: Occurs when the TDM controller generates an AIS and LOF alarm following a core link failure; the router drops traffic for 10 seconds after generating the alarm.

Workaround: There is no workaround.
- CSCua97383

Symptoms: A virtual circuit (VC) with an xconnect configuration stops forwarding traffic.

Conditions: Occurs with the 3.6(1) software under the following conditions:

 - You add and remove EFPs on an interface.
 - You remove and restore an interface configuration.
 - You are using multiple VTY sessions simultaneously to configure the router.

Workaround: Reload the router; you can use either of the following methods to avoid this issue:

 - Use a single VTY session for configuration.
 - Apply the **configuration mode exclusive** command to prevent multiple VTYS from entering configuration mode at once.
- CSCub10414

Symptoms: The router displays interface module (IM) traceback errors.

Conditions: Occurs with the GLC-SX-MMD or GLC-LH-SMD (Catskills) SFPs under the following scenarios:

 - IM reload
 - SSO
 - Router reload

- SFP insertion

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.6(2)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.6(2)S.

- CSCtx00558

Symptoms: The standby RSP crashes during bootup.

Conditions: The issue can occur during bootup of a dual RSP system.

Workaround: There is no workaround.

- CSCtx02522

Symptoms: The router displays intermittent traceback errors.

Conditions: Occurs when you configure REP.

Workaround: There is no workaround.

- CSCty22165

Symptoms: The router displays the following console message: Transceiver initialization failed: Unable to display idprom.

Conditions: The issue can occur when you perform an online insertion and removal (OIR) of an OC-3 interface module.

Workaround: Perform a hard OIR (IM replacement) followed by a soft OIR (RSP switchover) on the router.

- CSCty42336

Symptoms: BFD sessions flap on the router.

Conditions: Occurs when the router is running IP BFD sessions in echo mode with 64 200ms X3 timers.

Workaround: There is no workaround.

- CSCty57617

Symptoms: The router does not update IMA interface counters.

Conditions: Occurs after you perform an SSO on the router.

Workaround: There is no workaround.

- CSCty74129

Symptoms: A REP topology may reconverge during an RSP switchover. The console displays REP no-neighbor messages.

Conditions: Occurs when you configure REP between two Cisco ASR 903 Routers and you perform an RSP switchover.

Workaround: There is no workaround.

- CSCty77466

Symptoms: The port shaper rate changes on RSP switchover.

Conditions: Occurs under the following conditions: -You attach a shaper policy to an interface -The interface is configured with multiple EVCs -The EVC has a QoS policy attached.

- Workaround:** Remove and re-attach the policy on the interface.
- CSCty77704

Symptoms: CFM traceroute fails between two CE devices.

Conditions: Occurs under the following conditions:

 - There is a CFM xconnect between higher-level MEPs
 - The MEPs are between CE devices
 - The CE devices are in a different domain.

Workaround: Disable CFM on the Cisco ASR 903 Router acting as a PE device.
 - CSCtz03779

Symptoms: The standby RSP crashes during ISSU.

Conditions: Occurs when you perform an ISSU downgrade from Release 3.6 to 3.5.

Workaround: There is no workaround.
 - CSCtz54650

Symptoms: REP flaps intermittently.

Conditions: Occurs with a hybrid REP configuration containing ports with and without Fast LSL enabled.

Workaround: Configure all interfaces with Fast LSL.
 - CSCtz56517

Symptoms: The router drops MPLS packets with a checksum of 0xFFFF.

Conditions: Occurs when the ASR 903 is acting as a label disposition edge label switch router (LSR).

Workaround: There is no workaround.
 - CSCtz61153

Symptoms: The ASR 903 does not establish BFD neighbors over port-channel 16.

Conditions: Occurs when you configure BFD on port-channel 16 between two ASR 903 routers.

Workaround: Configure BFD on port-channels 1 - 15.
 - CSCtz75641

Symptoms: The router drops traffic over a port-channel.

Conditions: Occurs when you perform the following sequence of events:

 - Configure and bundle a Gigabit Ethernet interface into a port-channel
 - Remove the interface from the port-channel
 - Bundle another interface into the port-channel

Workaround: Reload the router.

Open Caveats—Cisco IOS XE Release 3.6(1)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.6(1)S.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtx00558

Symptoms: The standby RSP crashes during bootup.

Conditions: The issue can occur during bootup of a dual RSP system.

Workaround: There is no workaround.

- CSCtx02522

Symptoms: The router displays intermittent traceback errors.

Conditions: Occurs when you configure REP.

Workaround: There is no workaround.

- CSCty42336

Symptoms: BFD sessions flap on the router.

Conditions: Occurs when the router is running IP BFD sessions in echo mode with 64 200ms X3 timers.

Workaround: There is no workaround.

- CSCty70119

Symptoms: Port shaper rate changes do not take effect.

Conditions: Occurs when QoS policies attached to EVCs on an interface do not include a shaper configuration; the issue does not occur on EFP policies that include a shaper in a class.

Workaround: Include a shaper in one class of the EFP policy.

- CSCty74129

Symptoms: A REP topology may reconverge during an RSP switchover. The console displays REP no-neighbor messages.

Conditions: Occurs when you configure REP between two Cisco ASR 903 Routers and you perform an RSP switchover.

Workaround: There is no workaround.

- CSCty77466

Symptoms: The port shaper rate changes on RSP switchover.

Conditions: Occurs under the following conditions:

- You attach a shaper policy to an interface
- The interface is configured with multiple EVCs

- The EVC has a QoS policy attached.

Workaround: Remove and re-attach the policy on the interface.

- CSCtz03779

Symptoms: The standby RSP crashes during ISSU.

Conditions: Occurs when you perform an ISSU downgrade from Release 3.6 to 3.5.

Workaround: There is no workaround.

- CSCtz09708

Symptoms: The router cannot establish a PTP session when configured as a PTP slave device.

Conditions: Occurs when the router receives PTP packets containing a VPN or VRF label.

Workaround: There is no workaround.

- CSCtz20087

Symptoms: The router applies the class-default QoS policy to all outgoing traffic.

Conditions: Occurs under the following conditions: -You configure multiple egress QoS policies on a Gigabit Ethernet interface. -You configure a multilink interface with no ingress QoS policy

Workaround: There is no workaround.

- CSCtz54650

Symptoms: REP flaps intermittently.

Conditions: Occurs with a hybrid REP configuration containing ports with and without Fast LSL enabled.

Workaround: Configure all interfaces with Fast LSL.

- CSCtz56517

Symptoms: The router drops MPLS packets with a checksum of 0xFFFF.

Conditions: Occurs when the ASR 903 is acting as a label disposition edge label switch router (LSR).

Workaround: There is no workaround.

- CSCtz61153

Symptoms: The ASR 903 does not establish BFD neighbors over port-channel 16.

Conditions: Occurs when you configure BFD on port-channel 16 between two ASR 903 routers.

Workaround: Configure BFD on port-channels 1 - 15.

- CSCtz75641

Symptoms: The router does not pass traffic over an EVC PC port-channel.

Conditions: Occurs when you perform the following sequence of actions: -Remove an EVC member link from a port-channel interface -Configure a trunk EFP -Set the interface to default -Add the EVC member link back into the port-channel interface

Workaround: Reload the router.

- CSCua03439

Symptoms: The router displays error messages similar to the following:

```
%EVENTLIB-3-CPUHOG: SIP0: nile_mgr:
```

Conditions: Occurs when you boot the router running QoS configurations at a high scale, particularly queues.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.6(1)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.6S(1).

- CSCtu35052

Symptoms: Sweep ping fails when an ATM interface is configured with AAL5 encapsulation.

Conditions: Occurs when the ATM packet size is greater than 1484 bytes.

Workaround: There is no workaround.

- CSCtw94068

Symptoms: The router displays traceback messages, after which interfaces stop passing traffic.

Conditions: The issue can occur when you reload the router

Workaround: There is no workaround.

- CSCtx37768

Symptoms: QoS classification does not match traffic against an egress policy map between MPLS and IP access.

Conditions: This symptom is observed when a QoS policy is applied on an EVC bridge domain interface.

Workaround: Use one of the following workarounds:

- Reload the router.
- Remove and re-apply an encapsulation configuration such as a VLAN.
- Remove and re-attach the bridge domain under the EVC.
- Perform a shutdown/no shutdown on the BDI interface.

- CSCtx73691

Symptoms: The ASR 903 router forwards packets while in HSRP standby mode.

Conditions: Occurs when the ASR 903 is running HSRP and the HSRP session flaps.

Workaround: There is no workaround.

- CSCtx87145

Symptoms: The ASR 903 router does not support LDP label packets when transmitted in PTP delay-request messages.

Conditions: Occurs when you configure the ASR 903 router as a PTP (1588 version) boundary clock and the router sends an MPLS label packet within delay-request traffic.

Workaround: Align the grandmaster clock source to the same IGP domain and use a prefix-list for local label filtering.

- CSCty03480

Symptoms: The interface manager crashes when you remove a BFD template.

Conditions: Occurs when you remove a BFD template or modify an MPLS-TP label.

Workaround: There is no workaround.

- CSCty03617

Symptoms: The router displays the following message when executing a Stateful Switchover (SSO): %TRANSCEIVER-3-CHECKSUM_ERROR

Conditions: Occurs intermittently when the router is in SSO mode and performing a switchover between RSPs. The console displays this message repeatedly on the new active RSP.

Workaround: There is no workaround.

- CSCty26726

Symptoms: The IOS kernel crashes.

Conditions: Occurs following a reload on a dual RSP system.

Workaround: Power cycle the router.

- CSCty29449

Symptoms: The router crashes.

Conditions: The issue can occur when you shut down and reenables an interface module.

Workaround: There is no workaround.

- CSCty35365

Symptoms: The router drops traffic passing across ATM MPLS layer 2 virtual circuits (VCs).

Conditions: Occurs when you increase the scale above 100 VCs.

Workaround: There is no workaround.

- CSCty37479

Symptoms: The router experiences line protocol flapping on serial interfaces.

Conditions: Occurs with the A900-IMA40S and A900-IMA16D interface modules when the router is passing high volumes of HDLC or PPP traffic.

Workaround: Configure the no keepalive command on serial interfaces.

- CSCty47288

Symptoms: The router does not use a standby BITS clock source even when show commands indicate that the router has selected this clock source.

Conditions: Occurs when you configure a standby BITS clock source as an input clock source.

Workaround: There is no workaround.

- CSCty48493

Symptoms: The ASR 903 may reload with when acting as a hybrid clock.

Conditions: Occurs under the following conditions:

- The PLL mode is TOP CLIENT
- The session is in ACQUIRING state
- You issue the **no ptp clock or domain 0 hybrid** command.

Workaround: There is no workaround; however the issue occurs rarely.

- CSCty49157

Symptoms: Some members in an IMA group do not become active even though the interface controllers are up.

Conditions: Occurs when you perform an OIR on a remote line card or when the standby RSP becomes the active RSP.

- Workaround:** There is no workaround.
- CSCty51257

Symptoms: The T1/E1 interface module changes to inserted state during an in-service software upgrade (ISSU), causing the interface to fail and the router to generate a core file.

Conditions: Occurs when you perform an in-service software upgrade (ISSU) on a router with a T1/E1 interface module.

Workaround: Issue the shutdown command on the interface module before beginning ISSU; after ISSU is complete, issue the no shutdown command on the interface module.
 - CSCty57746

Symptoms: On the Cisco ASR 903 router, the **show environment** command displays incorrect values, including P0 and P1 voltages and Amps values.

Conditions: This symptom is observed with the Cisco ASR 903 router when you apply the **show environment** command.

Workaround: There is no workaround.
 - CSCty60908

Symptoms: The ASR 903 crashes and creates a core file.

Conditions: Occurs when the remote PE device is reloaded and an application such as VPLS or EoMPLS is running over MPLS TE FRR.

Workaround: There is no workaround.
 - CSCty61660

Symptoms: The Cisco ASR 903 Router displays a core dump file.

Conditions: Occurs when the remote PE device is reloaded while running VPLS-TP.

Workaround: There is no workaround.
 - CSCty71837

Symptoms: Ping does not work properly when traversing a BDI interface.

Conditions: Occurs when you configure MPLS on a BDI interface and ping packets are encapsulated in an MPLS header.

Workaround: There is no workaround.
 - CSCty72251

Symptoms: The router drops traffic following a reload.

Conditions: Occurs when you reload the router while running a VRF configuration.

Workaround: Remove the configuration, reload the router, and re-apply the configuration.
 - CSCty72901

Symptoms: Some CEM groups do not function correctly.

Conditions: Occurs when you configure more than 336 CEM groups on the T1/E1 or OC-3 interface module.

Workaround: There is no workaround; avoid configuring more than 336 CEM groups.
 - CSCty92979

Symptoms: The router loses ARP table entries after a network link flaps.

Conditions: Occurs following a network link flap when the routers ARP table contains entries for next-hop neighbors connected over a router bridge domain interface.

Workaround: There is no workaround.

- CSCty93985

Symptoms: Egress QoS policies do not take effect on an EFP interface.

Conditions: Occurs when you apply an egress QoS policy to an interface configured with more than 37 EFPs.

Workaround: There is no workaround.

- CSCty97391

Symptoms: The router drops traffic for approximately 9 milliseconds.

Conditions: Occurs on the active RSP following an HA switchover.

Workaround: There is no workaround.

- CSCtz07388

Symptoms: The router does not permit you to add an EFP interface to a split horizon group.

Conditions: Occurs after you make the following configuration changes:

- Configure 32 EFPs without a split horizon option to a bridge-domain interface.
- Configure 2 VPLS pseudowires.

Workaround: Configure 30 EFPs without a split horizon option, then apply the VPLS pseudowire configuration. After applying the VPLS pseudowire configuration, you can add 32 EFPs to the split horizon group.

- CSCtz17176

Symptoms: Layer 4 port range security ACLs do not function properly.

Conditions: Occurs when you apply port range security ACLs to an EVC interface.

Workaround: There is no workaround.

- CSCtz38119

Symptoms: The router does not complete a MAC address flush on the receiving side of a VPLS pseudowire.

Conditions: Occurs when the router receives a layer 2 MAC withdrawal over a VPLS pseudowire.

Workaround: There is no workaround.

- CSCtz40131

Symptoms: The router does not classify traffic when using QoS ACLs.

Conditions: Occurs when you apply a QoS ACL using the **range**, **lt**, and **gt** operators.

Workaround: There is no workaround.

- CSCtz45069

Symptoms: The router displays CPU hog messages or crashes.

Conditions: Occurs under conditions in which the router or an interface module is not responding and the interface module is in an improper state.

Workaround: There is no workaround; however the issue occurs very rarely.

- CSCtz45898

Symptoms: The router drops PTP packets.

Conditions: Occurs when PTP packets traverse a BDI with encapsulation configured.

Workaround: There is no workaround.

- CSCtz55566

Symptoms: The router displays I2C error messages intermittently.

Conditions: Occurs when you insert a copper SFP in the SFP interface module.

Workaround: There is no workaround.

- CSCtz83050

Symptoms: An interface module goes into Inserted state during ISSU.

Conditions: Occurs when you perform an ISSU upgrade or downgrade.

Workaround: There is no workaround.

- CSCtz96120

Symptoms: The router does not recognize interface modules after they are reset during a software upgrade.

Conditions: Occurs during ISSU upgrade or downgrade.

Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.6(0)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.6(0)S.

- CSCtr40582

Symptoms: Ping fails.

Conditions: Occurs when you configure AMI line code on a T1 controller.

Workaround: There is no workaround.

- CSCts75456

Symptoms: Multicast (S,G) entry not established.

Conditions: Occurs when you configure OIF and IIF within BDI that are part of a trunk EFP.

Workaround: Configure normal EVCs instead of trunk EVCs.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtv15403

Symptoms: 64 byte Line rate traffic not achieved.

Conditions: Occurs with more than 11 links in a MLP bundle with A900-IMA16D interface module and packet size 64 bytes.

- Workaround:** There is no workaround.
- CSCtw59780

Symptoms: BGP dynamic neighbor structures at the hub are not cleaned up after the spokes go down. The output of the **show ip bgp all sum** command continues to display dynamic neighbors.

Conditions: This issue is observed when all the following conditions are met:

 - The scale environment for dynamic neighbors contains several thousand peers.
 - The peers are brought up and then removed before they can transition into the Established state.

Workaround: There is no workaround.
 - CSCtw94068

Symptoms: The router displays traceback messages, after which interfaces stop passing traffic.

Conditions: The issue can occur when you reload the router

Workaround: There is no workaround.
 - CSCtx02522

Symptoms: The router displays intermittent traceback errors.

Conditions: Occurs when you configure REP.

Workaround: There is no workaround.
 - CSCtx37768

Symptoms: QoS classification does not match traffic against an egress policy map between MPLS and IP access.

Conditions: Occurs when you apply a QoS policy on an EVC bridge domain interface.

Workaround: Use one of the following workarounds:

 - Reload the router.
 - Remove and re-apply an encapsulation configuration such as a VLAN.
 - Remove and re-attach the bridge domain under the EVC.
 - Perform a **shutdown/no shutdown** on the BDI interface.
 - CSCtx38156

Symptoms: The router crashes.

Conditions: Occurs when you remove the **fast-reroute remote-lfa level-2 mpls-ldp** command from a configuration.

Workaround: This command is not currently supported; avoid including it in a configuration.
 - CSCtx44508

Symptoms: There is a delay in route processor synchronization after an SSO.

Conditions: This issue is observed when iBGP NSR is enabled and under scale conditions.

Workaround: There is no workaround.
 - CSCtx44688

Symptoms: Cannot configure policing and marking together in the same class of the egress policy-map.

Conditions: Set and police statements together in the same class of a policy is rejected at the CLI.

Workaround: In order to achieve marking and policing at the ingress we can use a conditional policer but this is not supported at the egress.

- CSCtx60094

Symptoms: Type 1 MVPN routes are not created.

Conditions: This issue is observed when the IP address of a loopback interface is changed.

Workaround: Create a dummy neighbor under the **address-family ipv4 mvpn** configuration or the **address-family ipv6 mvpn** configuration. Alternatively, unconfigure and reconfigure the MDT group under the VRF configuration.

- CSCtx73691

Symptoms: Standby gateway starts forwarding packet for some of the HSRP sessions.

Conditions: This is seen on flapping the HSRP session.

Workaround: There is no workaround.

- CSCtx75877

Symptoms: ICMP unreachable messages are sent even though route for destination ip is present in routing table. There is no ACL applied on any of the interface.

Conditions: This is seen on reload with VRRP configuration present on incoming interfaces.

Workaround: There is no workaround.

- CSCtx77233

Symptoms: The router displays an error message similar to the following:

```
FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP0: fman_fp_image: frr 0x1029 download to CPP
failed
```

Conditions: Occurs when you shut down a backup tunnel and shut down an FRR-protected interface, disabling TE tunnels.

Workaround: None; the error does not impact traffic forwarding.

- CSCtx75877

Symptoms: ICMP unreachable messages are sent when a route for the destination ip address exists in the routing table. There is no ACL applied on any of the interface.

Conditions: Occurs under the following conditions:

- There is a VRRP configuration applied to incoming interfaces.
- There are not ACLs applied on any interface.
- You reload the router.

Workaround: There is no workaround.

- CSCtx77233

Symptoms: The router displays an error message similar to the following:

```
FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP0: fman_fp_image: frr 0x1029 download to CPP
failed
```

Conditions: Occurs when you shut down a backup tunnel interface and a FRR-protected interface, bringing down MPLS TE tunnels.

Workaround: There is no workaround; the error does not appear to impact traffic forwarding.

- CSCtx80446

Symptoms: When the **no authentication** command is run on one BFD template, other MHOP BFD sessions on which authentication has been configured may change to the Down state.

Conditions: This issue is observed when there are multiple sessions that use different maps and templates.

Workaround: There is no workaround.
- CSCtx81871

Symptoms: MPLS convergence time is higher than normal.

Conditions: Occurs when the router is processing more than 3107 iBGP and label prefixes.

Workaround: There is no workaround.
- CSCty03480

Symptoms: The interface manager crashes when you remove a BFD template.

Conditions: Occurs when you remove a BFD template or modify an MPLS-TP label.

Workaround: There is no workaround.
- CSCty03617

Symptoms: The router displays the following message when executing a Stateful Switchover (SSO): %TRANSCIEVER-3-CHECKSUM_ERROR

Conditions: Occurs intermittently when the router is in SSO mode and performing a switchover between RSPs. The console displays this message repeatedly on the new active RSP.

Workaround: There is no workaround.
- CSCty13332

Symptoms: An imposition failure occurs on VCs configured with MPLS TP LSPs.

Conditions: Occurs under the following conditions:

 - There are input and output QoS policy-maps configured on service instance interfaces.
 - The router is configured with 255 MPLS TP tunnels.
 - The router is configured with a high number of virtual circuits (VCs).
 - The RSP in slot 0 is acting as the active RSP.
 - An event occurs that causes the router to tear down and rebuild all MPLS TP tunnels and VCs at once.

Workaround: Remove and reconfigure the service instance.
- CSCty13699

Symptoms: When L2VPN Pseudowire Stitching is configured between a static segment and a dynamic segment, both segments may move to the Down state.

Conditions: This issue is observed when L2VPN Pseudowire Stitching is configured between a static segment and a dynamic segment.

Workaround: There is no workaround.
- CSCty22165

Symptoms: The router displays the following console message: Transceiver initialization failed: Unable to display idprom.

Conditions: The issue can occur when you perform an online insertion and removal (OIR) of an OC-3 interface module.

Workaround: Perform a hard OIR (IM replacement) followed by a soft OIR (RSP switchover) on the router.

- CSCty24143

Symptoms: The router does not pass IPv6 OSPF traffic.

Conditions: Occurs when the router passes traffic at the full line rate of a link.

Workaround: Reduce the traffic rate by 10%.

- CSCty26726

Symptoms: The IOS kernel crashes.

Conditions: Occurs following a reload on a dual RSP system.

Workaround: Power cycle the router.

- CSCty28986

Symptoms: A configuration with a high number of down MEPs does not function properly.

Conditions: Occurs when you configure 500 or more down MEPs with 500 or more xconnect configurations between service instances.

Workaround: Configure no more than 300 CFM sessions.

- CSCty29449

Symptoms: The router crashes.

Conditions: The issue can occur when you shut down and reenables an interface module.

Workaround: There is no workaround.

- CSCty34054

Symptoms: The router displays CPU utilization traceback messages and drops all multicast traffic for 20–50 seconds.

Conditions: Occurs under the following conditions:

- Multicast is enabled with more than 500 multicast groups
- The router is using RSP1B in SSM mode
- BDI is configured on the access side of the router
- There are 24 EFPs on each bridge domain
- You enter a **shutdown** command on the access interface.

Workaround: There is no workaround.

- CSCty34521

Symptoms: The router does not pass CFM traffic over an Ethernet CFM cross-connect.

Conditions: Occurs under the following conditions:

- There is a CFM xconnect between two Cisco ASR 903 Router devices
- You perform an OIR and set a default interface.

Workaround: Do not continuously perform an OIR and set a default interface.

- CSCty34812
Symptoms: The router experiences traffic loss for between 10 and 50 seconds during RSP switchover.
Conditions: Occurs when you perform an RSP switchover on a router with a ten gigabit Ethernet interface module.
Workaround: There is no workaround.
- CSCty35365
Symptoms: The router drops traffic passing across ATM MPLS layer 2 virtual circuits (VCs).
Conditions: Occurs when you increase the scale above 100 VCs.
Workaround: There is no workaround.
- CSCty37479
Symptoms: The line protocol repeatedly drops (flaps) on serial interfaces.
Conditions: Occurs when you configure HDLC or PPP on serial interfaces on the A900-IMA4OS or A900-IMA16D interface modules when the router is passing high traffic volumes.
Workaround: Configure the **no keepalive** command on serial interfaces.
- CSCty38638
Symptoms: The router cannot download the ACL database.
Conditions: Occurs when the router is configured with an ACL containing more than 400 access control entries (ACEs).
Workaround: There is no workaround.
- CSCty39033
Symptoms: Interface modules stop passing traffic during an RSP switchover.
Conditions: Occurs when the router switches over to the standby RSP while traffic is passing on interface modules.
Workaround: There is no workaround.
- CSCty41536
Symptoms: The router crashes during when SNMP uses a high percentage of CPU for an extended period.
Conditions: Occurs when SNMP is running the background with an average of 50% CPU utilization for more than 8 hours.
Workaround: Reduce the load on the CPU using SNMP poll and SNMP walk.
- CSCty42336
Symptoms: BFD sessions flap on the router.
Conditions: Occurs when the router is running IP BFD sessions in echo mode with 64 200ms X3 timers.
Workaround: There is no workaround.
- CSCty42867
Symptoms: The router crashes.
Conditions: Occurs when you apply traffic soaking to the router with L2VPN services configured.
Workaround: There is no workaround.

- CSCty44345

Symptoms: The router experiences packet drops when passing 64 byte packets.

Conditions: Occurs when the router is passing 64 byte packets at the line rate on the OC-3 interface module.

Workaround: Configure a larger packet size on the interface.
- CSCty45058

Symptoms: Some CEM groups do not function correctly.

Conditions: Occurs when you configure more than 196 CEM groups on the T1/E1 or OC-3 interface module.

Workaround: There is no workaround; avoid configuring more than 196 CEM groups.
- CSCty45463

Symptoms: The router stops passing VPLS unicast traffic.

Conditions: Occurs after you reload the router while it is passing VPLS unicast traffic.

Workaround: Perform one of the following actions:

 - Clear the mac-address table on the affected virtual circuit (VC)
 - Stop VPLS traffic until the MAC address table is cleared, then resume VPLS traffic.
- CSCty46058

Symptoms: Shutting down a static multisegment VFI causes traffic to flow in one direction.

Conditions: This issue is observed when you configure a point-to-point VFI with two static neighbors and then shut down the VFI by using the **shutdown** command.

Workaround: There is no workaround.
- CSCty48710

Symptoms: The router drops multicast packets on layer 3 interfaces.

Conditions: Occurs when you configure 63 bridge domains per port and the router sends IGMP joins from all of the bridge domains to the same IGMP group.

Workaround: You can apply the following workarounds:

 - Applying a policy-map on each EVC can reduce the packet drops to some extent.
 - Increase the default port queue size.
- CSCty49041

Symptoms: The router drops VPLS traffic on one or more virtual circuits (VCs).

Conditions: Occurs when you reload a CPE or UPE device when there approximately 100 VCs configured between the UPE and NPE devices.

Workaround: Issue the **clear xconnect** command on the affected VC.
- CSCty49157

Symptoms: Some members in an IMA group do not become active even though the interface controllers are up.

Conditions: Occurs when you perform an OIR on a remote line card or when the standby RSP becomes the active RSP.

Workaround: There is no workaround.
- CSCty50377

Symptoms: The OC-3 interface module crashes when you perform multiple RSP switchovers.

Conditions: Occurs when the router is running a CEM configuration configured at full scale on all ports and passing traffic.

Workaround: There is no workaround.

- CSCty51175

Symptoms: Serial interfaces configured with HDLC display false LOF or AIS alarms.

Conditions: Occurs when you configure a high volume of serial interfaces using HDLC.

Workaround: Remove and re-apply the serial interface configuration.

- CSCty51257

Symptoms: The T1/E1 interface module changes to inserted state during an in-service software upgrade (ISSU), causing the interface to fail and the router to generate a core file.

Conditions: Occurs when you perform an in-service software upgrade (ISSU) on a router with a T1/E1 interface module.

Workaround: Issue the shutdown command on the interface module before beginning ISSU; after ISSU is complete, issue the no shutdown command on the interface module.

- CSCty51984

Symptoms: CEM circuits become inactive.

Conditions: Occurs when you perform an OIR, reload, or when you reconfigure a CEM circuit on the router. The issue occurs more consistently when the router is running more than 300 CEM circuits.

Workaround: Issue the **clear xconnect all** command.

- CSCty51990

Symptoms: The router may crash or restart; the console displays a `SW_WDOG: expired` message.

Conditions: Occurs under the following conditions:

- The router is configured with 63 or more instances of a unique EVC configured with a unique bridge domain interface (BDI).
- The router is sending IGMP joins to one multicast group.
- You perform a shutdown/no shutdown on the interface sending IGMP join messages.
- You perform an OIR on the router.

Workaround: There is no workaround.

- CSCty57746

Symptoms: The **show environment** command displays incorrect values, including P0 and P1 voltages, PSU status, PSU voltage, and critical alarms.

Conditions: Occurs when you apply the **show environment** command.

Workaround: There is no workaround.

- CSCty57751

Symptoms: The router crashes.

Conditions: Occurs under any of the following conditions:

- You perform an OIR on an interface module.
- You issue the no ppp multilink command on all MLP member links.

- You set the MTU to a higher value on an MLP bundle.

Workaround: There is no workaround.

- CSCty61660

Symptoms: The Cisco ASR 903 Router displays a core dump file.

Conditions: Occurs when the remote PE device is reloaded while running VPLS-TP.

Workaround: There is no workaround.

- CSCty66871

Symptoms: The router stops forwarding traffic across one or more EoMPLS virtual circuits (VC)s.

Conditions: Occurs when you perform a shut/no shutdown on the MPLS TE tunnel carrying the VC.

Workaround: Issue the clear xconnect command on the VC.

- CSCty70034

Symptoms: The router floods all EFPs in the same split horizon group with IGMP join messages.

Conditions: Occurs when the router is sending an IGMP join containing a dot1q tag for one EVC.

Workaround: None.

- CSCty72251

Symptoms: The router drops traffic following a reload.

Conditions: Occurs when you reload the router while running a VRF configuration.

Workaround: Remove the configuration, reload the router, and re-apply the configuration.

- CSCty72901

Symptoms: Some CEM groups do not function correctly.

Conditions: Occurs when you configure more than 196 CEM groups on the T1/E1 or OC-3 interface module.

Workaround: There is no workaround; avoid configuring more than 196 CEM groups.

- CSCty73142

Symptoms: An IPC Init failure occurs during downgrade, which makes the standby reload continuously.

Conditions: Occurs when you perform an ISSU downgrade from IOS XE 3.6 to IOS XE 3.5.1 or 3.5.

Workaround: There is no workaround.

- CSCty73362

Symptoms: The router experiences CPP download failures when sending IGMP join messages.

Conditions: Occurs when the router is configured with a trunk EFP in SM mode on the access side and is sending IGMP join messages to more than 1970 multicast groups.

Workaround: There is no workaround.

- CSCty73365

Symptoms: The router drops traffic on ATM subinterfaces using layer 2 PVCs.

Conditions: Occurs when you create 255 or more ATM PVCs.

Workaround: There is no workaround.

- CSCty73528
Symptoms: The router displays core dump files.
Conditions: Occurs when you perform an RSP switchover when CEF routes are configured.
Workaround: There is no workaround.
- CSCty74058
Symptoms: The router sends traffic for virtual circuits (VCs) over Gigabit Ethernet interfaces instead of MPLS-TP tunnels.
Conditions: Occurs when you perform an interface module OIR and the VCs are configured with a preferred path as the MPLS-TP tunnel.
Workaround: There is no workaround.
- CSCty74062
Symptoms: The router does not pass MLP traffic.
Conditions: Occurs when you perform an RSP switchover with an existing MLP configuration.
Workaround: There is no workaround.
- CSCty74129
Symptoms: A REP topology may reconverge during an RSP switchover. The consoles displays REP no-neighbor messages.
Conditions: Occurs when you configure REP between two Cisco ASR 903 Routers and you perform an RSP switchover.
Workaround: There is no workaround.
- CSCty77704
Symptoms: CFM traceroute fails between two CE devices.
Conditions: Occurs under the following conditions:
 - There is a CFM xconnect between higher-level MEPs
 - The MEPs are between CE devices
 - The CE devices are in a different domain.**Workaround:** Disable CFM on the Cisco ASR 903 Router acting as a PE device.
- CSCty79273
Symptoms: Multicast replication does not occur on all BDI interfaces on a given trunk EFP.
Conditions: Occurs under the following conditions:
 - The router is configured with 63 or more BDIs
 - The BDIs are configured as OIFs on a trunk EFP.
 - The port on which the EFP is configured is in a multicast group.**Workaround:** There is no workaround.
- CSCty80326
Symptoms: The router displays an Eamapper error.
Conditions: Occurs under the following conditions:
 - The router is configured with a port channel interface with 2 member links.
 - The port channel

- The configuration contains 48 EFPs with 24 EFPs in a given bridge domain
- SSM is enabled on the local and a remote router
- The router sends an IGMP join to a single multicast group.

Workaround: There is no workaround.

- CSCty87424

Symptoms: The router experiences a drop in forwarded packets on an MLPPP bundle.

Conditions: Occurs when the bundle is using 64% or more of the available bandwidth and an MTU value is configured on the bundle.

Workaround: There is no workaround.

- CSCty90425

Symptoms: The router crashes and reboots.

Conditions: Occurs when you perform a longevity test with traffic soaking while using Ethernet features such as EoMPLS, VPLS, CFM, or Y1731.

Workaround: There is no workaround.

- CSCty92979

Symptoms: The router loses ARP table entries after a network link flaps.

Conditions: Occurs following a network link flap when the router's ARP table contains entries for next-hop neighbors connected over a router bridge domain interface.

Workaround: There is no workaround.

- CSCty93985

Symptoms: Egress QoS policies do not take effect on an EFP interface.

Conditions: Occurs when you apply an egress QoS policy to an interface configured with more than 37 EFPs.

Workaround: There is no workaround.

- CSCty94081

Symptoms: The router displays an EgBridgeError_0 error when sending multicast traffic.

Conditions: Occurs in the following conditions:

- There are 40 bridge domain interfaces (BDIs) sending IGMP joins to a single multicast group.
- There are more than 40 OIFs and 24 EVCs in each bridge domain.

Workaround: There is no workaround.

- CSCty94437

Symptoms: The router crashes during RSP switchover or bootup.

Conditions: Occurs when L2VPN services are passing bidirectional traffic on the router and you perform a reload or RSP switchover.

Workaround: There is no workaround.

- CSCty96326

Symptoms: The router crashes.

Conditions: Occurs during bootup when the router is running BFD and CFM sessions that are offloaded to hardware.

Workaround: There is no workaround.

- CSCty96797

Symptoms: L2 OIF replication does not take effect when you add or delete an EVC.

Conditions: Occurs after a bridge domain or split horizon group change.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.6(0)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.6(0)S.

- CSCtx47195

Symptoms: BFD flaps when you perform a RSP switchover.

Conditions: Occurs under the following conditions:

- The router is configured as a mid-point node.
- The router is running MPLS-TP sessions with BFD.
- You perform a soft OIR.

Workaround: None.

- CSCtx83922

Symptoms: Interfaces go into a down-down state.

Conditions: The issue can occur when you use a script to implement a full-scale configuration.

Workaround: Perform an RSP switchover on both sides of the connection.

- CSCty04161

Symptoms: The RSP is unable to modify the configuration file or execute show interface commands.

Conditions: Occurs following an RSP switchover.

Workaround: None.

- CSCty43582

Symptoms: The router does not save the **port-channel load-balance-hash-algo** command in the running configuration.

Conditions: Occurs when you select the **src-ip**, **dst-ip**, or **src-dst-ip** hash algorithm.

Workaround: None.

- CSCty44236

Symptoms: Traffic switches over the protect-lsp of a mpls-tp tunnel interface, even though corresponding working-lsp link is active.

Conditions: Occurs when the protect-lsp bfd goes down while the protect lsp out-link interface going down.

Workaround: None.

- CSCty58020

Symptoms: Policy-map counters do not function properly.

Conditions: Occurs when you configure an ACL-based class-map under a policy-map.

Workaround: None.



Restrictions and Caveats in Cisco IOS XE 3.7S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.7S releases.



Note

Because Cisco IOS XE 3.7S is based on Cisco IOS XE 3.5 inherited releases, some caveats that apply to Cisco IOS XE 3.5 releases also apply to Cisco IOS XE 3.7S. Release 3.5 is not described in this document; for a list of the software caveats that apply to Cisco IOS XE 3.5, see the [Release Notes for Cisco IOS XE Release 3S](#).



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions, page 1](#)
- [Caveats in Cisco IOS XE 3.7S Releases, page 5](#)

Limitations and Restrictions

The following sections describe the Cisco ASR 903 Router limitations in Cisco IOS XE 3.7 releases:

- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(6\)S, page 2](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(5\)S, page 2](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(4\)S, page 2](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(3\)S, page 2](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(2\)S, page 2](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(1\)aS, page 3](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.7\(0\)S, page 3](#)

Limitations and Restrictions in Cisco IOS XE Release 3.7(6)S

- There are no changes in limitations and restrictions in Cisco IOS XE Release 3.7(6)S; the restrictions from IOS XE Release 3.7(2)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.7(5)S

There are no changes in limitations and restrictions in Cisco IOS XE Release 3.7(5)S; the restrictions from IOS XE Release 3.7(2)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.7(4)S

There are no changes in limitations and restrictions in Cisco IOS XE Release 3.7(4)S; the restrictions from IOS XE Release 3.7(2)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.7(3)S

There are no changes in limitations and restrictions in Cisco IOS XE Release 3.7(3)S; the restrictions from IOS XE Release 3.7(2)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.7(2)S

The following limitations and restrictions apply to Cisco IOS XE Release 3.7(2)S for the Cisco ASR 903 Router:

- LFA FRR Limitations—Release 3.7.2 has the following limitations for Loop Free Alternate Fast-reroute (LFA FRR):
 - To enable LFA FRR, you must include the **mpls ldp explicit-null** command. The implicit-null command is not supported.
 - LFA FRR is not supported with equal cost multipath (ECMP).
 - The ASR 903 supports up to 4000 LFA FRR routes.
 - Remote LFA tunnels are not HA aware; hence they are SSO co-existent but not SSO compliant.
- The restrictions from IOS XE Release 3.7(0)S apply to Release 3.7(2). For more information, see [Limitations and Restrictions in Cisco IOS XE Release 3.7\(0\)S, page 3](#).

Limitations and Restrictions in Cisco IOS XE Release 3.7(1)aS

There are no changes in limitations and restrictions in Cisco IOS XE Release 3.7(1)aS; the restrictions from IOS XE Release 3.7(0)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.7(0)S

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.7(0)S:

TDM Limitation

- The **configure replace** command is not supported for TDM interfaces.

ATM IMA Limitation

- You can create a maximum of 16 IMA groups on each T1/E1 interface module.

Bridge Domain Interface Limitation

- The **mtu** command is not supported on BDI interfaces; however the **ip mtu** command is supported.

Clocking and Timing Limitation

- Only a single clocking input source can be configured within each group of eight ports (0-7 and 8-15) on the T1/E1 interface module using the **network-clock input-source** command.
- Synchronous Ethernet clock sources are not supported with PTP. Conversely, PTP clock sources are not supported with synchronous Ethernet. However, you can use hybrid clocking to allow the router to obtain frequency using Synchronous Ethernet and phase using PTP.

EFP Limitation

- QinQ is not supported on trunk EFP interfaces.

Equal Cost Multipath Limitation

- The ASR 903 supports a maximum of 4 Equal Cost Multipath (ECMP) links.

Ethernet IM Limitations

- The Cisco ASR 903 Router does not support the Facilities Data Link (FDL) on Ethernet interfaces.
- The Cisco ASR 903 Router does not support the **mac-address** command on Gigabit Ethernet interface modules.
- 10 Gigabit Ethernet interface modules are not supported in slots 4 and 5.
- When you install a Gigabit Ethernet IM in the topmost interface module slot (slot 5), the last interface (interface GigabitEthernet0/5/0) is not operational; the port is reserved for internal communication.
- When you configure the copper and SFP Gigabit Ethernet interface modules on a router with redundant RSPs, the **speed** and **duplex** commands are not visible in interface configuration mode until you apply a **shutdown/no shutdown** to the interface.
- LACP Fast-Switchover Limitation—Cisco IOS has a default carrier-delay value of 2 seconds. When an LACP link fails, the router does not perform a switchover until the carrier-delay timer expires. The **carrier-delay** command helps reduce this value. We recommend that you set a **carrier-delay** value of greater than 0 as this value can result in slower convergence times. We also recommend that you set an identical **carrier-delay** value on all LACP member links.

MLPPP Limitations

The following limitations apply when using MLPPP on the Cisco ASR 903 Router:

- All links in an MLPPP bundle must be on the same interface module.
- All links in an MLPPP bundle must be of the same bandwidth.
- The Cisco ASR 903 Router supports a maximum of 8 links per bundle
- To change the MLPPP bundle fragmentation mode between enabled and disabled, perform a **shutdown/no shutdown** on the bundle.
- LFI is not supported
- Multiclass MLP is not supported
- The Cisco ASR 903 Router supports MLPPP statistics with the following limitations:
 - Packet counters on the bundle display the number of fragments rather than packets.
 - Control packets are accounted on the bundle.
- If you increase the maximum transmission unit (MTU) size on an MLPPP interface to a value higher than the maximum received reconstructed unit (MRRU) value on the peer interface, this can bring the MLPPP tunnel down. To restore the tunnel, perform a shutdown/no shutdown on the interface.

MPLS VPN Limitation

- MPLS VPN (L3VPN) Fragmentation does not function properly if an access interface has a higher MTU value than a core interface. To ensure that fragmentation functions correctly, configure the core interface MTU with a value that exceeds the access interface MTU and relevant headers.

OC-3 IM Limitations

- The **configure replace** command is not supported on the OC-3 IMs.
- SDH framing mode is supported; SONET is not supported.
- The optical interface module is designed for OC-3 and OC-12 traffic, but OC-12 functionality is not currently supported.
- If you issue the **no card type** command on the controller, you must reload the router in order to configure a new **card type** value.
- We recommend that you use Release 3.7.2 or later when using the OC-3 IM with high availability (HA) features such as stateful switchover (SSO).

Pseudowire/AToM Limitation

- The Cisco ASR 903 Router supports ATM over MPLS N-to-one cell mode for a single ATM Virtual Channel Connections (VCCs) or Permanent Virtual Circuits (PVCs) to a pseudowire, but does not support mapping to multiple VCCs or PVCs.
- The Cisco ASR 903 Router does not support ATM over MPLS one-to-one cell mode.
- The Cisco ASR 903 Router supports pseudowire ping using the CW method; pseudowire ping using the TTL method is not supported.
- The Cisco ASR 903 Router supports a maximum of 2000 pseudowires in any combination.

QoS Limitations

- For a description of QoS features and limitations on the Cisco ASR 903 Router in release 3.7S, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.7.0S/ASR903-Chassis-SW-37.html>.

Software Upgrade Limitation

- We recommend you set the **interface-module-delay** value to 150 or greater in order to ensure sufficient time for IM software upgrades.

Subinterfaces Limitation

- The Cisco ASR 903 router does not support subinterface configurations except on ATM interfaces.



Note You can configure similar functionality using multiple Ethernet Virtual Connections on an interface. For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#).

T1/E1 IM Limitations

- Inverting data on the T1/E1 interface is not supported—Inverting the data stream using the invert data interface command is not supported.
- Bit error rate test (BERT) patterns have limited support—Currently, only the 2¹¹, 2¹⁵, 2²⁰-O153, and 2²⁰-QRSS patterns are supported for BERT.

Caveats in Cisco IOS XE 3.7S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.7S releases.

In this section, the following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

**Note**

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select caveats of any severity. To reach the Bug Toolkit, log in to Cisco.com and go to http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl. (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.7S Releases:

- [Open Caveats—Cisco IOS XE Release 3.7\(6\)S, page 6](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(6\)S, page 6](#)
- [Open Caveats—Cisco IOS XE Release 3.7\(5\)S, page 7](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(5\)S, page 8](#)

- [Open Caveats—Cisco IOS XE Release 3.7\(4\)S, page 10](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(4\)S, page 13](#)
- [Open Caveats—Cisco IOS XE Release 3.7\(3\)S, page 20](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(3\)S, page 23](#)
- [Open Caveats—Cisco IOS XE Release 3.7\(2\)S, page 37](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(2\)S, page 46](#)
- [Open Caveats—Cisco IOS XE Release 3.7\(1\)aS, page 48](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(1\)aS, page 52](#)
- [Open Caveats—Cisco IOS XE Release 3.7\(0\)S, page 54](#)
- [Resolved Caveats—Cisco IOS XE Release 3.7\(0\)S, page 61](#)

Open Caveats—Cisco IOS XE Release 3.7(6)S

There are no open caveats in Cisco IOS XE Release 3.7(6)S.

Resolved Caveats—Cisco IOS XE Release 3.7(6)S

This section documents the resolved caveats for the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(6)S.

- CSCub50545
Symptom: Traceback observed on router when J1 functionality is used.
Conditions: This issue occurs when J1 expect message is configured.
Workaround: There is no workaround.
- CSCum76276
Symptom: Cross-connect backup **force-switchover interface** command does not showing the 10G option.
Conditions: This issue occurs on trying to perform a force-switchover for the 10G interface.
Workaround: There is no workaround.
- CSCun83688
Symptom: Sub-package mode boot fails on the router.
Conditions: This issue occurs when the sub-package mode boot is performed from USB.
Workaround: Boot using the consolidated mode from USB with stand-alone RSP.
- CSCuo26634
Symptom: Crash observed on router when **show frr-manager client det** command is executed.
Conditions: This issue is observed when **show frr-manager client *client-name* det** command is executed, and the client does not exist.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.7(5)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(5)S.

- CSCtq24011

Symptoms: The routers acts as though local proxy-arp is configured and does a proxy-arp for the systems in the same subnet.

Conditions: This issue occurs when the router receives ARP request on an interface when the interface is not fully initialized. The connected routes are not added in the routing table causing the proxy-arp to reply and thus the wrong ARP is entered.

Workaround: Execute a **shutdown** followed by a **no shutdown** on the routers.

- CSCty63969

Symptom: Ping fails to remote MEP.

Conditions: This issue occurs on configure CFM and a ping to remote MEP with packet size greater than 1478 bytes is performed.

Workaround: There is no workaround.

- CSCtz43158

Symptom: Memory leaks are seen on configuring IP FRR remote LFA on the router.

Conditions: This issue occurs on configuring and un-configuring IP-FRR remote LFA on the router.

Workaround: There is no workaround.

- CSCuc08397

Symptom: When IFM is configured on EVC BD, with encapsulation default in the core, the remote MEPS are not learned.

Conditions: This issue is observed when encapsulation default is configured towards the core facing side.

Workaround: There is no workaround.

- CSCuc24927

Symptom: Segmentation faults observed on the router.

Conditions: This issue is seen when IMA, CEM and Serial are configured on different controllers on the router and the image is loaded.

Workaround: Do not combine IMA, CEM and Serial configurations.

- CSCud55799

Symptom: Multiple priority commands get accepted per policy.

Conditions: This issue occurs when a policy-map with priority is configured in one of its classes. Adding another class with policer first and then with priority causes this issue..

Workaround: There is no workaround.

- CSCud90362

Symptom: The SYNC packets might go out quite irregularly when PTP master (OC/BC) is configured on the router.

Conditions: This issue occurs when the router is configured as PTP master.

Workaround: There is no workaround.

- CSCue73478
Symptom: The standby RSP Sync LED goes to holdover after switchover.
Conditions: This issue occurs in normal working conditions. This is a cosmetic issue.
Workaround: There is no workaround.
- CSCuf35542
Symptom: PFM fails for about fiveminutes after OIR on the master.
Conditions: This issue occurs when OIR is triggered on the master.
Workaround: Wait for 5-6 minutes after the OIR
- CSCug05214
Symptom: QOS does not reject policy-map with match EXP and extended num ACL (permit L4).
Conditions: This issue occurs when the policy-map with match exp and L4 ACL is configured and applied on main interface.
Workaround: There is no workaround.
- CSCug08566
Symptom: Next-hop of a static redistributed route is unexpectedly marked as unreachable.
Conditions: This issue occurs when redistributing a static route into BGP (in global or VRF table (X)), whose next-hop points to another VRF (Y), the next-hop will be looked up in (X), and thus the route may be marked with next-hop unreachable.
Workaround: Manually set the next-hop to 0 when redistributing using the **set ip next-hop peer-address** command.
- CSCul01582
Symptom: The PID for the new fan tray is not reflected for **show inventory** command output.
Conditions: This issue occurs when the **show inventory** command is issued. The fan tray PID does not show up for SNMP walk for Entity MIB.
Workaround: There is no workaround.
- CSCul50181
Symptom: The router may see unicast traffic not being forwarded out of the Gigabit Ethernet interface while multicast traffic is being processed by the router correctly. Pings fail to a directly connected neighbour but OSPF would be up.
Conditions: This issue occurs when BDI configs are configured on the Gigabit Ethernet interface.
Workaround: Reload the router.

Resolved Caveats—Cisco IOS XE Release 3.7(5)S

This section documents the resolved caveats for the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(5)S.

- CSCua20021
Symptom: The **clear ethernet cfm ais** command with evc option does not work.
Conditions: This issue occurs when evc name with **clear ethernet cfm ais** command is specified.
Workaround: Use the **service** option instead.

- CSCue69818
Symptom: The **show inventory** command displays wrong serial number.
Conditions: This issue occurs when the inventory is managed by the main serial number. However the RPS and IM display PCB Serial Number in the show inventory output.
Workaround: Use the **show diag all eeprom** detail command.
- CSCUh76845
Symptom: OSPF is stuck in INIT after performing a **shutdown** followed by **no shutdown** of the OSPF process. The router shows an LSA to be present on flood-list in the **show ip ospf flood-list** command output.
Conditions: This issue occurs after executing a **shutdown** followed by **no shutdown** of the OSPF process. The issue is only seen in timing conditions.
Workaround: Execute a **shutdown** followed by **no shutdown** on the physical interface which has LSA on its flood-list.
- CSCUi50577
Symptom: Traffic drop observed on the router after IM OIR.
Conditions: This issue occurs after an IM OIR.
Workaround: There is no workaround.
- CSCUi73921
Symptom: The 10 Gigabit Ethernet Interface Power and Status LED on the IM does not working as expected.
Conditions: This issue occurs on module OIR or reload.
Workaround: There is no workaround.
- CSCUi85019
Symptom: Executing **show xconnect** results in a memory leak. This issue was observed after issuing the **show memory debug leaks chunks** command as in example below:

```
Router# show memory debug leaks chunks Adding blocks for GD...
I/O memory
Address Size Alloc_pc PID Alloc-Proc Name
Chunk Elements:
AllocPC Address Size Parent Name
Processor memory
Address Size Alloc_pc PID Alloc-Proc Name AA3F8B4 2348 6D0B528 97 Exec
PW/UDP VC event trace
```


Conditions: This issue is observed when one or more xconnects are configured with UDP encapsulation.
Workaround: There is no workaround.
- CSCUi89069
Symptom: An ISIS flap is observed on performing SSO.
Conditions: This issue occurs when **nsf ietf** is configured and one or more loopbacks are configured as passive interfaces.
Workaround: Perform the following;
 - a. Use **nsf cisco**.
 - b. Use **nsf ietf** and configure **ip router isis process_name** on the loopback interfaces.

- CSCui89854
Symptom: Mismatch of the Gigabit Ethernet interface when Wait-to-Restore (WTR) is configured.
Conditions: This issue occurs when the Gigabit Ethernet interface is configured as input source and the WTR is configured as 0 and **shutdown** and **no shutdown** is executed.
Workaround: Configure the WTR greater than 20 seconds.
- CSCui99309
Symptom: IPv6 BFD with static client does not come up with VRF.
Conditions: This issue is seen on configuring BFD.
Workaround: There is no workaround.
- CSCuj11232
Symptom: Changing the local label on an existing static (no signaling), Any Transport over MPLS (AToM) pseudowire, or changing the static pseudowire to a dynamic one (with LDP signaling) may cause traffic to fail to traverse the pseudowire.
Conditions: This issue is observed when either the configured value of the static local label is changed, or if the pseudowire is changed to a dynamic one.
Workaround: Unconfigure the existing xconnect or pseudowire before entering the new configuration.
- CSCul14571
Symptom: The router crashes after OSPFv3 is unconfigured from an interface.
Conditions: This issue is observed when NSR is enabled.
Workaround: Unconfigure NSR before unconfiguring OSPFv3 from an interface.
- CSCum40613
Symptom: The Cisco ASR 903 TOD port tx when configured as slave does not work.
Conditions: This issue occurs when TOD is configured.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.7(4)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(4)S.

- CSCtw92458
Symptom: IFM CC messages are leaked to unmatched encapsulation on that bridge domain (BD).
Conditions: This issue occurs when EVCs with different encapsulation are present on same BD.
Workaround: There is no workaround.
- CSCty63969
Symptom: Ping fails to remote MEP.
Conditions: This issue occurs when CFM is configured and a ping to remote MEP with packet size greater than 1478 bytes is executed.
Workaround: There is no workaround.
- CSCua77688

Symptom: The router experiences remote CFM MEP flapping.

Conditions: Occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.

Workaround: Reduce the rate of traffic.

- CSCua99096

Symptoms: The **show ima interface** command omits some IMA group information such as ImaGroupSymmetry.

Conditions: This issue occurs when the **show ima interface** command.

Workaround: There is no workaround.

- CSCub94462

Symptom: The router displays object download error messages on the console.

Conditions: This issue occurs under the following conditions

- Execute the **mac address sticky** command.
- Configure 25 incremental MAC addresses and execute the **clean mac-address-table bdomain** command
- Remove a mac security sticky configuration from an EVC interface.

Workaround: Avoid issuing the **clear mac-address-table** command when the **mac security sticky** command is applied.

- CSCuc08397

Symptom: When IFM is configured on EVC BD, with encapsulation default in the core, the remote MEPS are not learnt.

Conditions: This issue is seen when encapsulation default is configured on the core facing side.

Workaround: There is no workaround.

- CSCud09142

Symptom: FP active error messages are seen when the tunnel-tp interface is removed in a high-availability setup.

Conditions: This issue is seen after removing tunnel-tp interface.

Workaround: There is no workaround.

- CSCud34600

Symptom: Event hog messages are received when 21k to 25k routes are advertised into MBGP and exported from one PE to another.

Conditions: This issue occurs when the redistributing routes range from 21k to 25k routes from OSFP are moved into MBGP and are exported from one PE to another.

Workaround: There is no workaround.

- CSCud90362

Symptom: the SYNC packets go out quite irregularly when PTP master is configured.

Conditions: This issue is seen when the router is configured as PTP master.

Workaround: There is no workaround.

- CSCue24854

Symptom: Loss of 70 msec are observed when performing an IM OIR in a remote LFA ring.

- Conditions:** This issue occurs when soft OIR is performed.
- Workaround:** Do a hard OIR to get less than 50 msec loss.
- CSCue73478

Symptom: The standby RSP Sync LED become holdover after switchover.

Conditions: This issue occurs in normal conditions,

Workaround: There is no workaround. This issue is cosmetic.
 - CSCue96886

Symptom: Complete MAC Address space is not available on the RSP.

Conditions: This issue occurs after removing the service instance with the MAC Addresses learnt on the BD.

Workaround: Shutdown the service instance corresponding to bridge-domain and clear the MAC-address-table of that bridge-domain. Remove the service instance.
 - CSCuf07508

Symptom: The Gigabit Ethernet port on IMA8S may not come up after reload.

Conditions: This issue occurs when the router is reloaded multiple times

Workaround: Perform an IM OIR.
 - CSCuf44077

Symptom: The show interface command output displays incorrect speed values after SSO.

Conditions: This issue occurs when 100M SFPs are used

Workaround: Perform hardware module reset.
 - CSCuf86247

Symptom: SNMP MIB variables related to BDI counters do not function properly.

Conditions: This issue occurs when SNMP MIB variables related to BDI interface counters are used.

Workaround: There is no workaround.
 - CSCuh46103

Symptom: The BDI statistics not getting incremented.

Conditions: This issue is observed when the **show interface bdi statistics** command is executed. The ingress and egress statistics displayed do not get incremented even if the traffic is going through the BDI interface.

Workaround: Use **show platform hardware pp active interface statistics bdi** command to view the statistics.
 - CSCuh65489

Symptom: The BGP session goes down when ICMP echo-request of 1500 pps is received.

Conditions: This issue occurs when the router has BGP peers and receives the ICMP-echo request. The BGP hold timer expires and BGP peer goes down.

Workaround: There is no workaround.
 - CSCuh79730

Symptom: The transmitting frequency is incorrectly displayed in case of DWDM-XFP-C.

Conditions: This issue occurs when **show hw-module subslot 0 transceiver idprom** command is executed.

Workaround: There is no workaround.

- CSCui50862

Symptom: Few CFM primary sessions stays inactive.

Conditions: This issue occurs when CFM domain with SLA is configured.

Workaround: There is no workaround.

- CSCui87257

Symptom: The interface clock is not detected after a switchover

Conditions: This issue occurs after a switchover is performed from RSP0 to RSP1.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.7(4)S

This section documents the resolved caveats for the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(4)S

- CSCtz43467

Symptom: All commands listed under the REP configuration modes cannot be configured. This was seen while configuring REP with BDI and configuring more than one source ports in a span session.

Conditions: This issue occurs in normal working conditions.

Workaround: There is no workaround.

- CSCua95675

Symptom: An Ethernet virtual circuit (EVC) interface stops forwarding traffic.

Conditions: This issue occurs when multiple EVCs are configured on a single interface. The EVCs have the same outer tag VLAN. When one of the EVCs is removed from the configuration, the other EVCs with the same outer tag VLAN stop passing traffic.

Workaround: Issue a **shutdown** command followed by a **no shutdown** command on the Ethernet interface.

- CSCuc60148

Symptom: System does not shut down when the temperature sensor reaches shutdown threshold region.

Conditions: This issue occurs when the temperature sensors reaches the shutdown threshold region.

Workaround: Configure the **facility-alarm critical exceed-action shutdown** command has to enable this system shutdown behavior.

- CSCud61551

Symptom: Serial Number of the RSP in slot 1 is not displayed some times in the **show inventory** command output.

Conditions: This issue occurs under normal working conditions.

Workaround: Reload the router again.

- CSCue24621

Symptom: When one EFP is shut, traffic get stops for other EVCs.

Conditions: This issue occurs where there are multiple qinq EFPs with same outer vlan tag on one interface.

Workaround: There is no workaround.
- CSCue25349

Symptom: Tracebacks seen on the router with inject bypass set to OFF.

Conditions: This issue occurs after shutting down the core facing interface or any OSPF enabled interface.

Workaround: There is no workaround. These traces does not have any functional impact.
- CSCue51682

Symptom: The REP protocol flaps, as indicated by the following error messages:

```
*Feb 8 06:51:38.857: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
non-operational due to neighbor not responding *Feb 8 06:51:39.096: %REP-4-LINKSTATUS:
GigabitEthernet0/0/1 (segment 10) is operational
```

Conditions: This issue occurs under the following conditions:

 - The router is sending traffic using the incremental MAC address table Fast LSL is configured using a 200ms timer.
 - The router is configured with more than 2000 MAC addresses.

Workaround: Remove fast LSL from the REP configuration.
- CSCue60699

Symptom: The router auto-negotiates full duplex with 1000M half/full duplex configuration.

Conditions: This issue occurs when the router has Copper SFP with auto-negotiate enabled. and SFP is configured with 1000M half-duplex mode.

Workaround: There is no workaround.
- CSCue61803

Symptom: The interface modules do not get powered off, when router is reloaded.

Conditions: This issue is occasionally seen on reload.

Workaround: There is no workaround.
- CSCue61850

Symptom: Memory allocation observed fro CFM EVC BD offload cases- scale configurations

Conditions: This issue occurs with CFM EVC BD, when 256 session of 3.3ms interval and 256 SLM session are configured and a **shutdown** command followed by a **no shutdown** command is issued on the traffic sending interface.

Workaround: Configure CFM session between 50-100.
- CSCue67835

Symptom: OSPF flap with aggressive timers (2 sec hello interval, 6 sec dead interval).

Conditions: This issue occurs on router Stateful switchover (SSO).

Workaround: Use the default OSPF hello timers.
- CSCue75372

Symptom: Time-hog traceback seen on router reload or IM reload.

Conditions: This issue occurs on router bootup or IM bootup.

Workaround: There is no workaround.

- CSCue77596

Symptom: CoS value gets wrongly marked for a qinq packet.

Conditions: This issue occurs when a service instance with dot1q encapsulation and **no rewrite** is configured on the interface; The policy map attached in the ingress has marking configured.

Workaround: There is no workaround.

- CSCue80866

Symptom: Label exhaustion message is seen with scale match vlan and match PHB policy; Classification fails to work.

Conditions: This issue occurs with TEFP with range of BDs that have match VLANs of the corresponding BD and a child policy to match prec/cos.

Workaround: There is no workaround.

- CSCue83621

Symptom: Policy-map stops working on removing class default class dynamically.

Conditions: This issue occurs when policy-map is attached to target and class-default of top level is deleted dynamically.

Workaround: Detach and reattach the policy-map on target.

- CSCue91533

Symptom: Traffic through VPLS pseudowire is flooded due to MAC aging.

Conditions: This symptom is observed when bridge descriptor index (internal index) assigned to MAC address exceeds 20480.

Workaround: There is no workaround.

- CSCue94811

Symptom: Process crash on standby router would not generate a core file.

Conditions: This issue occurs under normal conditions.

Workaround: There is no workaround.

- CSCuf02518

Symptom: IPv4 traffic gets affected on IPv6 ACL applied interface.

Condition: This issue occurs when both If IPv4 and IPv6 ACLs share the same label, the IPv4 traffic on the interface on which IPv6 ACL is applied is impacted.

Workaround: There is no workaround.

- CSCuf43992

Symptom: The router crashed with local span configuration.

Conditions: This issue occurs with local span configuration.

Workaround: Configure erspan configuration with source and destination erspan sessions in the router.

- CSCuf51509

Symptom: WRED counters for CS0 does not work in **show policy-map interface** command.

- Conditions:** This issue is observed when **show policy-map interface** command is executed.
- Workaround:** There is no workaround.
- CSCuf53527

Symptom: Cos inner value gets copied into the cos value.

Conditions: This issue occurs when QinQ without rewrite service instance is configured.

Workaround: Apply the qos policy-map to the cos inner value.
 - CSCuf56723

Symptom: The interface LED glows green when shut.

Conditions: This issue occurs after an SSO is performed.

Workaround: There is no workaround.
 - CSCuf65301

Symptom: Micro flaps observed on the router.

Conditions: This issue is seen when system is kept idle for hours.

Workaround: There is no workaround
 - CSCuf79397

Symptom: F1 is stuck in init state after the standby RSP reloads.

Conditions: This issue occurs on a reload or OIR of the standby RSP.

Workaround: Reload the standby RSP again.
 - CSCuf83886

Symptom: Label exhaust message is seen even on valid case if policy is configured before xconnect is configured on scaled configuration.

Conditions: This issue occurs when a service-policy is configured before configuring xconnect on the router that has consumed close to max labels.

Workaround: First configure xconnect and then configure service-policy.
 - CSCug05239

Symptom: Traffic drops on the router.

Conditions: This issue occurs when configuring multichassis Link Aggregation Control Protocol (MLACP) switchover with Ethernet over Multiprotocol Label Switching (EOMPLS).

Workaround: Configure port channel with EOMPLS.
 - CSCug05647

Symptom: Interface counters do not get updated with IP traffic.

Conditions: This issue occurs when pinging back to back connected interfaces; the interface counters stay at 0.

Workaround: Reload the device
 - CSCug18630

Symptom: When you perform an OIR on the standby and active RSPs, CMAND crashes.

Conditions: This issue is observed after performing multiple standby OIRs and bringing the standby machine up.

Workaround: There is no workaround.

- CSCug21145
Symptom: When system crashes, sometimes core files are generated with CRC errors.
Conditions: This issue occurs when the system crashes under stress conditions.
Workaround: There is no workaround.
- CSCug22122
Symptom: IOMD crash is seen for any IM on the router.
Conditions: The IOMD crash is seen when show platform software agent IOMD 0/1 driver stats command is executed to verify driver statistics.
Workaround: There is no workaround.
- CSCug23372
Symptom: Manager process crash occurs while configuration replace operation is performed.
Conditions: This issue occurs while moving from REP to G8032.
Workaround: Avoid performing a configuration replace.
- CSCug26432
Symptom: Egress layer3 multicast drops to few BDI outgoing interfaces after a router reload.
Conditions: This issue occurs after router reload.
Workaround: There is no workaround.
- CSCug31414
Symptom: Multicast traffic drops on changing interface configuration from TEFP to VPLS over port channel (PoCH).
Conditions: This issue occurs when converting a layer 2 interface to layer 3; and then configuring IP PIM and IP address in quick succession.
Workaround: Use **shutdown** and **no shutdown** command on the interface.
- CSCug39899
Symptom: Traffic stops flowing through QinQ BDI interface after ARP times out and ARP is removed by shutting the BDI.
Conditions: This issue occurs when static routing is configured, and no routing protocol is configured on the interface.
Workaround: Manually resolve the ARP by pinging the BDI interface.
- CSCug46010
Symptom: The non IP packets get classified under the second class instead of class-default when two class-maps one having match on L4 ACL and other having match on L3 ACL with permit ip any any is configured.
Conditions: This issue occurs when two class-maps one matching on L3 ACL match and another matching on TCP or UDP are configured.
Workaround: There is no workaround.
- CSCug52920
Symptom: EFP stats does not work after applying the QoS policy on the EFP.
Conditions: This issue occurs when service policy is applied on the EFP.
Workaround: There is no workaround.

- CSCug55586
Symptom: If you dynamically remove the egress markings, ingress marking does not work.
Conditions: This issue is observed if a marking is present at the logical level in the egress direction, DM does not work.
Workaround: Use the egress set at leaf or PHB level.
- CSCug67955
Symptom: The standby FP is stuck in init state.
Conditions: This issue occurs after ISSU is performed.
Workaround: There is no workaround.
- CSCug72785
Symptom: OSPF flap observed on the router.
Conditions: This issue occurs after IM OIR followed by SSO.
Workaround: There is no workaround.
- CSCug73776
Symptom: The standby router crashes on bootup when highly scaled configurations and when L2VPN and multicast are configured.
Conditions: This issue occurs on reloading the router 3-4 times with highly scaled configurations and L2VPN and multicast are configured.
Workaround: There is no workaround.
- CSCug83846
Symptom: The MTU value does not take effect on an interface.
Conditions: This issue is observed when you try to configure more than eight unique MTU values on the router.
Workaround: There is no workaround.
- CSCug86963
Symptom: Bidirectional Forwarding Detection (BFD) is unable to resolve neighbor Address Resolution Protocol (ARP).
Conditions: This issue occurs when software BFD is configured with static client; and IM OIR or reload is performed.
Workaround: Use manual ping.
- CSCug91295
Symptom: UDP based ACLs do not work after a router reload.
Conditions: This issue occurs after reload.
Workaround: Remove and add the ACL.
- CSCug97639
Symptom: IPv4 VRF ping fails when disabling IPv6 unicast-routing globally.
Conditions: This issue occurs when IPv6 unicast-routing is disabled.
Workaround: Enable IPv6 unicast-routing

- CSCuh16011
Symptom: FMAN-FP crashes when you perform ab IM OIR.
Conditions: This issue is observed when you perform multiple IM OIRs with around 65 BFD sessions.
Workaround: Reload the router.
- CSCuh27117
Symptom: Traffic loss of about six to eight seconds is observed when you perform an SSO.
Conditions: This issue is observed when you perform the switchover before IM OIR or the interface flaps.
Workaround: There is no workaround
- CSCuh77762
Symptom: The TenGigabitEthernet port operates at one gigabit speeds in WAN-PHY mode on Cisco ASR 903 Routers. This leads to a huge amount of output drop.
Conditions: This issue is observed if a QoS policy is configured on the TenGigabitEthernet interface.
Workaround: There is no workaround.
- CSCuh86102
Symptom: The interface stops forwarding traffic.
Conditions: This issue is observed when the TenGigabitEthernet interface is in WAN-PHY mode and R0 is active.
Workaround: Use R1
- CSCuh92939
Symptom: Replacing the copper SFP with SFP causes traffic drop after SSO is performed
Conditions: This issue occurs after replacing the copper SFP with the fiber SFP.
Workaround: Perform an IM OIR.
- CSCuh94841
Symptom: 10 Gigabit Ethernet interface flaps without trigger causing traffic to switch to protected label-switched path (LSP).
Conditions: This issue occurs when the script is run for continuous SSO.
Workaround: There is no workaround.
- CSCui08978
Symptom: Crash observed on the router.
Conditions: This issue occurs when shutdown followed by a no shutdown is performed on the physical interfaces.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.7(3)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(3)S.

- CSCuf89844

Symptom: The router crashes when a bridge domain interface (BDI) interface running Bidirectional Forwarding Detection (BFD) is deleted.

Conditions: This issue occurs when a static MAC address is assigned on the neighbor interface or on one of the BDI interface on the router and BDI interface running BFD is deleted.

Workaround: There is no workaround.

- CSCug18630

Symptom: CMAND process crash and tracebacks observed on the router.

Conditions: This issue occurs after a hard OIR is performed and the standby RSP comes up.

Workaround: There is no workaround.

- CSCuc42085

Symptom: The 1PPS output from the router is out of range when compared to the 1PPS output of the PTP master clock.

Conditions: This issue occurs when the router is configured as a hybrid clock (ordinary or boundary) and there are intermediate hops between the router and the PTP master clock. This issue occurs only when the intermediate hops are through an Cisco ASR 9000 router.

Workaround: There is no workaround.

- CSCud34600

Symptom: An event hog message is received when 21000 to 25000 routes are advertised into the Multiprotocol BGP (MBGP) and exported from one PE to other PE.

Conditions: This issue occurs when the redistributing routes range from 21000 to 25000 routes from OSPF into MBGP and exported from a PE to other PE.

Workaround: There is no workaround.

- CSCue77397

Symptom: The Cisco ASR 903 manager crashes while flapping local MPLS enabled interfaces at `nmpls_label_populate_flow_data`.

Conditions: This issue occurs when 6000 Layer3 VPN routes and 600 Layer2 VPN sessions exist.

Workaround: There is no workaround.

- CSCuf85588

Symptom: The pending objects from virtual forwarding interface (VFI) interfaces exists after shutdown of path when the core link comes up.

Conditions: This issue exists when Ethernet over MPLS (EoMPLS) or VPLS with MPLS Tunnel TE in the core exists.

Workaround: There is no workaround.

- CSCuf74113

Symptom: Interface mode cannot be entered for serial interfaces. Error messages are displayed.

Conditions: This issue occurs after creation of serial interfaces.

- Workaround:** There is no workaround.
- CSCud38115
Symptom: OSPF connections flap and drop traffic for approximately 20 seconds
Conditions: This issue occurs during stateful switchover (SSO).
Workaround: There is no workaround.
 - CSCue07502
Symptom: A crash is observed after completing ISSU. The F0/F1 are getting stuck in init state.
Conditions: This issue occurs after completing ISSU.
Workaround: Reload the router.
 - CSCue24854
Symptom: Performing an IM OIR in a remote LFA ring reports a loss of 70 ms.
Conditions: This issue occurs during a soft OIR of the IM.
Workaround: Perform a hard OIR for a loss less than 50 ms.
 - CSCue87571
Symptom: GLC-ZX-SM-RGD and GLC-LX-SM-RGD rapid SFP OIR causes iprom to fail.
Conditions: This issue occurs after rapid SFP OIR.
Workaround: Perform each OIR with a delay of 30-40 seconds between the OIR. Reload the IM to recover the port.
 - CSCuf07508
Symptom: The Gigabit Ethernet port on interface module does not come up after a reload.
Conditions: This issue occurs when the Cisco ASR 903 router is reloaded multiple times.
Workaround: Perform an OIR of the interface module.
 - CSCuf79397
Symptom: The F1 interface is stuck in init state after OIR of the standby RSP or standby reload.
Conditions: This issue occurs after the standby RSP is reloaded or OIR is performed.
Workaround: There is no workaround.
 - CSCub94462
Symptom: The router displays object download error messages on the console similar to the following example:

```
%FMFP-3-OBJ_DWNLD_TO_CPP_FAILED"
```


Conditions: Occurs when you take the following actions:
 - Apply the **mac address sticky** command
 - Configure 25 incremental MAC addresses
 - Apply the **clear mac-address-table bdomain** command
 - Remove a **mac security sticky** configuration from an EVC interface
Workaround: Do not issue **clear mac-address-table** command when the **mac security sticky** is configured.
 - CSCue51682

Symptom: The REP protocol flaps, as indicated by the following error messages:

```
*Feb  8 06:51:38.857: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
non-operational due to neighbor not responding
*Feb  8 06:51:39.096: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
operational
```

Conditions: Occurs under the following conditions:

- The router is sending traffic using the incremental MAC address table
- Fast LSL is configured using a 200ms timer.
- The router is configured with more than 2000 MAC addresses.

Workaround: Remove fast LSL from the REP configuration.

- CSCuf86247

Symptom: SNMP MIB variables related to BDI counters do not function properly.

Conditions: Occurs when you use SNMP MIB variables related to BDI interface counters.

Workaround: There is no workaround.

- CSCug05491

Symptom: The router drops traffic on VPLS circuits.

Conditions: Occurs when you take the following actions:

- Configure REP with VLAN load balancing
- Configure VPLS VFI on the VLANs
- Issue an stateful switchover (SSO)

Workaround: There is no workaround.

- CSCuf86184

Symptom: The **show interface BDI** command does not display the incrementing of counters when traffic is flowing.

Conditions: This issue occurs after executing the **show interface BDI** command.

Workaround: There is no workaround.

- CSCug30714

Symptom: OSPF flaps occur on interface module stop.

Conditions: This issue occurs when the interface module stops.

Workaround: There is no workaround.

- CSCud96866

Symptom: The router displays the following symptoms:

- Object download failures
- OSPF traffic flaps
- High CPU utilization
- Bundling and unbundling of port-channel member links
- Slow console updates
- Remote MEP learning failures

Conditions: Occurs when you configure CFM offloaded MEPs for xconnect on a port-channel interface at a high scale and issue a **shutdown/no shutdown** on the port-channel interface.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.7(3)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.7(3)S.

- CSCty30951

Symptom: The router displays the following console error message:

```
%QOSMGR-3-OUT_OF_TCAM_RESOURCES: SIP0: nile_mgr: Out of tcam resources to execute command
```

Conditions: Occurs when you remove a QoS configuration by setting the interface to the default configuration.

Workaround: There is no workaround.

- CSCty34054

Symptom: The router displays CPU utilization traceback messages and drops all multicast traffic for 2050 seconds.

Conditions: Occurs under the following conditions:

- Multicast is enabled with more than 500 multicast groups.
- The router is using RSP1B in SSM mode.
- BDI is configured on the access side of the router.
- There are 24 EFPs on each bridge domain.
- You enter a **shutdown** command on the access interface.

Workaround: There is no workaround.

- CSCty74115

Symptoms: The router displays traceback and CPU error messages.

Conditions: Occurs when you configure a high number of MAC address table entries while REP is enabled; the router displays errors during a REP topology change, REP preemption, or when you perform a **shutdown/no shutdown** on an interface.

Workaround: Reduce the number of MAC address entries.

- CSCua15499

Symptoms: The **show interface** command output displays 1000 Mbps information for both 100Mbps and 10 gigabyte transceivers.

Conditions: Occurs when you use 100 Mbps and 10 Gigabit Ethernet transceivers

Workaround: There is no workaround.

- CSCua25779

Symptom: An Ethernet virtual circuit (EVC) interface does not forward IPv4 traffic.

Conditions: Occurs when you apply the **encapsulation dot1q** command to an EVC, followed by the **encapsulation untagged** command.

Workaround: Issue a **shutdown/no shutdown** on the EVC interface.

- CSCua62305

Symptom: QoS does not function on the router.

Conditions: Occurs under the following conditions:

 - You apply a service-policy and an ACL to the same interface
 - You modify the ACL by adding an ACE containing a **permit ospf** statement.

Workaround: There is no workaround.
- CSCub64331

Symptom: The 10Mhz reference clock to the SDH Equipment Timing Source (SETS) goes to out-of-resource (OOR).

Conditions: Occurs when you connect both 10Mhz and 1pps inputs.

Workaround: Connect only the 10Mhz interface.
- CSCub71932

Symptom: The OC-3 interface module (IM) crashes.

Conditions: Occurs when you boot the router with an OC-3 IM and there are is no configuration applied to the IM. The issue occurs intermittently.

Workaround: There is no workaround; wait for the interface module to reset.
- CSCub89531

Symptom: Multicast statistics in the MFIB output can show NA/NA. This causes multicast traffic to drop every 3 minutes once the 3 minute timer expires.

Conditions: Occurs after an stateful switchover (SSO).

Workaround: Issue another SSO or reload the router.
- CSCuc43719

Symptoms: The router crashes.

Conditions: Occurs when you apply a Network Based Application Recognition (NBAR) configuration to the router. There is no specific trigger.

Workaround: Remove the NBAR configuration, it is not supported.
- CSCuc55382

Symptoms: The **show inventory** command displays incorrect serial number for SFPs and XFPs.

Conditions: Occurs after you issue repeated stateful switchovers (SSOs).

Workaround: There is no workaround.
- CSCuc59386

Symptoms: Continuous IOMD crashes occur on OC-3 IM. Interfaces on OC-3 IM are not configurable and the router displays the the following error message:

```
"stand-by does not support this command"
```

Conditions: Occurs with OC-3 IM in a redundant configuration when an IOMD crash occurs on the active RSP and the standby IOMD session handle is not cleared.

Workaround: Reload the standby RSP.
- CSCuc62784

Symptoms: The router displays traceback error messages at `niles_if_count_initialize`

- Conditions:** Occurs following a reload or stateful switchover (SSO).
- Workaround:** There is no workaround. However, the issue does not have any functionality impact.
- CSCuc64654

Symptom: The router is unable to ping the remote customer edge (CE) router.

Conditions: Occurs when the router is acting as a provider edge (PE) device and is connected to the remote PE using dual loopback interfaces for peering with iBGP sessions.

Workaround: Use a single loopback interface. Use the same loopback interface for IPv4 and VPNv4 address families.
 - CSCuc66393

Symptom: The router loses OC-3 interface configurations after an ISSU upgrade.

Conditions: Occurs on OC-3 serial and POS interfaces after an ISSU software upgrade.

Workaround: There is no workaround.
 - CSCuc68462

Symptom: The router drops PTP traffic.

Conditions: The issue occurs occasionally when you configure PTP slave clock to receive VLAN-tagged traffic.

Workaround: There is no workaround.
 - CSCuc85721

Symptom: The router crashes.

Conditions: Occurs under the following conditions:

 - MR-APS is configured on serial interfaces on the OC-3 interface module
 - The router is configured with a high number of serial interfaces
 - You reset an interface module or reload the router.

Workaround: There is no workaround.
 - CSCuc91007

Symptom: A slave clock displays a high 1PPS offset value from the master clock.

Conditions: Occurs after an interface module reset or stateful switchover (SSO) on the master device.

Workaround: There is no workaround.
 - CSCuc95590

Symptom: The router does not automatically upgrade the FPGA software.

Conditions: Occurs when you load a new image while running an older FPGA version.

Workaround: There is no workaround; however the issue has no functional impact.
 - CSCuc98185

Symptom: One out of 48 EFPs in a BDI does not receive traffic when running L3 multicast. The issue does not happen consistently.

Conditions: Occurs under the following conditions:

 - You configure Protocol-Independent Multicast-Sparse Mode (PIM-SM) with a static rendezvous point (RP).

- You configure a bridge domain interface (BDI) on the PE2 access side
- You use the BDI to send IGMP v2 static join messages to a single multicast group
- You disable IGMP snooping globally.
- You configure 24 EFPs and map them to a single bridge-domain.
- You initiate multicast traffic.
- With multicast traffic enabled, you configure 24 EFPs and map them to the existing bridge-domain.

One of the 48 EFPs does not receive traffic.

Workaround: Reload the router.

- CSCud01644

Symptom: The active forwarding processor (FP) is on the standby route switch processor (RSP).

Conditions: Occurs when you boot the two RSPs in quick succession and the FP on the standby RSP becomes active before the FP on the active RSP.

Workaround: Reload the router.

- CSCud07236

Symptoms: The router displays console error messages when reloading.

Conditions: Occurs when you reload the router.

Workaround: There is no workaround; however, the messages have no impact on device.

- CSCud07642

Symptom: The ASR 903 router is unable to pass traffic to the ASR 9000.

Conditions: Occurs with a clear-channel ATM over MPLS configuration using AAL0 encapsulation.

Workaround: Enable MPLS control-word on the ASR 9000.

- CSCud09632

Symptom: The router does not correctly update the J0 byte on the OC-3 or OC-12 interface module.

Conditions: Occurs in a back-to-back configuration with two ASR 903s passing SONET traffic.

Workaround: There is no workaround.

- CSCud15785

Symptom: The router experiences flapping on REP connections.

Conditions: Occurs under the following conditions:

- MAC limiting is enabled and a MAC address is at the maximum value
- REP is configured with a 200 millisecond LSL ageout timer

Workaround: Increase the REP timer to above 500 milliseconds or disable the MAC limiting feature.

- CSCud15841

Symptom: The **clear ip mroute *** command causes resource leakage.

Conditions: Occurs when you issue the **clear ip mroute *** command while IP multicast is enabled.

Workaround: Reload the router.

- CSCud17457
Symptom: The router drops IP multicast traffic.
Conditions: Occurs when you perform the following actions:
 - Configure EFPs as members of a port channel containing a single interface.
 - Remove the configuration for the EFPs
 - Remove the interface from the port channel
 - Add the EFPs back onto the interface**Workaround:** Reload the router or issue a stateful switchover (SSO).
- CSCud23698
Symptom: The router stops applying classification and marking for a class.
Conditions: Occurs when you remove a priority level while using dual priority for the class-map.
Workaround: Remove and reattach the policy-map on the interface.
- CSCud28982
Symptom: The router does not process egress CoS marking on an Ethernet service instance.
Conditions: Occurs when you configure QoS on an Ethernet service instance that is a member of a bridge-domain and uses dot1q encapsulation.
Workaround: There is no workaround.
- CSCud30806
Symptoms: The router accepts a QoS WRED configuration containing **match-all** configurations for two different **prec** values, which is not supported.
Conditions: Occurs when you configure a policy with a class-map containing **match-all** configurations for two different **prec** values.
Workaround: There is no workaround.
- CSCud33298
Symptom: The router crashes.
Conditions: Occurs when the peer device shuts down.
Workaround: There is no workaround.
- CSCud34346
Symptom: The router crashes.
Conditions: The issue can occur when:
 - The router is configured with multiple ECMP paths
 - MPLS IP is not enabled on one of the ECMP paths**Workaround:** There is no workaround.

- CSCud35689

Symptoms: The router accepts a queue-limit configuration at the parent level of a policy or at the Vlan class/ port level. This configuration is not supported.

Conditions: Occurs when you add a queue-limit configuration on a policy at the parent level or at the vlan class/ port level.

Workaround: There is no workaround.
- CSCud37927

Symptoms: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: Occurs when the router is passing REP or STP traffic and one port is in an ALT or BLK state.

Workaround: There is no workaround.
- CSCud38164

Symptom: The router displays an object download failure message on the console.

Conditions: Occurs when the number of ip routes reaches its maximum configurable limit.

Workaround: There is no workaround.
- CSCud38433

Symptom: The router is unable to establish MPLS neighborship or ping the destination loopback interface.

Conditions: Occurs when you configure two Equal Cost Multipath (ECMP) paths on a bridge domain interface (BDI) using static routes.

Workaround: The following workarounds exist:

 - Use Interior Gateway Protocol (IGP) instead of static IP routes.
 - Shut down one of the ECMP paths.
- CSCud40930

Symptom: Some interfaces within a bridge-domain are unable to send outbound L3 multicast traffic.

Conditions: Occurs when the bridge-domain contains EFP interfaces, some of which are on a port-channel. The issue can also occur after a router reload.

Workaround: Issue a **shutdown/no shutdown** on the BDI interface.
- CSCud44768

Symptom: Multilink bundles and member links flap when passing traffic.

Conditions: Occurs under the following conditions:

 - You configure more than 210 MLPPP bundles with one member link per bundle or 16 bundles with 16 member links each.
 - The line is operating at a 64 or 128 byte line rate

Workaround: There is no workaround.

- CSCud44942
Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).
Conditions: Occurs when you configure a MEP on an interface.
Workaround: There is no workaround.
- CSCud49980
Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).
Conditions: Occurs when you configure CFM MEPs on carrier edge (CE) routers and VPLS on provider edge (PE) routers.
Workaround: Create an EVC bridge-domain running CFM on the PE router and enable a virtual forwarding interface (VFI) on the bridge-domain.
- CSCud50851
Symptom: The router experiences flapping on REP connections.
Conditions: Occurs when you enable MAC limiting at a high scale and the set of MAC addresses changes continuously.
Workaround: Disable MAC limiting.
- CSCud50944
Symptom: The router drops traffic on an MLPPP bundle.
Conditions: Occurs following a reload while the router is passing traffic close to the line rate. The issue occurs less frequently with lower traffic rates.
Workaround: Issue a **shutdown/no shutdown** on multilink interface.
- CSCud55377
Symptom: The router crashes.
Conditions: Occurs when you configure offloaded CFM for xconnect sessions at a high scale.
Workaround: There is no workaround.
- CSCud55695
Symptom: The router applies the shaper value to the channel-level PIR for all serial interfaces on the interface module.
Conditions: Occurs when you apply QoS policy with a port level class-default configuration containing a shaper value to a serial interface.
Workaround: Add a dummy class-default level at the top of the policy and apply the shaper as a child policy of this class.
- CSCud56071
Symptom: The router does not pass loop-free alternate (LFA) IP fast reroute (IPFRR) traffic.
Conditions: Occurs when the router is configured with 10 or more IPv4 prefixes.
Workaround: Configure 9 or fewer prefixes.

- CSCud61931

Symptom: As OC-3 interface module controller does not become active using loopback local.

Conditions: Occurs with the A900-IMA4OS interface module when there is no SFP inserted in the port.

Workaround: Insert an SFP in the appropriate port.
- CSCud64034

Symptoms: T1 interfaces do not become active.

Conditions: Occurs when you perform the following actions:

 1. Configure T1 interfaces on the router.
 2. Use ping to verify that the interfaces are active
 3. Perform a stateful switchover (SSO)
 4. Use ping to verify that the interfaces are active
 5. Remove the T1 interface configuration
 6. Reload the standby RSP
 7. Reconfigure the T1 interfaces

The T1 interfaces do not become active.

Workaround: Perform an OIR on the interface module.
- CSCud64129

Symptoms: The router displays CLI options to configure control-plane policing, which is not supported.

```
ASR903 (config)#control-plane
ASR903 (config-cp)#service-policy ?
input   Assign policy-map to the input of an interface
output  Assign policy-map to the output of an interface
```

Conditions: Occurs when you attempt to configure control plane policing to restrict traffic punted by the CPU.

Workaround: There is no workaround; the feature is not supported.

Further Problem Description: The ASR 903 has an implicit policer to restrict traffic destined for the CPU. The router polices this traffic up to 1Mbps by default, and this value is adjustable. For more detail, see http://www.cisco.com/en/US/docs/ios-xml/ios/qos_plcshp/configuration/xe-3s/qos-plcshp-punt-policer-monitor.html
- CSCud65779

Symptom: The router does not update the Rx value for C2, J1, and S1S0 bytes.

Conditions: Occurs when you configure overhead bytes on OC-3 connections.

Workaround: There is no workaround.
- CSCud71546

Symptom: The ten Gigabit Ethernet interface drops traffic for 7 seconds following a stateful switchover (SSO).

Conditions: Occurs when the configuration contains static routes to the destination.

Workaround: There is no workaround.

- CSCud76209
Symptom: The OC-3 interface module goes into an out of service state.
Conditions: Occurs when you repeatedly perform an interface module reset (OIR) on the OC-3 interface module.
Workaround: There is no workaround.
- CSCud76770
Symptoms: The convergence time for FRR link/node protection is more than 2 seconds.
Conditions: Occurs when you configure Next-Nexthop (NNHOP) backup tunnels in a ring topology.
Workaround: There is no workaround.
- CSCud78168
Symptoms: A higher convergence (>5 seconds) is observed for 3107 label imposition prefixes.
Conditions: Occurs when you configure 3107 label imposition prefixes.
Workaround: There is no workaround.
- CSCud83056
Symptoms: PTP sessions remain in HOLDOVER mode.
Conditions: Occurs when you remove and restore the PTP configuration on the PTP Master device.
Workaround: Do not include the following commands in a PTP configuration unless ToD and 1PPS cables are directly connected:
 - `tod 0/0 ntp`
 - `input 1pps 0/0`
- CSCud83069
Symptom: The router does not pass traffic in ATM PVP Mode.
Conditions: Occurs when you enable ATM PVP Mode.
Workaround: There is no workaround.
- CSCud83698
Symptom: Links on the Gigabit Ethernet interface do not become active.
Conditions: Occurs on the Gigabit Ethernet interface when the local interface is configured for autonegotiation and the remote interface is configured for a speed of 10 Mbps or 100 Mbps.
Workaround: Toggle the auto-negotiation configuration on the Gigabit Ethernet interface.
- CSCud89451
Symptom: The router crashes with an error message showing `nmpls_label_populate_flow_data`.
Conditions: This issue occurs when the core interface is reset while the Cisco ASR 903 acts as a PE router running a configuration with Layer2 VPN and Layer3 VPN.
Workaround: There is no workaround.

- CSCud90457

Symptoms: The serial interface of Circuit Emulation interfaces connected to the CEM interfaces on PE remain down on router reload with scaled configuration.

Conditions: This issue is observed when you have Circuit Emulation Services over Packet (CESoP) and Structure-agnostic TDM over Packet (SAToP) scaled circuits and perform a router reload.

Workaround: Perform IM OIR to resolve the issue.
- CSCud90735

Symptom: The controller comes up without having a license.

Conditions: This issue occurs 16 port t1/e1 license are installed on PE1_W2

Workaround: There is no workaround.
- CSCud90890

Symptom: Routing over Trunk EFP over port-channel does not work on member ports associated with ASIC #1.

Conditions: This issue occurs if a Trunk EFP on port-channel has members on ASIC #1.

Workaround: There is no workaround.
- CSCud95359

Symptom: The show policy map command displays an incorrect number of total dropped packets (total drops).

Conditions: This issue occurs when the show policy-map command displays dropped packets on an interface.

Workaround: There is no workaround.
- CSCud96604

Symptoms: On system reset or reload, all traffic on certain Ethernet Flow Point (EFP)s do not egress.

Conditions: This issue occurs when traffic completely stops on certain EFPs.

Workaround: Delete and reconfigure EFPs.
- CSCud96962, CSCud97289

Symptom: After performing a **shutdown** followed by a **noshutdown** the member-link Connectivity Fault Management (CFM) crash is observed

Conditions: This issue occurs when CFM Trunk Ethernet Flow Point (EFP) is configured with 256 sessions.

Workaround: Configure around 50-100 CFM sessions.
- CSCud97289

Symptom: Precision Time Protocol (PTP) slave does not start the session with master.

Conditions: This issue occurs when the PTP session is not started when the loopback IP address of slave and Master are in same subnet.

Workaround: Configure Loopback IP addresses of slave and master in different subnets.

- CSCud99183
Symptom: The control plane protocols such as ISIS, LDP do not come up and pings failure occurs on booting with scaled ACE or ACL. The ACL configurations fail.
Conditions: This issue occurs on reload on the Cisco ASR 903 router.
Workaround: There is no workaround.
- CSCud99692
Symptom: The convergence time takes more than 3 seconds.
Conditions: This issue occurs in Border Gateway Protocol (BGP) PIC core when path is moved from one active path to 2 Equal Cost Multipath (ECMP) Paths.
Workaround: There is no workaround.
- CSCue00049
Symptom: Classification does not work properly with non-matching traffic when IP ACL is used.
Conditions: This issue occurs only for class-based ACL match. The ACL class are classified properly and other classes based on DSCP or class-default do not work
Workaround: There is no workaround.
- CSCue00332
Symptom: The Bidirectional Forwarding Detection (BFD) connections flap, bringing down IGP.
Conditions: This issue occurs when you enable BFD on an interface that is flapping.
Workaround: There is no workaround.
- CSCue03418
Symptom: The router displays OSPF protocol flaps causing a 20-30 second traffic loss.
Conditions: The issue occurs very intermittently on a HA system with a 6 second dead-interval value when you issue the redundancy force-switchover command;
Workaround: Increase the dead-interval value.
- CSCue11444
Symptom: Split horizon configurations does not clear with Layer2 multicast packets.
Conditions: This issue occurs when Ethernet Flow Point (EFP)s with split-horizon are configured.
Workaround: Perform a shutdown followed by no shutdown. Configure EFP first before moving into split-horizon group.
- CSCue16617
Symptom: The QoS classification does not work in core interfaces.
Conditions: This issue occurs when the output policy applied to interface has bridge domain interface (BDI) as the core interface.
Workaround: Enable `mpls ldp explicit null` command.
- CSCue18015
Symptom: S,G does not get created, the forwarding is based on (*,G).
Conditions: This issue occurs with Interior Gateway Protocol (IGP) change leading to Reverse Path Forwarding (RPF) change of the (*,G).
Workaround: Clear the (*,G) and recreate it.

- CSCue19898

Symptom: (*,G) based forwarding is observed with IIF registry change. The Interior Gateway Protocol (IGP) patch change leads to this issue.

Conditions: This issue occurs when IGP is changed causing a Reverse Path Forwarding (RPF) change notification.

Workaround: Timeout the (*,G) entry and recreate it again either by issuing **clear ip mroute** command or stopping the joins.
- CSCue20022

Symptom: Software forwarding of core encapsulation entries causes interface to flap.

Conditions: This issue occurs when interface has Protocol Independent Multicast (PIM) enabled on the BDI interface.

Workaround: Perform a soft interface module OIR. Clear the multicast routes for that VRF.
- CSCue20360

Symptom: The router does not learn the remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: This issue occurs when Resilient Ethernet Protocol (REP) or Spanning Tree Protocol (STP) exists on core with one port as ALT or BLK state.

Workaround: There is no workaround.
- CSCue20607

Symptom: The port-channel load balances the traffic on member-links in hot-standby state or down state resulting in loss of traffic.

Conditions: This issue occurs when there are redundant member-links in hot-standby state or down state.

Workaround: There is no workaround.
- CSCue25567

Symptom: Quack authentication failure messages are displayed on router console.

Conditions: This issue occurs randomly.

Workaround: Reload the router.
- CSCue26927

Symptom: Alarms are not forwarded in Circuit Emulation Services over Packet (CESoP).

Conditions: This issue occurs when alarms are not forwarded when AC goes down.

Workaround: There is no workaround.
- CSCue30481

Symptom: The Cisco ASR 903 router does not lock to the synchronous Ethernet clock source after reload. It remains in QI-failed state.

Conditions: This issue occurs after a reload of router with saved synchronous Ethernet clock configurations is performed.

Workaround: Unconfigure and reconfigure the clock source.

- CSCue32753

Symptom: The OC-3 interface modules are lost after a In Service Software Upgrade (ISSU) is performed on the Cisco ASR 903 router and configuration mismatch errors are displayed on router console. The standby RSP reaches standby-hot state causing continuous IOMD crash messages at regular intervals.

Conditions: This issue occurs when ISSU is performed.

Workaround: There is no workaround.

Try unconfiguring the OC-3 interface module configuration and reconfigure again. Reload the standby RSP to stop IOMD crashes. Perform a hard OIR or process kill if the interface module enters out of service state

- CSCue34618

Symptom: Traffic stops flowing with a combination of Bandwidth Remaining Ratio (BRR) and policer in different class-maps under a policy.

Conditions: This issue occurs when the bandwidth remaining ratio is configured as a combination of police with cir (total brr and police cir equal to 1000M).

Workaround: Configure total BRR and police cir lesser than 1000M. For example, class A Police cir 100m and class B BRR 90% fails but BRR 89% works.

- CSCue42315

Symptom: CPU hog messages and IOMD crash observed on the Cisco ASR 903 router.

Conditions: This issue occurs with OC-3 interface module after executing the **shutdown** command followed by a **no shutdown** command of the multilink bundle when traffic is sent with a packet size greater than 1500 byte.

Workaround: There is no workaround.

- CSCue45498

Symptom: CPU utilization is high when sending traffic with varying source MAC addresses for multiple streams for a bridge domain (BD).

Conditions: This issue occurs when port-channel is configured as Ethernet Flow Point (EFP) for the BD and **mac-limit** is configured to 0 for that BD.

Workaround: There is no workaround.

- CSCue50128

Symptom: FMFP download failure occurs on reaching 1980 odd number even though 2000 ternary content addressable memory (TCAM) space is allocated for ACLs in the IP template.

Conditions: This issue occurs in normal conditions when the scale reaches 1980.

Workaround: There is no workaround.

- CSCue52298

Symptom: TI/EI interfaces on interface module are lost as IOMD crashes after a switchover.

Conditions: This issue occurs after IOMD crashes when a switchover was performed.

Workaround: There is no workaround.

- CSCue52774
Symptom: Sonet controller as input clock source does not get selected on A900-IMA4OS interface module on a Cisco ASR 903 router.
Condition: This issue occurs when the port above 0 is used for the clock source.
Workaround: Use port 0 for clock source or insert the SFP in the odd port (protect port) adjacent to the actual port using an optical splitter. The cable is fed to the odd port to recover the proper clocking for the port.
- CSCue52968
Symptom: Ping failure occurs and traffic stops through Multilink bundle when Challenge Handshake Authentication Protocol (CHAP) authentication is enabled.
Conditions: This issue is seen when Policy Feature Card (PFC) and Control Field Compression (ACFC) is configured on the Cisco ASR 903 router.
Workaround: There is no workaround.
- CSCue57670
Symptom: The active RSP synchronization LED displays the state incorrectly.
Condition: This issue occurs after a Stateful Switchover (SSO) is performed without any network clock configuration.
Workaround: There is no workaround. This issue is a cosmetic issue.
- CSCue59544
Symptom: The A900-IMA16D generates a storm on closing the backup tunnel.
Condition: This issue occur after unshutting the tunnel.
Workaround: There is no workaround.
- CSCue66137
Symptom: The IOMD crashes with CPU hog messages.
Conditions: This issue occurs with OC-3 interface module and traffic is sent over a multilink bundle with packet size greater than 600 byte.
Workaround: There is no workaround.
- CSCue72438
Symptom: Link goes down with Rev-D I Gigabit interface module.
Conditions: This issue occurs on the 1 Gigabit Ethernet interface module port.
Workaround: There is no workaround.
- CSCue77612
Symptom: MAC address synchronization on 1 Gigabit Ethernet port on standby RSP causes traffic to be forwarded to incorrect port after a switchover.
Conditions: This issue occurs after a switchover.
Workaround: Clear MAC address after a switchover is performed.
- CSCue86696
Symptom: Interface flaps after longevity run is performed.
Conditions: This issue occurs after prolonged tests are performed with SPF interface modules.
Workaround: There is no workaround.

- CSCue87542
Symptom: Deleting bridge domain interfaces (BDIs) with routing traffic causes a flood to CPU resulting in control plane traffic loss.
Conditions: This issue occurs after a ping failure and the Bidirectional Forwarding Detection (BFD) protocol or OSPF protocol flaps on deleting the BDI while IPv4 traffic is flowing.
Workaround: Delete the Trunk EFP interface and then the BDI.
- CSCue89503
Symptom: The power supply status displays critical after removing and inserting the power supply on the Cisco ASR903 router.
Conditions: This issue occurs after multiple OIR of the power supply is performed.
Workaround: There is no workaround. This issue is cosmetic.
- CSCuf05039
Symptom: I2C-WRITE and MDIO_READ error messages are displayed on the Cisco ASR903 router.
Conditions: This issue occurs after an interface module hard or soft OIR is performed.
Workaround: There is no workaround.
- CSCuf61365
Symptom: Virtual circuit counters do not increment after interface module Online Insertion and Removal (OIR) followed by a SSO is performed.
Conditions: This issue occurs after an OIR followed by a SSO is performed.
Workaround: Perform a SSO without a interface module OIR.
- CSCuf65040
Symptom: 1 Gigabit Ethernet or 10 Gigabit Ethernet interface module enters out of service state.
Conditions: This issue occurs when a hard Online Insertion and Removal (OIR) is performed on the interface module.
Workaround: Perform another hard OIR or a Stateful Switchover (SSO) followed by a soft OIR.

Open Caveats—Cisco IOS XE Release 3.7(2)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(2)S.

- CSCts95896
Symptoms: The router stops passing traffic on EVC interfaces.
Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.
Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCty30951

Symptom: The router displays the following console error message:
%QOSMGR-3-OUT_OF_TCAM_RESOURCES: SIP0: nile_mgr: Out of tcam resources to execute command

Conditions: Occurs when you remove a QoS configuration by setting the interface to the default configuration.

Workaround: There is no workaround.
- CSCty34054

Symptom: The router displays CPU utilization traceback messages and drops all multicast traffic for 2050 seconds.

Conditions: Occurs under the following conditions:

 - Multicast is enabled with more than 500 multicast groups.
 - The router is using RSP1B in SSM mode.
 - BDI is configured on the access side of the router.
 - There are 24 EFPs on each bridge domain.
 - You enter a **shutdown** command on the access interface.

Workaround: There is no workaround.
- CSCty76744

Symptom: The **show mac-address-table** command does not show all of the EFPs with a given static MAC address; the command only displays the first EFP with the MAC address.

Conditions: Occurs when you configure the same static MAC address on multiple EFPs.

Workaround: There is no workaround; however, the issue is cosmetic and functionality is not affected.
- CSCua22323

Symptom: Bit error rate testing (BERT) does not go in sync state.

Conditions: Occurs when you configure BERT on the PDH controller in local loopback mode.

Workaround: Initiate BERT on both ends of the connection.
- CSCua25779

Symptom: An Ethernet virtual circuit (EVC) interface does not forward IPv4 traffic.

Conditions: Occurs when apply the **encapsulation dot1q** command to an EVC, followed by the **encapsulation untagged** command.

Workaround: Issue a **shutdown/no shutdown** on the EVC interface.
- CSCua35402

Symptom: The router crashes.

Conditions: Occurs under the following conditions:

 - The router is running static VPLS with 255 MPLS-TP tunnels and 2000 VCs.
 - The remote PE device reloads.

Workaround: There is no workaround.

- CSCua57325
Symptom: The router displays an OIR SPA error.
Conditions: Occurs under the following conditions:
 - The router is running offloaded CFM sessions over an xconnect (pseudowire) interface.
 - The router is using a redundant hardware (dual RSP) configuration.
 - The remote router is using a non-redundant (single RSP) hardware configuration.
 - You reload the router.**Workaround:** There is no workaround.
- CSCua77688
Symptom: The router experiences remote CFM MEP flapping.
Conditions: Occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.
Workaround: Reduce the rate of traffic.
- CSCua95675
Symptom: An Ethernet virtual circuit (EVC) interface stops forwarding traffic.
Conditions: Occurs when:
 - You configure multiple EVCs on a single interface
 - The EVCs have the same outer tag VLAN
 - You remove one of the EVCs from the configurationWhen you remove the EVC, other EVCs with the same outer tag VLAN can stop passing traffic.
Workaround: Issue a **shutdown/no shutdown** on the Ethernet interface.
- CSCua99096
Symptom: The **show ima interface** command omits some IMA group information such as ImaGroupSymmetry.
Conditions: Occurs when you apply the **show ima interface** command.
Workaround: There is no workaround.
- CSCub61344
Symptom: Link Control Protocol (LCP) negotiation fails, causing an MLP bundle to stop passing traffic.
Conditions: Occurs under the following conditions:
 - The router is configured with a T1 interface on the OC-3 interface module (IM)
 - The OC-3 interface module uses SONET framing
 - The T1 serial interface is part of an MLP bundle
 - You change the CRC configuration value of the MLP bundle**Workaround:** Follow these steps:
 - Remove the T1 interface from the MLP bundle.
 - Perform a soft OIR (IM reset) on both ends of the connection.
 - Wait for the T1 interface to become active.

- Add the T1 interface back into the MLP bundle.
- CSCub63072

Symptom: MPLS convergence can be slower than expected.

Conditions: Occurs when the router switches to a backup MPLS path in the event of a network failure.

Workaround: You can configure the following redundancy features to protect against network failures:

 - IPv4 Loop Free Alternate Fast Reroute (LFA FRR)
 - Border Gateway Protocol (BGP) Prefix-Independent Convergence (PIC)
 - MPLS Traffic Engineering (TE)--Fast Reroute (FRR) Link and Node Protection
- CSCub77354

Symptom: An RSP switchover causes the serial interfaces to flap on the peer device.

Conditions: Occurs when you perform an RSP switchover by physically removing the active RSP.

Workaround: Use the following workarounds:

 - Perform an RSP switchover using the **redundancy force-switchover** command.

Configure the local device to use **clock source line** and the remote device to use **clock source internal**.
- CSCub81445

Symptom: A link remains active while the router shows the line protocol status as down.

Link Stays up with Line Protocol status as down.

Conditions: Occurs when you perform an interface module (IM) OIR, followed by a stateful switchover (SSO).

Workaround: There is no workaround.
- CSCuc38878

Symptom: The router loops traffic between two nodes in a ring for approximately 100 ms.

Conditions: Occurs during a failover when multiple ASR 903 routers are configured as nodes in a ring using Remote LFA FRR.

Workaround: There is no workaround.
- CSCuc42085

Symptom: The 1PPS output from the ASR 903 is out of range when compared to the 1PPS output of the PTP master clock.

Conditions: Occurs when the router is configured as a hybrid clock (ordinary/boundary) and there are intermediate hops between the router and the PTP master clock. To date the problem occurs only when the intermediate hops are through an ASR 9000 router.

Workaround: There is no workaround.
- CSCuc44701

Symptom: The router displays an error message similar to the following: Oct 1 12:07:21.806 IST: %CMRP-3-CHASSIS_MONITOR_READY_TIME_EXCEEDED: R1/0: cmand: Reloading F1 because it has failed to become ready for packet processing

Conditions: Occurs when you reload the router while running a configuration that contains

- An egress QoS policy attached to a trunk EFP
- An encapsulation dot1q statement within the QoS policy that specifies a large range

Workaround: There is no workaround.

- CSCuc64654

Symptom: The router is unable to ping the remote customer edge (CE) router.

Conditions: Occurs when the router is acting as a provider edge (PE) device and is connected to the remote PE using dual loopback interfaces for peering with iBGP sessions.

Workaround: Use a single loopback interface. Use the same loopback interface for IPv4 and VPNv4 address families.

- CSCuc68699

Symptom: The router displays a segmentation fault error message at `cgmu_nq_ccm_convert` and crashes.

Conditions: Occurs when you:

- Remove QoS policy from an EFP interface
- Remove policy-maps and class-maps from the configuration

Workaround: There is no workaround.

- CSCuc83088

Symptom: The router drops traffic during stateful switchover (SSO).

Conditions: Occurs when the router is running HSRP or VRRP; the issue only occurs when the destination MAC address is a virtual MAC (vMAC) address.

Workaround: Change the traffic priority and detour traffic prior to the SSO.

- CSCuc88066

Symptom: The router does not classify egress traffic and the **show policy-map interface** command counters do not increment.

Conditions: Occurs when you configure an output QoS policy to an EFP interface.

Workaround: Remove and reconfigure the service policy on the EFP interface.

- CSCuc92350

Symptom: A connection between two copper SFPs does not become active.

Conditions: Occurs when two SFP interfaces are connected with one side set to 100 Mbps and the other side set to **negotiation auto**.

Workaround: Set the speed to 10Mbps at both sides, then configure negotiation auto on one side of the connection.

- CSCuc99908

Symptom: IEEE 802.1S Multiple STP (MSTP) convergence takes more than 4.1 seconds.

Conditions: Occurs under the following conditions:

- An Ethernet interface is acting as the Root forwarding MST port
- The Ethernet interface is configured with more than 1000 EVCs
- You perform a **shutdown/no shutdown** on the interface.

Workaround: To achieve a convergence time of approximately 900 milliseconds with 1000 VLANs on an Ethernet interface, configure MSTP on a trunk EFP.

- CSCud01908

Symptom: Debug commands show pending objects on the Forwarding Manager (FMAN) on the forwarding processor (FP), indicating a failure to download configurations from the Route Switch Processor (RSP) to the data plane (DP).

Conditions: Occurs when you apply a QoS shaping configuration at a high scale.

Workaround: Delete the QoS policies and remove the QoS configuration from the interface.
- CSCud04529

Symptom: The router can drop traffic for approximately 300 milliseconds.

Conditions: The issue occurs in rare instances when the router is configured in a ring topology with loop-free alternate (LFA) IP fast reroute (IPFRR) and the primary path recovers from a down state.

Workaround: There is no workaround.
- CSCud07642

Symptom: The ASR 903 is unable to pass traffic to the ASR 9000.

Conditions: Occurs with a clear-channel ATM over MPLS configuration using AAL0 encapsulation.

Workaround: Enable MPLS control-word on the ASR 9000.
- CSCud11843

Symptom: The router displays a CPU hog error message and crashes.

Conditions: Occurs when you issue an RSP switchover following an interface flap on the 10 Gigabit Ethernet interface module (IM).

Workaround: The issue does not occur in the absence of in interface flap on the 10 Gigabit Ethernet IM.
- CSCud15785

Symptom: The router experiences flapping on REP connections.

Conditions: Occurs under the following conditions:

 - MAC limiting is enabled and a MAC address is at the maximum value
 - REP is configured with a 200 millisecond LSL ageout timer

Workaround: Increase the REP timer to above 500 milliseconds or disable the MAC limiting feature.
- CSCud19845

Symptom: The router drops ping packets over VPN Routing and Forwarding (VRF) connections.

Conditions: Occurs when you specify a packet size using the **size** parameter.

Workaround: There is no workaround; however, the issue does not occur when you omit the **size** parameter.
- CSCud23647

Symptom: BDI adjacency fails on the standby RSP.

Conditions: The issue can occur during an interface module (IM) reset or router reload.

Workaround: There is no workaround.

- CSCud24704
Symptom: The router crashes.
Conditions: Occurs when you perform an interface module OIR (reset) on the gigabit Ethernet interface module while the standby RSP is booting.
Workaround: Perform the IM OIR after the standby RSP boots.
- CSCud26379
Symptom: The router displays a CWAN OIR Handler traceback error.
Conditions: Occurs when you perform an interface module OIR (reset) on the gigabit Ethernet interface module, followed by an RSP switchover.
Workaround: Complete the RSP switchover without resetting the gigabit Ethernet IM.
- CSCud26812
Symptom: The router CLI does not display some SFP PIDs
Conditions: Occurs when you install one of the following SFPs in the router:
 - ONS-SI-155-L2
 - ONS-SI-155-L1
 - ONS-SI-155-I1**Workaround:** There is no workaround.
- CSCud28787
Symptom: The 10 gigabit Ethernet interface module (IM) (IM- A900-IMA1X) flaps.
Conditions: Occurs when the IM passes high traffic volumes for an extended period of time.
Workaround: There is no workaround.
- CSCud28982
Symptom: The router does not process egress CoS marking on an Ethernet service instance.
Conditions: Occurs when you configure QoS on an Ethernet service instance that is a member of a bridge-domain and uses dot1q encapsulation.
Workaround: There is no workaround.
- CSCud29501
Symptom: The **show policy-map** command displays an incorrect drop rate value.
Conditions: Occurs when you configuring a policy map that contains a class that applies QoS policing.
Workaround: There is no workaround; however, the issue has no functional impact. The router displays the correct number of drops under the policer's exceeded bps value.
- CSCud33329
Symptom: The active RSP displays traceback error messages occurring on the standby RSP.
Conditions: Occurs with the following configuration:
 - The router is configured with 1000 multicast groups
 - The outgoing interface is a bridge-domain interface (BDI)
 - All hosts are receiving a high rate of traffic.The issue occurs after you issue a stateful switchover (SSO).

- Workaround:** Avoid performing an SSO with the configuration described.
- CSCud33906
Symptom: Equal Cost Multipath (ECMP) loopback does not function properly.
Conditions: Occurs when a port-channel link dynamically assigned as an ECMP path.
Workaround: There is no workaround.
 - CSCud34346
Symptom: The router crashes.
Conditions: The issue can occur when:
 - The router is configured with multiple ECMP paths
 - MPLS IP is not enabled on one of the ECMP paths**Workaround:** There is no workaround.
 - CSCud38038
Symptom: The router records incorrect delay measurements after a reload.
Conditions: Occurs under the following conditions:
 - You configure Delay Measurement Message (DMM) on a port-channel interface.
 - The port-channel member links are on different interface modules (IMs).
 - You reload the router.**Workaround:** You can use the following workarounds:
 - Remove the **ethernet cfm global** command and re-apply it after the port-channel member links recover.
 - Configure PTP clock synchronization.
 - CSCud38115
Symptom: OSPF connections flap and drop traffic for approximately 20 seconds
Conditions: Occurs during stateful switchover (SSO).
Workaround: There is no workaround.
 - CSCud38419
Symptom: The router crashes when you apply an access control list (ACL) configuration. The issue occurs rarely and when the router is configured at a high scale.
Conditions: Occurs when:
 - You create and apply IPv6 ACLs
 - You remove the IPv6 ACLs
 - You replace the IPv6 ACLs with IPv4 ACLs
 - The IPv6 ACLs and IPv4 ACLs have the same names**Workaround:** Create IPv4 ACLs with different names from the IPv6 ACLs.
 - CSCud38433
Symptom: The router is unable to establish MPLS neighborhood or ping the destination loopback interface.
Conditions: Occurs when you configure two Equal Cost Multipath (ECMP) paths on a bridge domain interface (BDI) using static routes.

- Workaround:** The following workarounds exist:
- Use Interior Gateway Protocol (IGP) instead of static IP routes.
 - Shut down one of the ECMP paths.
- CSCud40930

Symptom: Some interfaces within a bridge-domain are unable to send outbound L3 multicast traffic.

Conditions: Occurs when the bridge-domain contains EFP interfaces, some of which are on a port-channel. The issue can also occur after a router reload.

Workaround: Issue a **shutdown/no shutdown** on the BDI interface.
 - CSCud44768

Symptom: Multilink bundles and member links flap when passing traffic.

Conditions: Occurs under the following conditions:

 - You configure more than 210 MLPPP bundles with one member link per bundle or 16 bundles with 16 member links each.
 - The line is operating at a 64 or 128 byte line rate

Workaround: There is no workaround.
 - CSCud44942

Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: Occurs when you configure a MEP on an interface.

Workaround: There is no workaround.
 - CSCud45336

Symptom: The router displays CPU hog error messages and crashes.

Conditions: Occurs when you reload the router a high number of Structure-agnostic TDM over Packet (SAToP) pseudowires.

Workaround: There is no workaround.
 - CSCud49749

Symptom: Copper Ethernet interface module (IM) ports remain in a suspended state after stateful switchover (SSO).

Conditions: Occurs when you create a port-channel with

 - Two links from a copper Ethernet interface to another copper Ethernet interface
 - One link from a copper Ethernet interface to an SFP Ethernet interface

Workaround: Issue a **shutdown/no shutdown** on copper-to-copper connection interfaces.
 - CSCud49980

Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: Occurs when you configure CFM MEPs on carrier edge (CE) routers and VPLS on provider edge (PE) routers.

Workaround: Create an EVC bridge-domain running CFM on the PE router and enable a virtual forwarding interface (VFI) on the bridge-domain.

- CSCud50851
Symptom: The router experiences flapping on REP connections.
Conditions: Occurs when you enable MAC limiting at a high scale and the set of MAC addresses changes continuously.
Workaround: Disable MAC limiting.
- CSCud50944
Symptom: The router drops traffic on an MLPPP bundle.
Conditions: Occurs following a reload while the router is passing traffic close to the line rate. The issue occurs less frequently with lower traffic rates.
Workaround: Issue a **shutdown/no shutdown** on multilink interface.
- CSCud52920
Symptom: SFP interfaces tied to a port-channel flap.
Conditions: The issue occurs rarely when the router is passing a high traffic volume.
Workaround: There is no workaround.
- CSCud56071
Symptom: The router does not pass loop-free alternate (LFA) IP fast reroute (IPFRR) traffic.
Conditions: Occurs when the router is configured with 10 or more IPv4 prefixes.
Workaround: Configure 9 or fewer prefixes.

Resolved Caveats—Cisco IOS XE Release 3.7(2)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.7(2)S.

- CSCua62029
Symptom: The router crashes.
Conditions: Occurs when you configure a class-based QoS policy with the following characteristics:
 - The policy is attached to the main interface.
 - The policy classifies on multiple VLANs.
 - The classification statements specify a priority.
 - The classification statements are within a child QoS policy.**Workaround:** There is no workaround.
- CSCua73104
Symptoms: The router does not increment QoS port shaper policy counters displayed by the **show policy interface** command.
Conditions: Occurs when you configure -A class-default policy on a physical interface -A class-based policy on an EVC interface
Workaround: There is no workaround; however, the router applies the QoS policy normally.

- CSCua96186
Symptom: The router drops cells on a CE-to-CE connection.
Conditions: Occurs with ATM VCC and VPC cell relay mode with 64-byte traffic. The issue occurs between the ASR 903 and ASR 901 routers.
Workaround: There is no workaround.
- CSCub69132
Symptom: The OC-3 interface module crashes.
Conditions: Occurs when you issue a soft reload on the OC-3 interface module when the router is configured with MLPPP at a high scale.
Workaround: There is no workaround.
- CSCuc36056
Symptom: Security ACLs with port ranges configured on BDI interfaces will not work on NILE1 ports.
Conditions: Issue with only on NILE1 ports. NILE0 ports will work properly
Workaround: There is no workaround.
PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5/4.1:
<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:L/Au:N/C:P/I:N/A:N/E:F/RL:OF/RC:C> CVE ID CVE-2012-5716 has been assigned to document this issue. Additional information on Cisco's security vulnerability policy can be found at the following URL:
http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html
- CSCuc44394
Symptom: The router stops passing MLPPP traffic after a Stateful Switchover (SSO).
Conditions: Occurs when you perform an SSO with a TDM interface module.
Workaround: There is no workaround.
- CSCuc57130
Symptom: The router does not apply OC-3 interface module (IM) configurations.
Conditions: Occurs after an RSP switchover.
Workaround: There is no workaround.
- CSCuc64899
Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).
Conditions: Occurs on interfaces with an xconnect statement after a reload on a peer device.
Workaround: Remove and re-apply the CFM configuration.
- CSCuc80964
Symptom: Interface module (IM) IM FPGA upgrade fails.
Conditions: Occurs on some IMs when you install an IOS image with bundled FPGA software.
Workaround: Manually upgrade the FPGA.

- CSCuc98590
Symptom: The router can crash when you remove a boundary clock (BC) configuration.
Conditions: Occurs very rarely when you remove a BC configuration.
Workaround: There is no workaround. However, the issue occurs very rarely.
- CSCud12587
Symptom: When handling IS-IS packets, the router punts the traffic to the Route Switch Processor (RSP) and applies policing to limit the traffic to 1 Mbps.
Conditions: Occurs when you enable IS-IS over an Ethernet over MPLS (EoMPLS) connection.
Workaround: Use IS-IS over another connection type or limit the IS-IS traffic to less than 1 Mbps.
- CSCud13535
Symptom: The router drops imposition traffic sent to a neighbor device over a VPLS pseudowire.
Conditions: Occurs when the neighbor device configuration includes the **no split horizon group** command.
Workaround: Remove the **no split horizon group** command from the VPLS neighbor device.
- CSCud28787
Symptom: The 10 gigabit Ethernet interface module (IM) flaps.
Conditions: Occurs when the IM passes high traffic volumes for an extended period of time.
Workaround: There is no workaround.
- CSCud43580
Symptom: The router does not apply the **bandwidth remaining percent** command within a QoS policy in some instances.
Conditions: The issue can occur occasionally when:
 - There is a large discrepancy in **bandwidth remaining** values between QoS classes
 - The classes containing the **bandwidth remaining** statements are oversubscribed at a low rate or have a low queue-limit.**Workaround:** Apply the following workaround:
 - Increase the **queue-limit** value to 120 kilobytes or above.
 - If the QoS configuration uses WRED, increase the minimum threshold value.
 - Alter the bandwidth remaining values to reduce the ratio between values.

Open Caveats—Cisco IOS XE Release 3.7(1)aS

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7(1)aS.

- CSCts95896
Symptoms: The router stops passing traffic on EVC interfaces.
Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

- Workaround:** Wait for the router to clear the old EFP configuration before adding a new configuration.
- CSCtw76473

Symptom: The router displays packet drops on some VPLS pseudowire virtual circuits (VCs) on the disposition side.

Conditions: Occurs under the following conditions:

 - The core network is running MPLS-TP tunnels
 - There is an SSO switchover on the remote end or an LDP neighbor reset on the peer end.

Workaround: There is no workaround.
 - CSCty34054

Symptom: The router displays CPU utilization traceback messages and drops all multicast traffic for 2050 seconds.

Conditions: Occurs under the following conditions:

 - Multicast is enabled with more than 500 multicast groups.
 - The router is using RSP1B in SSM mode.
 - BDI is configured on the access side of the router.
 - There are 24 EFPs on each bridge domain.
 - You enter a **shutdown** command on the access interface.

Workaround: There is no workaround.
 - CSCty45696

Symptom: The **show policy-map** command displays incorrect information.

Conditions: Occurs when you use the **show policy-map** command to display QoS policies on an EFP that has a port shaping QoS policy.

Workaround: There is no workaround.
 - CSCtz55979

Symptom: The router crashes.

Conditions: Occurs when you configure CFM, SCE over MPLS, VPLS, or G.8032 services while running SNMP polling.

Workaround: There is no workaround.
 - CSCtz68510

Symptom: The router displays a CPU HOG message.

Conditions: Occurs when you remove a PTP configuration.

Workaround: There is no workaround; however, the issue does not have any functionality impact.
 - CSCua62029

Symptom: The router crashes.

Conditions: Occurs when you configure a class-based QoS policy with the following characteristics:

 - The policy is attached to the main interface.
 - The policy classifies on multiple VLANs.

- The classification statements specify a priority.
- The classification statements are within a child QoS policy.

Workaround: There is no workaround.

- CSCua96186

Symptom: The router drops cells on a CE-to-CE connection.

Conditions: Occurs with ATM VCC and VPC cell relay mode with 64-byte traffic. The issue occurs between the ASR 903 and ASR 901 routers.

Workaround: There is no workaround.

- CSCub04699

Symptom: The **bandwidth** and **bandwidth percent** commands do not function correctly.

Conditions: Occurs when you configure a service-policy with the **priority** and **police** commands in one class and the **bandwidth** or **bandwidth percent** commands in another class.

Workaround: There is no workaround.

- CSCub48081

Symptom: The router does not learn remote MEPs on an EVC bridge-domain MEP following an interface module reset (soft OIR). The router displays messages indicating object download failure; the interface status of the xconnect MEP on the peer router displays as administratively down.

Conditions: Occurs when you

- Configure offloaded EVC xconnect MEP sessions and the sessions are active
- Configure EVC bridge-domain MEPs
- Perform a reset (soft OIR) of the Ethernet interface module

Workaround: Remove and restore the local MEP configuration on both routers.

- CSCub55760

Symptom: The router displays a Delay Measurement Message (DMM) delay value of 0.

Conditions: Occurs under the following conditions:

- You configure an EVC down MEP on a port-channel interface.
- You dynamically add a member link to a port-channel interface.

Workaround: Configure PTP synchronization before scheduling DMM.

- CSCub60668

Symptom: The router is unable to establish an OSPF session.

Conditions: Occurs when you enable an OSPF session over an MPLS TP tunnel.

Workaround: There is no workaround.

- CSCub69132

Symptom: The OC-3 interface module crashes.

Conditions: Occurs when you issue a soft reload on the OC-3 interface module when the router is configured with MLPPP at a high scale.

Workaround: There is no workaround.

- CSCub78861
Symptom: Following a reload, the router handles CFM only on 128 VLANs or bridge-domains.
Conditions: Occurs when the router configuration contains CFM and more than 128 VLANs or bridge-domains.
Workaround: There is no workaround.
- CSCuc00986
Symptom: The router drops MPLS TP sessions, impacting traffic.
Conditions: Occurs following an software upgrade (ISSU).
Workaround: There is no workaround.
- CSCuc23610
Symptom: The router does not pass IP traffic with an MPLS LDP tunnel label of Imp-null.
Conditions: Occurs when the router is switching traffic using IP fast-reroute (FRR).
Workaround: Configure the `mpls ldp explicit-null` command.
- CSCuc31037
Symptom: The router stops passing traffic on pseudowire connections.
Conditions: Occurs in a redundant system following a stateful switchover (SSO).
Workaround: There is no workaround.
- CSCuc34088
Symptom: The router passes lower traffic levels when you add links to an IMA bundle and perform IM OIR/router reload.
Conditions: Occurs when you send traffic above the E1 line rate on one link within an IMA bundle and reset (OIR) the interface module.
Workaround: Remove and re-apply the IMA interface configuration.
- CSCuc36522
Symptom: The router does not timestamp traffic on port-channel interfaces.
Conditions: Occurs when you configure a CFM EVC bridge-domain up MEP on a port-channel.
Workaround: There is no workaround.
- CSCuc42085
Symptom: The 1PPS output from the ASR 903 is out of range when compared to the 1PPS output of the PTP master clock.
Conditions: Occurs when the router is configured as a hybrid clock (ordinary/boundary) and there are intermediate hops between the router and the PTP master clock. To date the problem occurs only when the intermediate hops are through an ASR 9000 router.
Workaround: There is no workaround.
- CSCuc42206
Symptom: Links on copper SFP interface flap during stateful switchover (SSO).
Conditions: Occurs when you initiate a stateful switchover (SSO) on a redundant system with a copper SFP.
Workaround: There is no workaround.

- CSCuc44394
Symptom: The router stops passing MLPPP traffic after a Stateful Switchover (SSO).
Conditions: Occurs when you perform an SSO with a TDM interface module.
Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.7(1)aS

This section documents the issues that have been resolved in Cisco IOS XE Release 3.7(1)aS.

- CSCty63969
Symptoms: Ping fails to remote MEPs.
Conditions: Occurs when you configure CFM and ping RMEPs with a packet size of greater than 1478 bytes.
Workaround: There is no workaround.
- CSCua02058
Symptoms: When you configure the OC-3 interface module, only 1000 of 1008 interfaces are configurable on the router; of the 1000 interfaces, only 957 become active.
Conditions: Occurs when you configure interfaces on the OC-3 interface module.
Workaround: There is no workaround.
- CSCua51772
Symptoms: The router does not display PID or DOM values.
Conditions: Occurs with the following SFPs:
 - ONS-SI-155-L2
 - ONS-SI-155-L1
 - ONS-SI-155-I1**Workaround:** There is no workaround.
- CSCua55122
Symptoms: The OC-3 interface module crashes when you create a high number of ATM IMA interfaces.
Conditions: Occurs when you configure multiple ATM IMA interfaces with fewer than 16 links per bundle.
Workaround: Perform a hard OIR on the interface module.
- CSCua87805
Symptoms: The OC-3 interface module goes into an Out Of Service state.
Conditions: The issue can occur during bootup or OIR of the OC-3 interface module.
Workaround: Perform an OIR on the OC-3 interface module.
- CSCua93803
Symptoms: The **boot system flash** command displays unexpected behavior.
Conditions: Occurs when you use the **boot system flash** command in either of the following formats:

- **boot system flash *filename***—The router does not boot using the specified file.
- **boot system flash**—The router does not boot the first image in bootflash.

Workaround: Use the **boot system bootflash** command as follows:

- **boot system bootflash: *filename***—Boots a specific file.
- **boot system bootflash:**—Boots the first image in bootflash.

- CSCua95522

Symptoms: The router displays the following warning during bootup:

```
"Warning: monitor nvram area is corrupt ... using default values"
```

Conditions: Occurs during bootup and indicates that the NVRAM is corrupted, causing loss of a bootloader variable. To verify the issue, confirm whether the **set rommon mode** command produces output matching the following example:

```
rommon 1 > set
PS1=rommon ! >
rommon 2 >
```

The issue can be caused by an error during shutdown or saving the configuration and occurs very rarely.

Workaround: Set the bootloader variables on the standby RSP.

- CSCua99096

Symptoms: The **show ima interface** command omits some IMA group information such as ImaGroupSymmetry.

Conditions: Occurs when you apply the **show ima interface** command.

Workaround: There is no workaround.

- CSCua99096

Symptoms: The **show ima interface** command omits some IMA group information such as ImaGroupSymmetry.

Conditions: Occurs when you apply the **show ima interface** command.

Workaround: There is no workaround.

- CSCub04699

Symptom: The **bandwidth** and **bandwidth percent** commands do not function correctly.

Conditions: Occurs when you configure a service-policy with the **priority** and **police** commands in one class and the **bandwidth** or **bandwidth percent** commands in another class.

Workaround: There is no workaround.

- CSCub55266

Symptoms: The router hangs when booting.

Conditions: Occurs under the following conditions:

- You issue the boot command without any arguments, e.g. `rommon 1> boot`
- The router attempts to boot using a non-bootable image in bootflash memory.

Workaround: There is no workaround.

- CSCub71578
Symptoms: The router displays traceback and failure messages on the standby RSP.
Conditions: Occurs after you issue an OIR on the T1/E1 interface module from the active RSP. The issue occurs in a redundant system.
Workaround: There is no workaround.
- CSCub74338
Symptoms: The router crashes.
Conditions: Occurs when you attach an ingress QoS policy-map to an EVC with a rewrite push configuration.
Workaround: There is no workaround.
- CSCub77285
Symptom: Some T1/E1 interfaces do not come up.
Conditions: Occurs with T1/E1 configurations at a high scale; the interfaces display a false alarm.
Workaround: Reset individual T1/E1 interfaces; after a reset, the interfaces become active.
- CSCub89029
Symptoms: When the router boots, copper Gigabit Ethernet ports display an up/up status but do not pass traffic.
Conditions: Occurs when the port has a negotiated speed other than 1 Gigabit, such as 100 Mbps.
Workaround: Issue a shutdown/no shutdown on affected ports.
- CSCuc36241
Symptoms: The router is unable to select a given PTP clock as a network clock source.
Conditions: Occurs when you configure PTP as an input network clock source while the slave clock is still in a holdover state. In the holdover state, the slave clock has not yet attempted to establish a frequency lock with a master clock.
Workaround: Wait for the PTP slave clock to lock to the master clock before configuring PTP as a network clock input source.

Open Caveats—Cisco IOS XE Release 3.7(0)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.7.0S.

- CSCts95896
Symptoms: The router stops passing traffic on EVC interfaces.
Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.
Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtw72855

Symptoms: The router does not pass traffic towards the access side on VCs configured with QoS shaping output policy.

Conditions: Occurs when you configure a QoS shaping output policy.

Workaround: There is no workaround.
- CSCty28986

Symptoms: A configuration with a high number of down MEPs does not function properly.

Conditions: Occurs when you configure 500 or more down MEPs with 500 or more xconnect configurations between service instances.

Workaround: Configure no more than 200 CFM sessions.
- CSCty34054

Symptoms: The router displays CPU utilization traceback messages and drops all multicast traffic for 2050 seconds.

Conditions: Occurs under the following conditions:

 - Multicast is enabled with more than 500 multicast groups
 - The router is using RSP1B in SSM mode
 - BDI is configured on the access side of the router
 - There are 24 EFPs on each bridge domain
 - You enter a **shutdown** command on the access interface.

Workaround: There is no workaround.
- CSCty51990

Symptoms: The router may crash or restart; the console displays a SW_WDOG: expired message.

Conditions: Occurs under the following conditions:

 - The router is configured with 63 or more instances of a unique EVC configured with a unique bridge domain interface (BDI).
 - The router is sending IGMP joins to one multicast group.
 - You perform a shutdown/no shutdown on the interface sending IGMP join messages.
 - You perform an OIR on the router.

Workaround: There is no workaround.
- CSCty70119

Symptoms: Port shaper rate changes do not take effect.

Conditions: Occurs when QoS policies attached to EVCs on an interface do not include a shaper configuration; the issue does not occur on EFP policies that include a shaper in a class.

Workaround: Include a shaper in one class of the EFP policy.
- CSCty73362

Symptoms: The router experiences CPP download failures when sending IGMP join messages.

Conditions: Occurs when the router is configured with a trunk EFP in SM mode on the access side and is sending IGMP join messages to more than 1970 multicast groups.

Workaround: There is no workaround.

- CSCty74115
Symptoms: The router displays traceback and CPU error messages.
Conditions: Occurs when you configure a high number of MAC address table entries while REP is enabled; the router displays errors during a REP topology change, REP preemption, or when you perform a shutdown/no shutdown on an interface.
Workaround: Reduce the MAC scale.
- CSCty79987
Symptoms: CFM up and down MEPs do not reach a scale of 1000 CFM sessions.
Conditions: Occurs when you configure CFM on a trunk EFP.
Workaround: There is no workaround.
- CSCtz20087
Symptoms: The router applies the class-default QoS policy to all outgoing traffic.
Conditions: Occurs under the following conditions:
 - You configure multiple egress QoS policies on a Gigabit Ethernet interface.
 - You configure a multilink interface with no ingress QoS policy**Workaround:** There is no workaround.
- CSCtz32327
Symptoms: The router crashes.
Conditions: Occurs when you perform an OIR on the OC-3 IM after an SSO switchover.
Workaround: There is no workaround.
- CSCtz40690
Symptoms: Traceroute to a remote MEP fails.
Conditions: Occurs under the following conditions:
 - You configure a EVC bridge-domain MEP on a remote device
 - You configure a MIP on a trunk EFP on an intermediate device.
 - You issue the **traceroute** command to the remote MEP**Workaround:** There is no workaround.
- CSCtz49927
Symptoms: Traffic floods on an EFP interface.
Conditions: Occurs when you configure a multicast static MAC on a bridge-domain and add more than 24 EFPs.
Workaround: Remove the extra EFPs from the bridge-domain.
- CSCtz55979
Symptoms: The router crashes.
Conditions: Occurs when you configure CFM, SCE over MPLS, VPLS, or G.8032 services while running SNMP polling.
Workaround: There is no workaround.

- CSCtz75641
Symptoms: The router does not pass traffic over an EVC PC port-channel.
Conditions: Occurs when you perform the following sequence of actions:
 - Remove an EVC member link from a port-channel interface
 - Configure a trunk EFP -Set the interface to default
 - Add the EVC member link back into the port-channel interface**Workaround:** Reload the router.
- CSCtz77491
Symptoms: The router stops passing traffic and crashes.
Conditions: Occurs when you remove a QoS policy applied to a trunk EFP.
Workaround: There is no workaround.
- CSCtz82725
Symptoms: The router intermittently drops packets.
Conditions: Occurs on 10 Gigabit Ethernet core links when the router passes traffic for an extended period and running a VPLS-TP configuration.
Workaround: There is no workaround.
- CSCtz87262
Symptoms: The router's convergence time is greater than 90 seconds when you clear the multicast routing table.
Conditions: Occurs with a ring topology with 2 parallel paths from the FHR to the LHR Receivers.
Workaround: There is no workaround.
- CSCtz90273
Symptoms: The router duplicates multicast traffic when configured as a static rendezvous point (RP) node.
Conditions: Occurs under either of the following conditions:
 - You remove Auto RP announce configurations on all routers.
 - You configure the router as a static RP and enable multicast traffic**Workaround:** Select an RP mode: static, auto, or bootstrap router (BSR) and avoid switching dynamically between RP modes.
- CSCtz92857
Symptoms: MAC learning fails and the router displays FIFO table overflow messages.
Conditions: Occurs with a MAC security configuration running at high scale.
Workaround: There is no workaround.
- CSCtz92914
Symptoms: L3 multicast replication fails on some of the EFPs.
Conditions: Occurs under the following conditions:
 1. You configure a group of EFPs and map each EVC to a different bridge-domain.
 2. You create a QoS policy-map on each EVC.
 3. All BDI send IGMP joins to single multicast group.

4. The router initiates multicast data traffic
 5. You remove and reconfigure some of the EFPs
- Workaround:** Configure the EFPs and bridge-domains and initiate traffic flow before attaching QoS policies.
- CSCua03439

Symptoms: The router displays error messages similar to the following:
%EVENTLIB-3-CPUHOG: SIP0: nile_mgr:

Conditions: Occurs when you boot the router running QoS configurations at a high scale, particularly queues.

Workaround: There is no workaround.
 - CSCua12366

Symptoms: The IOMD process corresponding to OC3 IM (interface module) crashes.

Conditions: Occurs when you perform an IM OIR after the router has been passing traffic.

Workaround: There is no workaround; the IM recovers after the crash and resumes traffic.
 - CSCua16143

Symptoms: IPv6 BFD sessions drop after you perform an SSO.

Conditions: Occurs when you perform an SSO on the router while running an IPv6 BFD configuration. The issue does not occur with an IPv4 BFD configuration.

Workaround: After SSO, perform a shutdown/no shutdown on the physical interface.
 - CSCua16492

Symptoms: Some IPv6 multi-hop BFD over BGP sessions flap.

Conditions: Occurs on port-channel interfaces running IPv6 multi-hop BFD over BGP sessions after you perform an SSO.

Workaround: There is no workaround.
 - CSCua25932

Symptoms: Convergence caused by an interface flap takes more than 50 milliseconds.

Conditions: Occurs when you enable BGP PIC core and LFA FRR at the same time.

Workaround: Use LFA FRR, as it converges in less than 50 milliseconds for BGP VPNv4 prefixes.
 - CSCua33453

Symptoms: A CFM configuration crashes after passing traffic for several hours.

Conditions: Occurs when you create the following configuration:

 - A port-channel interface configured with an EVC and applied to a bridge-domain
 - A physical interface configured as a trunk EFP
 - The **offload sampling** command is configured on both interfaces

Workaround: There is no workaround.
 - CSCua33788

Symptoms: The router does not pass multicast traffic consistently; only some traffic passes.

Conditions: Occurs when you configure 255 EVCs spanning across different slots on the router.

Workaround: There is no workaround.

- CSCua36065

Symptoms: The router forwards multicast traffic on 63 out of 255 multicast output interfaces (OIFs).

Conditions: Occurs when you configure the following:

 - 255 EVCs on a single port mapped to 255 BDIs (one EVC per BDI) using rewrite tagging.
 - 255 BDIs which send IGMP v2 Joins to a single multicast group.
 - 255 EVCs configured as a routed port with the port a member link of a port-channel.
 - 255 EVCs configured on a port-channel and sending multicast traffic to a multicast group

Workaround: There is no workaround.
- CSCua38675

Symptoms: The router displays a QoS Stats Stalled error message and stops applying QoS configurations.

Conditions: Occurs when you apply a flat VLAN policy to a trunk EFP interface.

Workaround: There is no workaround.
- CSCua41400

Symptoms: QoS classification does not function properly.

Conditions: Occurs when you create QoS class containing a policy that classifies on both ACL and DSCP value.

Workaround: There is no workaround.
- CSCua43843

Symptoms: QoS classification fails when you configure the **match vlan** command under a class-map.

Conditions: Occurs when the router is configured with an EVC with the **encapsulation default** command.

Workaround: Change the encapsulation to dot1q.
- CSCua52162

Symptoms: The router does not learn remote CFM MEPs on EFP interfaces.

Conditions: Occurs when you configure rewrite push operation on an EFP interface.

Workaround: There is no workaround.
- CSCua52187

Symptoms: The router crashes when you attach a QoS policy.

Conditions: Occurs when you apply a QoS class-map that

 - Matches traffic based on an ACL
 - References an ACL not present in the running configuration
 - Is referenced in a policy with a DSCP marking action

Workaround: There is no workaround.

- CSCua54547
Symptoms: The router does not learn remote CFM MEPs.
Conditions: Occurs under the following conditions:
 - The router is connected to the remote MEPs via a pseudowire connection.
 - The router is configured with MPLS on a bridge-domain interface
 - Dot1q encapsulation is configured on an EFP.**Workaround:** Configure the EFP encapsulation as untagged.
- CSCua55122
Symptoms: The OC-3 interface module crashes when you create a high number of ATM IMA interfaces.
Conditions: Occurs when you configure multiple ATM IMA interfaces with fewer than 16 links per bundle.
Workaround: Perform a hard OIR on the interface module.
- CSCua56761
Symptoms: Gigabit Ethernet port 0/5/1 does not timestamp Ethernet OAM Y.1731 packets.
Conditions: Occurs when you configure Ethernet OAM on port 0/5/1 of a copper or SFP Gigabit Ethernet interface module.
Workaround: There is no workaround.
- CSCua61909
Symptoms: Changes to the **police** QoS command do not take effect.
Conditions: Occurs under the following conditions:
 - You create a QoS policy with a policer and attach the policy to an interface.
 - You make a dynamic change to the police action such as altering the policer value, conform-action value, or exceed-action value.**Workaround:** Remove the policy from the interface, make the necessary changes, and re-attach the policy.
- CSCua67795
Symptoms: The router does not transmit Y.1731 Delay Measurement Message (DMM) values using QinQ encapsulation.
Conditions: Occurs with the following configuration:
 - An EFP is configured and applied to a bridge-domain.
 - The EFP is configured with QinQ encapsulation.
 - A Y.1731 Delay Measurement Message (DMM) value is applied.
 - The Y.1731 traffic uses a CoS value other than 0.**Workaround:** There is no workaround.
- CSCua70585
Symptoms: The router does not update Gigabit Ethernet interface bitmaps after you remove an EFP from a multicast group. The router can display CPU hog messages.
Conditions: Occurs under the following conditions:
 - You create an EFP on a single bridge-domain interface (BDI)

- The router receives IGMP v2 or v3 SSM Joins to the BDI
- You create a second EFP on the same BDI
- You delete the first or second EFP.

Workaround: There is no workaround.

- CSCua72298

Symptoms: The router stops passing traffic on 10-15 HDLC interfaces.

Conditions: Occurs when you configure a large number of HDLC interfaces: 84 per port or 336 per interface module.

Workaround: Remove and reconfigure the interface.

- CSCua73104

Symptoms: The router does not increment QoS port shaper policy counters displayed by the **show policy interface** command.

Conditions: Occurs when you configure -A class-default policy on a physical interface -A class-based policy on an EVC interface

Workaround: There is no workaround; however, the router applies the QoS policy normally.

Resolved Caveats—Cisco IOS XE Release 3.7(0)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.7.0S.

- CSCtx00558

Symptoms: The standby RSP crashes during bootup.

Conditions: The issue can occur during bootup of a dual RSP system.

Workaround: There is no workaround.

- CSCtx02522

Symptoms: The router displays intermittent traceback errors.

Conditions: Occurs when you configure REP.

Workaround: There is no workaround.

- CSCty42336

Symptoms: BFD sessions flap on the router.

Conditions: Occurs when the router is running IP BFD sessions in echo mode with 64 200ms X3 timers.

Workaround: There is no workaround.

- CSCty74129

Symptoms: A REP topology may reconverge during an RSP switchover. The console displays REP no-neighbor messages.

Conditions: Occurs when you configure REP between two Cisco ASR 903 Routers and you perform an RSP switchover.

Workaround: There is no workaround.

- CSCty77466
Symptoms: The port shaper rate changes on RSP switchover.
Conditions: Occurs under the following conditions:
 - You attach a shaper policy to an interface
 - The interface is configured with multiple EVCs
 - The EVC has a QoS policy attached.**Workaround:** Remove and re-attach the policy on the interface.
- CSCtz03779
Symptoms: The standby RSP crashes during ISSU.
Conditions: Occurs when you perform an ISSU downgrade from Release 3.6 to 3.5.
Workaround: There is no workaround.
- CSCtz09708
Symptoms: The router cannot establish a PTP session when configured as a PTP slave device.
Conditions: Occurs when the router receives PTP packets containing a VPN or VRF label.
Workaround: There is no workaround.
- CSCtz54650
Symptoms: REP flaps intermittently.
Conditions: Occurs with a hybrid REP configuration containing ports with and without Fast LSL enabled.
Workaround: Configure all interfaces with Fast LSL.
- CSCtz56517
Symptoms: The router drops MPLS packets with a checksum of 0xFFFF.
Conditions: Occurs when the ASR 903 is acting as a label disposition edge label switch router (LSR).
Workaround: There is no workaround.
- CSCtz61153
Symptoms: The ASR 903 does not establish BFD neighbors over port-channel 16.
Conditions: Occurs when you configure BFD on port-channel 16 between two ASR 903 routers.
Workaround: Configure BFD on port-channels 1 - 15.



Restrictions and Caveats in Cisco IOS XE 3.8S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.8 releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions, page 1](#)
- [Caveats in Cisco IOS XE 3.8S Releases, page 6](#)

Limitations and Restrictions

The following sections describe the Cisco ASR 903 Router limitations in IO S XE 3.8 releases:

- [Limitations and Restrictions in Cisco IOS XE Release 3.8\(2\)S, page 1](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.8\(1\)S, page 1](#)
- [Limitations and Restrictions in Cisco IOS XE Release 3.8\(0\)S, page 2](#)

Limitations and Restrictions in Cisco IOS XE Release 3.8(2)S

There are no changes in limitations and restrictions in Cisco IOS XE Release 3.8(2)S; the restrictions from Cisco IOS XE Release 3.8(0)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.8(1)S

Cisco IOS XE Release 3.8(1)S introduces the following new limitations:

EFP Limitation

- The Cisco ASR 903 Router supports a maximum of 36 trunk EFPs; this release increases the maximum number from 24 to 36.

All other restrictions from IOS XE Release 3.8(0)S still apply.

Limitations and Restrictions in Cisco IOS XE Release 3.8(0)S

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.8(0)S:

TDM Limitation

- The **configure replace** command is not supported for TDM interfaces.

ATM IMA Limitation

- You can create a maximum of 16 IMA groups on each T1/E1 interface module.
- High Availability (HA) is not supported with IMA.

Bidirectional Forwarding Detection Limitations

- The ASR 903 does not support BFD timers with a value of less than 200 ms x 3 (using a multiplier of 3) for software-based BFD sessions.

Bridge Domain Interface Limitation

- The **mtu** command is not supported on BDI interfaces; however the **ip mtu** command is supported.

Clocking and Timing Limitation

- Only a single clocking input source can be configured within each group of eight ports (0-7 and 8-15) on the T1/E1 interface module using the **network-clock input-source** command.
- Synchronous Ethernet clock sources are not supported with PTP. Conversely, PTP clock sources are not supported with synchronous Ethernet. However, you can use hybrid clocking to allow the router to obtain frequency using Synchronous Ethernet and phase using PTP.

Dying Gasp Limitations

The ASR 903 supports dying gasp under the following scenarios:

- Ethernet OAM is disabled
- Interface is shut down
- Interface enters error-disabled state
- Router reload

Dying Gasp is not supported in the event of a power failure.

EFP Limitations

- QinQ is not supported on trunk EFP interfaces.
- The Cisco ASR 903 Router supports a maximum of 24 trunk EFPs.

Equal Cost Multipath Limitation

- The Cisco ASR 903 Router supports a maximum of 4 Equal Cost Multipath (ECMP) links.

Ethernet IM Limitations

- The Cisco ASR 903 Router does not support the Facilities Data Link (FDL) on Ethernet interfaces.
- The Cisco ASR 903 Router does not support the **mac-address** command on Gigabit Ethernet interface modules.
- 10 Gigabit Ethernet interface modules are not supported in slots 4 and 5.

- When you install a Gigabit Ethernet IM in the topmost interface module slot (slot 5), the last interface (interface GigabitEthernet0/5/0) is not operational; the port is reserved for internal communication.
- When you configure the copper and SFP Gigabit Ethernet interface modules on a router with redundant RSPs, the **speed** and **duplex** commands are not visible in interface configuration mode until you apply a **shutdown/no shutdown** to the interface.
- Fragmentation is not supported with Multicast traffic.

IPv6 Limitations

The following limitation applies when using IPv6 on the Cisco ASR 903 Router:

- IPv6 Neighbor Discovery (ND) cache timer expiry is 4 hours. To prevent the neighbour adjacency from being deleted after the timer expires:
 - configure hardware based BFD sessions with the neighbours, or
 - configure static IPv6 neighbours, or
 - configure the **ipv6 nd cache expire timer refresh** command.

IS-IS Limitations

- IS-IS over IPv6 is not supported on VRF instances.
- Only one IS-IS process is permitted when you configure IS-IS with the **address-family ipv6** and **bfd-all-interfaces** commands.
- The IS-IS total and per-stream convergence time increases as the number of prefixes increases.

MLPPP Limitations

The following limitations apply when using MLPPP on the Cisco ASR 903 Router:

- All links in an MLPPP bundle must be on the same interface module.
- All links in an MLPPP bundle must be of the same bandwidth.
- The Cisco ASR 903 Router supports a maximum of 8 links per bundle
- To change the MLPPP bundle fragmentation mode between enabled and disabled, perform a **shutdown/no shutdown** on the bundle.
- LFI is not supported
- Multiclass MLP is not supported
- The Cisco ASR 903 Router supports MLPPP statistics with the following limitations:
 - Packet counters on the bundle display the number of fragments rather than packets.
 - Control packets are accounted on the bundle.
- If you increase the maximum transmission unit (MTU) size on an MLPPP interface to a value higher than the maximum received reconstructed unit (MRRU) value on the peer interface, this can bring the MLPPP tunnel down. To restore the tunnel, perform a shutdown/no shutdown on the interface.

MPLS VPN Limitation

- MPLS VPN (L3VPN) Fragmentation does not function properly if an access interface has a higher MTU value than a core interface. To ensure that fragmentation functions correctly, configure the core interface MTU with a value that exceeds the access interface MTU and relevant headers.

OC-3 IM Limitations

- The **configure replace** command is not supported on the OC-3 IMs.
- The optical interface module is designed for OC-3 and OC-12 traffic, but OC-12 functionality is not currently supported.
- MPLS-TP is not supported over POS interfaces.
- Multicast is not supported on POS, MLPPP and OC-12 interfaces.
- MPLS is supported only on PoS and MLPPP interfaces; MPLS on T1/E1 links is not supported.
- IP-FRR and BFD-triggered FRR are not supported on MPLS over POS links.
- Fragmentation is not supported with Multicast traffic on PoS interfaces.
- QoS is not supported with Multicast traffic on PoS interfaces.
- QoS is supported on POS interfaces on optical interface module.
- Three-level QoS policies are not supported on OC-3/OC-12 serial, MLPPP, and PoS interfaces. You can only apply QoS policies on two levels on these interfaces.

Pseudowire/AToM Limitation

- The Cisco ASR 903 Router supports ATM over MPLS N-to-one cell mode for a single ATM Virtual Channel Connections (VCCs) or Permanent Virtual Circuits (PVCs) to a pseudowire, but does not support mapping to multiple VCCs or PVCs.
- The Cisco ASR 903 Router does not support ATM over MPLS one-to-one cell mode.
- The Cisco ASR 903 Router supports pseudowire ping using the CW method; pseudowire ping using the TTL method is not supported.
- The Cisco ASR 903 Router supports a maximum of 2000 pseudowires in any combination.

The following pseudowire (PW) features are supported over MPLS-TP connections:

- ATM over MPLS PWs
- ATM attachment circuits
- AAL5 Encapsulation
- ATM VC Class Support
- Cell Relay including VC mode, VP mode, and Packed Cell Relay
- CESoPSN
- L2VPN pseudowire redundancy
- Multi-segment PWs
- PW OAM/Status TLV Support
- PW Redundancy
- SAToP

The following pseudowire (PW) features are not supported over MPLS-TP connections:

- ATM OAM Cell Emulation for ATM AAL5 over MPLS on PVC and in VC Class.
- BFD / VCCV over ATM AC over MPLS TP
- BFD/ VCCV over TDM PW over MPLS TP Manageability
- Ethernet VLAN to Ethernet VLAN L2VPN interworking (bridged and routed modes)
- Ethernet VLAN to ATM AAL5 L2VPN Interworking (bridged and routed modes)

- Ethernet port to ATM AAL5 PVC L2VPN Interworking (bridged and routed modes)
- Layer 2 QoS features such as classifying or marking based on an L2 value
- MIB support including PW-TDM-MIB, PW-ATM-MIB, and PW-CESOPSN-MIB
- N:1 PVC Mapping with non-unique VPI (N>1)

QoS Limitations

For a description of QoS features and limitations on the Cisco ASR 903 Router in Release 3.8S, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.8.0S/ASR903-Chassis-SW-38.html>

Software Upgrade Limitation

- We recommend you set the **interface-module-delay** value to 150 or greater in order to ensure sufficient time for IM software upgrades.

Subinterfaces Limitation

- The Cisco ASR 903 router does not support subinterface configurations except on ATM interfaces.



Note You can configure similar functionality using multiple Ethernet Virtual Connections on an interface. For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#).

T1/E1 IM Limitations

- Inverting data on the T1/E1 interface is not supported—Inverting the data stream using the invert data interface command is not supported.
- Bit error rate test (BERT) patterns have limited support—Currently, only the 2¹¹, 2¹⁵, 2²⁰-O153, and 2²⁰-QRSS patterns are supported for BERT.
- If you issue the **no card type** command on the controller, you must reload the router in order to configure a new **card type** value.

VPLS BGP Signaling

- TE as core interface is supported for VPLS BGP Signalling but TE as preferred path is *not* supported.
- MAC Flushing is *not* supported in this release for VPLS BGP Signaling.
- Templates are *not* supported in this release for VPLS BGP Signaling.
- Support for H-VPLS is available only for the hierarchical route reflector (RR) model.
- BGP Signaling Inter-AS Option A is supported in this release. BGP Signaling Inter-AS Option B and Inter-AS Option C are *not* supported in this release.
- Maximum number of supported BGP Signaling neighbors per VFI is 32.
- When route designator (RD) is explicitly configured within the same VPLS domain, the virtual forwarding interface (VFI)s with the same VPN ID on different PE's must have the same RD configured (as the auto-generated RD is same for Intra AS). Thus, all the PE's within a VPLS domain must have the same RD. See [Example: Configuring VPLS BGP Signaling with Explicit RD Configurations.](#), page 6.

For more information, see [VPLS BGP Signaling](#).

Example: Configuring VPLS BGP Signaling with Explicit RD Configurations:

```

l2vpn vfi context TEST1
  vpn id 1
  autodiscovery bgp signaling bgp
  ve id 1
  ve range 100
  rd 2:1      ---> RD must be same for all the VFI's in all the PE's
  route-target export 2:1
  route-target import 2:1
  no auto-route-target

router bgp 100
  bgp graceful-restart
  neighbor 209.165.200.224 remote-as 100
  neighbor 209.165.200.224 update-source Loopback1
  !
  address-family l2vpn vpls
    neighbor 209.165.200.224 activate
    neighbor 209.165.200.224 send-community extended
    neighbor 209.165.200.224 suppress-signaling-protocol ldp
  exit-address-family

```

Caveats in Cisco IOS XE 3.8S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.8S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

**Note**

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select caveats of any severity. To reach the Bug Toolkit, log in to Cisco.com and go to http://www.cisco.com/pcgi-bin/Support/Bugtool/launch_bugtool.pl. (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.8S Releases:

- [Open Caveats—Cisco IOS XE Release 3.8\(2\)S, page 7](#)
- [Resolved Caveats—Cisco IOS XE Release 3.8\(2\)S, page 12](#)
- [Open Caveats—Cisco IOS XE Release 3.8\(1\)S, page 20](#)
- [Resolved Caveats—Cisco IOS XE Release 3.8\(1\)S, page 23](#)
- [Open Caveats—Cisco IOS XE Release 3.8\(0\)S, page 36](#)

- [Resolved Caveats—Cisco IOS XE Release 3.8\(0\)S, page 43](#)

Open Caveats—Cisco IOS XE Release 3.8(2)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.8(2)S.

- CSCua77688

Symptom: The router experiences remote CFM MEP flapping.

Conditions: This issue occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.

Workaround: Reduce the rate of traffic.

- CSCub63072

Symptom: Traffic drop of more than 50ms observed after a network failure occurs even though LFA FRR and BGP PIC Core are configured.

Conditions: This issue occurs when there is a network failure.

Workaround: There is no workaround.

- CSCuc08397

Symptom: When IFM is configured on EVC BD with encapsulation default in the Core, the remote MEPS are not learnt.

Conditions: This issue occurs when encapsulation default is configured in the Core.

Workaround: There is no workaround.

- CSCuc59386

Symptoms: Continuous IOMD crashes occur on OC-3 IM. Interfaces on OC-3 IM are not configurable and the router displays the following error message:

```
"stand-by does not support this command"
```

Conditions: This issue occurs with OC-3 IM in a redundant configuration when an IOMD crash occurs on the active RSP and the standby IOMD session handle is not cleared.

Workaround: Reload the standby RSP.

- CSCuc62168

Symptom: FMFP-3-OBJ_DWNLD_TO_CPP_FAILED error messages seen after a HA switchover is performed when the standby RP is booting.

Conditions: This issue occurs when CFM offloads with a CC interval of 3.3/10/100ms.

Workaround: There is no workaround.

- CSCuc70509

Symptom: Packet rate counters (packets per second) are not cleared to 0 when interface goes down.

Conditions: This issue occurs on all TDM interfaces like serial, MLPPP, and POS. The issue is observed on controller shutdown and not observed on interface shutdown.

Workaround: There is no workaround.

- CSCuc93653

Symptom: Replication fails on the newly added BDIs for Trunk EFP.

Conditions: This issue occurs when new BDIs are added to Trunk EFP with static join.

Workaround: Use dynamic join to add the BDIs.

- CSCud04161

Symptom: The router incorrectly displays a CFM Delay Measurement Message (DMM) value of 0.

Conditions: This issue occurs under any of the following conditions:

– You dynamically add a member link to a port-channel.

– You issue a **shutdown** command followed by **no shutdown** command on a member link of a port-channel.

Workaround: Wait for PTP to synchronize before configuring DMM scheduling.

- CSCud09142

Symptom: Fp active errors are displayed after removing the tunnel-tp interface with high-availability configured.

Conditions: This issue occurs after removing the tunnel-tp interface.

Workaround: There is no workaround.

- CSCud28982

Symptom: The router does not process egress QoS marking on an Ethernet service instance.

Conditions: Occurs when you configure QoS on an Ethernet service instance that is a member of a bridge-domain and uses dot1q encapsulation.

Workaround: There is no workaround.

- CSCud30554

Symptom: Object download failure messages are displayed on console during object cleanup. This would cause a possible leak in the hardware resource if the objects are not cleaned up later.

Conditions: This issue occurs during object cleanup and during the VC deletion.

Workaround: There is no workaround.

- CSCud37927

Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs) and FPGA gets stuck.

Conditions: This issue occurs under the following conditions:

– UP MEP and more than one port on the core side connected to the other router.

– If REP or STP is already configured on core interface, and then UP MEP is configured.

– REP or STP is running and one of the port is ALT or BLK state and a **shutdown** followed by a **no shutdown** is performed on the interface. Or an OIR of the IM is performed causing REP/STP state changes and the FPGA gets stuck.

Workaround: There is no workaround.

- CSCud61551

Symptom: Serial Number of the RSP in slot 1 does not display in the **show inventory** command output.

Conditions: This issue occurs under unknown conditions.

Workaround: Reload the router.

- CSCud64436

Symptom: The router does not send the full line rate on POS interfaces.

Conditions: This issue occurs when you send traffic over a POS interface on the OC-3 interface module with a QoS configuration.

Workaround: There is no workaround.

- CSCud89451

Symptom: The router crashes with an error message showing `nmpls_label_populate_flow_data`.

Conditions: This issue occurs when you reset a core interface while the ASR 903 is acting as a PE router and running a configuration with L2VPN and L3VPN.

Workaround: There is no workaround.

- CSCud98985

Symptom: Invalid command errors were detected for a few commands.

Conditions: This issue occurs on executing **show tech-support** command.

Workaround: There is no workaround.

- CSCud99692

Symptom: The convergence time takes more than 3 seconds.

Conditions: This issue occurs in Border Gateway Protocol (BGP) PIC core when path is moved from one active path to 2 Equal Cost Multipath (ECMP) Paths.

Workaround: There is no workaround.

- CSCue01419

Symptoms: EIGRP neighborship is lost on OC-3 IM and OC-12 IM interfaces configured on port 0.

Conditions: This issue occurs on interfaces configured on port 0 of OC-3 IM and OC-12 IM. This issue is not seen on ports 1,2 or 3.

Workaround: Perform a shutdown followed by no shutdown on interfaces configured on port 0. Alternatively remove EIGRP and configure again.

- CSCue07502

Symptom: A crash is observed after completing ISSU. The F0/F1 are getting stuck in init state.

Conditions: This issue occurs after completing ISSU.

Workaround: Reload the router.

- CSCue16617

Symptom: The QoS classification does not work in core interfaces.

Conditions: This issue occurs when the output policy applied to interface has bridge domain interface (BDI) as the core interface.

Workaround: Enable **mpls ldp explicit null** command.

- CSCue19836

Symptom: Controller flaps are observed on the CE routers with MR-APS configured on the PE routers with CEM circuit configuration.

Conditions: This issue occurs when the controllers on CE routers flap. This issue occurs when MR-APS is configured on PEs having CEM circuit for corresponding controllers.

Workaround: There is no workaround.

- CSCue35103

Symptom: CPU utilization is high after executing the show mac-address-table command.

Conditions: This issue occurs after scaled MAC entries are learned over the BD.

Workaround: Execute the command with reduced term length.

- CSCue40248

Symptom: Traffic does not flow through newly created MLP interfaces after a switchover is performed.

Conditions: This issue occurs after you have a newly created MLP interface terminated under a VRF and a switchover is performed.

Workaround: There is no workaround.

- CSCue43036

Symptom: %IDBINDEX_SYNC-4-RESERVE traceback seen on OC-12 card type.

Conditions: This issue occurs after the card type is set to OC-12 and the router is reloaded. This issue is seen on a HA system with POS configuration.

Workaround: There is no workaround.

- CSCue51682

Symptom: The REP protocol flaps, as indicated by the following error messages:

```
*Feb  8 06:51:38.857: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
non-operational due to neighbor not responding
*Feb  8 06:51:39.096: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
operational
```

Conditions: This issue occurs with REP fast LSL (with lsl-ageout 200msec) is configured and when a burst of new MAC address (usually > 4k) is getting learnt into the system.

Workaround: Remove fast LSL from the REP configuration

- CSCue54997

Symptom: Two input clock sources are accepted from same OC-3 IM but the system can support only one input clock source per OC-3 IM.

Conditions: This issue occurs when two input clock sources are getting accepted from same OC-3 IM.

Workaround: There is no workaround. Do not configure the second input clock source from same OC-3 IM or remove both OC-3 IM sources and exit the configuration and configure the desired OC-3 IM controller alone.

- CSCue75372

Symptom: TIME-HOG messages are seen during an IM OIR.

Condition: This issue occurs when default and IP template is used.

Workaround: There is no workaround.

- CSCue96886

Symptoms: Complete MAC Address space is not available on the RSP.

Conditions: This issue occurs after removing the service instance with the MAC Addresses learnt on the BD.

Workaround: Reload the Router.

- CSCuf15768

- Symptom:** Multicast traffic is not bridged with REP.
- Conditions:** This issue occurs when multicast traffic flows on the REP configured interfaces.
- Workaround:** Unconfigure and configure REP on the interfaces.
- CSCuf61024

Symptom: TDM and OC-3 IM continuously crashes enters inserted state after ISSU is performed.

Conditions: This issue occurs after ISSU is performed.

Workaround: There is no workaround.
 - CSCuf74113

Symptom: Interface mode cannot be entered for serial interfaces. Error messages are displayed.

Conditions: This issue occurs after creation of serial interfaces.

Workaround: There is no workaround.
 - CSCuf80482

Symptom: Configuration synchronization fails from active to standby IOMD.

Conditions: This issue occurs on IM OIR.

Workaround: Perform a soft reset of the IM or the interface flap.
 - CSCuf86247

Symptom: SNMP MIB variables related to BDI counters do not function properly.

Conditions: This issue occurs when you use SNMP MIB variables related to BDI interface counters.

Workaround: There is no workaround.
 - CSCuf89725

Symptom: After IM OIR the remote MEP shows BLK state on CFM offload.

Conditions: This issue occurs when CFM MEP is configured an IM OIR is performed.

Workaround: There is no workaround.
 - CSCug05491

Symptom: The router drops traffic on VPLS circuits.

Conditions: This issue occurs when the following is performed:

 - Configure REP with or without VLAN load balancing
 - Configure VPLS VFI on the VLANs
 - Issue an stateful switchover (SSO).

Workaround: There is no workaround.
 - CSCug05647

Symptom: Interface counters do not get updated with IP traffic.

Conditions: This issue occurs when performing a back-to-back ping on the connected interfaces.

Workaround: Perform a router reload.
 - CSCug39899

Symptom: Traffic stops flowing through QinQ BDI interface after ARP times out and ARP is removed by shutting the BDI.

Conditions: This issue occurs when static routing is configured, and no routing protocol is configured on the interface.

Workaround: Manually resolve the ARP by pinging the BDI interface.

- CSCug52920

Symptom: EFP stats does not work after applying the QoS policy on the EFP.

Conditions: This issue occurs when service policy is applied on the EFP.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.8(2)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.8(2)S.

- CSCub80685

Symptom: Ping failure observed and BFD or OSPF flaps on BDI shut.

Conditions: This issue occurs after shutting down the BDI interface which is receiving IPv4 or IPv6 traffic. Similar conditions occur on no EFP or BDI configured or no IP address is configured.

Workaround: Stop routing traffic into shut BDI port.

- CSCub89304

Symptom: Remote meps not learnt for CFM UP MEPS on EVC BD.

Condition: This issue occurs when IP MEPS are configured on EVC BD and Core side has port-channel with Trunk EFP configured.

Workaround: There is no workaround.

- CSCub89531

Symptom: Multicast statistics in the MFIB output display NA/NA. This causes multicast traffic to drop every 3 minutes once the 3 minute timer expires.

Conditions: This issue occurs after an stateful switchover (SSO) is performed.

Workaround: Issue another SSO or reload the router.

- CSCuc41871

Symptoms: ATM interfaces stay down during normal operations.

Conditions: This issue occurs under the following conditions:

1. Post router reload is performed
2. Peer interface cable is pulled out & put back in.

Workaround: Perform an interface reset by issuing the **shutdown** command followed by a **no shutdown** command.

- CSCuc76353

Symptom: Boot flash is inaccessible in ROMMON and IOS prompt.

"dir bootflash:" CLI does't display boot flash contents.

Condition: This issue is observed randomly on bootup. This issue is mostly observed when access to the boot flash gets interrupted because of system reload or system crash. In these cases, boot flash goes to unknown state and is not accessible either from the ROMMON or IOS.

Workaround: Perform an OIR or power cycle of the RSP to recover the boot flash errors.

- CSCud13242
Symptom: The Cisco ASR 903 router does not display an alarm when nV satellite authentication fails.
Conditions: This issue occurs when the ASR 9000 and ASR 903 are in an nV satellite configuration and the routers are configured with a different serial-number value.
Workaround: There is no workaround.
- CSCud26812
Symptom: The router CLI does not display some SFP PIDs.
Conditions: This issue occurs when you install one of the following SFPs in the router:
 - ONS-SI-155-L2
 - ONS-SI-155-L1
 - ONS-SI-155-I1**Workaround:** There is no workaround.
- CSCud29479
Symptom: The router stops applying QoS configurations.
Conditions: Occurs under the following conditions:
 - An Ethernet interface is configured with a single service instance
 - A QoS policy is attached to the service instance
 - The QoS policy contains a single class containing a match EFP statement.
 - You reset the interface to the default configuration.**Workaround:** There is no workaround.
- CSCud30806
Symptom: The router accepts a QoS WRED configuration containing **match-all** configurations for two different **prec** values, which is not supported.
Conditions: This issue occurs when you configure a policy with a class-map containing **match-all** configurations for two different **prec** values.
Workaround: There is no workaround.
- CSCud34346
Symptom: The router crashes with multiple ECMP paths configured.
Conditions: The issue can occur when:
 - The router is configured with multiple ECMP paths.
 - MPLS IP is not enabled on one of the ECMP paths.**Workaround:** There is no workaround.
- CSCud38038
Symptom: The router records incorrect delay measurements after a reload.
Conditions: This issue occurs under the following conditions:
 - You configure Delay Measurement Message (DMM) on a port-channel interface.
 - The port-channel member links are on different interface modules (IMs).
 - You reload the router.

Workaround: You can use the following workarounds:

- Remove the **ethernet cfm global** command and re-apply it after the port-channel member links recover.
- Configure PTP clock synchronization.

- CSCud38589

Symptom: DMM session stops working.

Conditions: This issue occurs when DMM is configured on bridge domain UP MEP, with redundant links on the Core side, which are in STP Forwarding or blocked state. The issue is observed when the STP forward port is shut.

Workaround: Restart the IP SLA session or **unshut** the port and bring it forward state.

- CSCud44942

Symptom: Remote MEPS are not learnt for port MEPS.

Conditions: This issue occurs when we configure any EFP on the interface, which has port-me configurations, causing the port MEP to stop working.

Workaround: There is no workaround.

- CSCud48298

Symptom: The Cisco ASR 903 dataplane fails on bootup of the CEM PW after a switchover is performed.

Conditions: This issue occurs after a switchover is performed.

Workaround: There is no workaround.

CSCud50944

Symptom: The router drops traffic on an MLPPP bundle.

Conditions: This issue occurs following a reload while the router is passing traffic close to the line rate. The issue occurs less frequently with lower traffic rates.

Workaround: Issue a shutdown/no shutdown on multilink interface.

- CSCud64034

Symptom: The T1 interfaces do not come up after a SSO.

Conditions: This issue occurs under the following conditions:

- Configure T1 interfaces and verify that they come up
- Perform an SSO
- Verify the interfaces and check for traffic flowing through the interfaces
- Unconfigure T1 interfaces.
- Reload the standby RSP
- Configure T1 interfaces. The T1 interfaces do not come up.

Workaround: Perform an IM OIR on the router.

- CSCud76770

Symptom: Convergence time for FRR link or node protection is more than 2 seconds.

Conditions: This issue occurs when NNHOP backup tunnels are configured in a ring topology.

Workaround: There is no workaround.

- CSCud76957

Symptom: Traffic gets dropped during egress when service instance is configured.

Conditions: This issue occurs when service instance is configured.

Workaround: Unconfigure the service instance and reconfigure it again.
- CSCud90890

Symptom: Routing over Trunk EFP over port-channel does not work on member ports associated with ASIC #1.

Conditions: This issue occurs when a Trunk EFP on port-channel has members on ASIC#1, the routing traffic does not egress on those ports.

Workaround: There is no workaround.
- CSCud90955

Symptom: The following console messages are seen whenever BFD session is created or modified.

```
Jan 3 06:34:52.481: %HANDOFF_FUD-6-QDR_MULTI_BIT_ERROR_START: SIP1: nile_mgr:
Handoff FPGA could encounter MBE, check at start of create update BFD session
Jan 3 06:34:52.481: %HANDOFF_FUD-6-QDR_MULTI_BIT_ERROR_END: SIP1: nile_mgr: Handoff
FPGA could encounter MBE, check at end of create update BFD session
Jan 3 06:34:53.167: %HANDOFF_FUD-6-QDR_MULTI_BIT_ERROR_START: SIP0: nile_mgr:
Handoff FPGA could encounter MBE, check at start of create update BFD session
Jan 3 06:34:53.167: %HANDOFF_FUD-6-QDR_MULTI_BIT_ERROR_END: SIP0: nile_mgr: Handoff
FPGA could encounter MBE, check at end of create update BFD session
```

Conditions: This issue occurs when BFD sessions are created or modified.

Workaround: There is no workaround. This issue has no service impact.
- CSCud96604

Symptom: On system reset or reload, all traffic on certain Ethernet Flow Point (EFP)s do not egress.

Conditions: This issue occurs when traffic completely stops on certain EFPs.

Workaround: Delete and reconfigure EFPs.
- CSCue00049

Symptom: Classification does not work properly with non-matching traffic when IP ACL is used.

Conditions: This issue occurs only for class-based ACL match. The ACL class are classified properly and other classes based on DSCP or class-default do not work

Workaround: There is no workaround.
- CSCue10037

Symptom: Crash observed on the router.

Conditions: This issue after when CFM is offloaded and MEPs with 3.3ms were scaled on port-channel with Trunk EFP. This issue occurs after **shutdown** command followed by a **no shutdown** command is executed on the member links of port-channel.

Workaround: Configure around 50-100 CFM sessions.
- CSCue11444

Symptom: Split horizon configurations does not clear with Layer2 multicast packets.

Conditions: This issue occurs when Ethernet Flow Point (EFP)s with split-horizon are configured.

Workaround: Perform a shutdown followed by no shutdown. Configure EFP first before moving into split-horizon group.

- CSCue16828
Symptom: Back-to-Back ping failure observed on a PC with Core side Trunk EFP with BDI configured.
Conditions: This issue occurs when a PC with Core side Trunk EFP with BDI configuration is changed.
Workaround: Do not change the PC in Core side.
- CSCue18015
Symptom: S,G does not get created, the forwarding is based on (*,G).
Conditions: This issue occurs with Interior Gateway Protocol (IGP) change leading to Reverse Path Forwarding (RPF) change of the (*,G).
Workaround: Clear the (*,G) and recreate it.
- CSCue19898
Symptom: (*,G) based forwarding is observed with IIF registry change. The Interior Gateway Protocol (IGP) patch change leads to this issue.
Conditions: This issue occurs when IGP is changed causing a Reverse Path Forwarding (RFP) change notification.
Workaround: Timeout the (*,G) entry and recreate it again either by issuing **clear ip mroute** command or stopping the joins.
- CSCue20022
Symptom: Software forwarding of core encapsulation entries causes interface to flap.
Conditions: This issue occurs when interface has Protocol Independent Multicast (PIM) enabled on the BDI interface.
Workaround: Perform a soft interface module OIR. Clear the multicast routes for that VRF.
- CSCue25146
Symptom: The standby OC-3 IM gets reloaded after the controller flaps in active console.
Conditions: This issue occurs after configuring ATM and Controller and a **shutdown** command followed by a **no shutdown** command is issued when the controller in active.
Workaround: There is no workaround.
- CSCue25267
Symptom: The standby RSP reloads on an OC-3 interface module OIR on the active RSP. A crash was observed but core file generated is incomplete.
Conditions: This issue occurs when the active RSP is booted up first followed by the standby RSP. This issue occurs when APS configurations with serial links are present on the router and IM OIR is performed.
Workaround: There is no workaround.
- CSCue25567
Symptom: Quack authentication failure message seen on console.
Conditions: This issue is seen randomly.
Workaround: Reload the router.

- CSCue27652
Symptom: ATM interfaces get deleted after SSO is performed.
Conditions: This issue occurs after an the ATM interfaces are deleted on the standby RSP after an IM OIR is performed.
Workaround: There is no workaround.
- CSCue30481
Symptom: The router does not lock to the syncE clock source after reload. It will be in Q1-failed state.
Condition: Reload the router with saved syncE configuration.
Workaround: Unconfigure and configure the clock source.
- CSCue32753
Symptom: The OC-3 interface modules are lost after a In Service Software Upgrade (ISSU) is performed on the Cisco ASR 903 router and configuration mismatch errors are displayed on router console. The standby RSP reaches standby-hot state causing continuous IOMD crash messages at regular intervals.
Conditions: This issue occurs when ISSU is performed.
Workaround: There is no workaround.
- CSCue34597
Symptom: CHAP authentication process timed out. The PPP interface and multilink bundle does not come up.
Conditions: This issue occurs when PPP or MLPPP is configured and PPP authentication is enabled.
Workaround: Remove CHAP authentication from interface.
- CSCue40020
Symptom: Interior Gateway Protocol (IGP) flap or MPLS-enabled interface flap with 600 Layer2 VPN configured and 6000 Layer3 VPN configured can cause a crash.
Conditions: This issue occurs after the IGP flaps continuously.
Workaround: Configure IGP routes less than 100. Scale of Layer2 or Layer3 VPN configuration should be less than 100 to avoid a crash.
- CSCue42315
Symptom: CPU hog messages and IOMD crash observed on the Cisco ASR 903 router.
Conditions: This issue occurs with OC-3 interface module after executing the shutdown command followed by a no shutdown command of the multilink bundle when traffic is sent with a packet size greater then 1500 byte.
Workaround: There is no workaround.
- CSCue43250
Symptom: IMA configurations cannot be parsed correctly after a router reload.
Conditions: This issue occurs after the A903-IM40S is inserted in bay 4 or bay 5 of the Cisco ASR903 router and when the IMA and ATM interfaces are adjacent.
Workaround: Insert the IM in bay 0 or bay 3 for the IMA and ATM parsing to work or reconfigure the ATM and IMA interfaces.

- CSCue45306
Symptoms: CEM circuits configured over TDM IM go down after SSO is performed.
Conditions: This issue occurs after a SSO is performed.
Workaround: Perform a router reload.
- CSCue47317
Symptom: ISSU may get impacted due to synchronization damage.
Conditions: This issue occurs after modifying the TDL structures.
Workaround: There is no workaround.
- CSCue50128
Symptom: FMFP download failure occurs on reaching 1980 odd number even though 2000 ternary content addressable memory (TCAM) space is allocated for ACLs in the IP template.
Conditions: This issue occurs in normal conditions when the scale reaches 1980.
Workaround: There is no workaround.
- CSCue52298
Symptom: TI/EI interfaces on interface module are lost as IOMD crashes after a switchover.
Conditions: This issue occurs after IOMD crashes when a switchover was performed.
Workaround: There is no workaround.
- CSCue52774
Symptom: Sonet controller as input clock source does not get selected on A900-IMA4OS interface module on a Cisco ASR 903 router.
Condition: This issue occurs when the port above 0 is used for the clock source.
Workaround: Use port 0 for clock source or insert the SFP in the odd port (protect port) adjacent to the actual port using an optical splitter. The cable is fed to the odd port to recover the proper clocking for the port.
- CSCue52968
Symptom: Ping failure occurs and traffic stops through Multilink bundle when Challenge Handshake Authentication Protocol (CHAP) authentication is enabled.
Conditions: This issue is seen when Policy Feature Card (PFC) and Control Field Compression (ACFC) is configured on the Cisco ASR 903 router.
Workaround: There is no workaround.
- CSCue57670
Symptom: The active RSP synchronization LED displays the state incorrectly.
Condition: This issue occurs after a Stateful Switchover (SSO) is performed without any network clock configuration.
Workaround: There is no workaround. This issue is a cosmetic issue.
- CSCue59544
Symptom: The A900-IMA16D generates a storm on closing the backup tunnel.
Condition: This issue occur after closing the tunnel.
Workaround: There is no workaround.

- CSCue66137
Symptom: The IOMD crashes with CPU hog messages.
Conditions: This issue occurs with OC-3 interface module and traffic is sent over a multilink bundle with packet size greater than 600 byte.
Workaround: There is no workaround.
- CSCue77612
Symptom: MAC address synchronization on 1 Gigabit Ethernet port on standby RSP causes traffic to be forwarded to incorrect port after a switchover.
Conditions: This issue occurs after a switchover.
Workaround: Clear MAC address after a switchover is performed.
- CSCue86696
Symptom: Interface flaps are observed after longevity run is performed.
Conditions: This issue occurs after prolonged tests are performed with SPF interface modules.
Workaround: There is no workaround.
- CSCue87542
Symptom: Deleting bridge domain interfaces (BDIs) with routing traffic causes a flood to CPU resulting in control plane traffic loss.
Conditions: This issue occurs after a ping failure and the Bidirectional Forwarding Detection (BFD) protocol or OSPF protocol flaps on deleting the BDI while IPv4 traffic is flowing.
Workaround: Delete the Trunk EFP interface and then the BDI.
- CSCue89503
Symptom: The power supply status displays critical after removing and inserting the power supply on the Cisco ASR903 router.
Conditions: This issue occurs after multiple OIR of the power supply is performed.
Workaround: There is no workaround. This issue is cosmetic.
- CSCuf05039
Symptom: I2C-WRITE and MDIO_READ error messages are displayed on the Cisco ASR903 router.
Conditions: This issue occurs after an interface module hard or soft OIR is performed.
Workaround: There is no workaround.
- CSCuf61365
Symptom: Virtual circuit counters do not increment after interface module Online Insertion and Removal (OIR) followed by a SSO is performed.
Conditions: This issue occurs after an OIR followed by a SSO is performed.
Workaround: Perform a SSO without a interface module OIR.
- CSCuf65040
Symptom: 1 Gigabit Ethernet or 10 Gigabit Ethernet interface module enters out of service state.
Conditions: This issue occurs when a hard Online Insertion and Removal (OIR) is performed on the interface module.
Workaround: Perform another hard OIR or a Stateful Switchover (SSO) followed by a soft OIR.

- CSCuf79504

Symptom: ATM Virtual Channel Connections (VCCs) creation on standby RSP fails.

Conditions: This issue occurs after issuing **shutdown** command followed by **no shutdown** command on the multiple controller on active RSP.

Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.8(1)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.8(1)S.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtz65778

Symptom: The control plane goes down with VPNv6 traffic.

Conditions: Occurs with 64-byte VPNv6 traffic. The issue only occurs for small, tunnelled packets.

Workaround: There is no workaround.

- CSCua57325

Symptom: The router displays an OIR SPA error.

Conditions: Occurs under the following conditions:

- The router is running offloaded CFM sessions over an xconnect (pseudowire) interface.
- The router is using a redundant hardware (dual RSP) configuration.
- The remote router is using a non-redundant (single RSP) hardware configuration.
- You reload the router.

Workaround: There is no workaround.

- CSCua77688

Symptom: The router experiences remote CFM MEP flapping.

Conditions: Occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.

Workaround: Reduce the rate of traffic.

- CSCub18160

Symptom: The router drops traffic on a link twice and displays a remote fault error message.

Conditions: Occurs when you issue an interface module reset (OIR) while the 10.000M XFP (DWDM Edge performance) or XFP10GER-192IR-L XFPs are plugged into the ten Gigabit Ethernet interface module and active.

Reloading the router also takes significantly longer when using these XFPs.

- Workaround:** There is no workaround.
- CSCub41772

Symptom: Router console is flooded with CPUHOG and EVENTLIB messages.

Conditions: The issue occurs rarely when you issue multiple interface module reset (OIRs), RSP switchovers (SSO), or reloads while using a configuration with a high number of T1 serial links on the OC-3 interface module.

Workaround: There is no workaround; however, the messages do not affect router functionality.
 - CSCuc66393

Symptom: The router loses OC-3 interface configurations after an ISSU upgrade.

Conditions: Occurs on OC-3 serial and POS interfaces after an ISSU software upgrade.

Workaround: There is no workaround.
 - CSCud01908

Symptom: The **show platform software object-manager fp active statistics** command shows pending objects on the Forwarding Manager (FMAN) on the forwarding processor (FP), indicating a failure to download configurations from the Route Switch Processor (RSP) to the data plane (DP).

Conditions: Occurs when you apply a QoS shaping configuration at a high scale.

Workaround: There is no workaround.
 - CSCud06772

Symptom: IPv6 neighbor discovery does not function properly after stateful switchover (SSO); the router loses traffic and eventually recovers.

Conditions: Occurs with IPv6 traffic after stateful switchover (SSO).

Workaround: Configure software BFD sessions.
 - CSCud07085

Symptom: The serial interface on the OC-3 interface module remains in a down state.

Conditions: Occurs when you migrate from T1 mode to E1 mode using the OC-3 interface module.

Workaround: Issue an interface module reset (OIR) on the OC-3 interface module.
 - CSCud23647

Symptom: BDI adjacency fails on the standby RSP.

Conditions: The issue can occur during an interface module (IM) reset or router reload.

Workaround: There is no workaround.
 - CSCud27333

Symptom: The router crashes continuously.

Conditions: Occurs when you issue an interface module reset (OIR) while the standby RSP is booting.

Workaround: Do not issue an interface module reset (OIR) while the standby RSP is booting.
 - CSCud29479

Symptom: The router stops applying QoS configurations.

Conditions: Occurs under the following conditions:

 - An Ethernet interface is configured with a single service instance

- A QoS policy is attached to the service instance
- The QoS policy contains a single class containing a **match efp** statement.
- You reset the interface to the default configuration.

Workaround: There is no workaround.

- CSCud33906

Symptom: Equal Cost Multipath (ECMP) loopback does not function properly.

Conditions: Occurs when a port-channel link dynamically assigned as an ECMP path.

Workaround: There is no workaround.

- CSCud56262

Symptom: The router stops passing traffic on virtual circuits.

Conditions: Occurs an MPLS-TE/FRR configuration with L2VPN after you issue a stateful switchover (SSO).

Workaround: Reload the router.

- CSCud64436

Symptom: The router does not send the full line rate on POS interfaces.

Conditions: Occurs when you send traffic over a POS interface on the OC-3 interface module with a QoS configuration.

Workaround: There is no workaround.

- CSCud89451

Symptom: The router crashes with an error message showing `nmpls_label_populate_flow_data`.

Conditions: Occurs when you reset a core interface while the ASR 903 is acting as a PE router and running a configuration with L2VPN and L3VPN.

Workaround: There is no workaround.

- CSCud95359

Symptom: The `show policy map` command displays an incorrect number of total dropped packets (total drops).

Conditions: Occurs when you issue the `show policy-map` command to display dropped packets on an interface.

Workaround: There is no workaround.

- CSCue01419

Symptom: The router loses EIGRP neighborship.

Conditions: Occurs on OC-3 and OC-12 interface configured on port 0.

Workaround: Issue a **shutdown/no shutdown** on interfaces configured on port 0. You can also remove and reconfigure EIGRP.

- CSCue43205

Symptom: The router drops traffic when you set an interface to the default configuration.

Conditions: Occurs when you set an interface with QoS configurations to the default configuration. The issue occurs most often with the Ten Gigabit Ethernet interface using a full global configuration.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.8(1)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.8(1)S.

- CSCty30951

Symptom: The router displays the following console error message:

```
%QOSMGR-3-OUT_OF_TCAM_RESOURCES: SIP0: nile_mgr: Out of tcam resources to execute command
```

Conditions: Occurs when you remove a QoS configuration by setting the interface to the default configuration.

Workaround: There is no workaround.

- CSCty70119

Symptoms: Port shaper rate changes do not take effect.

Conditions: Occurs when QoS policies attached to EVCs on an interface do not include a shaper configuration; the issue does not occur on EFP policies that include a shaper in a class.

Workaround: Include a shaper in one class of the EFP policy.

- CSCtz03919

Symptoms: The router fails to store trace logs.

Conditions: Occurs when the /bootflash directory is full.

Workaround: Clean up the /bootflash and then reboot the router.

- CSCtz20839

Symptoms: IMA functionality does not work properly.

Conditions: Occurs after an RSP switchover when the router is running an IMA configuration.

Workaround: Reload the interface module with the IMA configuration.

- CSCua62029

Symptom: The router crashes.

Conditions: Occurs when you configure a class-based QoS policy with the following characteristics:

- The policy is attached to the main interface.
- The policy classifies on multiple VLANs.
- The classification statements specify a priority.
- The classification statements are within a child QoS policy.

Workaround: There is no workaround.

- CSCua73104

Symptoms: The router does not increment QoS port shaper policy counters displayed by the **show policy interface** command.

Conditions: Occurs when you configure

- A class-default policy on a physical interface
- A class-based policy on an EVC interface

Workaround: There is no workaround; however, the router applies the QoS policy normally.

- CSCua95873
Symptoms: The router continues passing traffic on the OC-3 interface after you shut down the controller.
Conditions: Occurs when you shut down the OC-3 controller; the router momentarily continues to increment interface counters.
Workaround: There is no workaround.
- CSCub73405
Symptom: Cisco ASR903 router can experience latency for process-switched traffic and display high CPU utilization at nile_mgr.
Conditions: Occurs on an ASR 903 with redundant RSPs after you reload the standby RSP.
Workaround: Reboot the router.
- CSCub78861
Symptom: Following a reload, the router handles CFM only on 128 VLANs or bridge-domains.
Conditions: Occurs when the router configuration contains CFM and more than 128 VLANs or bridge-domains.
Workaround: There is no workaround.
- CSCub79869
Symptom: BGP PIC edge convergence time is high.
Conditions: Occurs in a 3-label stack setup using LDP, BGP, and VPN labels.
Workaround: There is no workaround for a stack using 3 labels. However, the issue does not occur when you use 2 labels.
- CSCub98691
Symptom: The router displays an I2C write fail error message.
Conditions: The issue can occur when the router is idle or when the router is loaded and passing traffic.
Workaround: There is no workaround. However, the issue does not have any functional impact.
- CSCuc01154
Symptom: The router does not report B1, B2, and B3 alarms at normal thresholds.
Conditions: Occurs on the OC-3 interface module when the router sends errored frames.
Workaround: There is no workaround.
- CSCuc41763
Symptom: The router displays a RUNHOG traceback error message.
Conditions: Occurs when you reload the router or an interface module.
Workaround: There is no workaround.
- CSCuc51051
Symptom: Remote LFA FRR convergence takes more than 50 milliseconds.
Conditions: Occurs after you reload the router.
Workaround: Reset the interface on the primary path.

- CSCuc58371

Symptom: Some links do not become active on the OC-3 interface module.

Conditions: Occurs on the OC-3 interface module (IM) configured at a high scale after you perform a multiple soft OIRs on the IM. The issue occurs frequently with SONET framing.

Workaround: You can use the following workarounds:

 - Apply a **shutdown/no shutdown** to the OC-3 controller.
 - Re-apply the PDH configuration.
 - Add and remove a loopback configuration on the PDH.

Add and remove a loopback configuration on the OC-3 controller.
- CSCuc64654

Symptom: The router is unable to ping the remote customer edge (CE) router.

Conditions: Occurs when the router is acting as a provider edge (PE) device and is connected to the remote PE using dual loopback interfaces for peering with iBGP sessions.

Workaround: Use a single loopback interface. Use the same loopback interface for IPv4 and VPNv4 address families.
- CSCuc66393

Symptom: The router loses OC-3 interface configurations after an ISSU upgrade.

Conditions: Occurs on OC-3 serial and POS interfaces after an ISSU software upgrade.

Workaround: There is no workaround.
- CSCuc68462

Symptom: The router drops PTP traffic.

Conditions: The issue occurs occasionally when you configure PTP slave clock to receive VLAN-tagged traffic.

Workaround: There is no workaround.
- CSCuc71723

Symptom: The router erroneously accepts a service-policy configuration on a CEM interface and displays it within the running configuration.

Conditions: Occurs when you configure a service-policy on a CEM interface.

Workaround: There is no workaround.
- CSCuc85721

Symptom: The router crashes.

Conditions: Occurs under the following conditions:

 - MR-APS is configured on serial interfaces on the OC-3 interface module
 - The router is configured with a high number of serial interfaces
 - You reset an interface module or reload the router.

Workaround: There is no workaround.
- CSCuc90008

Symptom: The OC-3 controller stops passing traffic.

Conditions: Occurs after you reset the facing interface on the CE device.

Workaround: Reset the interface module.

- CSCuc91007

Symptom: A slave clock displays a high 1PPS offset value from the master clock.

Conditions: Occurs after an interface module reset or stateful switchover (SSO) on the master device.

Workaround: There is no workaround.

- CSCuc92953

Symptom: The RSP crashes.

Conditions: Occurs under the following conditions:

- You configure Protocol-Independent Multicast-Sparse Mode (PIM-SM) with a static rendezvous point (RP).
- You create an EVC port channel on the access side with one member link
- You create bridge domain interfaces (BDIs) with 1:1 mapping between EVCs and bridge-domains.
- You use the BDIs to send IGMP v2 static join messages to a single multicast group
- On the remote device, you create 150 EFPs and map them to the BDIs.
- You initiate multicast traffic.
- You set the EFPs to the default configuration and add them to the existing port-channel

The router crashes.

Workaround: There is no workaround.

- CSCuc95590

Symptom: The router does not automatically upgrade the FPGA software.

Conditions: Occurs when you load a new image while running an older FPGA version.

Workaround: There is no workaround; however the issue has no functional impact.

- CSCuc95716

Symptom: FPGA software for the OC-3 interface module is not bundled with the XE 3.8 image.

Conditions: Occurs when upgrading FPGA on the OC-3 interface module.

Workaround: Manually upgrade the OC-3 FPGA.

- CSCuc98185

Symptom: One out of 48 EFPs in a BDI does not receive traffic when running L3 multicast. The issue does not happen consistently.

Conditions: Occurs under the following conditions:

- You configure Protocol-Independent Multicast-Sparse Mode (PIM-SM) with a static rendezvous point (RP).
- You configure a bridge domain interface (BDI) on the PE2 access side
- You use the BDI to send IGMP v2 static join messages to a single multicast group
- You disable IGMP snooping globally.
- You configure 24 EFPs and map them to a single bridge-domain.
- You initiate multicast traffic.

- With multicast traffic enabled, you configure 24 EFPs and map them to the existing bridge-domain.

One of the 48 EFPs does not receive traffic.

Workaround: Reload the router.

- CSCud01641

Symptom: The standby RSP resets when you issue the write memory command on the active RSP.

Conditions: Occurs under the following conditions:

- The BITS interface is configured as an input clock source.
- Quality level-based clock selection is enabled.

Workaround: Disable QL-enabled mode for network-clock synchronization.

- CSCud01644

Symptom: The active forwarding processor (FP) is on the standby route switch processor (RSP).

Conditions: Occurs when you boot the two RSPs in quick succession and the FP on the standby RSP becomes active before the FP on the active RSP.

Workaround: Reload the router.

- CSCud06744

Symptom: The router does not download MPLS global prefixes.

Conditions: Occurs under the following conditions:

- You configure Loop Free Alternate Fast Reroute (LFA FRR) at a high scale.
- The primary or backup paths flap multiple times.

Workaround: There is no workaround.

- CSCud07642

Symptom: The ASR 903 is unable to pass traffic to the ASR 9000.

Conditions: Occurs with a clear-channel ATM over MPLS configuration using AAL0 encapsulation.

Workaround: Enable MPLS control-word on the ASR 9000.

- CSCud07854

Symptom: FPGA software upgrade fails.

Conditions: Occurs when you upgrade the FPGA software using an IOS image bundled with a new FPGA version.

Workaround: Manually upgrade the FPGA software.

- CSCud08913

Symptom: The router crashes.

Conditions: The issue occurs in rare instances when you perform an interface module (IM) reset (OIR) on the OC-3 interface module.

Workaround: There is no workaround.

- CSCud09246

Symptom: The router crashes.

Conditions: Occurs under the following conditions:

- You issue the **clear ip route *** command
- You issue an interface module reset (IM OIR)

Workaround: There is no workaround.

- CSCud09315

Symptom: The show ptp clock running domain 0 and show platform ptp all commands do not display a configured slave clock.

Conditions: Occurs when you issue a **shutdown/no shutdown** on the link between a boundary clock and a master clock during while the boundary clock is in phase alignment.

Workaround: Remove and restore the PTP configuration on the boundary clock.

- CSCud12587

Symptom: When handling IS-IS packets, the router punts the traffic to the Route Switch Processor (RSP) and applies policing to limit the traffic to 1 Mbps.

Conditions: Occurs when you enable IS-IS over an Ethernet over MPLS (EoMPLS) connection.

Workaround: Use IS-IS over another connection type or limit the IS-IS traffic to less than 1 Mbps.

- CSCud13535

Symptom: The router drops imposition traffic sent to a neighbor device over a VPLS pseudowire.

Conditions: Occurs when the neighbor device configuration includes the **no split horizon group** command.

Workaround: Remove the **no split horizon group** command from the VPLS neighbor device.

- CSCud15740

Symptom: The Gigabit Ethernet interface module crashes.

Conditions: Occurs when the router receives a flood of Wintegra interrupt packets.

Workaround: There is no workaround.

- CSCud15785

Symptom: The router experiences flapping on REP connections.

Conditions: Occurs under the following conditions:

- MAC limiting is enabled and a MAC address is at the maximum value
- REP is configured with a 200 millisecond LSL ageout timer

Workaround: Increase the REP timer to above 500 milliseconds or disable the MAC limiting feature.

- CSCud15841

Symptom: The clear ip mroute * command can cause resource leakage.

Conditions: Occurs when you issue the clear ip mroute * command while IP multicast is enabled.

Workaround: Reload the router.

- CSCud17457

Symptom: The router drops IP multicast traffic.

Conditions: Occurs when you perform the following actions:

- Configure EFPs as members of a port channel containing a single interface.
- Remove the configuration for the EFPs

- Remove the interface from the port channel
- Add the EFPs back onto the interface

Workaround: Reload the router or issue a stateful switchover (SSO).

- CSCud19563

Symptom: The T1/E1 interface module on the standby RSP crashes repeatedly.

Conditions: Occurs when the standby RSP is booting and there is a clock configured on the T1/E1 controller.

Workaround: Remove the clock configuration prior to booting the standby RSP and restore the configuration afterwards.

- CSCud22601

Symptom: MPLS-TP tunnels remain down after the standby RSP boots.

Conditions: Occurs when you boot the standby RSP after applying an MPLS-TP configuration and performing an SSO. The issue occurs rarely.

Workaround: Issue a shutdown/no shutdown on the MPLS-TP tunnel. A nonintrusive workaround is to cause a flap on the protect label switched path (LSP) by reconfiguring the path or physically shutting down and restoring the interface.

- CSCud23698

Symptom: The router stops applying classification and marking for a class.

Conditions: Occurs when you remove a priority level while using dual priority for the class-map.

Workaround: Remove and reattach the policy-map on the interface.

- CSCud24704

Symptom: The router crashes.

Conditions: Occurs when you perform an interface module OIR (reset) on the gigabit Ethernet interface module while the standby RSP is booting.

Workaround: Perform the IM OIR after the standby RSP boots.

- CSCud25813

Symptom: The router drops IP Multicast traffic.

Conditions: Occurs under the following conditions:

- You initiate multicast traffic to a single L3M group.
- You configure 50 EFPs with corresponding bridge domain interfaces (BDIs) and initiate IGMPv2 join traffic to a single multicast group.
- You add 25 EFPs with 25 bridge-domain interfaces (BDIs) at a 1:1 ratio.
- You remove 10 EFPs from the group of 50 and add the same EFPs to the group of 25.
- The newly added EFPs do not receive any traffic.

Workaround: Reload the router or issue a stateful switchover (SSO).

- CSCud26154

Symptom: The router displays incorrect ENV readings.

Conditions: Occurs when you switch off one power supply unit in a dual power supply configuration.

Workaround: There is no workaround. However, the issue does not have any functionality impact on the system.

- CSCud26240

Symptom: The router displays Nile mgrs leak error messages.

Conditions: Occurs when you configure L3VPN and L2VPN services at a high scale.

Workaround: There is no workaround.

- CSCud26382

Symptom: The router drops traffic on an EFP interface after you perform a stateful switchover (SSO).

Conditions: Occurs under the following conditions:

- You boot the standby RSP
- The router configuration contains an EFP interface on a Gigabit Ethernet port and a bridge domain interface in a down state.
- After the router reaches an SSO state, you issue a no shutdown command on the peer router to bring the EFP interface up.
- You perform an stateful switchover (SSO) on the router.

Workaround: Issue a shutdown/no shutdown on the gigabit Ethernet port.

- CSCud28553

Symptom: The router stops passing Switch Port Analyzer (SPAN) traffic.

Conditions: Occurs after you apply a **shutdown/no shutdown** on the SPAN source port with Ethernet flow point (EFP) and bridge domain interface (BDI) configurations.

Workaround: Enable and disable the SPAN session

- CSCud28685

Symptom: Ping fails between the CE1 and CE2 devices when the ASR 903 is acting as the PE device.

Conditions: Occurs when the SONET controller or ATM interface experiences an interface flap.

Workaround: Perform a soft OIR on the interface module.

- CSCud28787

Symptom: The 10 gigabit Ethernet interface module (IM- A900-IMA1X) flaps.

Conditions: Occurs when the IM passes high traffic volumes for an extended period of time.

Workaround: There is no workaround.

- CSCud31852

Symptom: The router displays traffic polarization with L3VPN traffic.

Conditions: Occurs under the following conditions:

- The P router has multiple ECMP paths
- The ECMP paths are port-channels

Traffic is distributed between ECMP paths, but polarization occurs on the port-channel member links.

Workaround: There is no workaround.

- CSCud33298
Symptom: The router crashes.
Conditions: Occurs when the peer device shuts down.
Workaround: There is no workaround.
- CSCud33822
Symptom: The router drops VPN traffic on an MPLS-TE tunnel using an explicit-null label advertisement after tunnel recovery.
Conditions: The issue occurs under specific network conditions where TE is LDP-enabled and runs over a 10G link with dampening enabled. VPN prefixes are advertised from route-reflector as well as from the VPN PE over the TE tunnel. The TE tunnel is delayed and this causes label forwarding to switch from the 2 stack labeled path to the 3 stack labeled path with same VPN label coming from 2 sources.
Workaround: Issue a **shutdown/no shutdown** on the tunnel or protect the tunnel from going down using fast reroute (FRR).
- CSCud36431
Symptom: Backup path is not programmed properly for global prefixes and can cause the cut-over to have a higher convergence time.
Conditions: Occurs when the router is running remote LFA FRR in a ring with 7 or more routers and one of the router in the ring reloads.
Workaround: Issue a **shutdown/no shutdown** on the backup or primary interface.
- CSCud38115
Symptom: OSPF connections flap and drop traffic for approximately 20 seconds
Conditions: Occurs during stateful switchover (SSO).
Workaround: There is no workaround.
- CSCud38123
Symptom: The router drops traffic and displays error messages similar to the following:
%FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP1: fman_fp_image: LENTRY
0XXXXXXXXXX (InLabel XX Table 0) download to CPP failed
Conditions: Occurs when the primary path flaps more than 15 times while the router is configured with 8000 global prefixes
Workaround: Reload the router.
- CSCud38164
Symptom: The router displays an Object download failure message on the console.
Conditions: Occurs when the number of ip routes reaches its maximum configurable limit.
Workaround: There is no workaround.
- CSCud38433
Symptom: The router is unable to establish MPLS neighborship or ping the destination loopback interface.
Conditions: Occurs when you configure two Equal Cost Multipath (ECMP) paths on a bridge domain interface (BDI) using static routes.
Workaround: The following workarounds exist:

- Use Interior Gateway Protocol (IGP) instead of static IP routes.
 - Shut down one of the ECMP paths.
- CSCud38592

Symptom: The router displays an fman_fp crash error and crashes.

Conditions: Occurs when the router is running Remote LFA with a high number of prefixes and there is an interface flap on the primary path.

Workaround: There is no workaround.
- CSCud38668

Symptom: The OC-3 interface module crashes.

Conditions: Occurs when you issue the **show platform software agent iomd 1/0 driver peek** command.

Workaround: There is no workaround.
- CSCud40930

Symptom: Some interfaces within a bridge-domain are unable to send outbound L3 multicast traffic.

Conditions: Occurs when the bridge-domain contains EFP interfaces, some of which are on a port-channel. The issue can also occur after a router reload.

Workaround: Issue a **shutdown/no shutdown** on the BDI interface.
- CSCud42315

Symptom: The OC-3 interface module crashes.

Conditions: Occurs when you apply the **forward-alarm ais** command on a T1 controller.

Workaround: There is no workaround.
- CSCud43580

Symptom: The router does not apply the **bandwidth remaining percent** command within a QoS policy in some instances.

Conditions: The issue can occur occasionally when:

 - There is a large discrepancy in **bandwidth remaining** values between QoS classes
 - The classes containing the **bandwidth remaining** statements are oversubscribed at a low rate or have a low queue-limit.

Workaround: Apply the following workaround:

 - Increase the **queue-limit** value to 120 kilobytes or above.
 - If the QoS configuration uses WRED, increase the minimum threshold value.
 - Alter the bandwidth remaining values to reduce the ratio between values.
- CSCud44640

Symptom: The router displays a traceback error when there one power supply unit slot is empty.

Conditions: Occurs during boot.

Workaround: There is no workaround.
- CSCud44768

Symptom: Multilink bundles and member links flap when passing traffic.

Conditions: Occurs under the following conditions:

- You configure more than 210 MLPPP bundles with one member link per bundle or 16 bundles with 16 member links each.
- The line is operating at a 64 or 128 byte line rate

Workaround: There is no workaround.

- CSCud49684

Symptom: The router displays an FMAN-FP memory leak error message.

Conditions: Occurs when you configure L3VPN at a high scale.

Workaround: There is no workaround.

- CSCud49980

Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: Occurs when you configure CFM MEPs on carrier edge (CE) routers and VPLS on provider edge (PE) routers.

Workaround: Create an EVC bridge-domain running CFM on the PE router and enable a virtual forwarding interface (VFI) on the bridge-domain.

- CSCud50851

Symptom: The router experiences flapping on REP connections.

Conditions: Occurs when you enable MAC limiting at a high scale and the set of MAC addresses changes continuously.

Workaround: Disable MAC limiting.

- CSCud54092

Symptom: The router displays an error message indicating a crash at `tdl_netsync_clk_src_message_create`.

Conditions: The issue can occur when the router is shutting down during a reload

Workaround: There is no workaround.

- CSCud55377

Symptom: The router crashes.

Conditions: Occurs when you configure offloaded CFM for xconnect sessions at a high scale.

Workaround: There is no workaround.

- CSCud55695

Symptom: When you apply an QoS policy with a port level class-default configuration containing a shaper value to a serial interface, the router applies the shaper value to the channel-level PIR for all serial interfaces on the IM.

Conditions: Occurs when you apply QoS policy with a port level class-default configuration containing a shaper value to a serial interface.

Workaround: Add a dummy class-default level at the top of the policy and apply the shaper as a child policy of this class.

- CSCud58793

Symptom: The FPD version is blank

Conditions: Upgrade to the new firmware rev. and a subsequent switchover. Occurs when you upgrade the router to a new firmware version and issue an RSP switchover.

Workaround: Reloading the RSP can resolve the issue.

- CSCud60410

Symptom: The router drops EFP traffic.

Conditions: Occurs when you add a new EFP to an existing bridge domain interface (BDI) while running L3 multicast.

Workaround: Issue a **shutdown/no shutdown** on the Ethernet interface and issue the **clear ip mroute** command.

- CSCud61931

Symptom: As OC-3 interface module controller does not become active using loopback local.

Conditions: Occurs with the A900-IMA4OS interface module when there is no SFP inserted in the port.

Workaround: Insert an SFP in the appropriate port.

- CSCud64347

Symptom: The router creates a data loop when using a REP VLAN load balancing configuration.

Conditions: Occurs with a REP VLAN load balancing configuration when a bridge-domain is bound to a VPLS VC.

Workaround: None; remove the VLAN load balancing configuration.

- CSCud64923

Symptom: OSPF connections flap.

Conditions: Occurs when you configure OSPF between an EVC bridge domain interface (BDI) and a trunk EFP bridge domain interface (BDI) using a port-channel trunk.

Workaround: There is no workaround.

- CSCud65779

Symptom: The router does not update the Rx value for C2, J1, and S1S0 bytes.

Conditions: Occurs when you configure overhead bytes on OC-3 connections.

Workaround: There is no workaround.

- CSCud65935

Symptom: End to end ATM ping does not work.

Conditions: Occurs when you configure a different set of VPI/VCI on either end of an ATM layer 2 circuit.

Workaround: Configure the same VPI/VCI values on both sides of the connection.

- CSCud71546

Symptom: The ten Gigabit Ethernet interface drops traffic for 7 seconds following a stateful switchover (SSO).

Conditions: Occurs when the configuration contains static routes to the destination.

Workaround: There is no workaround.

- CSCud76209

Symptom: The OC-3 interface module goes into an out of service state.

Conditions: Occurs when you repeatedly perform an interface module reset (OIR) on the OC-3 interface module.

Workaround: There is no workaround.

- CSCud76679

Symptom: The router displays a serial interface in the mroute table but does not forward traffic over the assigned interface.

Conditions: Occurs when you enable multicast traffic on the OC-3 interface module.

Workaround: There is no workaround.

- CSCud83069

Symptom: End-to-end traffic does not flow for ATM PVP Mode.

Conditions: Occurs when you enable ATM PVP Mode.

Workaround: There is no workaround.

- CSCud83698

Symptom: Links on the Gigabit Ethernet interface do not become active.

Conditions: Occurs on the Gigabit Ethernet interface when the local interface is configured for autonegotiation and the remote interface is configured for a speed of 10 Mbps or 100 Mbps.

Workaround: Toggle the auto-negotiation configuration on the Gigabit Ethernet interface.

- CSCud91892

Symptom: Remote LFA converges slowly and the router does not learn backup paths for global prefixes.

Conditions: Occurs when you configure remote LFA with a high number of global prefixes.

Workaround: There is no workaround.

- CSCue00332

Symptom: BFD connections flap, bringing down IGP.

Conditions: Occurs when you enable BFD on an interface that is flapping.

Workaround: There is no workaround.

- CSCue03418

Symptoms: The router displays OSPF protocol flaps causing a 20–30 second traffic loss.

Conditions: The issue occurs very intermittently on a HA system with a 6 second dead-interval value when you issue the **redundancy force-switchover** command;

Workaround: Increase the dead-interval value.

Open Caveats—Cisco IOS XE Release 3.8(0)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.8(0)S.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.
- CSCty70119

Symptom: Port shaper rate changes do not take effect.

Conditions: Occurs when QoS policies attached to EVCs on an interface do not include a shaper configuration; the issue does not occur on EFP policies that include a shaper in a class.

Workaround: Include a shaper in one class of the EFP policy.
- CSCua39109

Symptom: The router displays the following console error message:

```
%FMFP_ACL-3-ACL_OBJECT_DOWNLOAD: SIP0: fman_fp_image: ACL create/modify for ACL test9 fail to download because Cannot allocate memory.
```

Conditions: Occurs when the router is running a configuration containing a high number of ACLs.

Workaround: There is no workaround.
- CSCua55522

Symptom: The router experiences intermittent flapping on REP segments.

Conditions: Occurs under the following conditions:

 - An lsl-age-timer is configured
 - The configuration contains multiple REP segments
 - The router is experiencing high CPU utilization.

Workaround: There is no workaround. However, the following can limit the issue:

 - Limiting the configuration to a single REP segment
 - Using an **lsl-age-timer** of greater than 500 milliseconds
- CSCua62029

Symptom: The router crashes.

Conditions: Occurs when you configure a service policy with two child policies with the same name.

Workaround: Create a child service policy with a different name.
- CSCua73104

Symptom: The router does not increment QoS port shaper policy counters displayed by the show policy interface command.

Conditions: Occurs when you configure -A class-default policy on a physical interface -A class-based policy on an EVC interface

- Workaround:** There is no workaround; however, the router applies the QoS policy normally.
- CSCua77688
Symptom: The router experiences remote CFM MEP flapping.
Conditions: Occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.
Workaround: Reduce the rate of traffic.
 - CSCua90879
Symptom: QoS policies with a police statement on the class-default class do not take effect.
Conditions: Occurs when you apply a police statement to the class-default class within a QoS policy on an ingress EVC interface.
Workaround: Apply the police statement to a static class, such as class cos0.
 - CSCub50477
Symptom: The router does not pass Multicast traffic after a stateful switchover (SSO).
Conditions: Occurs when you issue an SSO while the router is passing Multicast traffic on an inbound MLP interface.
Workaround: There is no workaround.
 - CSCub65096
Symptom: The router crashes when running multicast traffic.
Conditions: Occurs when the router is passing IGMP join messages at a rate of 6 packets per second over 240 serial interfaces.
Workaround: Send IGMP joins at a lower rate.
 - CSCub77354
Symptom: An RSP switchover causes the serial interfaces to flap on the peer device.
Conditions: Occurs when you perform an RSP switchover by physically removing the active RSP.
Workaround: Use the following workarounds:
 - Perform an RSP switchover using the **redundancy force-switchover** command.
 - Configure the local device to use **clock source line** and the remote device to use **clock source internal**.
 - CSCub78861
Symptom: Following a reload, the router handles CFM only on 128 VLANs or bridge-domains.
Conditions: Occurs when the router configuration contains CFM and more than 128 VLANs or bridge-domains.
Workaround: There is no workaround.
 - CSCuc01154
Symptom: The router does not report B1, B2, and B3 alarms at normal thresholds.
Conditions: Occurs on the OC-3 interface module when the router sends errored frames.
Workaround: There is no workaround.
 - CSCuc02617
Symptom: The router stops passing MPLS LDP traffic.

- Conditions:** Occurs on MPLS over POS interfaces when the router is sending traffic above the line rate.
- Workaround:** Send MPLS LDP traffic below the line rate.
- CSCuc23610

Symptom: The router does not pass IP traffic with an MPLS LDP tunnel label of Imp-null.

Conditions: Occurs when the router is switching traffic using IP fast-reroute (FRR).

Workaround: Configure the **mpls ldp explicit-null** command.
 - CSCuc44701

Symptom: FP init fails on reload with TEFP QoS configs

The router displays an error message similar to the following: Oct 1 12:07:21.806 IST: %CMRP-3-CHASSIS_MONITOR_READY_TIME_EXCEEDED: R1/0: cmand: Reloading F1 because it has failed to become ready for packet processing

Conditions: Occurs when you reload the router while running a configuration that contains

 - An egress QoS policy attached to a trunk EFP
 - An **encapsulation dot1q** statement within the QoS policy that specifies a large range

Workaround: There is no workaround.
 - CSCuc55739

Symptom: The console displays an error message similar to the following example:

```
(Oct 8 10:46:53.126 IST: %FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP1: fman_fp_image: frr
0x200005ab download to CPP failed).
```

Conditions: Occurs following a stateful switchover (SSO).

Workaround: There is no workaround.
 - CSCuc57939

Symptom: The router stops passing traffic for more than 8 seconds.

Conditions: SSO Occurs when you initiate a stateful switchover (SSO) with a remote Loop Free Alternate Fast Reroute (LFA FRR) configuration.

Workaround: There is no workaround.
 - CSCuc58371

Symptom: Some links do not become active on the OC-3 interface module.

Conditions: Occurs on the OC-3 interface module (IM) configured at a high scale after you perform a multiple soft OIRs on the IM. The issue occurs frequently with SONET framing.

Workaround: You can use the following workarounds:

 - Apply a **shutdown/no shutdown** to the OC-3 controller.
 - Re-apply the PDH configuration.
 - Add and remove a loopback configuration on the PDH.
 - Add and remove a loopback configuration on the OC-3 controller.
 - CSCuc62049

Symptom: OSPF/BFD interfaces flap when you apply a test access list.

Conditions: Occurs when you configure an IP ACL on an EVC interface.

Workaround: Remove the configuration.

- CSCuc66393
Symptom: The router loses OC-3 interface configurations after an ISSU upgrade.
Conditions: Occurs on OC-3 serial and POS interfaces after an ISSU software upgrade.
Workaround: There is no workaround.
- CSCuc68699
Symptom: The displays a segmentation fault error at `cgmu_nq_ccm_convert` and crashes.
Conditions: Occurs when you perform the following actions:
 - Remove QoS policies from an EFP interface
 - Remove policy-maps and class-maps associated with the QoS policy.**Workaround:** There is no workaround.
- CSCuc80957
Symptom: The router crashes.
Conditions: Occurs when you rest the 10 gigabit Ethernet interface module (IM) on a non-redundant system using the **hw-module subslot reload** command.
Workaround: Administratively shut down the IM before resetting the IM.
- CSCuc81334
Symptom: The router selects a clock source attached to standby RSP.
Conditions: Occurs after a stateful switchover (SSO).
Workaround: Remove and restore the clock source configuration.
- CSCuc83088
Symptom: The router drops traffic during stateful switchover (SSO).
Conditions: Occurs when the router is running HSRP or VRRP; the issue only occurs when the destination MAC address is a virtual MAC (vMAC) address.
Workaround: Change the traffic priority and detour traffic prior to the SSO.
- CSCuc87791
Symptom: The router selects a network clock source before the wait-to-restore timer has expired.
Conditions: Occurs under the following conditions:
 - A clock source fails, triggering the wait-to-restore timer (which specifies how long the before including a restored clock source in the clock selection process.
 - The clock source becomes active and fails a second time before the wait-to-restore time has passed.**Workaround:** There is no workaround; in some cases you can clear the issue by removing and restoring the clock source configuration.
- CSCuc90006
Symptom: When you shut down a link within an Multiservice Transport Platform (MSTP) instance, interfaces in other MSTP instances are blocked.
Conditions: Occurs when the interface in the MSTP instance is the root port.
Workaround: There is no workaround.

- CSCuc92350
Symptom: A connection between two copper SFPs does not become active.
Conditions: Occurs when two SFP interfaces are connected with one side set to 100 Mbps and the other side set to **negotiation auto**.
Workaround: Set the speed to 10Mbps at both sides, then configure negotiation auto on one side of the connection.
- CSCuc93895
Symptom: The router has an Automatic Protection Switching (APS) switchover time of more than 1 second.
Conditions: Occurs on MLPPP interfaces configured at a high scale when the router is running with ICRM in SONET mode.
Workaround: There is no workaround.
- CSCuc93985
Symptom: The router initiates an Automatic Protection Switching (APS) switchover during a high availability (HA) stateful switchover (SSO).
Conditions: Occurs during an HA SSO with single router APS (SR-APS).
Workaround: There is no workaround.
- CSCuc95716
Symptom: FPGA software for the OC-3 interface module is not bundled with the XE 3.8 image.
Conditions: Occurs when upgrading FPGA on the OC-3 interface module.
Workaround: Manually upgrade the OC-3 FPGA.
- CSCud01644
Symptom: The active forwarding processor (FP) is on the standby route switch processor (RSP).
Conditions: Occurs when you boot the two RSPs in quick succession and the FP on the standby RSP becomes active before the FP on the active RSP.
Workaround: Reload the router.
- CSCud01908
Symptom: The **show platform software object-manager fp active statistics** command shows pending objects on the Forwarding Manager (FMAN) on the forwarding processor (FP), indicating a failure to download configurations from the Route Switch Processor (RSP) to the data plane (DP).
Conditions: Occurs when you apply a QoS shaping configuration at a high scale.
Workaround: There is no workaround.
- CSCud04407
Symptom: The router displays the following console error message: `Error - packet with unsupported linktype 3`
Conditions: Occurs when the router is passing traffic over the OC-3 interface module.
Workaround: There is no workaround.
- CSCud04529
Symptom: The router shows traffic loss.

- Conditions:** Occurs when the primary path is recovered via remote Loop Free Alternate Fast Reroute (LFA FRR).
- Workaround:** There is no workaround.
- CSCud06744

Symptom: The router does not download MPLS global prefixes.

Conditions: Occurs under the following conditions:

 - You configure Loop Free Alternate Fast Reroute (LFA FRR) at a high scale.
 - The primary or backup paths flap multiple times.

Workaround: There is no workaround.
 - CSCud06772

Symptom: IPv6 neighbor discovery does not function properly after stateful switchover (SSO); the router loses traffic and eventually recovers.

Conditions: Occurs with IPv6 traffic after stateful switchover (SSO).

Workaround: Configure software BFD sessions.
 - CSCud07642

Symptom: The ASR 903 is unable to pass traffic to the ASR 9000.

Conditions: Occurs with a clear-channel ATM over MPLS configuration using AAL0 encapsulation.

Workaround: Enable MPLS control-word on the ASR 9000.
 - CSCud12587

Symptom: When handling IS-IS packets, the router punts the traffic to the Route Switch Processor (RSP) and applies policing to limit the traffic to 1 Mbps.

Conditions: Occurs when you enable IS-IS over an Ethernet over MPLS (EoMPLS) connection.

Workaround: Use IS-IS over another connection type or limit the IS-IS traffic to less than 1 Mbps.
 - CSCud13242

Symptom: The ASR 903 does not display an alarm when nV satellite authentication fails.

Conditions: Occurs when the ASR 9000 and ASR 903 are in an nV satellite configuration and the routers are configured with a different serial-number value.

Workaround: There is no workaround.
 - CSCud13535

Symptom: The router drops imposition traffic sent to a neighbor device over a VPLS pseudowire.

Conditions: Occurs when the neighbor device configuration includes the **no split horizon group** command.

Workaround: Remove the **no split horizon group** command from the VPLS neighbor device.
 - CSCud15785

Symptom: The router experiences flaps in REP traffic.

Conditions: Occurs when the MAC limit feature is configured at a high scale.

Workaround: Disable the MAC limiting feature.
 - CSCud24648

Symptom: The router standby RSP displays an ether_efp_cfg_message_unmarshal_error message and crashes.

Conditions: Occurs under the following conditions:

- The router has an 8 port Gigabit Ethernet interface module (IM)
- The IM is configured with a service instance
- The service instance has an xconnect and bridge domain interface (BDI) configuration
- You perform a soft OIR (reset) on the IM while the standby RSP is booting

Workaround: Wait for the standby RSP to boot before resetting the IM.

- CSCud26382

Symptom: The router drops traffic on an EFP interface after you perform a stateful switchover (SSO).

Conditions: Occurs under the following conditions:

- You boot the standby RSP
- The router configuration contains an EFP interface on a Gigabit Ethernet port and a bridge domain interface in a down state.
- After the router reaches an SSO state, you issue a no shutdown command on the peer router to bring the EFP interface up.
- You perform a stateful switchover (SSO) on the router.

Workaround: Issue a shutdown/no shutdown on the gigabit Ethernet port.

- CSCud26997

Symptom: The IOMD process can crash on the T1/E1 interface module.

Conditions: Occurs during RSP switchover with a configuration containing CEM, ATM, IMA layer 2 attachment circuits, and pseudowires.

Workaround: There is no workaround.

- CSCud28553

Symptom: The router stops passing Switch Port Analyzer (SPAN) traffic.

Conditions: Occurs after you apply a **shutdown/no shutdown** on the SPAN source port with Ethernet flow point (EFP) and bridge domain interface (BDI) configurations.

Workaround: Enable and disable the SPAN session

- CSCud28685

Symptom: Ping fails between the CE1 and CE2 devices when the ASR 903 is acting as the PE device.

Conditions: Occurs when the SONET controller or ATM interface experiences an interface flap.

Workaround: Perform a soft OIR on the interface module.

Resolved Caveats—Cisco IOS XE Release 3.8(0)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.8(0)S.

- CSCty41692

Symptoms: Standby PRE crashes when you add an IPV4 VRF AF on the active PRE. The issue does not occur on the active PRE.

Conditions: Occurs when you remove and re-apply a configuration when BGP is in read-only mode.

Workaround: Once BGP exits read-only mode, this issue will not happen.

- CSCty85926

Symptoms: The VC (VPLS/EoMPLS) stays down and displays the following message in the **show mpls l2 vc detail** command: **signaling protocol: LDP, peer unknown**

Conditions: Occurs if you configure LDP GR; do a SSO switchover and configure the VC after the switchover is complete.

Workaround: There is no workaround; reload the switch.

- CSCtz96504

Symptoms: Backup VCs remain down after SSO.

Conditions: Occurs at high scale, such as when you create 500 primary and 500 backup VCs.

Workaround: You can use the **clear xconnect peerid peerid of the PW vcid vcid** command to bring the backup VCs to an SB state; however, this is not usually recommended.

- CSCtz98347

Symptoms: When IS-IS is configured to run level-2, IS-IS LFA does not create repair path if the total metric to a prefix is 1024.

Conditions: Seen with 15.2(2)S and when the IS-IS metric is more than 1024 and configured with level-2.

Workaround: Ensure the total metric to a prefix is less than 1024, or use narrow metric setting

- CSCua27852

Symptoms: Traffic loss is seen in pure BGP NSR peering environment.

Conditions: The symptom is seen on a Cisco router that is running Cisco IOS Release 15.2(2)S, and the BGP peerings to CEs and RR are all NSR-enabled.

Workaround: Enable the **bgp graceful-restart** command for RR peering.

- CSCua61330

Symptoms: Traffic loss is observed during switchover if BGP graceful restart is enabled or the next hop is learned by BGP.

Conditions: This symptom occurs on a Cisco router running Cisco IOS XE Release 3.5S.

Workaround: There is no workaround.

- CSCua66870

Symptoms: When changing RPF neighbor (S,G) in PIM-dense mode, OIF on (*,G) is pruned unexpectedly.

Conditions: Occurs when you use PIM-dense mode.

Workaround: There is no workaround.

- CSCub61344

Symptom: Link Control Protocol (LCP) negotiation fails, causing an MLP bundle to stop passing traffic.

Conditions: Occurs under the following conditions:

- The router is configured with a T1 interface on the OC-3 interface module (IM)
- The OC-3 interface module uses SONET framing
- The T1 serial interface is part of an MLP bundle
- You change the CRC configuration value of the MLP bundle

Workaround: Follow these steps:

- Remove the T1 interface from the MLP bundle.
- Perform a soft OIR (IM reset) on both ends of the connection.
- Wait for the T1 interface to become active.
- Add the T1 interface back into the MLP bundle.

- CSCud04161

Symptom: The router incorrectly displays a CFM Delay Measurement Message (DMM) value of 0.

Conditions: Occurs under any of the following conditions:

- You dynamically add a member link to a port-channel.
- You issue a shutdown/no shutdown on a member link of a port-channel.

Workaround: Wait for PTP to synchronize before configuring DMM scheduling.



Restrictions and Caveats in Cisco IOS XE 3.9S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.9 releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions, page 1](#)
- [Caveats in Cisco IOS XE 3.9S Releases, page 5](#)

Limitations and Restrictions

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.9(0)S and later:

TDM Limitation

- The **configure replace** command is not supported for TDM interfaces.

ATM IMA Limitation

- You can create a maximum of 16 IMA groups on each T1/E1 interface module.

Bidirectional Forwarding Detection Limitations

- The minimum supported timer value for software-based BFD sessions is 200 ms x 3 (using a multiplier of 3). The router supports up to 64 offloaded BFD sessions using a 200 ms x 3 timer.
- The Cisco ASR 903 Router supports hardware offloading of BFD echo mode packets for up to 255 sessions. The router handles additional BFD echo mode sessions in software.



Note

You cannot convert more than 255 normal BFD sessions to echo mode BFD sessions; the router reaches the offload limit and you must remove and reconfigure the remaining sessions.

- The minimum supported timer value for offloaded BFD echo mode sessions is 3.3 ms.

- In Release 3.9, the router keeps hardware and software-handled BFD echo mode sessions active during ISSU. Releases prior to 3.9 do not maintain hardware-offloaded BFD echo mode sessions during ISSU.
- If you downgrade from 3.9 to a prior release with a BFD echo mode configuration, you must increase the timer to 200ms or greater.

Bridge Domain Interface Limitation

- The **mtu** command is not supported on BDI interfaces; however the **ip mtu** command is supported.

Clocking and Timing Limitations

- Only a single clocking input source can be configured within each group of eight ports (0-7 and 8-15) on the T1/E1 interface module using the network-clock input-source command.
- Synchronous Ethernet clock sources are not supported with PTP. Conversely, PTP clock sources are not supported with synchronous Ethernet. However, you can use hybrid clocking to allow the router to obtain frequency using Synchronous Ethernet and phase using PTP.
- PTP over Ethernet is not supported in multicast mode; only unicast mode is supported
- G.8265.1 telecom profile is not supported for PTP over Ethernet.
- The Cisco ASR 903 Router does not support a mix of IPv4 and Ethernet clock-ports when acting as a transparent clock or boundary clock.
- Out-of-band clocking and the **recovered-clock** command are not supported.
- The Synchronization Status Message (SSM) is not currently on OC-3 and OC-12 interfaces.
- End-to-end Transparent Clock is not supported for PTP over Ethernet.

Dying Gasp Limitations

The Cisco ASR 903 Router supports dying gasp under the following scenarios:

- Ethernet OAM is disabled
- Interface is shut down
- Interface enters error-disabled state
- Router reload
- Dying Gasp is not supported in the event of a power failure.

EFP Limitations

- Trunk EFPs are not supported on port channel interfaces.
- Up to 1000 VLANs are supported for trunk EFP over etherchannel traffic.

Ethernet IM Limitations

- The Cisco ASR 903 Router does not support the Facilities Data Link (FDL) on Ethernet interfaces.
- The Cisco ASR 903 Router does not support the **mac-address** command on Gigabit Ethernet interface modules.
- 10 Gigabit Ethernet interface modules are not supported in slots 4 and 5.
- When you install a Gigabit Ethernet IM in the topmost interface module slot (slot 5), the last interface (interface GigabitEthernet0/5/0) is not operational; the port is reserved for internal communication.

- When you configure the copper and SFP Gigabit Ethernet interface modules on a router with redundant RSPs, the **speed** and **duplex** commands are not visible in interface configuration mode until you apply a **shutdown/no shutdown** to the interface.
- Fragmentation is not supported with Multicast traffic.
- The SFP-GE-T module supports only 100 Mbps and 1000 Mbps speeds.
- Load balancing using an odd number of port-channel member links is not supported.

IP Multicast Limitation

- Bandwidth-Based Call Admission Control (CAC) feature is not supported.

IPv6 Limitations

The following limitation applies when using IPv6 on the Cisco ASR 903 Router:

- IPv6 Neighbor Discovery (ND) cache timer expiry is 4 hours. To prevent the neighbour adjacency from being deleted after the timer expires:
 - configure hardware based BFD sessions with the neighbours, or
 - configure static IPv6 neighbours, or
 - configure the **ipv6 nd cache expire timer refresh** command.

IS-IS Limitations

- IS-IS over IPv6 is not supported on VRF instances.
- Only one IS-IS process is permitted when you configure IS-IS with the **address-family ipv6** and **bfd-all-interfaces** commands.
- The IS-IS total and per-stream convergence time increases as the number of prefixes increases.
- The Cisco ASR 903 Router supports up to 3000 IS-IS nodes.

MLPPP Limitations

The following limitations apply when using MLPPP on the Cisco ASR 903 Router:

- All links in an MLPPP bundle must be on the same interface module.
- All links in an MLPPP bundle must be of the same bandwidth.
- The Cisco ASR 903 Router supports a maximum of 16 links per bundle
- To change the MLPPP bundle fragmentation mode between enabled and disabled, perform a **shutdown/no shutdown** on the bundle.
- LFI is not supported
- Multiclass MLP is not supported
- The Cisco ASR 903 Router supports MLPPP statistics with the following limitations:
 - Packet counters on the bundle display the number of fragments rather than packets.
 - Control packets are accounted on the bundle.
- If you increase the maximum transmission unit (MTU) size on an MLPPP interface to a value higher than the maximum received reconstructed unit (MRRU) value on the peer interface, this can bring the MLPPP tunnel down. To restore the tunnel, perform a shutdown/no shutdown on the interface.

MPLS VPN Limitation

- MPLS VPN (L3VPN) Fragmentation does not function properly if an access interface has a higher MTU value than a core interface. To ensure that fragmentation functions correctly, configure the core interface MTU with a value that exceeds the access interface MTU and relevant headers.

OC-3 IM Limitations

- The **configure replace** command is not supported on the OC-3 IMs.
- MPLS-TP is not supported over POS interfaces.
- Multicast is not supported on OC-12 interfaces.
- DS0 channelization is not currently supported.
- MPLS is supported only on PoS interfaces; MPLS on T1/E1 links is not supported.
- IP-FRR and BFD-triggered FRR are not supported on MPLS over POS links.
- Fragmentation is not supported with Multicast traffic on PoS interfaces.
- QoS is not supported for Multicast traffic on PoS interfaces.
- QoS is supported on POS interfaces on optical interface module.
- Three-level QoS policies are not supported on OC-3/OC-12 serial, MLPPP, and PoS interfaces. You can only apply two-level QoS policies.
- The Synchronization Status Message (SSM) is not currently on OC-3 and OC-12 interfaces.

Pseudowire/AToM Limitation

- The Cisco ASR 903 Router supports ATM over MPLS N-to-one cell mode for a single ATM Virtual Channel Connections (VCCs) or Permanent Virtual Circuits (PVCs) to a pseudowire, but does not support mapping to multiple VCCs or PVCs.
- The Cisco ASR 903 Router does not support ATM over MPLS one-to-one cell mode.
- The Cisco ASR 903 Router supports pseudowire ping using the CW method; pseudowire ping using the TTL method is not supported.
- The Cisco ASR 903 Router supports a maximum of 2000 pseudowires in any combination.
- The following features are not currently supported on pseudowire connections:
 - Ethernet VLAN to Ethernet VLAN L2VPN interworking (bridged and routed modes)
 - Ethernet VLAN to ATM AAL5 L2VPN Interworking (bridged and routed modes)

The following pseudowire (PW) features are not supported over MPLS-TP connections:

- ATM OAM Cell Emulation for ATM AAL5 over MPLS on PVC and in VC Class.
- BFD / VCCV over ATM AC over MPLS TP
- Ethernet port to ATM AAL5 PVC L2VPN Interworking (bridged and routed modes)
- MIB support including PW-TDM-MIB, PW-ATM-MIB, and PW-CESOPSN-MIB
- N:1 PVC Mapping with non-unique VPI (N>1)

QoS Limitations

For a description of QoS features and limitations on the Cisco ASR 903 Router in Release 3.9S, see <http://www.cisco.com/en/US/docs/routers/asr903/software/guide/chassis/Release3.9.0S/ASR903-Chassis-SW-39.html>

Software Upgrade Limitation

We recommend you set the **interface-module-delay** value to 150 or greater in order to ensure sufficient time for IM software upgrades.

Subinterfaces Limitation

The Cisco ASR 903 Router does not support subinterface configurations except on ATM interfaces. You can configure similar functionality using multiple Ethernet Virtual Connections on an interface. For more information, see [Configuring Ethernet Virtual Connections on the Cisco ASR 903 Router](#).

T1/E1 IM Limitations

- Inverting data on the T1/E1 interface is not supported—Inverting the data stream using the invert data interface command is not supported.
- Bit error rate test (BERT) patterns have limited support—Currently, only the 2¹¹, 2¹⁵, 2²⁰-O153, and 2²⁰-QRSS patterns are supported for BERT.
- If you issue the **no card type** command on the controller, you must reload the router in order to configure a new **card type** value.

Caveats in Cisco IOS XE 3.9S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.9S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

**Note**

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select caveats of any severity. To reach the Bug Toolkit, log in to Cisco.com and go to http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl. (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.9S Releases:

- [Open Caveats—Cisco IOS XE Release 3.9\(2\)S, page 6](#)
- [Resolved Caveats—Cisco IOS XE Release 3.9\(2\)S, page 6](#)
- [Open Caveats—Cisco IOS XE Release 3.9\(1a\)S, page 14](#)
- [Resolved Caveats—Cisco IOS XE Release 3.9\(1a\)S, page 18](#)
- [Open Caveats—Cisco IOS XE Release 3.9\(0\)S, page 27](#)

- [Resolved Caveats—Cisco IOS XE Release 3.9\(0\)S, page 31](#)

Open Caveats—Cisco IOS XE Release 3.9(2)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.9.2S.

- CSCue20035
Symptom: Virtual circuit (VC) status goes down after reload.
Conditions: This issue occurs when reloading the core side trunk EFP BDI with port channel using cross connect. LDP comes up but VC status goes down.
Workaround: On core side, use EVC bridge-domain BDI with port channel instead of trunk EFP BDI with port channel.
- CSCue67267
Symptom: High traffic drop on Stateful Switchover (SSO). Double dip on SSO.
Conditions: This issue occurs occasionally (one in five iterations) on Cisco ASR 903 Router with MVPN scale setup.
Workaround: There is no workaround.
- CSCuf89283
Symptom: Connectivity Fault Management (CFM) sessions configured on pseudowire continue to flap.
Conditions: This issue occurs when route flaps quick enough to prevent bringing down of the pseudowire.
Workaround: Bring down the pseudowire and bring it back up again.
- CSCuh94841
Symptom: 10 Gigabit Ethernet interface flaps without trigger causing traffic to switch to protected label-switched path (LSP).
Conditions: This issue occurs when the script is run for continuous SSO.
Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.9(2)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.9.2S.

- CSCud61551
Symptom: Serial Number of the RSP in slot 1 does not display in the **show inventory** command output.
Conditions: This issue occurs under unknown conditions.
Workaround: Reload the router.
- CSCue29865
Symptom: Values do not display for OC-12 mode after shutting the IM bay.
Conditions: This issue occurs after shutting the IM bay. Values are not displayed for OC-12 mode, but the values are displayed for the Gigabit Ethernet card.

- Workaround:** There is no workaround.
- CSCue32016

Symptom: On IM online insertion and removal (OIR) or Router reload with shutdown on CE controller, Ethernet (core) does not transmit any packets.

Conditions: This issue occurs when remote peer does not assert alarm indication signal (AIS) downstream.

Workaround: There is no workaround.
 - CSCue44876

Symptom:

 - Packet-over-SONET (PoS) interface on the high availability (HA) system continues flapping
 - Complete traffic is dropped
 - PoS interface of the remote Cisco ASR 903 Router remains in up or down state.

Conditions: This issue occurs on activating SSO after an IM OIR when configuring PoS interface in OC-12 mode.

Workaround: There is no workaround.

More Info: This issue is not seen in OC-3 mode.
 - CSCue61850

Symptom: Maintenance End Points (MEPs) start flapping when **no shutdown** command is issued on EVC bridge-domain (BD) or port channel interface running CFM.

Conditions: This issue occurs when more than 256 CFM sessions are configured.

Workaround: Configure fewer CFM sessions (50 to 100).
 - CSCue67835

Symptom: OSPF flaps when you set the dead interval timer as 6 seconds and hello interval as 2 seconds.

Conditions: This issue is observed when you perform an SSO.

Workaround: Use the default OSPF hello timers.
 - CSCue69818

Symptom: The **show inventory** command displays a wrong serial number.

Conditions: Inventory is managed by the "main serial number". However, when using the **show inventory** command for Redundant Power System (RPS) and IM, "PCB serial number" is displayed instead of the "main serial number".

Workaround: Use the **show diag all eeprom detail** command to list the correct serial number.
 - CSCue75372

Symptom: Time-Hog traceback seen after router or IM reloads.

Conditions: This issue occurs on bootup of IM or router.

Workaround: There is no workaround.
 - CSCue97180

Symptom: The Cisco ASR 903 Router sometimes crashes when used as a multicast VPN (mVPN) Encap PE Router.

Conditions: This issue occurs in an mVPN network on exceeding core multicast distribution tree (MDT) scale of 1K with more than 20 virtual routing and forwarding (VRFs) on a flap access interface of a PE Router.

Workaround: Do not exceed more than 1K core MDT scale Work around for a crash is unavailable.

- CSCuf02007

Symptom: Continuous SEMHOG is seen on the router console with incremental sync failure and IOMD crashes on OC-3 IM.

Conditions: Router receives continuous SEMHOG for multiple processes.

Workaround: There is no workaround.

- CSCuf06001

Symptom: When TCAM limit is reached, statistics do not work accurately.

Conditions: This issue occurs when the TCAM entries exceed the limit during dynamic modification of service-policy.

Workaround: There is no workaround.

- CSCuf43992

Symptom: The router crashes if you configure local span.

Conditions: This issue is observed when you configure local span on the router.

Workaround: Use another Encapsulated Remote Switched Port Analyzer (ERSPAN) configuration to work as local span with source and destination ERSPAN session configured in one router.

- CSCuf45656

Symptom: Cisco ASR 903 Router crashes with segmentation fault.

Conditions: This issue occurs during multicast convergence on EFP's configured with split horizon.

Workaround: There is no workaround.

- CSCuf53527

Symptom: Class of Service (CoS) inner value gets copied into the CoS value.

Conditions: This issue occurs when configuring Q-in-Q without rewrite service instance.

Workaround: To ensure CoS inner value does not get copied, apply QoS policy-map.

- CSCuf65301

Symptom: Micro flaps observed on the router.

Conditions: This issue is seen when system is kept idle for hours.

Workaround: There is no workaround.

- CSCuf79397

Symptom: F1 is stuck in init state after the standby RSP reloads.

Conditions: This issue occurs on a reload or OIR of the standby RSP.

Workaround: Reload the standby RSP again.

- CSCuf81085

Symptom: After you use the **shutdown** and **no shutdown** commands on the controller of PE, IMA VCs go down.

Conditions: This issue is observed after using the **shutdown** and **no shutdown** commands on the OC3 controller on PE routers.

Workaround: Use the **shutdown** and **no shutdown** commands on the controller.

- CSCuf89767

Symptom: When IGMP snooping is enabled, multicast traffic is not accurately filtered. Layer 3 multicast traffic floods all ports of the bridge-domain.

Conditions: This issue occurs when start-up configuration includes port channels along with TEFP/EFP as part of the bridge-domain.

Workaround: There is no workaround.

- CSCug05239

Symptom: Traffic drops on the router.

Conditions: This issue occurs when configuring multichassis Link Aggregation Control Protocol (MLACP) switchover with Ethernet over Multiprotocol Label Switching (EOMPLS).

Workaround: Configure port channel with EOMPLS.
- CSCug10116

Symptom: Traffic and ping do not flow through ATM interfaces on multiple controllers.

Conditions: Series of **shutdown** and **no shutdown** commands on the controller or interface lead to the failure.

Workaround: There is no workaround. To recover from failure, perform an IM OIR.
- CSCug18185

Symptom: When the interfaces comes up after bootup, traffic received on the Cisco ASR 903 Router serial interfaces are not switched to the BDI connected to Ixia.

Conditions: This issue occurs when ARP resolution of the Ixia connected interface IP address fails.

Workaround: Ping the Ixia port connected to the Cisco ASR 903 Router from another router connected to the Cisco ASR 903 Router using Gigabit Ethernet interface.
- CSCug18630

Symptom: When you perform an OIR on the standby and active RSPs, CMAND crashes.

Conditions: This issue is observed after performing multiple standby OIRs and bringing the standby machine up.

Workaround: There is no workaround.
- CSCug21145

Symptom: When system crashes, sometimes core files are generated with CRC errors.

Conditions: This issue occurs when the system crashes under stress conditions.

Workaround: There is no workaround.
- CSCug27073

Symptom: Multicast replication is improper when 255 outgoing interfaces (OIF's) are configured.

Conditions: This issue occurs when:

 - Perfuming IM OIR (soft/hard)
 - Clearing MRoutes (sometimes)
 - Enabling/disabling IGMP Snooping

Workaround: There is no workaround.
- CSCug31414

Symptom: Multicast traffic drops on changing interface configuration from TEFP to VPLS over port channel (PoCH).

Conditions: This issue occurs when converting a layer 2 interface to layer 3; and then configuring IP PIM and IP address in quick succession.

Workaround: Use **shutdown** and **no shutdown** command on the interface.

More Info: The problem occurs only when the adjacency create notification is received earlier than the convert to layer 3 notification.

- CSCug44762
Symptom: The POS interface stays down after using the **shutdown** and **no shutdown** commands.
Conditions: This issue is observed when you use the **shutdown** and **no shutdown** commands on the POS interface.
Workaround: Use the **shutdown** and **no shutdown** commands on the controller.
- CSCug61357
Symptom: ISIS adjacency and BFD stay down after using the **shutdown** and **no shutdown** commands.
Conditions: This issue is observed in R-LFA configurations.
Workaround: Use the **shutdown** and **no shutdown** commands again.
- CSCug63862
Symptom: When configured, SATOP interfaces does not come up.
Conditions: This issue occurs on configuring SATOP on the router.
Workaround: Use IM OIR.
- CSCug74071
Symptom: When scaling up MPLS-TE tunnels to full scale (512), sometimes the following message is displayed: "%FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP1: fman_fp_image: adj 0x9fdd, Flags Incomplete download to CPP failed".
Conditions: This issue occurs when MPLS-TE tunnels are scaled to full scale (512) on the router in a single instance.
Workaround: There is no workaround.
- CSCug83807
Symptom: Multicast traffic is dropped as TCAM entries are encountered.
Conditions: This issue occurs when TCAM entries are encountered.
Workaround: There is no workaround.
- CSCug83842
Symptom: ATM/IMA path level controllers go down with alarms LP-AIS and T15 LOMF in the Cisco ASR 903 Router.
Conditions: This issue occurs on either on bootup of the router or OIR of the IM. Along with these alarms, B1/B2 alarms are reported at the controller level. As B1/B2 alarms are high priority alarms, the path level controllers stays down.
Workaround: Reload IM or use the **shutdown** and **no shutdown** command on the main controllers.
- CSCug84544
Symptom: POS interface output displays wrong counter values.
Conditions: This issue occurs when using PPP encapsulation.
Workaround: There is no workaround.
- CSCug86963
Symptom: Bidirectional Forwarding Detection (BFD) is unable to resolve neighbor Address Resolution Protocol (ARP).

Conditions: This issue occurs when software BFD is configured with static client; and IM OIR or reload is performed.

Workaround: Use manual ping.

- CSCug91295

Symptom: UDP based ACLs do not work after a router reload.

Conditions: This issue occurs after reload.

Workaround: Remove and add the ACL.

- CSCug96958

Symptom: Inverse Multiplexing for ATM (IMA) interfaces stay up even when you use the **shutdown** command to shut down the controller.

Conditions: This issue is observed when you use the **shutdown** command on the OC-3 controller.

Workaround: Use the **no shutdown** command bring up the controller and interfaces.

- CSCug97639

Symptom: IPv4 VRF ping fails when disabling IPv6 unicast-routing globally.

Conditions: This issue occurs when IPv6 unicast-routing is disabled.

Workaround: Enable IPv6 unicast-routing

- CSCug99750

Symptom: The Cisco ASR 903 Router crashes when it accesses unpopulated data structures.

Conditions: This issue is observed when you perform an IM OIR and use the **shutdown** and **no shutdown** commands.

Workaround: There is no workaround.

- CSCuh00343

Symptom: Node runs out of memory if node has more 1K pseudowires. Pseudowire can be either Ethernet over MPLS (EoMPLS) or Virtual Private LAN Services (VPLS).

Conditions: Access instability cause these memory leaks. If network is stable then chances of observing this issue is minimal.

Workaround: There is no workaround.

- CSCuh06740

Symptom: Router gets reloaded after performing a soft OIR.

Conditions: This issue is observed after you perform a soft OIR or subsequent SSOs.

Workaround: There is no workaround.

- CSCuh16011

Symptom: FMAN-FP crashes when you perform ab IM OIR.

Conditions: This issue is observed when you perform multiple IM OIRs with around 65 BFD sessions.

Workaround: Reload the router.

- CSCuh18073

Symptom: In a domain with 2 BGP exit points acting in Active or Repair mode, traffic would be exiting the domain through Repair path BGP PE instead of exiting through Active path BGP PE.

Conditions: This issue occurs in the following conditions:

- Environment has 2 BGP exit points
- A change in one of the core links to the primary BGP exit point results in Repair BGP PE becoming Active BGP PE and vice versa

In this scenario, even after BGP convergence, data packets would traverse through previous primary BGP PE (now repair path PE).

Workaround: There is no workaround.

- CSCuh18503

Symptom: BFD IPv6 sessions may not come up between Cisco ASR 9000 and Cisco ASR 903 Routers.

Conditions: This issue is observed when the packets sent from Cisco ASR 903 Router have invalid UDP checksums.

Workaround: There is no workaround.

- CSCuh27117

Symptom: Traffic loss of about six to eight seconds is observed when you perform an SSO.

Conditions: This issue is observed when you perform the switchover before IM OIR or the interface flaps.

Workaround: There is no workaround.

- CSCuh33255

Symptom: Traffic does not flow through most multilink PPP (MLP) interfaces post In-Service Software Upgrade (ISSU).

Conditions: This issue occurs on HA system performing ISSU or killing IOMD process followed by switchover.

Workaround: Use **shutdown** and **no shutdown** command on MLP interface to recover the traffic.

- CSCuh59723

Symptom: On removing one out of the two member links from the MLP bundle, traffic and ping fail.

Conditions: This issue occurs with T1E1/OC-3 IM when using **shutdown** and **no shutdown** command or when removing cable from one of the member serial interface.

Workaround: Reload the router.

- CSCuh65426

Symptom: Circuit emulation (CEM) packets use class default after **shutdown** and **no shutdown** on CEM circuit, with or without QoS policy

Conditions: After removing and adding QoS policy on CEM circuits, followed by CEM interface flap, CEM packets neither exit with default EXP marking of 5 nor exit with the marking specified in ingress qos policy. This occurs after reloading the router with policies intact on CEM interface and only in the presence of Hot-Standby Psuedo Wires (HSPW).

Workaround: There is no workaround.

- CSCuh77595
Symptom: On using **configure replace** command, the standby router crashes.
Conditions: This issue occurs when replacing the TE tunnel configuration with Startup configuration using **configure replace** command.
Workaround: There is no workaround.
- CSCuh77762
Symptom: The TenGigabitEthernet port operates at one gigabit speeds in WAN-PHY mode on Cisco ASR 903 Routers. This leads to a huge amount of output drop.
Conditions: This issue is observed if a QoS policy is configured on the TenGigabitEthernet interface.
Workaround: There is no workaround.
- CSCuh86102
Symptom: The interface stops forwarding traffic.
Conditions: This issue is observed when the TenGigabitEthernet interface is in WAN-PHY mode and R0 is active.
Workaround: Use R1.
- CSCuh99117
Symptom: Cisco ASR903 Router packets drop for some of the prefixes in MPLS network.
Conditions: This issue occurs when MPLS L3 VPN is configured on Cisco ASR903 Router with MVPN template.
Workaround: There is no workaround.
- CSCui08269
Symptom: Error objects are seen and traffic does not flow through HSPW VC's.
Conditions: This issue occurs on using **do clear mpls ldp ne** command when more than 100 HSPW VC's are configured.
Workaround: Remove and add the EFP.
- CSCui16418
Symptom: After SSO, 10 Gigabit Ethernet interface flaps and traffic is dropped.
Conditions: This issue occurs during SSO switchover on the 10 Gigabit Ethernet interface of a HA system.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.9(1a)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.9(1a)S.

- CSCuc33798
Symptom: IMA links goes down with over subscription traffic.
Conditions: This issue is seen with over subscription traffic
Workaround: Use line rate.

- CSCuc42085

Symptoms: The 1PPS output from the ASR 903 is out of range when compared to the 1PPS output of the PTP master clock.

Conditions: This issue occurs when the router is configured as a hybrid clock (ordinary/boundary) and there are intermediate hops between the router and the PTP master clock.

Workaround: There is no workaround.
- CSCue29809

Symptom: Mismatch in the MIB object entSensorThresholdEvaluation value for CiscoEntitySensorMIB.

```
entSensorThresholdEvaluation.1086.1 = false(2) (value should be true)
entSensorThresholdEvaluation.1086.2 = false(2) (value should be true)
```

Conditions: This issue occurs in normal working conditions.

Workaround: There is no workaround.
- CSCue29865

Symptom: Values do not display for OC-12 mode after shutting the IM bay.

Conditions: This issue after shutting the IM bay. Values are not displayed for OC-12 mode, but the values are displayed for the Gigabit Ethernet card.

Workaround: There is no workaround.
- CSCue35103

Symptom: CPU goes high on executing **show mac-address-table** command.

Conditions: Scaled MAC entries are learned over BD.

Workaround: Execute the command with reduced term length.
- CSCue42139

Symptom: The Precision Time Protocol (PTP) state is stuck in acquiring state.

Conditions: This issue occurs when the active RSP is removed and the T3 time-stamping is stuck and the PTP stays in acquiring state.

Workaround: Reload the IM or unconfigure and configure the PTP.
- CSCue63229

Symptom: IMA interfaces flap frequently every 1530 minutes. The issue does not occur on member links.

Conditions: This issue occurs when you increase the number of member links in the IMA group to 16.

Workaround: There is no workaround.
- CSCue67835

Symptom: OSPF flap with aggressive timers (2sec hello interval, 6sec dead interval).

Conditions: This issue occurs after performing an SSO.

Workaround: Use the default OSPF hello timers.

- CSCue75372
Symptom: Time-Hog traceback seen after router or IM reloads.
Conditions: This issue occurs on bootup of IM or router.
Workaround: There is no workaround.
- CSCue87629
Symptom: INFRA-6-PROCPATH_CLIENT_HOG: IOS shim client “iosd-nile” messages may appear on the console.
Conditions: This issue occurs when a **shutdown** followed by a **no shutdown** command is executed on the G8032 ring interface of a peer or local device.
Workaround: There is no workaround.
- CSCue92393
Symptom: CEM SatoP circuits with the router in Core remain in down state after initial configuration. The **show cem circuit** command output on ASR903 shows that the circuits are down.
Conditions: This issue occurs when the CEM SatoP circuits are configured using script via tcl and tftp_config. This forces a lot of configuration dump on router console simultaneously. The issue may also be seen after router reload with saved CEM Satop configurations.
Workaround: Perform a controller **shutdown** followed by a **no shutdown** on OC-3 IM on the router.
- CSCuf05090
Symptom: Standby IM resets continuously with running configuration synchronization failure.
Conditions: This issue occurs after a downgrade of all IMs and the IMS are removed from the slot and a upgrade is performed.
Workaround: Reload the router completely.
- CSCuf35542
Symptom: PFM is fails for about 5minutes after OIR on the master.
Conditions: This issue occurs after OIR is performed two times on the master
Workaround: Wait for 5-6 minutes after the OIR.
- CSCuf79397
Symptom: F1 is stuck in init state after the standby RSP reloads.
Conditions: This issue occurs on a reload or OIR of the standby RSP.
Workaround: Reload the standby RSP again.
- CSCug05491
Symptom: The router drops traffic on VPLS circuits.
Conditions: This issue occurs when you take the following actions:
 - Configure REP with VLAN load balancing
 - Configure VPLS VFI on the VLANs
 - Issue an stateful switchover (SSO)**Workaround:** There is no workaround.

- CSCug14420
Symptom: Traceback observed while performing OIR of IM.
Conditions: This issue occurs while performing OIR T1E1 IM
Workaround: There is no workaround.
- CSCug21352
Symptom: The convergence time is more than 2secs on the router.
Conditions: This issue occurs when convergence time is more than expected. It takes around 2.5 seconds to converge from Active to backup path with 450 CEM interfaces.
Workaround: There is no workaround.
- CSCug70182
Symptom: ASR903 -IMA8S port stays up without inserting a fiber.
Conditions: This issue is observed when GLC-FE-100FX optic is used
Workaround: There is no workaround.
- CSCug77786
Symptom: The router develops false notifications, syslog messages and cefcFRUInserted traps when performing RP card switchover. The false notifications create false alarms in Prime Network.
Conditions: This issue occurs after RP card switchover on the router.
Workaround: There is no workaround.
- CSCug81561
Symptom: Convergence time is more than 50ms with EoMPLS after SSO.
Conditions: This issue occurs when port channel and BDI configurations exist on the router and SSO convergence time is more than 50ms.
Workaround: There is no workaround.
- CSCug83807
Symptom: Multicast traffic is dropped as TCAM entries are encountered.
Conditions: This issue occurs when TCAM entries are encountered.
Workaround: There is no workaround.
- CSCug91295
Symptom: UDP based ACLs do not work after a router reload.
Conditions: This issue occurs after reload.
Workaround: Remove and add the ACL.
- CSCug94257
Symptom: The **show ptp port running detail** command shows the wrong stream id.
Conditions: This issue occurs under normal working conditions.
Workaround: Use the **show plat soft ptp** command get the correct stream id.

Resolved Caveats—Cisco IOS XE Release 3.9(1a)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.9(1a)S.

- CSCtw76473

Symptom: The router displays packet drops on some VPLS pseudowire virtual circuits (VCs) on the disposition side.

Conditions: Occurs under the following conditions:

 - The core network is running MPLS-TP tunnels
 - There is an SSO switchover on the remote end or an LDP neighbor reset on the peer end.

Workaround: There is no workaround.
- CSCud09142

Symptom: Fp active error messages seen when interface tunnel TP is removed when HA is configured.

Conditions: This issue is seen after removing tunnel TP interface.

Workaround: There is no workaround.
- CSCud30554

Symptom: Object download failure messages are displayed on console during object cleanup. This may cause a possible leak in the hardware resource if the objects are not cleaned up.

Conditions: This issue is seen during the Virtual Circuit deletion.

Workaround: There is no workaround.
- CSCud42914

Symptom: Object download messages are observed when default values are set on the MPLS core interface.

Conditions: This issue occurs when default values are set on the MPLS core interface.

Workaround: There is no workaround.
- CSCud59242

Symptom: Traffic stops forwarding for 10-20 groups out of 1000 groups when IGMP snooping is enabled.

Conditions: This issue occurs when outgoing Layer 2 interface flaps very quickly. This issue occurs when executing the **shutdown** command followed by a **no shutdown** command.

Workaround: Disable IGMP snooping.
- CSCue10037

Symptom: After executing the **shutdown** command followed by a **no shutdown** the member link crashes

Conditions: This issue occurs when CFM Trunk EFP with 256 sessions with an interval of 3.3ms is configured and **shutdown** command followed by a **no shutdown** command is executed.

Workaround: Configure 50-100 CFM sessions.
- CSCue13187

Symptom: Duplicate multicast traffic is received after replacing the bridge-domain ID with new bridge-domain ID.

Conditions: This issue occurs when the bridge-domain ID is changed from an existing bridge-domain ID to a new bridge-domain ID.

Workaround: If the bridge-domain needs to be changed, remove the old service instance and configure new service instance with new bridge-domain.

- CSCue15570

Symptom: Traffic does not resume on a POS interface.

Conditions: This issue is seen after the router reloads with POS configurations.

Workaround: Perform the following:

- Shutdown the interface and then execute a **no shutdown** on the TDM interface
- Shutdown the controller then execute a **no shutdown** on the TDM controller
- Soft OIR the OC3 IM.

- CSCue19836

Symptom: Controller flaps are observed on CE routers with Multirouter Automatic Protection Switching (MR-APS) configured on PE routers with CEM circuits.

Conditions: This issue occurs when controllers on CE routers flaps when is MR-APS configured on PEs having CEM circuits.

Workaround: There is no workaround.

- CSCue20607

Symptom: Port-channel load balances traffic on member-links which are in hot-standby or down state also resulting in traffic blackholes.

Conditions: This issue is seen when there are redundant member-links which are in hot-standby or down state.

Workaround: There is no workaround.

- CSCue24854

Symptom: 70 msec loss is observed after performing an IM OIR in a remote LFA ring.

Conditions: This issue occurs when doing soft OIR.

Workaround: Perform a hard OIR for a less than 50 msec loss.

- CSCue34781

Symptom: The policer in the parent policy-map of an hqos policy attached to an interface stops working after the child policy policer is dynamically modified.

Conditions: The policy-map attached to the interface is a hierarchical policing policy. Both the child and the parent policy-map have policing actions in their classes. It is seen that the policing in the parent class does not work correctly after the policing action in the child policy is modified dynamically

Workaround: Remove and re-attach the policy-map on the interface

- CSCue50128

Symptom: FMFP download failure occurs on reaching 1980 odd number even though 2000 ternary content addressable memory (TCAM) space is allocated for ACLs in the IP template.

Conditions: This issue occurs in normal conditions when the scale reaches 1980.

Workaround: There is no workaround.

- CSCue51682

Symptom: The REP protocol flaps, as indicated by the following error messages:

```
*Feb  8 06:51:38.857: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
non-operational due to neighbor not responding
*Feb  8 06:51:39.096: %REP-4-LINKSTATUS: GigabitEthernet0/0/1 (segment 10) is
operational.
```

Conditions: Occurs under the following conditions:

 - The router is sending traffic using the incremental MAC address table
 - Fast LSL is configured using a 200ms timer.
 - The router is configured with more than 2000 MAC addresses.

Workaround: Remove fast LSL from the REP configuration.
- CSCue54649

Symptom: Traceback is seen on new active RSP console after performing a SSO.

Conditions: This issue is seen when OC-3 IM is configured on OC-12 mode. The POS and serial interfaces mayor may not be configured.

Workaround: There is no workaround.
- CSCue61803

Symptom: IMs do not get powered off when router is reloaded.

Conditions: This issue is seen occasionally on reload.

Workaround: There is no workaround.
- CSCue65149

Symptom: OBJ messages are observed when changing the interval in EVC BD offload cases (scale).

Conditions: This issue occurs when 3.3ms session interval and MEPS is configured on the router and then the MEPS and domain configuration is removed and a session interval of 10ms interval is configured.

Workaround: Configure a low session interval.
- CSCue66137

Symptom: The IOMD crashes with CPU hog messages.

Conditions: This issue occurs with OC-3 interface module and traffic is sent over a multilink bundle with packet size greater than 600 byte.

Workaround: There is no workaround.
- CSCue73478

Symptom: Standby RSP Sync LED become holdover after switchover.

Conditions: This issue occurs after a switchover.

Workaround: There is no workaround.
- CSCue77596

Symptom: Cos value gets wrongly marked for a QinQ packet

Conditions: This issue occurs on a service instance with dot1q encapsulation and no rewrite is configured on the interface.The policy map attached in the ingress has marking in it.

Workaround: There is no workaround.

- CSCue81082
Symptom: FMAN OBJ download failure seen for (*,G/m) entries on ACL change.
Conditions: This issue occurs when ACL is configured on the RP and the ACL is deleted or added.
Workaround: There is no workaround.
- CSCue83621
Symptom: Policy-map stops working on removing class default class dynamically.
Conditions: This issue occurs when policy-map is attached to target and class-default of top level is deleted dynamically.
Workaround: Detach and reattach the policy-map on target.
- CSCue88974
Symptom: Standby RSP appears as UNKNOWN in **show inventory** command and alarm is raised. The **show facility-alarm** command status reports the alarm.
Conditions: This issue occurs after OIR is performed on the standby RSP.
Workaround: There is no workaround.
- CSCue89503
Symptom: Power supply status become “CRITICAL” after removing or inserting of the power supply.
Conditions: This issue is seen after multiple OIRs.
Workaround: There is no workaround.
- CSCue90867
Symptom: Machine check errors and kernel crash was seen on SSO.
Conditions: This issue occurs after performing SSO.
Workaround: There is no workaround.
- CSCue91533
Symptom: Traffic through VPLS pseudowire is flooded due to MAC aging.
Conditions: This symptom is observed when bridge descriptor index (internal index) assigned to MAC address exceeds 20480.
Workaround: There is no workaround.
- CSCue93989
Symptom: Less traffic received then expected rate for IMA link.
Conditions: This issue occurs when IMA group is configured with 16 OC-3 T1 links. 888 pvcs are created and traffic is sent to only one pvc.
Workaround: There is no workaround.
- CSCue94811
Symptom: Process crash on standby does not generate a core file.
Conditions: This issue occurs on normal conditions.
Workaround: There is no workaround.
- CSCuf02518
Symptom: IPv4 Traffic gets affected on IPv6 ACL applied interface.

Condition: This issue occurs if IPv4 ACLs and IPv6 ACLs in the system share the same label. The IPv4 traffic on the interface on which IPv6 ACL is applied is impacted.

Workaround: There is no workaround.

- CSCuf05039

Symptom: I2C_WRITE and MDIO_READ/WRITE error messages are seen on the router.

Conditions: This issue occurs on IM hard or soft OIR.

Workaround: There is no workaround.

- CSCuf07508

Symptom: The Gigabit Ethernet port on IMA8S may not come up after reload at times.

Conditions: This issue occurs when the router is reloaded multiple times.

Workaround: Perform an IM OIR.

- CSCuf42166

Symptom: BERT Errors and Path Code Violations counter keeps incrementing.

Conditions: This issue occurs when connected to E1E1 IM or the second PHY.

Workaround: Connect to first PHY.

- CSCuf43275

Symptom: The router does not detect or support traffic through GLC-FE-100EX and GLC-FE-100ZX transceivers.

Conditions: This issue occurs under normal conditions.

Workaround: There is no workaround.

- CSCuf48156

Symptom: Local fault is seen on a 10 Gigabit Ethernet port.

Conditions: This issue occurs when the interface is not shut and fibre is not connected.

Workaround: Shutdown the interface

- CSCuf51429

Symptom: Fast-Reroute FMFP-3-OBJ_DWNLD_TO_CPP_FAILED message seen on the console.

Conditions: This issue occurs on shutting the link between the routers.

Workaround: There is no workaround.

- CSCuf51462

Symptom: Remote maintenance end points (MEP)s do not learn Port MEP on PC member links.

Conditions: This issue occurs when port MEPs in PC member links are configured and remote MEPs do not learn it.

Workaround: Configure Ethernet Virtual Connections (EVC) bridge domain and MEP PC member links.

- CSCuf51509

Symptom: WRED counters for CS0 do not display in **show policy-map interface** command.

Conditions: This issue is observed when **show policy-map interface** command is executed.

Workaround: There is no workaround.

- CSCuf61365

Symptom: VC Counters do not increment On IM OIR followed by SSO.

Conditions: This is seen on HA system when IM OIR is followed by SSO switchover is performed.

Workaround: There is no workaround.

- CSCuf64704

Symptom: “%MPLS-3-OUT_OF_LABEL3_SPACE: SIP0: nile_mgr: Out of resource to create” labels errors are seen on the console.

Conditions: This issue is seen with scaled configurations, when LDP peer goes down and recovers.

Workaround: Reduce the scale.

- CSCuf65040

Symptom: The 1G or 10G IM may go in out of service state after a hard OIR of the IM.

Conditions: This issue occurs after a hard OIR is performed.

Workaround: Perform a another hard OIR or a SSO switchover followed by a soft OIR.

- CSCuf66022

Symptom: The 10 Gigabit Ethernet interface status goes down on one side.

Conditions: This issue occurs after shutting down the Ten Gigabit Ethernet interface and SSO is performed.

Workaround: Perform a **shutdown** followed by a **no shutdown** 10 Gigabit Ethernet interface

- CSCuf74072

Symptom: Seeing CRC errors on SFP IM with CU SFP.

Conditions: This issue occurs when the CU SFP is configured with 100Mbps speed.

Workaround: There is no workaround.

- CSCuf83316

Symptom: Traffic loss of more than 1sec was observed during router reload.

Conditions: This issue occurs on issuing **reload** command in middle router with R-LFA in RING topology.

Workaround: There is no workaround.

- CSCuf83453

Symptom: The **show ethernet service instance stats** command displays "0" at Egress stats counters.

Conditions: This issue is seen after using **show platform hardware pp active ASIC stats** command.

Workaround: Reload the router.

- CSCuf83886

Symptom: Label exhaust message is seen even on valid case if policy is configured before xconnect is configured on scaled configuration.

Conditions: This issue occurs when a service-policy is configured before configuring xconnect on the router that has consumed close to max labels.

Workaround: First configure xconnect and then configure service-policy

- CSCuf93174
Symptom: Packet Over SONET (POS) interfaces counters do not display correctly.
Conditions: This issue occurs after SSO is performed. The issue is observed on the standby router.
Workaround: There is no workaround.
- CSCug05647
Symptom: Interface counters not getting updated with IP traffic.
Conditions: This issue occurs when pinging back to back connected interfaces; the interface counters stay at 0.
Workaround: Reload the device.
- CSCug07795
Symptom: NQATM errors seen while adding new entries to ACL control region.
Conditions: This issue occurs on bootup. The last 2 ACL control entries fail to get programmed.
Workaround: There is no workaround.
- CSCug10134
Symptom: Traffic is not flooded on port-channel by default, as IGMP does not support port-channel traffic.
Conditions: This issue occurs when the incoming port is a Layer3 and outgoing is port is a BDI.
Workaround: There is no workaround.
- CSCug16244
Symptom: Traffic will not flow through few EoMPLS VCs.
Conditions: This issue is seen with scaled EoMPLS configurations.
Workaround: There is no workaround.
- CSCug22122
Symptom: IOMD crash is seen for any IM on the router.
Conditions: The IOMD crash is seen when **show platform software agent iomd 0/1 driver stats** command is executed to verify driver statistics.
Workaround: There is no workaround.
- CSCug23372
Symptom: Manager process crash occurs while configuration replace operation is performed.
Conditions: This issue occurs while moving from REP to G8032.
Workaround: Avoid performing a configuration replace.
- CSCug26991
Symptom: OSPF session goes down after applying the policy on EC main interface, EC EVC and EC Trunk EFP.
Conditions: This issue occurs after applying the policy EC main interface which has OSPF session enabled. The OSPF session goes down after application of Egress policy.
Workaround: Apply policy directly on EC member links.
- CSCug40852
Symptom: Link failure in L3VPN core takes a long time to converge with BGP PIC configuration.

- Conditions:** This issue occurs when BGP PIC core and PIC edge is configured and there are more than one ECMP core paths to reach backup BGP peer.
- Workaround:** Configure only one core path to reach both primary and repair BGP Peers in a BGP PIC Core and Edge configuration. If there are more than one equal cost physical paths to reach BGP peers, then adjust the configuration by increasing the distance for all paths except one.
- CSCug44908

Symptom: Traffic goes down after applying policy-map without ingress classification.

Conditions: This issue occurs when without classifying the traffic in the Ingress, this policy map is applied in the egress port.

Workaround: Edit the policy map by changing the bandwidth percentage number.
 - CSCug45557

Symptom: Ingress marking does not work when Egress marking has a match on qos-group.

Conditions: This issue occurs when ingress marking is not working when Egress marking matches on qos-group.

Workaround: There is no workaround.
 - CSCug45618

Symptom: OSPF does not come up with policy map having 2 different EFP classes and configured on 2 different interfaces.

Conditions: This issue is observed only when same policy map is applied on 2 interfaces with one EFP in the policy map.

Workaround: Remove the policy map from one of the interfaces to bring up the OSPF.
 - CSCug46010

Symptom: The non IP packets get classified under the second class instead of class-default when two class-maps one having match on L4 ACL and other having match on L3 ACL with permit ip any any is configured.

Conditions: This issue occurs when two class-maps one matching on L3 ACL match and another matching on TCP or UDP are configured.

Workaround: There is no workaround.
 - CSCug46157

Symptom: When an existing policer is deleted and added back, the policer fails to take effect.

Conditions: This issue occurs when the policing was dynamically deleted and added.

Workaround: Remove the policy-map and re-apply on the interface or EFP.
 - CSCug57503

Symptom: ESP crash observed on the router.

Conditions: This issue occurs after executing the **show platform hardware qfp** command on the active feature packet-trace configuration.

Workaround: Do not execute unsupported command.
 - CSCug61357

Symptom: The ISIS router fails to come up after issuing a **shutdown** followed by a **no shutdown** command.

Conditions: This issue occurs when RLFA and BFD configurations exist on the router.

Workaround: Issue a **shutdown** followed by a **no shutdown** command again.

- CSCug61508

Symptom: Classification based on ACL in the child does not work

Conditions: This issue occurs when the parent classification is EFP.

Workaround: There is no workaround.
- CSCuf65301

Symptom: Micro flaps observed on the router.

Conditions: This issue is seen when system is kept idle for hours.

Workaround: There is no workaround.
- CSCug67955

Symptom: The standby FP is stuck in init state.

Conditions: This issue occurs after ISSU is performed.

Workaround: There is no workaround.
- CSCug71853

Symptom: BFD flaps are observed on the router.

Conditions: This issue is seen when traffic flows at line rate.

Workaround: Keep traffic at around 90% line rate.
- CSCug72785

Symptom: OSPF flap observed on the router.

Conditions: This issue occurs after IM OIR followed by SSO.

Workaround: There is no workaround.
- CSCug73776

Symptom: The standby router crashes on bootup when highly scaled configurations and when L2VPN and multicast are configured.

Conditions: This issue occurs on reloading the router 3-4 times with highly scaled configurations and L2VPN and multicast are configured.

Workaround: There is no workaround.
- CSCuh18073

Symptom: In a domain with 2 BGP exit points acting in Active or Repair mode, traffic would be exiting the domain through Repair path BGP PE instead of exiting through Active path BGP PE.

Conditions: This issue occurs in the following conditions:

 - Environment has 2 BGP exit points
 - A change in one of the core links to the primary BGP exit point results in Repair BGP PE becoming Active BGP PE and vice versa

In this scenario, even after BGP convergence, data packets would traverse through previous primary BGP PE(now repair path PE).

Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.9(0)S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 Router in Cisco IOS XE Release 3.9(0)S.

- CSCud06772

Symptom: IPv6 neighbor discovery does not function properly after stateful switchover (SSO); the router loses traffic and eventually recovers.

Conditions: Occurs with IPv6 traffic after stateful switchover (SSO).

Workaround: Configure software BFD sessions.

- CSCud29491

Symptoms: Simultaneous policy can be applied

Conditions: On physical interface (having efps) and on efps (on that physical interface)

Workaround: None. As it is an unsupported config.

- CSCud35732

Symptoms: The router does not apply egress CFM MIP filtering.

Conditions: Occurs when you overwrite a MIP configuration using the **ethernet cfm mip level** command.

Workaround: Instead of overwriting the MIP level configuration, remove and re-apply the configuration.

- CSCue34781

Symptoms: The policer in the parent policy-map of an hqos policy attached to an interface stops working after the child policy policer is dynamically modified.

Conditions: Occurs when the policy-map attached to the interface is a hierarchical policing policy and both the child and parent policy-map have policing actions in their classes. The policing in the parent class does not work correctly after you dynamically modify the policing action in the child policy.

Workaround: Remove and re-attach the policy-map on the interface

- CSCue41416

Symptoms: IOMD CPUHOG messages seen on ASR903

Conditions: Seen when ISSU upgrade is performed between two XE39 images

Workaround: None

- CSCue42139

Symptoms: The ptp state is stuck in acquiring state all the time.

Conditions: When pulled out the active RSP, the T3 time-stamping is stuck and the ptp state stays in acquiring state all the time.

Workaround: Reload the IM or unconfigure or configure the ptp.

- CSCue46274

Symptoms:

Traffic flow stops over a particular prefix configured on TDM interface and Crash while executing show platform prefix command for the same prefix

Conditions: Configure route via a TDM interface and reload the router once.

Workaround: No workaround

Further Problem Description: With only Gigabit Ethernet interfaces this problem is not seen. Only when we have TDM interface we see the problem.

- CSCue63229

Symptoms: IMA interfaces flap frequently every 15–30 minutes. The issue does not occur on member links.

Conditions: Occurs when you increase the number of member links in the IMA group to 16.

Workaround: There is no workaround.

- CSCue65149

Symptoms: When changing the interval in evc bd offload cases(scale) getting OBJ messages.

Conditions: First configure the 3.3ms interval and meps after that removed the meps,domain and configure 10ms interval and meps will hit this issue.

Workaround: Configure very less session

- CSCue66019

Symptoms: output errors will be seen on mlppp interfaces.

Conditions: With 90% and above Line rate traffic with mix MTU patterns (IMIX), output errors will be seen on the mlppp interface.

Workaround: No. The issue is seen for IMIX pattern traffic with 90% & above Line rate traffic.

- CSCue67245

Symptoms: MFIB counters for some of the (S,G) are not updated on ASR903

Conditions: Is seen when we scale the number of Sources. Issue is seen for 2000 sources joining 1 group. No impact to traffic

Workaround: There is no workaround.

- CSCue67267

Symptoms: High Traffic drop seen on SSO Double dip seen on SSO

Conditions: Issue is seen occasionally (one in 5 iterations) on ASR903 with MVPN scale setup.

Workaround: There is no workaround.

- CSCue67995

Symptoms: Nile manager crashes while flapping mpls enabled interface on the peer end nodes.

Conditions: 6K routes L3VPN routes and 600 L2VPN sessions with flaps can crash nile manager of ASR903 at uea_untyped_dqueue_remove_elem

Workaround: No workaround

- CSCue70575

Symptoms: Kernel crash is observed

Conditions: On reload kernel crash is seen

Workaround: There is no workaround.

- CSCue72481

Symptoms: IP address and Meps accepting in the same interface

Conditions: configured the IP address and Port mep accepting in the same interface.

- Workaround:** There is no workaround.
- CSCue75775

Symptoms: fman fp crash causes router to crash with scale of 16000 queues on rsp1b

Conditions: large scale qos configurations

Workaround: There is no workaround.
 - CSCue76109

Symptoms: DMM reports delay of 0ns.

Conditions: Have Y1731 DMM sessions with CFMoXconnect and MPLS TE tunnels in the core.

Workaround: No Workaround. Having a single path between the 2 MEPs can avoid this.
 - CSCue77596

Symptoms: cos vlaue gets wrongly marked for a qinq packet

Conditions: a service instance with dot1q encap and no rewrite is configured on the interface... the policy map attached in the ingress has marking in it... the packet should not be ,marked in this case... but on asr903 its getting marked wrongly

Workaround: There is no workaround.
 - CSCue86047

Symptoms: Pkts Not Classified On Removing/Re-applying Marking action dynamically

Conditions: A class-default policy with marking action is applied and nn removing/re-applying exp marking action of the class-default, packets are not hitting the class-default and policy-map counters do not increment. This issue is seen on any type of interface.

Workaround: Instead of removing & adding marking action alone, detach the policy itself from the interface, modify the marking action and re-attach the policy to the interface.
 - CSCue87175

Symptoms: BFD sessions may flap on an ASR903 router.

Conditions: With around 2000 global IPv4 prefixes and with traffic running, when a core-facing interface is shutdown on a router in the ring, BFD flaps may be seen on another router in the ring.

Workaround: There is no work-around known as yet.
 - CSCue87629

Symptoms: INFRA-6-PROCPATH_CLIENT_HOG: IOS shim client 'iosd-nile' messages may appear on the console. **Conditions:** When a shut/no shut of G8032 ring interface of Peer or local device is done.

Workaround: No workaround.
 - CSCue90720

Symptoms: IPCP state mismatch and member link state mismatch in ppp multilink on back to back to connection. Traffic will get dropped

Conditions: Bundle having maximum links in it and perform a SSO. find steps to repro

Workaround: none
 - CSCue96512

Symptoms: RP crashes if punt/inject keepalives are missed.

- Conditions:** Punt/inject keepalives are missed and we are not holding a TTY while writing to punt/inject log file.
- Workaround:** none
- CSCue96886

Symptoms: Complete MAC Address space is not available on the RSP

Conditions: Removing the Service instance with the MAC Addresses learnt on the BD.

Workaround: Reload the Router is only workaround.
 - CSCue97114

Symptoms: Shut down the trunk efp in core side, meps are learnt for UP MEP

Conditions: Configured UP Mep evc bd (core side trunk efp) when i shut the trunk efp in core remote meps are learnt for UP MEP.

Workaround: Configure evc bd in core side
 - CSCuf05090

Symptoms: Standby will be resetting continuously with running config sync failure.

Conditions:

Downgrade all IMs and take the IMS out of slot.After booting up with XE39 image , insert IMs one by one. While upgrade was happening , this issue happened.Im got crashed and stanby was resetting continuously with SYNc failed.

Workaround: Reload the box completely.
 - CSCuf20275

Symptoms: On interoperating with an ASR901 router, BFD sessions may flap as the ASR903 router may some times not send BFD control messages.

Conditions: With around 200 global IPv4 prefixes, BFD session running in software with echo OFF and seen even without any data traffic.

Workaround: There is no work-around known as yet.
 - CSCuf44077

Symptoms: show interface output is showing wrong speed values after sso

Conditions: when we use the 100M SFP's

Workaround: There is no functionality impact because of this. HW module reset will resolve this.
 - CSCuf56723

Symptoms: Interface LED glows green with shut.

Conditions: After SSO

Workaround: No workaround.
 - CSCuf60346

Symptoms: IOMd Crash On Performing SSO Switchover With Interfaces Shut

Conditions: Have ATM/IMA interfaces shut. Perform switchover and notice IOMd crash on new Active

Workaround: No workaround
 - CSCuf64404

Symptoms: IOMD crash will be seen when flap is performed on remote router. The flap can be by shut/no shut or IM oir.

Conditions: IOMD crash seen on multiple mlp bundle flap becoz of memory leaks in wintegra.

Workaround: None.

- CSCuf64625

Symptoms: CRC Errors reported on RevD IM

Conditions: IM OIR or SSO

Workaround: No workaround.

- CSCuf64695

Symptoms: Error message seen on PE ASR903 :- *Mar 22 11:51:35.929 IST:
%FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: SIP1: fman_fp_image: atom_xconnect xid
0x1004013, ifh 16793619, dirty 0x1, state 0x2 download to CPP failed

Conditions: CEM configs on OC3IM and/or T1E1IM. Reported with CESOP circuits and scale of about 88. Seen with less scale also. Seems to be a non-function impacting message.

Workaround: None.

- CSCuf64811

Symptoms: Serial Links on CEs are in up/down state, when configured with CEM CeSop circuits on PEs.

Conditions: Configure CEM cesop circuits over MPLS core. Note that the serial interfaces on CE routers are UP/UP. Perform a SSO on PE2 router.

Workaround: Perform another SSO on PE2 router and issue is solved.

- CSCuf65012

Symptoms: Seeing syslog for the port 0/5/0 saying it is down which is used for HFPGA

Conditions: IM oir of Slot 4 or Slot 5

Workaround: No Functionality impact and no workaround.

- CSCuf74072

Symptoms: Seeing CRC errors on SFP IM with CU SFP.

Conditions: When the CU SFP is configured with 100Mbps speed.

Workaround: No workaround.

Resolved Caveats—Cisco IOS XE Release 3.9(0)S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.9(0)S.

- CSCts14725

Symptoms: mep does not come up sometimes, error messages always.

Conditions: change cc interval on the fly.

Workaround: None.

- CSCts95896

Symptoms: The router stops passing traffic on EVC interfaces.

Conditions: Occurs when you issue the default interface command and immediately restore the configuration. The issue occurs with configurations containing either a large number of EFPs or features that impact EFP programming at a lesser scale, such as QoS.

Workaround: Wait for the router to clear the old EFP configuration before adding a new configuration.

- CSCtu39377

Symptoms: "sh running" , "sh romvar" in exec mode and "set" command in rommon mode, displays multiple entries for the license being used.

Conditions: ASr903 with appropriate license and boot level set.

Workaround: No workaround.

- CSCtx44513

Symptoms: The router stops passing traffic on an interface

Conditions: Occurs when you remove all classes from a QoS policy-map attached to an interface.

Workaround: Remove and re-attach the policy-map.

- CSCtx44688

Symptoms: Cannot configure policing and marking together in the same class of the egress policy-map.

Conditions: Set and police statements together in the same class of a policy is rejected at the CLI.

Workaround: In order to achieve marking and policing at the ingress we can use a conditional policer but this is not supported at the egress.

- CSCtx70302

Symptoms: Traceback and Log message seen on performing a multilink bundle shut on ASR903 as described in the summary.

Conditions: Traffic should be flowing over the multilink bundle. Multiple ways to trigger the same issue, but traffic and mlppp bundle remain common to each scenario.

Workaround: None. Harmless traceback.

- CSCty73682

Symptoms: A small percentage of IPv6 packets that should be blocked by an interface ACL is instead pass through

Conditions: In certain conditions, when an IPv6 ACL is applied to an interface, a small percentage of IPv6 packets that would otherwise be dropped, will instead bypass an ACL and get through.

Workaround: None

PSIRT Evaluation: The Cisco PSIRT has assigned this bug the following CVSS version 2 score. The Base and Temporal CVSS scores as of the time of evaluation are 5/4.8:

<https://intellishield.cisco.com/security/alertmanager/cvssCalculator.do?dispatch=1&version=2&vector=AV:N/AC:L/Au:N/C:P/I:N/A:N/E:F/RL:U/RC:C> CVE ID CVE-2012-3946 has been assigned to document this issue. Additional information on Cisco's security vulnerability policy can be found at the following URL:

http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html

- CSCtz20839

Symptoms: IMA functionality does not work properly.

Conditions: Occurs after an RSP switchover when the router is running an IMA configuration.

- Workaround:** Reload the interface module with the IMA configuration.
- CSCtz43467

Symptoms: Not All CLI's listed under the REP configuration modes are allowed. For e.g The following configurations are allowed but will not work. 1) REP does not work on BDI. 2) More than 1 source ports in a span session.

Conditions: Seen all the time.

Workaround: No workaround
 - CSCtz65778

Symptom: The control plane goes down with VPNv6 traffic.

Conditions: Occurs with 64-byte VPNv6 traffic. The issue only occurs for small, tunnelled packets.

Workaround: There is no workaround.
 - CSCtz87775

Symptoms: An interface on the OC-3 interface module does not become active.

Conditions: Occurs when you change the interface mapping between au-4 and au-3 when changing an interface between T1 and E1 operation.

Workaround: Perform a soft OIR on the interface module.
 - CSCua16492

Symptoms: Some IPv6 multi-hop BFD over BGP sessions flap.

Conditions: Occurs on port-channel interfaces running IPv6 multi-hop BFD over BGP sessions after you perform an SSO.

Workaround: There is no workaround.
 - CSCua35446

Symptoms: gig 0/5/0 interface displayed in PRIME software.

Conditions: System being up.

Workaround: No workaround.
 - CSCua37816

Symptoms: "DHCP_SNOOP: Failed sending packet out of BD" errors on standby.

Conditions: DHCP snooping enabled with asr903 as relay with HA system.

Workaround: No workaround. Wont be seen on standalone system.
 - CSCua46443

Symptoms: Y1731 frames were received and forwarded by STP blocked port and hence database is corrupted.

Conditions: When 2 or more interfaces are there b/n the devices and only one is forwarding and remaining blocked by STP.

Workaround: None.
 - CSCua49623

Symptoms: CEM interface becomes inaccessible

Conditions: When same channel-group number and cem-group number is used for overlapping timeslots this issue is hit

Workaround: Use different timeslots, or make sure channel-group and cem-group numbers are different under the same controller

- CSCua57325

Symptom: The router displays an OIR SPA error.

Conditions: Occurs under the following conditions:

- The router is running offloaded CFM sessions over an xconnect (pseudowire) interface.
- The router is using a redundant hardware (dual RSP) configuration.
- The remote router is using a non-redundant (single RSP) hardware configuration.
- You reload the router.
- **Workaround:** There is no workaround.

- CSCua61934

Symptoms: When policy-map with priority in class-default is attached to interface its not getting rejected.

Conditions: Configure policy-map having priority in class-default. Attach the policy to interface it's not getting rejected.

- **Workaround:** None known at this time

- CSCua77688

Symptom: The router experiences remote CFM MEP flapping.

Conditions: Occurs when the router is connected via a CFM xconnect and the link is running a high traffic rate.

Workaround: Reduce the rate of traffic.

- CSCua90879

Symptom: QoS policies with a police statement on the class-default class do not take effect.

Conditions: Occurs when you apply a police statement to the class-default class within a QoS policy on an ingress EVC interface.

Workaround: Apply the police statement to a static class, such as class cos0.

- CSCub18160

Symptom: The router drops traffic on a link twice and displays a remote fault error message.

Conditions: Occurs when you issue an interface module reset (OIR) while the 10.000M XFP (DWDM Edge performance) or XFP10GER-192IR-L XFPs are plugged into the ten Gigabit Ethernet interface module and active.

Reloading the router also takes significantly longer when using these XFPs.

Workaround: There is no workaround.

- CSCub26877

Symptoms: When Bridge-domain of the efp is changed and the new bridge-domain is not accepted, the old bridge-domain gets rejected.

Conditions: EVC -BD configuration change.

Workaround: None

- CSCub33576

Symptoms: All IMA interfaces does not come up until OIR of IM.

- Conditions:** When IMA are configured.

Workaround: OIR.
- CSCub33664

Symptoms: High Delay values seen when using DMM Session on ASR903 post SSO.

Conditions: Delay values will be higher only after SSO on ASR903.

Workaround: Remove and reconfigure DMM sessions again post SSO on AR903.
- CSCub38619

Symptoms: System crashes when COS value for vlan under an EFP is modified.

Conditions: This happens only when a prior operator attempt to modify the COS value failed. This failure can be due to incompatible efp match conditions on the egress efp.

Workaround: None
- CSCub41772

Symptom: Router console is flooded with CPUHOG and EVENTLIB messages.

Conditions: The issue occurs rarely when you issue multiple interface module reset (OIRs), RSP switchovers (SSO), or reloads while using a configuration with a high number of T1 serial links on the OC-3 interface module.

Workaround: There is no workaround; however, the messages do not affect router functionality.
- CSCub48129

Symptoms: CFM CCM's were being sent out on egress interface with cfm disabled.

Conditions: Configure UP mep on EVC BD. Disable cfm on the egress interface.

Workaround: There is no workaround.
- CSCub49985

Symptoms: MPLS pseudowire ping from the peer to the Cisco ASR 903 fails if the peer is using TTL-based ping.

Conditions: This symptom occurs when the peer is using TTL-based ping.

Workaround: There is no workaround.
- CSCub50110

Symptoms: Tx timer table not programmed after shut/no shut for hardware offload BFD. It is not consistently seen.

Conditions: The issue is seen while we do shut/no shut on BDI/Physical interface which has BFD configured.

Workaround: None.
- CSCub50487

Symptoms: The router accepts a rewrite push statement on an EFP configured with QinQ encapsulation.

Conditions: Occurs when you configure an xconnect EFP with QinQ encapsulation and a rewrite push statement.

Workaround: There is no workaround.
- CSCub52571

Symptoms: Traceback seen on console. This traceback doesn't impact any functionality

Conditions: Traceback seen when BFD is enabled and flapped the interface where IPv6 BGP/OSPFv3/BFD is already UP.

Workaround: No Workaround. This ddt fixes the traceback occurrence.

- CSCub52657

Symptoms: CPP object download failure messages are seen while creating BDI interface.

Conditions: The problem is seen when the user tries to configure the BDI interfaces exceeding the platform limit. On asr903 RSP1A and RSP1B the maximum BDI interface limit is 256 and 1024 respectively. When user tries to exceed this limit the error message is seen as download failure on the console, this is not a bug.

Workaround: Not to exceed the BDI interface limit set for the platform

- CSCub55760

Symptom: The router displays a Delay Measurement Message (DMM) delay value of 0.

Conditions: Occurs under the following conditions:

- You configure an EVC down MEP on a port-channel interface.
- You dynamically add a member link to a port-channel interface.

Workaround: Configure PTP synchronization before scheduling DMM.

- CSCub59776

Symptoms: Router seems hang post removal of startup-config and reload

Conditions: Router has no startup config present.

Workaround: The following dialogue was missing to appear on the console.

--- System Configuration Dialog ---

Would you like to enter the initial configuration dialog? [yes/no]: % Please answer 'yes' or 'no'.

Just type no, and start the configuration dialogue later.

- CSCub60668

Symptom: The router is unable to establish an OSPF session.

Conditions: Occurs when you enable an OSPF session over an MPLS TP tunnel.

Workaround: There is no workaround.

- CSCub63072

Symptom: MPLS convergence can be slower than expected.

Conditions: Occurs when the router switches to a backup MPLS path in the event of a network failure.

Workaround: You can configure the following redundancy features to protect against network failures:

- IPv4 Loop Free Alternate Fast Reroute (LFA FRR)
- Border Gateway Protocol (BGP) Prefix-Independent Convergence (PIC)
- MPLS Traffic Engineering (TE)--Fast Reroute (FRR) Link and Node Protection

- CSCub63954

Symptoms: Speed configurations are rejected. Error message appears on active

Conditions: HA - Box. Speed configurations are rejected

- Workaround:** No Workaround.
- CSCub71578

Symptoms: The router displays traceback and failure messages on the standby RSP.

Conditions: Occurs after you issue an OIR on the T1/E1 interface module from the active RSP. The issue occurs in a redundant system.

Workaround: There is no workaround.
 - CSCub74338

Symptoms: The router crashes.

Conditions: Occurs when you attach an ingress QoS policy-map to an EVC with a rewrite push configuration.

Workaround: There is no workaround.
 - CSCub76908

Symptoms: If Y1731(DMM or SLM) sessions are configured for UP MEP, where the core facing and access interfaces have different encaps, then Y1731 sessions will not come up

Conditions: The condition will be same if the encaps are same and if rewrite ingress pop is configured

Workaround: None
 - CSCub80685

Symptoms: On BDI Shut, if routing traffic continues, it will be punted to the CPU which will flood out the CPU resulting in control plane loss

Conditions: Ping failure and BFD/OSPF flaps on BDI shut while ipv4/v6 traffic is running while BDI is shut.

Similar conditions occur on no EFP/BDI configured or no ip address configured.

Workaround: Stop routing traffic into shut BDI port.
 - CSCub84828

Symptoms: Iosd crash on standby when booting up

Conditions: Boot up of standby

Workaround: RSP has to be booted again.
 - CSCub85398

Symptoms: On customer's setup the following error message is seen. Dec 2 15:41:40.970 JST: %NILE_ASIC-2-TCAM_PARITY_ARRAY_ERR: TCAM4 Parity Array Error at Asic: 1 TCAM Index: 0x306D Application: UCASTV4 Region UCAST_32.

Conditions: No specific condition. There are no any operation or network events at that time.

Workaround: On reloading the box the message is disappeared.
 - CSCub88805

Symptoms: When alarms are seen it displays as ASR1000 instead of ASR903, no functionality impact, only display issue.

Conditions: On seeing alarms.

Workaround: None.
 - CSCub88822

Symptoms: NULL_DATA_STRUCTURE traceback is seen on ASR903 console.

Conditions: Issue is seen when OC3IM is present on the box and IM OIR is done on this OC3IM. Usually seen when no configs are present on IM. Quite inconsistent, not always seen.

Workaround: None. The traceback does not affect any functionality.

- CSCuc00853

Symptoms: ARP requests are not flooded on bridge-domains

Conditions: Dynamic ARP inspection configured on bridge-domains

Workaround: None

- CSCuc07697

Symptoms: BIT-4-OUTOFRANGE: tracebacks flooded on the console.

Conditions: Configure CFMoTEFP and vlan load-balancing for the BDs part of REP segment. Tracebacks are seen only when there is an untagged efp on the interface and there is an AIS condition.

Workaround: Do not have BD with untagged EFP on the box.

- CSCuc07747

Symptoms: On entering "show debugging" command on ios prompt, the following extraneous messages are seen,

% Invalid input detected at '^' marker.

Conditions: Seen in all conditions.

Workaround: No workaround. Though this doesn't have any functionality impact. Only issue is the extra prints.

- CSCuc07759

Symptoms: ARP responses are dropped

Conditions: Dynamic arp inspection is configured on the router

Workaround: None

- CSCuc08098

Symptoms: Trap config for AAA-SERVER mib is missing.

Conditions: When a asr903 device is loaded with metroaggrservices license.

Workaround: None.

- CSCuc12681

Symptoms: Intermittent packet drops when doing MPLS ping

Conditions: MPLS ping Rate has to exceed 1Mbps. sweep ping with high range High number of frames with huge pkt size

This is not applicable to IP icmp ping. Only applicable for MPLS ping.

Workaround: Try a lower number of frames.

- CSCuc21610

Symptoms: The console displays a message indicating that offloading is not supported for BFD echo mode.

Conditions: Occurs when you configure a BFD session in echo mode.

Workaround: There is no workaround; however, the issue has no functionality impact.

- CSCuc25058

Symptoms: Forced QL value on BITS port gets overwritten when a new primary clock source with different QL value is selected.

Conditions:

Network clocking should be enabled in QL mode and with BITS port configured to output system clock with forced QL value.

Workaround: Reconfigured the forced Tx QL value on the BITS port after the system switches to clock source with different QL value than the current selected.

Further Problem Description: When the system selects a new primary clock source, it propagates the QL value of that primary clock source on all the timing ports, so that all timing ports reflect the system QL value. When this update is send the forced TX QL value configured on each port gets overwritten by the system QL Value.
- CSCuc34088

Symptom: The router passes lower traffic levels when you add links to an IMA bundle and perform IM OIR/router reload.

Conditions: Occurs when you send traffic above the E1 line rate on one link within an IMA bundle and reset (OIR) the interface module.

Workaround: Remove and re-apply the IMA interface configuration.
- CSCuc35618

Symptoms: REP session flaps post SSO and traffic is dropped until the session re-converges after the SSO.

Conditions: Upon SSO.

Workaround: None
- CSCuc36241

Symptoms: The router is unable to select a given PTP clock as a network clock source.

Conditions: Occurs when you configure PTP as an input network clock source while the slave clock is still in a holdover state. In the holdover state, the slave clock has not yet attempted to establish a frequency lock with a master clock.

Workaround: Wait for the PTP slave clock to lock to the master clock before configuring PTP as a network clock input source.
- CSCuc36381

Symptoms: CLI show satellite env and show satellite alarm not displaying any output.

Conditions: Show satellite env and show satellite alarm CLI is not supported in satellite mode in 4.3.0

Workaround: Can check the status in ASR9k.
- CSCuc41871

Symptoms: ATM interfaces stay down during normal operations

Conditions: 1. Post router reload 2. When peer interface cable is pulled out & put back

Workaround: Interface reset (shut/no shut)
- CSCuc42002

Symptoms: The router crashes when configuring the ATM interface, displaying a segmentation fault error.

Conditions: This symptom is observed when you move an OC-3 interface module with an ATM configuration to a different bay and configure an ATM interface on the new bay.

Workaround: There is no workaround.

- CSCuc42117

Symptoms: The router does not include 0xff03 flag leading bits within ppp fragment messages.

Conditions: Occurs when the router has not negotiated ACFC.

Workaround: There is no workaround. Most remote devices should ignore this behavior by design, but some devices may display unexpected behavior, such as for IPCP PROTREJ messages.

- CSCuc43719

Symptoms: ASR903 with dual RSP may crash.

Conditions: No specific trigger, but any configuration related to NBAR can make the box hit this issue.

Workaround: Do not have any NBAR configurations on the box as these are not supported on ASR903.

- CSCuc57130

Symptom: The router does not apply OC-3 interface module (IM) configurations.

Conditions: Occurs after an RSP switchover.

Workaround: There is no workaround.

- CSCuc59386

Symptoms: Continuous iomd crash on oc3im. Interfaces on oc3im not configurable, error message seen :- stand-by dosen't support this command

Conditions: Seen on a HA ASR903 setup with oc3im. Seen when a iomd crash happens on active rsp and then standby iomd session handle is not cleared.

Workaround: Reload the stand-by rsp.

- CSCuc60148

Symptoms: System is not shutting down upon temperature sensor reaching 'SHUTDOWN' threshold region.

Conditions: Temperature sensors reached shutdown threshold region

Workaround: IOS config command has to be explicitly configured to enable this system shutdown behavior. 'facility-alarm critical exceed-action shutdown'

- CSCuc62784

Symptoms: Traces @ nils_if_count_initialize some times

Conditions: On performing Reload, Standby Reload, SSO

Workaround: No workaround. And these traces are displayed on the console and does not have any functionality impact to the system.

- CSCuc64509

Symptom: ASR903 as PTP master transmits clock class corresponding to holdover state on fresh bootup.

Conditions: ASR903 is not connected to any external frequency and Phase source and is using freerun internal clock to provide synchronization.

Workaround: ASR903 PTP master should be locked to external frequency and phase source.

Further Problem Description: ASR903 when locked to internal free-running clock, then ASR903 PTP master function transmits clockclass value 14 which corresponds to holdover state instead of 58 which corresponds to free-running clock.

- CSCuc64899

Symptom: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: Occurs on interfaces with an xconnect statement after a reload on a peer device.

Workaround: Remove and re-apply the CFM configuration.

- CSCuc66393

Symptom: The router loses OC-3 interface configurations after an ISSU upgrade.

Conditions: Occurs on OC-3 serial and POS interfaces after an ISSU software upgrade.

Workaround: There is no workaround.

- CSCuc66895

Symptom: Layer 2 traffic loop seen in REP topology for a transient time, when the Cisco ASR 903 which is a part of the REP ring is reloaded.

Conditions: This symptom is observed when the Cisco ASR 903 is part of an REP ring, and the box is reloaded with saved REP configurations.

Workaround: Traffic loop is transient, once REP convergence looping is stopped.

- CSCuc68246

Symptom: The standby IOMD crashes on booting up the standby RSP.

Conditions: This symptom occurs when booting up the standby RSP with a configuration that is already present.

Workaround: Boot up the standby without any configurations and start configuration once the standby has reached STANDBY_HOT state.

- CSCuc68462

Symptom: The router drops PTP traffic.

Conditions: The issue occurs occasionally when you configure PTP slave clock to receive VLAN-tagged traffic.

Workaround: There is no workaround.

- CSCuc70509

Symptom: Packet rate counters i.e. packets per second is not cleared to 0 when interface goes down.

Conditions: Applies to all TDM interfaces like serial , mlppp , POS , etc. Issue seen on controller shut etc, not seen on interface shut.

Workaround: None. Should be fixed now.

- CSCuc71410

Symptoms: Config sync failure but it doesn't have much of an impact on the service

Conditions: We have a mac limit configured with action as limit and when the configured limit is exceeded, the standby comes up after the limit is hit

Workaround: none

- CSCuc71723

Symptom: The router erroneously accepts a service-policy configuration on a CEM interface and displays it within the running configuration.

Conditions: Occurs when you configure a service-policy on a CEM interface.

Workaround: There is no workaround.
- CSCuc74205

Symptoms: Tracebacks displayed continuously on performing IM OIR

Conditions: Have CEM, ATM, IMA configured on a TDM IM. Now, on performing IM OIR, notice this traceback continuously on active RSP. This is noticed on performing OIR operation every 2 out of 5 times.

Workaround: No workaround
- CSCuc81334

Symptom: The router selects a clock source attached to standby RSP.

Conditions: Occurs after a stateful switchover (SSO).

Workaround: Remove and restore the clock source configuration.
- CSCuc81416

Symptoms: Traces may be seen on active with SNMP configuration

Conditions: Seen when Hard pull of Standby is done

Workaround: Do soft reset/ sso switchover
- CSCuc83088

Symptom: The router drops traffic during stateful switchover (SSO).

Conditions: Occurs when the router is running HSRP or VRRP; the issue only occurs when the destination MAC address is a virtual MAC (vMAC) address.

Workaround: Change the traffic priority and detour traffic prior to the SSO.
- CSCuc87791

Symptom: The router selects a network clock source before the wait-to-restore timer has expired.

Conditions: Occurs under the following conditions:

 - A clock source fails, triggering the wait-to-restore timer (which specifies how long the before including a restored clock source in the clock selection process.
 - The clock source becomes active and fails a second time before the wait-to-restore time has passed.

Workaround: There is no workaround; in some cases you can clear the issue by removing and restoring the clock source configuration.
- CSCuc91582

Symptom: Adding EFP to Bridge-Domain fails and errors are seen when reloading with Cisco IOS XE Release 3.7.1a.

Conditions: This symptom is observed when reloading the Cisco ASR 903 with Cisco IOS XE Release 3.7.1a, when EFP and PW are in the same Bridge-Domain.

Workaround: Post reload, remove the EFP configurations, and configure PW first and then EFP.

- CSCuc92953

Symptom: The RSP crashes.

Conditions: Occurs under the following conditions:

- You configure Protocol-Independent Multicast-Sparse Mode (PIM-SM) with a static rendezvous point (RP).
- You create an EVC port channel on the access side with one member link
- You create bridge domain interfaces (BDIs) with 1:1 mapping between EVCs and bridge-domains.
- You use the BDIs to send IGMP v2 static join messages to a single multicast group
- On the remote device, you create 150 EFPs and map them to the BDIs.
- You initiate multicast traffic.
- You set the EFPs to the default configuration and add them to the existing port-channel

The router crashes.

Workaround: There is no workaround.

- CSCuc93985

Symptom: The router initiates an Automatic Protection Switching (APS) switchover during a high availability (HA) stateful switchover (SSO).

Conditions: Occurs during an HA SSO with single router APS (SR-APS).

Workaround: There is no workaround.

- CSCuc95716

Symptom: FPGA software for the OC-3 interface module is not bundled with the XE 3.8 image.

Conditions: Occurs when upgrading FPGA on the OC-3 interface module.

Workaround: Manually upgrade the OC-3 FPGA.

- CSCud01855

Symptoms: APS switchover may occasionally lead to inconsistent/incorrect APS states with CEM config.

Conditions: Seen when APS is configured with CEM/ATM on IM-4OS on ASR903. Caused due to notifications not being correctly sent to CEM subsystem.

Workaround: No workaround.

- CSCud01908

Symptom: Debug commands show pending objects on the Forwarding Manager (FMAN) on the forwarding processor (FP), indicating a failure to download configurations from the Route Switch Processor (RSP) to the data plane (DP).

Conditions: Occurs when you apply a QoS shaping configuration at a high scale.

Workaround: Delete the QoS policies and remove the QoS configuration from the interface.

- CSCud04407

Symptom: The router displays the following console error message: `Error - packet with unsupported linktype 3`

Conditions: Occurs when the router is passing traffic over the OC-3 interface module.

Workaround: There is no workaround.

- CSCud07085
Symptom: The serial interface on the OC-3 interface module remains in a down state.
Conditions: Occurs when you migrate from T1 mode to E1 mode using the OC-3 interface module.
Workaround: Issue an interface module reset (OIR) on the OC-3 interface module.
- CSCud07236
Symptoms: Upon reload few harmless messages will seen.
Conditions: Upon reload few harmless messages will seen.
Workaround: No impact on device.
- CSCud07642
Symptom: The ASR 903 is unable to pass traffic to the ASR 9000.
Conditions: Occurs with a clear-channel ATM over MPLS configuration using AAL0 encapsulation.
Workaround: Enable MPLS control-word on the ASR 9000.
- CSCud09813
Symptoms: Timestamping not happening in CFM over xconnect down mep/PC
Conditions: When we configured cfm over xconnect down mep/PC from Asr903-Me3600 timestamping not happening in ASR903.
Workaround: No workaround.
- CSCud22601
Symptom: MPLS-TP tunnels remain down after the standby RSP boots.
Conditions: Occurs when you boot the standby RSP after applying an MPLS-TP configuration and performing an SSO. The issue occurs rarely.
Workaround: Issue a shutdown/no shutdown on the MPLS-TP tunnel. A nonintrusive workaround is to cause a flap on the protect label switched path (LSP) by reconfiguring the path or physically shutting down and restoring the interface.
- CSCud23647
Symptom: BDI adjacency fails on the standby RSP.
Conditions: The issue can occur during an interface module (IM) reset or router reload.
Workaround: There is no workaround.
- CSCud25764
Symptoms: 903 part id to be populated in the discovery messages.
Conditions: Currently it is being displayed as "cisco, asr903" against Vendor in host by executing this CLI "show nv satellite protocol discovery interface Bundle-Ether1000". This must be displayed as cisco, ASR-903. This is mainly used by ASR9K ACT tool for rendering 903 graphic on Act tool.
Workaround: No workaround.
- CSCud26812
Symptom: The router CLI does not display some SFP PIDs
Conditions: Occurs when you install one of the following SFPs in the router:
 - ONS-SI-155-L2
 - ONS-SI-155-L1

- ONS-SI-155-I1

Workaround: There is no workaround.

- CSCud27333

Symptom: The router crashes continuously.

Conditions: Occurs when you issue an interface module reset (OIR) while the standby RSP is booting.

Workaround: Do not issue an interface module reset (OIR) while the standby RSP is booting.

- CSCud28982

Symptom: The router does not process egress CoS marking on an Ethernet service instance.

Conditions: Occurs when you configure QoS on an Ethernet service instance that is a member of a bridge-domain and uses dot1q encapsulation.

Workaround: There is no workaround.

- CSCud29479

Symptom: The router stops applying QoS configurations.

Conditions: Occurs under the following conditions:

- An Ethernet interface is configured with a single service instance
- A QoS policy is attached to the service instance
- The QoS policy contains a single class containing a **match efp** statement.
- You reset the interface to the default configuration.

Workaround: There is no workaround.

- CSCud30806

Symptoms: Policy with class map match-all with prec 1 and prec 2 is accepted for WRED.

Conditions: match-all should not accept 2 prec values class-map match-all prec1_2 match precedence 1 match precedence 2

Workaround: N/A

- CSCud33298

Symptom: The router crashes.

Conditions: Occurs when the peer device shuts down.

Workaround: There is no workaround.

- CSCud33906

Symptom: Equal Cost Multipath (ECMP) loopback does not function properly.

Conditions: Occurs when a port-channel link dynamically assigned as an ECMP path.

Workaround: There is no workaround.

- CSCud34346

Symptom: Nile manager crashes with the ECMP path when IPv4 scale is exceeded.

Conditions: This symptom occurs when scale is exceeded with the ECMP path.

Workaround: Do not allow the user to exceed the supported IPv4 route scale with ECMP.

- CSCud34600

Symptom: Receive a event hog msg when advertise 21k to 25 k routes into MBGP and export from a PE to other PE.

Conditions: When the redistributing routes from range of 21k to 25k customer routes from ospf into MBGP and export from a PE to other PE.

Workaround: No workaround as of now.

- CSCud35689

Symptoms: Queue-limit configuration at parent level of a policy or in a Vlan class/ port level is accepted. It should be rejected

Conditions: When configuring queue limit on policy at parent level or in vlan class/ port level.

Workaround: None

- CSCud36014

Symptoms: Multiple entries are seen in configs

Conditions: while configuring licence in bootlevel

Workaround: -none-

- CSCud37927

Symptoms: The router does not learn remote Connectivity Fault Management (CFM) Maintenance Endpoint (MEPs).

Conditions: If we have REP or STP on core with one port as ALT or BLK state.

Workaround: None.

- CSCud38038

Symptom: The router records incorrect delay measurements after a reload.

Conditions: Occurs under the following conditions:

- You configure Delay Measurement Message (DMM) on a port-channel interface.
- The port-channel member links are on different interface modules (IMs).
- You reload the router.

Workaround: You can use the following workarounds:

- Remove the **ethernet cfm global** command and re-apply it after the port-channel member links recover.
- Configure PTP clock synchronization.

- CSCud38115

Symptom: OSPF connections flap and drop traffic for approximately 20 seconds

Conditions: Occurs during stateful switchover (SSO).

Workaround: There is no workaround.

- CSCud38433

Symptom: The router is unable to establish MPLS neighborship or ping the destination loopback interface.

Conditions: Occurs when you configure two Equal Cost Multipath (ECMP) paths on a bridge domain interface (BDI) using static routes.

Workaround: The following workarounds exist:

- Use Interior Gateway Protocol (IGP) instead of static IP routes.

- Shut down one of the ECMP paths.
- CSCud38589

Symptoms: DMM Session Stops Working

Conditions: DMM configured on BD UP MEP, with redundant links on the Core side, which are in STP Fwding / Blocked state, Issue seen when the STP Fwd Port is shut.

Workaround: restart the IP SLA session or unshut the port and bring it FWD state
- CSCud38880

Symptoms: IPv6 traffic drop post SSO with MetroIP services license.

Conditions: 1. Start bidirectional IPv6 traffic on ASR903 with dual RSP and MetroIP services license, 3.7.1a. Put at least 3-4 streams each running at 10Mbps 2. Force switchover " redundancy force switchover" 3. IPv6 traffic will drop for 4-5 seconds. If you see drops in few milliseconds, then try adding more traffic. Issue is consistently recreatable.

Workaround: Upgrade the license to MetroAgg, add v6 static neighbor on the port facing test set and force switchover, now there will be no ipv6 traffic loss.
- CSCud41217

Symptoms: Multicast traffic dropped on 903.

Conditions: The following l2 configuration are there. There are 3 satellites connected in the setup, only 903 satellite interfaces are showed here. All interfaces are in the same bridge domain. When sent the mcast traffic from 2/4, it is expected that all the satellite interface would received the traffic. But the two 903 satellite interfaces didn't receive the traffic, the other interfaces from other satellite were fine.

```
2/4 -----gi0/3/0/11 PE1 gi400/0/2/1 -----3/2 gi400/0/3/1 -----7/4 ..... (901, 9000v satellite
interfaces are omitted)
```

2/4 sent (225.1.1.1, 192.10.1.1) at the rate of 2000 pps.

Workaround: No workaround.
- CSCud44768

Symptom: Multilink bundles and member links flap when passing traffic.

Conditions: Occurs under the following conditions:

 - You configure more than 210 MLPPP bundles with one member link per bundle or 16 bundles with 16 member links each.
 - The line is operating at a 64 or 128 byte line rate

Workaround: There is no workaround.
- CSCud48356

Symptoms: Nile Manager crash seen while configuring service instance

Conditions: After applying mpls tp config on back to back consoles

Workaround: There is no workaround.
- CSCud50944

Symptom: The router drops traffic on an MLPPP bundle.

Conditions: Occurs following a reload while the router is passing traffic close to the line rate. The issue occurs less frequently with lower traffic rates.

Workaround: Issue a **shutdown/no shutdown** on multilink interface.

- CSCud55377

Symptom: The router crashes.

Conditions: Occurs when you configure offloaded CFM for xconnect sessions at a high scale.

Workaround: There is no workaround.
- CSCud55695

Symptom: When you apply an QoS policy with a port level class-default configuration containing a shaper value to a serial interface, the router applies the shaper value to the channel-level PIR for all serial interfaces on the IM.

Conditions: Occurs when you apply QoS policy with a port level class-default configuration containing a shaper value to a serial interface.

Workaround: Add a dummy class-default level at the top of the policy and apply the shaper as a child policy of this class.
- CSCud55799

Symptoms: Multiple priority commands get accepted per policy

Conditions:

Have a policy-map with priority configured in one of its classes, add another class with policer first and then with priority, this policy must be rejected.

Workaround: none
- CSCud56262

Symptom: The router stops passing traffic on virtual circuits.

Conditions: Occurs an MPLS-TE/FRR configuration with L2VPN after you issue a stateful switchover (SSO).

Workaround: Reload the router.
- CSCud56364

Symptoms: Convergence time for POS links for rsp SSO is about 4-7 seconds.

Conditions: All 4 POS links must be created on OC3IM. Issue not seen on port 0 of OC3IM.

Workaround: None. Expected to be fixed.
- CSCud60410

Symptom: The router drops EFP traffic.

Conditions: Occurs when you add a new EFP to an existing bridge domain interface (BDI) while running L3 multicast.

Workaround: Issue a **shutdown/no shutdown** on the Ethernet interface and issue the **clear ip mroute** command.
- CSCud64034

Symptoms: Interfaces not coming up

Conditions: 1) Configure t1 interfaces 2) Verify ping & they are coming up 3) Perform SSO 4) Verify Ping again & traffic 5) Unconfigure t1 interfaces .6) Reload the standby 7) Configure t1 interfaces 8) T1 interfaces are not coming up

Workaround: IM OIR on box
- CSCud64129

Symptoms: Control-plane policing is not working on ASR903; despite CLI showing the options to do it: ASR903(config)#control-plane ASR903(config-cp)#service-policy ? input Assign policy-map to the input of an interface output Assign policy-map to the output of an interface

Conditions: Using traditional CoPP CLI to restrict CPU punted traffic

Workaround: This is not a supported feature on ASR903.

Further Problem Description: ASR903 has an implicit policer to protect different kinds of traffic destined to RP's CPU. By default, they are policed up to 1Mbps. This is tunable as well. For more details:

http://www.cisco.com/en/US/docs/ios-xml/ios/qos_plcshp/configuration/xe-3s/qos-plcshp-punt-policer-monitor.html This software defect is a means to get the unsupported CLI removed from the IOS-XE.

- CSCud64347

Symptom: The router creates a data loop when using a REP VLAN load balancing configuration.

Conditions: Occurs with a REP VLAN load balancing configuration when a bridge-domain is bound to a VPLS VC.

Workaround: None; remove the VLAN load balancing configuration.

- CSCud64436

Symptom: The router does not send the full line rate on POS interfaces.

Conditions: Occurs when you send traffic over a POS interface on the OC-3 interface module with a QoS configuration.

Workaround: There is no workaround.

- CSCud64923

Symptom: OSPF connections flap.

Conditions: Occurs when you configure OSPF between an EVC bridge domain interface (BDI) and a trunk EFP bridge domain interface (BDI) using a port-channel trunk.

Workaround: There is no workaround.

- CSCud65779

Symptom: The router does not update the Rx value for C2, J1, and S1S0 bytes.

Conditions: Occurs when you configure overhead bytes on OC-3 connections.

Workaround: There is no workaround.

- CSCud71286

Symptoms: Config Sync Failures seen with respect interface.

Conditions: when AutoNeg is disabled on the interface and configured with speed 100/1000

Workaround: There is no Functionality impact.No Workaround.

- CSCud71546

Symptom: The ten Gigabit Ethernet interface drops traffic for 7 seconds following a stateful switchover (SSO).

Conditions: Occurs when the configuration contains static routes to the destination.

Workaround: There is no workaround.

- CSCud74804
Symptoms: Building of rudy_satellite_super image failed. **Conditions:** While building rudy_satellite_super image, not able to find some subsystem and build failed. **Workaround:** No Workaround.
- CSCud76209
Symptom: The OC-3 interface module goes into an out of service state.
Conditions: Occurs when you repeatedly perform an interface module reset (OIR) on the OC-3 interface module.
Workaround: There is no workaround.
- CSCud76679
Symptom: The router displays a serial interface in the mroute table but does not forward traffic over the assigned interface.
Conditions: Occurs when you enable multicast traffic on the OC-3 interface module.
Workaround: There is no workaround.
- CSCud76770
Symptoms: Convergence time for FRR link/node protection is more than 2 seconds.
Conditions: NNHOP backup tunnels configured in a ring topology.
Workaround: No workaround.
- CSCud78168
Symptoms: Higher convergence (>5 seconds) is observed for 3107 label imposition prefixes.
Conditions: With 3107 label imposition configured.
Workaround: No workaround
- CSCud83069
Symptom: End-to-end traffic does not flow for ATM PVP Mode.
Conditions: Occurs when you enable ATM PVP Mode.
Workaround: There is no workaround.
- CSCud83698
Symptom: Links on the Gigabit Ethernet interface do not become active.
Conditions: Occurs on the Gigabit Ethernet interface when the local interface is configured for autonegotiation and the remote interface is configured for a speed of 10 Mbps or 100 Mbps.
Workaround: Toggle the auto-negotiation configuration on the Gigabit Ethernet interface.
- CSCud89451
Symptom: The router crashes with an error message showing nmpls_label_populate_flow_data.
Conditions: Occurs when you reset a core interface while the ASR 903 is acting as a PE router and running a configuration with L2VPN and L3VPN.
Workaround: There is no workaround.
- CSCud90362
Symptoms: PTP master (OC/BC) on ASR903, the SYNC packets might go out quite irregularly.
Conditions: This is seen with ASR903 is configured as PTP master.

- Workaround:** There is no workaround.
- Further Description:** This depends a lot on the slave and its tolerance levels with respect to SYNC packets reception and processing. With most of the vendors and Test tools it works today except few.
- CSCud90890

Symptoms: Routing over Trunk EFP over Port-channel doesn't work on member ports associated with Asic #1

Conditions: If a Trunk EFP on Port-channel has members on asic#1, routing traffic won't egress on those ports

Workaround: None
 - CSCud92915

Symptoms: Enable BFD support for IPFRR in 3.8.1

Conditions: BFD with IPFRR

Workaround: There is no workaround.
 - CSCud95359

Symptom: The show policy map command displays an incorrect number of total dropped packets (total drops).

Conditions: Occurs when you issue the show policy-map command to display dropped packets on an interface.

Workaround: There is no workaround.
 - CSCud96604

Symptoms: On system reset/reload, all traffic on certain EFPs will not egress

Conditions: Complete traffic stoppage on certain EFPs

Workaround: Delete and reconfigure EFPs
 - CSCud96962

Symptoms: After shut/noshut the mem link interface getting tracebacks - IM Flapping

Conditions: Configured cfm trunk efp pc -256 session -3.3ms interval after that shut/no shut the traffic sending interface will hit this issue

Workaround: Configure very less session 50-100 cfm session
 - CSCud98985

Symptoms: on executing show tech-support, invalid command errors were detected for a few commands

Conditions: on executing show tech-support, invalid command errors were detected for a few commands

Workaround: There is no workaround.
 - CSCud99183

Symptoms: Ctrl protocols stay down, pings fail on booting with scaled ACE/ACL, (ACL configurations are failing)

Conditions: it occurs only on reload time

Workaround: There is no workaround.
 - CSCue00049

Symptoms: classification not works properly with non-matching traffic when IP acl is used.

Conditions: This occurs only if we have classes based on acl match. only acl class will classify properly and other classes based on dscp or class-default wont work

Workaround: No known workaround

- CSCue00332

Symptom: BFD connections flap, bringing down IGP.

Conditions: Occurs when you enable BFD on an interface that is flapping.

Workaround: There is no workaround.

- CSCue01419

Symptoms: EIGRP neighborship is lost on OC3IM / OC12 IM interfaces configured on port 0.

Conditions: Seen only for interfaces which are configured on port 0 of OC3IM or OC12 IM. Not seen on ports 1,2 or 3.

Workaround: Perform a shut/no shut on interfaces configured on port 0. Alternatively remove EIGRP and configure again.

- CSCue01919

Symptoms: Enhancement to L2 protocol tunnelling feature to forward/drop more protocols and reserved mac addresses that are under IEEE wellknown mac address range (0180C2000002-0F) as a part of CE2.0 certification.

Conditions: This the L2 protocol tunnelling enhancement for CE2.0 certification.

Workaround: There is no workaround.

- CSCue03418

Symptoms: The router displays OSPF protocol flaps causing a 20–30 second traffic loss.

Conditions: The issue occurs very intermittently on a HA system with a 6 second dead-interval value when you issue the **redundancy force-switchover** command;

Workaround: Increase the dead-interval value.

- CSCue05962

Symptoms: Cos/Vlan Classification doesn't work on port channel member links

Conditions: Apply a Cos based Qos policy on port-channel member links. All the packets will start flowing through class default instead of getting classified on the interface. Look at the attached console logs for configs details.

Workaround: None

- CSCue07849

Symptoms: Link failure in L3VPN core takes a long time (in 10s of seconds) to converge even with BGP PIC enabled.

Conditions: BGP PIC core and PIC edge is configured and there are more than one ECMP core paths to reach backup BGP peer.

Workaround: Configure only one core path to reach both primary and repair BGP Peers in a BGP PIC Core + Edge configuration. If these are more than one equal cost physical paths to reach BGP peers, then adjust the configuration by increasing the distance for all paths except one.

Post fix caveat: With the fix for this issue, there are following limitations on the scale of prefixes:
 1. Global labeled BGP prefix scale: 3200
 2. VPN (with or without labeled-BGP nexthop) prefix scale: 4000
 3. Combination of Global labeled BGP and VPN prefix: less than 3200 depending on number of VPN and number of labeled BGP prefixes.

- CSCue11444

Symptoms: Split horizon configurations doesn't work on nile 1 with L2 multicast packets

Conditions: EFPs with split-horizon configured on nile 1 doesn't honor SH conditions (remain just using deja vu)

Workaround: shut/no shut. Configure EFP first before moving into split-horizon group.

- CSCue16617

Symptoms: QoS classification not working in core

Conditions: When Output policy applied to interface having the BDI as core interface.

Workaround: Enable "mpls ldp explicit null" on all the Routers.

- CSCue16828

Symptoms: b2b ping is not working - core side trunk efp PC with BDI

Conditions: when we have core side trunk efp pc with BDI and changed the port channel in core side b2b ping is not working.

Workaround: Don't change the PC in core side.

- CSCue17123

Symptoms: ATM/IMA Ping Fails From 2nd Interface Post SSO In xe39 nightly.

Conditions: This is seen when you have multiple ATM interfaces and issue switchover. Traffic doesn't flow from 2nd interface after switchover.

Workaround: No workaround

- CSCue18015

Symptoms: No S,G created. Forwarding based on (*,G).

Conditions: Happens with IGP change leading to RPF change of the (*,G).

Workaround: Clearing th (*,G) and recreating should help fixing the problem.

Further Problem Description: Timing issue and hence chances of landing into the problem depends on the events getting triggered.

- CSCue19898

Symptoms: (*,G) based forwarding can be seen with IIF change. IGP patch change to the source might lead to this problem.

Conditions: If the IGP change, the RPF change notification comes. In that case we miss adding the cpuq to the (*G).

Workaround: Timeout the (*,G) entry and recreating it again either by clear ip mroute or stopping the joins.

- CSCue20022

Symptoms: -Core (S, G) entries will software switch with-out any hardware forwarding

Conditions: -IIF is PIM enabled BDI interface. -Scale EVCs configured under single port -Scale BDIs as IIFs -Trigger: Flap main interface having EFPs

- Workaround:** -Clear Multicast Routes for failing (S, G) -Soft IM OIR for failing IIF interface having scale EVCs
- CSCue24621

Symptoms: when we do shut on one of the efp, traffic gets stop for other evcs also

Conditions: Where there are multiple qinq efp with same outer vlan tag on one interface.

Workaround: None.
 - CSCue25267

Symptoms: Stand-by rsp reloads on IM OIR on OC3IM on active rsp. Nile manager crash seen but core file incompletely generated.

Conditions: Seen when active rsp is booted up first, then standby rsp is booted. With serial links and APS configs on ASR903, perform IM OIR.

Workaround: None.
 - CSCue25567

Symptoms: quack authentication failure msg seen on console.

Conditions: It is seen randomly.

Workaround: Reload the router.
 - CSCue26927

Symptoms: Alarms are not forwarded in CEM.

Conditions: Alarms are not forwarded when AC goes down.

Workaround: No Workaround.
 - CSCue27652

Symptoms: ATM interfaces getting deleted on SSO

Conditions: ATM Interfaces are deleted on standby after IM OIR

Workaround: No Workaround.
 - CSCue27922

Symptoms: Syslog showing Object download for the prefix and traffic will not flow for the particular prefix.

Conditions: Issue is seen during multiple interface flap with 4K prefix and rLFA enabled.

Workaround: Reload the router
 - CSCue30481

Symptoms: The router does not lock to the syncE clock source after reload. It will be in QI-failed state.

Conditions: Reload the router with saved syncE configuration.

Workaround: Unconfigure and configure the clock source.
 - CSCue32753

Symptoms: While performing ISSU, the OC3IM interfaces are lost on ISSU completion. This is followed with config mismatch errors on router console. When new stand-by reaches standby-hot state, continuous iomd crash messages are seen at regular intervals.

Conditions: Seen when ISSU is performed from older label images to XE39 image.

- Workaround:** None. Unconfigure controller level OC3 configs and configure again. To stop continuous iomd crash, reload the standby rsp once. If IM went into inserted or out of service state, then a HARD OIR or process kill might be required.
- CSCue34597

Symptoms: CHAP authentication process timed out. PPP interface and multilink bundle doesn't come up.

Conditions: When PPP or MLPPP is configured and PPP authentication is enabled.

Workaround: remove CHAP authentication from interface
 - CSCue34618

Symptoms: Traffic stops flowing with combination of BRR and policer: in different class-maps under a policy.

Conditions: When the BW remaining ratio is configured in combination of police with cir (total brr and police cir equal to 1000M):

Workaround: Configuring total of BRR and police cir <1000M works fine: Ex: class A Police cir 100m and class B BRR 90% fails but BRR 89% works fine
 - CSCue35356

Symptoms: Policy-map attached on the PC interface stops working after service instance is removed and re-configured.

Conditions: A policy-map is attached to the main interface of the port-channel. The policy stops working when the service instance from the interface is deleted dynamically and then re-configured.

Workaround: Remove and re-attach the policy-map on the PC interface
 - CSCue36239

Symptoms: Match EFP policy on PC stops working after one of the policy on the member links is removed.

Conditions: Attach policy to all the memberlinks on the PC. Then remove it from one of the member links from which traffic was flowing. The traffic gets redirected but the QoS is no longer working

Workaround: Remove policy from all the member links and then reattach
 - CSCue43205

Symptoms: The router drops traffic when you set an interface to the default configuration.

Conditions: Occurs when you set an interface with QoS configurations to the default configuration. The issue occurs most often with the Ten Gigabit Ethernet interface using a full global configuration.

Workaround: There is no workaround.
 - CSCue42315

Symptoms: CPU Hogs messages and IOMD Crash seen

Conditions: With OC3 IM on doing shut/no shut of Multilink Bundle when traffic sent with packet size greater than 1500 byte

Workaround: none
 - CSCue42341

Symptoms: Backup path will be used to carry traffic instead of Primary path after reopt

Conditions: R-LFA + BFD needs to be configured together

- Workaround:** Flap the backup path interface
- CSCue43250

Symptoms: IMA config won't be parsed correctly after router reload when the A903-IM40S is inserted in Bay4/Bay5 of the ASR903 router

Conditions: when the IMA and ATM interfaces are adjacent. happens only for IM inserted on Bay 4 or above.

Workaround: insert the IM in bay 0 bay 3 if you want the IMA and ATM parsing to work. or reconfigure the ATM and IMA interfaces, it would work.
 - CSCue45306

Symptoms: CEM circuits configured over TDM IM go down after SSO.

Conditions: on SSO, CEM circuits configured over TDM IM are down.

Workaround: Router reload.
 - CSCue45498

Symptoms: CPU goes high when sending traffic with varying source mac addresses for multiple streams for BD.

Conditions: port-channel is configured as efp for the BD and mac-limit is configured to 0 for that BD.

Workaround: N/A
 - CSCue47317

Symptoms: Builds and ISSU may get impacted due to sync damage in latest throttles with respect to CCO data.

Conditions: Modification in implementation of TDL structures.

Workaround: Sync with CCO data will be committed shortly.
 - CSCue52774

Symptoms: observed with A900-IMA40S IM in ASR903 box. only when the port above 0 is used for clock-source, the clocking is not received by the system correctly.

Conditions: when the port above 0 is used for the clock source. issue is seen due to wrong conversion.

Workaround: 1. use port 0 for clock-sync 2. or insert the SFP in the odd port(protect ones) adjacent to actual port and using a optical splitter, the cable can be fed to this odd port which can recover the proper clocking for the given port.
 - CSCue52968

Symptoms: Ping fails and traffic stops through Multilink bundle when CHAP authentication is enabled

Conditions: This is seen when PFC and ACFC is configured.

Workaround: None, in case PFC and ACFC is configured.
 - CSCue57670

Symptoms: After SSO without any network-clock config new Active RSP Sync LED reflects Holdover state.

Conditions:

Workaround: Reload This is a cosmetic issue.

- CSCue57671
Symptoms: Router Crashes while running with REP configurations **Conditions:** Crash seen while removing REP configuration from interface. **Workaround:** None
- CSCue59544
Symptoms: Once path is once available for TE tunnel, it doesn't comes up **Conditions:** If A900-IMA16D is also present on router, it generates storm which prevent RSVP processing and TE tunnel doesn't up once TE path is available again
Workaround: None
- CSCue77612
Symptoms: The mac sync can happen on wrong lportid in the standby which can cause traffic forwarding to the wrong port after switchover.
Conditions: The traffic impact will be seen only after the switchover.
Workaround: clear mac-add after switchover.
- CSCue86696
Symptoms: Noticed interface flap on one of the routers, during overnight soak run.
Conditions: Seen during prolonged soak tests with SFP IM.
Workaround: None
- CSCue87542
Symptoms: On BDI delete, if routing traffic continues, it will be punted to the CPU which will flood out the CPU resulting in control plane loss
Conditions: Ping failure and BFD/OSPF flaps on BDI delete while ipv4/v6 traffic is running.
Workaround: The workaround is to delete the TEFP and then delete the BDI interfaces.
- CSCue89790
Symptoms: IPv6 traffic outage after SSO when NSF timer expires.
Conditions: Occurs when configuring IPv6 static routing or IPv6 OSPF routing.
Workaround: For IPv6 SSO support, ensure the following:
 - IPv6 neighbor are configured statically.
 - For dynamic route or static route, you must run a hardware BFD between IPV6 neighbors.



Restrictions and Caveats in Cisco IOS XE 3.10S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.10 releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions, page 20-1](#)
- [Caveats in Cisco IOS XE 3.10S Releases, page 20-2](#)

Limitations and Restrictions

The following limitations apply to the Cisco ASR 903 Router in IOS XE Release 3.10(0)S:

TDM Limitation

- The **configure replace** command is not supported for TDM interfaces.

IPv6 Limitations

The following limitation applies when using IPv6 on the Cisco ASR 903 Router:

- IPv6 Neighbor Discovery (ND) cache timer expiry is 4 hours. To prevent the neighbor adjacency from being deleted after the timer expires:
 - configure hardware based BFD sessions with the neighbors, or
 - configure static IPv6 neighbors, or
 - configure the **ipv6 nd cache expire timer refresh** command.

OC-3 IM Limitations

- The **configure replace** command is not supported on the OC-3 IMs.

Caveats in Cisco IOS XE 3.10S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.10S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.10S Releases:

- [Open Caveats—Cisco IOS XE Release 3.10.9S, page 20-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.9S, page 20-3](#)
- [Open Caveats—Cisco IOS XE Release 3.10.7S, page 20-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.7S, page 20-3](#)
- [Open Caveats—Cisco IOS XE Release 3.10.6S, page 20-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.6S, page 20-4](#)
- [Open Caveats—Cisco IOS XE Release 3.10.5S, page 20-4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.5S, page 20-4](#)
- [Open Caveats—Cisco IOS XE Release 3.10.4S, page 20-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.4S, page 20-5](#)
- [Open Caveats—Cisco IOS XE Release 3.10.3S, page 20-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.3S, page 20-6](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.\(2\)aS, page 20-8](#)
- [Open Caveats—Cisco IOS XE Release 3.10.2S, page 20-8](#)
- [Resolved Caveats—Cisco IOS XE Release 3.10.2S, page 20-9](#)
- [Open Caveats—Cisco IOS XE Release 3.10.1S, page 20-14](#)

- [Resolved Caveats—Cisco IOS XE Release 3.10.1S](#), page 20-16
- [Open Caveats—Cisco IOS XE Release 3.10S](#), page 20-20
- [Resolved Caveats—Cisco IOS XE Release 3.10S](#), page 20-23

Open Caveats—Cisco IOS XE Release 3.10.9S

There are no open caveats in Cisco IOS XE Release 3.10.9.

Resolved Caveats—Cisco IOS XE Release 3.10.9S

Caveat ID Number	Description
CSCvb29204	BenignCertain on IOS and IOS-XE
CSCuv87976	CLI Knob for handling Leap second Add/delee ignore/ handle
CSCvb19326	NTP leap second failure to insert after leap second occurs
CSCvb16274	PPTP Start-Control-Connection-Reply packet leaks router memory contents

Open Caveats—Cisco IOS XE Release 3.10.7S

There are no open caveats in Cisco IOS XE Release 3.10.7.

Resolved Caveats—Cisco IOS XE Release 3.10.7S

Identifier	Description
CSCuv30635	RSP1: standby rsp led not glowing post ISSU
CSCut33723	error counters getting incremented on ports which are down

Open Caveats—Cisco IOS XE Release 3.10.6S

There are no open caveats in Cisco IOS XE Release 3.10.6.

Resolved Caveats—Cisco IOS XE Release 3.10.6S

Identifier	Description
CSCut28876	ASR903 xconnect uni-directional traffic when new xconnect built or moved
CSCut03279	OC12/3:Forwarding alarm for CESOP is not propagating
CSCut33723	error counters getting incremented on ports which are down
CSCus60755	ASR903 crashes due to Memory Leak
CSCur76549	ASR903 RSP1 :Incorrect bytes count on BDI interface

Open Caveats—Cisco IOS XE Release 3.10.5S

- [CSCur76549](#)
ASR 903:Incorrect bytes count on BDI interface.
- [CSCus05877](#)
RPF-Failure packets are not filtered by IPv4 ACL applied over SVI.

Resolved Caveats—Cisco IOS XE Release 3.10.5S

- [CSCuo67326](#)
ASR 903: GSQ from L3 is not sent out of the box.
- [CSCur06724](#)
ASR 903: Local ping fails with Host queue qnode in stuck state.
- [CSCur17529](#)
Bulk sync failure in case of ingress QoS policy on CEM-ACR interface.
- [CSCur19046](#)
Traffic drop due to wrong PW programming.
- [CSCur37740](#)
Crash after SNMP polls transceiver information.
- [CSCur52148](#)
Image upgrade using reload command causes FP reset and stuck in init state.
- [CSCur96455](#)
ARP not generated in VRF when MPLS packet is received from POS/TDM interface.

Open Caveats—Cisco IOS XE Release 3.10.4S

- CSCuq38761
UMMT: BFD triggered FRR does not work as expected over BDI interface.
- CSCuq60722
RSPPID has disappeared from **show platform diag** command after reloading standby RSP.
- CSCuq87125
DPS fix for MLPPP buffer leak issue.
- CSCuq92777
Port-channel not getting removed-FMAN manager on deleting from IOS.

Resolved Caveats—Cisco IOS XE Release 3.10.4S

- CSCun07843
Critical Alarm reporting link down on FPGA port 0/5/0 after SSO.
- CSCuo09866
RSP1:FMAN-FP logs are flooded with error messages creating many trace log files.
- CSCuo15916
QoS classification does not work after reload.
- CSCuo21766
SNMP IF-MIB "ifHCOUcastPkts" and "ifInUcastPkts" fetches wrong value.
- CSCuo26304
CMAND logs are filled with "func call cman_cc_invalid" every minute.
- CSCuo76490
PIM register causes small buffer and IDB leak over BDI interface.
- CSCup03938
Enable 9K Jumbo packet length on Cisco ASR 903.
- CSCup06402
Cisco ASR 903: BGP session flaps with shaped egress policy.
- CSCup20634
Core interface ping fails when router has seven L3 Port-channels.
- CSCuq12880
Cisco ASR 903 crashes on running **show platform hard pp active nqatm 0 ipv4tunnel all** command.

Open Caveats—Cisco IOS XE Release 3.10.3S

- CSCuo11380
Symptom: AIS alarm observed on OC-3 controller.

- Conditions:** This issue occurs during a reload or after performing multiple IM OIR.
- Workaround:** Perform a soft OIR on the IM.
- CSCuo40840
Symptom: Layer2 traffic on TEF is punted to CPU.
Conditions: This issue occurs on loading and removing the configuration using config replace procedure.
Workaround: There is no workaround.
 - CSCuo95061
Symptom: Ping fails when standby configured with Hot Standby Router Protocol (HSRP) takes over from the active RSP.
Conditions: This issue occurs when standby configured with HSRP takes over from the active RSP.
Workaround: There is no workaround.
 - CSCuo97889
Symptom: IPv6 traffic gets dropped while doing an SSO.
Conditions: This issue occurs during SSO.
Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.10.3S

- CSCul50165
Symptom: The Cisco ASR 903 fails to forward packets with the maximum configurable MTU on A900-IMA16D and A900-IMA4OS.
Conditions: This issue occurs when `mtu max MTU` interface command is executed.
Workaround: There is no workaround.
- CSCum05115
Symptom: IPv4 labeled BGP traffic drops on the router.
Conditions: This issue occurs for prefixes after a reload of the router.
Workaround: There is no workaround.
- CSCum45110
Symptom: Multicast traffic is not sent over BDI interface with IGMP snooping enabled.
Conditions: This issue occurs on the router when IGMP snooping is enabled.
Workaround: Disable IGMP snooping.
- CSCum54906
Symptom: Crash observed on the router after executing the `show interfaces pseudowire counters` command.
Conditions: This issue occurs after executing the `show interfaces pseudowire counters` command.
Workaround: There is no workaround.
- CSCun07802
Symptom: AutoNegotiation configuration on the fiber ports is not retained after IM OIR or reload.

- Conditions:** This issue occurs on IM OIR/ or router reload.
- Workaround:** Do not disable the AutoNegotiation property on the fiber ports, else reconfigure the AutoNegotiation on the ports manually.
- CSCun47966

Symptom: Memory leak observed during ASP switchover.

Conditions: This issue occurs when APS switchover is performed.

Workaround: There is no workaround.
 - CSCun70703

Symptom: Interface Module Goes to out of service after ISSU.

Conditions: This issue occurs after performing ISSU when there is a IM FPGA change.

Workaround: Perform IM FPGA upgrade using the package file and proceed with ISSU.
 - CSCun75471

Symptom: Memory usage gradually increases over time, when storm control feature is enabled on the router.

Conditions: This issue is observed when storm control feature is enabled.

Workaround: There is no workaround.
 - CSCun79358

Symptom: DHCP packets getting dropped on a transparent node between client and server.

Conditions: This issue occurs when global DHCP snooping is enabled on the transparent node.

Workaround: Disable the global DHCP snooping feature.
 - CSCun83203

Symptom: Bandwidth percentage does not working on changing the port speed.

Conditions: This issue occurs after changing the port speed.

Workaround: There is no workaround.
 - CSCuo03508

Symptom: Bulk sync failure seen on router when DAI is configured and **ip arp inspection filter nag bridge-domain static** command is executed.

Conditions: This issue occurs with DAI configuration.

Workaround: After switchover or router reload, configure the **ip arp inspection filter nag bridge-domain static** command.
 - CSCuo05897

Symptom: Multicast traffic stops flowing over psuedowire on changing the configuration. The traffic does not resume till reloaded.

Conditions: This issue occurs on changing the configuration.

Workaround: Reload the device.
 - CSCuo06895

Symptom: Router crash observed after reload.

Conditions: This issue occurs in normal conditions. There is no specific trigger or condition under which this may occur.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.10.(2)aS

This section documents the issues that have been resolved in Cisco IOS XE Release 3.10.(2)aS.

- CSCul06921

Symptom: Port-channel member-links flaps are observed on the router.

Conditions: This issue is seen on router switchover.

Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.10.2S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.10.2S.

- CSCuf15863

Symptom: Traffic loss of few milliseconds seen on the router.

Conditions: This issue occurs when remote LFA is configured on the core, and on shutting a primary path, the site which is not on primary path gets some milliseconds loss.

Workaround: There is no workaround.

- CSCuf35464

Symptom: The active bits port does not send out the QL properly which is received from the remote bits.

Conditions: This issue occurs when the remote bits are configured as input and active bits as output.

Workaround: There is no workaround.

- CSCui74718

Symptom: %EVENTLIB-3-RUNHOG tracebacks are reported on the console.

Conditions: This issue occurs when the router is configured in PTP slave mode. The clock is in phase aligned state and PTP configurations are removed using the **no ptp clock ordinary domain** command.

Workaround: There is no workaround.

- CSCul07048

Symptom: IPv6 nd cache expire after reload or IM OIR is performed.

Conditions: This issue occurs when ISIS with BFD is enabled on the BDI interface.

Workaround: Reload or replace the configuration.

- CSCul50165

Symptom: The router fails to forward packets with the maximum configured MTU.

Conditions: This issue was observed on MLPPP, T1, POS interfaces when the **mtu max MTU interface** command was executed on the router.

Workaround: There is no workaround.

- CSCul58083

Symptom: After IP mtu is configured on an interface, any change in to the MTU are not reflected on the interface.

Conditions: This issue occurs when IP mtu is configured and the MTU is changed.

Workaround: Set the required interface MTU before executing the **ip mtu** command or unconfigure the IP MTU on the interface and then change the interface MTU.

- CSCum40613

Symptom: The TOD port on the router does not function when configured as slave.

Conditions: This issue occurs after configuring TOD on the router.

Workaround: There is no workaround.

- CSCum47925

Symptom: SSO convergence time of ~0.9 sec is observed with 100m SFP.

Conditions: This issue occurs when VPLS VC and EVC BD exists on the access.

Workaround: There is no workaround.

- CSCum79011

Symptom: Pending objects take a long time (approx 30 min) to clear on the router.

Conditions: This issue occurs when QoS-policy is applied on member-link and services like psuedowire, HSRP on BDI are configured on the port-channel.

Workaround: There is no workaround.

- CSCun70703

Symptom: Interface module goes to out of service during ISSU and when FPGA is changed.

Conditions: This issue occurs on performing ISSU when there is a IM FPGA change between the releases.

Workaround: Perform the following:

- Perform IM FPGA upgrade using the package file.
- Proceed with ISSU.

Resolved Caveats—Cisco IOS XE Release 3.10.2S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.10.2S.

- CSCuf35542

Symptom: PFM fails for about 5minutes after OIR on the master.

Conditions: This issue occurs after OIR is triggered two times on the master

Workaround: Wait for 5-6 minutes

- CSCuh06123

Symptom: QL-mapping displays incorrectly on master.

Conditions: This issue occurs when QL value is configured first and then PTP master is configured

Workaround: Reconfigure QL values or reload the router.

- CSCuh49073

Symptom: OSPF does not come up when PIM is enabled on the VPLS core interface.

Conditions: This issue occurs when PIM is enabled on the VPLS core interface.

Workaround: There is no workaround.

- CSCuh54159

Symptom: Packet drops are seen under QOS policy map attached on the multilink bundle for traffic rate less than bundle capacity

Conditions: This issue occurs when unexpected packet drops are seen for QOS for traffic rates less than bundle bandwidth. After reloading the router with QOS policy attached on bundle, packet prioritization into different queues with differing bandwidth profiles occurs.

Workaround: Remove and reattach the policy map on the bundle

- CSCui41169

Symptom: Active card reloads when standby comes active after switchover with scaled configuration

Conditions: This issue occurs when 4000K EVCs with 1-level ingress policy, and 2-level egress policy is configured on the router. Ingress policy should have 1-level policer, egress policy should have one parent and child policer. The issue occurs after a reload of the card with this configuration.

Workaround: There is no workaround.

- CSCui44409

Symptom: No console message are seen on insertion or removal of USB

Conditions: This issue is observed standby RSP.

Workaround: More Info:

- CSCui45075

Symptom: When an IM is removed from the router, the MST states are not reflected in the standby RSP. If a switchover happens at this state, it could cause total traffic drop.

Conditions: This issue is seen when HA is configured on the router.

Workaround: There is no workaround.

- CSCui98883

Symptom: System crashes on configuring TOD.

Conditions: This issue occurs on dual RSP setup and PTP is configured.

Workaround: There is no workaround.

- CSCui99309

Symptom: IPv6 BFD with static client does not display when VRF is configured.

Conditions: This issue occurs when VRF is configured on the router.

Workaround: There is no workaround.

- CSCuj30644

Symptom: Multicast does not function in scaled mode and when BDI is configured on the core.

Conditions: This issue was seen in the scaled mode.

Workaround: Execute the **no ip igmp snooping** command on the router to forward the multicast traffic.

- CSCuj34652

Symptom: IPv6 traffic drops for the packets with next header options. Next header options include Hop-by-hop options, fragment header.

Conditions: This issue occurs when option packets are punted to CPU and generates the time exceeded message.

Workaround: There is no workaround.

- CSCuj38988, CSCum45935

Symptom: QL does not move to QL-FAILED state when the Gigabit ethernet interface is shutdown.

Conditions: This issue occurs when the Gigabit ethernet interface is shutdown.

Workaround: There is no workaround.

- CSCuj42208

Symptom: Layer3 multicast traffic drop is seen on Trunk port.

Conditions: This issue occurs when multicast is converged. Performing a **shutdown** followed by a **no shutdown** on the multicast router interface fails to transmit multicast traffic to TEFP's.

Workaround: Clear IP multicast routes using **clear ip mroute** command for IPv4 traffic and **clear ipv6 pim topo** command for IPv6 traffic.

- CSCuj43453

Symptom: IOSd crash was seen on the router on bootup of PTP process.

Conditions: This issue occurs during bootup when multiple reloads of the router is performed.

Workaround: There is no workaround.

- CSCuj43795

Symptom: The port in error-disabled state & physical status shows as down but is UP on the other connected end device.

Conditions: This issue occurs when the port is configured with DHCP rate limiting values so that the port goes to error-disable state once it reaches the rate configured.

Workaround: Perform a **shutdown** followed by a **no shutdown** on the respective interface to move the port to UP state.

- CSCuj60116

Symptom: SYNC-E does not get synced in WAN mode.

Conditions: This issue occurs in WAN mode.

Workaround: There is no workaround.

- CSCuj60771

Symptom: Self-generated DHCP traffic generating out of the router is not getting marked (cos) with user specified value.

Conditions: This issue occurs when DHCP packets (CPU to client) are not getting marked.

Workaround: There is no workaround.

- CSCuj96689

Symptom: **Queue-limit** command is not programmed for priority queue.

Conditions: This issue occurs when the policy map has both BRP and Priority queue with queue-limit configured for priority queue.

Workaround: Perform the following;

- Attach the policy with all BRP configuration.
 - Dynamically add the **queue-limit** command to the priority class.
- CSCul10279
Symptom: Crash observed on the router with multicast VPN configuration.
Conditions: This issue occurs when the router is configured with multicast VPN IPv4 configuration, Scaled ACL and IGMP Static Join configuration.
Workaround: There is no workaround.
- CSCul11877
Symptom: HSRP standby router cannot ping the virtual IP.
Conditions: This issue occurs when the BDI interfaces are configured along with a range of bridge domains.
Workaround: There is no workaround.
- CSCul21294
Symptom: PTSF alarms do not get posted when the egress interface is shutdown.
Conditions: This issue occurs when a PTP slave has one or more masters.
Workaround: There is no workaround.
- CSCul21429
Symptom: The router console freezes and the OSPF or BFD sessions flap.
Conditions: This issue occurs when TOD type is changed dynamically on a PTP master from NTP to Cisco or vice-versa.
Workaround: Unconfigure TOD and reconfigure a new TOD type.
- CSCul21447
Symptom: The ANNOUNCE message does not get updated.
Conditions: This issue occurs in the PTP slave.
Workaround: There is no workaround.
- CSCul40676
Symptom: Ping failure observed on the interface connected with port 0/0/0 with ACR configuration.
Conditions: This issue occurs when ACR is configured on the router.
Workaround: Install the IM in the other bay or change the port other than 0/0/0 as the core.
- CSCul46353
Symptom: Traffic drop observed on priority queues.
Conditions: This issue occurs on QoS policy with 2-level priority queues (priority level classes) that do not guarantee the bandwidth on 1-level priority against 2-level traffic.
Workaround: There is no workaround.
- CSCul46643
Symptom: Convergence with SSO for REP with multicast is greater than 3 seconds.
Conditions: This issue occurs on performing an SSO on the Receiver
Workaround: There is no workaround.
- CSCul49147

Symptom: Time exceed message is generated when IPv6 packets are received on the router.

Conditions: This issue occurs when IPv6 packets have option headers.

Workaround: If the IPv6 options have fragment header then increase the MTU size.

- CSCul50181

Symptom: A Cisco router may see unicast traffic not being forwarded out of the Gigabit ethernet interface while multicast traffic is being processed by the router correctly.

Conditions: This issue occurs when the router has BDI configured to the Gigabit ethernet interface.

Workaround: Reload the router.

- CSCul51784

Symptom: IPv6 packets fails to get forwarded out of the router.

Conditions: This issue occurs when unicast RPF enabled for IPv4 traffic and IPv6 traffic is received on the interface.

Workaround: Remove unicast RPF checks on the interface where dual stack is configured.

- CSCul52778

Symptom: STM -1 port keeps on increasing on changing the **card type** command multiple times.

Conditions: This issue occurs after executing the card type command many times.

Workaround: There is no workaround.

- CSCul65485

Symptom: Wrong speed and bandwidth is displayed with DWDM XFP

Conditions: This issue occurs when the DWDM XFP is inserted and the **show interface** command is executed.

Workaround: There is no workaround.

- CSCul65977

Symptom: Enabling DAI on one interface leads to ARP packets being dropped on another interface in the same BD or cross-connect.

Conditions: This issue occurs after enabling DAI on one interface.

Workaround: There is no workaround.

- CSCul80289

Symptom: Crash observed on the router.

Conditions: This issue occurs after unconfiguring the BDI interface and TEF is learnt as mrouter.

Workaround: There is no workaround.

- CSCum02924

Symptom: PTP session gets stuck in unknown state.

Conditions: This issue occurs when OSPF, clock domain & clock source are unconfigured and reconfigured.

Workaround: There is no workaround.

- CSCum42701

Symptom: Tx and Rx power does not display the right values for OC-3 SFP.

Conditions: This issue is seen when the controller is disabled and the SFP is inserted.

Workaround: Perform a hard OIR of the OC-3 SFP.

Open Caveats—Cisco IOS XE Release 3.10.1S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.10.1S.

- CSCue42139

Symptom: The ptp state is stuck in acquiring state all the time

Conditions: This issue occurs when the active RSP is removed; the T3 timestamping is stuck and the ptp state stays in acquiring state all the time.

Workaround: Unconfigure and configure the ptp.
- CSCuf78234

Symptom: The **queue-limit** command displays packets as default.

Conditions: This issue occurs when **queue-limit** command is configured on the router.

Workaround: Configure queue-limit is microseconds (us) or bytes.
- CSCug97269

Symptom: The serial interface flaps when the neighbor controller is shut.

Conditions: This issue occurs on performing shutdown on peer OC-3 controller with ATM or IMA channels.

Workaround: There is no workaround.
- CSCuh83433

Symptom: The path level controllers status on OC-3 IM sonet controller is not displayed after a second SSO is triggered manually after removing the RSP.

Conditions: This issue is seen on hard RSP reset of RSP1.

Workaround: Perform a controller **shutdown** followed by a **no shut down**.
- CSCui08697

Symptom: The interface LED glows green after SSO.

Conditions: This issue occurs after an SSO is performed and shut down of the ports on the router.

Workaround: There is no workaround.
- CSCui34041

Symptom: Traffic does not flow on one of the prefix of the MPLS template.

Conditions: This issue occurs when the MAX MPLS label of that template is assigned to that prefix

Workaround: Disable and enable that prefix.
- CSCui41169

Symptom: The active card reloads when standby become active after switchover with scaled configurations.

Conditions: This issue occurs with 4000 EVCs with first and second level ingress policy. The Ingress policy has one policer and the egress policy has one parent and child policer. This issue occurs with reloading the card with this configuration.

Workaround: There is no workaround.

- CSCui53268
Symptom: Adding a child policy map with Vlan class to parent PHB class dynamically, does not trigger the error message.
Conditions: This issue occurs when a PHB level policy is attached to an interface and any policy is being dynamically added as a child to one of the existing PHB classes.
Workaround: Detaching the policy and performing a modification and trying to reattach displays the error.
- CSCui62568
Symptom: No error reported when invalid policer is dynamically modified to remove the PIR configuration with violate-action.
Conditions: This issue occurs when a policy-map with CIR and PIR value attached to an EFP is dynamically modified to just CIR which make the policer have exceed action without PIR.
Workaround: Remove the violate-action first and then remove PIR configuration.
- CSCui74718
Symptom: “%EVENTLIB-3-RUNHOG” tracebacks reported on the console.
Conditions: This issue occurs on the router in ptp slave mode. The clock is in phase aligned state and the ptp configurations are removed using the **no ptp clock ordinary domain** command.
Workaround: There is no workaround. There is no functional impact.
- CSCui92961
Symptom: 100% traffic loss is observed on few pseudowires.
Conditions: This issue occurs when the router experiences couple of link flaps.
Workaround: Issue **shutdown** command followed by **no shutdown** command on the EFP; this can be tedious if impacted pseudowire count is more.
- CSCuj04299
Symptom: FMAN FP core traceback observed on the router.
Conditions: This issue occurs after adding several new EFPs or BDIs to running configuration and updating the QoS configuration on the physical interface
Workaround: There is no workaround.
- CSCuj09392
Symptom: Dynamically modifying the user-defined to class-default triggers error.
Conditions: This issue was seen when modifying the user-defined to class-default.
Workaround: There is no workaround.
- CSCuj32391
Symptom: Dynamic modify of parent with class default policer to child policer does not take effect.
Conditions: This issue occurs on dynamic modify DM of parent having class-default policer value greater than child policer value.
Workaround: Reattach the policy-map
- CSCuj38988
Symptom: Queue-limit does not go to queue-limit failed state when we the gigabit ethernet interface is shutdown.

Conditions: This issue occurs while shutting down the gigabit ethernet interface.

Workaround: There is no workaround.

- CSCuj51830

Symptom: Traffic drops if policy is attached on port-channel interface.

Conditions: This issue occurs when the policy is attached on port-channel interface

Workaround: Use port-channel IDs less than 10.

- CSCuj56164

Symptom: TCAM utilization shows incorrect current usage percentage.

Conditions: This issue occurs when EQoS application is enabled.

Workaround: There is no workaround.

- CSCun70703

Symptom: Interface module goes to out of service during ISSU and when FPGA is changed.

Conditions: This issue occurs on performing ISSU when there is a IM FPGA change between the releases.

Workaround: Perform the following:

- Perform IM FPGA upgrade using the package file.
- Proceed with ISSU.

Resolved Caveats—Cisco IOS XE Release 3.10.1S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.10.1S.

- CSCue60699

Symptom: Router auto negotiates full duplex with 1000M half/full duplex configuration.

Conditions: This issue occurs when a router with Copper SFP with auto-negotiating is enabled and the peer router with Cu SFP configured with 1000M half-duplex mode exists.

Workaround: There is no workaround.

- CSCug31550

Symptom: Incorrect TCAM entries with scale configuration are displayed after reapplying the policy map.

Conditions: This issue occurs after removing the policy map and reapplying it to service instances.

Workaround: There is no workaround.

- CSCug36190

Symptom: Object Download failures are seen when configuring cross connect on the main interface and configure cross connect under the service instance.

Conditions: This issue occurs when cross connect is configured on the main interface.

Workaround: Remove the cross connect configuration from the main interface.

- CSCug50280

Symptom: QoS does not work on the router.

- Conditions:** This issue occurs while adding user class to a port level policer dynamically when the policer already has class-default configured.
- Workaround:** Reload the router.
- CSCug68820

Symptom: The **show inventory** command does not display PSU and fan tray information.

Conditions: This issue occurs after the PSU or fan tray is inserted after bootup and SSO is performed.

Workaround: Reload after PSU or the fan tray after it is inserted.
 - CSCug70182

Symptom: The ASR903-IMA8S port remains up without the fiber.

Conditions: This issue occurs when the GLC-FE-100FX optic is used.

Workaround: There is no workaround.
 - CSCug96284

Symptom: Memory leaks seen on boot up of the router.

Conditions: This issue occurs on booting the system.

Workaround: There is no workaround.
 - CSCuh00108

Symptom: CMAND crash seen on the router.

Conditions: This issue occurs during midplane idprom read at bootup.

Workaround: Reload the router.
 - CSCuh03023

Symptom: IP connectivity over BDI fails after a link flap network event.

Conditions: This issue occurs intermittently with BDI enabled for IP/MPLS forwarding and running VPN services over it. Adjacency failures are seen after couple of link flap events, which impacts Layer3 forwarding over BDI.

Workaround: There is no workaround.
 - CSCuh13883

Symptom: Standby IOMD crashes continuously at system bootup.

Conditions: This issue occurs at system bootup and when the system waits for a user input at the initial dialog box during configuration.

Workaround: There is no workaround.
 - CSCuh16707

Symptom: The interface module (IM) status LED glows green before the PHY Init state is complete.

Conditions: This issue occurs after an IM OIR is performed.

Workaround: Use the **show platform** command output to check if the IM reaches the OK state.
 - CSCuh42926

Symptom: High CPU utilization is seen when Trunk EFP is configured on port channel and MAC address table limit is configured on the bridge domain.

Conditions: This issue occurs when Trunk EFP is configured on port channel and MAC address table limit is configured on the bridge domain.

- Workaround:** Do not use port channel.
- CSCuh46103
Symptom: BDI statistics not getting incremented on the router.
Conditions: This issue occurs when the ingress and egress statistics displayed using **show interface bdi** or the **show int bdi statistics** command does not get incremented even if the traffic is flowing through the BDI interface.
Workaround: Use **show platform hardware pp active interface statistics bdi** command to view the statistics.
 - CSCuh51651
Symptom: CPP download failures and CFM remote MEPS not learnt.
Conditions: This issue occurs during configuring CFM offload scaled configurations using TFTP.
Workaround: There is no workaround.
 - CSCuh51702
Symptom: The system shuts down after 5mins irrespective of ambient temperature after removing the fan tray.
Conditions: This issue occurs after removing the fan tray.
Workaround: There is no workaround.
 - CSCuh81135
Symptom: Port speed configuration is changed automatically on changing the SFP module.
Conditions: This issue occurs on changing the SFP module.
Workaround: There is no workaround.
 - CSCuh85990
Symptom: Some CFM MEPs are not learnt when configuring large number (about 1K) on the router.
Conditions: This issue is seen only if large number of MEPs are configured.
Workaround: Remove and re-apply the configuration.
 - CSCuh92939
Symptom: Traffic drop occurs after replacing a Cu SFP with a fiber FP
Conditions: This issue occurs after replacing Cu SFP with fiber SFP after an SSO is performed.
Workaround: Perform an IM OIR.
 - CSCuh99117
Symptom: Packet drops for some of the prefixes in MPLS network are observed.
Conditions: This issue occurs when MPLS Layer3 VPN is configured on the router with MVPN template.
Workaround: There is no workaround.
 - CSCui16418
Symptom: After a switchover is performed, the ten gigabit ethernet interface might flap and traffic drops.
Conditions: This issue occurs after SSO is performed.
Workaround: There is no workaround.

- CSCui32127

Symptom: CFM download error-objects are observed when CFM peers are reloaded or IM OIR is done on a scaled VPLS and CFM setup.

Conditions: This issue occurs on the router with 250 or more CFM MEP sessions and more than 1250 Layer2 virtual circuit sessions.

Workaround: There is no workaround.
- CSCui34041

Symptom: Traffic does not flow to one of the prefix on MPLS template.

Conditions: This issue occurs when maximum MPLS label of that template is assigned to that prefix.

Workaround: Disable and enable the prefix.
- CSCui40994

Symptom: Ethernet CFM ping fails because remote MEPs are not learnt.

Conditions: This issue occurs when MIP is configured on the same Vlan as MEP on the CFM domain.

Workaround: Remove MIP configuration.
- CSCui50577

Symptom: Traffic drops are observed on router.

Conditions: This issue occurs after performing an IM OIR.

Workaround: There is no workaround.
- CSCui58365

Symptom: Router reboots while modifying a policy-map with class-map "**match vlan 100**".

Conditions: This issue occurs while attaching the "**match vlan 100**" egress policy-map. This issue occurs after adding an ingress policy with no-match class and then adding an egress policy with **match** on Vlan or dynamically adding match vlan class on egress policy.

Workaround: There is no workaround.
- CSCui68159

Symptom: Traffic drops when two EFPs are configured on with default encapsulation and **rewrite push do1q** on same BD.

Conditions: This issue occurs when two EFPs are configured on with default encapsulation and **rewrite push do1q** on the same BD.

Workaround: There is no workaround.
- CSCui87339

Symptom: Transceiver init_failure observed after transceiver OIR is performed.

Conditions: This issue is seen after the OIR of transceiver is performed.

Workaround: A slow OIR of transceiver might recover the port.
- CSCui93830

Symptom: HQoS top level service-policy fails on the router when switching between the RSPs.

Conditions: This issue occurs when switching between the RSPs.

Workaround: Reattach the policy-map.

- CSCuj07507
Symptom: High convergence for downstream traffic observed on the router.
Conditions: This issue occurs when VPLS VFI's is controlled by g.8032 open ring, with a large scale of about 500VC's and 10000 MAC (40 per BD).
Workaround: Use small MAC scales for traffic.
- CSCuj42080
Symptom: The FGPA gets stuck while pumping high volume of CFM packets.
Conditions: This issue occurs while pumping high volume of CFM packets on the router.
Workaround: There is no workaround.
- CSCuj50260
Symptom: CFM ping fail to MPIDS on the router.
Conditions: This issue occurs when MEPS are configured over port channel.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.10S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.10S.

- CSCue36365
Symptom: During initial bootup of the serial interface module, the first character of the first packet received might be missing.
Conditions: Problem occurs during a cold boot of the serial interface module.
Workaround: There is no workaround. Problem is a transient condition and traffic resumes after receipt of the first message on the module.
- CSCue42144
Symptom: PHY stops timestamping and the session stays at acquiring state.
Conditions: This issue is observed when you insert the Cu-SFP on the slave.
Workaround: There is no workaround.
- CSCue49537
Symptom: The Cisco ASR 903 router crashes when you perform an OC3 IM OIR.
Conditions: This issue is observed when you have about 700 CEM circuits and perform an OC3 IM OIR.
Workaround: There is no workaround.
- CSCue87629
Symptom: The following error message is displayed:

```
INFRA-6-PROCPATH_CLIENT_HOG: IOS shim client 'iosd-nile'
```

Conditions: This issue is observed when you use the **shutdown** and **no shutdown** commands on the G8032 ring interface of peer or local device.
Workaround: There is no workaround.

- CSCuf16426
Symptom: FMAN_FP download fails and the following error message is displayed:

```
%CHUNK-2-BADREFCOUNT errors.
```


Conditions: Have an MPLS TE in the core and flap the tunnels intermittently.
Workaround: Do not flap the core TE tunnels often.
- CSCug15175
Symptom: The Cisco ASR 903 router falsely displays the following error message saying that a BFD node is down:

```
%OSPF-5-ADJCHG: Process 232, Nbr 192.0.2.33 on BDI632 from FULL to DOWN, Neighbor Down: BFD node down
```


Conditions: This issue is observed when you configure a BFD software session.
Workaround: There is no workaround.
- CSCug36590
Symptom: The Cisco ASR 903 router displays the following error message:

```
%IDBINDEXT_SYNC-4-RESERVE: Failed to lookup existing ifindex for an interface on the Standby, allocating a new ifindex from the Active (ifindex=126, idbtype=SWIDB)
```


Conditions: This issue is observed when you create an ATM channel, create a POS link, or create DS3 links.
Workaround: There is no workaround.
- CSCug43550
Symptom: The receiver node crashes when the number of traffic sources increases beyond 400 with 196 OIFs at the receiver end.
Conditions: This issue is observed when 196 IGMP packets are sent to a node per second.
Workaround: Reduce the number of IGMP packets to four per second.
- CSCug84082
Symptom: Ping fails and traffic drops on ATM/IMA PVP links configured on either T1E1 IM or OC3 IM.
Conditions: This issue is observed when you perform an SSO and flap the ATM/IMA link.
Workaround: Perform an IM OIR or reload the router.
- CSCug96003
Symptom: When operating with a large number of TCP Raw Socket connections (greater than 512) and with traffic on all of them we saw some TCP retransmissions.
Conditions: The issue occurred in a stress test within a lab setup.
Workaround: None required.
- CSCuh06123
Symptom: QL mapping is incorrect on the PTP master.
Conditions: This issue is observed when you first reboot the router or configure and unconfigure the router multiple times.
Workaround: Reconfigure the QI values.
- CSCuh33291

Symptom: The Cisco ASR 903 router generates linkDown traps when an interface changes from administratively down state to down state.

Conditions: This issue is observed when an interface changes from administratively down state to down state.

Workaround: There is no workaround.

- CSCuh33314

Symptom: When you perform an ISSU or terminate the IOMd process, IOMd crashes on the standby RSP.

Conditions: This issue is observed when you terminate the IOMd process on the active RSP or when you perform an ISSU.

Workaround: There is no workaround.

- CSCuh81658

Symptom: Although a QoS policy is configured, PTP packets are treated as default packets.

Conditions: This issue is observed when the CPU-generated PTP packets do not reach egress QoS with high a priority label (15 or 126).

Workaround: There is no workaround.

- CSCuh85041

Symptom: SNMP returns the wrong card type for the serial interface module.

Conditions: Issue occurs during SNMP walk of ASR903.

Workaround: There is no workaround. This issue is not service affecting.

- CSCuh85990

Symptom: When you use the **show ethernet cfm maintenance-points remote** command, only 992 remote maintenance endpoints are displayed.

Conditions: This issue is observed when you configure CFM MEP domains on an EVC.

Workaround: There is no workaround.

- CSCuh88500

Symptom: Standby router reloads due to SPA bulk synchronization failure.

Conditions: This issue is observed when you perform an SSO.

Workaround: There is no workaround.

- CSCui06748

Symptom: ICMP packets are punted to the CPU even after using the **no ip redirect** command on the Cisco ASR 903 router.

Conditions: This issue is observed when ICMP packets are punted initially.

Workaround: There is no workaround.

- CSCui14481

Symptom: Traffic does not flow for HSPW sessions as the tunnel ID is incorrect.

Conditions: This issue is observed when you perform an IM OIR.

Workaround: Perform an SSO and flap the access interface.

- CSCui19632

Symptom: BFD sessions flap randomly.

Conditions: This issue is observed in FPGA version 30020.

Workaround: There is no workaround.

- CSCui19700

Symptom: When you apply a QoS policy on the core interface, QoS counters do not increment.

Conditions: This issue is observed when you apply a policy on the access interface with 500 EFPs and apply another policy on the core interface.

Workaround: There is no workaround.

- CSCui22637

Symptom: The Cisco ASR 903 router crashes.

Conditions: This issue is observed when you unconfigure 1000 Ethernet service instances.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.10S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.10S.

- CSCtx70302

Symptom: Traceback and log messages are seen while performing a multilink bundle shutdown on the Cisco ASR 903 router.

Conditions: This issue is observed when traffic flows over the multilink bundle.

Workaround: There is no workaround. This issue does not impact the operation of the router.

- CSCua61934

Symptom: When a policy map with priority in class-default is attached to an interface, it is not rejected.

Conditions: This issue is observed when you configure policy-map having priority in class-default and attach the policy to an interface.

Workaround: There is no workaround.

- CSCua90879

Symptom: QoS policies with a police statement on the class-default class do not take effect.

Conditions: This issue is observed when you apply a police statement to the class-default class within a QoS policy on an ingress EVC interface.

Workaround: Apply the police statement to a static class, such as class cos0.

- CSCuc59386

Symptom: IOMD crashes continuously on OC-3 IM. The interfaces on OC-3 IM are not configurable and the following error message is displayed:

```
stand-by does not support this command
```

Conditions: This issue is observed on a Cisco ASR 903 router high availability setup with OC-3 IM.

Workaround: Reload the standby RSP.

- CSCuc60148

Symptom: The router does not shut down when the temperature sensor reaches the shutdown threshold.

Conditions: Temperature sensor reaches shutdown threshold.

Workaround: Use the **facility-alarm critical exceed-action shutdown** commands to enable system shutdown.

- CSCuc83088

Symptom: The router drops traffic while performing a Stateful Switchover (SSO).

Conditions: This issue is observed when the router is running HSRP or VRRP. It occurs when the destination MAC address is a virtual MAC (vMAC) address.

Workaround: Change the traffic priority and detour traffic before performing an SSO.

- CSCud09100

Symptom: The router accepts a policy with marking at two levels. It should not accept a policy with marking at two levels.

Conditions: This issue is observed when you apply a policy with marking at two levels.

Workaround: There is no workaround.

- CSCud09813

Symptom: Timestamping does not work in CFM over cross-connected MEP with port channel.

Conditions: This issue is observed when you configure CFM over cross-connected MEP with port channel from a Cisco ASR 903 router to a Cisco ME 3600 switch.

Workaround: There is no workaround.

- CSCud12624

Symptom: Traceback is displayed when you configure the ACR group.

Conditions: This issue is observed when you configure an ACR group.

Workaround: There is no workaround.

- CSCud29491

Symptom: A two-level policy with match EFP in parent and PHB-based policy in child can be applied.

Conditions: This issue is observed when you apply a policy on a physical interface having EFPs on that physical interface.

Workaround: There is no workaround. This configuration is not supported.

- CSCud34630

Symptom: The following error message is displayed on the standby machine while using the **shutdown** and **no shutdown** commands on the ACR controller:

```
NETWORK_RF_API-3-FAILDECODEDATADDESC
```

Conditions: This issue is observed on the standby machine when you configure ACR interface.

Workaround: There is no workaround.

- CSCud35689

Symptoms: The router accepts a queue-limit configuration at the parent level of a policy or at the vlan class or port level.

Conditions: This issue is observed when you add a queue-limit configuration on a policy at the parent level or at the vlan class or at port level.

Workaround: There is no workaround. This configuration is not supported.

- CSCud35732
Symptom: The router does not apply egress CFM MIP filtering.
Conditions: This issue is observed when you overwrite a MIP configuration using the ethernet CFM MIP level command.
Workaround: Instead of overwriting the MIP level configuration, remove and reapply the configuration.
- CSCud38038
Symptom: The router records incorrect delay measurements after a reload.
Conditions: This issue is observed under the following conditions:
 - You configure Delay Measurement Message (DMM) on a port-channel interface.
 - The port-channel member links are on different interface modules (IMs).
 - You reload the router.**Workaround:** Remove the **ethernet cfm global** command and reapply it after the port-channel member links to bundle. Alternatively, configure PTP clock synchronization.
- CSCud38833
Symptom: When you configure the ACR CEM interfaces, tracebacks are displayed and the serial interface remains down.
Conditions: This issue is observed when you create a second CEM circuit under the same controller and delete the CEM circuit immediately.
Workaround: There is no workaround.
- CSCud41297
Symptom: Multicast snooping traffic drops after removing and reconfiguring the querier EFP on 1000 groups.
Conditions: This issue is observed when you remove and reconfigure querier EFP with more than 500 multicast routs.
Workaround: There is no workaround.
- CSCud43718
Symptom: After performing an SSO, multicast traffic is dropped for a few groups.
Conditions: This issue is observed in a scaled configuration with IGMP snooping enabled in a bridge-domain.
Workaround: There is no workaround.
- CSCud55695
Symptom: When you apply a QoS policy with a port level class-default configuration containing a shaper value to a serial interface, the router applies the shaper value to the channel-level PIR for all serial interfaces on the IM.
Conditions: This issue is observed when you apply a QoS policy with a port level class-default configuration containing a shaper value to a serial interface.
Workaround: Add a dummy class-default level at the top of the policy and apply the shaper as a child policy.
- CSCud55799
Symptom: Multiple priority commands are accepted per policy.

Conditions: This issue is observed when you have a policy map with priority configured in one of its classes. Add another class with policer first and with priority.

Workaround: There is no work around.

- CSCud56364

Symptom: Convergence time for POS links for RSP SSO is about four to seven seconds.

Conditions: This issue is observed when all four POS links are created on OC-3 IM. This issue is not observed on port 0 of OC-3 IM.

Workaround: There is no work around.

- CSCud61551

Symptom: The serial number of the RSP in slot 1 is sometimes not displayed in the **show inventory** command output.

Conditions: This issue is sometimes observed in the **show inventory** command output.

Workaround: Reload the router.

- CSCud64129

Symptom: The router displays command options to configure control-plane policing, which is not supported.

```
Router(config)# control-plane
Router(config-cp)# service-policy ?
input Assign policy-map to the input of an interface
output Assign policy-map to the output of an interface
```

Conditions: This issue is observed when you attempt to configure control plane policing to restrict traffic by the CPU.

Workaround: There is no workaround. This feature is not supported.

- CSCud71286

Symptom: Configuration synchronization failure is noticed on the interfaces.

Conditions: This issue is observed when you disable autonegotiation and configure the interface speed as 100 or 1000.

Workaround: There is no workaround. There is no impact on functionality.

- CSCud90457

Symptoms: The serial interface on the CE end connected to the CEM interfaces on PE remain down on router reload with scaled configuration.

Conditions: This symptom is observed when you have CESoP and SAToP scaled circuits and reload the router.

Workaround: Perform an IM OIR to resolve the issue.

- CSCud93007

Symptom: If you use the command **channel-group 1 mode active** on a interface, the router does not reject the command.

Conditions: This issue is observed after you configure a trunk EFP MEP using the **ethernet cfm mep domain v7 mpid 1537 service v7137** command on an interface.

Workaround: There is no workaround.

- CSCud96866

Symptom: The router displays the following symptoms:

- Object download failures.
- OSPF traffic flaps.
- High CPU utilization.
- Bundling and unbundling of port-channel member links.
- Slow console updates.
- Remote MEP learning failures.

Conditions: This issue is observed when you configure CFM offloaded MEPs on a port-channel interface at a high scale and use the **shutdown** and **no shutdown** command on the port-channel interface.

Workaround: There is no workaround.

- CSCue00045

Symptom: Data traffic drops for a few groups when you use the **shutdown** and **no shutdown** commands on the interface.

Conditions: This issue is observed if join request is sent to the router within three minutes.

Workaround: There is no workaround.

- CSCue01419

Symptom: EIGRP neighborship is lost on OC3IM and OC12 IM interfaces configured on port 0.

Conditions: This issue is observed only on interfaces that are configured on port 0 of OC3IM or OC12 IM. It is not seen on ports 1,2, or 3.

Workaround: Use the **shutdown** and **no shutdown** commands on the interfaces configured on port 0. Alternatively, remove and reconfigure EIGRP.

- CSCue03418

Symptoms: Intermittently OSPF protocol flaps are noticed when you use the **redundancy force-switchover** or the **switchover** command. It can cause about 20 to 30 seconds of traffic loss.

Conditions: This symptom is observed while performing an SSO or when using the **redundancy force-switchover** command and on a HA system with 6 seconds as OSPF dead interval.

Workaround: Increase the dead interval value.

- CSCue07040

Symptom: The router continuously displays ESDHC and MMCBLK0 errors.

Conditions: This issue is observed when the SD flash memory is being accessed.

Workaround: There is no workaround. Replace or format the bootflash.

- CSCue14054

Symptom: When a port joins more number of multicast groups at a time, traffic drops for a few groups.

Conditions: This issue is observed when a port joins more than 900 multicast groups.

Workaround: Use the **shutdown** and **no shutdown** commands on that interface.

- CSCue17123

Symptom: ATM and IMA pings fail from the second interface after performing an SSO.

Conditions: This issue is observed when you have multiple ATM interfaces and perform a switchover.

- Workaround:** There is no workaround.
- CSCue18997

Symptom: In unicast mode, the PTP slave stream does not lock to the PTP master.

Conditions: This issue is observed after the PTP master configuration is removed and reconfigured.

Workaround: There is no workaround.
 - CSCue25146

Symptom: When the controller in active machine flaps, the standby machine is reloaded.

Conditions: This issue is observed when you configure ATM and the controller, use **shutdown** and **no shutdown** commands on the controller in the active machine.

Workaround: There is no workaround.
 - CSCue27652

Symptoms: The ATM interfaces are deleted while performing an SSO.

Conditions: This issue is observed when the ATM interfaces are deleted on the standby machine after performing an IM OIR.

Workaround: There is no workaround.
 - CSCue30481

Symptom: The router does not lock to the syncE clock source after a reload. It is in Q1-failed state.

Conditions: This issue is observed when you reload the router with a saved syncE configuration.

Workaround: Delete and reconfigure the clock source.
 - CSCue35295

Symptom: Traffic drops when you remove the BFD template.

Conditions: This issue is observed when you remove the BFD template from the global configuration.

Workaround: There is no workaround.
 - CSCue36239

Symptom: Match EFP policy on a port channel stops working after one of the policies on the member links is removed.

Conditions: This issue is observed when you attach a policy to all the member links on the port channel, remove it from one of the member links from which traffic flows.

Workaround: Remove policies from all the member links and reattach the policies.
 - CSCue39978

Symptom: Traffic stops in ATM PVP after performing an IM OIR followed by SSO.

Conditions: This issue is observed after performing an IM OIR followed by SSO when ATM PVP is configured.

Workaround: Reload the router.
 - CSCue43250

Symptom: IMA configuration is not parsed correctly after a router reload when the A903-IM40S module is inserted in Bay4 or Bay5 of the Cisco ASR 903 router.

Conditions: This issue is observed when the IMA and ATM interfaces are adjacent. It happens only if the IM is inserted on Bay 4 or above.

- Workaround:** Insert the IM in bay 0 or bay 3 if you want the IMA and ATM parsing to work. Alternatively, reconfigure the ATM and IMA interfaces.
- CSCue45274

Symptom: Traffic drop is seen on a port for more than 8 minutes when a BDI, which is not part of this new port is shut down.

Conditions: This issue is observed when a BDI is shut down and another port which is not a part of the shut down BDI port join the multicast group.

Workaround: There is no workaround.
 - CSCue45306

Symptom: The CEM circuits that are configured over TDM IM go down after performing an SSO.

Conditions: This issue is observed when you perform an SSO, the CEM circuits that are configured over TDM IM go down.

Workaround: Reload the router.
 - CSCue47834

Symptom: IOMd crashes and IM goes out of service during SSO.

Conditions: This issue is observed when you have ATM and IMA configured and perform an SSO. IOMd crashes and the IM goes out of service.

Workaround: There is no workaround.
 - CSCue54997

Symptom: The system accepts two input clock sources from the same OC3 IM although the system supports only one input clock source per OC3 IM. This results in clock failures.

Conditions: This issue is observed when two input clock sources are accepted from the same OC3 IM although the framer on the IM can support only one clock source.

Workaround: Do not configure the second input clock source from the same OC3 IM. Alternatively, remove both OC3 clock sources and configure the desired OC3 controller.
 - CSCue57671

Symptom: Router crashes while running the REP configuration.

Conditions: This issue is observed while removing the REP configuration from the interface.

Workaround: There is no workaround.
 - CSCue66019

Symptom: The router displays MLPPP interface errors.

Conditions: This issue is observed when there is more than 90% line rate traffic with mix MTU patterns.

Workaround: There is no workaround.
 - CSCue67835

Symptom: OSPF flaps when you set the dead interval timer as 6 seconds and hello interval as 2 seconds.

Conditions: This issue is observed when you perform an SSO.

Workaround: Use the default OSPF hello timers.
 - CSCue72481

Symptom: The same interface accepts an IP address and a MEP.

Conditions: This issue is observed when you configure an IP address and a MEP to the same interface.

Workaround: There is no workaround.

- CSCue83621

Symptom: Policy map stops working after you dynamically remove class default class.

Conditions: This issue is observed when the policy map is attached to the target and the class default of the top level is deleted dynamically, the policy stops working.

Workaround: Detach and reattach the policy map on the target.

- CSCue89503

Symptom: The power supply status reports critical after you remove and insert the power supply.

Conditions: This issue is observed after performing multiple OIRs.

Workaround: There is no workaround.

- CSCuf01120

Symptom: IOMD crash is seen while performing an SSO when card type is not configured for T1E1 IM.

Conditions: This issue is observed when the TDM card type is not configured before performing an SSO.

Workaround: Configure the card type for T1E1 IM before performing an SSO.

- CSCuf20151

Symptom: The following error message is displayed when you apply a policy map:

```
QoS: Configuration failed. Can NOT match ACL in an output policy-map
```

Conditions: This issue is observed when you apply a policy map, reload, or reconfigure of the policy map.

Workaround: There is no workaround.

- CSCuf43275

Symptom: The router does not detect traffic through GLC-FE-100EX and GLC-FE-100ZX transceivers.

Conditions: The router does not support traffic through GLC-FE-100EX and GLC-FE-100ZX transceivers.

Workaround: There is no workaround.

- CSCuf43992

Symptom: The router crashes if you configure local span.

Conditions: This issue is observed when you configure local span on the router.

Workaround: There is no workaround.

- CSCuf44077

Symptom: The **show interface** command output shows incorrect speed values after performing an SSO.

Conditions: This issue is observed when you use a 100M SFP.

Workaround: There is no impact on functionality. Reset the hardware module to resolve this issue.

- CSCuf57632

Symptoms: When you reload the router, the device may not be able to load the startup configuration from NVRAM.

Conditions: This issue is sometimes observed when you reload the router.

Workaround: Reload the router again.
- CSCuf65012

Symptom: When you perform an IM OIR on slot 4, the router may display syslog messages from the GigabitEthernet 0/5/0 port.

Conditions: This issue is observed when you perform an IM OIR on slot 4 and Slot 5.

Workaround: There is no workaround.
- CSCuf79364

Symptom: When you try configure speed on the interface on the standby machine, it does not accept the command.

Conditions: This issue is observed after you insert a new IM and GE-T connector when router is running.

Workaround: Reload the router before configuring the speed.
- CSCuf79504

Symptom: When you use the **shutdown** and **no shutdown** commands multiple times on the controller, ATM VC creation on the standby RSP fails.

Conditions: This issue is observed when you use the **shutdown** and **no shutdown** commands multiple times on the controller on active RSP.

Workaround: There is no workaround.
- CSCuf81085

Symptom: After you use the **shutdown** and **no shutdown** commands on the controller of PE, IMA VCs go down.

Conditions: This issue is observed after using the **shutdown** and **no shutdown** commands on the OC3 controller on PE routers.

Workaround: Use the **shutdown** and **no shutdown** commands on the controller.
- CSCuf85460

Symptom: When you delete the POS interface and try to create an ATM interface, the following error message is displayed:

```
%OC3.STS1 0/2/0.1:Port type not supported
Insufficient resources to create channel group
```

Conditions: This issue is observed when you reload the OC3-IM having POS interface and try to create an ATM interface.

Workaround: Create the POS interface, delete it, and the create an ATM interface.
- CSCuf89665

Symptom: Flow control identifiers of active and protect interfaces are not created on to the standby. Due to which, the interface goes down when you perform an SSO.

Conditions: This issue is observed when you set up ACR on the standby machine.

Workaround: There is no workaround.

- CSCuf89844
Symptom: The router crashes when you delete a BDI interface running BFD.
Conditions: This issue is observed when you assign a static MAC address on a neighbor router or on one of the BDI interfaces on the Cisco ASR 903 router, and delete the BDI interface running BFD on the Cisco ASR 903 router.
Workaround: There is no workaround. Do not change the MAC address on the BDI interface.
- CSCug16135
Symptom: Critical alarm LED does not illuminate. The **show facility-alarm status** command shows a critical alarm.
Condition: This issue occurs when both active and standby RSP are in UP state.
Workaround: Use the **show facility-alarm status** command to view the alarm status.
- CSCug17844
Symptom: Traffic does not match the configured class map of the applied policy.
Conditions: This issue is observed at egress, if a policy map which contains 8 user-defined class-maps is applied. As it exceeds the allowed number of class maps, traffic hits the class default.
Workaround: Remove the 8th user-defined class map and reapply the policy.
- CSCug18630
Symptom: When you perform an OIR on the standby and active RSPs, CMAND crashes.
Conditions: This issue is observed after performing multiple standby OIRs and bringing the standby machine up.
Workaround: There is no workaround.
- CSCug31212
Symptom: When you apply a policy map, the console shows an error message.
Conditions: This issue is observed when you apply a policy map with numbered ACLs.
Workaround: There is no workaround.
- CSCug31645
Symptom: If you change the template on the router and change it again within two minutes, the standby RSP is unable to synchronize with the new template and the router reloads twice.
Conditions: This issue is observed when you change the template, and change it again within two minutes before reloading the router.
Workaround: Do not change the template and change it again within two minutes.
- CSCug44762
Symptom: The POS interface stays down after using the **shutdown** and **no shutdown** commands.
Conditions: This issue is observed when you use the **shutdown** and **no shutdown** commands on the POS interface.
Workaround: Use the **shutdown** and **no shutdown** commands on the controller.
- CSCug48534
Symptom: Multicast traffic is forwarded on untagged EFPs when snooping is enabled.
Conditions: This issue is observed when untagged EFPs are shutdown at least once after it comes up.

- Workaround:** Reload the router or toggle IGMP snooping.
- CSCug55586

Symptom: If you dynamically remove the egress markings, ingress marking does not work.

Conditions: This issue is observed if a marking is present at the logical level in the egress direction, DM does not work.

Workaround: Use the egress set at leaf or PHB level.
 - CSCug58606

Symptom: When you use the **no shutdown** command, the LED of 1G and 10G IM turns off.

Conditions: This issue is observed when you use the **no shutdown** command on 1G and 10G interfaces.

Workaround: There is no workaround.
 - CSCug61357

Symptom: ISIS adjacency and BFD stay down after using the **shutdown** and **no shutdown** commands.

Conditions: This issue is observed in R-LFA configurations.

Workaround: Use the **shutdown** and **no shutdown** commands again.
 - CSCug83426

Symptom: Interface reports loss of frame alarm and goes down.

Conditions: This issue is observed when you use the **shutdown** and **no shutdown** commands on the controllers of PE and CE.

Workaround: Perform an OIR on CE side.
 - CSCug83846

Symptom: The MTU value does not take effect on an interface.

Conditions: This issue is observed when you try to configure more than eight unique MTU values on the router.

Workaround: There is no workaround.
 - CSCug94540

Symptom: The total drop counters on an interface is not displayed when HQoS policy map is applied.

Conditions: This issue is observed when you apply a two-level policy on a port.

Workaround: Use the **show policy-map interface gigabitethernet 0/0/0** command or **show hqf interface gigabitethernet 0/0/0** command.
 - CSCug96958

Symptom: IMA interfaces stay up even when you use the **shutdown** command to shut down the controller.

Conditions: This issue is observed when you use the **shutdown** command on the OC3 controller.

Workaround: Use the no shutdown command bring up the controller and interfaces.
 - CSCug99750

Symptom: The Cisco ASR 903 router crashes when it accesses unpopulated data structures.

- Conditions:** This issue is observed when you perform an IM OIR and use the **shutdown** and **no shutdown** commands.
- Workaround:** There is no workaround.
- CSCuh00009

Symptom: RSP crashes due to keepalive failure.

Conditions: This issue is observed when the router is being polled from different SNMP servers at different intervals.

Workaround: Increase the SNMP polling interval.
 - CSCuh06740

Symptom: Router gets reloaded after performing a soft OIR.

Conditions: This issue is observed after you perform a soft OIR or subsequent SSOs.

Workaround: There is no workaround.
 - CSCuh16011

Symptom: FMAN-FP crashes when you perform ab IM OIR.

Conditions: This issue is observed when you perform multiple IM OIRs with around 65 BFD sessions.

Workaround: Reload the router.
 - CSCuh18503

Symptom: BFD IPv6 sessions may not come up between Cisco ASR 9000 and Cisco ASR 903 routers.

Conditions: This issue is observed when the packets sent from Cisco ASR 903 router have invalid UDP checksums.

Workaround: There is no workaround.
 - CSCuh21696

Symptom: When you disable IGMP snooping, the IGMP control packets are not flooded on all ports.

Conditions: This issue is observed with TEFP over 10Gig, normal EFP, EFP over PC, and TEFP with IGMP SN.

Workaround: There is no workaround.
 - CSCuh27117

Symptom: Traffic loss of about six to eight seconds is observed when you perform an SSO.

Conditions: This issue is observed when you perform the switchover before IM OIR or the interface flaps.

Workaround: There is no workaround.
 - CSCuh48988

Symptom: When you create a policy map the following error message appears:

```
"Max class-maps in an Egress policy-map (port-channel_egress) cannot exceed 8"
```

Conditions: This issue is observed when a policy map with more than 8 class maps is configured.

Workaround: There is no workaround.
 - CSCuh77762

Symptom: On Cisco ASR 903 routers, the TenGigabitEthernet port operates at one gigabit speeds in WAN-PHY mode. This leads to a huge amount of output drop.

Conditions: This issue is observed if a QoS policy is configured on the TenGigabitEthernet interface.

Workaround: There is no workaround.

- CSCuh79730

Symptom: The transmitting frequency is incorrectly displayed in the output of the **show hw-module subslot 0 transceiver idprom** command.

Conditions: This issue is observed if you use DWDM-XFP-C modules.

Workaround: There is no workaround.

- CSCuh86102

Symptom: The interface stops forwarding traffic

Conditions: This issue is observed when the TenGigabitEthernet interface is in WAN-PHY mode and R0 is active.

Workaround: Use R1.



Restrictions and Caveats in Cisco IOS XE 3.11S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.11 releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

Caveats in Cisco IOS XE 3.11S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.11S releases. The following information is provided for each caveat:

- **Symptom**—A description of what is observed when the caveat occurs.
- **Conditions**—The conditions under which the caveat has been known to occur.
- **Workaround**—Solutions, if available, to counteract the caveat.

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.11S Releases:

- [Open Caveats—Cisco IOS XE Release 3.11.4S](#), page 21-2
- [Resolved Caveats—Cisco IOS XE Release 3.11.4S](#), page 21-2
- [Open Caveats—Cisco IOS XE Release 3.11.3S](#), page 21-2
- [Resolved Caveats—Cisco IOS XE Release 3.11.3S](#), page 21-3
- [Open Caveats—Cisco IOS XE Release 3.11.2S](#), page 21-3
- [Resolved Caveats—Cisco IOS XE Release 3.11.2S](#), page 21-4
- [Open Caveats—Cisco IOS XE Release 3.11.1S](#), page 21-5
- [Resolved Caveats—Cisco IOS XE Release 3.11.1S](#), page 21-6
- [Open Caveats—Cisco IOS XE Release 3.11S](#), page 21-8
- [Resolved Caveats—Cisco IOS XE Release 3.11S](#), page 21-9

Open Caveats—Cisco IOS XE Release 3.11.4S

Identifier	Description
CSCUu34256	RSP1_MCAST_THS: Ipv6 traffic does not flow with Cross connect.
CSCUu34839	RSP1_MCAST_THS: Multicast traffic deviation with VRF LITE observed.
CSCUr70758	Winpath trace buffer initialization seen on router.

Resolved Caveats—Cisco IOS XE Release 3.11.4S

There are no resolved caveats in Cisco IOS XE Release 3.11.4.

Open Caveats—Cisco IOS XE Release 3.11.3S

- CSCui71901
Ping stopped working after swapping
- CSCul58148
On setting the mtu on an interface, the **ip mtu** command is also set. When interface is set to default **ip mtu** command is not unconfigured.
- CSCum69818
Error logs seen after removal of IPv6 address on ISIS IPv6 router.
- CSCuo21766
SNMPwalk for ifHCOuUcastPkts and ifInUcastPkts table adds multicast packet in output.
- CSCuo85111
Port speed displays incorrectly with 100M SFP module on performing on OIR.

- CSCur76549
BDI interface showing incorrect byte count.

Resolved Caveats—Cisco IOS XE Release 3.11.3S

- CSCum66277
Resource leak is observed when network events like interface flaps, IM OIRs, and increase in prefix scale (beyond scale) leading to forwarding issues or router crash.
- CSCun07843
A critical alarm is observed on the FPGA port 0/5/0.
- CSCuo15916
COS classification does not work after reload.
- CSCuo76490
Small buffer and IDB leak seen with PIM registers on a the router.
- CSCup12983
Issues with MTU settings seen on POS interfaces.
- CSCup20634
Core interface ping fails when system has 7 Layer3 port-channels configured.
- CSCup87578
IPV6 MH-BFD session fail to come up when ECMP path to prefix exists.
- CSCur17529
Bulk synchronization failure occurs when ingress QoS policy is configured on the CEM circuit under CEM-ACR interface.

Open Caveats—Cisco IOS XE Release 3.11.2S

- CSCuo11380
Symptom: AIS alarm observed on OC-3 controller.
Conditions: This issue occurs during a reload or after performing multiple IM OIR.
Workaround: Perform a soft OIR on the IM.
- CSCuo40840
Symptom: Layer2 traffic on TEFPP is punted to CPU.
Conditions: This issue occurs on loading and removing the configuration using config replace procedure.
Workaround: There is no workaround.
- CSCuo85701
Symptom: Prec6 packets get incremented after interface flaps and reload is performed.
Conditions: This issue occurs after configuring policy-maps with classifying cos 6 and prec 6 packets on port channel

- Workaround:** There is no workaround.
- CSCuo95061

Symptom: Ping fails when standby configured with Hot Standby Router Protocol (HSRP) takes over from the active RSP.

Conditions: This issue occurs when standby configured with HSRP takes over from the active RSP.

Workaround: There is no workaround.
- CSCuo97889

Symptom: IPv6 traffic gets dropped while doing an SSO.

Conditions: This issue occurs during SSO.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.11.2S

- CSCul50165

Symptom: The Cisco ASR 903 fails to forward packets with the maximum configurable MTU on A900-IMA16D and A900-IMA4OS.

Conditions: This issue occurs when `mtu max MTU` interface command is executed.

Workaround: There is no workaround.
- CSCum05115

Symptom: IPv4 labeled BGP traffic drops on the router.

Conditions: This issue occurs for prefixes after a reload of the router.

Workaround: There is no workaround.
- CSCum45110

Symptom: Multicast traffic is not sent over BDI interface with IGMP snooping enabled.

Conditions: This issue occurs on the router when IGMP snooping is enabled.

Workaround: Disable IGMP snooping.
- CSCun07802

Symptom: AutoNegotiation configuration on the fiber ports is not retained after IM OIR or reload.

Conditions: This issue occurs on IM OIR/ or router reload.

Workaround: Do not disable the AutoNegotiation property on the fiber ports, else reconfigure the AutoNegotiation on the ports manually.
- CSCun47966

Symptom: Memory leak observed during ASP switchover.

Conditions: This issue occurs when APS switchover is performed.

Workaround: There is no workaround.
- CSCun70703

Symptom: Interface Module Goes to out of service after ISSU.

Conditions: This issue occurs after performing ISSU when there is a IM FPGA change.

Workaround: Perform IM FPGA upgrade using the package file and proceed with ISSU.

- CSCun75471
Symptom: Memory usage gradually increases over time, when storm control feature is enabled on the router.
Conditions: This issue is observed when storm control feature is enabled.
Workaround: There is no workaround.
- CSCun79358
Symptom: DHCP packets getting dropped on a transparent node between client and server.
Conditions: This issue occurs when global DHCP snooping is enabled on the transparent node.
Workaround: Disable the global DHCP snooping feature.
- CSCun83203
Symptom: Bandwidth percentage does not working on changing the port speed.
Conditions: This issue occurs after changing the port speed.
Workaround: There is no workaround.
- CSCuo03508
Symptom: Bulk sync failure seen on router when DAI is configured and **ip arp inspection filter nag bridge-domain static** command is executed.
Conditions: This issue occurs with DAI configuration.
Workaround: After switchover or router reload, configure the **ip arp inspection filter nag bridge-domain static** command.
- CSCuo05897
Symptom: Multicast traffic stops flowing over pseudowire on changing the configuration. The traffic does not resume till reloaded.
Conditions: This issue occurs on changing the configuration.
Workaround: Reload the device.
- CSCuo06895
Symptom: Router crash observed after reload.
Conditions: This issue occurs in normal conditions. There is no specific trigger or condition under which this may occur.
Workaround: There is no workaround.

Open Caveats—Cisco IOS XE Release 3.11.1S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.11.1S.

- CCSCul58083
Symptom: After IP mtu is configured on an interface, any change in to the MTU are not reflected on the interface.
Conditions: This issue occurs when IP MTU is configured and the MTU is changed.
Workaround: Set the required interface MTU before executing the **ip mtu** command or unconfigure the IP MTU on the interface and then change the interface MTU.

- CSCu158148
Symptom: After setting the MTU on an interface, the **ip mtu** is also set. However, when the interface is defaulted, the **ip mtu** setting is not unconfigured.
Conditions: This issue occurs when the IP address is set on the interface and MTU is configured. The issue occurs when the interface is defaulted
Workaround: Do not default the interface. Use **no mtu** command instead.
- CSCum70550
Symptom: IPv4 and MPLS TTL does not get decremented when fragmentation is involved in the same router.
Conditions: This issue occurs when IP fragmentation is performed.
Workaround: There is no workaround.
- CSCum81665
Symptom: Console errors and incremental leaks are observed on the Cisco ASR 903 router.
Conditions: This issue is observed on executing the **clear ip mroute** with pim-ssm configured for core replication.
Workaround: There is no workaround.
- CSCum85248
Symptom: Stale entries do not get timed out or get removed, even after there is no multicast traffic for the corresponding group.
Conditions: This issue occurs when the supported limit of entries is exceeded.
Workaround: Reload the router to remove the entries.

Resolved Caveats—Cisco IOS XE Release 3.11.1S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.11.1S.

- CSCuj34652
Symptom: IPv6 traffic drops for the packets with next header options. Next header options include Hop-by-hop options, fragment header.
Conditions: This issue occurs when option packets are punted to CPU and generates the time exceeded message.
Workaround: There is no workaround.
- CSCuj43795
Symptom: The port in error-disabled state & physical status shows as down but is UP on the other connected end device.
Conditions: This issue occurs when the port is configured with DHCP rate limiting values so that the port goes to error-disable state once it reaches the rate configured.
Workaround: Perform a **shutdown** followed by a **no shutdown** on the respective interface to move the port to UP state.
- CSCuj60771
Symptom: Self-generated DHCP traffic generating out of the router is not getting marked (cos) with user specified value.

Conditions: This issue occurs when DHCP packets (CPU to client) are not getting marked.

Workaround: There is no workaround.

- CSCuj83619

Symptom: DHCP binding does not happen with multiple clients over T-EFP.

Conditions: This issue occurs when TEFP with multiple vlans are configured.

Workaround: Configure EFPS instead of TEFP.

- CSCul65485

Symptom: Wrong speed and bandwidth is displayed with DWDM XFP

Conditions: This issue occurs when the DWDM XFP is inserted and the **show interface** command is executed.

Workaround: There is no workaround.

CSCul65832

Symptom: Multicast VPN traffic is not received by the receivers.

Conditions: This issue occurs the multicast traffic is begins and joins the VRFs.

Workaround: Increase the MTU size of the core interface on the router that is not forwarding the mVPN traffic.

- CSCul70905

Symptom: Warning messages are seen when an HSRP group is configured on the physical interface.

Conditions: This issue occurs when an HSRP group is configured on the physical interface.

Workaround: There is no workaround.

- CSCum14431

Symptom: MVPN traffic is incorrectly received by the receivers due to core replication not working.

Conditions: This issue occurs when large scale is present or when data MDT is used with scale for MVPN.

Workaround: Use default MDT.

- CSCum26178

Symptom: Bert does not go in sync with hard loop; The reports display that the BERT is running forever. The BERT cannot be stopped and a new BERT cannot be started.

Conditions: This issue occurs when hard loop is configured on OC-3 controller. The BERT is not in sync & BERT is running forever & new BERT cannot be started.

Workaround: There is no workaround.

- CSCum65037

Symptom: The **set ip next-hop peer-address** command configured within a route-map does not appear in the running-configuration, causing a loss in configuration across a reload.

Conditions: This issue occurs in Unified MPLS for Mobile transport model with IGP-LDP Access, IGP routes (mainly CSG loopbacks) from Access ring would be redistributed into BGP in the pre-aggregation device (Cisco ASR 903 router). When this happens, IGP next hops that are directly connected to the pre-aggregation devices are treated as BGP next hops in the local BGP database of the pre-aggregation device. Hence when the corresponding link goes down, there might be unnecessary BGP next hop scan for AF IPv4 taking place.

Workaround: Reconfigure the **set ip next-hop peer-address** command within the route-map after reboot of the device to get the intended functionality.

- CSCum69866

Symptom: ONS-SC-155-EL optic does not get recognized by the router when inserted in the OC-3 IM.

Conditions: This issue occurs on insertion of ONS-SC-155-EL optic in OC-3 IM in the router. An error message gets displayed on the console that the transceiver is not supported. The optic does not get detected in **show inventory** command output.

Workaround: There is no workaround.

- CSCum81574

Symptom: Ingress PE node with pim-ssm gets crashed on sending multicast traffic.

Conditions: This issue occurs when the node gets crashed when core MDT routes reach around 1K with the video template.

Workaround: There is no workaround.

- CSCum92427

Symptom: Ping fails when ARP type goes to UNKNOWN state.

Conditions: This issue occurs when the Cisco ASR 903 router resides between the DHCP server and a Cisco ASR 901 router, which acts as a helper.

Workaround: Perform a **shutdown** followed by a **no shutdown** on the interface. Execute **clear arp-cache** to clear the cache.

Open Caveats—Cisco IOS XE Release 3.11S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.11S.

- CSCuh86847

Symptom: When MR-APS CEM feature is configured on the router, the traffic stops flowing on deletion and recreation of CEM groups and cross connects.

Conditions: This issue occurs after deletion and recreation of CEM groups is performed and after a few iterations of performing an RSP SSO on a HA configured router.

Workaround: Perform an OIR of the OC-3 IM to resume the traffic.

- CSCuj60116

Symptom: WANPHY:SYNC-E does not get synced in WAN mode.

Conditions: This issue occurs in WAN mode.

Workaround: There is no workaround.

- CSCul15030

Symptom: Traffic drops for few seconds then resumes for 2-3 minutes.

Conditions: This issue may be observed with a specific topology.

Workaround: There is no workaround.

- CSCul21349

Symptom: Crash is observed after seeing out of TCAM entries on the console.

Conditions: This issue occurs after seeing out of TCAM entries on the console.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.11S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.11S.

- CSCuf35542

Symptom: Precise Frequency Monitor (PFM) fails for about 5 minutes after OIR is performed.

Conditions: This issue occurs after an OIR is triggered.

Workaround: Wait for 5-6 minutes after an OIR.

- CSCug05491

Symptom: The router drops traffic on VPLS circuits.

Conditions: This issue occurs when REP is configured with VLAN load balancing and VPLS VFI is configured on the VLANs. This issue occurs after Stateful switchover (SSO) is performed.

Workaround: There is no workaround.

- CSCug39899

Symptom: Traffic stops flowing through QinQ BDI interface after ARP times out and the ARP is removed by shutting the BDI interface.

Conditions: This issue occurs when static routing is configured and no routing protocol is configured on the interface.

Workaround: Manually resolve ARP by pinging the next hops BDI interface.

- CSCug44762

Symptom: POS interface stays down after a **shutdown** followed by a **no shutdown** on POS interface.

Conditions: This issue is seen when a **shutdown** followed by a **no shutdown** is performed on POS interface.

Workaround: Perform **shutdown** followed by a **no shutdown** on the controller.

- CSCug50283

Symptom: Only 2-path are utilized for load sharing though 3-path is available.

Conditions: This issue occurs when ECMP is configured.

Workaround: There is no workaround.

- CSCug61505

Symptom: The **platform enable** command is seen for ACR virtual controller when OC-3 IM is present in slot 0.

Conditions: This issue occurs after configuring **aps group acr** command on the OC-3 controller.

Workaround: Insert the IM in other bays instead of bay 0.

- CSCug83434

Symptom: Lot of memory leak chunks are seen for FMANRP on the standby RSP.

Conditions: This issue occurs after memory leaks are verified on standby RSP.

Workaround: Perform a router reload.

- CSCug84082
Symptom: ATM/IMA PVP links configured on either T1/E1 IM or OC-3IM exhibit traffic or ping failure.
Conditions: This issue occurs when ATM/IMA link flaps and is followed by SSO. Link flap can be IM OIR, etc.
Workaround: Performing an IM OIR may fix the issue, else perform a router reload.
- CSCug84428
Symptom: Traffic drop are seen on the T1/E1 IM serial and MLPPP links.
Conditions: This issue occurs when traffic is sent via streams with jumbo packet sizes of 7000 bytes or larger. The interfaces toggle between the up/down state.
Workaround: Perform a IM OIR of the T1/E1 IM.
- CSCug89348
Symptom: IOSXE_RP_SPA-3-IPCPORTFAIL tracebacks are seen on router with high availability configured.
Conditions: This issue occurs after SSO is performed.
Workaround: There is no workaround.
- CSCug92536
Symptom: PLATFORM-3-NOMAC traceback is seen on standby console.
Conditions: This issue is seen when CEM-ACR is configured on a HA setup.
Workaround: There is no workaround.
- CSCug96958
Symptom: IMA interfaces stay up when controller is shutdown.
Conditions: This issue occurs after performing an admin shutdown on OC-3 controller.
Workaround: Perform **no shutdown** on the controller.
- CSCug97639
Symptom: IPv4 VRF ping fails when disabling IPv6 unicast-routing globally on the router.
Conditions: This issue occurs when IPv6 unicast-routing is disabled.
Workaround: Enable IPv6 unicast-routing
- CSCuh06123
Symptom: Incorrect quality level (QL) mapping between the clock class and quality level on the PTP master.
Conditions: This issue is seen when QL value is configured before configuring the PTP master.
Workaround: Reconfigure the QL values or reload the router.
- CSCuh18073
Symptom: In a domain with 2 BGP exit points acting in Active or Repair mode, the traffic exits the domain through Repair Path BGP PE instead of exiting through Active Path BGP PE.
Conditions: This issue exists when the environment has 2 BGP exit points.
Workaround: There is no workaround.
- CSCuh22045

Symptom: Small MTU size is not fragmented on the OC-3 IM.

Conditions: This issue occurs after a reload and SSO is performed.

Workaround: Unconfigure and configure the IM.

- CSCuh46103

Symptom: The BDI statistics do not get incremented on the router.

Conditions: This issue occurs when the ingress and egress statistics are displayed using the **show interface bdi** or **show interface bdi stats** command.

Workaround: Use **show platform hardware pp active interface statistics bdi** command.

- CSCuh81658

Symptom: PTP packets are being treated as default packets even though QoS policy is configured

Conditions: This issue occurs after CPU generated PTP packets do not reach egress QoS with high priority label (15 or 126) and hence does not hit the corresponding default port entries or even the EFP policy's control entries matching these labels.

Workaround: There is no workaround.

- CSCuh93765

Symptom: The interface goes down reporting loss of frame alarm.

Conditions: This issue occurs on performing **shutdown** followed by a **no shutdown** on the PE and CE.

Workaround: Perform an OIR on CE side.

- CSCui22637

Symptom: Crash observed on the router after unconfiguring 1000 psuedowires.

Conditions: This issue occurs after unconfiguring 1000 psuedowires at a stretch.

Workaround: There is no workaround.

- CSCui30240

Symptom: SPA is not initialized messages are seen on bootup.

Conditions: This message is seen post bootup as well during **shutdown** command followed by a **no shutdown** command is issued on the controller. This issue occurs on remote PE reload.

Workaround: Disable console logging.

- CSCui34041

Symptom: Traffic is not flowing for one of the prefix.

Conditions: This issue occurs when the MAX MPLS label of that template is assigned to that prefix.

Workaround: Disable and enable that prefix.

- CSCui34989

Symptom: OC-3 IM IOMD crash is seen post SSO.

Conditions: This issue occurs after SSO is performed.

Workaround: There is no workaround.

- CSCui47776

Symptom: Virtual circuit receive counters do not increment after SSO is performed.

Conditions: This issue occurs when 1000 VCs are configured and SSO is performed.

- Workaround:** There is no workaround.
- CSCui52938

Symptom: Layer 3 interface adjacency is incomplete.

Conditions: This issue occurs after the RSP is removed from the router.

Workaround: There is no workaround.
 - CSCui55567

Symptom: Traffic convergence for OC-3 IM with TDM features such as serial, MLPPP or POS is high after RSP SSO.

Conditions: This issue occurs after SSO is performed.

Workaround: There is no workaround.
 - CSCui75901

Symptom: Sync packets are not sent at a regular interval by the router and inter-packet gap is not within the standard range.

Conditions: This issue occurs under normal conditions.

Workaround: There is no workaround.
 - CSCui97872

Symptom: The controller remains in disabled state after enabling the license.

Conditions: This issue occurs on performing IM OIR or framing.

Workaround: Disable the license and enable it.
 - CSCuj06140

Symptom: SPAN captured packet has wrong destination MAC address.

Conditions: This issue is seen when MPLS-TP BFD packet is captured.

Workaround: There is no workaround.
 - CSCuj07507

Symptom: High convergence for downstream traffic observed on the router.

Conditions: This issue occurs when VPLS VFI's controlled by g.8032 open ring with a large scale of about 500VC's and 10000 MAC address (40 per BD).

Workaround: Use a lower MAC address scale.
 - CSCuj46477

Symptom: Layer 2 multicast traffic stops on VPLS VCs and starts flowing back on the ingress EFP.

Conditions: This issue occurs when one of the VPLS VC goes down.

Workaround: Traffic resumes after the VC comes up.
 - CSCuj55599

Symptom: ARP request for HSRP VRRP MAC (VMAC) is not punted to CPU.

Conditions: This issue occurs while sending unicast ARP packets on the router.

Workaround: There is no workaround.
 - CSCuj76162

Symptom: The input error counter constantly increases in **show platform infrastructure lsmapi** command.

Conditions: This problem occurs when the synchronous mode is configured on the interface of router.

Workaround: There is no workaround.

- CSCul14925

Symptom: The following message displays on the console:

```
%PMAN-3-PROCHOLDDOWN: SIP1: pman.sh: The process iomd has been helddown (rc 143)
```

Conditions: When you perform a hard interface module (IM) online insertion and removal (OIR), IM pull out, or soft IM OIR and IOMD is gracefully terminated from the kernel.

Workaround: There is no workaround. There is no service impact.



Restrictions and Caveats in Cisco IOS XE 3.12S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.12S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.12S Releases, page 22-1](#)

Caveats in Cisco IOS XE 3.12S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.10S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.12S Releases:

- [Open Caveats—Cisco IOS XE Release 3.12.4S, page 22-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.12.4S, page 22-3](#)
- [Open Caveats—Cisco IOS XE Release 3.12.3S, page 22-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.12.3S, page 22-3](#)
- [Open Caveats—Cisco IOS XE Release 3.12.2S, page 22-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.12.2S, page 22-5](#)
- [Open Caveats—Cisco IOS XE Release 3.12.1S, page 22-7](#)
- [Resolved Caveats—Cisco IOS XE Release 3.12.1S, page 22-7](#)
- [Open Caveats—Cisco IOS XE Release 3.12S, page 22-9](#)
- [Resolved Caveats—Cisco IOS XE Release 3.12S, page 22-9](#)

Open Caveats—Cisco IOS XE Release 3.12.4S

There are no open caveats in Cisco IOS XE Release 3.12.4S.

Resolved Caveats—Cisco IOS XE Release 3.12.4S

Identifier	Description
CSCut55741	Wrong extraneous fan entries in Entity MIB.

Open Caveats—Cisco IOS XE Release 3.12.3S

There are no open caveats in Cisco IOS XE Release 3.12.3S.

Resolved Caveats—Cisco IOS XE Release 3.12.3S

Identifier	Description
CSCur77331	Led Indicator on ASR903 showing down after port flapping for XCONNECT

Open Caveats—Cisco IOS XE Release 3.12.2S

This section documents the issues that have are open in Cisco IOS XE Release 3.12.2S.

- [CSCtg39038](#)
Symptom: Memory leak observed on router causing router reload.
Conditions: This issue occurs under normal conditions.
Workaround: There is no workaround.
- [CSCuc58315](#), [CSCup09007](#)
Symptom: Router crashed observed on unconfiguring the CEM interface without logging out of the CEM configuration mode.
Conditions: This issue occurs on adding and removing the CEM interface configuration.
Workaround: Exit from the sub-mode before issuing the **no xconnect** command.
- [CSCul90379](#)
Symptom: In Virtual Private Wire Service (VPWS) configuration, some circuits remain down in the Standby RP and after SSO is performed.
Conditions: This issue occurs after single MTU change operation to update MTU to a valid value is performed on a set of interfaces (in the range of 100's).

Workaround: Retry MTU change either on a smaller set of interfaces or on those interfaces separately for which circuits are down.

- CSCum69818

Symptom: Error logs seen on removal of IPv6 address on the BDI interface.

Conditions: This issue occurs after removal of IPv6 address or IPv6 ISIS router on the BDI interface.

Workaround: There is no workaround.

- CSCun19434

Symptom: Memory leaks observed on router.

Conditions: This issue occurs when DMVPN crypto sessions are configured.

Workaround: There is no workaround.

- CSCun30855
Symptom: Configurations are not removed on standby RSP after unconfiguring 63 CEM channels on active RSP.
Conditions: This issue occurs after unconfiguring 63 CEM channels on active RSP on OC-3 controller.
Workaround: There is no workaround.
- CSCuo55797
Symptom: Inter VRF ping fails in router memory leak.
Conditions: This issue occurs after pinging a VRF prefix in a different VRF.
Workaround: There is no workaround.
- CSCuq19954
Symptom: The IOS OAM implementation displays incorrect values for dying gasp conditions for “Power Failure” and “Physical Down”.
Conditions: This issue occurs when a "Physical Down" or "Power Failure" dying gasp is sent when an IOS box is peering with an IOX box.
Workaround: Interpret a dying gasp reported as "Physical Down" as actually being "Power Failure" and vice versa.
- CSCuq60722
Symptom: PID disappears after standby RSP reboot.
Conditions: This issue occurs on standby RSP reboot.
Workaround: There is no workaround.
- CSCur06724
Symptom: Local ping fails with host queue in stuck state.
Conditions: This issue occurs when a packet descriptor may get corrupted leading to host queue in stuck state.
Workaround: Reload the router.

Resolved Caveats—Cisco IOS XE Release 3.12.2S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.12.2S.

- CSCud65150
Symptom: Router crash observed to an address error.
Conditions: This issue occurs due to a Kron policy configuration.
Workaround: Remove the Kron configurations from the system.
- CSCui93830
Symptom: H-QoS top level service-policy fails on the router after switching between RSP modules.
Conditions: This issue occurs after switching RSP modules.
Workaround: Reattach the policy-map.

- CSCul15647
Symptom: ACL QoS classification breaks with IPSec tunnel.
Conditions: This issue occurs with ACL classification in policy-map and is applied to a physical interface. QoS pre-classify is configured under IPSec tunnel.
Workaround: Apply a QoS to IPSec tunnel.
- CSCun83203
Symptom: Bandwidth percentage does not work on changing the port speed.
Conditions: This issue occurs on changing bandwidth percentage.
Workaround: There is no workaround.
- CSCuo05897
Symptom: Multicast traffic stops flowing over pseudowire on changing the configuration.
Conditions: This issue occurs when BDI goes down and comes up.
Workaround: Reload the device.
- CSCuo15916
Symptom: COS classification does not work after router reload.
Conditions: This issue occurs on a policy with class-map having cos match configuration and reload is performed.
Workaround: Remove and re-apply the policy-map.
- CSCuo26304
Symptom: CMAND logs have invalid function call messages.
Conditions: This issue is observed on reload.
Workaround: There is no workaround.
- CSCuo76490
Symptom: Small buffer and IDB leak seen with PIM registers on the router.
Conditions: This issue was observed with PIM registers egressing a BDI interface.
Workaround: Block PIM registers using boundaries.
- CSCup03259
Symptom: Memory leak observed in normal buffer output of router.
Conditions: This issue occurs under normal conditions.
Workaround: Remove the **qos pre-classify** command in the crypto map. Reload the device. Use the **memory-size iomem** command to assign more memory.
- CSCup12983
Symptom: MTU settings on POS interface do not work correctly.
Conditions: This issue occurs when POS is unconfigured.
Workaround: There is no workaround.
- CSCup20634
Symptom: Core interface ping fails when system has seven Layer3 port-channels.
Conditions: This issue occurs on the Ten Gigabit IM inserted in slot 1.

- Workaround:** There is no workaround.
- CSCup34371
Symptom: GETVPN GM stops decrypting traffic after TEK rekey.
Conditions: This issue occurs on crypto map.
Workaround: There is no workaround.
 - CSCup49206
Symptom: Restarting the router may flush and later originate default type-5 LSA during NSF/NSR restart. The flush may cause traffic loss.
Conditions: This issue occurs on NSF or NSR restart.
Workaround: There is no workaround.
 - CSCuq12880
Symptom: RSP1A crashes when multicast VPN configuration is used but SDM profile remains default.
Conditions: This issue occurs when **show platform hardware pp active nqatm 0 ipv4tunnel all** command is executed.
Workaround: Use correct SDM profile.

Open Caveats—Cisco IOS XE Release 3.12.1S

There are no open caveats in Cisco IOS XE Release 3.12.1S.

Resolved Caveats—Cisco IOS XE Release 3.12.1S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.12.1S.

- CSCum05115
Symptom: IPv4 labelled BGP traffic drops on the router.
Conditions: This issue occurs for prefixes after a reload of the router.
Workaround: There is no workaround.
- CSCum45110
Symptom: Multicast traffic is not sent over BDI interface with IGMP snooping enabled.
Conditions: This issue occurs on the router when IGMP snooping is enabled.
Workaround: Disable IGMP snooping.
- CSCum96961
Symptom: Continuous increase in output drop counters observed on the interface despite no traffic flow through the interface.
Conditions: This issue occurs on port-channel configurations with QoS applied on them.
Workaround: Remove the QoS configuration.
- CSCun07802
Symptom: AutoNegotiation configuration on the fiber ports is not retained after IM OIR or reload.

Conditions: This issue occurs on IM OIR/ or router reload.

Workaround: Do not disable the AutoNegotiation property on the fiber ports, else reconfigure the AutoNegotiation on the ports manually.

- CSCun07843

Symptom: Critical alarm goes out on FPGA of port.

Conditions: This issue occurs after performing an SSO on the router.

Workaround: There is no workaround.

- CSCun35642

Symptom: Class-map filter modification do not work for uninstalled policy-maps.

Conditions: This issue occurs when a policy-map with 2 classes exist on the router. Modify the class-map filter gets rejected.

Workaround: Remove the class from the policy-map and modify it.

- CSCun79358

Symptom: DHCP packets getting dropped on a transparent node between client and server.

Conditions: This issue occurs when global DHCP snooping is enabled on the transparent node.

Workaround: Disable the global DHCP snooping feature.

- CSCuo03508

Symptom: Bulk sync failure seen on router when DAI is configured and **ip arp inspection filter nag bridge-domain static** command is executed.

Conditions: This issue occurs with DAI configuration.

Workaround: After switchover or router reload, configure the **ip arp inspection filter nag bridge-domain static** command.

- CSCuo06895

Symptom: Router crash observed after reload.

Conditions: This issue occurs in normal conditions. There is no specific trigger or condition under which this may occur.

Workaround: There is no workaround.

- CSCuo09866

Symptom: Forwarding Manager (FMAN) FP logs filled with error messages.

Conditions: This issue is observed on image upgrade.

Workaround: There is no workaround.

Further Problem Description:

- CSCuo90854

Symptom: P TV does not work with RSP1B video template.

Conditions: This issue occurs when BDI numbers lesser than 4000 is used.

Workaround: Use BDI numbers greater than 4000.

Open Caveats—Cisco IOS XE Release 3.12S

This section documents the unexpected behavior that might be seen with the Cisco ASR 900 router in Cisco IOS XE Release 3.12.S.

- CSCun13151

Symptom: Egress traffic drop was observed on an ACR ATM interface in PVP mode.

Conditions: This issue occurs on the ACR ATM interface after performing SSO.

Workaround: There is no workaround.

Resolved Caveats—Cisco IOS XE Release 3.12S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.12S.

- CSCui50577

Symptom: Traffic drop observed on the router.

Conditions: This issue occurs after performing an IM OIR.

Workaround: There is no workaround.

- CSCuj30644

Symptom: Multicast does not function in scaled mode with SM mode and BDI in core.

Conditions: This issue was seen in the scaled mode.

Workaround: Execute the **no ip igmp snooping** command on the router to forward multicast traffic.

- CSCuj32358

Symptom: Multicast packets with TTL=0 are forwarded and not dropped.

Conditions: This issue occurs with multicast incoming traffic with TTL=0.

Workaround: There is no workaround.

- CSCuj42208

Symptom: Layer 3 multicast traffic drop was observed on the trunk port.

Conditions: This issue occurs when multicast is converged, and a **shutdown** followed by a **no shutdown** command is executed on the multicast router interface (mrouter port).

Workaround: Execute command **clear ip mroute** command to clear IPv4 multicast routes and the command **clear ipv6 pim topology** to clear IPv6 multicast routes.

- CSCuj43701

Symptom: Multicast receivers received duplicate traffic.

Conditions: This issue occurs in the following conditions:

- Executing a **shutdown** command or **default shutdown** command on the last EFP under a bridge-domain configured on the port-channel interface.
- Executing a **shutdown** or **default shutdown** command on the last TEFP under a bridge-domain configured on the port-channel interface.
- Executing a **shutdown** or **default shutdown** command on the port-channel and configuring an EFP or TEFP without waiting for at least 3 minutes.

- Deleting the last TEFP on a particular NILE (either 0 or 1 or both) and immediately configuring EFP under the same port and for the same bridge-domain.

Workaround: Clearing multicast routes for the multicast group receiving duplicate traffic may resolve the issue. Execute command **clear ip mroute** command to clear IPv4 multicast routes and the command **clear ipv6 pim topology** to clear IPv6 multicast routes.

- CSCuj49095

Symptom: The router displays an OUT_OF_TCAM error message on the console.

Conditions: This issue occurs when a PIM-enabled interface is added or deleted.

Workaround: Reload the router.

- CSCuj49110

Symptom: S/N entries are allocated for BDI in down state.

Conditions: This occurs when the BDI state is down.

Workaround: There is no workaround.

- CSCuj56146

Symptom: Deletion of last EFP configured under port-channel fails to update ASIC in the router. The EFP is removed from the running configuration but the router continues to forward multicast traffic on the last EFP configured under the port-channel.

Conditions: This issue occurs under the following conditions:

- Defaulting port-channel interface.
- Executing the shut or no shut commands on the port-channel interface.
- Executing the shut or no shut commands on the last EFP of a bridge-domain under the port-channel.

Workaround: There is no workaround.

- CSCuj56513

Symptom: Multicast traffic was flooded back on Source Tx port.

Conditions: This issue occurs when:

- The router is configured with PIM-SM.
- IIF is the Trunk EFP (BDI) and OIF is used as the Regular EFP.
- Both IIF and OIF are in the same bridge-domain (BD).

The Trunk EFP IIF configuration is removed with (either no service instance or port default) and a Normal EFP is configured on the same IIF Port belonging to the same BD.

Workaround: Execute the **clear ip mroute** command.

- CSCul01233

Symptom: EMPLSintd memory leak is observed on configuration and unconfiguration of remote LFA FRR tunnels.

Conditions: This issue occurs when memory leaks are seen on interface flap or after unconfiguring and configuring the remote LFA FRR.

Workaround: There is no workaround.

- CSCul10120

Symptom: Self ping fails when ICMP punt traffic congests the host queue.

- Conditions:** This issue occurs when the host queue is congested by ICMP punt traffic for a long time.
- Workaround:** There is no workaround.
- CSCul27129

Symptom: Remote MEPs are not learnt on cross-connect service with a POS interfaces the core link.

Conditions: This issue occurs when CFM up MEPs are configured for an cross-connect service configured on an access interface, with POS links in core.

Workaround: There is no workaround.
 - CSCul37563

Symptom: Packet drop observed after resetting the multilink bundle more than 3 or 4 times.

Conditions: This issue occurs on an MLPPP interface over channelized STM.

Workaround: Configure the remote end to accept compressed packets.
 - CSCul40676

Symptom: Ping failure observed on the interface connected with port 0/0/0 with ACR configuration.

Conditions: This issue occurs when ACR is configured on the router.

Workaround: Install the IM in the other bay or use a port other than 0/0/0 as the core.
 - CSCul64840

Symptom: The router shuts down when the SNMP host is enabled by executing the **snmp-server host** command globally.

Conditions: This issue occurs when the **snmp-server host** command is executed.

Workaround: Use the management interface VRF for the SNMP host.
 - CSCul68008

Symptom: Bulk synchronization fails for ATM layer 2 configuration on T1E1 IM is observed on the router.

Conditions: This issue occurs on TDM IM with ATM configuration.

Workaround: There is no workaround.
 - CSCul93778

Symptom: No alarm is reported after executing the **shutdown** command on the controller, when high availability (HA) is setup.

Conditions: This issue occurs when a POS interface is created on an HA setup, and a **shutdown** command is executed on the interface after SSO.

Workaround: There is no workaround.
 - CSCum66060

Symptom: Increased usage of MPLSintd observed after scale configuration and stress test. Interface flaps and BFD flaps are observed on the router.

Conditions: This issue occurs with increased usage in MPLSintd resource leading to router crash over a prolong period of time.

Workaround: There is no workaround.
 - CSCum69866

Symptom: ONS-SC-155-EL optic is not recognized by the router when inserted in the OC-3 IM.

Conditions: This issue occurs when the ONS-SC-155-EL optic is inserted in the OC-3 IM on the router. An error message is displayed on the console indicating that the transceiver is not supported. The optic is not detected when the **show inventory** command is executed.

Workaround: There is no workaround.

- CSCum92427

Symptom: Ping fails when the ARP type is in UNKNOWN state

Conditions: This issue occurs when the Cisco ASR 903 router acts as a helper and resides between the DHCP sever and a Cisco ASR 901 router.

Workaround: Execute the **shutdown** command followed by the **no shutdown** command on the interface. Execute **clear arp-cache** command, to clear the cache.

- CSCun08534

Symptom: IGMP snooping is not supported with the IP services license, thereby breaking multicast routing.

Conditions: This issue occurs with IP service licenses.

Workaround: Disable IGMP snooping and cause flooding of multicast packets.



Restrictions and Caveats in Cisco IOS XE 3.13S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.13S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.13S Releases, page 23-1](#)

Caveats in Cisco IOS XE 3.13S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.13S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.10S Releases:

- [Open Caveats—Cisco IOS XE Release 3.13.7S, page 23-2](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.7S, page 23-2](#)
- [Open Caveats—Cisco IOS XE Release 3.13.6S, page 23-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.6S, page 23-3](#)
- [Open Caveats—Cisco IOS XE Release 3.13.5S, page 23-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.5S, page 23-4](#)
- [Open Caveats—Cisco IOS XE Release 3.13.4S, page 23-4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.4S, page 23-4](#)
- [Open Caveats—Cisco IOS XE Release 3.13.3S, page 23-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.3S, page 23-5](#)
- [Open Caveats—Cisco IOS XE Release 3.13.2S, page 23-6](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.2S, page 23-6](#)
- [Open Caveats—Cisco IOS XE Release 3.13.1S, page 23-7](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13.1S, page 23-7](#)
- [Open Caveats—Cisco IOS XE Release 3.13S, page 23-8](#)
- [Resolved Caveats—Cisco IOS XE Release 3.13S, page 23-10](#)

Open Caveats—Cisco IOS XE Release 3.13.7S

Caveat ID Number	Description
CSCvb24913	ASR903 - Last reload reason can be misleading
CSCur98481	Service unsupported-transceiver does not change the behavior

Resolved Caveats—Cisco IOS XE Release 3.13.7S

Caveat ID Number	Description
CSCus82338	In loose mode uRPF ipv4/6 traffic dos not get dropped for NUI10 interface

Open Caveats—Cisco IOS XE Release 3.13.6S

Identifier	Description
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCur98481	service unsupported-transceiver does not change the behavior
CSCut93166	Last IMA Link Added Stuck in DOWN State on Delete and Add Few Links
CSCuq19919	Nsn_hsbby data traffic is observing on Standby link in RSP2

Resolved Caveats—Cisco IOS XE Release 3.13.6S

Identifier	Description
CSCuv73613	Policy shaping 90% is not working for QOS in egress-RSP1
CSCux81666	Policy shaping 90% is not working in egress direction
CSCuw57376	External alarms cleared on 2nd SSO

Open Caveats—Cisco IOS XE Release 3.13.5S

Identifier	Description
CSCux21020	BGP/BFD session goes down on REP interface state change
CSCun30277	"show platform hardware pp active feat cef database prefix" CLI remove
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCup76962	RSP2:IOMD traceback @mcprp_spa_tdl_marshal_err
CSCur98481	service unsupported-transceiver does not change the behavior
CSCut93166	Last IMA Link Added Stuck in DOWN State on Delete and Add Few Links
CSCun10191	ATM:IFMGR-3-DUP_IFINDEX: Duplicate ifIndex error msg on stby
CSCuq32740	TDM System Test : Traceback pointing to IMA on reload on PE
CSCuq11133	ASR903: TDM IM crash on ISSU rolling upgrade

Identifier	Description
CSCuq19919	Nsn_hsby data traffic is observing on Standby link in RSP2

Resolved Caveats—Cisco IOS XE Release 3.13.5S

Identifier	Description
CSCuv57383	RSP1: In rare situations , mpls is not enabled in hardware after upgrade
CSCuv30635	RSP1: standby rsp led not glowing post ISSU

Open Caveats—Cisco IOS XE Release 3.13.4S

Identifier	Description
CSCuv67090	ASR903 Egress InterfaceID Misprogrammed from MPLS to IP path
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCuw39821	ASR903 acting as MVPN 'P' device duplicates multicast traffic
CSCuw06487	%SYS-2-CHUNKBADMAGIC: Traceback on router when using PTP
CSCuv30635	RSP1: standby rsp led not glowing post ISSU
CSCup76962	RSP2:IOMD traceback @mcprp_spa_tdl_marshal_err
CSCur98481	service unsupported-transceiver does not change the behavior
CSCut93166	Last IMA Link Added Stuck in DOWN State on Delete and Add Few Links
CSCuq32740	TDM System Test : Traceback pointing to IMA on reload on PE
CSCuq11133	ASR903: TDM IM crash on ISSU rolling upgrade

Resolved Caveats—Cisco IOS XE Release 3.13.4S

Identifier	Description
CSCut86756	"sh platf hardware pp active acl ipv6 name ACL_OUT" shows incorrect o/p

Identifier	Description
CSCut86740	Egress IPv6 ACL doesn't work on router reload
CSCus70811	Cannot configure bridge domain with id more than max bridge domains
CSCut33723	error counters getting incremented on ports which are down
CSCuv37266	PPPoE sessions not getting established across VPN betwn 903(RSP2) and 9K
CSCuu10463	Traffic is getting drop over TEFP after dynamic range modification
CSCut08392	Array Boundary violation in code.
CSCur69542	Crash @nile_mc_handle_prefix_L2_and_not_L3
CSCut84743	IGMPSN is taking more memory consumption on high scale in latest MCP
CSCut92954	RSP1 : IPv6 traffic doesnt flow over VPLS
CSCuu64975	10 gig port goes down at remote side once the system locked after reboot
CSCuv39362	BFD flaps during RFC2544 test
CSCuu35013	Crash seen when qos is applied on EVC with encap untagged
CSCuu56931	Outdrops seen on ten gig interface that is not part of I2 connectivity.
CSCut02011	ASR-902, ASR-903 & ASR-920 show interface transceiver is not dependable
CSCup07145	Error log seen @ quack_main.c:quack_write: write failed:.
CSCut99827	IMA Group Up Though Far-end Signalled Insufficient Links Group State

Open Caveats—Cisco IOS XE Release 3.13.3S

There are no open defects in Cisco IOS XE Release 3.13.3S.

Resolved Caveats—Cisco IOS XE Release 3.13.3S

Identifier	Description
CSCus60787	ACL counter does not work when applying IPv6 ACL to BDI intf on egress.
CSCut40156	IPv6 ACL causes LDP down and ospf flap.
CSCut28876	xconnect uni-directional traffic when new xconnect built or moved.
CSCut03279	OC12/3: Forwarding alarm for CESOP does not propagate.
CSCus97020	The router crashes on configuring Ethernet loopback.

Identifier	Description
CSCur83200	Policy on encapsulation default not working.
CSCus60755	The router crashes due to memory leak.
CSCur77326	TenGig interface remains down with EVC configuration.
CSCus62460	BGP flap when Ping is sent continuously at 18 mbps.
CSCus16433	Incorrect values in entSensorThresholdEvaluation for SPA subslot sensors.
CSCus98172	GLC-EX-SMD %SFF8472-3-THRESHOLD_VIOLATION
CSCup71022	WANPHY: incorrect behavior with L-RDI and UNEQ-P alarm inject.

Open Caveats—Cisco IOS XE Release 3.13.2S

This section documents the unexpected behavior that might be seen with the Cisco ASR 900 router in Cisco IOS XE Release 3.13.2S.

- [CSCun69848](#)
ACR ATM: unconfiguring and configuring followed by SSO multiple issues are seen.
- [CSCup71022](#)
ASR 903:WANPHY:incorrect behavior with L-RDI and UNEQ-P alarm inject.
- [CSCuq11133](#)
ASR 903: TDM IM crash on ISSU rolling upgrade.
- [CSCur77326](#)
ASR 903 TenGig interface remains down with EVC configuration.
- [CSCus05877](#)
RPF-Failure packets are not filtered by IPv4 ACL applied over SVI.
- [CSCus14747](#)
ASR 903- CPU generated L2/L3 packets not sent via proper queues on egress.
- [CSCus16433](#)
Incorrect values in entSensorThresholdEvaluation for SPA Subslot Sensors.

Resolved Caveats—Cisco IOS XE Release 3.13.2S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.13.2S.

- [CSCur06724](#)
ASR 903: Local ping fails with Host queue node in stuck state.
- [CSCur13616](#)
TLDP not up over PW.
- [CSCur17529](#)
Bulk sync failure in case of ingress QoS policy on CEM-ACR interface.
- [CSCur19046](#)

- Traffic drop due to wrong PW programming.
- CSCur31007
ASR 903: Error handling in uea_mpls_frr_modify_fld.
- CSCur37740
Crash after SNMP polls transceiver information.
- CSCur52148
Image upgrade using reload command causing FP reset and stuck in init state.
- CSCur88602
Disable VASI related commands on ASR 903.
- CSCur96455
ARP not generated in VRF when MPLS packet received from POS/TDM interface.

Open Caveats—Cisco IOS XE Release 3.13.1S

This section documents the unexpected behavior that might be seen with the Cisco ASR 900 router in Cisco IOS XE Release 3.13.1S.

- CSCuo77420
The router crashes and reloads in a multi-D scale environment.

Resolved Caveats—Cisco IOS XE Release 3.13.1S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.13.1S.

- CSCuo05897
Multicast traffic stops flowing over pseudowire after changing the configuration. The traffic does not resume till reloaded.
- CSCuo26304
CMAND logs are filled with invalid function call messages after reload.
- CSCuo67326
Group specific query forwarded by the Layer 3 interface is not sent out of the router.
- CSCuo95061
Ping failure observed when HSRP configured Standby module is taken over from Active module.
- CSCup12983
Issues with MTU settings on POS interface are observed on the router.
- CSCup99088
OIDs for the USB-Ports, Network-Management-Port and the CPU are not seen on the standby RSP.
- CSCuq12880
The RSP1A module crashes when mVPN configuration is used but SDM profile remains default instead of mvpn_rsp1a.

- CSCuq17910
Symptom: With a third party APS, the router interprets traffic incorrectly wrongly causing a APS revert to working port while protect port should remain active.
- CSCuq32699
Track unicast on router using commands
 1. show platform hardware pp active feature cef database ipv4 10.0.0.2/32 0
 2. show platform hardware pp active feature multicast database ipv4 table 0 226.0.0.4/32 3.
 3. show platform hardware pp active adjmgr l3m_print_nh_handle 0x342014d8
- CSCur17185
Error messages observed on router followed by traceback on issuing **show interfaces transceiver detail** command.

Open Caveats—Cisco IOS XE Release 3.13S

This section documents the unexpected behavior that might be seen with the Cisco ASR 900 router in Cisco IOS XE Release 3.13S.

- CSCuo94567
Symptom: Delay request packets stop after moving to `FREQ_LOCKED` state.
Conditions: This issue occurs after moving to the `FREQ_LOCKED` state.
Workaround: There is no workaround.
- CSCuo97779
Symptom: Crash observed on the router after clearing the counters and logging buffer.
Conditions: This issue occurs after clearing the counters and logging buffer.
Workaround: There is no workaround.
- CSCup09987
Symptom: For port-channel interface, broadcast packets incorrect values during SNMP MIB query.
Conditions: This issue occurs during SNMP MIB query.
Workaround: There is no workaround.
- CSCup25290
Symptom: Router crash observed after overnight interface flaps. The protocol flaps and continuous churn is network is observed.
Conditions: This issue occurs when overnight network churn occurs.
Workaround: There is no workaround.
- CSCup26783
Symptom: High convergence observed during local interface shutdown with remote LFA is configured.
Conditions: This issue occurs when remote LFA is configured.
Workaround: There is no workaround.
- CSCup48672

Symptom: BGP goes down after recreating the POS interface.

Conditions: This issue occurs after the recreating the POS interface.

Workaround: Perform a shutdown followed by a no shutdown of the POS interface.

- CSCup49082

Symptom: IPV6 traffic (both up and downstream) is taking traffic hit of 2200 msec but IPV4 traffic took normal hit (well under the committed down time of 50 msec)

Conditions: This issue occurs after performing ISSU upgrade.

Workaround: There is no workaround.

- CSCup54245

Symptom: Traffic does not flow when IMA PVP is configured and SSO is performed.

Conditions: This issue occurs when incorrect MPLS labels are configured and SSO is performed.

Workaround: There is no workaround.

- CSCup56048

Symptom: Cross connect configuration goes down after performing an SSO after an OIR.

Conditions: This issue occurs after performing and SSO after an OIR.

Workaround: Perform an IM OIR.

- CSCup57265

Symptom: Missing alarms observed on transceiver module.

Conditions: This issue occurs on the RJ45 ports with 8-port Cu 1xGE IM + 1-port SFP 1x GE (Copper combination) IM inserted on RSP2 chassis.

Workaround: Shutdown all the unused ports on this IM.

- CSCup60018

Symptom: Traffic loss observed after performing SSO post IM OIR.

Conditions: This issue occurs after performing an SSO post IM OIR.

Workaround: Reload the router.

- CSCup67271

Symptom: Match_efp egress policy-map replication does not happen on all member-links for port-channel Ids from 17 to 64

Conditions: This issue occurs on port-channel Ids from 17-64.

Workaround: Apply policy-map on all the member-links.

- CSCup82219

Symptom: PFM failure occurs while changing the mode from LAN to WAN on the AA900-IMA2Z IM.

Conditions: This issue was observed on the AA900-IMA2Z IM. It is an intermittent issue.

Workaround: Reconfigure the LAN mode to WAN mode.

- CSCup87274

Symptom: High convergence observed on SSO for MR-APS CEM configuration. Traffic does not resume completely on all configured circuits.

Conditions: This issue occurs on performing an IM OIR or controller shutdown or an APSs force prior to SSO. The issue may also be seen on repeated SSO.

Workaround: Perform a APS SSO.

- CSCup87578

Symptom: IPV6 MH-BFD session fail to come up when there is ECMP path to prefix.

Conditions: This issue occurs when IPV6 MH-BFD session fails if there is ECMP path.

Workaround: There is no workaround.

- CSCup97273

Symptom: ISIS goes down following heavy traffic hitting management port(70 mbps). CPU spike was also observed.

Conditions: The issue occurs following a loop in the management network and excess of 70 mbps traffic hits the management port.

Workaround: Reload the chassis.

Resolved Caveats—Cisco IOS XE Release 3.13S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.13S.

- CSCul72354

Symptom: Traffic failure observed for some of prefixes which are learned through BGP.

Conditions: This issue occurs when a sheer load (more than 100 PE's) of next hops with recurring routes are learned on the router with BGP PIC enabled.

Workaround: Disable BGP PIC.

- CSCum02329

Symptom: MPLS MTU cannot be configured on an interface that is not programmed in the hardware.

Conditions: This issue occurs when MPLS MTU is configured on an interface; MPLS MTU value is not programmed in the hardware and a packet larger than MPLS MTU value is allowed.

Workaround: Use IP MTU or interface MTU instead of MPLS MTU.

- CSCum05115

Symptom: IPv4 Labelled BGP traffic drops on the router.

Conditions: This issue is observed for a few prefixes post reload.

Workaround: There is no workaround.

- CSCum42701

Symptom: Tx and Rx power values are incorrectly displayed on OC-3 interface module.

Conditions: This issue occurs on the OC-3 interface module.

Workaround: Hard OIR of the OC-3 interface module.

- CSCum45110

Symptom: Multicast traffic is not sent over BDI interface with IGMP snooping is enabled.

Conditions: This issue occurs when IGMP snooping is enabled.

Workaround: Disable IGMP snooping.

- CSCum54906
Symptom: Crash observed on the router after executing the **show interface pseudowire** command.
Conditions: This issue occurs after executing the **show interface pseudowire** command.
Workaround: There is no workaround.
- CSCum69866
Symptom: The ONS-SC-155-EL optic is not recognized when inserted in OC-3 IM.
Conditions: This issue occurs when the ONS-SC-155-EL optic is inserted in OC-3 IM. An error message is displayed on the console that the transceiver is not supported. The optic is detected in show inventory command output.
Workaround: There is no workaround.
- CSCum92427
Symptom: Ping fails when ARP type becomes "UNKNOWN".
Conditions: This issue occurs when the router is configured for ZTP and the IP address is issued from the DHCP server. The ARP type on the router connected to the ASR 901 router interface becomes "UNKOWN".
Workaround: Perform a **shutdown** followed by a **no shutdown** of the ASR 901 router (interface vlan), or execute the **clear arp-cache** command.
- CSCum96961
Symptom: After application of a QoS policy-map on an interface, continuous increase in output drop counters on the interface is observed despite there being no traffic through the interface.
Conditions: This issue occurs on the router with port-channel configurations with QoS applied.
Workaround: Remove the QoS configurations.
- CSCun07802
Symptom: Auto Negotiation configuration on Fiber ports is not retained.
Conditions: This issue occurs on IM OIR or chassis reload.
Workaround: Do not disable Auto Negotiation property on the fiber ports. Else reconfigure or disable the Auto Negotiation on the ports manually.
- CSCun07843
Symptom: A critical alarm is observed on the FPGA port 0/5/0.
Conditions: This issue occurs after performing an SSO.
Workaround: There is no workaround.
- CSCun35642
Symptom: Class-map filter modification does not work for an un-installed policy-map.
Conditions: This issue occurs when a policy-map is configured with 2 classes. When the class-map filter is modified, the filter modification is rejected.
Workaround: Remove the class from the policy-map and modify.
- CSCun47966
Symptom: Memory leak observed during ASP switchover.
Conditions: This issue occurs when APS switch is performed.
Workaround: There is no workaround.

- CSCun70703
Symptom: Interface Module goes to Out of service state.
Conditions: This issue occurs on performing an ISSU when there is a IM FPGA change between the releases.
Workaround: Perform IM FPGA upgrade using the package file and proceed with ISSU.
- CSCun75471
Symptom: Process memory usage gradually increases over time when storm control is enabled on the router.
Conditions: This issue is observed when storm control feature is enabled on the router.
Workaround: There is no workaround.
- CSCun79358
Symptom: DHCP packets get dropped on the transparent node between client and server.
Conditions: This issue occurs when global DHCP snooping is enabled on the transparent node.
Workaround: Disable the global DHCP snooping command.
- CSCun83203
Symptom: Bandwidth percentage does not work on changing the port speed.
Conditions: This issue occurs after changing the port speed with sequence.
Workaround: There is no workaround.
- CSCuo03508
Symptom: Bulk sync failure seen on DAI API using **ip arp inspection filter nag bridge-domain static** command.
Conditions: This issue occurs when DAI is configured using the using **ip arp inspection filter nag bridge-domain static** command. After routed reload is not accepted and not synchronized to standby.
Workaround: After switchover or router reload, reconfigure the command.
- CSCuo06895
Symptom: Router crash observed with reload as RP-Reset.
Conditions: There is no specific trigger or condition under which this may occur.
Workaround: There is no workaround.
- CSCuo09866
Symptom: FMAN FP logs filled with error messages.
Conditions: This issue occurs on reload.
Workaround: There is no workaround.
- CSCuo55797
Symptom: Inter VRF ping failure observed in route leak.
Conditions: This issue occurs while pinging other VRF prefix in different a VRF.
Workaround: There is no workaround.
- CSCuo72279
Symptom: Crash observed after a failover during the MPLS labels processing.

Conditions: This issue was observed when R-LFA and BGP PIC is configured in the RING topology and optimum scale prefix (with global and VRF prefix) is set.

Workaround: There is no workaround.

- CSCuo76490

Symptom: Small buffer and IDB leak seen with PIM registers on a Cisco router.

Conditions: This issue was first observed with PIM registers egressing a BDI interface.

Workaround: Block PIM registers using boundaries.

- CSCuo90854

Symptom: IP TV does not working with RSP1B Video template.

Conditions: This issue occurs when BDI numbers greater than 4000 is configured.

Workaround: Configure BDI numbers lesser than or equal to 4000.

- CSCup20634

Symptom: Core interface ping failure observed when system has 7 Layer3 port-channels configured.

Conditions: This issue occurs when the a 10 GE IM is inserted in slot 1 on the router.

Workaround: There is no workaround.



Restrictions and Caveats in Cisco IOS XE 3.14S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.14S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.14S Releases, page 24-1](#)

Caveats in Cisco IOS XE 3.14S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.14S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.14S Releases:

- [Open Caveats—Cisco IOS XE Release 3.14.3S, page 24-2](#)
- [Resolved Caveats—Cisco IOS XE Release 3.14.3S, page 24-2](#)
- [Open Caveats—Cisco IOS XE Release 3.14.2S, page 24-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.14.2S, page 24-3](#)
- [Open Caveats—Cisco IOS XE Release 3.14.1S, page 24-3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.14.1S, page 24-4](#)
- [Open Caveats—Cisco IOS XE Release 3.14S, page 24-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.14S, page 24-7](#)

Open Caveats—Cisco IOS XE Release 3.14.3S

Identifier	Description
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCuv37266	PPPoE sessions not getting established across VPN betwn 903(RSP2) and 9K
CSCuw59358	MPLS forwarding drops on interface due to incorrect 2nd level EAID
CSCut92954	RSP : IPv6 traffic doesnt flow over VPLS
CSCuu35013	Crash seen when qos is applied on EVC with encap untagged
CSCuv45494	ZR optics, link is going down over a period of time

Resolved Caveats—Cisco IOS XE Release 3.14.3S

Identifier	Description
CSCut86740	Egress IPV6 ACL doesn't work on router reload
CSCus82338	In loose mode uRPF ipv4/6 traffic not dropped for NUI10 interface
CSCut03410	OC12/OC3 :PDH level shut in SATOP is not asserting AIS on remote CE
CSCut33723	error counters getting incremented on ports which are down
CSCuw39821	ASR903 acting as MVPN 'P' device duplicates multicast traffic
CSCur69542	Crash @nile_mc_handle_prefix_L2_and_not_L3
CSCur67324	Crash @uea_l3mc_group_get_member
CSCut84743	IGMPSN is taking more memory consumption on high scale in latest MCP
CSCuu64975	10 gig port goes down at remote side once the system locked after reboot
CSCuu56931	Outdrops seen on ten gig interface that is not part of 12 connectivity
CSCuv62761	CPU due to cmand process is always at 90%
CSCup07145	Error log seen @ quack_main.c:quack_write: write failed

Identifier	Description
CSCus53278	IOMD crash @ iomd_bsess_open_callback_retry
CSCuv30635	RSP1: standby rsp led not glowing post ISSU
CSCur98481	service unsupported-transceiver does not change the behavior
CSCus87139	AIS Sent on CESoPSN E1 even after L-bit Cleared by Remote PE
CSCus94620	RSP1/2/3: Standby Reset due to "RF Client Expiry Cat6k SPA TSM(1505)"

Open Caveats—Cisco IOS XE Release 3.14.2S

Identifier	Description
CSCut33723	Error counters are incremented on ports that are down.
CSCuu10641	All the interfaces are in the admin down state after a router upgrade.

Resolved Caveats—Cisco IOS XE Release 3.14.2S

Identifier	Description
CSCut28876	xconnect uni-directional traffic when new xconnect is built or moved.
CSCus97020	The router crashes on configuring Ethernet loopback.
CSCur82708	Egress policy not working after removing and recreating PC.
CSCut88397	RSP2: Egress exp classification not working as expected.
CSCut26934	CEM-ACR CEMoUDP: IOSd crash after reload.
CSCus94994	False power, voltage and bias THRESHOLD_VIOLATION alarms for BX10-U.
CSCut38645	No traffic passing through Tengig 12 and 13 connected "SFP-GE-T".
CSCut31422	Unable to enable 'OC3 Interface' in Smart License mode.
CSCur29027	32T1E1: Ping failure observed on second multilink interface.

Open Caveats—Cisco IOS XE Release 3.14.1S

Identifier	Description
CSCus60755	Router crashes due to memory leak.
CSCur82708	Egress policy does not after removing and recreating PC
CSCus92763	The show platform hardware feature cef command displays incorrect values

Resolved Caveats—Cisco IOS XE Release 3.14.1S

Identifier	Description
CSCur76202	DHCP packets with vlan tag fail to flow with DHCP snooping.
CSCur77326	The Ten Gigabit Ethernet interface remains down with EVC configuration.
CSCur88602	Disable Vasi commands on the router.
CSCus94059	The SFP+ link flaps and does not come up with combo interface modules.
CSCur96455	ARP is not generated in VRF when MPLS packet are received from POS or TDM interfaces
CSCur31007	Error handling seen after FRR configuration
CSCur13616	Targeted LDP not come up over pseudowire.
CSCur37740	Crash observed after SNMP polls the transceiver information.

Open Caveats—Cisco IOS XE Release 3.14S

This section documents the unexpected behavior that might be seen with the Cisco ASR 900 router in Cisco IOS XE Release 3.14S.

- CSCuq00263
A new EFP is added after performing SSO.
- CSCuq35676
Traceback observed on unconfiguring or reconfiguring ACR working and protect groups on one port to another. These tracebacks are seen when ACR-CEM group from work and protect ports are unconfigured and configured in new ports.
- CSCuq39533
Traceback error message invalid segment observed on router.
- CSCuq49685
EoMPLS traffic drops after a **clear ip route** command is executed on the imposition router.
- CSCuq54176
CPU HOG and traceback observed on link flaps in G8032 ring.
- CSCuq54343
Router does not send OAM dying gasp messages before the port is error disabled.
- CSCuq60503
IPv6 ping over cross connect does not work.
- CSCuq73280
Policer creation fails due to policer reservation for CoPP on performing ISSU.
- CSCuq83650
Connection Manager error observed on soft OIR of router.
- CSCuq83689
Serial links keep flapping on the work and protect nodes after OIR of ACR CEM interface module.
- CSCuq94190
Multicast traffic loss is seen with BFD.
- CSCur00633
High convergence is seen with mrouter in port shut state and with the receiver router in REP ring configuration.
- CSCur13502
OAM remote loopback functionality does not work.
- CSCur13616
Targeted LDP sessions between customer edge devices flaps every 3 minutes.
- CSCur20971
Crash observed in punt path API with 500 cross connects with egress policy map.
- CSCur25147
Crash observed on SSO with multicast.

- CSCur28807
CPU hogs observed after executing the show bridge-domain command.
- CSCur29027
Ping not working properly for second multilink interface on 32port T1/E1 interface module/
- CSCur37740
SNMP polling entSensorThresholdTable crashes on system IOSd. This occurs when SPA transceiver entity sensors exist in the entity table.
- CSCur37847
Serial interface module physical port details are not populated in entPhysicalTable.
- CSCur47619
Bridge domain EFP-bind error objects are not seen on continuous or multiple interface flaps on the router.
- CSCur50091
Traffic not reaching the receivers after configuring REP on defaulted core interfaces.
- CSCur69485
L4 classification does not work on Layer2 port-channel after reload.
- CSCur69877
CCM TDL leaks are observed with CFM configured.
- CSCur74387
The source interface of a RSPAN session in shutdown state does not forward traffic after reload.
- CSCur74496
Traffic stops flowing after removing APS configuration from protect controller.
- CSCur76202
DHCP packets with VLAN tag get dropped on a transparent node between client and server.
- CSCur76549
BDI interface show incorrect byte count.
- CSCur78086
Data path breaks observed after SSO on T1/E1 controllers.

Resolved Caveats—Cisco IOS XE Release 3.14S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.14S.

- CSCuh55919
Track unicast on router using command:
 1. show platform hardware pp active feature cef database ipv4 10.0.0.2/32 0
 2. show platform hardware pp active feature multicast database ipv4 table 0 226.0.0.4/32 3.
 3. show platform hardware pp active adjmgr l3m_print_nh_handle 0x342014d8
- CSCuo05897
Multicast traffic stops flowing over pseudowire on changing the configuration. Traffic does not resume till reloaded.
- CSCuo21766
SNMPwalk for ifHCOOutUcastPkts & ifInUcastPkts tables adds multicast packets.
- CSCuo23361
Standby router reloads continuously.
- CSCuo38668
With the DAI configuration, the BDI goes to err-disable state instead of physical port when a Trunk EFP is configured at the access side.
- CSCuo39893
Egress SPAN large packets (size > 208B) gets dropped.
- CSCuo45869
Error or pending objects observed after copying the configuration to the running configuration on the router.
- CSCuo46174
Multicast traffic not forwarded over BDI with SSO on FHR.
- CSCuo47380
Traffic drops in the MST region during IM-OIR followed by an SSO.
- CSCuo54454
IPv6 multicast traffic does not recover with IM OIR followed by a **shutdown** and **no shutdown** command.
- CSCuo67326
Group specific query forwarded by the Layer3 interface is not sent out of the router.
- CSCuo70249
The UP Meps are not learnt when port channel is down.
- CSCuo76490
Small buffer and IDB leak are seen with PIM registers on the router.
- CSCuo87731
IP SLA session ID not found with different encapsulation on core & access port.

- CSCuo89567
Transceiver missing alarms seen on RJ45 ports with the Copper Combo interface module.
- CSCuo90224
RS232 type port is configurable through using command.
- CSCuo95061
Ping failure observed when HSRP standby takes over from active router.
- CSCup01578
Active FP stuck in disconnecting state.
- CSCup06436
ToD format NMEA ZDA is supported on the router.
- CSCup08732
Mismatch errors observed on the RSP card types post switchover.
- CSCup09960
The SNMP MIB do not work on the port channel.
 - ifHCInUcastPkts (1.3.6.1.2.1.31.1.1.1.7)
 - ifHCOutUcastPkts (1.3.6.1.2.1.31.1.1.1.11)
- CSCup09987
Broadcast packet information is displayed incorrectly for port-channel through SNMP MIB query.
- CSCup12983
Issues with MTU settings observed on POS interface.
- CSCup20221
The BITS LED remains GREEN on unconfiguration of the input-source.
- CSCup20634
Core interface ping fails when system has seven Layer3 port-channels configured.
- CSCup68102
Unsupported configuration errors are seen when trying to configure SPAN between 10 Gigabit Ethernet and 1 Gigabit Ethernet ports.
- CSCup99732
DB output is not seen for active ethernet CFM pm sessions.
- CSCuq06466
Ingress classification based on DSCP and ACL does not work. The packets get classified as class-default.
- CSCuq12880
RSP module crashes with mVPN configuration, but SDM profile remains default instead of mvpn_rsp1a.
- CSCuq17910
With a third party APS, the router interprets traffic incorrectly wrongly causing a APS revert to working port while protect port should remain active.

- CSCuq19919
The TEFP on the standby interfaces TEFP is exists in the flood MET.
- CSCuq23746
Multicast traffic fails on the router.
- CSCuq26416
ACM is does not on RSP2 module.
- CSCuq65062
Layer2protocol forward does not traffic on slots 0,1,2 of the interface.
- CSCur17185
Error followed by traceback on issuing show interfaces transceiver detail command.
- CSCur17529
Bulk sync failure occurs when ingress Qos policy is configured on the CEM circuit under CEM-ACR interface.
- CSCur21171
SNMP and RADIUS not working when **cemudp reserve bay x** command is configured under loopback used for SNMP or RaDIUS.



Restrictions and Caveats in Cisco IOS XE 3.15S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.15S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.15S Releases, page 25-1](#)

Caveats in Cisco IOS XE 3.15S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.15S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.15S Releases:

- [Open Caveats—Cisco IOS XE Release 3.15.2S, page 25-2](#)
- [Resolved Caveats—Cisco IOS XE Release 3.15.2S, page 25-2](#)
- [Open Caveats—Cisco IOS XE Release 3.15.1S, page 25-4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.15.1S, page 25-4](#)
- [Open Caveats—Cisco IOS XE Release 3.15S, page 25-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.15S, page 25-5](#)

Open Caveats—Cisco IOS XE Release 3.15.2S

Identifier	Description
CSCur63705	ASR903-RSP1:memleak @mcp_eobc_rx_interrupt in ha box with mpls
CSCus98671	ENMIM:DPIDX_LKUP_ERR on standby
CSCut09880	ASR903: On SDH TUG2 E1 Shut RAI is Detected at RX and CEM M-bits are Set
CSCus68778	CEMoUDP-T1/E1:Serial interface shows up/down after reload
CSCur90777	RSP2THS:MRAPS ping fails after 4 aps sso
CSCuq34656	mLDP:FID,INL3IDC_NONVLAN, POLICERD
CSCur20933	RSP2: Multicast ping is not working over the P2MP Tunnel
CSCut13887	ASR903-RSP2: Unable to configure the threshold levels for EQOS tcam
CSCus21083	RPW/RVPLS: BFD for OSPF between BDIs does not come up
CSCus98350	CPLD version shown in Show platform is HW revision instead of CPLD version
CSCuv61769	parser configuration cache interface adds shutdown to the interface configuration
CSCuv83498	STATIC EAID DUPLICATE CREATION ATTEMPT error seen on config-replace

Resolved Caveats—Cisco IOS XE Release 3.15.2S

Identifier	Description
CSCut68540	ACR:OIR of protect IM,OIR of work IM causes some cem circuits to go down

Identifier	Description
CSCUs70811	Cannot configure bridge domain with id more than max bridge domains
CSCUv66661	ELB does not swap MAC when ELB is enabled as Internal mode in ASIC 1
CSCUt84743	IGMPSN is taking more memory consumption on high scale in latest MCP
CSCUu64975	10 gig port goes down at remote side once the system locked after reboot
CSCUu35013	Crash seen when qos is applied on EVC with encap untagged
CSCUs98172	ASR903 GLC-EX-SMD %SFF8472-3-THRESHOLD_VIOLATION: Warning
CSCUv62761	CPU due to command process is always at 90%
CSCUp07145	Error log seen @ quack_main.c:quack_write: write failed
CSCUu85439	32xT1E1 IM Low Amplitude on E1 signal
CSCUt61651	ASR903 crashed in Pseudowire function
CSCUt99827	IMA Group Up Though Far-end Signalled Insufficient Links Group State
CSCUu17435	cylon mgr crash in RSP2 upon applying L3 acl on EVC and EVC in PC
CSCUv37358	Stale TCAM after removing BDI with ACL and reconfiguring
CSCUu36976	VPLS traffic is not taking correct route while sending the traffic out
CSCUv77921	ASR920 does not allow the dhcp packet to be parsed with option 82
CSCUu27902	CCMs on port channel member getting punted with port channel IDB
CSCUt55709	cfm_mp_ifh OBJ-DWNLD failure while reload the router
CSCUv00831	Failure to match local dying gasp on Ethernet line card
CSCUu74961	Intermittent failures of dying gasp seen on Pegasus
CSCUu43214	OAM remote loopback is failing for Trunk EFP traffic
CSCUv66875	Port MEP entry have not been removed fully when delete port MEP from DUT
CSCUs55728	Tagged traffic not forwarded via efp with "untag, priority-t, dot1q" encap
CSCUv46278	valgrind: local datastructure was allocated twice for ELB FID
CSCUv13923	ZTP process is not stopped with ztp clear command
CSCUv04666	% Unable to find mpls-te-dest-list modedisco" message seen during bootup

Identifier	Description
CSCut97251	router crash @ nl2mcm_igmp_snooping_enable
CSCuu58725	ASR920 / Eth CFM PM, sends default domain level 7
CSCuu52410	Match-all class with multi-match works when added in a specific sequence
CSCuv44538	Memory leak due to EFP policer on ASR 920
CSCut91272	service-policy is disappears after reload
CSCuu10641	all the interfaces are admin down state after router upgrade
CSCuv01055	ASR 920 - Remote Ping is not working on Ten gig port with Extended Vlan
CSCuv07771	ASR920:Incorrect error message displayed while try to load wrong ROMMON
CSCuv35142	IM1X IM interfaces are admin down state after router upgrade
CSCuu00644	ZTP service instance config failed to apply on Tengig interface
CSCut97628	crete UI: Observing traffic drop when license changed from onegig to bulk

Open Caveats—Cisco IOS XE Release 3.15.1S

Identifier	Description
CSCuu36976	VPLS traffic is not taking correct route while sending the traffic out

Resolved Caveats—Cisco IOS XE Release 3.15.1S

Identifier	Description
CSCut40156	IPV6 ACL causes LDP down and OSPF flap
CSCut28876	ASR903: xconnect uni-directional traffic when new xconnect is built or moved
CSCuu52794	ASR903: L-bit in Rx SAToP packets does not trigger AIS to be Tx into TDM AC
CSCut03410	OC12/OC3: PDH level shut in SATOP is not asserting AIS on remote CE
CSCut13789	IPv6 multicast traffic is not switched in bd on RPF failure
CSCup58590	mLDP: IOSXE-PLATFORM:kernel: lsmpt_transmit_thread messages on console

Identifier	Description
CSCus87139	AIS sent on CESoPSN E1 even after L-bit cleared by remote PE
CSCus87631	ASR903 reloads when using TCP raw sockets
CSCut26934	CEM-ACR CEMoUDP: IOsd crash after reload
CSCur02351	P2MPTE: MFIB HW counter shows incorrect average packet size for IIF as Lspvif
CSCuu35146	ASR920: snmp-server enable traps syslog does not work
CSCuw63344	HSRP/VRRP group scale numbers for RSP1 and RSP2

Open Caveats—Cisco IOS XE Release 3.15S

Identifier	Description
CSCus68778	CEMoUDP-T1/E1:Serial interface shows up/down after reload
CSCup58590	mLDP: IOSXE-PLATFORM:kernel: lsmpi_transmit_thread messages on Console
CSCur20933	RSP2: Multicast ping is not working over the P2MP Tunnel
CSCut24768	ASR920 - Egress policy with shaping is not working
CSCut36129	Egress Classification on Core of MPLS does not work with Transport Vlan COS

Resolved Caveats—Cisco IOS XE Release 3.15S

Identifier	Description
CSCur76202	DHCP packets with vlan tag fail to flow with dhcp snooping transparent
CSCus72769	Jumbo packets not going from serial Intf to gig Intf on RSP1 on reload
CSCur17185	%SF8472-3-INTERNAL_ERROR: CE0/2/0: ether sub-block missing
CSCur10101	ASR903 : OC3 IM LED state: Even after removal of cable, LED stays green
CSCuq43201	Port channel MAC address overlapping
CSCur29193	HC+BC sending packets to downstream when it is in <code>FREQ_LOCKED</code> .
CSCuq37233	ASR920: Jitter generation failed on 2x10G IM

Identifier	Description
CSCuq87532	Striker Current calculation
CSCum47925	RSP2/RSP1:SSO convergence time of ~0.9 sec with 100m SFP.
CSCup93720	Link Alarms are not persistent after reload on the combo CU IM



Restrictions and Caveats in Cisco IOS XE 3.16S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.16S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections

- [Limitations and Restrictions in IOS XE Release 3.16.1aS](#)
- [Caveats in Cisco IOS XE 3.16S Releases, page 26-2](#)

Limitations and Restrictions in IOS XE Release 3.16.1aS

- ISSU upgrade may fail when the EVC is configured with split horizon group configuration. We recommend that before upgrading from Cisco IOS XE Release 3.16.1aS to another Cisco IOS XE release, you do the following:
 - Save the running configuration in bootflash
 - Upgrade the router
 - Remove the split-horizon group number from the split-horizon configuration
 - Apply the changed configuration to the running configuration.
- This is applicable only to Cisco ASR 903 RSP2 module. Traffic is dropped when packets of size 64 to 100 bytes are sent on 1G and 10G ports:
 - For 64-byte packets, traffic drop is seen at 70% and beyond of the line rate.
 - For 90-byte packets, traffic drop is seen at 90% and beyond of the line rate
 - For 95-byte packets, traffic drop is seen at 95% and beyond of the line rate.

Traffic is dropped when:

- Traffic is sent on a VRF interface
- Traffic is sent across Layer 2 and Layer 3

However, traffic is not dropped when the packet size is greater than 100 bytes, even if the packets are sent bi-directionally at the line rate.

Limitations and Restrictions in IOS XE Release 3.16.2

- ISSU might fail during the upgrade to Cisco IOS XE 3.16.2, due to FPGA upgrade on standby. This issue is observed with the T1/E1 interface modules.

Caveats in Cisco IOS XE 3.16S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.16.1aS releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.16S Releases:

- [Open Caveats—Cisco IOS XE Release 3.16.10S \(Cisco IOS Release 15.5\(3\)S10\)](#), page 26-3
- [Resolved Caveats—Cisco IOS XE Release 3.16.10S \(Cisco IOS Release 15.5\(3\)S10\)](#), page 26-3
- [Resolved Caveats—Cisco IOS XE Release 3.18.10S \(Cisco IOS Release 15.5\(3\)S10 Platform Independent\)](#), page 26-3
- [Open Caveats—Cisco IOS XE Release 3.16.9S \(Cisco IOS Release 15.5\(3\)S9\)](#), page 26-4
- [Resolved Caveats—Cisco IOS XE Release 3.16.9S \(Cisco IOS Release 15.5\(3\)S9\)](#), page 26-4
- [Open Caveats—Cisco IOS XE Release 3.16.8S \(Cisco IOS Release 15.5\(3\)S8\)](#), page 26-4
- [Resolved Caveats—Cisco IOS XE Release 3.16.8S \(Cisco IOS Release 15.5\(3\)S8\)](#), page 26-4
- [Open Caveats—Cisco IOS XE Release 3.16.8S \(Cisco IOS Release 15.5\(3\)S8\)](#), page 26-4
- [Resolved Caveats—Cisco IOS XE Release 3.16.8S \(Cisco IOS Release 15.5\(3\)S8\)](#), page 26-4

- [Open Caveats—Cisco IOS XE Release 3.16.6S \(Cisco IOS Release 15.5\(3\)S6\)](#), page 26-5
- [Resolved Caveats—Cisco IOS XE Release 3.16.6S \(Cisco IOS Release 15.5\(3\)S6\)](#), page 26-5
- [Open Caveats—Cisco IOS XE Release 3.16.5S \(Cisco IOS Release 15.5\(3\)S5\)](#), page 26-6
- [Resolved Caveats—Cisco IOS XE Release 3.16.5S \(Cisco IOS Release 15.5\(3\)S5\)](#), page 26-6
- [Open Caveats—Cisco IOS XE Release 3.16.4S \(Cisco IOS Release 15.5\(3\)S4\)](#), page 26-7
- [Resolved Caveats—Cisco IOS XE Release 3.16.4S \(Cisco IOS Release 15.5\(3\)S4\)](#), page 26-7
- [Open Caveats—Cisco IOS XE Release 3.16.3aS \(Cisco IOS Release 15.5\(3\)S3a\)](#), page 26-8
- [Resolved Caveats—Cisco IOS XE Release 3.16.3aS \(Cisco IOS Release 15.5\(3\)S3a\)](#), page 26-8
- [Open Caveats—Cisco IOS XE Release 3.16.2 \(Cisco IOS Release 15.5\(3\)S2a\)](#), page 26-9
- [Resolved Caveats—Cisco IOS XE Release 3.16.2 \(Cisco IOS Release 15.5\(3\)S2a\)](#), page 26-9
- [Open Caveats—Cisco IOS XE Release 3.16.1aS \(Cisco IOS Release 15.5\(3\)S1a\)](#), page 26-11
- [Resolved Caveats—Cisco IOS XE Release 3.16.1aS \(Cisco IOS Release 15.5\(3\)S1a\)](#), page 26-12
- [Open Caveats—Cisco IOS XE Release 3.16S \(Cisco IOS Release 15.5\(3\)S\)](#), page 26-13
- [Resolved Caveats—Cisco IOS XE Release 3.16S \(Cisco IOS Release 15.5\(3\)S\)](#), page 26-13

Open Caveats—Cisco IOS XE Release 3.16.10S (Cisco IOS Release 15.5(3)S10)

There are no open caveats in this release.

Resolved Caveats—Cisco IOS XE Release 3.16.10S (Cisco IOS Release 15.5(3)S10)

There are no open caveats in this release.

Resolved Caveats—Cisco IOS XE Release 3.18.10S (Cisco IOS Release 15.5(3)S10 Platform Independent)

Caveat ID Number	Description
CSCuv14856	WATCHDOG timeout crash during IPSEC phase 2
CSCvf16448	No all IPv6 GRE crypto tunnels may come up or recover from flapping at scale
CSCvm76452	IPSec background crash while sending SNMP trap
CSCvm95236	BGP update not properly processed by inbound route-map
CSCvn78113	Tunnel PMTUD not being aged out after PMTUD ager timer expires
CSCvo66216	IPSec-Session count in "show crypto eli" reaches max causing VPN failure
CSCvo71721	When sending account-logon ISG do not reply with ACK nor NACK.

Caveat ID Number	Description
CSCvp70459	IOS: Prevent crypto ACL change if already mapped with crypto map configuration
CSCvq19673	Evaluation of asr1k for TCP_SACK

Open Caveats—Cisco IOS XE Release 3.16.9S (Cisco IOS Release 15.5(3)S9)

There are no open caveats in this release.

Resolved Caveats—Cisco IOS XE Release 3.16.9S (Cisco IOS Release 15.5(3)S9)

Caveat ID Number	Description
CSCvm02572	Router crashes on SSH connection with "login on-failure log" enabled

Open Caveats—Cisco IOS XE Release 3.16.8S (Cisco IOS Release 15.5(3)S8)

Caveat ID Number	Description
CSCuw50181	Cisco RSP3 Module: Total mac available space shows huge number
CSCvc24776	Cisco RSP3 Module: uea_mgr crash with diagnostic command "diag alloc Failover"

Resolved Caveats—Cisco IOS XE Release 3.16.8S (Cisco IOS Release 15.5(3)S8)

Caveat ID Number	Description
CSCuz70546	907:Management Interface Down on reload
CSCvc26350	100% downstream loss after SSO on rsp1b
CSCve64323	Cisco RSP1Module:MPLS MTU programming fails on standby with latest image

Open Caveats—Cisco IOS XE Release 3.16.6S (Cisco IOS Release 15.5(3)S6)

Caveat ID Number	Description
CSCvc24776	RSP3: uea_mgr crash with diagnostic command "diag alloc Failover"
CSCUw50181	RSP3: Total mac available space shows huge number.
CSCUw46635	IOT: Raw socket does not come up until interface is bounced.
CSCUu83294	IOT: Serial IM 0-7 interface should be blocked to be configured as sync.
CSCUu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO.
CSCUw78594	IOT:TCP: Configuring the speed does not show up on standby router.
CSCvb91263	Memory leak observed on router with native multicast configuration.

Resolved Caveats—Cisco IOS XE Release 3.16.6S (Cisco IOS Release 15.5(3)S6)

Caveat ID Number	Description
CSCvc46936	RJIL:RSP1B-Pending Object update @ ACL NAT_ACL
CSCvb13590	ASR900:In OC3 IM Winpath BUS ERROR is observed due to invalid multi-class number in the packet
CSCvc79143	IOT:Serial:traceback seen when serial IM is removed
CSCvd38455	ASR 903 after RSP switchover stop to pass traffic for one BDI
CSCUy27433	RSP1: Imposition Traffic TX Out Standby PW on IGP Delete Reconfig
CSCvb17864	RSP3:uea_mgr crash is seen @ tbn_inl_get_nextnode
CSCvd18135	MLDP: Unsupported OIF type 0x0. Unable to add in platform Seen on MLDP Script runs
CSCvd67376	ASR920 'set mpls experimental topmost' is causing 'set mpls experimental imposition' to not work.
CSCvd72604	Crash after policy map applied
CSCvb83795	RSP2: Queue node stuck during config replace results in 100% traffic loss on MLPPP Interface
CSCvc37483	Memory leak in SNMP on ASR903 with RSP3c/RSP2
CSCvb96905	Serial Path in ifTable and min and oper status stay up after cable unplug

Caveat ID Number	Description
CSCvc95602	ASR903 SDH counter errors

Open Caveats—Cisco IOS XE Release 3.16.5S (Cisco IOS Release 15.5(3)S5)

Caveat ID Number	Description
CSCUw46635	IOT: Raw socket does not come up until interface is bounced.
CSCUu83294	IOT: Serial IM 0-7 interface should be blocked to be configured as sync.
CSCUu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO.
CSCUw78594	IOT:TCP: Configuring the speed does not show up on standby router.
CSCvb91263	Memory leak observed on router with native multicast configuration.

Resolved Caveats—Cisco IOS XE Release 3.16.5S (Cisco IOS Release 15.5(3)S5)

Caveat ID Number	Description
CSCuz95664	ASR900: OC3 IM runs Out of FIFO Buffer on Reassembling MLPPP Fragments
CSCUt44696	Semaphore lock error and tracebacks with ERP.
CSCva87330	ASR903 behavior with " no mpls ip ttl propagate " configuration
CSCvb38142	MR-APS MLP. Forwarding failure on Protect Active SSO (With work disabled).
CSCvb18966	mlacp standby POA link forwards mcast/broadcast traffic after reboot.
CSCvb34126	L3 Loopback is not working on ASIC 1 interface in RSP2 with latest FPGA
CSCvb71337	ASR9xx after config changes to service instance - misclassified QoS on egress into class-default.
CSCvc03451	RSP3:Mgmt interface not accepting manual speed (10/100 mbps).

Open Caveats—Cisco IOS XE Release 3.16.4S (Cisco IOS Release 15.5(3)S4)

Caveat ID Number	Description
CSCvb24913	ASR903 - Last reload reason can be misleading
CSCut44696	Semaphore lock error and tracebacks with ERP.
CSCux89775	RSP2:CFM UP MEP is not working when the core interface are POS
CSCuu83294	IOT:Serial IM 0-7 interface should be blocked to be configured as sync
CSCuu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO
CSCuw46635	IOT: raw socket not coming up until interface is bounced
CSCuw78594	IOT:TCP: configuring the speed does not show up on standby router
CSCva15526	PW down after clear mpls ldp neighbor followed by RSP SSO

Resolved Caveats—Cisco IOS XE Release 3.16.4S (Cisco IOS Release 15.5(3)S4)

Caveat ID Number	Description
CSCva35619	Cisco IOS Software Crafted NTP Packets Denial of Service Vulnerability
CSCva90880	RSP1: Crash observed and the RSP1 box is reloaded.
CSCux21020	BGP/BFD session goes down on REP interface state change
CSCux42536	Cannot execute Xconnect with pseudowire force switchover
CSCuw97906	OC12: IOSD crash on configuring the e1 serial interface
CSCuz67645	EFP stats not incrementing for MPLS packets in imposition
CSCuz71631	ASR903 drop label traffic in certain range with more than 2 label stacks
CSCva21655	BDI MPLS MTU cannot be set more than 1500
CSCuz67921	OSPF hello over sham link is not punted for de-agg case
CSCux94951	Invalid CF set by intermediate slave as ptp pkt traverses 1g to 10g
CSCuz81746	UDP checksum error seen on ptp packets.

Caveat ID Number	Description
CSCva71102	"cefcFanTrayOperStatus" to provide a state "warning(4)" for fan failures
CSCva68157	SFF8472-3-THRESHOLD_VIOLATION: Tx bias low alarm on "Cisco QSFP-40G-LR4

Open Caveats—Cisco IOS XE Release 3.16.3aS (Cisco IOS Release 15.5(3)S3a)

Identifier	Description
CSCuw46635	IOT: raw socket not coming up until interface is bounced
CSCuu83294	IOT:Serial IM 0-7 interface should be blocked to be configured as sync
CSCuu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO
CSCuw78594	IOT:TCP:configuring the speed does not show up on stanby router
CSCuw50181	RSP3 : Total mac available space shows huge number
CSCuz26672	ASR903: Nile mgr crash - CPU Catastrophic Error
CSCuz47926	ASR 903 crashed due to traffic.
CSCuz39929	ASR900 memory leak in SSFPD code
CSCuy19614	RSP3 - Observing iomd crash while performing IM_OIR
CSCuu89839	UEA: RSP1 and RSP2 TDL Metafile checkin of xe315 timeframe
CSCuu87930	32 T1E1: Clock recovery in E1 mode failing (with G8262 op1 mask)
CSCva15526	PW down after clear mpls ldp neighbor followed by RSP SSO

Resolved Caveats—Cisco IOS XE Release 3.16.3aS (Cisco IOS Release 15.5(3)S3a)

Identifier	Description
CSCux65136	Traffic is not hitting the class-map on dynamicmodification of class-map
CSCux58640	LDP NSR: Label Mapping Messages Not Sent on RP SSO and VCs Re-bind
CSCuy09202	MCAST THS:IPv4 and IPv6 Multicast traffic doesn't flow over VPLS

Identifier	Description
CSCuz29486	'Ran out of ingress team resources' causes QoS crash

Open Caveats—Cisco IOS XE Release 3.16.2 (Cisco IOS Release 15.5(3)S2a)

Identifier	Description
CSCux21020	BGP/BFD session goes down on REP interface state change
CSCun30277	"show platform hardware pp active feat cef database prefix" CLI remove
CSCuu43827	ASR900: OC3 IM Performance Monitoring counters are not correct
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCuw46635	IOT: raw socket not coming up until interface is bounced
CSCuu83294	IOT:Serial IM 0-7 interface should be blocked to be configured as sync
CSCuu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO
CSCuw78594	IOT:TCP:configuring the speed does not show up on stanby router
CSCuw50181	RSP3 : Total mac available space shows huge number
CSCuw59358	MPLS forwarding drops on interface due to incorrect 2nd level EAID
CSCux57305	MPLS traffic forwarding issue at ASR 903
CSCuv36806	RSP3:Data path failure is seen with Inter-AS option AB
CSCuq34656	mLDP:FID,INL3IDC_NONVLAN, POLICERD
CSCuu89839	UEA: RSP1 and RSP2 TDL Metafile checkin of xe315 timeframe
CSCuu87930	32 T1E1: Clock recovery in E1 mode failing (with G8262 op1 mask)
CSCut93166	Last IMA Link Added Stuck in DOWN State on Delete and Add Few Links

Resolved Caveats—Cisco IOS XE Release 3.16.2 (Cisco IOS Release 15.5(3)S2a)

Identifier	Description
CSCux91894	ASR9xx iomd memory leak

Identifier	Description
CSCux79666	BFD Flap on ASR 903
CSCuv67090	ASR903 Egress InterfaceID Misprogrammed from MPLS to IP path
CSCuw57281	Changing MTU doesn't reflect in HW
CSCuu69516	RSP1: MET chain programmed wrongly, traffic drops seen
CSCuu35378	RSP2:Soak:Crash@cam_handle_gethwindex on soak run with intf flaps
CSCuw70038	RSP1: IOMD Crash on Egress IPv4 Flows Modify on MLPPP Sessions Flaps
CSCuv65276	RSP2THS: CEM CESOP and STAOP Disposition FID invalid
CSCuw76167	Clear raw socket command doesnt accept sessions higher than 136
CSCuv00703	IOT: Not able to delete TCP session under line config
CSCuw43940	IOT: raw socket session in global space using IP in VRF
CSCux45680	IOT: Serial IM Fpga Upgrade to Version 0x43
CSCuv00832	IOT:HA ERROR: Standby doesn't support this command
CSCuw75486	port LED on the serial IM is not green
CSCuu23983	SerialIM: Crash seen during OIR
CSCux56871	TWAMP functionality support over Trunk EFP for ASR903
CSCux74770	RSP1: Packets Do Not Egress From Winpath when MLP Member-Link E1 Down
CSCux60542	Getting DWNLD_TO_CPP_FAILED in RSP2 with starting ELB over xconnect
CSCuv37266	PPPoE sessions not getting established across VPN betwn 903(RSP2) and 9K
CSCuu28034	ASR903:Soak:Nile_mgr Crash during EoMPLS AC Unbind on Flapping IP Routes
CSCuw08717	RSP3 : mpls_unknown_label trap is hit after cutover in the core
CSCuw97303	RSP3:Pseudowire in lif set to 0 on ECMP path changes for Poch Access.
CSCuv22146	RSP3:RFC 3107 Label push fails in the case of pseudowire stitching
CSCuw39821	ASR903 acting as MVPN 'PE' device duplicates multicast traffic
CSCux64454	P2MP: Memory gets depleted while switching form multiple MP2MP to P2MP
CSCuw38880	Unable to create the 6th MTU on ASR-903

Identifier	Description
CSCux51223	BFD flaps during RFC2544 test
CSCux25567	IPv4 acl policy is not working properly
CSCuw99232	New Template Creation "max-ipv6-qos" to augment IPV6 QoS ACL Scale
CSCux81666	Policy shaping 90% is not working in wanphy script for QOS testcase-RSP1
CSCux45920	QOSMGR-3-EQOS_CXT_EXCEEDED message are seen on loading CU configs
CSCux79921	QOSMGR-3-OUT_OF_TCAM_RESOURCES on applying o/p policy with scalingconfig
CSCux61983	Traceback is seen during SSO on loading Customer Configuration
CSCux59365	Traffic is not flowing on loading Customer configs
CSCuu28316	ASR903: IOSd WATCHDOG Crash on Bootflash File Lookup on SNMP WALK
CSCuv17866	Out of Frame Alignment - IOS output to go through spell checker;-)
CSCuw43234	[RSP3] IOSD Crash on IM OIR RSP3 weekend soak run
CSCuv88996	adding support for GLC-GE-DR-LX optic
CSCux03323	ISSU failed due to FPGA upgrade in Standby
CSCuw95283	ASR903: CEMoUDP Packets Are Not Triggering ARP Resolution

Open Caveats—Cisco IOS XE Release 3.16.1aS (Cisco IOS Release 15.5(3)S1a)

Identifier	Description
CSCuu38382	FMFP-3-OBJ_DWNLD_TO_CPP_FAILED observed while remove/attach route-map
CSCuu69516	RSP1: MET chain programmed wrongly, traffic drops seen
CSCuu35378	RSP2:Soak:Crash@cam_handle_gethwindex on soak run with intf flaps
CSCuu43827	ASR900: OC3 IM Performance Monitoring counters are not correct
CSCur94076	RSP1 soak : WP_IwSystemBuild() returning Error on Soak test
CSCuw76167	Clear raw socket command does not accept sessions higher than 136
CSCuv00703	IOT: Not able to delete TCP session under line config
CSCuw46635	IOT: raw socket not coming up until interface is bounced
CSCuw43940	IOT: raw socket session in global space using IP in VRF
CSCuv00771	IOT: Console message : Interface placed in "shutdown" state during bootup
CSCuv00832	IOT:HA ERROR: Standby does not support this command
CSCuu25419	IOT:Ping fails for raw socket when the x.21 xconnect is down

Identifier	Description
CSCuu83294	IOT:Serial IM 0-7 interface should be blocked to be configured as sync
CSCuu94177	IOT:TCP Raw socket: memory leak seen with OIR and SSO
CSCuu83275	Serial IM interfaces 0- 7 should be blocked to be configured as sync .
CSCuv15263	SerialIM: Read, Write issue with FPGA registers.
CSCuv37266	PPPoE sessions not getting established across VPN betwn 903(RSP2) and 9K
CSCuu17412	ASR903:Soak:H-VPLS VFI Leak on Xconnects, Routes and IGP Flaps
CSCuu28034	ASR903:Soak:Nile_mgr Crash during EoMPLS AC Unbind on Flapping IP Routes
CSCuw59358	MPLS forwarding drops on interface due to incorrect 2nd level EAID
CSCuq34656	mLDP:FID,INL3IDC_NONVLAN, POLICERD
CSCuw38880	Unable to create the 6th MTU on ASR-903
CSCuw06487	%SYS-2-CHUNKBADMAGIC: Traceback on router when using PTP
CSCuu89839	UEA: RSP1 and RSP2 TDL Metafile checkin of xe315 timeframe
CSCuu87930	Crete: Accuracy :E1 RX failing for Tdev
CSCut93166	Last IMA Link Added Stuck in DOWN State on Delete and Add Few Links
CSCvb34126	L3 Loopback is not working on ASIC 1 interface in RSP2 with latest FPGA

Resolved Caveats—Cisco IOS XE Release 3.16.1aS (Cisco IOS Release 15.5(3)S1a)

Identifier	Description
CSCut68540	ACR:OIR of protect IM,OIR of work IM causes some cem circuits to go down
CSCuv07019	RSP2: Bigger File transfer over CC ATM is failing after few bit transfer
CSCur90777	RSP2THS:MRAPS ping fails after 4 aps sso
CSCuu94144	IOT: Ping fails with Serial IM on Slot-0
CSCuv50387	RSP1: Storm-control applies filter on both unknown and known unicast
CSCuv66661	ELB doesnot swap MAC when ELB is enabled as Internal mode in ASIC 1
CSCuw13508	Object download failures from cfm over the TEFP
CSCut92954	RSP1: IPv6 traffic does not flow over VPLS
CSCuv03712	RSP3:kernel: Process: TOD_task (31711) encountered fatal signal 6
CSCuu94056	LAG data (ifType) is wrongly populating in IF-MIB for ASR903
CSCuw21323	ASR902:optics not getting detected, and port is not coming up
CSCuv62761	CPU due to command process is always at 90 %
CSCuv30635	RSP1: standby rsp led not glowing post ISSU
CSCuv45494	ZR optics, link is going down over a period of time
CSCuu85439	32xT1E1 IM Low Amplitude on E1 signal
CSCuv71138	asr903 IMA32D E1 controller not working in unframed mode

Identifier	Description
CSCuv89254	RSP3: EVC BD UP Mep's are not being learnt with port mep used for 8032
CSCuv57140	RSP3: sw mac is learnt on blocked port
CSCuv84630	[RSP3-L2pt]: L2pt Pkts are not honoring Stp port status
CSCuv37182	[RSP3-split]: with dynamic modification of split horizon traffic is not flo
CSCuv43611	RSP3/BFD:Soak: Random ping failure after SSO soak
CSCuw59758	RSP3:Map-e packet (IPV4inIPV6) traffic drops
CSCuu51165	RSP3:Soak:EoMPLS Imposition and Disposition failure with access flaps
CSCuv13573	RSP3: class-default mpls exp imposition marking not working on EFP level
CSCut69049	IOSXE_OIR-3-QUIESCE_FAIL: Quiesce failed for subslot 0/2 (error = 1)
CSCuv15829	RSP3: Complete traffic drop after OIR on OC3 IM
CSCuv75706	8x1GE RSP3: Mean Path Delay and Reverse Path Delay outputs are zero
CSCut77920	RSP3:cTE is failing for 8x1GE IM's
CSCuu45971	Transparent clock performance is not good with 100G IM

Open Caveats—Cisco IOS XE Release 3.16S (Cisco IOS Release 15.5(3)S)

Identifier	Description
CSCus68778	CEMoUDP-T1/E1:Serial interface shows up/down after reload
CSCup58590	mLDP: IOSXE-PLATFORM:kernel: lsmpi_transmit_thread messages on Console
CSCur20933	RSP2: Multicast ping is not working over the P2MP Tunnel
CSCut24768	Egress policy with shaping is not working
CSCut36129	Egress Classification on Core of MPLS dosent work withTransport Vlan COS

Resolved Caveats—Cisco IOS XE Release 3.16S (Cisco IOS Release 15.5(3)S)

Identifier	Description
CSCuw21323	ASR902:optics not getting detected, and port is not coming up
CSCus60787	ACL counter does not work when applying IPv6 ACL to BDI intf on egress
CSCus65479	CEMoUDP: Traceback seen while performing OIR afte SSO @uea_cemoudp_pw_ud
CSCur52122	RSP1 : SPA_VC_MAX_LIMIT_REACHED and %ACR-6-ACRVPADD
CSCus00887	Mcast With Rep: Traffic not flowing after Reload
CSCus65819	SBB:ACL deny cmd doesn't drop the OSPF and PIM packets
CSCur88602	Disable Vasi related commands on ASR-903
CSCur74496	CEMoUDP: links on CE down after removing config from protect controller
CSCus12301	UDP : show pw-udp vc counters issue

Identifier	Description
CSCuo87402	False uncorrectable words reported on CTC
CSCut40156	IPV6 acl causes LDP down and ospf flap
CSCus98671	ENMIM:DPIDX_LKUP_ERR on standby
CSCus87139	AIS Sent on CESoPSN E1 even after L-bit Cleared by Remote PE
CSCut26934	CEM-ACR CEMoUDP: IOSd Crash after Reload
CSCup58590	mLDP: kernel: lsmipi_transmit_thread messages on Console
CSCut86756	"show platf hardware pp active acl ipv6 name ACL_OUT" shows incorrect output
CSCut86740	Egress IPV6 ACL doesn't work on router reload
CSCuu52794	L-bit in Rx SAToP pkts doesn't trigger AIS to be Tx into TDM AC
CSCut03410	OC12/OC3 :PDH level shut in SATOP is not asserting AIS on remote CE
CSCus97020	Crashes on configuring Ethernet loopback
CSCut74328	Traffic doesnt get flooded to BD members in RPF Fail
CSCuu35013	Crash seen when qos is applied on EVC with encap untagged
CSCus60754	IP SLA packet QOS classification on egress policy-map
CSCuu56931	Outdrops seen on ten gig interface that is not part of I2 connectivity.
CSCut88397	RSP2: Egress exp classification not working as expected
CSCut61651	ASR903 crashed in Pseudowire function
CSCut99827	IMA Group Up Though Far-end Signalled Insufficient Links Group State
CSCur63705	ASR903-RSP1:memleak @mcp_eobc_rx_interrupt in high availability box with mpls
CSCuu03655	IOMD crash seen on OC3 IM
CSCus16433	Incorrect values in entSensorThresholdEvaluation for SPA Subslot Sensors
CSCus07369	No Traps when decreased the device input voltage to 18 V
CSCut02011	Show interface transceiver is not dependable
CSCus98172	ASR903 GLC-EX-SMD %SFF8472-3-THRESHOLD_VIOLATION: Warning
CSCut13887	ASR903-RSP2: Unable to configure the threshold levels for EQOS tcam.
CSCup76962	RSP2:IOMD traceback @mcp_rpr_spa_tdl_marshal_err
CSCur98481	service unsupported-transceiver does not change the behavior
CSCus11642	IOSd crash seen with router reload with CEMoUDP enabled
CSCus78553	Seeing an error message for cemoudp reserving bay on 8E1T1 IM
CSCut84743	IGMPSN is taking more memory consumption on high scale in latest MCP
CSCuu04183	RPF Fail traffic doesnt flood with G8032



Restrictions and Caveats in Cisco IOS XE 3.17 Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.17 releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Limitations and Restrictions in IOS XE Release 3.17](#)
- [Caveats in Cisco IOS XE 3.17 Releases, page 27-1](#)

Limitations and Restrictions in IOS XE Release 3.17

- This is applicable only to Cisco ASR 903 RSP2 module. Traffic is dropped when packets of size 64 to 100 bytes are sent on 1G and 10G ports:
 - For 64-byte packets, traffic drop is seen at 70% and beyond of the line rate.
 - For 90-byte packets, traffic drop is seen at 90% and beyond of the line rate
 - For 95-byte packets, traffic drop is seen at 95% and beyond of the line rate.

Traffic is dropped when:

- Traffic is sent on a VRF interface
- Traffic is sent across Layer 2 and Layer 3

However, traffic is not dropped when the packet size is greater than 100 bytes, even if the packets are sent bi-directionally at the line rate.

Caveats in Cisco IOS XE 3.17 Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.17 releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.17 Releases:

- [Open Caveats—Cisco IOS XE Release 3.17.3S, page 27-2](#)
- [Resolved Caveats—Cisco IOS XE Release 3.17.3S, page 27-3](#)
- [Open Caveats—Cisco IOS XE Release 3.17.2S, page 27-3](#)
- [Closed Caveats—Cisco IOS XE Release 3.17.2S, page 27-4](#)
- [Open Caveats—Cisco IOS XE Release 3.17.1S, page 27-5](#)
- [Resolved Caveats—Cisco IOS XE Release 3.17.1S, page 27-6](#)
- [Open Caveats—Cisco IOS XE Release 3.17, page 27-7](#)
- [Resolved Caveats—Cisco IOS XE Release 3.17, page 27-8](#)

Open Caveats—Cisco IOS XE Release 3.17.3S

Caveat ID Number	Description
CSCuz88464	BFD is not coming up after IM_OIR of A900-IMA8Z
CSCvc24776	RSP3: uea_mgr crash with diagnostic command "diag alloc Failover"
CSCvc29309	TDM IM OIR traceback seen and router hangs
CSCuu25209	CPU hog @arad_pp_ihp_lif_table_ac_mp_tbl_get_unsafe

Caveat ID Number	Description
CSCvb72640	MET Entries getting exhausted
CSCuy23816	PTP TSU auto recovery for 1Gig link

Resolved Caveats—Cisco IOS XE Release 3.17.3S

Caveat ID Number	Description
CSCuy87254	RSP3 : CFM with service name configured with 6 charc fails
CSCuy02961	RSP3 : POCH with fast switchover flap on shutting other 8032 interface
CSCuz71631	ASR903 drop label traffic in certain range with more than 2 label stacks
CSCva21655	BDI MPLS MTU cannot be set more than 1500
CSCva23724	Wrong Bandwidth displayed for ONS-SE-100-BX10-U/D optics after SSO
CSCva68157	SFF8472-3-THRESHOLD_VIOLATION: Tx bias low alarm on "Cisco QSFP-40G-LR4
CSCuy15175	Cisco ASR 900 Series Aggregation Services Routers Buffer Overflow Vulnerability
CSCvb75771	DHCP snooping adds padding before END option in DHCP offer
CSCva84721	UDLD 9K Err-disable on 920 reboot
CSCva63921	ZTP disable not working on ASR-920-12SZ-IM
CSCva33116	Speed and bandwidth getting changed after reinsert of ONS-SE-100-BX10
CSCuz89006	ASR920 allows incorrect speed setting when using 100FX SPF
CSCuz86786	UDLD Moves to Err Disable in 9K on reloading ASR920

Open Caveats—Cisco IOS XE Release 3.17.2S

Identifier	Description
CSCuw31345	RSP1: OC3 IOMD Crash on Repeated SONET shut and no shut
CSCuw46635	IOT: raw socket not coming up until interface is bounced

Identifier	Description
CSCuy00846	RSP3 : Traffic drop seen on one interface on shutting another int
CSCuy01260	RSP3 : Unstable cfm sessions on RSP3 post SSO
CSCuz26672	ASR903: Nile mgr crash - CPU Catastrophic Error
CSCuz43377	cylon_mgr crash with shut and unshut of interfaces
CSCux72833	SR soak: cylon mgr crash at nmpls_lentry_delete and nmpls_lentry_modify
CSCuu25209	CPU hog @arad_pp_ihp_lif_table_ac_mp_tbl_get_unsafe
CSCuq34656	mLDP:FID,INL3IDC_NONVLAN, POLICERD
CSCuz29486	'Ran out of ingress tcam resources' causes QoS crash
CSCuz47926	ASR 903 crashed due to traffic.
CSCuz39929	ASR900 memory leak in SSFPD code
CSCuy12864	ASR903: FPGA Stuck because of MBE
CSCuz60282	RSP3 - iomd crash while performing IM_OIR in WRT
CSCuy19614	RSP3 - Observing iomd crash while performing IM_OIR
CSCuy58595	XFP-10GZR-OC192LR XFP recognized @ 100Mbps
CSCuy81971	ZR sfp+ link going down in remote side with sso, in 2X10gig im
CSCuu87930	32 T1E1: Clock recovery in E1 mode failing (with G8262 op1 mask)

Closed Caveats—Cisco IOS XE Release 3.17.2S

Identifier	Description
CSCun30277	"show platform hardware pp active feat cef database prefix" CLI remove
CSCuw10519	RSP3:HSPW Programming Fails with PoCH Dynamic Changes
CSCuw61230	E&M IM : Post SSO sometimes %EVENTLIB-3-CPUHOG traceback seen
CSCux57467	IOT:E&M: 1/6 IM does not come up when we insert 6 E&M IM in 1 chassis
CSCuy64017	fman_rp_flexlinks_vlan_evt not needed to sync popup all the TAFP

Identifier	Description
CSCux97136	RSP3 : Multiple issue due to BIPC channel stuck
CSCuy01260	RSP3 : Unstable cfm sessions on RSP3 post SSO
CSCuz02389	label programmed does not get properly when the value is beyond 65535
CSCuy08188	RSP3: fr obj download error on standby RSP on upgrade to latest XE318
CSCuy08692	MCAST : V6 traffic is getting replicated multiple times even with 1 oif
CSCux91628	RSP2: Cylon_Mgr Crash on Standby RP after RP Reaches HOT State on Bootup
CSCuz69474	Failed to config PTP as input src when only Ph3 IM's are in system
CSCuy29894	DM deletion of last v6 match class leaves stale entries in v6 ACL region
CSCux65136	Traffic is not hitting the class-map on dynamicmodification of class-map
CSCuz29486	'Ran out of ingress team resources' causes QoS crash
CSCuy12864	ASR903: FPGA Stuck because of MBE
CSCuz60282	RSP3 - iomd crash while performing IM_OIR in WRT
CSCuy58595	XFP-10GZR-OC192LR XFP recognized @ 100Mbps
CSCuy81971	ZR sfp+ link going down in remote side with sso, in 2X10gig im
CSCuw59221	RSP1-CEMoUDP-ACR: Serial interface shows up/down after reload
CSCuv87380	RSP1: Few 100 msec Traffic Loss on 1 IMA Group on Another IMA Group Flap
CSCuy09081	RSP2: MLP Ingress Traffic Fail as InL3IDC Not Programmed on SONET Flaps

Open Caveats—Cisco IOS XE Release 3.17.1S

Identifier	Description
CSCux79666	BFD Flap on ASR 903
CSCux21020	BGP/BFD session goes down on REP interface state change
CSCun30277	"show platform hardware pp active feat cef database prefix" CLI remove
CSCuv67090	ASR903 Egress InterfaceID Misprogrammed from MPLS to IP path
CSCuu69516	RSP1: MET chain programmed wrongly, traffic drops seen
CSCuw66918	IoT: Some time LED goes off after HA but call is ON
CSCuw31345	RSP1: OC3 IOMD Crash on Repeated SONET shut and no shut
CSCuw46635	IOT: raw socket not coming up until interface is bounced

Identifier	Description
CSCux56871	TWAMP functionality support over Trunk EFP for ASR903
CSCux74770	RSP1: Packets Do Not Egress From Winpath when MLP Member-Link E1 Down
CSCux57305	MPLS traffic forwarding issue at ASR 903
CSCuv36806	RSP3:Data path failure is seen with Inter-AS option AB
CSCux50984	Tx packet capture is getting completely drop with local span
CSCuu25209	CPU hog @arad_pp_ihp_lif_table_ac_mp_tbl_get_unsafe
CSCux81692	Crash observed @ nl3mm_unlink_mcast_mpls on "clear ospf process" trigger
CSCuy00090	cyclon crash due to NULL met entry
CSCuq34656	mLDP:FID,INL3IDC_NONVLAN, POLICERD
CSCuw11089	Crash @uea_cef_gtrie_get_idb_from_prefix in choke script
CSCux25567	IPv4 acl policy is not working properly
CSCux81666	Policy shaping 90% is not working in wanphy script for QOS testcase-RSP1
CSCuy06242	ASR903: Trap "entSensorThresholdNotification" is not reported properly.
CSCuw57376	External alarms cleared on 2nd SSO
CSCuy12864	Rudy: FPGA Stuck because of MBE
CSCuu87930	32 T1E1: Clock recovery in E1 mode failing (with G8262 op1 mask)
CSCuy25389	CEM support across full STM-4
CSCuw59221	RSP1-CEMoUDP-ACR: Serial interface shows up/down after reload
CSCuw26295	RSP1: MR-APS Protect Active RSP SSO Convergence Time 2 seconds

Resolved Caveats—Cisco IOS XE Release 3.17.1S

Identifier	Description
CSCuw33451	AVC: revert workaround for conversation tool following CSCuv05447 fix
CSCux88010	XE3.16: Optimize HSL Punt buffer size for high scale MMA punt records
CSCuw47720	ASR1001-X Mgmt port negotiation issue with peer device
CSCux16182	ECFM cannot work on EFP with VPWS interworking vlan
CSCuw30599	ISR4331-B: traceback occurred when enabling Ethernet Data Plane Loopback
CSCux00303	Router crash after stopping EPC
CSCuu14719	ArgusX/Kahuna : entPhysicalFirmwareRev value does not match with CLI
CSCux29703	ASR1000-2T+20X1GE fails to boot on router reload with SPA-3-NULL_BAY_PTR
CSCuu48458	ASR1k/15.4(3)S QinQ frames are dropped under "TCAM Failure Drops"
CSCuw43640	EPA1x100G: %SYS-2-LINKED: SIP0/0: Bad enqueue error message
CSCux55692	TCAM Errors in NL11k TCAM of Fixed Ethernet Linecards
CSCut62449	Disable HTTP AIC support
CSCuw98135	ZBFW HA not replicating sessions when matching based upon L4 proto/port
CSCux50997	IOS crashes on bootstrap without any startup configuration
CSCux62928	IOS-XE IKE over 4500 & IKE nat-t keepalive drop with certain possibility
CSCux44606	Name ACL for Multicast Boundary Stops Working Upon Reload

Identifier	Description
CSCUw12883	IPSec dummy packet feature does not work in VRF-aware IPsec
CSCUx33568	ESP crash while reconfiguring FR interface to MFR bundle
CSCUx02656	ASR1K: Crash related to collecting NetFlow data for IPv6 flows
CSCUw36887	Crash with with Flexible Netflow enabled
CSCUw98732	PfRv3 - show domain border channel service-provider filter not working
CSCUx45284	PLR negoation issue: should high speed and plr_ack=1 smp packets
CSCUx07224	ASR1K crash with OTV due to L2BD FIB entry change
CSCUw14239	fman-fp traceback from cpp_common_os - numclasses 0 download to CPP fail
CSCUw78755	IOS-XE need not require appxk9 license to support per-tunnel DMVPN QoS
CSCUw70220	IOSXE PACTRAC: cpp crash when packet trace enabled for MPLS and SSLVPN
CSCUx01133	interface counter stuck on build-in interfaces in ASR1001X
CSCUx43951	Packet drops on built-in 1Gig ports of ASR1001-X
CSCUx97951	dpss packets are getting punted on CSR box
CSCUx69222	Truncated counters/names in the 'show proc mem platform' output
CSCUx42411	ASR1001-X Frame Relay with Fortitude NIM fails due to LMI packet padding
CSCUx14860	ASR1K:Packet Tracing failed with FW,NAT&FW enabled.
CSCUw94014	cpp_cp crashes with BB profile #6 48k PTA
CSCUx49714	GEC:QoS: pkt buff util high after apply/remove flat policy w/ fair-queue
CSCUw73223	Polaris : cpp_cp_svr crash when the interface goes down
CSCUx10321	ASR1000 CLI hangs on executing the "show platform hardware qfp xxx"
CSCUw73226	GRE checksum is wrong for Fragmented packets
CSCUx40633	ISR 4451 Continuous Crash/ Core Crash File generated with WAAS/Appnav
CSCUv71273	fragmented packet cause high qfp load

Open Caveats—Cisco IOS XE Release 3.17

Identifier	Description
CSCUv70649	Traffic not flowing after moving back to primary tunnel/TE tunnel-FRR
CSCUw26295	RSP1: MR-APS Protect Active RSP SSO Convergence Time 2 seconds
CSCUw55351	MLDP:Router crashes on clear ip ospf/soak test
CSCUx12563	[rsp3-xe317]Complete traffic drop on SSO
CSCUx21020	BGP/BFD session goes down on REP interface state change
CSCUx42536	Cannot execute Xconnect with pseudowire force switchover
CSCUv44135	RSP2: After changing core RP, (S,G) is not formed for data mdt
CSCUw11089	Crash @uea_cef_gtrie_get_idb_from_prefix in choke script
CSCUw31345	RSP1: OC3 IOMD Crash on Repeated SONET shut and no shut

Identifier	Description
CSCuw57376	RSP3 - External alarms cleared on 2nd SSO
CSCuw59221	RSP1-CEMoUDP-ACR: Serial interface shows up/down after reload
CSCuw66918	IoT: Some time LED goes off after HA but call is ON

Resolved Caveats—Cisco IOS XE Release 3.17

Identifier	Description
CSCuv94517	RSP3: L2FIB Multicast fman code crash on tefp + EFP config add/removal
CSCus96430	ASR903: CEMoUDP Traffic over 1 MLP Impacted when another MLP goes Down
CSCva15526	PW down after clear mpls ldp neighbor followed by RSP SSO



Restrictions and Caveats in Cisco IOS XE 3.18S Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.18S releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.18S Releases, page 28-1](#)

Restrictions in Cisco IOS XE 3.18S Releases

- In Cisco IOS XE Release 3.18S, PTP packets carrying MPLS labels are not supported in the ingress or egress direction on the RSP3 module.
- This is applicable only to Cisco ASR 903 RSP2 module. Traffic is dropped when packets of size 64 to 100 bytes are sent on 1G and 10G ports:
 - For 64-byte packets, traffic drop is seen at 70% and beyond of the line rate.
 - For 90-byte packets, traffic drop is seen at 90% and beyond of the line rate
 - For 95-byte packets, traffic drop is seen at 95% and beyond of the line rate.

Traffic is dropped when:

- Traffic is sent on a VRF interface
- Traffic is sent across Layer 2 and Layer 3

However, traffic is not dropped when the packet size is greater than 100 bytes, even if the packets are sent bi-directionally at the line rate.

Caveats in Cisco IOS XE 3.18S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.18S releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.18S Releases:

- [Open Caveats—Cisco IOS XE Release 3.18.3S \(Cisco IOS Release 15.6\(2\)S3\), page 28-2](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.3S \(Cisco IOS Release 15.6\(2\)S3\), page 28-2](#)
- [Open Caveats—Cisco IOS XE Release 3.18.2S \(Cisco IOS Release 15.6\(2\)S2\), page 3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.2S \(Cisco IOS Release 15.6\(2\)S2\), page 3](#)
- [Open Caveats—Cisco IOS XE Release 3.18.1S \(Cisco IOS Release 15.6\(2\)S1\), page 4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.1S \(Cisco IOS Release 15.6\(2\)S1\), page 4](#)
- [Open Caveats—Cisco IOS XE Release 3.18S \(Cisco IOS Release 15.6\(2\)S\), page 28-4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18S \(Cisco IOS Release 15.6\(2\)S\), page 28-5](#)

Open Caveats—Cisco IOS XE Release 3.18.3S (Cisco IOS Release 15.6(2)S3)

There are no open caveats for the Cisco ASR 903 Series Router running Cisco IOS XE Release 3.18.3S.

Resolved Caveats—Cisco IOS XE Release 3.18.3S (Cisco IOS Release 15.6(2)S3)

Identifier	Description
CSCvc14648	RSP3: LB/FRR/Adj obj download errors after link flap
CSCvc29475	RSP3:Wrong path selected for MPLS Label results in traffic failure
CSCvb72640	MET Entries getting exhausted
CSCvb71337	ASR9xx after config changes to service instance - misclassified QoS on egress into class-default

Identifier	Description
CSCvb61016	RSP3: BFD Flap on 8x10G, performing SSO on Peer Node
CSCvb96905	Serial Path in ifTable and min and oper status stay up after cable unplug
CSCuz95664	ASR900: OC3 IM Runs Out of FIFO Buffer on Reassembling MLPPP Fragments
CSCux45450	ASR900: OC3 IOMD CPUHOG on SOAK Test of SONET Shut and No Shut
CSCuw31345	RSP1: OC3 IOMD Crash on Repeated SONET shut and no shut
CSCvb01725	LEAPSEC: BC in holdover is not sending the last learnt utcOffset
CSCuz49602	TDM-ST: RSP2 adj manager crash observed after OIR on TDM T1E1 IMs
CSCvb63314	Traffic not egressing out on AC after Standby PW became Active PW
CSCvb49400	RSP1:Back to back failed because of either Invalid adjacency in PD or Incomplete adjacency in PD
CSCva14704	cem xconnection is down and tracebacks when changing dejitter buffer
CSCvb61160	RSP3: HW-LB: L3VPN - Path is preselected though PIC is enabled
CSCuy03441	RSP3:Data path failure is seen with Inter-AS option AB
CSCuz45306	POS MRAPS high convergence time with Protect Active Power Cycle

Open Caveats—Cisco IOS XE Release 3.18.2S (Cisco IOS Release 15.6(2)S2)

Identifier	Description
CSCuz95664	ASR900: OC3 IM Runs Out of FIFO Buffer on Reassembling MLPPP Fragments
CSCux45450	ASR900: OC3 IOMD CPUHOG on SOAK Test of SONET Shut and No Shut
CSCuw31345	RSP1: OC3 IOMD Crash on Repeated SONET shut and no shut
CSCvb01725	LEAPSEC: BC in holdover is not sending the last learnt utcOffset
CSCuz49602	TDM-ST: RSP2 adj manager crash observed after OIR on TDM T1E1 IMs
CSCvb63314	Traffic not egressing out on AC after Standby PW became Active PW
CSCvb49400	RSP1:Back to back failed because of either Invalid adjacency in PD or Incomplete adjacency in PD
CSCva14704	cem xconnection is down and tracebacks when changing dejitter buffer
CSCvb61160	RSP3: HW-LB: L3VPN - Path is preselected though PIC is enabled
CSCuy03441	RSP3:Data path failure is seen with Inter-AS option AB
CSCuz45306	POS MRAPS high convergence time with Protect Active Power Cycle

Resolved Caveats—Cisco IOS XE Release 3.18.2S (Cisco IOS Release 15.6(2)S2)

Identifier	Description
CSCuz95621	ASR900: OC3 IOMD Crash on RP SSO while MLPPP Scale Sessions Flap
CSCuw72998	RSP1: Large Number of 3072-byte Memory Leaks in ASR1000 SPA TDL process
CSCuy96309	IOT: ASR900-IMA14A/S performance issue

Identifier	Description
CSCuz67645	EFP stats not incrementing for MPLS packets in imposition
CSCuz71631	ASR903 drop label traffic in certain range with more than 2 label stacks
CSCva21655	BDI MPLS MTU cannot be set more than 1500
CSCva39555	MPLS Forwarding Issue on ASR903
CSCuz67921	OSPF hello over sham link is not punted for de-agg case
CSCux94951	Invalid CF set by intermediate slave as ptp pkt traverses 1g to 10g
CSCvb49938	UDP packets are getting corrupted in MPLS De-Agg case
CSCuz78209	RSP3/QOS: Ingress policer drops are accounted at egress queue level

Open Caveats—Cisco IOS XE Release 3.18.1S (Cisco IOS Release 15.6(2)S1)

Identifier	Description
CSCuy35875	Tx bias low alarm on 100G CPAK 100GE LR4 optics
CSCuz64141	x21 cesop could not pass traffic with 64Kbps baud rate

Resolved Caveats—Cisco IOS XE Release 3.18.1S (Cisco IOS Release 15.6(2)S1)

Identifier	Description
CSCuz02389	label programmed does not get properly when the value is beyond 65535
CSCuy27433	RSP1: Imposition Traffic TX Out Standby PW on IGP Delete Reconfig
CSCuz39929	ASR900 memory leak in SSFPD code
CSCuy58595	XFP-10GZR-OC192LR XFP recognized @ 100Mbps
CSCuy81971	ZR sfp+ link going down in remote side with sso, in 2X10gig im

Open Caveats—Cisco IOS XE Release 3.18S (Cisco IOS Release 15.6(2)S)

Identifier	Description
CSCuw67453	32T1E1:Shut on CEM group not results in Serial Interface Protocol down
CSCuw86907	907:Act Resets with CMAND crash on downgrading the IM FPGA using IOS
CSCux37882	On routed Port, 2nd time population of ARP entries lead to error object
CSCux48983	SR: RSP2 sends out corrupted pkts with UMMT TI-LFA 5 label push scenario
CSCux53766	CEMoUDP:Circuits are not Not up if we configure CEM for full scale.
CSCux55714	RSP3 : OAMP generating packets even after disabling cfm globally
CSCux73183	G.8275.1 T-BC: Allow simultaneous i/p and o/p 1PPS with Virtual Port
CSCux76373	DSCP value is not set correctly at IP header which carries PTP packet

Identifier	Description
CSCux87797	MLDPv6 : Crash @ nmpls_rlist_create_hw_fid
CSCux91894	ASR9xx iomd memory leak
CSCux93941	OC3:CEM config are lost after setting boot host command and reload
CSCux94962	ToD: Cisco and ubx formats are not working
CSCux96664	Phase2 IM: HBC-907: Traceback seen after box comes up after a reload
CSCuy00543	RSP3 : Observing cfm errors due to missing fields in ccm
CSCuy00846	RSP3 : Traffic drop seen on one interface on shutting another int
CSCuy08188	RSP3: frr obj download error on standby RSP on upgrade to latest XE318
CSCuy09202	MCAST THS:IPv4 and IPv6 Multicast traffic doesn't flow over VPLS
CSCuy27212	show platform hardware pp active int all queue counters are not updating
CSCuy29403	SR Punt from incomplete ADJ reaches ROUTING THROTTLE Q but not PI module
CSCuy73110	After core IM-OIR CFM traceroute is not working between CEs

Resolved Caveats—Cisco IOS XE Release 3.18S (Cisco IOS Release 15.6(2)S)

Identifier	Description
CSCun30277	"show platform hardware pp active feat cef database prefix" CLI remove
CSCut16038	Crete: OC master does not output PTP based on TOD input
CSCuu28316	ASR903: IOSd WATCHDOG Crash on Bootflash File Lookup on SNMP WALK
CSCuv57383	RSP1: In rare situations , mplS is not enabled in hardware after upgrade
CSCuw26295	RSP1: MR-APS Protect Active RSP SSO Convergence Time 2 seconds
CSCuw38880	Unable to create the 6th MTU on ASR-903
CSCuw39821	ASR903 acting as MVPN 'PE' device duplicates multicast traffic
CSCuw57281	Changing MTU doesn't reflect in HW
CSCuw59221	RSP1-CEMoUDP-ACR: Serial interface shows up/down after reload
CSCuw70038	RSP1: IOMD Crash on Egress IPv4 Flows Modify on MLPPP Sessions Flaps
CSCuw95283	ASR903: CEMoUDP Packets Are Not Triggering ARP Resolution
CSCux60630	RSP2 & Pegasus:Modifying MTU value fails in Multilink interface
CSCux62888	RSP2: 126 Cylon EAIDs Leaked when 126 MLPPP Bundles Flapped
CSCux64454	P2MP: Memory gets depleted while switching form multiple MP2MP to P2MP
CSCux79666	BFD Flap on ASR 903
CSCuy09081	RSP2: MLP Ingress Traffic Fail as InL3IDC Not Programmed on SONET Flaps



Restrictions and Caveats in Cisco IOS XE 3.18SP Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.18SP releases.



Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.

This chapter contains the following sections:

- [Caveats in Cisco IOS XE 3.18SP Releases, page 29-2](#)

Restrictions in Cisco IOS XE 3.18.1SP

- In the Cisco IOS XE Release 3.18.1S, for non payload encryption (NPE) image, there is no support for IPsec tunnels on the Cisco RSP3 module. As a result, the **tunnel mode ipsec** and **tunnel protection ipsec profile** commands are also disabled in this release.
- In the Cisco IOS XE Release 3.18.1SP, PTP packets carrying MPLS labels are not supported in the ingress or egress direction on the Cisco RSP3 module.
- To use IPsec, use the payload encryption (PE) image and acquire the IPsec license (only available for Cisco RSP3 Module)
- The Cisco IOS XE 3.18.1SP release is applicable only on the Cisco ASR900 RSP1 and RSP2 modules.
- The Cisco IOS XE 3.18.1bSP release is applicable only on the Cisco ASR900 RSP3 modules.
- This is applicable only to Cisco ASR 903 RSP2 module. Traffic is dropped when packets of size 64 to 100 bytes are sent on 1G and 10G ports:
 - For 64-byte packets, traffic drop is seen at 70% and beyond of the line rate.
 - For 90-byte packets, traffic drop is seen at 90% and beyond of the line rate
 - For 95-byte packets, traffic drop is seen at 95% and beyond of the line rate.

Traffic is dropped when:

- Traffic is sent on a VRF interface
- Traffic is sent across Layer 2 and Layer 3

However, traffic is not dropped when the packet size is greater than 100 bytes, even if the packets are sent bi-directionally at the line rate.

Caveats in Cisco IOS XE 3.18SP Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.18SP releases. The following information is provided for each caveat:

- Symptom—A description of what is observed when the caveat occurs.
- Conditions—The conditions under which the caveat has been known to occur.
- Workaround—Solutions, if available, to counteract the caveat.

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document: [Resolved Caveats—Cisco IOS XE Release 3.18.2SP \(Cisco IOS Release 15.6\(2\)SP2\), page 19](#) [Resolved Caveats—Cisco IOS XE Release 3.18.2SP \(Cisco IOS Release 15.6\(2\)SP2\), page 19](#)

[http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>.

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Caveats

The following sections describe the open and resolved caveats in 3.18SP Releases:

- [Open Caveats—Cisco IOS XE Release 3.18.9SP \(Cisco IOS Release 15.6\(2\)SP9\), page 3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.9SP \(Cisco IOS Release 15.6\(2\)SP9\), page 3](#)
- [Open Caveats—Cisco IOS XE Release 3.18.8aSP \(Cisco IOS Release 15.6\(2\)SP8\), page 3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.8aSP \(Cisco IOS Release 15.6\(2\)SP8\), page 3](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.8aSP \(Cisco IOS Release 15.6\(2\)SP8\) Platform Independent, page 4](#)
- [Open Caveats—Cisco IOS XE Release 3.18.7SP \(Cisco IOS Release 15.6\(2\)SP7\), page 4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.7SP \(Cisco IOS Release 15.6\(2\)SP7\), page 4](#)
- [Resolved Caveats—Cisco IOS XE Release 3.18.7SP \(Cisco IOS Release 15.6\(2\)SP7\) Platform Independent, page 5](#)
- [Open Caveats—Cisco IOS XE Release 3.18.6SP \(Cisco IOS Release 15.6\(2\)SP6\), page 5](#)

- Resolved Caveats—Cisco IOS XE Release 3.18.6SP (Cisco IOS Release 15.6(2)SP6), page 6
- Open Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5), page 7
- Resolved Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5), page 8
- Open Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4), page 29-10
- Resolved Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4), page 29-12
- Open Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3), page 14
- Resolved Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3), page 16
- Open Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2), page 18
- Resolved Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2), page 19
- Open Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1), page 19
- Resolved Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1), page 21
- Open Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP), page 23
- Resolved Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP), page 24

Open Caveats—Cisco IOS XE Release 3.18.9SP (Cisco IOS Release 15.6(2)SP9)

There are no open caveats for this release.

Resolved Caveats—Cisco IOS XE Release 3.18.9SP (Cisco IOS Release 15.6(2)SP9)

There are no resolved caveats for this release.

Open Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8)

Caveat ID Number	Description
CSCvm76770	Unpredictable asymmetry on T1/E1 IM
CSCva43417	e1 Interfaces go DOWN on remote alarm (RDI)

Resolved Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8)

Caveat ID Number	Description
CSCvi02398	SNMP MIB and device configurations do not match

Resolved Caveats—Cisco IOS XE Release 3.18.8aSP (Cisco IOS Release 15.6(2)SP8) Platform Independent

Caveat ID Number	Description
CSCvm79556	RSP3: MSPW VC down after Switchover (Error Local access circuit is not ready for label advertise)
CSCvj15469	Remove crypto group access check

Open Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7)

Caveat ID Number	Description
CSCvm76770	Unpredictable asymmetry on T1/E1 IM
CSCva43417	e1 Interfaces go DOWN on remote alarm (RDI)

Resolved Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7)

Caveat ID Number	Description
CSCvp67025	RSP2: Software-Induced Multi-Bit Errors on Handoff FPGA When Exceeding Max FNF Cache Size
CSCvm04696	Mac learnt on G8032 blocked ports due to DHCPv4 discovery pkts
CSCvo65688	16.9.3-QIP-crete-TOD flaps in Crete (master) when setup is left overnight
CSCvo58053	High memory usage only on standby RSP in iomd
CSCvj87085	ptpd crashed after removing the ptp configs, default profile <169>
CSCvj75078	RSP3: IOMD crash @ iomd_bsess_open_callback_retry on new active after RP SSO
CSCvk32423	IMA8Z 6-port mode, hwidx not created leading to complete traffic drop
CSCvf72273	RSP3_G8275.1: Both the PLL locked to REMOTE RP and PLL lock status is OFF
CSCvf90832	RSP3_907: UTC Offset is NOT taken care properly when VP is selected.
CSCvq55841	With netflow enabled, FPGA_INTERRUPTS_ERROR observed upon modifying the flow count
CSCvj49266	Rx getting dropped at Master after losing its 10M input

Resolved Caveats—Cisco IOS XE Release 3.18.7SP (Cisco IOS Release 15.6(2)SP7) Platform Independent

Caveat ID Number	Description
CSCvk36863	MAC learning not working
CSCvf20607	ASR1K RSP crash when command 'show ip rsvp sender detail' was executed
CSCvh62861	IOSd crash @ NHRP nhrp_group_tunnel_qos_remove
CSCvj43156	Crash in XDR process: "fib_rp_table_broker_encode_buf.size <= FIB_RP_TABLE_BROKER_ENC_BUF_SZ"
CSCvk17998	Rekey Timer are same for both the Server and Client
CSCvm64865	[EIGRP] a summary route is updated by an external route
CSCvn00218	CUBE Crash in sipSPIAppAddCallInfoUI
CSCvn56017	Crash while processing ISIS updates when DiffServ-TE is enabled
CSCvn93524	Cisco REST API Container for IOS XE Software Authentication Bypass Vulnerability
CSCvo55194	After RSP switchover label imposition was not programmed in Software on APS standby router
CSCvo66216	IPSec-Session count in "show crypto eli" reaches max causing VPN failure
CSCvp76434	OSPF summary-route (Type 5) redistribute into ospf via 'summary-address' cmd is not install in RIB
CSCvp78236	Crash during SNMP Configuration, ospfv3_pdb_from_router_info
CSCvp81102	IPsec SA installation fails with simultaneous negotiations despite fix for CSCve08418
CSCvp87125	Default-route is not installed in Local PE VRF if there is 0.0.0.0/X route present in routing table
CSCvp99881	BGP set wrong local preference for routes in RPKI invalid state
CSCvq19673	Evaluation of asr1k for TCP_SACK
CSCvq46617	RLFA config causing OSPF to ignore backup path addition for NSSA prefix after primary link flap
CSCvq67901	Crash in HTTP core process
CSCvb05793	Traffic drop observed upto 2 mins on active Sup pull with ECMP

Open Caveats—Cisco IOS XE Release 3.18.6SP (Cisco IOS Release 15.6(2)SP6)


Caveat ID Number	Description
CSCva43417	E1 Interfaces go DOWN on remote alarm (RDI)
CSCvj75078	RSP3: IOMD crash @ iomd_bsess_open_callback_retry on new active after RP SSO
CSCvk32423	IMA8Z 6-port mode, hwidx not created leading to complete traffic drop
CSCvm04696	MAC learnt on G8032 blocked ports due to DHCPv4 discovery pkts
CSCvm76770	Unpredictable asymmetry on T1/E1 IM
CSCvo58053	High memory usage only on standby RSP in iomd

Resolved Caveats—Cisco IOS XE Release 3.18.6SP (Cisco IOS Release 15.6(2)SP6)

Caveat ID Number	Description
CSCux22473	IPv6 Tracking for route learned from IBGP Neighbor is Down.
CSCux68796	IOS-XE Router - High CPU When Handling get-next on "entStateStandby" MIB
CSCuz74957	Cisco IOS and IOS XE Software ISDN Interface Denial of Service Vulnerability
CSCuz99865	IPSec MIB queries returns wrong tunnel count
CSCva00765	crash after no ipv4 multicast multitopology command
CSCva64842	Observing kernel: EXT2-fs error while moving between polaris and MCP_DEV
CSCve56559	Incorrect Track Resolution Metric for GRE Tunnel
CSCve57830	SUBALTNNAME DECODE fails for APIC_EM self-signed cert when validating server identity
CSCve89361	Crash in SISF while processing IPv6 packet
CSCvf11776	VRRPv3 with VRRS remains NOT READY after shutdown Port-channel IF.
CSCvf36269	Cisco IOS and IOS XE Software Network Plug-and-Play Certificate Validation Vulnerability
CSCvf73552	VRRP non-zero authentication data on 16.3.3
CSCvf96294	MIB counter for IPSec tunnels does not decrement under high tunnel scale and churn
CSCvg06142	'ipsm Tunnel Entry' and 'Crypto IKMP' memory leak due to IKE tunnel entry not deleted
CSCvg37952	Cisco IOS XE Software ISR4400 Series IPsec Denial of Service Vulnerability
CSCvh54672	VRRP doesnt work over Port-channel L3 interface
CSCvh72848	"no track resolution ip route" and "default track resolution ip route" not working
CSCvh83319	Interop vrrp doesnt work between cedge and vedge
CSCvi83306	Crash with IOSXE-WATCHDOG: Process = IPv6 RIB Event Handler
CSCvj02910	Reload removing ipv6 VRRP group
CSCvj61307	Cisco IOS XE Software Command Injection Vulnerability
CSCvj73544	ospf routing loop for external route with multiple VLINKs/ABRs
CSCvj86790	RIP does not send updates on unnumbered interfaces after reload of ISR 4k
CSCvj98575	Cisco IOS and IOS XE HSRPv2 Information Leak Vulnerability
CSCvk03910	OSPF neighbor stuck in loading after VSS switchover
CSCvk56331	Initial contact in IKEv1 phase 2 rekey (QM1) causes all crypto sessions to drop
CSCvk71047	Router fails to reserve necessary ports for VPN traffic (UDP 500 & 4500) for ISAKMP
CSCvm00765	BFD crash on imitating traffic loss
CSCvm02572	Router crashes on SSH connection with "login on-failure log" enabled
CSCvm28421	ASR901-ESMC padding is having non-zero random values which is causing duplicate QL-TLV
CSCvm40496	iBGP PE-CE When Route-Reflect enable VRF import all Route Target.
CSCvm51112	"clear crypto sa vrf MyVrf" triggers crash after updating pre-shared-keys
CSCvm55465	BGP updates missing ISIS advertising-bits led to LDP label purge on peer.

Caveat ID Number	Description
CSCvm62554	BGP multipath feature drops a path from list after BGP update event
CSCvm76070	Not able to enable the CLI http-status-code-ignore
CSCvm92116	Bulk-sync failure due to bgp router-id interface Loopback0
CSCvm93603	IP change on dialer-int does not trigger a correct "local crypto entpt" in DMVPN
CSCvm95236	BGP update not properly processed by inbound route-map
CSCvn07060	Redistributed metric is not be applied if it is in narrow-style
CSCvn28017	ISR4331 Routers May Crash When "eigrp default-route-tag" Configured on IPv4 AF
CSCvn59020	Modified EIGRP timers on Virtual-Template put all associated Vi interfaces into passive mode
CSCvm10079	Force QL Tx option is not working when netsync configured with more than 3 input sources.
CSCvn08456	RSP3: Giant counters incremented for packets bigger than 1500 bytes
CSCvn17722	SONET ACR Pending Object with CEM GROUP interfaces.

Open Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5)

Caveat ID Number	Description
CSCvf62586	FAN missing in ASR902 RSP2 chassis.  Note Migrate to the latest 3.18 SP6 image.
CSCvb82613	Tunnel/IGP down on SSO due to ingress VOQ packet drop
CSCvd00780	8275.1: PTP Packets are being dropped without untagged EFP on a tagged EFP interface
CSCvd44667	RSP3: PREFIX Object Errored Objects on Local Core Flaps and in Parallel on Other Routers in the Core
CSCvd89421	RMEP failure due to CFM HW table corruption
CSCve43404	PTP Clock Creation Fails for Specific Sequence of Triggers
CSCve49550	IOX: OOS issue seen with 100Mbps sfp inserted on a SFP combo IM
CSCve68911	Nested Enhanced Route Refresh requests triggers Stale Prefixes.
CSCve86912	[Counter]: Giant/Runt/Pause Frame counters issue.
CSCvf08577	RSP3 Arad not able to timestamp higher stream id packets in default profile
CSCvf09940	RSP3_2x10GE: output netsync drifting after SSO when locked to 2x10GE
CSCvf11776	VRRPv3 with VRRS remains NOT READY after shutdown Port-channel IF.
CSCvf19415	Port MEP Timeout in RSP1
CSCvf34496	RSP3-QIP:Error objects on Stby cfm_mp_ifh 16794673 sid 3001 download to CPP failed seen upon IM-OIR
CSCvg10313	Cu clock source still squelched on interface bring up after two SSOs
CSCvh51179	RSP3: Stale Mac entries are present on a specific scenario which results in ADJ download failure
CSCvi61745	Crash when running MPLS Tunnel protection command

Caveat ID Number	Description
CSCvj02910	Reload removing ipv6 VRRP group
CSCvj43156	Crash in XDR process: "fib_rp_table_broker_encode_buf.size <= FIB_RP_TABLE_BROKER_ENC_BUF_SZ"
CSCvj85437	Bheem FPGA : SEU support on standby RSP for SBE and MBE
CSCvk22449	BGP Traceback/Crash seen with 20k IPv4 BGP scale after reload/clearing bgp
CSCvk24933	RSP3: QSGMI out of lock with IM OIR + SSO soak
CSCvk59137	Fan tray temperature read as 0 degree Celsius
CSCvm00765	BFD crash on imitating traffic loss
CSCvm04696	Mac learnt on G8032 blocked ports due to DHCPv4 discovery pkts

Resolved Caveats—Cisco IOS XE Release 3.18.5SP (Cisco IOS Release 15.6(2)SP5)

Caveat ID Number	Description
CSCsd58148	%SEC_LOGIN-4-LOGIN_FAILED does not show username in [user:]
CSCCue25168	TPM reserves UDP/4500 for no apparent reason
CSCCuv90519	Map doesn't get updated with socket change on local address change
CSCCuy27746	CDP packet causes switch to crash due unexpected exception to CPUvector
CSCCuy54623	Evaluation of all for OpenSSL March 2016
CSCCuy96461	IOS-XE EPC does not work on port-channel subinterfaces
CSCCuz42299	Crash when configuring CWS
CSCCuz52528	Evaluation of all for OpenSSL May 2016
CSCCuz82303	Setting MTU to 9216 on routed interface causes scheduler(BRP/BRR) fail
CSCCuz92785	Evaluation of all for NTP June 2016
CSCCva08142	IOSd crash on LISP enable router
CSCCva36556	Smart call home crash with debugs enabled
CSCCvb71086	CWS + NVI NAT not working for web traffic
CSCCvc07577	Crash in BGP due to regular expressions
CSCCvc23569	Evaluation of all for NTP November 2016
CSCCvc60745	tcp_getbuffer memory leak - refcount not reduced when packet dropped
CSCCvc98571	EEM applet will not release the Config Session Lock if it ends when CLI is in configuration mode
CSCCvd21340	IOSd crashed while issuing 'show isdn status'
CSCCvd35443	Site-prefix-learning:Crash on EIGRP process when issuing "no ip vrf red" on HMCBR
CSCCvd80715	ASR1k IOSD crash due to memory corruption in aaa accounting
CSCCvd80837	Crash observed in DHCP SIP

Caveat ID Number	Description
CSCve00087	Line-by-Line sync verifying failure on command: client test01 server-key 0 Password
CSCve52155	RSP3: BFD Session Between 2 RSP3s Down on Reloading 1 RSP3
CSCve55089	BGP crashes at bgp_ha_sso_enable_ssomode
CSCve72906	RSP3:ECMP LB seen when flags field is changed in ip header with l4 header in 4 label scenario
CSCve76947	Eigrp hmac-sha-256 secret string changes when show running-config is executed
CSCvf21005	config mismatch after code upgraded
CSCvf35507	Crash in SSH Process due to SCP memory corruption
CSCvf37923	Crash due to Stack overflow
CSCvf63979	Crash when trying to establish new SSH connection
CSCvf67481	AAA process not sending malloc if dynamic heap free mem is under aaa mem threshold
CSCvf81579	ASR1K: IOSd crash in kmi_initial_check on null map dereference
CSCvg01156	G275.2 Huge TIE jump seen on slave after reload completes on RSP3 master
CSCvg02533	router crashed after triggers with debug
CSCvg03444	Hub MC continues to send EIGRP SAF hellos after adjacency removed
CSCvg06222	RSP3: ~30sec traffic loss for EOMPLS services during ReOpt after TE Node Protection trigger
CSCvg06788	RSP3:3-10sec traffic loss for FlexLsp Tunnels (unidirectional) from HE to TE on Active path cutover
CSCvg39082	Cisco device unexpectedly reloads after TCP session timeout
CSCvg41950	Cisco IOS XE Software Diagnostic Shell Path Traversal Vulnerability
CSCvg48470	ISIS 11-12 redistribution prefix doesnt get redistributed till clear isis rib redistribution is done
CSCvg67028	VRF deletion status <being deleted> after removing the RD
CSCvg67742	ASR903-RSP3C Enhancement of log messages on FAN Tray OIR
CSCvg71566	"no cdp enable" is rewritten to "no cdp tlv app" after reload.
CSCvg84699	BFD session not coming up on RSP3 due to wrong platform offload limit
CSCvg85879	BGP sets the wrong Local Preference for routes validated by RPKI server
CSCvg87048	Few Stale session are observed during vpdn longetivity
CSCvg98953	UEA_MGR Crash@uea_asic_mpls_lentry_modify seen during stressed soak run
CSCvh06249	Crash when receiving EVPN NLRI with incorrect NLRI length field value
CSCvh52708	RSP3: LAG LB is not working based on VC label
CSCvh55744	SSH password length restricted to 25 for avoiding one of the low impact vulnerability.
CSCvh58909	OSPFv3 cost calculation not correct in some specific topology
CSCvh61436	Nvram error seen while upgrading ROMMON in second RSP2
CSCvh67279	ADJ error object seen on Active
CSCvh69518	%SYS-3-TIMERNEG:Cannot start timer with negative offset Process= "ARP Background"
CSCvh76761	A900-RSP3C-200-S RSP module crashes while MPLS TE tunnel interfaces comes up
CSCvh96821	ASR1004 started relaying clients' DHCP Discover messages to DHCP Server with the wrong IP address
CSCvi01558	iBGP dynamic peer using TTL 1
CSCvi06358	Label & outgoing interface programmed wrongly for prefix in RSP3

Caveat ID Number	Description
CSCvi42002	CDP packets not getting encapsulated over multipoint GRE tunnel
CSCvi44298	ISR4451 Installs 2 IPsec SA's with different peers having same proxy identities
CSCvi52608	CLI show aaa clients detailed command triggered SSH to crash
CSCvi53346	RSP3 : BFD packets not sent out towards 9K after timer change and link flap
CSCvi65958	Standby RP crashes due to Memory usage in ospf_insert_multicast_workQ
CSCvi70145	ASR1k Segmentation fault in dhcp_sip process
CSCvi72479	ISR4K CWS - admission commands override (method-list vs bypass list)
CSCvi74088	link local multicast packets are received when the SVI is in down state
CSCvi93528	PI IOSd reload due to call-home at kex_dh_hash conn pointing to eem
CSCvj23301	IOS: Crypto Ruleset fails to get deleted
CSCvj27560	cman-fp/cmcc heartbeat failure crash due to pca954x channel selection errors.
CSCvj29126	RADIUS client on network fails to solicit PAC key from CTS even though the device has a valid PAC
CSCvj40006	[16.9 rsp3-qip]:adding one more vlan tag to the existing service instance causing entire traffic dr
CSCvj50537	ISSU Failure in Vz ME lab
CSCvj60379	RSP3: ARP Request Not Generated when IPv4 Routable Packets with L4 Header are Punted
CSCvj76013	RSP3: Error Objects wrt to Load balance on on increasing the BGP next-hop
CSCvj87273	False high temp readings from ARAD+ sensor causing system shutdown
CSCvk04547	Port-channel member link flap on RP OIR
CSCvk10633	bgp crash while running show command and same time bgp peer reset
CSCvk22455	3650 configured with AE and PK country codes crashes when 3800 AP plugged in
CSCvk49905	Crash when shifting the layer 2 LACP member peer from one link to another

Open Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4)

Caveat ID Number	Description
CSCvb96943	Offset from master jumps to Huge value with SPAN
CSCvd58258	IOS-XE display issue show hw-module subslot X/X transceiver X idprom detail
CSCve43404	PTP Clock Creation Fails for Specific Sequence of Triggers
CSCve54554	ASR-920-12SZ-IM will not warn when copying an invalid image
CSCvi02398	snmp mib and device configs not matching
CSCvi18644	ASR903 - BFD flaps during SSO

Caveat ID Number	Description
CSCux20143	RSP3/BFD:[new]Timeout not happening after shut of link with host traffic
CSCuz82303	Setting MTU to 9216 on routed interface causes scheduler(BRP/BRR) fail
CSCva43417	e1 Interfaces go DOWN on remote alarm (RDI)
CSCva61618	SADT throws Warnings more than one time for more iterations
CSCvb01698	LEAPSEC:leap second is not considered while setting PTP to system time
CSCve05859	Exxx EIN: G.8275.1 testing: Clock loop forming between synce and ptp
CSCve78337	MLP MRAPS Convergence is high on Work-Active SSO node
CSCvf09940	RSP3_2x10GE: output netsync drifting after SSO when locked to 2x10GE
CSCvg88747	IOS hung and stuck in loop if there is any issue in USB port
CSCvh06656	crash @ pak_qos_feature_object_cleanup
CSCvc59436	RSP3:Delay in updating egress efp stats for Tengig interfaces
CSCvd44667	RSP3: PREFIX Object Errored Objects on Local Core Flaps and in Parallel on Other Routers in the Core
CSCvd50734	RSP3-200:Router Crash while trying to delete label uea_oce_base_delete uea_mpls_label_delete_async
CSCvd77735	RSP3 - Small loss (6-10ms) observed for VPLS traffic when BGP backup peer is powered down
CSCvd89421	RMEP failure due to CFM HW table corruption
CSCve05859	Exxx EIN: G.8275.1 testing: Clock loop forming between synce and ptp
CSCve14324	ASR 907 / RSP3C : port level shaper is counting packets twice.
CSCve86912	[Counter]: Giant/Runt/Pause Frame counters issue.
CSCvf08577	RSP3 Arad not able to timestamp higher stream id packets in default profile
CSCvf08656	RSP3 : Traffic failure for few Labelled BGP prefixes (BGP label imposed is incorrect)
CSCvf16468	RSP3-QIP: CFM H/w offloaded sessions over xconnect affecting S/w sessions configured over BD
CSCvf19136	Debugability : show platform software agent iomd <> np datapath hdlc <CEMA-ID>
CSCvf21748	RSP3-QIP: Traffic flowing though TEFP is shut in G8032 ring

Caveat ID Number	Description
CSCvf34496	RSP3-QIP:Error objects on Stby cfm_mp_ifh 16794673 sid 3001 download to CPP failed seen upon IM-OIR
CSCvf45267	RSP3 - Loadbalance map not getting deleted (IM OIR)
CSCvg84699	BFD session not coming up on RSP3 due to wrong platform offload limit
CSCvg99675	RSP3:Transient FRR download failure during soak testing
CSCvh15762	RSP3: IOSd Crash in FastPath Thread during Punt Packet Buffer Dequeue on ARP Flaps Soak
CSCvh51179	RSP3: Stale Mac entries are present on a specific scenario which results in ADJ download failure
CSCvh77868	ASR-903 (RSP3_400) fsck of bootflash returned error code 8. Recommend reformatting
CSCvi06300	RSP3: Pending issues seen when converting from Access EFP's to Trunk EFP's
CSCvi06358	Label & outgoing interface programmed wrongly for prefix in RSP3

Resolved Caveats—Cisco IOS XE Release 3.18.4SP (Cisco IOS Release 15.6(2)SP4)

Caveat ID Number	Description
CSCvc38538	IPSLA Y1731 start time is much greater than sysUpTime while doing snmpwalk
CSCve64336	RSP1-Continuous ESMC tracebacks observed after IMA8T OIR followed by SSO
CSCvf51341	Crash after show ip ospf database summary command
CSCvf63541	BGP w/global import/export crashes when several nbrs deleted simultaneously
CSCvf83216	ASR903: Negative broadcast counters on port channel interface after clearing the counters
CSCvf84349	Router crash on polling cEigrpPeerEntry
CSCvf95077	Stale Mac entry in MLRIB
CSCvg03542	[RIB route watch] detect stale pointer from client to avoid system crash with corrupted memory
CSCvg07169	D6 Update attribute Total Bandwidth = 37901kbps is incorrect

Caveat ID Number	Description
CSCvg14825	Require varbind entSensorPrecision,Scale & Type along with trap entSensorThresholdNotification
CSCvg70173	ASR920 : Not able to configure xconnect untagged service instance with EVPN under the same interface
CSCvg85163	ZTP not triggered with Gratuitous ARP
CSCvg97160	on ASR920-24SZ-IM Tengig interface MTU has not been set more than 1500 in H/W
CSCvh71856	IOSd crash when enabling dot1q in a port-channel sub-interface
CSCvh86486	ASR-920-12SZ-IM: Cisco ASR 920 routers issue with sfp-h10gb-cu1m cabling
CSCuy30341	Skywalker: Failed to create, Pseudowire interface
CSCvb96911	OSPF NSSA Translator ABR does not Translate Type 7 to 5 with only VRF Superbackbone as non-NSSA area
CSCvc38538	IPSLA Y1731 start time is much greater than sysUpTime while doing snmpwalk
CSCvc63685	%QOS-4-INVALIDDBW: errors occur on reboot when policing is used
CSCvd87285	ASR920 - Display issue - Egress i/f and L2 stats shows "unknown" and no packet drops
CSCve64341	920 : Mid Point LSP creation failure after reload with latest polaris Image
CSCvf76512	option 82 circuit-id-tag restricted by 6 bytes
CSCvf80495	IPv6 BGP network advertized not seen in the peer
CSCui67191	Cisco IOS XE Software Ethernet Virtual Private Network Border Gateway Protocol DOS Vulnerability
CSCvc38538	IPSLA Y1731 start time is much greater than sysUpTime while doing snmpwalk
CSCvc61899	static route is not getting redistributed into RIP database
CSCvd38391	Standby Router: uea_mgr crashed @ ml2vpn_provision_pw_and_ac
CSCve37398	RSP3-L2VPN: Load balancing is happening based on wrong fields in P node when CW is enabled.
CSCvf30801	RSP3-QIP: LTM b/w CEs not working if MIP is configured on PE participating in VPLS
CSCvf52432	RSP3:Pending-issues & Ack upon defaulting all core interfaces in VPLS scale setup
CSCvf55306	Static route of which next-hop intf is GRE tunnel remains even if the tunnel is down
CSCvf56274	BGP VRF route redistribution into global routing table fails after a VRF route flap

Caveat ID Number	Description
CSCvf62916	Router crashes when doing "show ip bgp neighbor" on a flapping BGP neighborhood
CSCvf67269	IS-IS support for multi-instance redistribution for IPv6.
CSCvf72154	RSP3 - PIM neighborhood down on BDI interface due to packets ASIC loop.
CSCvf82663	ASR903/RSP3C crashed at dl_callback
CSCvg03308	[RSP3-DHCP-Relay]:unicast dhcp relay is getting dropped in transparent case with HSRP/VRRP/GLBP
CSCvg03542	[RIB route watch] detect stale pointer from client to avoid system crash with corrupted memory
CSCvg28721	RSP3:uea-mgr crashed while trying to install a label entry in kbp(update case)
CSCvg42691	RSP3- P node ECMP loadbalancing failing for ip traffic
CSCvg43975	RSP3: Leak in G8032 IOS TDL Messaging on Flapping the Ring
CSCvg48485	RSP3 - Ingress LDP label incorrectly programmed to FEC 0x0
CSCvh08220	RSP3: Crash in IOSD chasfs task on Defaulting and Removing IMA-1X
CSCvh10730	BFD stuck at init state for Sessin ID 1023 alone on ASR903 RSP3C after link flap
CSCvh20968	Multicast traffic not forwarded on VPLS after trigger
CSCvh51377	RSP3_400 : False Tx bias violation alerts seen on console with CPAK-100G-LR4 SFP's

Open Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3)

Caveat ID Number	Description
CSCvg03308	Unicast dhcp relay is dropped in transparent case with HSRP/VRRP/GLBP
CSCvf84386	Router crashed after configuring PPP CHAP in multilink interface (OC3IM OC12IM)
CSCvf53910	Router crash on removing ipv4 address from BDI
CSCvf30034	On shut/no-shut Scaled BFD sessions continue to Flap, never stabilizes.
CSCve52155	RSP3: BFD Session Between 2 RSP3s Down on Reloading 1 RSP3
CSCve49550	IOX: OOS issue seen with 100Mbps sfp inserted on a SFP combo IM

Caveat ID Number	Description
CSCvf75773	RSP1: SYS-2-INPUT_GETBUF: Bad getbuffer, ... Process= ""<interrupt level>" traceback seen in RSP1.
CSCvf02136	VLAN Untagged Traffic Wrongly Punted to CPU When Service Instance Deleted
CSCvd89421	RMEP failure due to CFM HW table corruption
CSCvf30801	RSP3-QIP: LTM b/w CEs not working if MIP is configured on PE participating in VPLS
CSCvf34496	RSP3-QIP:Error objects on Stby cfm_mp_ifh 16794673 sid 3001 download to CPP failed seen upon IM-OIR
CSCvd83274	ASR903/RSP1B 4second upstream packet loss after SSO
CSCvd34256	RSP1 & RSP2 : metchain points to drop handle on SSO
CSCve37398	RSP3-L2VPN: Load balancing is happening based on wrong fields in P node when CW is enabled.
CSCvd44667	RSP3: PREFIX Object Errored Objects on Local Core Flaps and in Parallel on Other Routers in the Core
CSCvf52432	RSP3:Pending-issues & Ack upon defaulting all core interfaces in VPLS scale setup
CSCvf72154	RSP3 - PIM neighborship down on BDI interface due to packets ASIC loop.
CSCvf21368	RSP3: UEA_Mgr Crash on Checking IPv6 Multicast Flow in the Platform while Flows are Flapping
CSCvd13823	Storm control - L3 Mcast Traffic :: Not all packets are dropped
CSCvd06766	BC slave port stuck at Initializing state upon BC gets reconfigured.
CSCve05859	Exxx EIN: G.8275.1 testing: Clock loop forming between synce and ptp
CSCve43404	PTP Clock Creation Fails for Specific Sequence of Triggers
CSCvf08577	RSP3 Arad not able to timestamp higher stream id packets in default profile
CSCvf21504	RSP3: Gig TX RX Fails when RP SSO During Link Flap of Another Gig on Same IMA8S1Z IM
CSCve87759	RSP3: Link flaps on configuring G8275.1
CSCuz82303	Setting MTU to 9216 on routed interface causes scheduler(BRP/BRR) fail
CSCve86912	[Counter]: Giant/Runt/Pause Frame counters issue.
CSCvf13101	903/RSP3 - Active RSP3 crashes without any core file and standby RSP3 in hung state
CSCvf35475	RSP3: Standby RP packages.conf Not Updated when RP Crashes after RP SSO during ISSU
CSCvc50710	RSP2: Standby RP Crash in HA-IDB-SYNC Process on SOAK of Delete Reconfig CEM and ACR
CSCvb96943	Offset from master jumps to Huge value with SPAN
CSCvf80159	ASR9xx: nile_mgr crashes from cef lb msg
CSCvd77735	RSP3 - Small loss (6-10ms) observed for VPLS traffic when BGP backup peer is powered down
CSCvf03668	Mid-chain ADJ Error Object on MPLS TE Tunnel Interfaces and Core Gig Flap SOAK

Resolved Caveats—Cisco IOS XE Release 3.18.3SP (Cisco IOS Release 15.6(2)SP3)

Caveat ID Number	Description
CSCvf06768	TSoP: Add support for handling link failure (LOS condition)
CSCvd39154	RSP3: Preservation of Inner DSCP for IPV4 and IPV6 in Uniform Mode
CSCvd45201	Application of MQC under EC interface results in policing TeGi interface
CSCvd82957	RSP3 - L3VPN convergence during BGP LU PIC Edge is high
CSCve13089	License:unexpected rommon license boot variable&boot level metroservice configs set in standbyRSP3 .
CSCve49784	ASR903-RSP1/RSP3/RSP2 and ASR920 : router crashed during SNMPwalk in ISSU/SSO/reload
CSCve50842	OIR of PSU doesnt turn off of power supply alarm with platform expect-single-psu command
CSCve54991	Memory leaks due to Flexible NetFlow
CSCve58878	No APS trigger to Protect with core flaps/recover in Work followed by protect & then on work
CSCve81583	G8265.1: PTP not locking with some disturbance on master or master switch triggered
CSCve88177	Router reloaded due to SYS-2-INPUT_GETBUF: Bad getbuffer, ... Process= ""<interrupt level>"
CSCve91007	IoT: c3794 and EnM IMs are "out of service" in RSP2-64
CSCvf06768	TSoP: Add support for handling link failure (LOS condition)
CSCvf20723	Power supply alarm generated in the absence of power supply
CSCvf27398	RSP1: IOSd Crash in OCE Punted Pkts Process on ARP Flaps SOAK on Downstream Router
CSCvf54458	903: OOS issue seen at 8X1G IM
CSCvf55743	ASR903: ifHCInBroadcastPkts, ifHCOutBroadcastPkts return incorrect decreasing values for portchannel
CSCvf61265	Router was stucked in boot loop due to Line card in Slot 3 A900-IMA16D
CSCvf63185	Sticky bit not cleared and IOMD CPU utilization going upto 50%
CSCvf75418	Combo IM/2x10gig IM iomd cpu utilisation more than 50%
CSCve29462	BFD/ISIS stays in INIT-Down state on multiple interfaces.
CSCvf33518	On SSO L3VPN prefix is programmed with LFA backup interface as primary interface in PD.
CSCvf06625	Programming mismatch between Active & STBY after STBY reload for L3VPN prefix
CSCvd29919	RSP3-Not able to ping external IPv6 address from BINOS.
CSCve73883	[ASR903] RSP3 Ping is not successful after IP moved to different EFP
CSCvc60542	100% traffic loss seen with vlan_disable & untagged traffic in latest polaris_dev
CSCve22853	ASR900 improper SIGDET register setting could cause traffic failure and link down conditions
CSCvf01287	ASR907: ARP not getting resolved due to link fault between ARAD and PHY
CSCvf21487	ASR907: L2VPN attachment circuit is going down after SSO on the line card A900-IMA8S1Z
CSCvd99533	PHY INTR disable during XCVR INIT
CSCve65904	Tengig port going down after few reloads
CSCvd04381	Loopback local at tug levle e1 or t1 doesnt handle the Alarm condition
CSCvd69942	100% ipv6 packet drop for downstream traffic on ASR903 (RSP3C) when RPL state changes.

Caveat ID Number	Description
CSCvf21127	2 AC's in a VFI, when one interface is shutdown, traffic is not flood to other interface
CSCve10269	RSP3 unable to route(drops) unicast dhcp packets with giaddr field as 0.0.0.0
CSCve77231	RSP3:traffic failure on VRRP session and traces @ vrrp_comms_process_pak
CSCve10547	[RSP3-DHCP]:rsp3 is dropping dhcp bootp packets with src port 4011 and dest port 67/68
CSCve56434	"FMFP-3-OBJ_DWNLD_TO_DP_FAILED: SIP0: fman_fp_image: LENTRY" upon PC flap
CSCve26350	100% downstream loss after SSO on rsp1b
CSCve15834	BGP PIC-E: Double dip traffic loss on recovering primary ABR for CEM And EOMPLS VC
CSCvc32082	Handling FRR for reopt cases
CSCvc40326	HSPW : pw programming going for toss and traffic gets dropped after int flap
CSCvf05386	RSP2: Standby RP Get AToM Forwarding Context Cylon_Mgr Crash on Core Gigs Flap SOAK on RRs
CSCvf05587	RSP3 : 2 KBP entries created for ingress vpnv4 label - Label swap case
CSCvd96938	RSP3 crashes @ tbn_lookup, uea_cef_get_leaf
CSCve71908	RSP3-SOAK-Observing error objects "LB 0x938f download to DP failed" with soak
CSCvf22961	RSP3: VFI RCY LABEL IDMGR Leak on ARP and MAC Tables Flaps SOAK
CSCve81377	RSP3:CFMoVPLS scale:VPLS PD entry missing for few neighbors upon Soak
CSCvd57077	RSP3:Traffic Fails on FRR backup path while Primary is Active.
CSCvd76024	RSP3C : LB-MAP download error (PMF Prot Ptr already exists)
CSCvd42420	UMMT XE318SP RSP3: UEA_Mgr Crash in TBM Search on NFT PTP Next-Hop Lookup
CSCvd24027	UMMT XE318SP-ES5 RSP1 SOAK: PAN3 Nile_Mgr Crash on Flapping Global IPv4 and IPv6 Routes
CSCvd55076	UMMT: RLFA FRR - High convergence on shutting the core link
CSCve27750	ASR903/RSP1B Multicast Joins are not forwarded in ERPS scenario from Non-DR to DR.
CSCve88827	RSP1B not forwarding multicast traffic after ERPS link flap
CSCvd32237	RSP2 : MLDPv4 Full scale no DI programming on HE
CSCvd36747	RSP3 - Native IPv6 multicast stops working with soak test
CSCvd75444	UMMT XE318SP RSP1: Nile_Mgr Crash in IPv6 Native Multicast on Boot-up
CSCvd07855	1pps under a virtual port remains down after SSO on RSP2
CSCvd47051	8275.1 DPLL1 Lock status OFF sometimes
CSCve92481	After ASR9k PTP reconfiguration, slave 903 stuck in freq-lock state.
CSCve87122	Frequency Traceable Flag is set to false on downstream routers when 1pps is made down on TGM
CSCvd12047	G8275.1: syncE drift when PTP is removed from G8275.1 TBC.
CSCvd69590	G8275.1_RSP3: accuracy is ~500nsec when it uses to 10GE IM on first time boot
CSCve09409	HBC Slave router doesnot choose best clock based on Clock Class
CSCve27195	Non PTP packets getting timestamped post PTP loopback shut at PTP master
CSCvd83975	ptpd_uea crash observed after switchover
CSCvd72847	RSP2: [SW Workaround for FPGA bug] TOD load failing with IMA8S1Z after IM-OIR
CSCvf24207	RSP2_BC: Accuracy is bad on RSP2
CSCvf38857	RSP3 PTP BC is not locking to the Master via intermediate PTP aware nodes with tagging enabled.

Caveat ID Number	Description
CSCve83541	RSP3: IOSd Crash on Deleting PTP Loopbacks during ISSU SOAK
CSCve12246	RSP3: RSP3 which is locked to GNSS VP is not giving better accuracy
CSCvd00614	RSP3:BFD is flapping when removing PTP config
CSCvf19017	RSP3_GNSS: ToD down after reload on G8275.1T-BC
CSCvd49392	SETS introducing 1pps out value in 479ms as compared to input 1pps
CSCve34869	Traffic is not operation though it is up at 1G port.
CSCve43475	Vitesse SDK API's for timestamping should be called under WD disabled
CSCvd67376	ASR920 'set mpls experimental topmost' is causing 'set mpls experimental imposition' to not work.
CSCvd72604	Crash after policy map applied
CSCvb83795	RSP2: Queue node stuck during config replace results in 100% traffic loss on MLPPP Interface
CSCvd34788	ASR903 with RSP3 might crash with reason bulk sync failure
CSCvf40636	RSP3-200:Observing Packets drops if the Line Rate is more than 32%
CSCvd82999	ASR903 R0 suddenly switchover
CSCvd42504	UMMT XE318SP RSP1: Kernel Crash on Core 1G 10G Interface and BFD Flaps Multiple Times on Peer
CSCvc95602	ASR903 SDH counter errors
CSCvd79657	ENTITY-MIB table entries missing for E1/T1 ports on the IMA16D card for ASR903
CSCve73831	THS:After SSO/ISSU observed AIS Alarm in SYSTEM THS with XE318SP Image
CSCve65791	RSP1:Unexpected reload occurred in RSP1 with iosd crash and reload reason2
CSCvd38455	ASR 903 after RSP switchover stop to pass traffic for one BDI
CSCvb01698	LEAPSEC:leap second is not considered while setting PTP to system time
CSCvc99710	configuration of no-crc4 on protected cem-acr is failing
CSCvc21452	ASR903:ISIS routes are set with Max Metric due to IGP LDP Sync
CSCvc51408	ISIS route oscillation due to ldp sync and interface max metric
CSCvd81475	PTP: Transparent Clock is not supported on RSP3
CSCvd81474	PTP: Virtual-Port is not supported on RSP2
CSCvd00780	8275.1: PTP Packets are being dropped without untagged EFP on a tagged EFP interface
CSCvc94414	RSP3: Incorrect traffic rate received with specific values of CIR/PIR in HQOS policy
CSCvb82613	Tunnel/IGP down on SSO due to ingress VOQ packet drop

Open Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2)

Caveat ID Number	Description
CSCvb45433	SLOS reported when we shutdown ais-shut enabled in SDH and SONET mode
CSCvd38455	ASR 903 after RSP switchover stop to pass traffic for one BDI
CSCvb01698	LEAPSEC:leap second is not considered while setting PTP to system time

Caveat ID Number	Description
CSCvb96943	Offset from master jumps to Huge value with SPAN
CSCvc99710	configuration of no-crc4 on protected cem-acr is failing
CSCvb51372	CEM jitterbuffer underruns with CEM marking policy
CSCvc21452	ASR903:ISIS routes are set with Max Metric due to IGP LDP Sync
CSCvc51408	ISIS route oscillation due to ldp sync and interface max metric
CSCvd81475	PTP: Transparent Clock is not supported on RSP3
CSCvd81474	PTP: Virtual-Port is not supported on RSP2

Resolved Caveats—Cisco IOS XE Release 3.18.2SP (Cisco IOS Release 15.6(2)SP2)

Caveat ID Number	Description
CSCvd12231	RSP3: Unicast ARP resolution fails in VRRP master state
CSCvc93188	Point to point is not pinging in REP topology on upgrade to 3.18SP1
CSCvc44209	RSP3: PTP synchronization not working MPLS speculative parsing
CSCvb91263	Memory leak in Cylong_mgr with native multicast configuration
CSCvb72640	MET Entries getting exhausted
CSCvb44210	EXP marking fails for untagged flows on EFP with "default" encapsulation
CSCvc37483	Memory leak in SNMP on ASR903 with RSP3c/RSP2
CSCvc27413	nile_netif (ERR) LINK messages are wrongly mapped ERR's in tracelogs
CSCvc15717	Fan speed control measures for overheating ASR920
CSCvb58857	LDP NSR : Remote Side VCs stays up even with local access interface shut after SSO
CSCvb41889	NTP leap second inserted every day after leap second occurs
CSCvb46984	Leap second is being set in spite of leap ignore being configured
CSCvb18384	SPF on adjacency down must wait for LSP GEN
CSCvc53794	RSP3: PTP over MPLS support
CSCvc77387	RSP3-DHCP-Relay]:unicast dhcp relay is getting dropped over vrf (transparent case)

Open Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1)



Note

The Cisco IOS XE 3.18.1SP release is applicable only on the Cisco ASR900 RSP1 and RSP2 modules. The Cisco IOS XE 3.18.1bSP release is applicable only on the Cisco ASR900 RSP3 modules.

- [Open Caveats—Cisco IOS XE Release 3.18.1bSP, page 21](#)

Caveat ID Number	Description
CSCva16169	DS1:Traffic not resuming after Ctrl shut then SSO and No shut
CSCva54675	Incorrect Input/Output Rate Counters on T1/t3 CEM interface
CSCvb84096	"no channelized" configurations not saved for the DS3 ports
CSCvb77938	DS3 : On Channelized T1, AIS is not reporting properly
CSCvb13590	ASR900: OC3 IM Stops MLPPP Traffic due to Winpath BUS ERROR
CSCux45450	ASR900: OC3 IOMD CPUHOG on SOAK Test of SONET Shut and No Shut
CSCvb53939	CEMoUDP ACR : Cem circuit traffic loss on unconfiguring One Cem Ckt
CSCvb88307	Error on OCx IM soft reset with hw rev 1.0 OR less
CSCvb38142	MR-APS MLP. Fwding failure on Protect Activ SSO (With work disabled)
CSCvb62473	unwanted cem counters increment for 64kbps speed
CSCvb61221	RSP3 : IKEv2 IPsec tunnels stays down after ISSU
CSCvb59196	RSP3 : Ping/Traffic Failure on IPsec Tunnels after SSO
CSCvb73784	"dhcp_snooping_platform_parse_evc_cid: idb not found" for IMs on bay 15
CSCvc03169	"l2protocol tunnel" issue with Portchannel numbers >32
CSCvb77215	RSP3 : 6PE/6VPE traffic drop on SSO for ~30-40sec with VRRP
CSCvb75091	RSP3C is sending tagged PTP Packets to downstream node
CSCvb62690	ASR903 MPLS Label mismatch issue in PD
CSCvb17783	ASR903: RSP3C leak of PMF protection pointer resource
CSCvb72995	P2P Ping Failure due to ChCompactChecksumerrorCount
CSCvb49400	RSP1:Back to back failed because of either Invalid adjacency in PD or Incomplete adjacency in PD
CSCvb63314	Traffic not egressing out on AC after Standby PW became Active PW
CSCvb67543	uea mgr crash @"uea_mpls_atom" upon flapping core A/A Poch interface of peer box
CSCvb91263	Memory leak in Cylong_mgr with native multicast configuration
CSCvb72640	MET Entries getting exhausted
CSCvb35480	Port-channel flaps when OIR of RSP is done on RSP1
CSCvb71584	Bulk-sync failure - t3 clock source internal
CSCvb79737	RSP2: CEM Disposition FID Not Programmed on SONET Shut No Shut SOAK
CSCvb69334	RSP3 : default ingress CEM policy marking does not marks CEMoMPLS
CSCvb05110	ACR Not able to remove cem configs if only single physical controller is configured
CSCvb51372	CEM jitterbuffer underruns with CEM marking policy
CSCvb84308	CLI are not accepted for Path configured as T3 Mode.
CSCva77248	OCx APS-ACR ACR-DCR: ACR/DCR is not enabled for CT3 mode for t1 5
CSCvb57740	OCN IM Crash post IM FPGA upgrade + SSO
CSCvb78285	OCx:Iomd crash on Active RSP post SSO of admin down IM
CSCvb78369	OCX:Standby RSP crashed with hw-module stop
CSCvb24067	PMON Cleanup

Caveat ID Number	Description
CSCvb55300	Port-lic: Port licensing cmds Not synced to HA when IM is shut
CSCvb71044	RSP1: TUG2 AIS Alarm Not Syslogged
CSCuz39371	STS-1 path behaviour problem upon controller shut.
CSCvb68652	VTCEP AIS & B3 alarms on SSO & few DS1/VT1.5 SATOP with AIS
CSCuz51456	TSOP OC3 , POS takes 1-10 seconds to Convergence on SSO
CSCvb95537	VCoP OCx requesting the OCx license on the fly whenever the VCoP platform cmd configured
CSCuz89582	VCOP: B1/B2/B3 errors not detected

Open Caveats—Cisco IOS XE Release 3.18.1bSP

All open caveats that apply to Cisco IOS XE Release 3.18.1SP also apply to Cisco IOS XE Release 3.18.1bSP.



Note

This release is applicable only on the Cisco ASR 900 RSP3 Module.

Resolved Caveats—Cisco IOS XE Release 3.18.1SP (Cisco IOS Release 15.6(2)SP1)



Note

The Cisco IOS XE 3.18.1SP release is applicable only on the Cisco ASR900 RSP1 and RSP2 modules. The Cisco IOS XE 3.18.1bSP release is applicable only on the Cisco ASR900 RSP3 modules.

- [Resolved Caveats—Cisco IOS XE Release 3.18.1bSP, page 23](#)

Caveat ID Number	Description
CSCva90880	RSP1: Crash observed and the RSP1 box is reloaded.
CSCva63859	CEM FPGA Upgrade on ISSU
CSCva85759	CLI and MIB value not matching
CSCva27910	DS3 Jitterbuffer underruns/overruns
CSCvb25070	DS3: DSX-3-T3CFG_ERROR seen on standby console with ctrl shut
CSCva05301	4xOC3 IM unable to reset itself after IM FPGA upgrade
CSCuz95664	ASR900: OC3 IM Runs Out of FIFO Buffer on Reassembling MLPPP Fragments
CSCuz95621	ASR900: OC3 IOMD Crash on RP SSO while MLPPP Scale Sessions Flap
CSCva30101	snmp mib and device configs not matching
CSCva73212	serialim payload size should be started from 4
CSCvb83576	ASR903 crash & reboot when set ospfv3 auth & ipv6 BDI & Porchannel.
CSCvb39328	IM in Slot 2 is OutOfService without IPsec license on UNIVERSALK9 image

Caveat ID Number	Description
CSCva99605	RSP1B:AIS enter/exit defect condition msgs even with RMEP's learnt
CSCva95949	G8032:Getting doubled packets at access side in RSP2
CSCvb18966	mIacp standby POA link forwards mcast/broadcast traffic after reboot
CSCvb41430	Ping fails on BDI configured for EVC untagged poch interface
CSCvb25184	RSP3: Ingress traffic flow via AdminDown EFP on PoCh interface
CSCCuz90585	RSP3:Egress filtering rule might fail here messages on configuring T-EFP
CSCva13798	RSP3:Uea mgr crash on "show mac-address-table secure" command
CSCva38115	SMMac on EFP not getting flushed out on deleting & reconfiguring the BD
CSCCuz94074	Spanned CCM tx packets are incorrect for Up mep on 1gig interface
CSCvb50175	Traffic flow via mst block port upon removing & re-add mem-links across IM
CSCvb50432	[RSP3-DHCP-Relay]:unicast dhcp relay is getting dropped in transparent case
CSCva21655	BDI MPLS MTU cannot be set more than 1500
CSCCuy46447	Flex-LSP:Tunnel flap is observed due to W-LSP BFD goes down after reopt
CSCva39555	MPLS Forwarding Issue on ASR903
CSCva66169	RSP2 crashed @ nmpls_lentry_get_atom_fwd_ctxt when flaps
CSCva01298	RSP2: 1st Iteration PIC Edge Cutover Downtime Above 1sec on VC Flap
CSCvb61160	RSP3: HW-LB: L3VPN - Path is preselected though PIC is enabled
CSCCuy07786	RSP3:ECMP Load-balance for TAG-TO-TAG in hardware does not work
CSCva52316	uea_mgr crash is observed after multiple shut/no shut xconnect
CSCva77243	PIM neighbours doesn't come up with portchannel on shutting the backup link
CSCvb63102	cfm interface status tlv show down when CFM up mep session running on top of HSPW
CSCva77020	cmand crashes while doing SSO
CSCva51751	PTP packets are not time stamped with MPLS label
CSCva14621	ptpd_uea crash due to watchdog due to mutex deadlock
CSCvb49938	UDP packets are getting corrupted in MPLS De-Agg case
CSCvb19265	IPv6 QoS ACL - When host ip doesn't get matched traffic flow is blocked
CSCvb34371	Qnode struck when attaching qos policy on members of portchannel
CSCva97899	RSP2: class level queue getting exhausted on hqos configuration
CSCvb00921	EXP to COS propagation for CEM traffic
CSCva71102	"cefcFanTrayOperStatus" to provide a state "warning(4)" for fan failures
CSCva89579	Incorrect values for cevcEvcStatusChangedNotification trap components
CSCva61563	MRAPS 1+1: High convergence on work active router reload
CSCvb39826	MRAPS 1+1: one sec traffic outage on protect active reload.
CSCva06999	ACR/DCR Clock state is not changing for shut on CE after SSO
CSCvb32105	APS STS-3C CEP TX failure due to null DMAC for CEM in FPGA
CSCvb28653	OCx controller state not in sync on shut/no shut
CSCvb41793	Port Licensing

Caveat ID Number	Description
CSCva79592	Epar enablement and support of N/P bits and ACR support on APS
CSCvb01623	Loopback network for ct3 and vt1.5 not working
CSCvb05150	Not able to remove cem-config
CSCvb69429	OCx: Active RSP crash after OCN IM OIR
CSCvb42004	OCx: Syslog Msg for AC_DCR for T1 to change
CSCvb05140	Order of removal of global recovered-clock config
CSCvb85315	POS interface J1 byte message & PATH TRACE not seen under show controller POS<> output
CSCvb81516	router crash when show platform software dpidb index command is run
CSCuy11711	TIM-S,TIM-P and TIM-V fields are not showing on show controller output
CSCva63855	Unable to configure APS service with CEM group > 0
CSCvb47802	VZ IM: STS-12c crashed after multiple config + unconfig

Resolved Caveats—Cisco IOS XE Release 3.18.1bSP

All resolved caveats that apply to Cisco IOS XE Release 3.18.1SP also apply to Cisco IOS XE Release 3.18.1bSP.



Note

This release is applicable only on the Cisco ASR 900 RSP3 Module.

Caveat ID Number	Description
CSCvc45543	RSP3: Outgoing interface/label is not correctly programmed
CSCvc44209	RSP3: PTP synchronization not working MPLS speculative parsing

Open Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP)

Caveat ID Number	Description
CSCux62561	Flex-LSP:High convergence is observed randomly during cutover
CSCux74888	DS3: uea_mgr crash seen after multiple IM hard OIR
CSCuz26189	Standby crashed after several iterations of Config/Unconfig script
CSCuz49527	slot 5 in 907/4216,intermittent drop & traffic down post router reload
CSCuz51456	TSOP OC3, POS takes 1-10 seconds to Convergence on SSO
CSCuz78113	OCx HA: Traffic outage is seen during SSO for few ckts at 4K scale
CSCuz83377	GNSS:Huge offset seen in HBC on OC-M RSP3 switchover
CSCuz89880	RSP1: EoMPLS HSPW Traffic Fails as NILE Disposition Object Invalid

Caveat ID Number	Description
CSCuz92275	RSP3: Egress COS marking not supported on inner vlan (dot1q/ad)
CSCuz95621	ASR900: OC3 IOMD Crash on RP SSO while MLPPP Scale Sessions Flap
CSCuz95664	ASR900: OC3 IM Runs Out of FIFO Buffer on Reassembling MLPPP Fragments
CSCva01298	RSP2: 1st Iteration PIC Edge Cutover Downtime Above 1sec on VC Flap
CSCva06999	ACR/DCR Clock state is not changing for shut on CE after SSO
CSCva14263	DS3 IM: IOMD crash on slot 10 in DSx loaded setup over router reload
CSCva14445	OCN IM FPGA Upgrade fails with ISSU
CSCva16169	DS1:Traffic not resuming after Ctrl shut then SSO and No shut
CSCva19705	RMEP not learn with PUSH TAG + FLEXLSP
CSCva27910	DS3 Jitterbuffer underruns/overruns
CSCva48138	G8275.1 : Peer interface down with local SSO or config changes on RSP2
CSCux45450	AASR900: OC3 IOMD CPUHOG on SOAK Test of SONET Shut and No Shut
CSCux89775	RSP2:CFM UP MEP is not working when the core interface are POS
CSCva05301	4xOC3 IM unable to reset itself after IM FPGA upgrade
CSCva41678	OC3 IM continuously rebooting after shutdown at high temperature

Resolved Caveats—Cisco IOS XE Release 3.18SP (Cisco IOS Release 15.6(2)SP)

Caveat ID Number	Description
CSCuw26295	RSP1: MR-APS Protect Active RSP SSO Convergence Time 2 seconds
CSCux57467	IOT:E&M: 1/6 IM does not come up when we insert 6 E&M IM in 1 chassis
CSCux62888	RSP2: 126 EAIDs Leaked when 126 MLPPP Bundles Flapped
CSCux77242	RSP3-IGMP snooping not able to snoop joins of all 800 groups from a rcvr
CSCux78031	RSP2: CEM Disposition Traffic Fails on Protect Active SONET Shut No Shut
CSCux91743	32T1E1: 1st VC goes down after Unconfig/Config of Loopback associated
CSCuy00543	RSP3 : Observing cfm errors due to missing fields in ccm
CSCuy09081	RSP2: MLP Ingress Traffic Fail as InL3IDC Not Programmed on SONET Flaps
CSCuy35875	Tx bias low alarm on 100G CPAK 100GE LR4 optics
CSCuy81971	ZR sfp+ link going down in remote side with sso, in 2X10gig im
CSCuz01915	RSP-3C-200 BFD stuck in Init state
CSCuz39929	ASR900 memory leak in SSFPD code
CSCuz89488	EPAR clocking: PAIS seen every 10mins for STS-12C CEP
CSCva13798	RSP3:Uea mgr crash on "show mac-address-table secure" command

