

# Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.7(0)

December 07, 2022

---

# Contents

<b>What's new in this release</b> .....	3
<b>Installation</b> .....	3
<b>Open bugs</b> .....	4
<b>Resolved bugs</b> .....	4
<b>Bug Search Tool</b> .....	4

---

These release notes support the Cisco Wireless Phone 840 and 860 software release 1.7(0). These wireless smartphones require:

- **Call Control**
  - Cisco Unified Communications Manager
    - Minimum: 11.5(1)
    - Recommended: 12.5(1), 14.0(1), or higher
  - Webex Calling
- **Wireless LAN Controller and Access Points**
  - See the [\*Cisco Wireless Phone 840 and 860 Deployment Guide\*](#) for supported solutions.

## What's new in this release?

The following sections describe the features that are new or have changed in this release.

### Phone Volume Control Application

The new Sound Stage application for the Cisco Wireless Phone 840 and 860 allows administrators to configure sound profiles and volume levels for the system and application sounds.

### Ringtones per Line

Ringtone can be configured for each line from the Cisco Phone application on the Cisco Wireless Phone 840 and 860, where with previous releases, only a single ringtone could be configured that applied to all lines.

### Maximum Battery Charge Cycles Notification

A notification will be presented when the Cisco Wireless Phone 840 or 860 battery has reached 500 charge cycles to inform the user that the battery should be replaced. The current number of charge cycles is visible in the Battery Life application when battery monitoring is enabled.

### Lightweight Directory Access Protocol (LDAP) for Webex Calling

The Cisco Wireless Phone 840 and 860 now supports the Lightweight Directory Access Protocol (LDAP) feature for Webex Calling.

### Local Phone Unlock Password for Webex Calling

The Cisco Wireless Phone 840 and 860 now supports the Local Phone Unlock Password option for Webex Calling.

## Installation

Refer to the following documents for installation instructions.

840 - <https://www.cisco.com/web/software/282074288/162502/cmterm-840.1-7-0-1523-51408-readme.html>

860 - <https://www.cisco.com/web/software/282074288/162502/cmterm-860.1-7-0-1975-51408-readme.html>

## Open bugs

Bug number	Description
<a href="#">CSCwb11302</a>	EMMA - the EAP Phase 2 auth options for PEAP should only be MSCHAPV2 and GTC
<a href="#">CSCwc31472</a>	WxC: Resync_Periodic not occur at the specific time period

## Resolved bugs

Bug number	Description
<a href="#">CSCwc09897</a>	Web access is disabled when the phone is manually put into WxC mode and the profile rule is entered

## Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- View [All Caveats](#)
- View [Open Caveats](#)
- View [Resolved Caveats](#)

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)