



Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(0)

First Published: 2023-10-16

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(0)

These release notes support the Cisco Wireless Phone 840 and 860 software release 1.10(0). These wireless smartphones require:

- **Call Control**
 - Cisco Unified Communications Manager
 - Minimum: 11.5(1)
 - Recommended: 12.5(1), 14.0(1), or higher
 - Webex Calling
- **Wireless LAN Controller and Access Points**
 - See the [Cisco Wireless Phone 840 and 860 Deployment Guide](#) for supported solutions.

What's New in This Release?

The following sections describe the features that are new or have changed in this release.

Hoteling Guest Login for Webex Calling

Cisco Wireless Phones 840 and 860 now support device-based Hoteling guest login.

Japanese Locale Support

Japanese locale support for Cisco Wireless Phone 840 and 860 applications.

Updated Ringtone Per Line Management for Cisco Unified Communications Manager

You can set the ringtone type to "None" for any line on your phone. By which the phone doesn't ring, but displays the incoming calls.

Limited CTI Control Support

You can control your Cisco Wireless Phone from Computer Telephony Integration (CTI).

XML Support for Informacast

Cisco Wireless Phone 840 or 860 can now use the Informacast solution for emergency notifications.

Enhancement to Incoming Call UI Screen and Heads-Up Notification

The incoming call UI screen and heads-up notification now display the calling party number.

Important Notes

Third Party Application Conflicts

Third party application interference can be eliminated by factory reset and reregistration of a problematic phone.

Where to Find More Information

Cisco Wireless Phone 840 and 860 User Guide

Cisco Wireless Phone 840 and 860 Administration Guide for Cisco Unified Communications Manager

Installation

Refer to the following documents for installation instructions.

840 - <https://www.cisco.com/web/software/282074288/166324/cmterm-840.1-10-0-2264-82035-readme.html>

860 - <https://www.cisco.com/web/software/282074288/166324/cmterm-860.1-10-0-2677-82035-readme.html>

Open Bugs

Bug number	Description
CSCwc20252	860–840 Bluetooth Pairing Mode Confusion vulnerability.
CSCwd73349	Conference not recorded when a user creates a conference with a call on hold.

Resolved Bugs

Bug number	Description
CSCwe57179	Phone didn't re-register to Webex Calling after network outage and initial reconnect attempt failed.
CSCwf82245	Cisco Phone application does not re-register after a reboot.

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- View [All Caveats](#)
- View [Open Caveats](#)
- View [Resolved Caveats](#)

Americas Headquarters

Cisco Systems, Inc.

San Jose, CA

Asia pacific Headquarters

Cisco Systems (USA) Pte. Ltd.

Singapore

Europe HeadquartersCisco Systems International BV
Amsterdam,

The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

