



## **Cisco Wireless IP Phone 8821 and 8821-EX Solution Compatibility Matrix**

**First Published:** 2023-11-03

**Last Modified:** 2024-01-12

### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2024 Cisco Systems, Inc. All rights reserved.



# CONTENTS

---

**CHAPTER 1**

**Cisco Wireless IP Phone 8821 and 8821-EX Solution Compatibility Matrix 0.3 1**





# CHAPTER 1

## Cisco Wireless IP Phone 8821 and 8821-EX Solution Compatibility Matrix 0.3

The Cisco Wireless IP Phone 8821 and 8821-EX Compatibility Matrix list which 8821 software releases and Cisco Wireless LAN solution combinations have completed Cisco Interoperability Testing. For the complete list of supported Wireless LAN solutions, please refer to deployment guide.

**Table 1: Wireless IP Phone 8821/8821-EX with Cisco Catalyst 9800 Series Wireless Controllers**

| 8821 Software Release 11.0(6)SR5 |  |                  |                  |
|----------------------------------|--|------------------|------------------|
| Cisco Access Points Model        | Cisco Catalyst 9800 Series Wireless Controller Software Releases |                  |                  |
|                                  | Dublin 17.12.1   | Cupertino 17.9.4 | Bengaluru 17.6.6 |
| 9166                             | T  | T                | N/A              |
| 9162                             |  |                  |                  |
| 9136                             | T  | T                | N/A              |
| 9130                             | T  | T                | T                |
| 9120                             | T  | T                | T                |
| 4800                             | T  | T                | T                |
| 3800                             | T  | T                | T                |

**Table 2: Wireless IP Phone 8821/8821-EX with Cisco Meraki Access Points**

| 8821 Software Release 11.0(6)SR5 |  |          |
|----------------------------------|--|----------|
| Meraki Access Points Model       | Meraki Access Points Firmware Releases |          |
|                                  | MR30.5                                 | MR29.5.1 |
| CW9166                           | T                                      | T        |
| MR42                             | T                                      | T        |



---

**Note** T: Validation has been performed for this solution.

N/A: Not supported solution.

---

**For Catalyst 9800 Wireless LAN Controllers software releases, refer to:** [Recommended Cisco IOS XE Releases for Catalyst 9800 Wireless LAN Controllers](#)

**For Wireless IP Phone 8821 deployment guide, refer to:** [Cisco Wireless IP Phone 8821 and 8821-EX Deployment Guide](#)