

Release Notes for Cisco Mobility Services Engine, Release 8.0.110.0

First Published: December, 2014 Last Updated: February, 2015 0L-32458-01

These release notes describe what is new in this release, instructions to upgrade to this release, open and resolved caveats for this release, and related information for release 8.0.110.0 of the Cisco Mobility Services Engine (MSE) and its services.

- Location Service
- Wireless Intrusion Protection System (wIPS)
- Mobile Concierge Service
- CMX Analytics Service
- CMX Connect & Engage



Before installing this software, see the "Upgrading the MSE" section on page 12 for details on compatibility with the Cisco Wireless LAN controllers (WLC) and the Cisco Prime Infrastructure.



Licenses are required to run all services. For ordering information, see the "Base Location license" section on page 19.



Cisco MSE 3310 and 3350 are not supported beyond Release 7.3.

Contents

These release notes contain the following sections:

- Introduction, page 2
- Upgrading the MSE, page 12



Cisco Systems, Inc. www.cisco.com

- Licensing Information for MSE, page 17
- MSE License Product Numbers and SKUs, page 20
- What's New in This Release, page 25
- Important Notes, page 26
- Operational Notes for Mobility Services Engine, page 27
- Caveats, page 36
- If You Need More Information, page 37
- Troubleshooting, page 37
- Related Documentation, page 38
- Obtaining Documentation and Submitting a Service Request, page 39

Introduction

This section introduces the Cisco Mobility Services Engine (MSE) and the various services that it supports.

Cisco Mobility Services Engine and Services

The Cisco Mobility Services Engine supports various services within the overall Cisco Unified Wireless Network (CUWN).

The Cisco Mobility Services Engine currently supports the following services:

- Location Service—Also known as Context Aware Service (CAS). This is the core service of the Mobility Services Engine (MSE) that turns on Wi-Fi client tracking and location API functionality. Allows MSE to simultaneously track thousands of mobile assets and clients by retrieving contextual information such as presence, location, telemetry data, and historical information.
- Wireless Intrusion Protection Service—Provides wireless-specific network threat detection and mitigation against malicious attacks, security vulnerabilities, and sources of performance disruption within the CUWN infrastructure. wIPS visualizes, analyzes, and identifies wireless threats, and centrally manages mitigation and resolution of security and performance issues using Cisco monitor mode and Enhanced Local Mode (ELM) Access Points. Proactive threat prevention is also supported to create a hardened wireless network core that is impenetrable by most wireless attacks.
- Mobile Concierge—Mobile Concierge enables the Cisco Mobility Services Advertisement Protocol
 (MSAP). This protocol enables direct communication between the MSE and mobile devices,
 allowing content to be pushed directly to the mobile device pre-association. This functionality is
 dependent on the mobile device supporting 802.11u and MSAP.
- CMX Analytics Service—The CMX Analytics service analyzes wireless device location
 information in a particular network. The CMX Analytics service uses the data provided by the Cisco
 Mobility Services Engine (MSE) to calculate the location of Wi-Fi devices in the Wireless Local
 Area Network (WLAN). In addition, the FastLocate feature sends information about the RSSI
 strength of data packets to the Cisco WLC that can be used for location calculations.

When a wireless device is enabled in a network, it transmits probe request packets to identify the wireless network in its neighborhood. Even after connecting to the access point in the WLAN, the client devices continue to transmit probe request packets to identify other access points for better

quality of service. The access points gather these request and the associated RSSI from the various wireless devices and forwards them to the Wireless LAN Controller (WLC). The controller then forwards this information to the MSE.

The basic data that is collected from various APs, when analyzed, produces information and knowledge about the movement and behavior patterns of people who are using Wi-Fi devices in the building. For example, the building can be an airport, shopping mall, city center, and so on. The CMX Analytics service helps the airport authorities or the building owners to understand the movement of passengers or customer within their building. This helps them improve the signage, make changes to the under utilized areas, and so on.

• CMX Connect and Engage Service—Formerly known as Browser Engage Service. The CMX Connect and Engage service provides Connect, a guest Wi-Fi onboarding solution, as well as zone and message configuration for the CMX Software Development Kit (SDK).



From Release 7.5 onwards, Cisco Location engine is used to track clients and tags. If AeroScout engine is detected when you are upgrading from Release 7.2 and later Releases to Release 7.5, then a warning message is displayed about removing the AeroScout license and engine. If you accept, the installer will remove all partner engine sub services. If you do not accept the removal of partner engine, then the installer will exit.



Starting from Release 7.4, the evaluation licenses for 100 clients, 100 tags, and 10 wIPS monitor mode access points come standard on each Mobility Services Engine installed for 120 days, which earlier from Release 6.0 till Release 7.3 was installed for 60 days.



From Release 7.4 onwards, licensing is based on AP count and not based on tracked device count.

Software Compatibility Matrix

Table 1 lists the Cisco MSE compatibility matrix.

Table 2 lists the Cisco MSE compatibility matrix for legacy software versions.

Cisco MSE Compatibility Matrix

Table 1 lists the Cisco MSE compatibility matrix.

Table 1 Cisco MSE Compatibility Matrix

MSE 3355	MSE Virtual Appliance	PI	WLC	Converged Access	Remarks
8.0.110.0	8.0.110.0	2.2	8.0.110.0	3.7.0	* For FIPS compliance,
		2.1.2***	8.0.100.0 7.6.130.0	3.6.1	MSE 8.0 works with PI 2.2, Wireless LAN
		2.1.1***	7.6.120.0	3.6.0	Controller (WLC)
		1.4****	7.6.110.0* 7.6.100.0* 7.5.102.0****	3.3.5 3.3.4	8.0.100.0, and Converged access 3.6.0.
			7.4.121.0****	3.3.3	***While using PI 2.1.1 and 2.1.2, the wIPS will
			7.4.110.0**** 7.4.100.60****	3.3.2	have MSE 7.4 feature parity.
			7.4.100.0****	3.2.3	-
			7.3.112.0**** 7.3.101.0**** 7.2.111.3**** 7.2.110.0**** 7.2.103.0**** 7.0.240.0**** 7.0.235.3**** 7.0.235.0**** 7.0.230.0**** 7.0.220.0**** 7.0.116.0**** 7.0.98.218****	3.2.2	****wIPS profile cannot be applied to Cisco WLC Version 7.5 or prior using the Prime Infrastructure 2.2 ***** If you are you are running Analytics and Location services on different machines and using Cisco Prime Infrastructure 1.4 Version, then additional setup is required. You can download the Setup script
			7.0.250.0		from this location:
			7.0.251.0		https://software.cisco.com /download/release.html?m
			7.0.252.0		dfid=283765380&flowid= 24866&softwareid=28248 7503&release=8.0.110.0 &relind=AVAILABLE&r ellifecycle=ED&reltype=l atest

Table 1 Cisco MSE Compatibility Matrix (continued)

MSE 3355	MSE Virtual Appliance	PI	WLC	Converged Access	Remarks
8.0.100.0*	8.0.100.0	2.2	8.0.100.0	3.7.0	* For FIPS compliance,
		2.1.1***	7.6.130.0	3.6.1	MSE 8.0 works with PI
			7.6.120.0		2.2, Wireless LAN
		1.4	7.6.110.0*	3.6.0	Controller (WLC)
			7.6.100.0*	3.3.5	8.0.100.0, and Converged
			7.5.102.0****	3.3.4	access 3.6.0.
			7.4.121.0****		*** While using PI 2.1.1,
			7.4.110.0****	3.3.3	the wIPS will have MSE
			7.4.100.60****	3.3.2	7.4 feature parity.
			7.4.100.0****	3.2.3	**** wIPS profile cannot
			7.3.112.0****		be applied to Cisco WLC
			7.3.101.0****	3.2.2	Version 7.5 or prior using
			7.2.111.3****		the Prime Infrastructure
			7.2.110.0****		2.2.
			7.2.103.0**** 7.0.240.0****		
			7.0.240.0*****		
			7.0.235.0****		
			7.0.233.0		
			7.1.91.0****		
			7.0.220.0****		
			7.0.116.0****		
			7.0.98.218****		
			7.0.98.0****		
7.6.120.0	7.6.120.0	2.1.1**	7.6.120.0	_	**Prime Infrastructure
		1.4.2	7.6.110.0*		2.1.1 allows you to
		1.4.2			manage Cisco MSE
			7.6.100.0*		Releases 7.5.102.101 and
			7.5.102.0		7.6.120.0 with feature
			7.4.121.0		compatibility of Cisco
			7.4.110.0		MSE Release 7.4.121.0.
			7.4.100.60		Prime Infrastructure 2.1.1
			7.4.100.0		does not support any new
			7.3.112.0		features introduced in
			7.3.101.0		Cisco MSE Releases
			7.2.111.3 7.2.110.0		7.5.102.101 and
			7.2.110.0		7.6.120.0.
			7.0.240.0		Note For PI 2.1.1 to
			7.0.235.3		work with MSE
			7.0.235.0		7.6, you need to
			7.0.230.0		install a patch for
			7.1.91.0		Cisco bug Id
			7.0.220.0		CSCup93101.
			7.0.116.0		Contact Cisco
			7.0.98.218		TAC for a patch.
			7.0.98.0		

Table 1 Cisco MSE Compatibility Matrix (continued)

MSE 3355	MSE Virtual Appliance	PI	WLC	Converged Access	Remarks
7.6.100.0	7.6.100.0	Update 1 for 1.4.0.45* Update 2 for 1.4.0.45**	7.6.110.0* 7.6.100.0* 7.5.102.0 7.4.121.0 7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.98.218 7.0.98.0		*The Update 1 for Cisco Prime Infrastructure 1.4.0.45 enables you to manage Cisco WLC 7.6.x with the features of Cisco WLC 7.5.102.0 and earlier releases. This release does not support any new features of Cisco WLC 7.6.x including the new access point platforms. **The Update 2 for Cisco Prime Infrastructure 1.4.0.45 enables you to manage Cisco WLC 7.6.x with the features of Cisco WLC 7.5.102.0 and earlier releases. This release does not support any new features of Cisco WLC 7.6.x. However, this release supports two new AP platforms—Cisco 702w and Cisco 2700.

Table 1 Cisco MSE Compatibility Matrix (continued)

MSE 3355	MSE Virtual Appliance	PI	WLC	Converged Access	Remarks
7.6.100.0	7.6.100.0	2.0*	7.6.110.0** 7.6.100.0** 7.5.102.0** 7.4.121.0 7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	3.2.2** 3.3.2**	*Cisco Prime Infrastructure 2.0 enables you to manage Cisco WLC 7.5.102.0 with the features of Cisco WLC 7.4.110.0 and earlier releases. Prime Infrastructure 2.0 does not support any features that are introduced in Cisco WLC 7.5.102.0 or later releases including the new access point platforms. **Supports 7.4 MSE feature parity—CAS, wIPS, and CMX Analytics service. Note wIPS profile cannot be pushed to Cisco Wireless LAN Controller (WLC) Version 7.5 or prior using the Prime Infrastructure 1.4.x or 2.x with MSE 7.6 Release.
7.5.102.10	7.5.102.101	Update 1 for 1.4.0.45 1.4.0.45	7.5.102.0 7.4.121.0 7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0		

Table 1 Cisco MSE Compatibility Matrix (continued)

MSE 3355	MSE Virtual Appliance	PI	WLC	Converged Access	Remarks
7.5.102.10	7.5.102.101	2.0*	7.5.102.0 7.4.121.0 7.4.110.0 7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	3.2.2** 3.3.2**	*Cisco Prime Infrastructure 2.0 enables you to manage Cisco WLC 7.5.102.0 with the features of Cisco WLC 7.4.110.0 and earlier releases. Prime Infrastructure 2.0 does not support any features that are introduced in Cisco WLC 7.5.102.0 or later releases including the new access point platforms. **Supports 7.4 MSE feature parity—CAS, wIPS, and CMX Analytics service.

Table 2 Cisco MSE Compatibility Matrix—Legacy Software Versions

MSE 3355	MSE 3350	MSE Virtual Appliance	AeroScout CLE	wcs	WLC	Prime Infrastructure / NCS
7.4.121.0		7.4.121.0	4.5.2.16 4.4.2.11		7.4.121.0 7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	2.0 Update 1 for 1.4.0.45 1.4.0.45 Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20

Table 2 Cisco MSE Compatibility Matrix—Legacy Software Versions (continued)

MSE 3355	MSE 3350	MSE Virtual Appliance	AeroScout CLE	wcs	WLC	Prime Infrastructure / NCS
7.4.110.0		7.4.110.0	4.5.2.16 4.4.2.11		7.4.110.0 7.4.100.60 7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.0 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	2.0 Update 1 for 1.4.0.45 1.4.0.45 Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20
7.4.100.0		7.4.100.0	4.5.2.16 4.4.2.11 4.4.2.7		7.4.100.0 7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 1 for 1.4.0.45 1.4.0.45 Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20
7.3.101.0	7.3.101.0	7.3.101.0	4.4.2.4		7.3.112.0 7.3.101.0 7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12

Table 2 Cisco MSE Compatibility Matrix—Legacy Software Versions (continued)

MSE 3355	MSE 3350	MSE Virtual Appliance	AeroScout CLE	wcs	WLC	Prime Infrastructure / NCS
7.2.110.0	7.2.110.0	7.2.110.0	4.4.2.4		7.2.111.3 7.2.110.0 7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58
7.2.103.0	7.2.103.0	7.2.103.0	4.4.1.4		7.2.103.0 7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.124 1.1.0.58
7.0.240.0	7.0.240.0		4.3.1.10	7.0.240.0	7.0.240.0 7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29
7.0.230.0	7.0.230.0		4.3.1.19	7.0.230.0	7.0.235.3 7.0.235.0 7.0.230.0 7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29

Table 2 Cisco MSE Compatibility Matrix—Legacy Software Versions (continued)

MSE 3355	MSE 3350	MSE Virtual Appliance	AeroScout CLE	wcs	WLC	Prime Infrastructure / NCS
7.0.220.0	7.0.220.0		4.3.1.19	7.0.220.0	7.1.91.0 7.0.220.0 7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29 1.0.1.4
7.0.201.204	7.0.201.204	_	4.2.4.4	7.0.172.0	7.0.116.0 7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29 1.0.1.4 1.0.0.96
7.0.112.0	7.0.112.0		4.2.4.4	7.0.164.3 7.0.164.0	7.0.98.218 7.0.98.0	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29 1.0.1.4 1.0.0.96
7.0.105.0	7.0.105.0		4.2.4.4	7.0.164.3	7.0.98.218	Update 4 for 1.3.0.20 Update 1 for 1.3.0.20 1.3.0.20 1.2.1.12 1.1.1.24 1.1.0.58 1.0.2.29 1.0.1.4 1.0.0.96



Note

AeroScout CLE is no longer bundled with MSE starting from Release 7.5 Release. However, AeroScout CLE is compatible with MSE Release 7.5 and above using the API interface.



Note

Cisco MSE 3310 and 3350 are not supported beyond Release 7.3.



This compatibility matrix lists only the compatibility information of Cisco MSE with other Cisco wireless products. This matrix does not reflect compatibility information between Cisco WLC and Cisco Prime Infrastructure or Cisco NCS. For compatibility information about Cisco Prime Infrastructure with Cisco WLC and other wireless products, see the Cisco Prime Infrastructure Release Notes.

Upgrading the MSE

For instructions on automatically downloading the software using the Prime Infrastructure or for manually downloading the software using a local or remote connection, see the "Updating Mobility Services Engine Software" section in Chapter 2 of the Cisco Mobility Services Engine Getting Started Guide.

You can find these documents at the following URL:

http://www.cisco.com/en/US/products/ps9742/prod_installation_guides_list.html

This section contains the following topics:

- Upgrade Scenarios, page 12
- Compressed Software Image, page 16
- Updated Software Version Shown in the Prime Infrastructure After Polling, page 17
- Licensing Information for MSE, page 17
- Base Location license, page 19

Upgrade Scenarios

The following scenarios are available to upgrade MSE to 8.0.110.0 from 7.x releases:



Do not run uninstall on the 7.4, 7.5, or 7.6 Release, instead stop the MSE and directly run the installer.



Cisco MSE no longer supports management from HTTP. As a workaround, use HTTPS or allow HTTP in the Cisco MSE firewall with "iptables - L".

You can downgrade a device installed with CMX 10.x to MSE 8.x. Refer to the Software Recovery of MSE Using a USB or Flash Drive in the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0 guide given below. http://www.cisco.com/c/en/us/td/docs/wireless/mse/8-0/MSE-CMX/8 0 MSE CAS/8 0 MSE C AS_chapter_010010.html, page 13

- Upgrading the MSE to 8.0.110.0 from 7.x Release Without Data Migration, page 15
- Restoring an Old Database to 8.0.110.0, page 16

Upgrading From Cisco MSE 8.x to CMX 10.x

You can upgrade a device installed with MSE 8.x to CMX 10.x. Refer to the **Software Recovery of MSE** Using CIMC in the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0 guide given below.

http://www.cisco.com/c/en/us/td/docs/wireless/mse/8-0/MSE-CMX/8_0_MSE_CAS/8_0_MSE_CAS_chapter_010010.html

Upgrading from Cisco CMX 10.x to CMX 8.x

You can downgrade a device installed with CMX 10.x to MSE 8.x. Refer to the **Software Recovery of MSE Using a USB or Flash Drive** in the **Cisco Connected Mobile Experiences Configuration Guide, Release 8.0** guide given below.

http://www.cisco.com/c/en/us/td/docs/wireless/mse/8-0/MSE-CMX/8 0 MSE CAS/8 0 MSE CAS chapter 010010.html

Upgrading the MSE to 8.0.110.0 from 7.x Release

To upgrade from 7.x release to 8.0.110.0, follow these steps:



You must untar the MSE software image before placing it in the /opt/installers directory (CSCuo09569).

Step 1 Download the 8.0.110.0 software image from Cisco.com. The file to be downloaded is: CISCO-MSE-L-K9-8-0-110-0-64bit.bin.tar.gz.



If you are downloading the above file on a Windows system, remember that some browsers modify the downloaded filename. If the downloaded filename is not correct, you must update it to the correct filename before using Prime Infrastructure to transfer the file, or directly copying the file to MSE. The correct filename is CISCO-MSE-L-K9-8-0-110-0-64bit.bin.tar.gz

- **Step 2** Back up the MSE using Prime Infrastructure (highly recommended).
- Step 3 To download software to a Mobility Services Engine, choose Services > Mobility Services Engine from the Prime Infrastructure UI.
- **Step 4** Click the name of the mobility services engine to which you want to download software.
- Step 5 Choose System > Maintenance > Download Software from the left sidebar menu.
- **Step 6** To download software, do one of the following:
 - To download software listed in the Prime Infrastructure directory, select the Select from uploaded images to transfer into the Server radio button. Choose a binary image from the drop-down list.

Prime Infrastructure downloads the binary image to the FTP server directory you specified during the Prime Infrastructure installation.

- To use download software available locally or over the network, select the Browse a new software
 image to transfer into the Server radio button, and click Choose File. Locate the file, and click
 Open.
- **Step 7** Click **Download** to send the software to the /opt/installers directory on the Mobility Services Engine.
- Step 8 When using Prime Infrastructure to transfer the image to MSE, the file will be decompressed, and the ".gz" will be removed from the filename. Verify that the MSE image file

 (CISCO-MSE-L-K9-8-0-110-0-64bit.bin.tar) is in the Mobility Services Engines

 /opt/installers directory.



When copying the image file directly to the MSE, without using Prime Infrastructure, the filename on MSE will remain unchanged and it will be CISCO-MSE-L-K9-8-0-110-0-64bit.bin.tar.gz.

- Step 9 Go to /opt/installers and create a directory to extract the installer files using the command: mkdir 8.0.110.0
- Step 10 Move to the new directory using the command: cd 8.0.110.0
- **Step 11** To unpack the installation files, run the following command:

tar xvf ./CISCO-MSE-L-K9-8-0-110-0-64bit.bin.tar

This unpack yields the following three files. These three files must be in the same directory when running the installer. The installation process uses the MSE_PUB.pem and signhash.bin to validate the integrity of the MSE image.

- Cisco-MSE-L-K9-8-0-110-0-64bit.bin
- MSE_PUB.pem
- signhash.bin



If the MSE image file was transferred directly to the MSE and not downloaded using PI, then the following command should be used to decompress and unpack the installer files: tar zxvf ../CISCO-MSE-L-K9-8-0-110-0.bin.tar.gz

Step 12 Make sure that the CISCO-MSE-L-K9-8-0-110-0-64bit. bin file has execute permissions for the root user. If not, enter the following command:

chmod +x CISCO-MSE-L-K9-8-0-110-0-64bit.bin

Step 13 Manually stop the MSE service using the following command:

/etc/init.d/msed stop or service msed stop

Step 14 To install the new Mobility Services Engine image, enter the following command:

/opt/installers/8.0.110.0/CISCO-MSE-L-K9-8-0-110-0-64bit.bin



The installation process takes a minimum of 30 minutes. The actual installation time depends on the amount of data present in your system. After the installation, you need to reboot the system before starting the MSE.

Step 15 Start the new Mobility Services Engine software by entering the following command. If you attempt to start the MSE, it just returns an error saying that MSE needs to be rebooted.

/etc/init.d/msed start

Step 16 The system must be rebooted after upgrading the MSE. After exiting the installer, enter the command reboot at the prompt to reboot the MSE.

Upgrading the MSE to 8.0.110.0 from 7.x Release Without Data Migration

To upgrade from 7.x release to 8.0.11.0 without data migration, follow these steps.



Use the db installer CISCO-MSE-K9-8-0-110-0-64.bit-db.tar to upgrade to 8.0.110.0 without migrating any data from the previous release.

- **Step 1** Back up the existing database using the Prime Infrastructure. (We recommended this).
 - All data existing on the system will be lost and a fresh blank database will be created.
- **Step 2** To download software to a mobility services engine, choose **Services > Mobility Services Engine** from the Prime Infrastructure user interface.
- **Step 3** Click the name of the mobility services engine to which you want to download software.
- Step 4 Choose System > Maintenance > Download Software from the left sidebar menu.
- **Step 5** To download software, do one of the following:
 - To download software listed in the Prime Infrastructure directory, select the Select from uploaded images to transfer into the Server radio button. Choose a binary image from the drop-down list. Prime Infrastructure downloads the binary image to the FTP server directory you specified during the Prime Infrastructure installation.
 - To use download software available locally or over the network, select the Browse a new software image to transfer into the Server radio button, and click **Choose File**. Locate the file, and click **Open**.
- **Step 6** Click **Download** to send the software to the /opt/installers directory on the mobility services engine.
- Step 7 Choose System > Maintenance > Download Software from the left sidebar menu.
- **Step 8** Select the file and click **Download**.
- Step 9 Browse to your local directory where you have downloaded the file and send the software to the /opt/installers directory on the mobility services engine.
- **Step 10** Untar the file: tar -xvf CISCO-MSE-K9-8-0-110-0-64.bit-db.tar. This gives you the following:
 - 5 files
 - 4 zips
 - database_installer_part1of4.zip
 - database_installer_part20f4.zip
 - database_installer_part3of4.zip
 - database_installer_part4of4.zip
 - Cisco-MSE-L-K9-8-0-110-0-64bit.bin.tar.gz
- Step 11 To decompress (unzip) the file, execute: tar -xvf CISCO-MSE-L-K9-8-0-110-0-0-64bit.bin.tar.gz.
- **Step 12** Enter the following command:
 - chmod +x CISCO-MSE-L-K9-8-0-110-0-64bit

- **Step 13** Stop the MSE service using the following command:
 - service msed stop
- **Step 14** Uninstall the existing MSE software. Invoke the uninstall script from the /opt/mse/uninstall folder. Choose deletion of database when prompted.
- Step 15 Invoke the MSE installer CISCO-MSE-L-K9-8-0-110-0-0-64bit.bin.

Restoring an Old Database to 8.0.110.0

To restore an old database, follow these steps:



The regular Restore option on the Prime Infrastructure cannot be used to restore a backup from an older MSE releases such as 6.0, 7.0.105.0, or 7.0.110.0 onto 8.0.110.0.

- **Step 1** Stop the MSE service: /etc/init.d/msed stop
- **Step 2** Uninstall the software and select to delete the database.
- **Step 3** To restore the backup data, you must first install the appropriate version of MSE software. Use the table below to determine the correct version of MSE to install.

Table 3 Release Matrix

Version of Database to be restored	New Version that Should be Installed
5.2.0	6.0, 7.0
6.0	6.0, 7.0

- **Step 4** Once you have installed the software, restore the desired database backup onto this new MSE using the regular procedure from Prime Infrastructure.
- Step 5 To migrate data to 7.x.x.x, follow the steps in the "You can downgrade a device installed with CMX 10.x to MSE 8.x. Refer to the Software Recovery of MSE Using a USB or Flash Drive in the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0 guide given below. http://www.cisco.com/c/en/us/td/docs/wireless/mse/8-0/MSE-CMX/8_0_MSE_CAS/8_0_MSE_CAS_chapter_010010.html" section on page 13.

Compressed Software Image

If you download the Mobility Services Engine image *.gz file using the Prime Infrastructure, the Mobility Services Engine automatically decompresses (unzips) it, and you can proceed with the installation as before.

If you manually download the compressed *.gz file using FTP, you must decompress the files before running the installer. These files are compressed under the LINUX operating system and must be decompressed using the tar zxvf command. For more information, see the Manually Downloading Software section in the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0.

To make the bin file executable, use the **chmod** +x **filename.bin** command.

The MSE virtual appliance is distributed as:

- Open Virtualization Format (OVF) for VMware
- Virtual Hard Disk (VHD) for Microsoft Hyper-V
- Open Virtualization Format (OVF) for Citrix XenServer

For more information on deploying the MSE virtual appliance, see the *Cisco MSE Virtual Appliance Configuration Guide, Release 8.0.*

Updated Software Version Shown in the Prime Infrastructure After Polling

After a software update, the new Mobility Services Engine software version does not immediately appear in Mobility Services Engine queries on the Prime Infrastructure. Up to 5 minutes is required for the new version to appear. Prime Infrastructure, by default, queries the Mobility Services Engine for status every 5 minutes.

Licensing Information for MSE

The Cisco Mobility Services Engine (MSE) provides a wide variety of location-based services. To enable these services, the following are required:

- Cisco MSE hardware or software appliance
 - Physical Appliance—An activation license is not required.
 - Virtual Appliance—Virtual Appliance instance requires a MSE Virtual Appliance Activation license (L-MSE-7.0-K9). It is not sufficient to simply have a service/feature license on an MSE Virtual Appliance.
- Licenses
- Support

There are three types of MSE licenses available:

Table 4 MSE License Types

MSE Service License	Provides			
Base Location License	Provides advanced spectrum capability with the ability to detect, track, and trace rogue devices, Cisco CleanAir® interferers, Wi-Fi clients, and RFID tags. The Base Location license also enables customers and partners to use standard MSE APIs.			
CMX License	Provides the above Base Location license capabilities and the CMX features:			
	• CMX Analytics, a user-friendly location analytics platform to view and analyze how, where, and when visitors move through a venue.			
	• CMX Connect and Engage for a customizable and location-aware captive portal to on-board guest users to Wi-Fi including:			
	• CMX for Facebook Wi-Fi, helping guests connect to Wi-Fi and use the Internet. Enterprises or merchants gain social demographic data via Facebook Insights.			
	 CMX SDK for enabling organizations to integrate Wi-Fi-based indoor navigation with push notification and auto-launch capabilities into mobile applications. 			
wIPS License	Provides complete wireless threat detection and mitigation in the wireless network infrastructure			
	Rogue Detection, Classification, and Mitigation			
	Over-the-Air Attack Detection			
	Security Vulnerability Monitoring			
	Performance Monitoring, and Auto-Optimization			
	Management, Monitoring, and Reporting			
	Requires a separate MSE running the wIPS service.			
	There are 3 deployment options:			
	• Enhanced Local mode: Number of wIPS licenses required equals the number of access points in local mode (data serving) deployed in the network.			
	• Monitor mode: Number of wIPS licenses required equals the number of access points configured in the full-time monitor mode.			
	• Wireless Security Module (WSM)/Monitor module: Number of wIPS licenses required equals the number of wireless security and spectrum intelligence modules deployed in the network.			

Client and wIPS licenses are installed from the Prime Infrastructure UI (Administration > License Center). See, Chapter 2: "Adding and Deleting Mobility Services Engines and Licenses" in the *Cisco Connected Mobile Experiences Configuration Guide, Release 8.0, Cisco Wireless Intrusion Prevention System, Release 8.0,* and *Cisco Location Analytics Configuration Guide, Release 8.0* respectively.

For complete details on ordering and downloading licenses, see the *Cisco Mobility Services Engine Licensing and Ordering Guide* at the following URL:

http://www.cisco.com/en/US/prod/collateral/wireless/ps9733/ps9742/data_sheet_c07-473865.html

Base Location license

Table 5 Base Location License

MSE Release	License Name	Based On
Post 7.4	Base Location Services license	Number of APs
7.4	Location services license	Number of APs
Prior 7.4	Context Aware Services (CAS) license	Number of elements

The Base Location Services License is equivalent to the Location Services license in software release 7.4, which itself replaced the Context Aware Services (CAS) license in the software versions prior to release 7.4. This license is used for device endpoint tracking, enabling basic calculation of the x,y coordinates of a tracked device. The license count is based on the number of APs supported since release 7.4.

The part number format of this license is L-LS-100AP. Here 'LS' refers to Location Services and '100AP' refers to 100 AP count.

CMX License

Table 6 CMX License

MSE Release	License Name	Based On
Post 7.4	CMX license	Number of APs
7.4	Advanced Location Services license	Number of APs
Prior 7.4	Nonexistent	_

The CMX license, called Advanced Location license in release 7.4, supports new features, such as:

- CMX Analytics
- CMX Connect
- CMX for Facebook Wi-Fi
- Mobile Concierge

The CMX license includes the Base Location license features used for device tracking and the new additional features of CMX.

The part number format of this license is L-AD-LS-100AP. Here 'AD-LS' refers to Advanced Location services license and '100AP' gives the AP count supported.

wIPS License

Table 7 wIPS License

MSE Release	License Name	Based On
Post 7.4	wIPS license	Number of APs
7.4	wIPS license	Number of APs
Prior 7.4	wIPS license	Number of elements

There are 3 deployment options:

- Enhanced Local mode: Number of wIPS licenses required equals the number of access points in local mode (data serving) deployed in the network.
- Monitor mode: Number of wIPS licenses required equals the number of access points configured in the full-time monitor mode.
- Monitor module: Number of wIPS licenses required equals the number of wireless security and spectrum intelligence modules deployed in the network.



AP with a third module needs a monitor mode wips license even if AP is running in local mode.

 Provides advanced spectrum capability and the ability to detect presence and track rogue device, interferers, Wi-Fi clients and RFID tags. Cisco Base Location also enables third-party solutions that use the MSE API.

Licensing is based on the number of access points in the environment. The licenses are additive.



Connected Mobile Experiences licenses will be End of Life with standard 6 months of End of Sales and until then both Connected Mobile Experiences and LS licenses will co-exist.

MSE License Product Numbers and SKUs

Ordering Support for Physical and Virtual Appliance

The MSE Virtual appliance activation license is required for every instance of an MSE Virtual Appliance. No separate license is required for high availability. To enable high availability, you need to deploy a primary Cisco MSE appliance with Cisco Connected Mobile Experiences and wIPS licenses, and a secondary Cisco MSE appliance without any Cisco Connected Mobile Experiences or wIPS license

Table 8 lists the ordering support for physical and virtual appliance.

Table 8 Ordering Support for Physical and Virtual Appliance

MSE Model	SKU	Service SKU	Description
MSE 3355	AIR-MSE-3355-	CON-SNT-MSE3355	Hardware and licenses support
(Physical Appliance)	K9		

Table 8 Ordering Support for Physical and Virtual Appliance

MSE Model	SKU	Service SKU	Description
MSE Virtual Appliance	L-MSE-7.0-K9	CON-SAU-LMSE7K	Software and licenses support

Licenses Summary

Table 9 License Summary

Base Location License SKU	CMX License SKU	wIPS Monitor Mode/Monitor Mode SKUs	wIPS Enhanced Local Mode SKUs	Description
L-LS-1AP	L-AD-LS-1AP	L-WIPS-MM-1AP	L-WIPS-ELM-1AP	Supports 1 AP
L-LS-100AP	L-AD-LS-100AP	L-WIPS-MM-100AP	L-WIPS-ELM-100AP	Supports 100 APs
L-LS-1000AP	L-AD-LS-1000AP	L-WIPS-MM-1000AP	L-WIPS-ELM-1000AP	Supports 1000 APs

- 1 AP license gives 10 elements for evaluation license.
- 100 AP license gives 1000 elements for evaluation license.
- 1000 AP license gives 10000 elements for evaluation license.

Base Location Services Licenses

Table 10 Base Location Services Licenses

License SKU	Description
L-LS-1AP	1 AP Base Location Services license
L-LS-100AP	100 AP Base Location Services license
L-LS-1000AP	1000 AP Base Location Services license

CMX Licenses (Previously known as Advanced Location Services)

Table 11 CMX Licenses

License SKU	Description
L-AD-LS-1AP	1 AP CMX license (Advanced Location Services)
L-AD-LS-100AP	100 AP CMX license (Advanced Location Services)
L-AD-LS-1000AP	1000 AP CMX license (Advanced Location Services)

The CMX licenses include the Base Location Service licenses. There is no need to purchase a separate Base Location Service license when purchasing a CMX license.

Base Location Services to CMX Upgrade License

Table 12 Base Location Services to CMX Upgrade License

License SKU	Description
L-UPG-LS-1AP	1 AP Upgrade from Base Location to CMX
	license.

wIPS Enhanced Local Mode License

Table 13 wIPS Enhanced Local Mode License

License SKU	Description
L-WIPS-ELM-1AP	1 AP wIPS Enhanced Local Mode License
L-WIPS-ELM-100AP	100 AP wIPS Enhanced Local Mode License
L-WIPS-ELM-1000AP	1000 AP wIPS Enhanced Local Mode License

wIPS Monitor Mode/Monitor Module License

Table 14 wIPS Monitor Mode Licenses

License SKU	Description
L-WIPS-MM-1AP	1 AP wIPS Monitor Mode License
L-WIPS-MM-100AP	100 AP wIPS Monitor Mode License
L-WIPS-MM-1000AP	1000 AP wIPS Monitor Mode License

Cisco MSE Virtual Appliance Product Specifications

Table 15 Cisco MSE Virtual Appliance Product Specifications

Feature	Cisco MSE Virtual Appliance
Virtual appliance versions	VMware ESX/ESXi version 4.1/5.0/5.1/5.1 or higher
	Xen Server version 6.1 or higher
	Hyper-V version 2008, 2012
	(Note: Hyper-V version 2012R2 is not supported.)

Table 15 Cisco MSE Virtual Appliance Product Specifications

Feature	Cisco MSE Virtual Appliance
Minimum Server Requirements	Cisco MSE High-End Virtual Appliance
	Base location license: 5000 access points
	CMX license: 5000 access points
	• wIPS license: 10,000 access points
	• Maximum number of tracked devices: 50,000 (regardless of number of access point licenses). Note that the end device scaling guidelines differ if using FastLocate or presence as a method for determining device location. See the MSE ordering and licensing guide for more details.
	Minimum RAN: 24 GB
	 Minimum hard disk space allocation: 500 GB with SAS drivers and 1600 I/O operations per second (IOPS)
	• Processors: 16 vCPUs at 2.0 GHz or faster and a passmark (cpubenchmark.net) no less than 4000
	Cisco UCS ® ref: Cisco UCS C240 M3 Rack Server or C460 M2 High-Performance Rack Server
	Cisco MSE Standard Virtual Appliance
	Base Location license: 2500 access points
	CMX license: 2500 access points
	• wIPS license: 6000 access points
	• Maximum number of tracked devices: 25,000 (regardless of number of access point licenses). Note that the end device scaling guidelines differ if using FastLocate or presence as a method for determining device location. See the MSE ordering and licensing guide for more details.
	Minimum RAM: 16 GB
	Minimum hard disk space allocation: 500 GB with SAS drivers and 1000 IOPS
	• Processors: 8 vCPUs at 2.0 GHz or faster and a passmark (cpubenchmark.net) no less than 4000
	Cisco UCS ref: Cisco UCS C240 M3 Rack Server
	Cisco MSE Low-End Virtual Appliance
	Base Location license: 200 access points
	CMX license: Does not support CMX license
	• wIPS license: 2000 access points
	• Maximum number of tracked devices: 2000 (regardless of number of access point licenses). Note that the end device scaling guidelines differ if using FastLocate as a method for determining device location. See the MSE ordering and licensing guide for more details.
	Minimum RAM: 8 GB
	Minimum hard disk space allocation: 250 GB with SAS drives and 900 IOPS
	• Processors: 4 vCPUs at 2.0 GHz or faster and a passmark (cpubenchmark.net) no less than 4000

What's New in This Release

This section provides a brief description of what is new in Release 8.0.110.0. For more information about instruction on how to configure these features, see the Cisco Connected Mobile Experiences Configuration Guide, Cisco Wireless Intrusion Prevention System Configuration Guide, Cisco CMX Analytics Service Configuration Guide, Cisco CMX Connect and Engage Configuration Guide, and Cisco MSE Virtual Appliance Configuration Guide at

http://www.cisco.com/en/US/products/ps9742/products_installation_and_configuration_guides_list.ht ml

HA Certificate Install Script

A new script is added to install signed certificates for HA connection between primary and secondary in 8.0.110.0 Release. See *Cisco Connected Mobile Experiences Configuration Guide, Release* 8.0 for more information.

iOS 8 Dynamic MAC Filtering

Apple devices running iOS8 (or higher) under certain conditions have the ability to probe the network utilizing randomized MAC addresses. As a result, a single device may be counted several times by the Cisco Connected Mobile Experiences (CMX) solution. The MSE 8.0.110.0 has the ability to filter out the randomized MAC addresses and track or count only those devices with valid MAC address for use with the Cisco CMX services.

To enable the iOS 8 randomized MAC filtering, follow these steps:

- 1. Launch the Cisco Mobility Services Engine (MSE) user interface by typing https://mseip/mseui/ in the Web Browser.
- 2. Click Configuration icon on the top right of the home page.
- 3. Choose Context Aware Service > Filtering to display the configuration options.
- 4. Under the MAC Filtering Params group box, enable the following filtering parameters:
 - 1. Enable Location MAC Filtering
 - 2. Filter Locally Administered MAC Addresses
 - 3. Click Save.




Figure 1 Editing MAC Filtering Params

From Cisco MSE CLI, you need to stop and then start all Cisco MSE services using these commands:

- service msed stop
- service msed start

Important Notes

This section describes the operational notes and navigation changes for Connected Mobile Experiences, wIPS, and the Mobility Services Engine for Release 6.0.103.0 and later releases.

Features and operational notes are summarized separately for the Mobility Services Engine, Connected Mobile Experiences, and wIPS.

This section contains the following topics:

- Operational Notes for Mobility Services Engine, page 27
- Operational Notes for Context Aware Service, page 32
- Operational Notes for CMX Analytics, page 34

- Operational Notes for Facebook Wi-Fi, page 35
- Operational Notes for CMX Connect and Engage, page 35
- Operational Notes for Mobile SDK, page 36
- Enabling Root Access Control (RAC) in HA Mode, page 36

Operational Notes for Mobility Services Engine

This section lists the operational notes for the Mobility Services Engine and contains the following topics:

- Resolution to NMSP/SHA2 keyhash Mismatch Issue, page 27
- DNS Server, page 28
- How and When to Use the db.tar installer, page 28
- Reboot MSE After Fresh Installation or Upgrade, page 29
- Automatic Installation Script for Initial Setup, page 29
- Controller and Associated Mobility Services Engine Must be Mapped to the Same NTP and Prime Infrastructure Server, page 29
- Mandatory Default Root Password Change, page 29
- Configuring the Prime Infrastructure Communication Username and Password Using MSE setup.sh, page 30
- Configuration Changes for Greater Location Accuracy, page 30
- Wireless Security Module with 3600 AP, page 30
- AeroScout Engine Module Changes, page 31
- Ports to be Opened for High Availability Between MSEs, page 31
- Synchronizing Floor Maps in Location Service, page 31
- MSE Location REST APIs, page 32


Resolution to NMSP/SHA2 keyhash Mismatch Issue

MSE 8.0 by default supports SHA-2 keyhash algorithm for peer authentication with Cisco WLC 8.0 during the SSL handshake. Prime Infrastructure 1.4.2 and 2.1 supports only SHA-1 AP (or MSE) Authorization template when synchronizing Cisco WLC with the MSE. This causes keyhash mismatch issue because the PI and MSE uses different keyhash algorithm on Cisco WLC 8.0. An option is added to the Advanced Parameters page in the MSE user interface (UI) to allow the user to force MSE 8.0 to use SHA-1 keyhash algorithm.

Follow these instructions to configure SHA-1 Cipher:

- 1. Launch the MSE admin UI by typing https://mseip/mseui/app in the web browser.
- 2. Click Configuration.
- 3. Choose System > Advanced Parameters from the left sidebar menu.
- 4. Select the **Enable Use of SHA-1 Ciphers** check box (see Figure 2).
- 5. Click Save.

Figure 2 Advanced Parameters



- 6. Un-synchronize Cisco WLC from MSE, and then re-synchronize WLC with MSE from PI.
- 7. The NMSP status should go into active state.



If the FIPS mode (also known as Root Access Control) is enabled on the MSE, then this option will not be available to the users as FIPS mode requires all operations in SHS-2.

DNS Server

Use a valid DNS sever as CAS and Analytics service use nslookups.

How and When to Use the db.tar installer



You can use the db.tar installer file when you want to install the MSE newly along with the fresh DB installation. The recommended method is to follow the usual Upgrade process unless you want a fresh installation.

• Stop the MSE software (/etc/init.d/msed stop).

- You must delete the following directories if you want to reinstall again:
 - /opt/mse
 - /opt/data
 - /opt/oracle
 - /opt/ORCLfmap
 - /opt/installers/*
- Scp the db.tar file to /opt/installers directory and untar it at that location.
- Run the MSE installer.

Reboot MSE After Fresh Installation or Upgrade

After a new installation or upgrade of the MSE software, you must reboot the MSE using the "reboot" command.

Automatic Installation Script for Initial Setup

An automatic setup wizard is available to help you initially set up the Mobility Services Engine.

An example of the complete automatic setup script is provided in the Cisco Mobility Services Engine Getting Started Guide.

You can find these documents at the following URL:

http://www.cisco.com/en/US/products/ps9742/prod installation guides list.html

Controller and Associated Mobility Services Engine Must be Mapped to the Same NTP and Prime Infrastructure Server

Communication between the Mobility Services Engine, the Prime Infrastructure, and the controller are in Coordinated Universal Time (UTC). Configuring the Network Time Protocol (NTP) on each system provides devices with the UTC time. An NTP server is required to automatically synchronize time between the controller, Prime Infrastructure, and the Mobility Services Engine.

The Mobility Services Engine and its associated controllers must be mapped to the same NTP server and the same Prime Infrastructure server.

Local time zones can be configured on a Mobility Services Engine to assist network operations center personnel in locating events within logs.



You can configure NTP server settings while running the automatic installation script. See the *Cisco Mobility Services Engine Getting Started Guide Started Guide* for details on the automatic installation script at the following URL:

http://www.cisco.com/en/US/products/ps9742/prod_installation_guides_list.html

Mandatory Default Root Password Change

You must change the default root password of the Mobility Services Engine while running the automatic installation script to ensure optimum network security.

You can also change the password using the Linux passwd command.



For the initial login, even if you choose Skip (S), you will be prompted to enter the password. This is because it is mandatory to change the root password at the initial login.

Configuring the Prime Infrastructure Communication Username and Password Using MSE setup.sh

You can configure the Prime Infrastructure Communication username and password using the MSE setup.sh script file.

Scenarios which you might encounter while configuring the Prime Infrastructure username and password are as follows:

- If you configure a new Prime Infrastructure username and password, the password provided is applicable for the new Prime Infrastructure username created.
- If you only configure the Prime Infrastructure username without configuring the Prime Infrastructure password, then the default password admin is applied to the configured username.
- If you only configure the Prime Infrastructure password without configuring the Prime Infrastructure username, then the password for the admin user is changed.
- If you configure an existing username for the Prime Infrastructure username and also configure the password, then the password for that existing user is changed.



These users are API users, and they do not have corresponding OS users on the MSE appliance.

Configuration Changes for Greater Location Accuracy

In some RF environments, where location accuracy is around 60 to 70% or where incorrect client or tag floor location map placements occur, you might need to modify the moment RSSI thresholds in the **Context Aware Service > Advanced > Location Parameters** page on the Prime Infrastructure.

The following RSSI parameters might require modification:

- locp-individual-rssi-change-threshold
- locp-aggregated-rssi-change-threshold
- locp-many-new-rssi-threshold-in-percent
- locp-many-missing-rssi-threshold-in-percent



Contact Cisco TAC for assistance in modifying these parameters.

Wireless Security Module with 3600 AP

If you are attempting to deploy Wireless Security Module (WSM) with 3600 APs, then APs should be placed in monitor mode with submode wIPS and advanced wIPS engine enabled on the Prime Infrastructure.

AeroScout Engine Module Changes

Starting Release 7.5, the AeroScout engine module is removed from both the Connected Mobile Experiences setup and location code. During installation, if you are upgrading from Release 7.2 and later to Release 7.5, then you will be prompted to remove the AeroScout engine. If you agree to remove, the it removes the AeroScout engine and by default, the Cisco Tag Engine is started as part of Connected Mobile Experiences. If you do not agree to remove the AeroScout engine, then installation will exit.

Ports to be Opened for High Availability Between MSEs

The following is the list of ports to be opened for High Availability between MSEs:

- tcp 22
- tcp 80
- tcp 443
- tcp 1411
- tcp 1521
- tcp 1522
- tcp 1523
- tcp 1524
- tcp 1525
- tcp 1621
- tcp 1622
- tcp 1623
- tcp 1624
- tcp 1625
- tcp 8001
- tcp 8080
- tcp 8081
- tcp 9006
- tcp 15080
- tcp 59000
- tcp 61617
- udp 12091

Synchronizing Floor Maps in Location Service

While synchronizing floor maps in location service, we recommend that you synchronize floor maps in batches of 1000 access points at a time.

MSE Location REST APIs

The MSE Location REST APIs always show the last known state of clients. When it shows the last known state as Probing, it does not mean that the client is probing currently. This is the same with other fields such as x, y, floorid. Networkstatus is the only field that shows whether the client is active or inactive, and all other fields show the last known values.

Operational Notes for Context Aware Service

This section lists the operational notes for a Mobility Services Engine and contains the following topics:

- Synchronization Required When Upgrading to Release 8.0.110.0 or Importing CAD Floor Images, page 32
- Floor Change or Minimum Distance Required for Location Transitions to Post to the History Log, page 32
- Non-Cisco Compatible Extensions Tags Not Supported, page 33
- Cisco Compatible Extensions Version 1 Tags Required at a Minimum, page 33
- Calibration Models and Data, page 33
- Advanced Location Parameters, page 33
- Location History Time stamps Match Browser Location, page 33
- Tablets and Smartphone with Limited Probe Requests Might Affect Location, page 33

Synchronization Required When Upgrading to Release 8.0.110.0 or Importing CAD Floor Images

When upgrading to Release 8.0.110.0 from Release 7.x, you must synchronize after the software upgrade and also when CAD-generated floor images are imported into the Prime Infrastructure.

Floor Change or Minimum Distance Required for Location Transitions to Post to the History Log

When history logging is enabled for any or all elements (client stations, asset tags, rogue clients, and access points), a location transition for an element is posted only if it changes floors or the new location of the element is at least 30 feet (10 meters) from its original location.



The other conditions for history logging are as follows:

- Clients: Association, authentication, re-association, re-authentication, or disassociation.
- Tags: Tag Emergency button.
- Interferers: Interferer severity change, cluster center change, or merge.

See Services > Mobility Services > Device Name > Context Aware Service > Administration > History Parameters.

Logs can be viewed at Services > Mobility Services > Device Name > Systems > Log.

Non-Cisco Compatible Extensions Tags Not Supported

The Mobility Services Engine does not support non-Cisco CX Wi-Fi tags. Additionally, these non-compliant tags are not used in location calculations or shown on the Prime Infrastructure maps.

Cisco Compatible Extensions Version 1 Tags Required at a Minimum

Only Cisco CX Version 1 (or later) tags are used in location calculations and mapped in the Prime Infrastructure.

Monitoring Information Varies for Clients and Tags

In the Monitor > Clients page (when Location Debug is enabled), you can view information on the last heard access point and its corresponding Received Signal Strength Indicator (RSSI) reading.

Calibration Models and Data

Calibration models always applies to Wireless clients, Interferers, Rogue APs, and Rogue Clients.

See Chapter 7, "Context-Aware Planning and Verification" in the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0 for more details on client calibration.

Advanced Location Parameters

Settings for advanced location parameters related to RSSI, chokepoint usage, location smoothing, and assignment of outside walls on floors, are not applicable to tags.

See the "Editing Advanced Location Parameters" section in Chapter 7 of the Cisco Connected Mobile Experiences Configuration Guide, Release 8.0.

See Services > Mobility Services > Device Name > Context Aware Service > Advanced > Location Parameters.

Location History Time stamps Match Browser Location

The Prime Infrastructure time stamp is based on the browser location and not on the Mobility Services Engine settings. Changing the time zone on the Prime Infrastructure or on the Mobility Services Engine does not change the time stamp for the location history.

Tablets and Smartphone with Limited Probe Requests Might Affect Location

Many tablets, smartphones, and other Wi-Fi devices with power save mode do not continuously send out probe requests after an initial association to the CUWN. Therefore, calculating the location accuracy of such devices using RSSI readings is not always optimal.

Repeat Use of FloorID returns +1 After Every Hour

In the relevant CAS API, the use of the parameter FLOORID is not guaranteed to return the same value on consecutive calls. It may get changed by such activities as resynchronizing the MSE. Instead, the parameter FLOORAESUID should be used. The API call getStationHistoryListByArgs now can use both parameters in MSE Release 8.0.

Operational Notes for wIPS

wIPS Profile

wIPS profile cannot be pushed to Cisco Wireless LAN Controller (WLC) Version 7.5 or prior using the Prime Infrastructure 1.4.x or 2.x with MSE 7.6 Release.

Operational Notes for CMX Analytics

This section lists the operational notes for CMX Analytics service and contains the following topics:

- Peer's Certificate Invalid Signature Error with Firefox Browser, page 34
- WebGL Compatibility, page 34
- Jboss Issue, page 35

Peer's Certificate Invalid Signature Error with Firefox Browser

While using the newer version of Firefox browser to connect to the MSE user interface or CMX Analytics user interface, an error message appears saying "Peer's certificate has an invalid signature". For more information on how to fix this, see the https://support.mozilla.org/en-US/questions/776144.

To fix this, follow these steps:

- Open the Firefox browser.
- Enter about: config in the address/URL.
- Enter browser.xul in the Filter box.
- Check if browser.xul.error_pages.expert_bad_cert property exists with a value of false.
- Right-click on browser.xul.error_pages.expert_bad_cert and select Toggle. The value will change to true.
- Exit from Firefox.
- Restart the browser and try the CMX Analytics user interface. You are now asked to add the exception.

WebGL Compatibility

The CMX Analytics in Release 8.0 provides ability to view the analytic results in both 2D (Open Street Maps) and 3D (WebGL) environments. This provides improved understanding of results on multiple floor paths or when dwell times are calculated throughout a multi-storey building. The 3D environment presents the same information as the 2D environment.

WebGL is an advanced feature that provides graphic capabilities. All browsers do not support WebGL on a particular hardware. Verify your browser compatibility in the Get WebGL website. If your browser supports WebGL, then you must see a spinning cube.

If your browser does not support WebGL, you must do the following:

• Update your latest drivers for video card.

- For Google Chrome, follow the instructions given for WebGL and 3D Graphics in the Google Chrome support website.
- For Firefox, follow these steps to enable WebGL:
 - Download the latest build of Firefox browser and launch Firefox on your computer.
 - In the browser address line, enter about:config
 - In the Search text box, enter webgl to filter the settings
 - Double click webgl.enabled_for_all_sites
 - Set the webgl.enabled_for_all_sites=true
- For Safari, follow these steps to enable WebGL:
 - Choose Safari > Preferences.
 - Click the Advanced tab.
 - Select the **Show Develop menu in menu bar** check box.
 - Choose Enable WebGL from the Develop menu.



If your system does not support 3D, then the analytic results are displayed only in 2D Open Street Maps view.

Jboss Issue

Sometimes CMX Analytics service does not start up because of a stray Jboss process that runs as a root user. If Analytics engine does not start and if you notice a stray Jboss process with root permissions running, then you must to do the following:

- Stop CMX Analytics service from the Prime Infrastructure.
- Kill the Jboss process. command
- Run the chown -R nobody:nobody /opt/mse/analytics command.
- Start CMX Analytics service from the Prime Infrastructure.

Operational Notes for Facebook Wi-Fi

When you try to pair a location with the Facebook page, it may fail with no notification in Connect and Engage user interface. One of the reasons could be due to Facebook site outage. You can check Facebook API health at the following URL: http://developers.facebook.com/status/

Operational Notes for CMX Connect and Engage

While upgrading the Prime Infrastructure server, the map IDs and the information also gets updated. This results in the new identifiers for maps. The new identifiers are not automatically synchronized with the CMX Connect and Engage. This causes the location updates to use the new identifiers but the CMX Connect and Engage will not be aware of the new identifiers and cause the location updates to get ignored. To resolve this issue, you must update maps in the CMX Connect and Engage user interface. To update maps, login to CMX Connect and Engage user interface and choose **Maps** from left sidebar menu and click **Update Maps from PI**.

Operational Notes for Mobile SDK

Two different venues with the same MSEs receiving location updates result in the device location bouncing from one venue to another venue. The Mobile Application Server (MAS) receives updates and changes the location to the most recent update received. The client location then changes from the most recent location update which can be from either venue.

Enabling Root Access Control (RAC) in HA Mode

To enable Root Access Control (RAC) in HA mode, you need to enable RAC on both primary and secondary MSEs. The RAC configuration is not synchronized across the primary and secondary servers and hence you need to enable it on both servers. This will enable the RAC configurations to work on the active server properly in case of a failover or failback.

Caveats

- Cisco Bug Search Tool, page 36
- Open Caveats, page 31
- Resolved Caveats, page 36

Cisco Bug Search Tool

The Bug Search Tool (BST), which is the online successor to Bug Toolkit, is designed to improve the effectiveness in network risk management and device troubleshooting. The BST allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat listed in this document:

- 1. Access the BST (use your Cisco user ID and password) at https://tools.cisco.com/bugsearch/.
- 2. Enter the bug ID in the **Search For:** field.

Open Caveats

ID	Headline
CSCuz43526	PI3.1 MSE-Floor launch fails when map hierarchy having # symbol

Resolved Caveats

Use the BST to view the details of a caveat listed in this section. For more information about the BST, see the "Cisco Bug Search Tool" section on page 36.

ID	Headline
CSCuq82161	Location Accuracy issue in MSE 7.6.
CSCur24635	Improper splash page is displayed when a guest client is redirected to Visitor Connect splash portal.
CSCur44944	MSE 8.0 logs show "Floor id not found in DB" when loading floor location.
CSCur45021	The active client count reported by MSE is incorrect. Old inactive clients are reported as active clients.
CSCur57520	Support meters is required in API/notifications.
CSCur58891	Interferers active value on tracking parameters becomes huge value.
CSCuq24699	MSE NMSP shows active, though last active time is a week old.
CSCur83820	wIPS meta alert not getting cleared in Prime Infrastructure when it becomes inactive.
CSCur57693	Guest client browsers display the "Network Not Found" error after redirected to Facebook during Guest WiFi on boarding using Facebook WiFi.

If You Need More Information

If you need information about a specific caveat that does not appear in these release notes, you can use the Cisco Bug Toolkit to find caveats of any severity. Click this URL to browse to the Bug Toolkit:

http://tools.cisco.com/Support/BugToolKit/

(If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.)

Troubleshooting

For the most up-to-date, detailed troubleshooting information, see the Cisco TAC website at the following URL:

http://www.cisco.com/cisco/web/support/index.html

Click **Troubleshooting**, choose your product, and then click the **Troubleshoot and Alerts** heading on the product page to find information on the problem you are experiencing and other service advisories.

Related Documentation

The following documents are related to the Mobility Services Engine:

- Cisco Connected Mobile Experiences Configuration Guide, Release 8.0
 http://www.cisco.com/en/US/products/ps9742/tsd_products_support_series_home.html
- Cisco Wireless Intrusion Prevention System Configuration Guide, Release 8.0
 http://www.cisco.com/en/US/products/ps9817/products_installation_and_configuration_guides_list.html
- Cisco CMX Analytics Configuration Guide, Release 8.0
 http://www.cisco.com/en/US/products/ps9742/products_installation_and_configuration_guides_list.html
- Cisco CMX Connect and Engage Configuration Guide for Visitor Connect, Release 8.0
 http://www-author.cisco.com/c/en/us/support/wireless/mobility-services-engine/products-installation-and-configuration-guides-list.html
- Cisco CMX Connect and Engage Configuration Guide for SDK, Release 8.0
 http://www-author.cisco.com/c/en/us/support/wireless/mobility-services-engine/products-installation-and-configuration-guides-list.html
- Cisco Virtual Appliance Installation and Configuration Guide, Release 8.0
 http://www.cisco.com/en/US/products/ps9742/tsd_products_support_series_home.html
- Cisco Mobility Services Engine Getting Started Guide
 http://www.cisco.com/en/US/products/ps9742/prod_installation_guides_list.html
- The Prime Infrastructure Online Help is available with the Prime Infrastructure product.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.

This document is to be used in conjunction with the documents listed in the "Related Documentation" section. Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2015 Cisco Systems, Inc. All rights reserved.

Obtaining Documentation and Submitting a Service Request