

#### **Caveats**

- Open Caveats in Cisco Smart PHY 3.1.4, on page 1
- Resolved Caveats in Cisco Smart PHY 3.1.4, on page 1
- Open Caveats in Cisco Smart PHY 3.1.3, on page 2
- Resolved Caveats in Cisco Smart PHY 3.1.3, on page 2
- Open Caveats in Cisco Smart PHY 3.1.2, on page 3
- Resolved Caveats in Cisco Smart PHY 3.1.2, on page 3
- Open Caveats in Cisco Smart PHY 3.1.1, on page 4
- Cisco Bug Search, on page 4

# **Open Caveats in Cisco Smart PHY 3.1.4**

The following caveats are found in the Cisco Smart PHY application:

| Caveat ID Number | Description  |
|------------------|--|
| CSCvx75112       | Inventory data is not getting imported all the time, soon after a fresh install. |
| CSCvx76464       | Redis leader election fails at times and the Cisco Smart PHY UI does not work.   |

#### **Resolved Caveats in Cisco Smart PHY 3.1.4**

The following caveats are resolved in the Cisco Smart PHY application 3.1.4:

| Caveat ID Number | Description   |
|------------------|---|
| CSCvw76260       | Cisco cBR-8 is getting added to Smart PHY by passing a non-unique UUID.                                       |
| CSCvw80225       | Cisco cBR-8 is not able to come back from maintenance mode.   |
| CSCvw81159       | Error 500 seen when v1 version of SetRPDPairingList API is used to configure data and video services on RPDs. |

# **Open Caveats in Cisco Smart PHY 3.1.3**

The following caveat is found in the Cisco Smart PHY application:

| Caveat ID Number | Description   |
|------------------|---|
| CSCvw76260       | Cisco cBR-8 is getting added to Smart PHY by passing a non-unique UUID.                                       |
| CSCvw80225       | Cisco cBR-8 is not able to come back from maintenance mode.   |
| CSCvw81159       | Error 500 seen when v1 version of SetRPDPairingList API is used to configure data and video services on RPDs. |

### **Resolved Caveats in Cisco Smart PHY 3.1.3**

The following caveats are resolved in the Cisco Smart PHY application 3.1.3:

| Caveat ID Number | Description  |
|------------------|--|
| CSCvn25389       | Latency in switching between authentication plugins.                                       |
| CSCvn99646       | UI RPD page displays 502 bad gateway error.  |
| CSCvo88956       | Kong does not switch between different authentication plugins after Worker Node power-off. |
| CSCvp07165       | Changing password using the UI users page sometimes fails.                                 |
| CSCvp12529       | Latency seen in creation of Kong Credentials associated with Kong Consumers.               |
| CSCvp89858       | Kong pods status remains as CrashLoopBackOffafter new installation of multinode.           |
| CSCvp94756       | Cisco Smart PHY does not detect LC switchover or revert back when CBR8 CPU usage is high.  |
| CSCvr83277       | UI: RPD Assignment record not updated dynamically with search.                             |
| CSCvs02350       | Backend: In the service template zero is accepted for secondUpstreamVARPD Profile.         |
| CSCvt68898       | ConfigurePushError when disable network-delay per RPD in UI.                               |
| CSCvs02350       | Backend: In the service template zero is accepted for secondUpstreamVARPD Profile.         |
| CSCvv78841       | Clear RPD failed from UI due to commit queue failure.                                      |

# **Open Caveats in Cisco Smart PHY 3.1.2**

The following caveats are found in the Cisco Smart PHY application:

| Caveat ID Number | Description   |
|------------------|---|
| CSCvn25389       | Latency in switching between authentication plugins.                                      |
| CSCvn99646       | UI RPD page displays 502 bad gateway error.   |
| CSCvo88956       | Kong doesn't switch between different authentication plugins after Worker Node power-off. |
| CSCvp07165       | Changing password using the UI users page sometimes fails.                                |
| CSCvp12529       | Latency seen in creation of Kong Credentials associated with Kong Consumers.              |
| CSCvp89858       | Kong pods status remains as CrashLoopBackOff after new installation of multinode.         |
| CSCvr83277       | UI: RPD Assignment record not updated dynamically with search.                            |
| CSCvs02350       | Backend: In the service template zero is accepted for secondUpstreamVARPD Profile.        |
| CSCvv78841       | Clear RPD failed from UI due to commit queue failure.                                     |

### **Resolved Caveats in Cisco Smart PHY 3.1.2**

The following caveats are resolved in the Cisco Smart PHY application:

| Caveat ID Number | Description   |
|------------------|---|
| CSCvp94756       | Cisco Smart PHY does not detect LC switchover or revertback when Cisco cBR-8 CPU usage is high. |
| CSCvs63014       | PushConfig error gets ignored when deleting is not allowed during LC switchover.                |
| CSCvt00378       | Virtual-service-group takes more than 8 minutes to synchronize over to the RPD service manager. |
| CSCvt68898       | ConfigurePushError when disabling network-delay per RPD in the UI.                              |
| CSCvv46603       | RPD is sometimes stuck in delete pending state.   |
| CSCvv66738       | RPD pairing V2 query returns wrong video after V1 is set with BC first.                         |
| CSCvv66744       | UI: RPD data doubles in the RPD table when the <b>Refresh</b> button is clicked rapidly.        |

## **Open Caveats in Cisco Smart PHY 3.1.1**


The following caveats are found in the Cisco Smart PHY application:

| Caveat ID Number | Description   |
|------------------|---|
| CSCvn25389       | Latency in switching between authentication plugins.                                      |
| CSCvn99646       | UI RPD page displays 502 bad gateway error.   |
| CSCvo88956       | Kong doesn't switch between different authentication plugins after Worker Node power-off. |
| CSCvp07165       | Changing password using the UI users page sometimes fails.                                |
| CSCvp12529       | Latency seen in creation of Kong Credentials associated with Kong Consumers.              |
| CSCvp89858       | Kong pods status remains as CrashLoopBackOff after new installation of multinode.         |
| CSCvp94756       | Cisco Smart PHY does not detect LC switchover or revert back when CBR8 CPU usage is high. |
| CSCvr83277       | UI: RPD Assignment record not updated dynamically with search.                            |
| CSCvs02350       | Backend: In the service template zero is accepted for secondUpstreamVARPD Profile.        |
| CSCvt68898       | ConfigurePushError when disable network-delay per RPD in UI.                              |


### **Cisco Bug Search**

Use the Cisco Bug Search Tool to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.



You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.



Cisco Bug Search