Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The "Open Caveats" sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

- The "Resolved Caveats" sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.

✎

Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

Resolved Caveats - Cisco IOS XE Dublin 17.10.1

Identifier	Headline
CSCwb82994	RSTP loop can be noticed when the router becomes alive
CSCwc41135	Continuous assertion and clear of LAIS on protect channel causing IPC failure
CSCwb55575	TPOP: enabling RTP is not inserting RTP header in TPOP until DCR is configured
CSCwb78907	DS3_RX_RAI is shown in both facility-alarm and facility-condition status cli
CSCwb76150	STS1e ⇒ vt-15 ⇒ Difference in ifName string format for controller up/down syslog messages
CSCwb60002	Router may experience an unexpected reset when configuring or using interface BDI >= 4097

Identifier	Headline
CSCwb90111	APS-ACR config/unconfig results in traffic drop
CSCwb69025	Change in SD-BER threshold value to 10e-9 causes SD alarm assertion
CSCwc53354	Alarm assertion/clearing not happening for port x+1 when complete sonet config for port x is removed
CSCwb65890	NCS4200-1T8S-20CS MLPPP: Fake AIS alarm is seen on controller during channel group config
CSCwc25182	Synchronization Status Messaging (S1) Processing and Generation issue

Resolved Caveats - Cisco IOS XE Dublin 17.10.1 - Platform Independent

There are no platform independent resolved caveats for this release.

Open Caveats - Cisco IOS XE Dublin 17.10.1

Identifier	Headline
CSCwd28107	RSP3: Bundle rommon version 15.6(57r)S to polaris_dev
CSCwc77502	Unexpected router reload due to MLDPv6
CSCwc93296	Port Te0/0/10 went admin down after successive reloads
CSCwd05362	Performance issue on ASR900 platform
CSCwc65971	RSP3: MPLS pseudowirte - Incorrect label stack pushed to packet

Open Caveats - Cisco IOS XE Dublin 17.10.1 - Platform Independent

There are no platform independent open caveats for this release.

Cisco Bug Search Tool

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at http://www.cisco.com/web/applicat/cbsshelp/help.html