New and Changed Information

This document provides release-specific information for each new and changed feature in Cisco Data Mobility Manager.

Table 1: New and Changed Features for Cisco Data Mobility Manager summarizes the new and changed features as described in the *Cisco MDS 9000 Series Data Mobility Manager Configuration Guide* , and tells you where they are documented. The table includes a brief description of each new feature and the release in which the change occurred.

Table 1: New and Changed Features for Cisco Data Mobility Manager

Feature	Description	Changed in Release	Where Documented
DMM	Updated the Limitations and Restrictions section for the bulk notification feature.	6.2(7)	Cisco MDS DMM Overview
Cisco MDS 9250i Multiservice Fabric Switch	Added the support for Cisco MDS 9250i Multiservice Fabric Switch.	6.2(5)	Cisco MDS DMM Overview Getting Started Understanding DMM Topologies
Method 3	Deprecated Method 3	6.2(3)	—
Greater than 2 Terabyte LUN support (Method 1 Only)	Added capability to migrate LUNs greater than 2TB (Method 1 Jobs only).	6.2(3)	Cisco MDS DMM Overview
FC-Redirect on Cisco MDS 9710	Added support for hosts and storages connected to MDS 9710.	6.2(3)	Cisco MDS DMM Overview Understanding DMM Topologies
There are no changes since 5.0(1a).	—	—	—

Feature	Description	Changed in Release	Where Documented
DMM Pre-Configuration Wizard	Steps and screenshots added to configure the MDS modules using the DMM Pre-Configuration Wizard.	5.0(1a)	Getting Started
CPP and default-gateway	Note added about configuring CPP interface default-gateway on Fabric Manager.	4.2(1)	Getting Started