

Release Notes for Cisco WAP551 and WAP561 Firmware Version 1.2.1.6

Contents

This document includes the following topics:

- **Cisco WAP551 and WAP561 Wireless Access Points, Firmware Version 1.2.1.6, on page 2**
- **Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.2.1.3, on page 3**
- **Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.2.0.2, on page 6**
- **Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.1.2.x, on page 8**
- **Related Information, page 10**

Cisco WAP551 and WAP561 Wireless Access Points, Firmware Version 1.2.1.6

December 2017

These release notes describe the known issues for the Cisco WAP551 and WAP561 Wireless Access Points.

Requirements

Your computer must meet the recommended hardware and software requirements.

A computer with Browser support for:

- Internet Explorer v7.0 or later
- Chrome v5.0 or later
- Firefox v3.0 or later
- Safari v3.0 or later

New Features and Enhancements

- Openssl upgrade to version 1.0.2l
- NTP upgrade to version 4.2.8p10

Resolved Issues

Ref Number	Description
CSCvf96818	Symptom: Key Reinstallation attacks against WPA protocol

Known Issues

These are the known issues for firmware version 1.2.1.6

Ref Number	Description
CSCud33819	Symptom: WAP5x1 access points do not have a real-time clock (RTC) so they cannot store the system time. System time will show it correctly as long as you do not reboot the access point. Workaround: Cisco recommends using NTP to set system time.
CSCui10930	Symptom: Configure excluded view cannot access all MIB tree. Workaround: None.
CSCuh42442	Symptom: When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day. Workaround: None.

Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.2.1.3

March, 2016

These release notes describe the open issues for the Cisco WAP551 and WAP561 Wireless Access Points.

Requirements

Your computer must meet the recommended hardware and software requirements.

A computer with Browser support for:

- Internet Explorer v7.0 or later
- Chrome v5.0 or later
- Firefox v3.0 or later
- Safari v3.0 or later

New Features and Enhancements

- Https remove SSLv3 and add TLSv1.2 support. This may cause browsers which not support TLS1.2 cannot access GUI via https, please use latest version with TLS1.2 support.
- Enhancement for Wireless Neighborhood Signal Strength.

Resolved Issues

Ref Number	Description
CSCuy86859	Symptom: RADIUS Accounting cannot work for Apple Device.
CSCuw95919	Symptom: WAP5x1 Wireless Clients disconnect intermittently.

Known Issues

These are the known issues for firmware version 1.2.1.3

Ref Number	Description
CSCud33819	Symptom: WAP5x1 access points do not have a real-time clock (RTC) so they cannot store the system time. System time will show it correctly as long as you do not reboot the access point. Workaround: Cisco recommends using NTP to set system time.
CSCui10930	Symptom: Configure excluded view cannot access all MIB tree. Workaround: None.
CSCuh42442	Symptom: When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day. Workaround: None.

Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.2.0.2

June, 2015

These release notes describe the open issues for the Cisco WAP551 and WAP561 Wireless Access Points.

Requirements

Your computer must meet the recommended hardware and software requirements.

A computer with Browser support for:

- Internet Explorer v7.0 or later
- Chrome v5.0 or later
- Firefox v3.0 or later
- Safari v3.0 or later

New Features and Enhancements

- IGMP Snooping
- 802.11w - PMF

Resolved Issues

Ref Number	Description
CSCuq93941	Symptom: When traffic on tagged VLAN the throughout (especially download) is very slow.
CSCuq92093	Symptom: Email alert is blank with Microsoft Exchange Server 2007 or 2010.
CSCus78507	Symptom: GUI issue for “Session Key Refresh Rate”
CSCuu34454	Symptom: Improvement for multi-client throughput
CSCur00783	Symptom: WAP5x1: AP dropping out of cluster
CSCus23303	Symptom: Wireless client cannot get IP from DHCP server after a period of time
CSCui21821	Symptom: WAP5X1 Clients cannot connect when they see 16+ SSID from different APs
CSCul73641	Symptom: Wireless clients lose connection/cannot connect to the AP periodically
CSCul96092	Symptom: On latest builds user is able to configure SSID with all special characters. But on the networks help page, help content is not updated accordingly.

Known Issues

These are the known issues for firmware version 1.2.0.2

Ref Number	Description
CSCud33819	<p>Symptom: WAP5x1 access points do not have a real-time clock (RTC) so they cannot store the system time. System time will show it correctly as long as you do not reboot the access point.</p> <p>Workaround: Cisco recommends using NTP to set system time.</p>

Release Notes

Ref Number	Description
CSCui10930	<p>Symptom: Configure excluded view cannot access all MIB tree.</p> <p>Workaround: None.</p>
CSCuh42442	<p>Symptom: When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day.</p> <p>Workaround: None.</p>

Cisco WAP151 and WAP561 Wireless Access Points, Firmware Version 1.1.2.x

January, 2015

These release notes describe the open issues for the Cisco WAP551 and WAP561 Wireless Access Points.

Requirements

Your computer must meet the recommended hardware and software requirements.

A computer with Browser support for:

- Internet Explorer v7.0 or later
- Chrome v5.0 or later
- Firefox v3.0 or later
- Safari v3.0 or later

New Features and Enhancements

- Added LED Display Feature with Scheduler
- Added CLM implementation for -K and -R SKU

Resolved Issues

Ref Number	Description
CSCup48488	Symptom: Power LED flashing even when you set the static IPv6 address.
CSCuq93941	Symptom: When traffic on tagged VLAN, the throughput (especially download) is very slow.

Known Issues

These are the known issues for firmware version 1.1.2.x

Ref Number	Description
CSCui10930	Symptom: Configure excluded view cannot access all MIB tree. Workaround: None.
CSCuh42442	Symptom: When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day. Workaround: None.
CSCul96092	Symptom: On latest builds user is able to configure SSID with all special characters. But on the networks help page, help content is not updated accordingly. Workaround: None.
CSCud33819	Symptom: WAP5x1 access points do not have a real-time clock (RTC) so they cannot store the system time. System time will show it correctly as long as you do not reboot the access point. Workaround: Cisco recommends using NTP to set system time.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	http://www.cisco.com/go/sbpc
EU lot 26	For EU lot 26 related test result, please check this web page: www.cisco.com/go/eu-lot26-results
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP551 and WAP561 Administration Guide	www.cisco.com/go/500_wap_resources
Cisco Power Adaptors	www.cisco.com/go/wap_accessories

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.

78-20593-02