

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.9(1)

First Published: 2023-06-27

Last Modified: 2023-06-27

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.9(1)



Note There are no updates for Cisco Wireless Phone 860.

These release notes support the Cisco Wireless Phone 840 software release 1.9(1) only. This wireless smartphone requires:

- **Call Control**
 - Cisco Unified Communications Manager
 - Minimum: 11.5(1)
 - Recommended: 12.5(1), 14.0(1), or higher
 - Webex Calling
- **Wireless LAN Controller and Access Points**
 - See the [Cisco Wireless Phone 840 and 860 Wireless LAN Deployment Guide](#) for supported solutions.

What's new in this release

The following sections describe the features that are new or have changed in this release.

Cisco Wireless Phone 840 roaming recovery enhancements when a roam failure occurs

Added an enhancement to send an association to candidate Access Point after a reassociation time-out occurs without disconnecting the TCP socket to the Cisco Unified Communications Manager.

Where to Find More Information

Cisco Wireless Phone 840 and 860 user guide

Cisco Wireless Phone 840 and 860 administration guide for Cisco Unified Communications Manager

Installation

Refer to the following documents for installation instructions.

840 - <https://www.cisco.com/web/software/282074288/165240/cmterm-840.1-9-1-2098-68532-readme.html>

Open bugs

Bug number	Description
CSCwc20252	860–840 Bluetooth Pairing Mode Confusion vulnerability.
CSCwd73349	Conference not recorded when user creates a conference with a call on hold.
CSCwe57179	Phone didn't reregister to Webex after network outage and initial reconnection attempt failed.

Resolved bugs

Bug number	Description
-	-

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- View [All Caveats](#)
- View [Open Caveats](#)
- View [Resolved Caveats](#)

Americas Headquarters

Cisco Systems, Inc.
San Jose, CA

Asia pacific Headquarters

Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters

Cisco Systems International BV
Amsterdam,
The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

