



END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR CISCO IOS SOFTWARE RELEASES 12.1(19)EW AND 12.1(20)EW ON THE CISCO CATALYST 4000 AND CATALYST 4500 SERIES SWITCHES

Cisco Systems® announces the end-of-sale and end-of-life dates for Cisco IOS® Software releases 12.1(19)EW and 12.1(20)EW for the Cisco® Catalyst® 4000 and Catalyst 4500 Series Switches. The last day to order the affected product is October 4, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until October 4, 2010.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement, as well as replacement product part numbers.

Customers are encouraged to migrate to Cisco IOS Software Release 12.2(18)EW or newer for the Cisco Catalyst 4500 Series, which offers more hardware support and software functions. Information about the replacement product can be found at <http://www.cisco.com/univercd/cc/td/doc/product/lan/cat4000/>.

Table 1. End-of-Life Milestones and Dates for Cisco IOS Software Releases 12.1(19)EW and 12.1(20)EW on the Cisco Catalyst 4000 and Catalyst 4500 Series

| Milestone | Definition | Date |
|--|---|-----------------|
| End-of-Life Announcement Date | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | April 4, 2005 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | October 4, 2005 |
| Last Shipment Date | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | January 4, 2006 |
| End of Software Maintenance Releases Date | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. | October 4, 2006 |
| Last Date of Support | The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete. | October 4, 2010 |

Table 2. Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number |
|---------------------------------|---|---|
| S4KL3-12119EW | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; Routing Information Protocol (RIP), static routes, Internetwork Packet Exchange (IPX), AppleTalk | S4KL3-12218EW S4KL3-12220EW S4KL3-12220EWA S4KL3-12225EW S4KL3-12225EWA |
| S4KL3-12119EW= | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; with RIP, static routes, IPX, AppleTalk | S4KL3-12218EW= S4KL3-12220EW= S4KL3-12220EWA= S4KL3-12225EW= S4KL3-12225EWA= |
| S4KL3E-12119EW | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; Open Shortest Path First (OSPF), Interior Gateway Routing Protocol (IGRP), Enhanced IGRP, Intermediate System-to-Intermediate System (IS-IS) Protocol | S4KL3E-12218EW S4KL3E-12220EW S4KL3E-12220EWA S4KL3E-12225EW S4KL3E-12225EWA |
| S4KL3E-12119EW= | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; OSPF, IGRP, EIGRP, IS-IS | S4KL3E-12218EW= S4KL3E-12220EW= S4KL3E-12220EWA= S4KL3E-12225EW= S4KL3E-12225EWA= |
| S4KL3K2-12119EW | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; Triple Data Encryption Standard (3DES); RIP, static routes, IPX, AppleTalk | S4KL3K91-12218EW S4KL3K91-12220EW S4KL3K9-12220EWA S4KL3K9-12225EW S4KL3K9-12225EWA |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number |
|---------------------------------|---|---|
| S4KL3K2-12119EW= | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; 3DES; RIP, static routes, IPX, AppleTalk | S4KL3K91-12218EW= S4KL3K91-12220EW= S4KL3K9-12220EWA= S4KL3K9-12225EW= S4KL3K9-12225EWA= |
| S4KL3EK2-12119EW | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; 3DES; OSPF, IGRP, EIGRP, IS-IS | S4KL3EK91-12218EW S4KL3EK91-12220EW S4KL3EK9-12220EWA S4KL3EK9-12225EW S4KL3EK9-12225EWA |
| S4KL3EK2-12119EW= | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; 3DES; OSPF, IGRP, EIGRP, IS-IS | S4KL3EK91-12218EW= S4KL3EK91-12220EW= S4KL3EK9-12220EWA= S4KL3EK9-12225EW= S4KL3EK9-12225EWA= |
| S4KL3-12120EW | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; RIP, static routes, IPX, AppleTalk | S4KL3-12218EW S4KL3-12220EW S4KL3-12220EWA S4KL3-12225EW S4KL3-12225EWA |
| S4KL3-12120EW= | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; RIP, static routes, IPX, AppleTalk | S4KL3-12218EW= S4KL3-12220EW= S4KL3-12220EWA= S4KL3-12225EW= S4KL3-12225EWA= |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number |
|---------------------------------|---|--|
| S4KL3E-12120EW | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; OSPF, IGRP, EIGRP, IS-IS | S4KL3E-12218EW S4KL3E-12220EW S4KL3E-12220EWA S4KL3E-12225EW S4KL3E-12225EWA |
| S4KL3E-12120EW= | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; OSPF, IGRP, EIGRP, IS-IS | S4KL3E-12218EW= S4KL3E-12220EW= S4KL3E-12220EWA= S4KL3E-12225EW= S4KL3E-12225EWA= |
| S4KL3K2-12120EW | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; 3DES; RIP, static routes, IPX, AppleTalk | S4KL3K91-12218EW S4KL3K91-12220EW S4KL3K9-12220EWA S4KL3K9-12225EW S4KL3K9-12225EWA |
| S4KL3K2-12120EW= | Cisco IOS Software basic Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine II-Plus, III, and IV; 3DES; RIP, static routes, IPX, AppleTalk | S4KL3K91-12218EW= S4KL3K91-12220EW= S4KL3K9-12220EWA= S4KL3K9-12225EW= S4KL3K9-12225EWA= |
| S4KL3EK2-12120EW | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; 3DES; OSPF, IGRP, EIGRP, IS-IS | S4KL3EK91-12218EW S4KL3EK91-12220EW S4KL3EK9-12220EWA S4KL3EK9-12225EW S4KL3EK9-12225EWA |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number |
|---------------------------------|--|---|
| S4KL3EK2-12120EW= | Cisco IOS Software enhanced Layer 3 image, for Cisco Catalyst 4000 and Catalyst 4500 Series Supervisor Engine III and IV; 3DES; OSPF, IGRP, EIGRP, IS-IS | S4KL3EK91-12218EW= S4KL3EK91-12220EW= S4KL3EK9-12220EWA= S4KL3EK9-12225EW= S4KL3EK9-12225EWA= |

PRODUCT MIGRATION OPTIONS

The recommended replacement for Cisco IOS Software releases 12.1(19)EW and 12.1(20)EW on the Cisco Catalyst 4000 and Catalyst 4500 Series Switches is Cisco IOS Software Release 12.2(18)EW or newer. Software features such as stateful switchover (SSO); software-based IPv6; user-based rate limiting; community private VLAN; 802.1Q tunneling; per-port per-VLAN quality of service (QoS); and SmartPort Macros, as well as support for the Cisco Catalyst 4000/4500 Supervisor Engine V, Catalyst 4000/4500 Supervisor Engine V-10GE, Catalyst 4510R Switch chassis, and Power over Ethernet (PoE) 802.3af line cards are contained in the newer Cisco IOS Software releases.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about the Cisco Catalyst 4500 Series Switch, visit <http://www.cisco.com/univercd/cc/td/doc/product/lan/cat4000/index.htm> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 204189.bh_ETMG_JR_3.05

