

Nortel CS1000 R 4.0 using T1 QSIG to Cisco Unified Communications Manager 5.1.2 and Cisco Emergency Responder 2.0.

Disclaimer

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS DOCUMENT ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS DOCUMENT ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE CUSTOMER ASSUMES ALL RESPONSIBILITY FOR PROPERLY CONFIGURING THE CISCO EMERGENCY RESPONDER. CISCO HEREBY DISCLAIMS ANY AND ALL LIABILITY ARISING FROM OR IN CONNECTION WITH A USERS INABILITY TO REACH EMERGENCY SERVICE RESPONDERS (INCLUDING INABILITY TO ACCESS A PUBLIC SAFETY ANSWERING POINT) OR THE INABILITY OF EMERGENCY SERVICE RESPONDERS TO IDENTIFY A USERS LOCATION. CISCO STRONGLY RECOMMENDS THAT ALL CUSTOMERS VERIFY AND TEST CONFIGURATION OF THE CISCO EMERGENCY RESPONDER IMMEDIATELY FOLLOWING INITIAL CONFIGURATION AND ON A PERIODIC BASIS THEREAFTER. CISCO FURTHER RECOMMENDS THAT ALL CUSTOMERS PROVIDE ADEQUATE TRUNK AND BANDWIDTH CAPACITY TO ENSURE THAT AUDIO PATHS ARE AVAILABLE FOR EMERGENCY CALLS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS PRODUCT, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

August 31, 2007 Revision 4

Table of Contents

Introduction	2
Network Topology	
Limitations	3
System Components	3
Hardware Requirements	3
Software Requirements	3
Features	
Conclusion	
Configuration	
Configuring Cisco Communications Manager	
Configuring Cisco Emergency Responder	41
Configuring Nortel CS1000 PBX with Succession 4.0 Software Release	71
Acronyms	
ACIONYMS	/ 0



Introduction

The following is an Application Note for E911 Interoperability of a Cisco Unified Communications Manager (CUCM) 5.1.2 and Cisco Emergency Responder (CER) 2.0 to a Nortel CS1000 R 4.0 via a Cisco 3825 T1-QSIG trunk as MGCP gateway. The CUCM system is connected to a simulated E911 Public Safety Answering Point (PSAP) via a Cisco 3825 w/ CAMA trunk registered using H323.

The Network Topology diagram shows the test set-up for interoperability between the Cisco Unified Communications Manager and Cisco Emergency Responder connected to the PBX via a Cisco 3825 (MGCP gateway) T1 QSIG trunk and connected to E911 PSAP using a Cisco 3825 H323 gateway via a CAMA trunk.

This Application Note uses the C3825 IOS-voice-gateway, however other Cisco voice gateways are also an option to use since the voice gateway implementation does not depend on the platform. Here is a list of Cisco Products capable of voice gateway functionality: Care must be taken when selecting a voice gateway platform depending of the capacity required for the intended deployments


Cisco 2800 Series Integrated Services Routers

Cisco 3800 Series Integrated Services Routers

Cisco 2600XM Series Multiservice Platforms

Cisco 3700 Series Routers

Network Topology





Limitations

Unique DID numbers must be used to associate with each Emergency Response Location to allow the return call if the 911 caller is disconnected.

Each available calling party that might dial 911 from the PBX side must have that calling party number configured in the Manually Configured Phones screen of the Cisco Emergency Responder.

System Components

Hardware Requirements

Cisco 3825 Gateway with VIC2-4FXO (CAMA trunk) Cisco 3825 Gateway with VWIC-2MFT-T1 (QSIG) Cisco Cat3500 switch Cisco Unified Communications Manager server Cisco Emergency Responder server

Software Requirements

Nortel CS1000 PBX

IOS Software release "C3825-ipvoiceK9-m.12.4 (15)T1"
IOS Software release "C3825-ADVENTERPRISEK9_IVS-M .12.4(11).T1
Cisco Unified Communications Manager 5.1.2
Cisco Emergency Responder 2.0
PBX Software: Release 4.0

Features

Key features supported

Calling Number

E911 ERL DID number passed to PSAP

Incoming DID calling to disconnected 911 originating caller

Conclusion

Test emergency 911 call from a PBX digital station was routed to the T1 QSIG trunk, of the Cisco Voice MGCP gateway, and was correctly associated to the appropriate Emergency Response Location. The call was connected through the Cisco 3825 CAMA trunk to the PSAP Emulator. The Emergency Response Location associated the ten digit DID call back number (ELIN) correctly and sent it to the PSAP, audio connection was also achieved. The PBX digital station was then disconnected.

A return call was originated from an incoming trunk (PSTN side) in the same Cisco Unified Communications Manager Partition. The number dialed was the DID digits of the 10 digit call back number sent to the PSAP on the previous 911 call (ELIN number). The call was routed through to the PBX digital station that had originated the E911 call. The call was disconnected and an alternate trunk was used to dial the same DID number and the call was routed through, again, to the PBX digital station that had originated the E911 call.

Test emergency 911calls were made from each PBX digital station and Cisco IP phone. All calls were confirmed to select its associated Emergency Response Location and the associated 10 digit DID call back number. In each case, the call was disconnected and the call back number was confirmed to reach the phone that had originated the E911 call.

Emergency 911calls made from a Nortel CS1000 PBX utilizing a T1 QSIG trunk configured as ISO, associates with the correct Emergency Response Location and routes to the associated PSAP with the correctly formatted 10 digit DID call back number.


The call back DID number routes the return call to the correct phone that had originated the E911 call from the PBX digital phone.



Configuration


Configuring Cisco Communications Manager

Partitions






Phone Partition






E911 Partition




Calling Search Space






CSS phones






CSS E911





CUCM IP phones





Network Locale	< None >	
Built In Bridge*	Default	-
Privacy*	Default	-
Owner User ID	< None >	-
Phone Load Name		
Retry Video Call as Audio		
Ignore Presentation Indicate	ors (internal calls only)	
Allow Control of Device from	СТІ	
Protocol Specific Information		
Packet Capture Mode*	None	-
Packet Capture Duration	0	
Presence Group*	Standard Presence group	
Device Security Profile*	Cisco 7961 - Standard SCCP Non-Secure Profile	
SUBSCRIBE Calling Search Space		
Unattended Port	- (Notice)	
Require DTMF Reception		
RFC2833 Disabled		
	Function (CAPF) Information o Pending Operation	
	y Null String	
Authentication String	y Wall String	
Generate String		
	224	
	024	
Certificate Operation Status: No	07 9 6 12 (YYYY:MM:DD:HH)	
Note: Security Profile Contains		
Expansion Module Information	an .	
Expansion Floudie Informatio	"	




	☐ Expansion Module Information	
	Module 1 < None >	
	Module 1 Load Name	
	Module 2 < None > ▼	
	Module 2 Load Name	
	External Data Locations Information (Leave blank to use default) Information	
	Directory	
	Messages	
	Services	
	Authentication Server	
	Proxy Server	
	Idle	
	Idle Timer (seconds)	
	rule fillier (Seconds)	
	Extension Information	
	Enable Extension Mobility	
	Log Out Profile Not Selected ▼	
	Login in User ID < None > Log in Time	
	Log out Time < None >	
	MLPP Information	
	MLPP Domain < None > ▼	
	MLPP Indication* Default ▼	
	MLPP Preemption* Default	
	Secure Shell Information	
<u> </u>	Secure Shell User	



MLPP Information	on —		
MLPP Domain	< None >	•	
MLPP Indication*	Default	▼	
MLPP Preemption*	Default	▼	
G GI 117 6			
Secure Shell Info	ormation		
Secure Shell Passy	word		
Secure Stream assv	voru		
□ Product Specific	Configuration Layout —		
			?
☐ Disable Speake	rphone		•
Disable Speake	rphone and Headset		
Forwarding Delay*	'	Disabled	•
PC Port *	Ī	Enabled	•
Settings Access*		Enabled	•
Gratuitous ARP*		Enabled	-
PC Voice VLAN Acce	ess*	Enabled	▼
Video Capabilities*	*	Disabled	▼
Auto Line Select*		Enabled	▼
Web Access*	_	Enabled	
Span to PC Port*		Disabled	
Logging Display*		PC Controlled	
Load Server			
Recording Tone*		Disabled	_
Recording Tone Lo	· · · · · · · · · · · · · · · · · · ·		-
Recording Tone Re		100	
		50	
Recording Tone Du	iration		








AAR Group	< None >	•		
User Hold MOH Audio Source	< None >	•		
Network Hold MOH Audio Source	< None >	•		
Auto Answer*	Auto Answer Off	▼		
Call Forward and Call Pickup	Settings			
	Voice Mail Destination		Calling Search Space	
Forward All	or or		< None >	▼
Secondary Calling Search Space	for Forward All		< None >	▼
Forward Busy Internal	or or		< None >	▼
Forward Busy External	or or		< None >	▼
Forward No Answer Internal	or or		< None >	-
Forward No Answer External	or or		< None >	•
Forward No Coverage Internal	or or		< None >	-
Forward No Coverage External	or or		< None >	-
Forward on CTI Failure	or or		< None >	-
No Answer Ring Duration (secon	ids)			
Call Pickup Group	< None >	•		
MLPP Alternate Party Setting Target (Destination)	s			
MLPP Calling Search Space	< None >	▼		
MLPP No Answer Ring Duration ((seconds)	,		
Line 1 on Device SEP00170E	E67E8E			
Display (Internal CER SCCP	3011	Display text for a line appear	rance is intended for displaying text such a	as a name instead of a
Caller ID) directory number for internal calls. If you specify a number, the person receiving a call may not see the proper identity of the caller.				
ASCII Display CER SCCP (Internal Caller ID)	3011			



MLPP No Answer Rin	ng Duration (seconds)			
Line 1 on Device	SEP00170EE67E8E			
Display (Internal	CER SCCP 3011	Display	ext for a line appearance is i	ntended for displaying text such as a name instead of a
	directory number for internal calls. If you specify a number, the person receiving a call may not see the proper identity of the caller.			
ASCII Display (Internal Caller ID)	CER SCCP 3011			
Line Text Label	CER SCCP 3011			
ASCII Line Text Label	CER SCCP 3011			
External Phone Number Mask				
Message Waiting Lamp Policy*	Use System Policy	•		
Ring Setting (Phone Idle)*	Use System Default	•		
Ring Setting (Phone Active)	Use System Default	▼ Applies to	this line when any line on the	phone has a call in progress.
	Waiting Settings on Device SEP001 select the Max Number of calls is: 1-20 f Calls*			(Less than or equal to Max. Calls)
Forwarded Call In Caller Name	formation Display on Device SEP00	170EE67E8E		
☑ Caller Number				
☑ Redirected Number				
☑ Dialed Number				
- Save Delete Reset Add New				
*- indicates required item.				
**- Changes to Line or Directory Number settings require restart.				




CTI Route Points







CTI Route Point 911
















CTI Route Point 913













Note: A Backup CER server was not used during testing therefore CTI route point for 912 was not created.



CTI Port










MLPP Calling Search	Space < None >		▼	
MLPP No Answer Rin	g Duration (seconds)		,	
ASCII Display (Internal Caller ID) Line Text Label				nded for displaying text such as a name instead of a see the proper identity of the caller.
ASCII Line Text Label External Phone				
Number Mask Message Waiting Lamp Policy*	Use System Policy	▼		
	Waiting Settings on Device CERSe elect the Max Number of calls is: 1-			
Busy Trigger*	Calls*	2	(L	ess than or equal to Max. Calls)
Forwarded Call In Caller Name	formation Display on Device CERS	Sec1		
Caller Number				
Redirected Numb Dialed Number	er			
	set Add New			
*- indicates req	uired item. Line or Directory Number settings i			
***- Changes to	Line of Directory Number settings i	equire restart.		




Route Patterns for ELINs






Route Pattern 10911






Route Pattern 11911











Route Pattern 13911






Translation Pattern for ELINs












PSAP Gateway configuration (CAMA TRUNK)








Cisco Unified Communications Manager User











T1-QSIG Gateway











Call Routing Information - Outb					
Calling Party Presentation*	Default	•			
Calling Party Selection*	Originator	•			
Called party IE number type unkno	ologo odminanago.	▼			
Calling party IE number type unkn	own* Cisco CallManager	•			
Called Numbering Plan*	Cisco CallManager	•			
Calling Numbering Plan*	Cisco CallManager	•			
Number of digits to strip*	0	•			
Caller ID DN					
SMDI Base Port*	0				
PRI Protocol Type Specific Info	rmation				
Display IE Delivery					
Redirecting Number IE Delivery					
Redirecting Number IE Delivery					
Send Extra Leading Character					
Setup non-ISDN Progress India					
☐ MCDN Channel Number Extensi ☐ Send Calling Name In Facility IE					
Interface Identifier Present**					
Interface Identifier Value**	n				
Connected Line ID Presentation (0	QSIG Inbound Call)* Default		•		
UUIE Configuration			· 		
Passing Precedence Level Thro	uah UUIE				
Security Access Level*	ag., 6				-
15					
12		I	1 1 1 1 1 1	-	1
Interface Identifier Value**	0				
Interface Identifier Value** Connected Line ID Presentation ((QSIG Inbound Call)* Default	1	•		
Connected Line ID Presentation (QSIG Inbound Call)* Default		V		
Connected Line ID Presentation (1	•		
Connected Line ID Presentation (V		
Connected Line ID Presentation (C UUIE Configuration Passing Precedence Level Thro			V		
Connected Line ID Presentation (C UUIE Configuration Passing Precedence Level Thro	ugh UUIE		•		
Connected Line ID Presentation (COUTE Configuration Passing Precedence Level Thro Security Access Level* Product Specific Configuration	ugh UUIE Layout	?	▼		
Connected Line ID Presentation (COUTE Configuration Passing Precedence Level Throsecurity Access Level* Product Specific Configuration In Line Coding*	Layout B8ZS	-	▼		
Connected Line ID Presentation (CONNECTED IN THE PROPERTY OF T	Layout B8ZS ESF	•	•		
Connected Line ID Presentation (COUTE Configuration Passing Precedence Level Throsecurity Access Level* Product Specific Configuration In Line Coding* Framing* Clock*	Layout B8ZS ESF External	-	•		
Connected Line ID Presentation (CONNECTED IN THE IDENTITY OF T	Layout B8ZS ESF	•	•		
Connected Line ID Presentation (CONNECTED IN THE PROPERTY OF T	Layout B8ZS ESF External	•	•		
Connected Line ID Presentation (CONNECTED IN THE PROPERTY OF T	B8ZS ESF External 0 0 Enable	•	•		
Connected Line ID Presentation (CONNECTED IN THE PROPERTY OF T	B8ZS ESF External 0 0 Enable	*	T		
Connected Line ID Presentation (CONNECTED IN THE PROPERTY OF T	B8ZS ESF External 0 0 Enable	*	T		
Connected Line ID Presentation (CONNECTED IN IDEA OF SECURITY ACCESS LEVEL * 2 Product Specific Configuration IDEA OF SECURITY ACCESS LEVEL * 2 Product Specific Configuration IDEA OF SECURITY ACCESS LEVEL * 2 Product Specific Configuration IDEA OF SECURITY ACCESS LEVEL * 2 Line Coding * Framing * Clock * Input Gain (-614 db) * Output Attenuation (-614 db) * Echo Cancellation Enable * Echo Cancellation Coverage (ms) *	B8ZS ESF External 0 0 Enable	*	•		
Connected Line ID Presentation (CONNECTED IN IDEA OF SECURITY ACCESS LEVEL TO Security Access Level CONFIGURATION IDEA OF SECURITY ACCESS LEVEL TO	B8ZS ESF External 0 0 Enable 8	*	•		
Connected Line ID Presentation (COUIE Configuration Passing Precedence Level Thro Security Access Level* Product Specific Configuration ID Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset ** - indicates required item. ** - applies to DMS-100 proto	B8ZS ESF External 0 0 Enable 8	*	▼		
Connected Line ID Presentation (COUIE Configuration Passing Precedence Level Thro Security Access Level* Product Specific Configuration ID Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset ** - indicates required item. ** - applies to DMS-100 proto	B8ZS ESF External 0 0 Enable 8	*	V		



Route Pattern to QSIG Trunk








Note: For detailed information regarding QSIG interoperability between CUCM and Nortel CS1000 PBX go to: http://www.cisco.com/warp/public/779/largeent/avvid/inter_operability/flash/portal.html


SNMP service must be active






Configuring Cisco Emergency Responder

Cisco Unified Communications Manager Details






Cisco Emergency Responder Server group






Telephony Settings






Server Settings






ERLs List






ERL 1






ERL 2






ERL 3






SNMP connection






LAN Switch identifying







Switch Port Details















Defining Manual Phones (PBX Stations)









Cisco CMM IOS Gateway MGCP Configuration for QSIG Connectivity

Ri-3825#sh ver

Cisco IOS Software, 3800 Software (C3825-IPVOICEK9-M), Version 12.4(15)T1, RELEA

SE SOFTWARE (fc2)

Technical Support: http://www.cisco.com/techsupport

Copyright (c) 1986-2007 by Cisco Systems, Inc.

Compiled Wed 18-Jul-07 11:23 by prod_rel_team

ROM: System Bootstrap, Version 12.3(11r)T2, RELEASE SOFTWARE (fc1)

Ri-3825 uptime is 4 weeks, 6 days, 23 hours, 15 minutes System returned to ROM by reload at 17:08:17 UTC Tue Jul 24 2007 System image file is "flash:c3825-ipvoicek9-mz.124-15.T1.bin"

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 3825 (revision 1.0) with 224256K/37888K bytes of memory.

Processor board ID FTX0946A1BT

2 Gigabit Ethernet interfaces

48 Serial interfaces

2 Channelized T1/PRI ports

2 Voice FXS interfaces



DRAM configuration is 64 bits wide with parity enabled.
479K bytes of NVRAM.
62720K bytes of ATA System CompactFlash (Read/Write)

Configuration register is 0x2102

Ri-3825#sh run

Building configuration...

```
Current configuration: 2419 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname Ri-3825
!
boot-start-marker
boot-end-marker
enable password cisco
no aaa new-model
network-clock-participate slot 1
no network-clock-participate slot 2
network-clock-select 1 T1 1/0/0
voice-card 0
no dspfarm
voice-card 1
dspfarm
voice-card 2
no dspfarm
```

!



```
ip cef
no ip domain lookup
ip host CM-Titanic 172.20.140.254 >=====Active Host
ip host CM-SPURS 172.20.192.254
multilink bundle-name authenticated
isdn switch-type primary-qsig
archive
log config
 hidekeys
controller T1 1/0/0
framing esf
linecode b8zs
pri-group timeslots 1-24 service mgcp
controller T1 1/0/1
shutdown
framing esf
linecode b8zs
cablelength short 399
pri-group timeslots 1-24 service mgcp
```



```
interface GigabitEthernet0/0
ip address 172.20.192.21 255.255.255.0
duplex auto
speed auto
media-type rj45
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
media-type rj45
interface Serial1/0/0:23
no ip address
encapsulation hdlc
isdn switch-type primary-qsig
isdn timer T310 120000
isdn protocol-emulate network
isdn incoming-voice voice
isdn bind-13 ccm-manager
no cdp enable
interface Serial1/0/1:23
no ip address
encapsulation hdlc
shutdown
isdn switch-type primary-qsig
isdn incoming-voice voice
isdn bind-13 ccm-manager
no cdp enable
```



```
ip route 0.0.0.0 0.0.0.0 172.20.192.1
ip http server
no ip http secure-server
control-plane
voice-port 1/0/0:23
voice-port 1/0/1:23
!
voice-port 2/0/0
voice-port 2/0/1
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server CM-Titanic
ccm-manager config
!
mgcp
mgcp call-agent CM-Titanic 2427 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp rtp unreachable timeout 1000 action notify
mgcp modem passthrough voip mode nse
mgcp package-capability rtp-package
mgcp package-capability sst-package
mgcp package-capability pre-package
no mgcp package-capability res-package
```



```
no mgcp package-capability fxr-package
no mgcp timer receive-rtcp
mgcp sdp simple
mgcp fax t38 inhibit
mgcp rtp payload-type g726r16 static
!
mgcp profile default
!
line con 0
password cisco
login
stopbits 1
line aux 0
stopbits 1
line vty 04
password cisco
login
!
scheduler allocate 20000 1000
!
end
 Cisco 3825 IOS Gateway H323 configuration for CAMA trunk connectivity
Router#sh ver
Cisco IOS Software, 3800 Software (C3825-ADVENTERPRISEK9_IVS-M), Version 12.4(11
)T1, RELEASE SOFTWARE (fc5)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2007 by Cisco Systems, Inc.
Compiled Thu 25-Jan-07 17:16 by prod_rel_team
ROM: System Bootstrap, Version 12.3(11r)T2, RELEASE SOFTWARE (fc1)
Router uptime is 1 week, 3 days, 17 hours, 23 minutes
System returned to ROM by power-on
```



System image file is "flash:c3825-adventerprisek9_ivs-mz.124-11.T1.bin" This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 3825 (revision 1.0) with 223232K/38912K bytes of memory.

Processor board ID FTX0946A1BV

- 2 Gigabit Ethernet interfaces
- 24 Serial interfaces
- 1 Channelized T1/PRI port
- 1 Virtual Private Network (VPN) Module
- 2 Voice FXO interfaces
- 2 Voice FXS interfaces

DRAM configuration is 64 bits wide with parity enabled.

479K bytes of NVRAM.

62720K bytes of ATA System CompactFlash (Read/Write)

Configuration register is 0x2102



Router#sh run

Building configuration...

```
Current configuration: 2545 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname Router
boot-start-marker
boot system flash:c3825-adventerprisek9_ivs-mz.124-11.T1.bin
boot-end-marker
logging buffered 10000000
no logging console
enable password cisco
no aaa new-model
no network-clock-participate slot 1
voice-card 0
dspfarm
dsp services dspfarm
voice-card 1
dspfarm
ip cef
```



multilink bundle-name authenticated
!
isdn switch-type primary-dms100
!
!
!
voice service voip
allow-connections h323 to h323=====H323 protocol
allow-connections h323 to sip
allow-connections sip to h323
allow-connections sip to sip
h323
sip
!
!
!
voice class codec 1
codec preference 1 g729r8
!
!
!
!
!
!
!
controller T1 1/0/0
framing esf
linecode b8zs
pri-group timeslots 1-24
!
!
!
!
!



```
interface GigabitEthernet0/0
ip address 172.20.192.102 255.255.255.0
duplex auto
speed auto
media-type rj45
no keepalive
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
media-type rj45
no keepalive
interface Serial1/0/0:23
no ip address
encapsulation hdlc
isdn switch-type primary-dms100
isdn incoming-voice voice
no cdp enable
ip default-gateway 172.20.192.1
ip route 0.0.0.0 0.0.0.0 172.20.192.1
ip http server
no ip http secure-server
```



```
control-plane
voice-port 0/0/0 ===→CAMA signaling
signal cama KP-0-NPA-NXX-XXXX-ST
dial-type mf
timing hookflash-out 500
description CAMA
voice-port 0/0/1
voice-port 0/2/0
station-id name Test Analog
station-id number 7055
voice-port 0/2/1
station-id name RI-NGUYEN
station-id number 4085261122
caller-id enable
voice-port 1/0/0:23
sccp local GigabitEthernet0/0
sccp ccm 172.20.8.254 identifier 1 version 4.1
sccp
sccp ccm group 1
associate ccm 1 priority 1
associate profile 1 register mtp0015f90d1590
dspfarm profile 1 mtp
codec g711ulaw
```



```
maximum sessions software 10
associate application SCCP
shutdown
dial-peer voice 911 pots
destination-pattern 911
no digit-strip
port 0/0/0
forward-digits all
dial-peer voice 999 voip
description call in PSTN simulation
destination-pattern .T
session target ipv4:172.20.140.254
gateway
timer receive-rtp 1200
sip-ua
retry options 0
gatekeeper
shutdown
line con 0
exec-timeout 0 0
password cisco
login
stopbits 1
line aux 0
```



```
stopbits 1
line vty 0 4
exec-timeout 0 0
password cisco
login
line vty 5 10
exec-timeout 0 0
password cisco
login
!
scheduler allocate 20000 1000
!
end
```



CAMA voice-port config

Router#sh voice port 0/0/0

Foreign Exchange Office 0/0/0 Slot is 0, Sub-unit is 0, Port is 0

Type of VoicePort is FXO

Operation State is DORMANT

Administrative State is UP

The Last Interface Down Failure Cause is Administrative Shutdown

Description is CAMA

Noise Regeneration is enabled

Non Linear Processing is enabled

Non Linear Mute is disabled

Non Linear Threshold is -21 dB

Music On Hold Threshold is Set to -38 dBm

In Gain is Set to 0 dB

Out Attenuation is Set to 3 dB

Echo Cancellation is enabled

Echo Cancellation NLP mute is disabled

Echo Cancellation NLP threshold is -21 dB

Echo Cancel Coverage is set to 64 ms

Echo Cancel worst case ERL is set to 6 dB

Playout-delay Mode is set to adaptive

Playout-delay Nominal is set to 60 ms

Playout-delay Maximum is set to 250 ms

Playout-delay Minimum mode is set to default, value 40 ms

Playout-delay Fax is set to 300 ms

Connection Mode is normal

Connection Number is not set

Initial Time Out is set to 10 s

Interdigit Time Out is set to 10 s

Call Disconnect Time Out is set to 60 s

Ringing Time Out is set to 180 s

Wait Release Time Out is set to 30 s

Companding Type is u-law

Region Tone is set for US



Analog Info Follows:
Currently processing none
Maintenance Mode Set to None (not in mtc mode)
Number of signaling protocol errors are 9
Impedance is set to 600r Ohm
Station name None, Station number None
Translation profile (Incoming):
Translation profile (Outgoing):
Voice card specific Info Follows:
Signal Type is cama
Cama Type is KP-0-NPA-NXX-XXXX-ST
Battery-Reversal is enabled
Number Of Rings is set to 1
Supervisory Disconnect is signal
Answer Supervision is inactive
Hook Status is On Hook
Ring Detect Status is inactive
Ring Ground Status is inactive
Tip Ground Status is inactive
Dial Out Type is mf
Digit Duration Timing is set to 75 ms
InterDigit Duration Timing is set to 65 ms
Pulse Rate Timing is set to 10 pulses/second
InterDigit Pulse Duration Timing is set to 750 ms
Percent Break of Pulse is 60 percent
GuardOut timer is 2000 ms
Minimum ring duration timer is 125 ms
Hookflash-in Timing is set to 600 ms
Hookflash-out Timing is set to 500 ms
Supervisory Disconnect Timing is set to 350 ms
OPX Ring Wait Timing is set to 6000 ms



Configuring Nortel CS1000 PBX with Succession 4.0 Software Release

The Nortel CS1000 Switch requires a substantial amount of programming and circuit card switch settings to properly install T1 PRI. It is beyond the scope of this document to provide the entire configuration, therefore the Nortel CS1000 information below is directed to Nortel techs

The switch settings and software references in this document assume a familiarity with the Nortel CS1000. It is highly recommended to have a Nortel ISDN certified technician setup the Nortel portion.

Common equipment:

```
REO PRT
TYPE CEQU
CEQU
 MPED 8D
 SUPL 000 004
                 008
                      012
       016 032 036
                      040
       044 048 064
                      068
       072 V096 V100
 TDS
       000
 CONF
       029
            030
                 031 062
       094
            095
 DLOP
       NUM DCH FRM TMDI LCMT YALM T1TE TRSH
  PRT
       0.2
                        B8S FDL -
            23 ESF NO
                                       0.0
       04
            24
                ESF YES
                        B8S
                             DG2
                                  0
                                       00
       05
            23 ESF NO
                        B8S FDL -
                                       00
       06
            23 ESF NO
                        B8S FDL
                                       00
       07
            23 ESF NO
                        B8S FDL
 PRI2 11
 DTI2
      12 13 21
 MISP
```

Configure D-Channel

```
>ld 22
PT2000
REQ prt
TYPE adan dch 5
ADAN
        DCH 5
 CTYP MSDL
 CARD 05
 PORT 1
 DES BARCLAYS1
 USR PRI
 DCHL 5
 OTBF 32
 PARM RS422 DTE
 DRAT 64KC
 CLOK EXT
 IFC ISGF
   PINX_CUST 0
```



```
ISDN_MCNT 300
CLID OPT0
CO_TYPE STD
SIDE NET
CNEG 1
RLS ID **
RCAP COLP NDI CCBI CCNI PRI DV3I CTI QMWI
PR_TRIGS DIV 2 3
         CNG 2 3
         CTR2 2 3
PR_RTN NO
MBGA NO
OVLR NO
OVLS NO
T310 120
T200 3
T203 10
N200 3
N201 260
```

Configure Route Data Block

```
>ld 21
PT1000
REQ: prt
TYPE: rdb
CUST 0
ROUT 105
TYPE RDB
CUST 00
DMOD
ROUT 105
DES BARCLAYS1
TKTP TIE
NPID_TBL_NUM
ESN NO
CNVT NO
SAT NO
RCLS EXT
VTRK NO
NODE
DTRK YES
BRIP NO
DGTP PRI
ISDN YES
   MODE PRA
    IFC ISGF
   SBN NO
PNI 00001
    NCNA NO
    NCRD NO
    CHTY BCH
    CTYP UKWN
    INAC NO
    ISAR NO
    CPFXS YES
   DAPC NO
   INTC NO
DSEL VOD
PTYP PRI
AUTO NO
DNIS NO
```

DCDR NO



```
ICOG IAO
SRCH RRB
TRMB YES
STEP
ACOD 205
TCPP NO
TARG 01
CLEN 1
BILN NO
OABS
INST
ANTK
SIGO STD
ICIS YES
TIMR ICF 512
     OGF 512
    EOD 13952
    NRD 10112
    DDL 70
     ODT
         4096
    RGV 640
     GRD 896
     SFB
    NBS 2048
    NBL 4096
     IENB 5
     TFD 0
PAGE 002
         0
     VSS
     VGD
          6
DRNG NO
CDR NO
VRAT NO
MUS NO
FRL 0 0
FRL 1 0
FRL 2 0
FRL 3 0
FRL 4 0
FRL 5 0
FRL 6 0
FRL 7 0
OHQ NO
OHQT 00
CBQ NO
AUTH NO
TTBL 0
ATAN NO
PLEV 2
ALRM NO
ART 0
SGRP 0
AACR NO
```

Configure Trunk

>ld 20

PT0000 REQ: prt TYPE: tnb TN 5 1



```
DATE
PAGE
DES
DES BARCLAYS1
TN 005 01
TYPE TIE
CDEN SD
CUST 0
TRK PRI
PDCA 1
PCML MU
NCOS 0
RTMB 105 1
B-CHANNEL SIGNALING
TGAR 0
AST NO
IAPG 0
CLS UNR DTN WTA LPR APN THFD HKD
    P10 VNL
TKID
AACR NO
DATE 10 APR 2007
NACT
Software Release
>LD 22
PT2000
REQ ISS
CALL SERVER/MAIN CAB
VERSION 2121
RELEASE 4
ISSUE 00 T +
IDLE_SET_DISPLAY NORTEL
```

Software package Installed (Succession 4.0)

OPTF	1
CUST	2
CDR	4
CTY	5
RAN	7
TAD	8
DNDI	9
EES	10
INTR	11
ANI	12
ANIR	13
BRTE	14
DNDG	16
MSB	17
SS25	18
DDSP	19
ODAS	20
DI	21
CHG	23
CAB	24
BAUT	25
CASM	26
CASR	27
BQUE	28
NTRF	29
NCOS	32
CPRK	33



SSC	34
IMS	35
UST	35
UMG	35
ROA	36
NSIG	37
MCBQ	38
NSC	39
BACD	40
	41
ACDB	
ACDC	42
TMAN	43
LMAN	
MUS	44
	4 -
ACDA	45
MWC	46
AAB	47
GRP	48
NFCR	49
LNK	51
FCA	52
SR	53
AA	54
HIST	55
AOP	56
BARS	57
NARS	58
CDP	59
PQUE	60
FCBO	61
~	
OHQ	62
NAUT	63
SNR	64
NXFR	67
HOT	70
DHLD	71
LSEL	72
SS5	73
DRNG	74
PBXI	75
DLDN	76
CSL	77
OOD	79
SCI	80
CCOS	81
CDRQ	83
TENS	86
FTDS	87
DSET	88
TSET	89
LNR	90
DLT2	91
PXLT	92
	93
SUPV	
CPND	95
DNIS	98
DNIS	
BGD	99
RMS	100
MR	101
	102
AWU	
PMSI	103
	105
LLC	
MCT	107
ICDR	108
APL	109
	110
TVS	
TOF	111
IDC	113
100	113



DCP	115
PAGT	116
CBC	117
	118
CCDR	
EMUS	119
PLDN	120
SCMP	121
FTC	125
BKI	127
DTI2	129
TBAR	132
ENS	133
FFC	139
DCON	140
MPO	141
ISDN	145
PRA	146
	147
ISL	
NTWK	148
IEC	149
DNXP	150
CDRE	151
FXS	152
IAP3P	153
PRI2	154
THF	157
FGD	158
NAS	159
FNP	160
ISDN_INTL_SUP	161
SAR	162
MINT	163
	164
LAPW	
GPRI	167
ARIE	170
CPGS	172
ECCS	173
AAA	174
NMS	175
EOVF	178
HVS	179
DKS	180
SACP	181
VNS	183
OVLP	184
EDRG	185
POVR	186
SECL	191
	192
ORC-RVQ	
AINS	200
IPRA	202
XPE	203
XCT0	204
XCT1	205
MLWU	206
HSE	208
MLM	209
MAID	210
VAWU	212
EAR	214
ECT	215
BRI	216
IVR	218
MWI	219
MSDL	222
FC68	223
SSAU	229



BRIT	233
FCDR	234
BRIL	235
MCMO	240
MULTI_USER	242
ALRM_FILTER	243
SYS_MSG_LKUP	245
VMBA	246
CALL_ID	247
DPNA	250
SCDR	251
ARFW	253
PHTN	254
ADMINSET	256
ATX	258
CDRX	259
QSIG	263
NI-2	291
IPEX	295
MAT	296
CPP	301
OSIGGF	305
CPRKNET	306
PAGENET	307
CPCI	310
TATO	312
OPEN_ALARM	315
OSIG-SS	316
NGEN	324
RANBRD	327
MUSBRD	328
ESA	329
ESA_SUPP	330
ESA_CLMP	331
CNUMB	332
CNAME	333
NI-2_CBC	334
MEET	348
MC32	350
DBA	351
FDID	362
NMCE	364
STS_MSG	380
CDIR	381
VIRTUAL_OFFICE	382
ATAN	384
NI2NAME	385
M3900_PROD_ENH	386
VIR_OFF_ENH	387
OAS	394
ICON	397
PCA	398
H323_VTRK	399
LOCX	400
PVQM	401
SIP	406

REQ



Acronyms

Acronym	Definitions
CAMA	Centralized Automatic Message Accounting
PSAP	Public Safety Answering Point
CER	Cisco Emergency Responder
CUCM	Cisco Unified Communications Manager



Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.





Corporate **Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 LISA

www.cisco.com Tel: 408 526-4000

800 553-NETS (6387) Fax: 408 526-4100

European **Headquarters**

Cisco Systems International

Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands

www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 LISA

www.cisco.com Tel: 408 526-7660

Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com Tel: +65 317 7777

Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

© 2007 Cisco Systems, Inc. All rights reserved.

CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0709R)

Printed in the USA