

Cisco 1-Port ISDN BRI U High-Speed WAN Interface Card

Product Overview

Cisco® integrated services routers offer a wide variety of WAN connectivity modules to accommodate the range of application needs in customer networks. The Cisco 1-Port BRI U High-Speed WAN Interface Card (HWIC, Figure 1) offers BRI-U-based WAN connectivity for modular routers deployed in small to medium-sized businesses (SMBs) and enterprise branch offices.

Figure 1. Cisco 1-Port BRI U interface High-Speed WAN Interface Card



Features

- One ISDN BRI port with U interface (built-in NT1)
- Utilizes an RJ-49C connector

Benefits

Integration

The Cisco 1-Port HWIC-1B-U offers a single ISDN BRI port with U interface. The ISDN HWIC is supported on the Cisco 1841, 1941, 2800, 2900, 3800 and 3900 Series Routers. It provides a cost-effective ISDN routing solution with the following benefits of integration:

- Fewer devices and cables to deploy and manage
- Remote and local configuration, monitoring, and troubleshooting with the Cisco IOS® Software command-line interface (CLI) and Simple Network Management Protocol (SNMP)
- Single-vendor support
- Enhanced reliability
- Physical space savings

Flexibility and Investment Protection

The Cisco 1-Port ISDN U interface HWIC upholds Cisco's commitment to providing customers with maximum flexibility and investment protection through modular HWICs that are supported on award-winning router platforms. When WAN bandwidth requirements or service provider pricing changes, users can easily change WAN services either by changing the software configuration or replacing the HWIC. Because the same card can be used on Cisco 1841, 2800, and 3800 Series router platforms, the number of stocking units can be reduced, and the HWIC can be redeployed from one platform to another.

Enhanced Reliability

An integrated solution has fewer components and hence, fewer points of failure (for example, one less power supply and fewer cables). This leads to enhanced reliability.

Converged Platform for SMB and Enterprise Branch Applications

The Cisco 1841, 1941, 2800, 3800, and 3900 Series Integrated Services Routers with the Cisco 1-Port ISDN U interface HWIC provide customers with a choice of converged platforms that offer best-of-class data, security, WAN access, and voice services in a single system. The Cisco 2800 and 3800 Series routers and the Cisco 2900 and 3900 Series Routers embed voice functions directly inside the router, enabling customers to deploy voice services by installing digital signal processors (DSPs) and advanced integration modules (AIMs) for IP telephony conferencing, voice gateways, and Cisco Unity® Express voicemail and automated attendant. For call processing, customers can enable the Cisco Communications Manager Express solution as part of Cisco IOS Software and reconfigure the same software to support Cisco Survivable Remote Site Telephony (SRST) for centralized call processing with Cisco Communications Manager. Such an integrated solution enables rapid service deployment, increases efficiency of network operations, and provides opportunities to protect, grow, and optimize your business.

Shared Features with Cisco 1-Port ISDN WIC

The Cisco 1-Port ISDN U interface HWIC offers all of the features of the Cisco 1-Port ISDN U interface WIC (WIC-1B-U-V2) and can be smoothly deployed without any additional training.

Table 1. Comparison Between WIC and HWIC

Cisco 1-Port ISDN WIC	Cisco 1-Port ISDN HWIC
One ISDN BRI port (U interface, integrated NT1)	One ISDN BRI port (U interface, integrated NT1)
Supported on Cisco 1841, 2800, and 3800 Series	Supported on Cisco 1841, 2800, 3800, 1941, 2900, and 3900 Series
Supported in NM-1FE2W-V2, NM-1FE1R2W, NM-2FE2W-V2, and NM-2W	Supported in NM-1FE2W-V2, NM-1FE1R2W, NM-2FE2W-V2, and NM-2W

Product Specifications

Platform Support

Table 2 lists the routing platforms that support the Cisco 1-Port ISDN HWIC and WIC.

Table 2. Platform Support Details

Feature	Description
Supporting Platforms	1841 (HWIC), 2801 (WIC/HWIC), 2811 (HWIC), 2821 (HWIC), 2851 (HWIC), 3825 (HWIC), 3845 (HWIC), 1941(HWIC), 2901(HWIC), 2911 (HWIC), 2921 (HWIC), 2951 (HWIC), 3925 (HWIC), 3945 (HWIC)

Table 3 gives the maximum number of Cisco 1-Port ISDN HWICs per platform.

Table 3. Maximum Number of HWICs per Platform

Platform	Maximum Number of HWICs
Cisco 1841 and 2801	2
Cisco 1941 and 2901	2
Cisco 2811, 2821, 2851	4
Cisco 2911, 2921, 2951	4
Cisco 3825 and 3845	4
Cisco 3925 and 3945	4

Software Requirements

Table 4 gives the minimum Cisco IOS Software release required for the supporting platforms.

Table 4. Minimum Cisco IOS Software Release

Platform	Minimum Cisco IOS Software Release	Cisco IOS Software Feature Set or Licenses
Cisco 1841, 2801, 2811, 2821, 2851, 3825, and 3845	12.4(16) and 12.4(20)T	IP Base and Up
Cisco 1941, 2901, 2911, 2921, 2951, 3925, and 3945	15.0(1)M	IP Base and up

Ordering Information

Table 5 gives product ordering information for the Cisco 1-Port ISDN HWIC, and Table 6 lists hardware specifications.

Table 5. Ordering Information

Product Number	Description
HWIC-1B-U	1-Port ISDN BRI U interface High-Speed WAN Interface Card

Hardware Specifications

Table 6. Hardware Specifications

Feature	Cisco 1-Port ISDN HWIC
ISDN Chipset	Infineon
Dimensions	<ul style="list-style-type: none"> • Width: 2.80 inches • Depth: 4.75 inches • Height: 0.75 inches
Weight	0.45 lbs
LEDs	<ul style="list-style-type: none"> • B1 and B2 for ISDN channel status • NT1 for connection status
Ports	Single RJ-49C port

Safety, EMC, Telecom, Network Homologation, Power, Environmental Requirements, and Regulatory Approvals

When installed in a Cisco 1841, 2800, or 3800 Series Integrated Services Router, the Cisco 1-Port ISDN HWIC does not change the standards (safety, EMC, telecom, network homologation, power, environmental requirements, and regulatory approvals) of the router itself. Refer to the following data sheets for additional information about mechanical, environmental, and agency certifications.

- Cisco 1800 Series (modular):
http://www.cisco.com/en/US/products/ps5853/products_data_sheet0900aec8016a59b.html
- Cisco 2800 Series:
http://www.cisco.com/en/US/products/ps5854/products_data_sheet0900aec8016fa68.html
- Cisco 3800 Series:
http://www.cisco.com/en/US/products/ps5855/products_data_sheet0900aec8016a8e8.html
- Cisco 1900 Series (modular): <http://www.cisco.com/en/US/products/ps10538/index.html>
- Cisco 2900 Series: <http://www.cisco.com/en/US/products/ps10537/index.html>
- Cisco 3900 Series: <http://www.cisco.com/en/US/products/ps10536/index.html>

Country Support

Contact your local Cisco representative for country-specific approval status, or visit:

http://tools.cisco.com/cse/prdapp/jsp/externalsearch.do?action=externalsearch&page=EXTERNAL_SEARCH

Cisco and Partner Services for the Branch

Services from Cisco and our certified partners can help you transform the branch experience and accelerate business innovation and growth in the Borderless Network. We have the depth and breadth of expertise to create a clear, replicable, optimized branch footprint across technologies. Planning and design services align technology with business goals and can increase the accuracy, speed, and efficiency of deployment. Technical services help improve operational efficiency, save money, and mitigate risk. Optimization services are designed to continuously improve performance and help your team succeed with new technologies. For more information, visit

<http://www.cisco.com/go/services>.

For More Information

For more information about the Cisco 1-Port BRI U interface High-Speed WAN Interface Card, visit <http://www.cisco.com> or contact your local account representative.

For more information about Cisco products, contact:

- United States and Canada: 800 553-NETS (6387)
- Europe: +32 2 778 4242
- Australia: +61 2 9935 4107
- Other: 408 526-7209
- Web: <http://www.cisco.com>



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, CCSI, Cisco Eos, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco Nurse Connect, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flip Video, Flip Video (Design), Flipshare (Design), Flip Ultra, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Store, and Flip Gift Card are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0907R)