



New and Changed Information for this Release

- [New and Changed Information for this Release, on page 1](#)

New and Changed Information for this Release

The following table provides an overview of the significant changes to this guide for this current release. The table does not provide an exhaustive list of all changes made to this guide or of all new features in this release.

Table 1: New Features and Changed Behavior in Cisco HX Data Platform

Feature	Description	Release	Where Documented
HyperFlex Software Versions table	Updated Recommended FI/Server Firmware to UCSM 4.0(4i) for HX 3.5(2g) and HX 3.5(2h) releases.	September 4, 2020	Recommended FI/Server Firmware - 3.5(x) Releases
HyperFlex Software Versions table	Added USCM 4.1(2a) as qualified for HX 3.5(2h)	August 11, 2020	Recommended FI/Server Firmware - 3.5(x) Releases
HyperFlex Software Versions table	Added qualification for Cisco UCS Manager 4.0(4i) and 4.1(1d) for HX 3.5(2g).	July 23, 2020	Recommended FI/Server Firmware - 3.5(x) Releases
Host Upgrade Utility (HUU)	Updated Host Upgrade Utility (HUU) for M5 to UCS 4.0(4k) for HX 3.5(2h).	May 4, 2020	HyperFlex Edge and Firmware Compatibility Matrix for 3.x Deployments
Issued Software Deferral Notice for CSCvp90129	Cisco HyperFlex Data Platform releases 3.5(2c) is no longer available for download.	January 14, 2020	HyperFlex Deferred Releases

Feature	Description	Release	Where Documented
Software Versions for HyperFlex Witness Node	Required Witness VM upgrade to version 1.06 for stretch cluster in in 3.5.2f	3.5(2f)	HX Data Platform Software Versions for HyperFlex Witness Node for Stretched Cluster - 3.5(x) Releases
ESXi 6.7 U2 Support	Provides support for upgrading HyperFlex clusters to VMware vSphere Hypervisor (ESXi) 6.7 U2.	3.5(2c)	Recommended FI/Server Firmware - 3.5(x) Releases
ESXi 6.7 U1 Support	Provides support for upgrading HyperFlex clusters to VMware vSphere Hypervisor (ESXi) 6.7 U1.	3.5(2a)	Recommended FI/Server Firmware - 3.5(x) Releases