

## **Caveats in Cisco IOS XE Release 3.18.9SP**

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The "Open Caveats" sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The "Resolved Caveats" sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note

The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Open Caveats Cisco IOS XE Release 3.18.9SP, on page 1
- Resolved Caveats Cisco IOS XE Release 3.18.9SP, on page 1

## **Open Caveats – Cisco IOS XE Release 3.18.9SP**

There are no open caveats in this release.

## Resolved Caveats — Cisco IOS XE Release 3.18.9SP

Caveat ID Number	Description
CSCvu78801	PPPoE VSA tags get overwritten at each PPPoE IA

Resolved Caveats – Cisco IOS XE Release 3.18.9SP