



## New and Changed Information

This chapter provides release-specific information for each new and changed feature in the *Cisco Nexus 9000 Series NX-OS Troubleshooting Guide, Release 6.x*.

- [New and Changed Information, on page 1](#)

## New and Changed Information

This table summarizes the new and changed features for the *Cisco Nexus 9000 Series NX-OS Troubleshooting Guide, Release 6.x* and tells you where they are documented.

**Table 1: New and Changed Features for Cisco NX-OS Release 6.x**

Feature	Description	Changed in Release	Where Documented
Private VLANs (PVLANS)	Introduced this feature.	6.1(2)I3(4)	<a href="#">Troubleshooting VLANs</a>
Traceroute	Added source interface support.	6.1(2)I3(3)	<a href="#">Troubleshooting Tools and Methodology</a>
Policy-based routing	Introduced this feature.	6.1(2)I3(1)	<a href="#">Troubleshooting Routing</a>
Consistency checker commands	Added commands for Layer 2 and VLANs.	6.1(2)I2(1)	<a href="#">Consistency Checker Commands</a>
DCNM	Introduced this feature.	6.1(2)I2(1)	<a href="#">Before Contacting Technical Support</a>
Layer 2	Added support for Layer 2 connectivity.	6.1(2)I2(1)	<a href="#">Overview</a>
Software upgrades	Added support for software upgrades.	6.1(2)I2(1)	<a href="#">Troubleshooting Installations, Upgrades, and Reboots</a>
Spanning Tree Protocol	Introduced this feature.	6.1(2)I2(1)	<a href="#">Troubleshooting STP</a>
Trunk ports	Introduced this feature.	6.1(2)I2(1)	<a href="#">Overview</a>

<b>Feature</b>	<b>Description</b>	<b>Changed in Release</b>	<b>Where Documented</b>
VLANs	Introduced this feature.	6.1(2)I2(1)	<a href="#">Troubleshooting VLANs</a>
vPCs	Introduced this feature.	6.1(2)I2(1)	<a href="#">Troubleshooting vPCs</a>