

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(3)

First Published: 2024-06-11

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(3)

These release notes support the Cisco Wireless Phone 840 and 860 software release 1.10(3). These wireless smartphones require:

- **Call Control**
 - Cisco Unified Communications Manager
 - Minimum: 11.5(1)
 - Recommended: 12.5(1), 14.0(1), or higher
 - Webex Calling
- **Wireless LAN Controller and Access Points**
 - See the [Cisco Wireless Phone 840 and 860 Deployment Guide](#) for supported solutions.

What's New in This Release?

The following sections describe the features that are new or have changed in this release.

Answer and end calls using the hardware buttons

You can answer and disconnect the calls by pressing the hardware buttons instead of using the on-screen controls.



Note By default, this feature doesn't come enabled. So, you have to turn it on manually using the Buttons application.

Turn ON and OFF flashlight using the hardware buttons

You can turn ON and OFF the flashlight by pressing the hardware buttons.

Where to Find More Information

Cisco Wireless Phone 840 and 860 User Guide

Cisco Wireless Phone 840 and 860 Administration Guide for Cisco Unified Communications Manager

Installation

Refer to the following documents for installation instructions.

840 - <https://www.cisco.com/web/software/282074288/168506/cmterm-840.1-10-3-2587-88918-readme.html>

860 - <https://www.cisco.com/web/software/282074288/168506/cmterm-860.1-10-3-2975-88918-readme.html>

Open Bugs

Bug number	Description
CSCwc20252	860-840 Bluetooth Pairing Mode Confusion vulnerability.

Resolved Bugs

Bug number	Description
CSCwj42171	Stuttering and audio packet drop every few seconds with Informacast.

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- View [All Caveats](#)
- View [Open Caveats](#)
- View [Resolved Caveats](#)

Americas Headquarters

Cisco Systems, Inc.
San Jose, CA

Asia pacific Headquarters

Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters

Cisco Systems International BV
Amsterdam,
The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

