

New and Changed Information

• New and Changed Information, on page 1

New and Changed Information

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(4a).

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(4a)

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect supports 16 unified ports.	With release 4.0(4n) and later Cisco UCS 6454 Fabric Interconnect supports 16 unified ports (ports 1 - 16).	Cisco UCS 6454 Fabric Interconnect Overview
Cisco UCS-IOM-2304V2 I/O module	introduces the Cisco UCS-IOM-2304V2 I/O module which is based on Cisco UCS-IOM-2304 I/O module.	I/O Module Management in Cisco UCS Manager CLI

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(2a).

Table 2: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(2a)

Feature	Description	Where Documented
Breakout Uplink Ports	Cisco UCS Manager Release 4.0(2) and later releases support splitting a single 40/100G QSFP port into four 10/25G ports using a supported breakout cable. These ports can be used only as Ethernet uplink or FCoE uplink ports connecting to a 10/25G switch. They cannot be configured as server ports, FCoE storage ports, appliance ports or monitoring ports.	•

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(1a).

Table 3: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(1a)

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect	This release introduces Cisco UCS 6454 Fabric Interconnect that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	Cisco UCS 6454 Fabric Interconnect Overview
Cisco UCS VIC 1455	In Cisco UCS Manager Release 4.0(1a), Cisco UCS VIC 1455 are supported.	Port-Channeling
Cisco UCS C125 M5 Server	Cisco UCS Manager extends support for all existing features on Cisco UCS C125 M5 Server.	Rack-Enclosure Server Management