

FIELD NOTICE: END-OF-SALE FOR PCMCIA 16-MB FLASH MEMORY FOR CISCO 7200 SERIES ROUTER

RATIONALE

With the introduction of 40-MB and 110-MB Flash Disk Personal Computer Memory Card Industry Association (PCMCIA) Memory, Cisco® announces End-of-Sale of 16-MB PCMCIA Flash memory. The Cisco I/O PCMCIA 20-MB Flash memory has been price-reduced so that end customers receive more memory for the same price. 40-MB and 110-MB Flash disk PCMCIA memory is also available. To streamline Cisco 7200 Series product options, the PCMCIA 16-MB Flash will no longer be a configurable option as of January 31, 2000.

PRODUCTS AFFECTED

| Product Number | Description | Last Sale Date | Substitutes |
|-----------------|--|----------------|----------------|
| MEM-I/O-FLC8M= | Cisco 7200 I/O PCMCIA Flash Memory, 8 MB | 1/31/2000 | MEM-I/O-FLC20M |
| MEM-I/O-FLC16M | Cisco 7200 I/O PCMCIA Flash Memory, 16-MB Option | 1/31/2000 | MEM-I/O-FLC20M |
| MEM-I/O-FLC16M= | Cisco 7200 I/O PCMCIA Flash Memory, 16 MB | 1/31/2000 | MEM-I/O-FLC20M |

Prices have changed for the Cisco 7200 I/O PCMCIA Flash Memory, 20-MB option (MEM-I/O-FLC20M and MEM-I/O-FLC20M=). Please contact your account representative for complete details.

SUBSTITUTES

| Bundle | Description |
|-------------------|---|
| CISCO7204VXR/100 | 7204VXR Bundle with NPE 100 and I/O Controller with Fast Ethernet. |
| CISCO7204VXR/175 | 7204VXR Bundle with NPE 175 and I/O Controller without Fast Ethernet. |
| CISCO7204VXR/200 | 7204VXR Bundle with NPE 200 and I/O Controller with Fast Ethernet. |
| CISCO7204VXR/225 | 7204VXR Bundle with NPE 225 and I/O Controller without Fast Ethernet. |
| CISCO7204VXR/1C-E | 7204VXR Bundle with NPE 175 and ESCON Port Adapter. |
| CISCO7206/200 | 7206 Bundle with NPE 200 and I/O Controller with Fast Ethernet. |
| CISCO7206VXR/225 | 7206VXR Bundle with NPE 225 and I/O Controller with Fast Ethernet. |
| CISCO7206VXR/300 | 7206VXR Bundle with NPE 300 and I/O Controller with Fast Ethernet. |

For the NPE-100, NPE-150, and NPE-200, PCMCIA 16-MB Flash memory can be replaced with:

| Product Number | Description |
|----------------|---|
| MEM-I/O-FLC20M | Cisco 7200 I/O PCMCIA Flash Memory, 20 MB |

For the NPE-175, NPE-225, and NPE-300, PCMCIA 16MB Flash memory can be replaced with:

| Product Number | Description |
|-----------------|--|
| MEM-I/O-FLC20M | Cisco 7200 I/O PCMCIA Flash Memory, 20 MB |
| MEM-I/O-FLD40M | Cisco 7200 I/O PCMCIA Flash Memory, 40 MB |
| MEM-I/O-FLD110M | Cisco 7200 I/O PCMCIA Flash Memory, 110 MB |

FOR MORE INFORMATION

If you require further assistance, or if you have any further questions regarding this field notice, please contact the Cisco Systems Technical Assistance Center (TAC) at: https://www.cisco.com/c/dam/en_us/buy/cs-info/downloads/commarch/html/reference-guides/module09-tac.pdf



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the [Cisco Website at www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05