

END-OF-LIFE NOTICE, NO. 1061

ADDENDUM IN REFERENCE TO ORIGINAL END-OF-SALE NOTICE FOR NPE-100, NPE-150, AND CISCO 7204 SERIES ROUTER

Addendum Date	August 27, 2004
Effective Date	September 1, 2004
Original Bulletin Information	Product Bulletin, No. 1061

The End-of-Sale date for Cisco[®] 7200 Network Processing Engines NPE-100 and NPE-150 as well as Cisco 7204 Series Router was April 30, 2000. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until April 30, 2005. Table 1 describes the end-of-life milestones, definitions, and dates for the NPE-100, NPE-150, and Cisco 7204 Series Router. Table 2 lists the product numbers affected by this announcement and replacement product information. This notice is an addendum to the original end-of-sale and end-of-life bulletin for NPE-100, NPE-150, and Cisco 7204 Series Router.

The End of Software Support for NPE-100, NPE-150, and Cisco 7204 Series Router is as follows:

- Software Support ends in 12.1(14)E, 12.2(24), 12.0(27)S, and 12.2(15)T
- Bug fixes will be provided for 36 months after EOS date (April 30, 2000)
- Last date to receive support from the Cisco TAC is April 30, 2005

Table 1.	End-of-Life Milestones and Dates for NPE-100, NPE-150, and Cisco 7204 Series Router	
----------	---	--

Milestone	Definition	Date
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 30, 2000
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	July 30, 2000
End of software maintenance releases date	The last date that Cisco Engineering may release any software maintenance releases or bug fixes to the software product. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. The last software releases supported include Cisco IOS [®] Software releases 12.2(24), 12.2(15)T, 12.0(27)S, 12.1(14)E.	12.0(27)S: April 30, 2003 12.1(14)E: April 30, 2003 12.2(15)T: April 30, 2003 12.2(24): April 30, 2003
End of service contract renewal	The last date to extend or renew a service contract. The extension or renewal period cannot extend beyond the last date of support.	April 30, 2004
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2005

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
NPE-100	Cisco 7200 Series Network Processing Engine 100	NPE-400 or NPE-G1	7200VXR NPE-400 or
			7200 Network Processing Engine with 3 GE/FE/E ports
NPE-100=	Cisco 7200 Series Network Processing Engine 100 (Spare)	NPE-400= or NPE-G1=	7200VXR NPE-400, SPARE or
			7200 Network Processing Engine with 3 GE/FE/E ports (Spare)
NPE-150	Cisco 7200 Series Network Processing Engine 150	NPE-400 or NPE-G1	7200VXR NPE-400 or
			7200 Network Processing Engine with 3 GE/FE/E ports
NPE-150=	Cisco 7200 Series Network Processing Engine 150 (Spare)	NPE-400= or NPE-G1=	7200VXR NPE-400, SPARE or
			7200 Network Processing Engine with 3 GE/FE/E ports (Spare)
CISCO7204	Cisco 7204, 4-Slot Chassis, 1 AC Supply with IP Software	CISCO7204VXR	Cisco 7204VXR, 4-slot chassis, 1 AC Supply with IP Software
CISCO7204=	4 Slot Chassis with AC Power Supply (Spare)	CISCO7204VXR=	7204VXR, 4-slot chassis, 1 AC Supply, Spare (without IP SW)
CISCO7204-CH	Cisco 7204 Modular Router, 4 Slots, AC Power		
CISCO7204/150	7204 Bundle with NPE-150 and I/O Controller W/O FE		

Table 2. Product Part Numbers Affected by This Announcement

PRODUCT MIGRATION OPTIONS

The recommended replacement for NPE-100 and NPE-150 is the NPE-400 or NPE-G1. The recommended replacement for Cisco 7204 Series Router is Cisco 7204VXR Series Router. Please note that NPE-400 and NPE-G1 require a Cisco 7200VXR chassis. More information about the NPE-400, NPE-G1, and Cisco 7204VXR Series Router can be found at:

http://www.cisco.com/en/US/products/hw/routers/ps341/products_data_sheet09186a00800ae715.html

http://www.cisco.com/en/US/products/hw/routers/ps341/products_data_sheet09186a00800c6bd6.html

http://www.cisco.com/en/US/products/hw/routers/ps341/ps347/index.html

Customers can use the Cisco Technology Migration Program (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <u>http://www.cisco.com/go/tradein</u>. The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive EOL/EOS information please go to: <u>http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice</u>.



Corporate Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100

European Headquarters

Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United .States. or certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0406R) De/LW7392 11/04