

# End-of-Sale and End-of-Life Announcement for the Cisco Announcement of 896 and 897 VDSL<sub>2</sub>/ADSL<sub>2</sub>+ Routers

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	4
For more information	5

## Overview

### EOL12789 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco End-of-Sale and End-of-Life Announcement of 896 and 897 VDSL2/ADSL2+ Routers. The last day to order the affected product(s) is July 29, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco End-of-Sale and End-of-Life Announcement of 896 and 897 VDSL2/ADSL2+ Routers

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 1, 2018
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 29, 2019
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 27, 2019
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 28, 2020
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	July 28, 2022
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	July 28, 2020
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 28, 2020
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 24, 2023
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 31, 2024

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-sale product part number	Product description	Replacement product part number	Replacement product description	Additional information
C896VA-K9	Cisco 896 VDSL2/ADSL2+ over ISDN and 1GE/SFP Sec Router	C1112-8P	ISR 1100 G.FAST with GE SFP Ethernet Router	-
C896VA-K9	Cisco 896 VDSL2/ADSL2+ over ISDN and 1GE/SFP Sec Router	C1116-4P	ISR 1100 4 Ports DSL Annex B/J and GE WAN Router	-
C897VA-K9	Cisco 897 VDSL2/ADSL2+ over POTs and 1GE/SFP Sec Router	C1113-8P	ISR 1100 G.FAST GE SFP Ethernet Router	-
C897VA-K9	Cisco 897 VDSL2/ADSL2+ over POTs and 1GE/SFP Sec Router	C1117-4P	ISR 1100 4 Ports DSL Annex A/M and GE WAN Router	-
C897VA-M-K9	Cisco 897 Annex M over POTs and 1GE/SFP Sec Router	C1113-8PM	ISR 1100 G.FAST GE SFP Ethernet Router	-
C897VA-M-K9	Cisco 897 Annex M over POTs and 1GE/SFP Sec Router	C1117-4PM	ISR 1100 4 Ports DSL Annex M and GE WAN Router	-

## Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at: [https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

---

Customers may be able to continue to purchase the Cisco End-of-Sale and End-of-Life Announcement of 896 and 897 VDSL2/ADSL2+ Routers through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: [https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For more information

For more information about the Cisco End-of-Life Policy, go to: [https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to: [https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)