#### **Contents**

Introduction
Background Information
TAC Analysis and Recommendation
Related Information

#### Introduction

This document describes how to overcome when no netflow data and application statistics are shown as **MACE** is not enabled on ISR 2951.

# **Background Information**

There is no Netflow data and application statistics shown for few of our devices.

For example:

Product: Cisco 2951 Integrated Services Router G2 Version: 15.1(4)M4

following cisco recommended way of configuring net flow for ISR Devices -

http://www.cisco.com/c/en/us/td/docs/net\_mgmt/prime/infrastructure/3-0/user/guide/pi\_ug/setup\_monitor.html#77453

Trying to enable AVC / MACE on 2900 ISR , mace command is not available, following G2 configuration

# **TAC Analysis and Recommendation**

Evaluation license for datak9 package that needs to be applied on the router as it is not in use at this time.

```
Index: 5 Feature: datak9 Version: 1.0

License Type: EvalRightToUse

License State: Active, Not in Use, EULA not accepted

Evaluation total period: 8 weeks 4 days

Evaluation period left: 8 weeks 4 days

Period used: 0 minute 0 second

License Count: Non-Counted

License Priority: None

Store Index: 2
```

```
Store Name: Built-In License Storage
```

To apply it, accept the End User License agreement (EULA) using this command and then change the boot level to datak9 and reload the router:

```
Router(config) # license accept end user agreement

Router(config) # license boot module c2900 technology-package datak9

After enabling the datak9, you can see the flows.
```

how do we make evaluation license as permanent > It will automatically be permanent after time period stated under the feature.

### **Related Information**

- <a href="http://www.cisco.com/en/US/docs/routers/access/sw\_activation/SA\_on\_ISR.html">http://www.cisco.com/en/US/docs/routers/access/sw\_activation/SA\_on\_ISR.html</a>
- Technical Support & Documentation Cisco Systems