



Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.9(0)SR1

First Published: 2023-05-16

Last Modified: 2023-05-19

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.9(0)SR1

What's new in this release

The following sections describe the features that are new or have changed in this release.

Enhancement to allow toggling Managed Home Screen mode for WebAPI App to enable direct url opening

When the phone is managed by an Enterprise Mobility Management (EMM) application, it allows you to perform the following functions:

- Short tap the Web API application icon to open the first configured URL.
- Long tap the Web API application icon to open the configuration menu for the Web API application.

Installation

Refer to the following documents for installation instructions.

840 - <https://www.cisco.com/web/software/282074288/164917/cmterm-840.1-9-0-1914-68532-readme.html>

860 - <https://www.cisco.com/web/software/282074288/164917/cmterm-860.1-9-0-2409-68532-readme.html>

Open bugs

Bug number	Description
CSCwc20252	860–840 Bluetooth Pairing Mode Confusion vulnerability.
CSCwd73349	Conference not recorded when user creates a conference with a call on hold.
CSCwe57179	Phone didn't re-register to Webex Calling after network outage and initial reconnect attempt failed.
CSCwf19802	840 sometimes does not process reassociation response resulting in a fast roam failure.

Resolved bugs

Bug number	Description
CSCwf21210	840/860 phones are not downloading custom ringtones, notification or alarm sounds, or wallpaper.
CSCwe98811	WebAPI Widget on 840 and 860 phones goes into "loading icons" state.

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- View [All Caveats](#)
- View [Open Caveats](#)
- View [Resolved Caveats](#)

Americas Headquarters

Cisco Systems, Inc.
San Jose, CA

Asia pacific Headquarters

Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters

Cisco Systems International BV
Amsterdam,
The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

