



## End-of-Sale and End-of-Life Announcement for the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards

Cisco Systems® announces the end-of-sale and end-of-life dates for the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards. The last day to order the affected product is September 25, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 in EoL product bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards. Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 25, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 25, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 25, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	September 24, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 24, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	December 24, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 23, 2012

HW = Hardware OS SW = Operating System Software App SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement


End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
15310-CE-100T-8	15310-CL 8-port 10/100 Ethernet L1 only	15310-P-CE-100T-8	15310 8-port 10/100 Ethernet L1 only
15310-CE-100T-8=	15310-CL 8-port 10/100 Ethernet L1 only	15310-P-CE-100T-8=	15310 8-port 10/100 Ethernet L1 only
15310-ML-100T-8	15310-CL ML series 10/100 Ethernet	15310-P-ML-100T-8	15310 ML series 10/100 Ethernet
15310-ML-100T-8=	15310-CL ML series 10/100 Ethernet	15310-P-ML-100T-8=	15310 ML series 10/100 Ethernet

### PRODUCT MIGRATION OPTIONS

The recommended replacement for the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards is the Cisco ONS 15310 CE Series and ML Series Cards compatible with CL and MA Platforms.

Customers are encouraged to migrate to the ONS 15310 platform CE Series and ML Series cards that are compatible with both Cisco ONS 15310 CL and MA platforms. Information about this product can be found at:

[http://www.cisco.com/en/US/prod/collateral/optical/ps5726/ps2001/ps5977/product\\_data\\_sheet0900aecd801ba81c.html](http://www.cisco.com/en/US/prod/collateral/optical/ps5726/ps2001/ps5977/product_data_sheet0900aecd801ba81c.html) and [http://www.cisco.com/en/US/prod/collateral/optical/ps5726/ps2001/ps5977/product\\_data\\_sheet0900aecd801ba822.html](http://www.cisco.com/en/US/prod/collateral/optical/ps5726/ps2001/ps5977/product_data_sheet0900aecd801ba822.html).



Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:  
[http://www.cisco.com/web/ordering/ciscocapital/or6/or17/order\\_refurbished\\_equipment\\_high\\_level\\_listing.html](http://www.cisco.com/web/ordering/ciscocapital/or6/or17/order_refurbished_equipment_high_level_listing.html).

#### **FOR MORE INFORMATION**

For more information about the Initial Version of Cisco ONS 15310 CE Series and ML Series Cards, visit [http://www.cisco.com/en/US/products/hw/optical/ps2001/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/hw/optical/ps2001/prod_eol_notices_list.html) or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Corporate Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco.com Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic  
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy  
Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in USA

CS1-364280-00 09/06