



## End-of-Sale and End-of-Life announcement for the Legacy Cisco MGX Frame and Circuit Emulation Service Modules and 4-Port 155-MBPS Back Card

Cisco Systems® announces the end-of-sale and end-of life dates for the Legacy Cisco MGX Frame and Circuit Emulation Service Modules and 4-Port 155-Mbps Back Card. The last day to order the affected product is May 31, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 31, 2011. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco MGX Multiprotocol Service Modules or the newer back cards (/C version), as appropriate. Table 2 provides relevant information for migrating to the replacement product.

**Table 1.** End-of-Life Milestones and Dates for the Legacy Cisco MGX Frame and Circuit Emulation Service Modules and 4-Port 155-Mbps Back Card.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 30, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 31, 2006
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 31, 2009
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 31, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 31, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	August 31, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 31, 2011

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
AX-FRSM-8T1	Frame Service Module, Eight Fractional T1 Ports	MPSM-8-T1E1	Multiprotocol Service Module—8 T1/E1 Ports
AX-FRSM-8T1=	Frame Service Module, Eight Fractional T1 Ports	MPSM-8-T1E1=	Multiprotocol Service Module—8 T1/E1 Ports
MGX-CESM-T3E3	Circuit Emulation Service Module, One T3 or E3 Port	There is currently no replacement product available for this product.	
MGX-CESM-T3E3=	Circuit Emulation Service Module, One T3 or E3 Port	There is currently no replacement product available for this product.	
MGX-SMFLR-4-155/B	PXM1 4 port 155 Mbps Back Card, SMF-LR, SC connectors	MGX-SMFLR-4-155/C	4 OC-3c/STM-1c single height BC, SMFLR, SC
MGX-SMFLR-4-155/B=	PXM1 4 port 155 Mbps Back Card, SMF-LR, SC connectors	MGX-SMFLR-4-155/C=	4 OC-3c/STM-1c single height BC, SMFLR, SC

## PRODUCT MIGRATION OPTIONS

The recommended replacement for the Legacy Cisco MGX Frame and Circuit Emulation Service Modules and 4-Port 155-Mbps Back Card is the Cisco MGX Multiprotocol Service Module and Newer Back Card (/C Version).

Information about the replacement products can be found at:

[http://www.cisco.com/en/US/products/hw/switches/ps1938/products\\_data\\_sheets\\_list.html](http://www.cisco.com/en/US/products/hw/switches/ps1938/products_data_sheets_list.html)

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: [http://www.cisco.com/en/US/ordering/or6/or17/order\\_refurbished\\_equipment\\_program\\_description.html](http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html)

## FOR MORE INFORMATION

For more information about the Legacy Cisco MGX Frame and Circuit Emulation Service Modules and 4-Port 155-Mbps Back Card, visit [http://www.cisco.com/en/US/products/hw/switches/ps1925/prod\\_eol\\_notices\\_list.html](http://www.cisco.com/en/US/products/hw/switches/ps1925/prod_eol_notices_list.html), or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel  
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

