

End-of-Sale and End-of-Life Announcement for the Cisco Catalyst 3750G-16TD Switch

EOL5459

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco Catalyst 3750G-16TD Switch. The last day to order the Cisco Catalyst 3750G-16TD Switch is October 15, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Catalyst 3750G-16TD Switch. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Cisco Catalyst 3750G-16TD Switch.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 16, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 15, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 13, 2008
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	October 14, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 14, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	January 10, 2012
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 13, 2012

HW = Hardware
OS SW = Operating System Software App.
SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WS-C3750G-16TD-E	Catalyst 3750 16 10/100/1000BT+ 10GbE (req XENPAK) Enh Image	WS-C3750E-24TD-E	Catalyst 3750E 24 10/100/1000+2*10GE(X2), 265W,IPS s/w
WS-C3750G-16TD-S	Catalyst 3750 16 10/100/1000BT+ 10GbE (req XENPAK) Std Image	WS-C3750E-24TD-S	Catalyst 3750E 24 10/100/1000+2*10GE(X2), 265W,IPB s/w

Product Migration Options

The recommended replacement for the affected Cisco Catalyst 3750G-16TD Switch is the Cisco Catalyst 3750E-24TD Switch. The Cisco Catalyst 3750-E Series Switches with StackWise Plus is an enterprise-class line of stackable wiring closet switches that facilitates the deployment of secure converged applications while maximizing investment protection for evolving network and application requirements. Combining 10/100/1000 and Power over Ethernet (PoE) configurations with upgradeable one GbE to 10 GbE uplinks, the Cisco Catalyst 3750-E Series enhances worker productivity by enabling applications such as IP telephony and video.

Cisco Catalyst 3750-E Series primary features:

- Cisco TwinGig converter module for migrating uplinks from Gigabit Ethernet to 10 Gigabit Ethernet
- PoE configurations with up to 15.4W of PoE on all 48 ports
- StackWise Plus for ease of use and resiliency with 64 Gbps of throughput
- Modular power supply with externally available backup
- Multicast routing, IPv6 routing, and access control list in hardware
- Out-of-band Ethernet management port along with RS-232 console port

For more information about the Catalyst 3750E-24TD switch, please go to:

http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps7077/product_data_sheet0900aecd805bbe67.html

Table 3. Product Comparisons

Feature	Cisco Catalyst 3750G-16TD Switch	Cisco Catalyst 3750E-24TD Switch
Ports	16 Ethernet 10/100/1000 ports and 1 Xenpak 10 Gigabit Ethernet uplink	24 Ethernet 10/100/1000 ports and 2 X2 10 Gigabit Ethernet uplinks
TwinGig converter module	No	Yes
Stacking Capacity	32 Gig with StackWise	64 Gig with StackWise Plus
Ethernet management port	No	Yes
Modular Power Supply and Fan	No	Yes
Local Switching	No	Yes
Unicast RPF	No	Yes
DRAM / FLASH	128 MB / 16 MB	256 MB / 64 MB
DC Power Supply	No	Yes, 265WDC
Jumbo Routing	No	Yes

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html

For More Information

For more information about the Cisco Catalyst 3750E-24TD Switch, visit

http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps7077/product_data_sheet0900aecd805bbe67.html, contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the IQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0701R)