

AVAYA Definity G3 Release CM 2.0 using T1 QSIG to Cisco Unified Communications Manager 5.1.2 and Cisco Emergency Responder 2.0.

Disclaimer

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS DOCUMENT ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS DOCUMENT ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE CUSTOMER ASSUMES ALL RESPONSIBILITY FOR PROPERLY CONFIGURING THE CISCO EMERGENCY RESPONDER. CISCO HEREBY DISCLAIMS ANY AND ALL LIABILITY ARISING FROM OR IN CONNECTION WITH A USERS INABILITY TO REACH EMERGENCY SERVICE RESPONDERS (INCLUDING INABILITY TO ACCESS A PUBLIC SAFETY ANSWERING POINT) OR THE INABILITY OF EMERGENCY SERVICE RESPONDERS TO IDENTIFY A USERS LOCATION. CISCO STRONGLY RECOMMENDS THAT ALL CUSTOMERS VERIFY AND TEST CONFIGURATION OF THE CISCO EMERGENCY RESPONDER IMMEDIATELY FOLLOWING INITIAL CONFIGURATION AND ON A PERIODIC BASIS THEREAFTER. CISCO FURTHER RECOMMENDS THAT ALL CUSTOMERS PROVIDE ADEQUATE TRUNK AND BANDWIDTH CAPACITY TO ENSURE THAT AUDIO PATHS ARE AVAILABLE FOR EMERGENCY CALLS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS PRODUCT, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

August 31, 2007 Revision 4

Table of Contents

ntroduction	2
Network Topology	3
Network TopologyLimitations	3
System Components	3
Hardware Requirements	
Hardware Requirements Software Requirements Features	
Features	
Features Supported	
Conclusion	
Configuration	5
Configuring Cisco Communications Manager	5
Configuring Cisco Emergency Responder	42
Cisco CMM IOS Gateway MGCP Configuration for QSIG Connectivity	57
AVAYA Definity G3si Configuration	72
Acronyms	



Introduction

The following is an Application Note for E911 Interoperability of a Cisco Unified Communications Manager (CUCM) 5.1.2 and Cisco Emergency Responder (CER) 2.0 to an AVAYA G3si CM2.0 via a Cisco 3825 T1-QSIG trunk as MGCP gateway. The CUCM system is connected to a simulated E911 Public Safety Answering Point (PSAP) via a Cisco 3825 w/ CAMA trunk registered using H323.

The Network Topology diagram shows the test set-up for interoperability between the Cisco Unified Communications Manager and Cisco Emergency Responder connected to the PBX via a Cisco 3825 (MGCP gateway) T1 QSIG trunk and connected to E911 PSAP using a Cisco 3825 H323 gateway via a CAMA trunk.

This Application Note uses the C3825 IOS-voice-gateway, however other Cisco voice gateways are also an option to use since the voice gateway implementation does not depend on the platform. Here is a list of Cisco Products capable of voice gateway functionality: Care must be taken when selecting a voice gateway platform depending of the capacity required for the intended deployments

Cisco 2800 Series Integrated Services Routers


Cisco 3800 Series Integrated Services Routers

Cisco 2600XM Series Multiservice Platforms

Cisco 3700 Series Routers



Network Topology



Limitations

Unique DID numbers must be used to associate with each Emergency Response Location to allow the return call if the 911 caller is disconnected.

Each available calling party that might dial 911 from the PBX side must have that calling party number configured in the Manually Configured Phones screen of the Cisco Emergency Responder.



System Components

Hardware Requirements

Cisco 3825 Gateway with VIC2-4FXO (CAMA trunk) Cisco 3825 Gateway with VWIC-2MFT-T1 (QSIG) Cisco Cat3500 switch Cisco Unified Communications Manager server Cisco Emergency Responder server

AVAYA Definity G3si CM 2.0 PBX

Software Requirements

IOS Software release "C3825-ipvoiceK9-m.12.4 (15)T1"
IOS Software release "C3825-ADVENTERPRISEK9_IVS-M .12.4(11).T1
Cisco Unified Communications Manager 5.1.2
Cisco Emergency Responder 2.0
PBX Software: Release CM 2.0

Features

Features Supported

Calling Number

E911 ERL DID number passed to PSAP

Incoming DID calling to disconnected 911 originating caller

Conclusion

Test emergency 911 call from a PBX digital station was routed to the T1 QSIG trunk, of the Cisco Voice MGCP gateway, and was correctly associated to the appropriate Emergency Response Location. The call was connected through the Cisco 3825 CAMA trunk to the PSAP Emulator. The Emergency Response Location associated the ten digit DID call back number (ELIN) correctly and sent it to the PSAP, audio connection was also achieved. The PBX digital station was then disconnected.

A return call was originated from an incoming trunk (PSTN side) in the same Cisco Unified Communications Manager Partition. The number dialed was the DID digits of the 10 digit call back number sent to the PSAP on the previous 911 call (ELIN number). The call was routed through to the PBX digital station that had originated the E911 call. The call was disconnected and an alternate trunk was used to dial the same DID number and the call was routed through, again, to the PBX digital station that had originated the E911 call.

Test emergency 911calls were made from each PBX digital station and Cisco IP phone. All calls were confirmed to select its associated Emergency Response Location and the associated 10 digit DID call back number. In each case, the call was disconnected and the call back number was confirmed to reach the phone that had originated the E911 call.

Emergency 911calls made from an AVAYA Definity G3si PBX utilizing a T1 QSIG trunk configured as ISO, associates with the correct Emergency Response Location and routes to the associated PSAP with the correctly formatted 10 digit DID call back number.

The call back DID number routes the return call to the correct phone that had originated the E911 call from the PBX digital phone.



Configuration


Configuring Cisco Communications Manager

Partitions






Phone Partition






E911 Partition




Calling Search Space






CSS phones






CSS E911





CUCM IP phones





Ne	etwork Locale	< None >	
Bu	uilt In Bridge*	Default	
Pri	ivacy*	Default	
Ov	wner User ID	< None >	
Ph	none Load Name		
	Retry Video Call as Audio		
	Ignore Presentation Indicator	s (internal calls only)	
	Allow Control of Device from C	TI .	
	Protocol Considir Information		
	Protocol Specific Information acket Capture Mode*	None	
Pa	acket Capture Duration	0	
Pre	esence Group*	Standard Presence group	
	evice Security Profile*		
	•	Cisco 7961 - Standard SCCP Non-Secure Profile	
	JBSCRIBE Calling Search Space	< None >	
	Unattended Port		
NII .	Require DTMF Reception		
	RFC2833 Disabled		
	Certification Authority Proxy F	Function (CAPF) Information	
	and the state of t	Pending Operation ▼	
Au	ithentication Mode*	Null String	
Au	thentication String		
	Generate String		
Ke	ey Size (Bits)*	24	
Ор	peration Completes By 200	7 9 6 12 (YYYY:MM:DD:HH)	
	ertificate Operation Status: Non ote: Security Profile Contains A	ie	
	xpansion Module Information		




Formula Made	de Tufermentien
Expansion Modu Module 1	None > ▼
Module 1 Load Na	ame
Module 2	< None > ▼
Module 2 Load Na	ame
External Data Lo Information	ocations Information (Leave blank to use default)
Directory	
Messages	
Services	
Authentication Ser	erver
Proxy Server	
Idle	
Idle Timer (second	ds)
Extension Inform	
Enable Extensi	
Log Out Profile	Not Selected ▼
Login in User ID <	
Log in Time < Log out Time <	
Log out Time <	. Note >
─ MLPP Informatio	ion
MLPP Domain	< None > ▼
MLPP Indication*	Delauit
MLPP Preemption*	* Default
Common Chall Tail	formation
Secure Shell Inf	



	─ MLPP Information ─────────		
	MLPP Domain < None >	▼	
	MLPP Indication* Default	▼	
	MLPP Preemption* Default	▼	
	Secure Shell Information		
	Secure Shell User		
	Secure Shell Password		
	Product Specific Configuration Layout		
			?
	Disable Speakerphone		
	Disable Speakerphone and Headset		
	Forwarding Delay*	Disabled	•
	PC Port *	Enabled	▼
	Settings Access*	Enabled	▼
	Gratuitous ARP*	Enabled	▼
	PC Voice VLAN Access*	Enabled	-
	Video Capabilities*	Disabled	▼
	Auto Line Select*	Enabled	▼
	Web Access*	Enabled	▼
	Span to PC Port*	Disabled	_
	Logging Display*	PC Controlled	
	Load Server		
	Recording Tone*	Disabled	
	Recording Tone Local Volume*	100	
	Recording Tone Remote Volume*	50	
	Recording Tone Duration	50	
<u> </u>	Recording fore Duration		








AAR Group	< None >	•		
User Hold MOH Audio Source	< None >	•		
Network Hold MOH Audio Source	< None >	•		
Auto Answer*	Auto Answer Off	•		
Call Forward and Call Pickup	Settings			
	Voice Mail Destination		Calling Search Space	
Forward All	or e		< None >	▼
Secondary Calling Search Space	e for Forward All		< None >	•
Forward Busy Internal	or or		< None >	▼
Forward Busy External	or		< None >	•
Forward No Answer Internal	or or		< None >	•
Forward No Answer External	□ ог		< None >	•
Forward No Coverage Internal	or		< None >	•
Forward No Coverage External	or or		< None >	•
Forward on CTI Failure	or		< None >	•
No Answer Ring Duration (secor	nds)			
Call Pickup Group	< None >	•		
MLPP Alternate Party Setting Target (Destination)	ıs			
MLPP Calling Search Space	< None >	▼		
MLPP No Answer Ring Duration	(seconds)			
Line 1 on Device SEP00170E	E67E8E			
Display (Internal CER SCCP Caller ID)	3011	Display text for a line appeara	ance is intended for displaying text such a	s a name instead of a
directory nu	umber for internal calls. If you spe		call may not see the proper identity of the	
ASCII Display CER SCCP (Internal Caller ID)	3011			



MLPP No Answer Rir	ng Duration (seconds)				
Line 1 on Device	SEP00170EE67E8E				
Display (Internal	CER SCCP 3011 Display text for a line appearance is intended for displaying text such as a name instead of a				
Caller ID)	directory number for internal calls. If y		eiving a call may not see the proper identity of the caller.		
ASCII Display (Internal Caller ID)	CER SCCP 3011				
Line Text Label	CER SCCP 3011				
ASCII Line Text Label	CER SCCP 3011				
External Phone Number Mask					
Message Waiting Lamp Policy*	Use System Policy	•			
Ring Setting (Phone Idle)*	Use System Default	•			
Ring Setting (Phone Active)	Use System Default	▼ Applies to this line whe	n any line on the phone has a call in progress.		
	Waiting Settings on Device SEP0017 select the Max Number of calls is: 1-200 f Calls*		(Less than or equal to Max. Calls)		
			(Less trial of equal to Max. Calls)		
Forwarded Call In	nformation Display on Device SEP001	70EE67E8E			
Caller Number					
Redirected Numb	oor				
Dialed Number					
Didica Hamber					
- Save Delete Re	eset Add New				
i *- indicates req	quired item.				
**- Changes to Line or Directory Number settings require restart.					




CTI Route Points






CTI Route Point 911






				Navigation	Cisco Unified CallManager Administration ▼
Cisco Unified C	CallManager Adı	ministration F	or Cisco Unified C	ommunications Solutions	Logged in as: CCMAdministr
	Media Resources ▼ Voic		lication - User Manag		Log 01
		e maii 🕶 Device 🕶 App	ication + oser manag		
ectory Number Confi	guration			5	Related Links: Back To Find/List
) × °+					
Status —					
Status: Ready					
Directory Number Inf	formation —				
rectory Number* 91	1				
	nones		<u> </u>		
escription erting Name					
SCII Alerting Name					
ssociated Devices	2044				
Sociated Devices Ri	2911		Edit Devic	e	
			Edit Lir	ne Appearance	
issociate Devices	**		_		
L					
Directory Number Se Dice Mail Profile					
alling Search Space	< None >			hoose <none> to use system default)</none>	
resence Group*	E911css Standard Pres	conco group	▼		
resence Group*	Standard Pre	nonno graun	~		
AR Group	< None >	sence group	· ·		
Iser Hold MOH Audio S			▼		
letwork Hold MOH Aud	lio Source < None >		•		
Call Forward and Cal	Il Pickup Settinas —				
orward All	Voice Ma	ail Destination		Calling Search	Space
	e or rch Space for Forward	All		< None >	Y
-				< None >	▼
orward Busy Internal	or e	912			
	■ 0-	012		E011000	
orward Busy External		912		E911css	<u> </u>
orward Busy External orward No Answer In	ternal or	912		E911css	· ·
orward Busy Internal forward Busy External forward No Answer Inf forward No Answer Ex forward No Coverage	ternal or			E911css E911css	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage	ternal or or or Internal or	912		E911css E911css < None >	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage orward No Coverage	ternal or or Internal or External or	912 912		E911css E911css < None > < None >	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage orward No Coverage orward on CTI Failure	ternal or or Internal or External or	912		E911css E911css < None >	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer Ini orward No Answer Ex orward No Coverage orward No Coverage orward on CTI Failure o Answer Ring Duratio	ternal or or Internal or External or	912 912 912	•	E911css E911css < None > < None > E911css	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage orward No Coverage orward on CTI Failure o Answer Ring Duratio all Pickup Group	ternal or or or Internal or External or or or (seconds)	912 912 912		E911css E911css < None > < None > E911css	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer Int orward No Answer Ex	ternal or or or Internal or External or or or (seconds)	912 912 912	•	E911css E911css < None > < None > E911css	• • • • • • • • • • • • • • • • • • •
Forward Busy External Forward No Answer Inforward No Coverage Forward No Coverage Forward No Coverage Forward on CTI Failure Io Answer Ring Duration Fail Pickup Group	ternal or iternal or Internal or External or External or internal or	912 912 912	•	E911css E911css < None > < None > E911css	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage orward No Coverage orward on CTI Failure o Answer Ring Duration all Pickup Group MLPP Alternate Part arget (Destination)	ternal or iternal or Internal or External or External or or on (seconds) < None > y Settings	912 912 912		E911css E911css < None > < None > E911css	• • • • • • • • • • • • • • • • • • •
orward Busy External orward No Answer In orward No Answer Ex orward No Coverage orward On CTI Failure o Answer Ring Duration all Pickup Group MLPP Alternate Parts arget (Destination) LPP Calling Search Sp	ternal or ternal or Internal or External or External or (None > y Settings Ouration (seconds)	912 912 912		E911css E911css < None > < None > E911css	









CTI Route Point 913













Note: A Backup CER server was not used during testing therefore CTI route point for 912 was not created.



CTI Port










MLPP Calling Search	Space < None >		▼
MLPP No Answer Rin	ng Duration (seconds)		
Line 1 on Device (Display (Internal Caller ID) ASCII Display (Internal Caller ID) Line Text Label			a line appearance is intended for displaying text such as a name instead of a n receiving a call may not see the proper identity of the caller.
ASCII Line Text Label External Phone			
Number Mask Message Waiting Lamp Policy*	Use System Policy	•	
	Waiting Settings on Device CEF elect the Max Number of calls is: f Calls*		
Busy Trigger*		2	(Less than or equal to Max. Calls)
Forwarded Call In Caller Name Caller Number Redirected Numb	oformation Display on Device Cl	RSec1	
☑ Dialed Number			
i *- indicates req	aset Add New quired item. Deline or Directory Number setting	js require restart.	




Route Patterns for ELINs






Route Pattern 10911






Route Pattern 11911











Route Pattern 13911






Translation Pattern for ELINs












PSAP Gateway configuration (CAMA TRUNK)








Cisco Unified Communications Manager User











T1-QSIG Gateway











Call Routing Information - Outbo				
Calling Party Presentation*	Default	▼		
Calling Party Selection*	Originator	•		
Called party IE number type unkno	oloco odilividriagei	▼		
Calling party IE number type unkno	ologo dalimanagoi	▼		
Called Numbering Plan*	Cisco CallManager	▼		
Calling Numbering Plan*	Cisco CallManager	•		
Number of digits to strip*	0	~		
Caller ID DN				
SMDI Base Port*	0			
PRI Protocol Type Specific Infor	mation —			
Display IE Delivery				
Redirecting Number IE Delivery -	- Outbound			
Redirecting Number IE Delivery -				
Send Extra Leading Character in				
Setup non-ISDN Progress Indica				
MCDN Channel Number Extension	on Bit Set to Zero**			
Send Calling Name In Facility IE				
☐ Interface Identifier Present** Interface Identifier Value**				
Connected Line ID Presentation (Q	CIC Inhaumd Call*			
Connected Line ID Presentation (Q	SIG Inbound Call) Default		▼	
UUIE Configuration				
Passing Precedence Level Throu	igh UUIE			
Security Access Level* 2				
			1 1 1 1 1 1 -	
Interface Identifier Value**				
Interface Identifier Value**	0			
Interface Identifier Value** Connected Line ID Presentation (Q:	SIG Inbound Call)* Default		V	
	SIG Inbound Call)* Default		•	
Connected Line ID Presentation (Q: UUIE Configuration Passing Precedence Level Throu			V	
Connected Line ID Presentation (Q:			V	
Connected Line ID Presentation (Q: UUIE Configuration Passing Precedence Level Throu Security Access Level*	igh UUIE		v	
Connected Line ID Presentation (Q: - UUIE Configuration - Passing Precedence Level Throuse Security Access Level* - Product Specific Configuration Line - Product Specific Configuration Line - Connected Line ID Presentation (Q: - UUIE Configuration (Q: - Product Specific Configuration Line ID Presentation (Q: - Product Specific Configuration Line ID Presentation (Q: - UUIE Configuration (Q: - UUIE C	igh UUIE	?	•	
Connected Line ID Presentation (Q	igh UUIE	?	•	
Connected Line ID Presentation (Quality of the Configuration Passing Precedence Level Throuse Security Access Level* 2 Product Specific Configuration Line Coding*	igh UUIE ayout	?	*	
Connected Line ID Presentation (QI UUIE Configuration Passing Precedence Level Throusecurity Access Level* Product Specific Configuration Line Coding* Framing*	ayout B8ZS	•	•	
Connected Line ID Presentation (QI - UUIE Configuration - Passing Precedence Level Throusecurity Access Level* - Product Specific Configuration Line Coding* Framing* Clock*	ayout B8ZS ESF	•	•	
Connected Line ID Presentation (QI	ayout B8ZS ESF External	•	•	
Connected Line ID Presentation (QI - UUIE Configuration - Passing Precedence Level Throuse Security Access Level* - Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)*	ayout B8ZS ESF External 0	•		
Connected Line ID Presentation (QI - UUIE Configuration - Passing Precedence Level Throuse Security Access Level* - Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)*	ayout B8ZS ESF External 0 0 Enable	•	V	
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* 2 Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)*	ayout B8ZS ESF External 0 0 Enable	•	•	
Connected Line ID Presentation (QI - UUIE Configuration - Passing Precedence Level Throuse Security Access Level* - Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable*	ayout B8ZS ESF External 0 0 Enable	•		
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* 2 Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)*	ayout B8ZS ESF External 0 0 Enable	•		
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset	ayout B8ZS ESF External 0 0 Enable 8	•		
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset *- indicates required item. **- applies to DMS-100 protocomes	ayout B8ZS ESF External 0 0 Enable 8	•		
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset *- indicates required item. **- applies to DMS-100 protocod ***- applies to DMS-100 protocod ***- applies to DMS-100 protocod	ayout B8ZS ESF External 0 0 Enable 8	•		
Connected Line ID Presentation (Quality Configuration Passing Precedence Level Throusecurity Access Level* Product Specific Configuration Line Coding* Framing* Clock* Input Gain (-614 db)* Output Attenuation (-614 db)* Echo Cancellation Enable* Echo Cancellation Coverage (ms)* Save Delete Reset * - indicates required item. ** - applies to DMS-100 protoc. *** - applies to DMS-100 protoc. *** - applies to DMS-100 protoc.	ayout B8ZS ESF External 0 0 Enable 8		oture Duration.	



Route Pattern to QSIG Trunk







Note: For detailed information regarding QSIG interoperability between CUCM and AVAYA G3si PBX go to: http://www.cisco.com/warp/public/779/largeent/avvid/inter_operability/flash/portal.html


SNMP service must be active






Configuring Cisco Emergency Responder

Cisco Unified Communications Manager Details






Cisco Emergency Responder Server group






Telephony Settings






Server Settings






ERLs List





ERL 1






ERL 2






ERL 3






SNMP connection






LAN Switch identifying







Switch Port Details















Defining Manual Phones (PBX Stations)









Cisco CMM IOS Gateway MGCP Configuration for QSIG Connectivity

Ri-3825#sh ver

Cisco IOS Software, 3800 Software (C3825-IPVOICEK9-M), Version 12.4(15)T1, RELEA

SE SOFTWARE (fc2)

Technical Support: http://www.cisco.com/techsupport

Copyright (c) 1986-2007 by Cisco Systems, Inc.

Compiled Wed 18-Jul-07 11:23 by prod_rel_team

ROM: System Bootstrap, Version 12.3(11r)T2, RELEASE SOFTWARE (fc1)

Ri-3825 uptime is 4 weeks, 6 days, 23 hours, 15 minutes System returned to ROM by reload at 17:08:17 UTC Tue Jul 24 2007 System image file is "flash:c3825-ipvoicek9-mz.124-15.T1.bin"

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 3825 (revision 1.0) with 224256K/37888K bytes of memory.

Processor board ID FTX0946A1BT

2 Gigabit Ethernet interfaces

48 Serial interfaces

2 Channelized T1/PRI ports

2 Voice FXS interfaces



DRAM configuration is 64 bits wide with parity enabled.
479K bytes of NVRAM.
62720K bytes of ATA System CompactFlash (Read/Write)

Configuration register is 0x2102

Ri-3825#sh run

Building configuration...

```
Current configuration: 2419 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname Ri-3825
!
boot-start-marker
boot-end-marker
enable password cisco
no aaa new-model
network-clock-participate slot 1
no network-clock-participate slot 2
network-clock-select 1 T1 1/0/0
voice-card 0
no dspfarm
voice-card 1
dspfarm
voice-card 2
no dspfarm
```

!



```
ip cef
no ip domain lookup
ip host CM-Titanic 172.20.140.254 >=====Active Host
ip host CM-SPURS 172.20.192.254
multilink bundle-name authenticated
isdn switch-type primary-qsig
archive
log config
 hidekeys
controller T1 1/0/0
framing esf
linecode b8zs
pri-group timeslots 1-24 service mgcp
controller T1 1/0/1
shutdown
framing esf
linecode b8zs
cablelength short 399
pri-group timeslots 1-24 service mgcp
```



```
interface GigabitEthernet0/0
ip address 172.20.192.21 255.255.255.0
duplex auto
speed auto
media-type rj45
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
media-type rj45
interface Serial1/0/0:23
no ip address
encapsulation hdlc
isdn switch-type primary-qsig
isdn timer T310 120000
isdn protocol-emulate network
isdn incoming-voice voice
isdn bind-13 ccm-manager
no cdp enable
interface Serial1/0/1:23
no ip address
encapsulation hdlc
shutdown
isdn switch-type primary-qsig
isdn incoming-voice voice
isdn bind-13 ccm-manager
no cdp enable
```



```
ip route 0.0.0.0 0.0.0.0 172.20.192.1
ip http server
no ip http secure-server
control-plane
voice-port 1/0/0:23
voice-port 1/0/1:23
!
voice-port 2/0/0
voice-port 2/0/1
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server CM-Titanic
ccm-manager config
!
mgcp
mgcp call-agent CM-Titanic 2427 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp rtp unreachable timeout 1000 action notify
mgcp modem passthrough voip mode nse
mgcp package-capability rtp-package
mgcp package-capability sst-package
mgcp package-capability pre-package
no mgcp package-capability res-package
```



```
no mgcp package-capability fxr-package
no mgcp timer receive-rtcp
mgcp sdp simple
mgcp fax t38 inhibit
mgcp rtp payload-type g726r16 static
!
mgcp profile default
!
line con 0
password cisco
login
stopbits 1
line aux 0
stopbits 1
line vty 04
password cisco
login
!
scheduler allocate 20000 1000
!
end
 Cisco 3825 IOS Gateway H323 configuration for CAMA trunk connectivity
Router#sh ver
Cisco IOS Software, 3800 Software (C3825-ADVENTERPRISEK9_IVS-M), Version 12.4(11
)T1, RELEASE SOFTWARE (fc5)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2007 by Cisco Systems, Inc.
Compiled Thu 25-Jan-07 17:16 by prod_rel_team
ROM: System Bootstrap, Version 12.3(11r)T2, RELEASE SOFTWARE (fc1)
Router uptime is 1 week, 3 days, 17 hours, 23 minutes
System returned to ROM by power-on
```



System image file is "flash:c3825-adventerprisek9_ivs-mz.124-11.T1.bin" This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 3825 (revision 1.0) with 223232K/38912K bytes of memory.

Processor board ID FTX0946A1BV

- 2 Gigabit Ethernet interfaces
- 24 Serial interfaces
- 1 Channelized T1/PRI port
- 1 Virtual Private Network (VPN) Module
- 2 Voice FXO interfaces
- 2 Voice FXS interfaces

DRAM configuration is 64 bits wide with parity enabled.

479K bytes of NVRAM.

62720K bytes of ATA System CompactFlash (Read/Write)

Configuration register is 0x2102



Router#sh run

Building configuration...

```
Current configuration: 2545 bytes
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption
hostname Router
boot-start-marker
boot system flash:c3825-adventerprisek9_ivs-mz.124-11.T1.bin
boot-end-marker
logging buffered 10000000
no logging console
enable password cisco
no aaa new-model
no network-clock-participate slot 1
voice-card 0
dspfarm
dsp services dspfarm
voice-card 1
dspfarm
ip cef
```



multilink bundle-name authenticated
!
isdn switch-type primary-dms100
!
!
!
voice service voip
allow-connections h323 to h323=====H323 protocol
allow-connections h323 to sip
allow-connections sip to h323
allow-connections sip to sip
h323
sip
!
!
!
voice class codec 1
codec preference 1 g729r8
!
!
!
!
!
!
!
controller T1 1/0/0
framing esf
linecode b8zs
pri-group timeslots 1-24
!
!
!
!
!



```
interface GigabitEthernet0/0
ip address 172.20.192.102 255.255.255.0
duplex auto
speed auto
media-type rj45
no keepalive
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
media-type rj45
no keepalive
interface Serial1/0/0:23
no ip address
encapsulation hdlc
isdn switch-type primary-dms100
isdn incoming-voice voice
no cdp enable
ip default-gateway 172.20.192.1
ip route 0.0.0.0 0.0.0.0 172.20.192.1
ip http server
no ip http secure-server
```



```
control-plane
voice-port 0/0/0 ===→CAMA signaling
signal cama KP-0-NPA-NXX-XXXX-ST
dial-type mf
timing hookflash-out 500
description CAMA
voice-port 0/0/1
voice-port 0/2/0
station-id name Test Analog
station-id number 7055
voice-port 0/2/1
station-id name RI-NGUYEN
station-id number 4085261122
caller-id enable
voice-port 1/0/0:23
sccp local GigabitEthernet0/0
sccp ccm 172.20.8.254 identifier 1 version 4.1
sccp
sccp ccm group 1
associate ccm 1 priority 1
associate profile 1 register mtp0015f90d1590
dspfarm profile 1 mtp
codec g711ulaw
```



```
maximum sessions software 10
associate application SCCP
shutdown
dial-peer voice 911 pots
destination-pattern 911
no digit-strip
port 0/0/0
forward-digits all
dial-peer voice 999 voip
description call in PSTN simulation
destination-pattern .T
session target ipv4:172.20.140.254
gateway
timer receive-rtp 1200
sip-ua
retry options 0
gatekeeper
shutdown
line con 0
exec-timeout 0 0
password cisco
login
stopbits 1
line aux 0
```



```
stopbits 1
line vty 0 4
exec-timeout 0 0
password cisco
login
line vty 5 10
exec-timeout 0 0
password cisco
login
!
scheduler allocate 20000 1000
!
end
```



CAMA voice-port configuration

Router#sh voice port 0/0/0

Foreign Exchange Office 0/0/0 Slot is 0, Sub-unit is 0, Port is 0

Type of VoicePort is FXO

Operation State is DORMANT

Administrative State is UP

The Last Interface Down Failure Cause is Administrative Shutdown

Description is CAMA

Noise Regeneration is enabled

Non Linear Processing is enabled

Non Linear Mute is disabled

Non Linear Threshold is -21 dB

Music On Hold Threshold is Set to -38 dBm

In Gain is Set to 0 dB

Out Attenuation is Set to 3 dB

Echo Cancellation is enabled

Echo Cancellation NLP mute is disabled

Echo Cancellation NLP threshold is -21 dB

Echo Cancel Coverage is set to 64 ms

Echo Cancel worst case ERL is set to 6 dB

Playout-delay Mode is set to adaptive

Playout-delay Nominal is set to 60 ms

Playout-delay Maximum is set to 250 ms

Playout-delay Minimum mode is set to default, value 40 ms

Playout-delay Fax is set to 300 ms

Connection Mode is normal

Connection Number is not set

Initial Time Out is set to 10 s

Interdigit Time Out is set to 10 s

Call Disconnect Time Out is set to 60 s

Ringing Time Out is set to 180 s

Wait Release Time Out is set to 30 s

Companding Type is u-law

Region Tone is set for US



Analog Info Follows:
Currently processing none
Maintenance Mode Set to None (not in mtc mode)
Number of signaling protocol errors are 9
Impedance is set to 600r Ohm
Station name None, Station number None
Translation profile (Incoming):
Translation profile (Outgoing):
Voice card specific Info Follows:
Signal Type is cama
Cama Type is KP-0-NPA-NXX-XXXX-ST
Battery-Reversal is enabled
Number Of Rings is set to 1
Supervisory Disconnect is signal
Answer Supervision is inactive
Hook Status is On Hook
Ring Detect Status is inactive
Ring Ground Status is inactive
Tip Ground Status is inactive
Dial Out Type is mf
Digit Duration Timing is set to 75 ms
InterDigit Duration Timing is set to 65 ms
Pulse Rate Timing is set to 10 pulses/second
InterDigit Pulse Duration Timing is set to 750 ms
Percent Break of Pulse is 60 percent
GuardOut timer is 2000 ms
Minimum ring duration timer is 125 ms
Hookflash-in Timing is set to 600 ms
Hookflash-out Timing is set to 500 ms
Supervisory Disconnect Timing is set to 350 ms
OPX Ring Wait Timing is set to 6000 ms



AVAYA Definity G3si Configuration

The AVAYA Definity G3si Switch requires a substantial amount of programming and circuit card switch settings to properly install T1 PRI. It is beyond the scope of this document to provide the entire configuration, therefore the AVAYA information below is directed to AVAYA techs

The switch settings and software references in this document assume a familiarity with the AVAYA Definity G3si. It is highly recommended to have a AVAYA Definity G3si ISDN certified technician setup the AVAYA portion.

DS1 CIRCUIT PACK

```
1 2
                                DS1 CIRCUIT PACK
                                                      Name: CER 2.0
             Location: 01A12
            Bit Rate: 1.544
                                               Line Coding: b8zs
    Line Compensation: 1
                                              Framing Mode: esf
      Signaling Mode: isdn-pri
             Connect: pbx
                                                 Interface: peer-master
    TN-C7 Long Timers? n
                                             Peer Protocol: Q-SIG
 Interworking Message: ALERTing
                                                      Side: a
 Interface Companding: mulaw
                                                       CRC? n
           Idle Code: 11111111
                              DCP/Analog Bearer Capability: speech
       Slip Detection? n
                                        Near-end CSU Type: other
```

SIGNALING GROUP

```
SIGNALING GROUP

Group Number: 12 Group Type: isdn-pri

Associated Signaling? y Max number of NCA TSC: 12

Primary D-Channel: 01A1224 Max number of CA TSC: 12

Trunk Group for NCA TSC: 12

Trunk Group for Channel Selection: 12 X-Mobility/Wireless Type: NONE

Supplementary Service Protocol: b
```



TRUNK GROUP

```
1 2 3 4 5 6 7 8 9 10
                              TRUNK GROUP
Group Number: 12
                                 Group Type: isdn
                                                         CDR Reports: y
  Group Name: CER 2.0
                                       COR: 1
                                                     TN: 1 TAC: 612
                                                      Carrier Medium: PRI/BRI
   Direction: two-way
                           Outgoing Display? n
 Dial Access? y
                             Busy Threshold: 99
                                                      Night Service:
Queue Length: 0
Service Type: tie
                                  Auth Code? n
                                                         TestCall ITC: rest
                        Far End Test Line No:
 TestCall BCC: 4
 TRUNK PARAMETERS
        Codeset to Send Display: 0
                                      Codeset to Send National IEs: 6
        Max Message Size to Send: 260
                                      Charge Advice: none
  Supplementary Service Protocol: b
                                      Digit Handling (in/out): enbloc/enbloc
           Trunk Hunt: descend
                                                  QSIG Value-Added? n
                                                Digital Loss Group: 13
Calling Number - Delete:
                         Insert:
                                                 Numbering Format: unk-unk
             Bit Rate: 1200 Synchronization: async Duplex: full
 Disconnect Supervision - In? y Out? y
 Answer Supervision Timeout: 0
```


```
1 2 3 4 5 6 7 8 9 10
TRUNK FEATURES
         ACA Assignment? n
                                     Measured: none
                                                        Wideband Support? n
                               Internal Alert? n
                                                       Maintenance Tests? y
                             Data Restriction? n
                                                    NCA-TSC Trunk Member: 1
                                    Send Name: y
                                                    Send Calling Number: y
                                     Hop Dat? n
           Used for DCS? n
  Suppress # Outpulsing? n
                             Numbering Format: unknown
Outgoing Channel ID Encoding: preferred
                                          UUI IE Treatment: service-provider
                                              Replace Restricted Numbers? y
                                              Replace Unavailable Numbers? y
                                                   Send Connected Number: y
            Send UUI IE? n
             Send UCID? n
                                                 Ds1 Echo Cancellation? n
Send Codeset 6/7 LAI IE? n
Path Replacement with Retention? n
Path Replacement Method: better-route
                   SBS? n Network (Japan) Needs Connect Before Disconnect? n
```



1 2 3 4 5 6 7	8 9 10	
	TRUNK GROUP	
	Administered Members (min/max):	1/5
GROUP MEMBER ASSIGNMENTS	Total Administered Members:	5
Port Code Sfx N		
1: 01A1201 TN464 F	12	
2: 01A1202 TN464 F	12	
3: 01A1203 TN464 F	12	
4: 01A1204 TN464 F	12	
5: 01A12O5 TN464 F	12	
6:		
7:		
8:		
9:		
10:		
11:		
12:		
13:		
14:		
15:		

Note: Only 5 timeslots were used for testing purposes. For actual deployment assign all 23 (for single T1) available B-cahnnels

Uniform Dial-plan to call CUCM extension



AAR analysis



1 2							
	1	AAR DI	GIT ANALYS	SIS TABI	LE		
						Percent Full:	9
Diale	d Tot	tal	Route	Call	Node	ANI	
Strin		Max	Pattern	Type	Num	Reqd	
612	7	7	12	aar	2	n .	
613	7	7	13	aar	1	n	
614	7	7	14	aar		y	
615	7	7	15	aar		n	
616	7	7	16	aar		n	
617	7	7	17	aar		n	
627	7	7	7	aar		n	
668	7	7	199	aar		n	
678	7	7	199	aar		n	
681	7	7	81	aar		n	
7	7	7	254	aar		n	
8	7	7	9	aar		n	
9	7	7	253	aar		n	
972	6	10	12	aar		n	
999	7	7	99	aar		n	




Route-pattern to call CUCM extensions

```
Pattern Number: 12 Pattern Name:
   Grp FRL NPA Pfx Hop Toll No. Inserted
                                                                  DCS/ IXC
              Mrk Lmt List Del Digits
  No
                                                                  QSIG
                          Dgts
                                                                  Intw
1: 12
                           3
                                                                   n
                                                                      user
2:
                                                                       user
                                                                   n
3:
                                                                   n
                                                                      user
4:
                                                                   n
                                                                      user
5:
                                                                      user
                                                                      user
   BCC VALUE TSC CA-TSC
                           ITC BCIE Service/Feature BAND No. Numbering LAR
   0 1 2 3 4 W
                  Request
                                                       Dgts Format
                                                     Subaddress
1: yyyyyn y none
                           rest
                                                                      none
2: yyyyyn n
                           rest
                                                                      none
3: уууууп п
                           rest
                                                                      none
4: yyyyyn n
                           rest
                                                                      none
5: yyyyyn n
                           rest
                                                                      none
6: yyyyyn n
                           rest
                                                                      none
```

ARS access-code '9'

```
1 2 3 4 5 6 7
                               FEATURE ACCESS CODE (FAC)
          Abbreviated Dialing List1 Access Code:
          Abbreviated Dialing List2 Access Code:
         Abbreviated Dialing List3 Access Code:
 Abbreviated Dial - Prgm Group List Access Code:
                      Announcement Access Code:
                       Answer Back Access Code:
       Auto Alternate Routing (AAR) Access Code: 8
     Auto Route Selection (ARS) - Access Code 1: 9
                                                      Access Code 2:
                 Automatic Callback Activation:
                                                       Deactivation:
 Call Forwarding Activation Busy/DA: *72 All: *70
                                                       Deactivation: *71
                         Call Park Access Code:
                       Call Pickup Access Code:
 CAS Remote Hold/Answer Hold-Unhold Access Code:
                  CDR Account Code Access Code:
                        Change COR Access Code:
                   Change Coverage Access Code:
```

ARS 9911






911 route-pattern

```
Pattern Number: 9 Pattern Name:
   Grp FRL NPA Pfx Hop Toll No. Inserted
                                                                 DCS/ IXC
             Mrk Lmt List Del Digits
                                                                QSIG
  No
                         Dgts
                                                                 Intw
1: 12
                                                                 n
                                                                     user
2:
                                                                     user
                                                                 n
3:
                                                                     user
                                                                 n
4:
                                                                 n
                                                                     user
5:
                                                                     user
6:
                                                                     user
   BCC VALUE TSC CA-TSC
                          ITC BCIE Service/Feature BAND No. Numbering LAR
   0 1 2 3 4 W
                                                      Dgts Format
                 Request
                                                   Subaddress
none
                          rest
                                                                    none
2: yyyyyn n
                          rest
                                                                    none
                          rest
3: yyyyyn n
                                                                    none
4: уууууп п
                          rest
                                                                    none
5: yyyyyn n
                          rest
                                                                    none
                           rest
6: yyyyyn n
                                                                    none
```

Digital Station

```
1 2 3 4
                                     STATION
Extension: 2004
                                                                     BCC: 0
                                           Lock Messages? n
     Type: 8410D
                                           Security Code:
                                                                      TN: 1
     Port: 01A0604
                                         Coverage Path 1: 103
                                                                     COR: 1
     Name: PBX-Ken1
                                         Coverage Path 2:
                                                                     COS: 1
                                         Hunt-to Station:
STATION OPTIONS
              Loss Group: 2
                                         Personalized Ringing Pattern: 1
                                                     Message Lamp Ext: 2004
             Data Module? n
            Speakerphone: 2-way
                                                  Mute Button Enabled? y
        Display Language: english
                                                    Media Complex Ext:
                                                         IP SoftPhone? n
1 2 3 4
                                     STATION
FEATURE OPTIONS
           LWC Reception: spe
                                           Auto Select Any Idle Appearance? n
          LWC Activation? y
                                                    Coverage Msg Retrieval? y
  LWC Log External Calls? n
                                                               Auto Answer: none
             CDR Privacy? n
                                                          Data Restriction? n
   Redirect Notification? y
                                                Idle Appearance Preference? n
 Per Button Ring Control? n
   Bridged Call Alerting? n
                                                  Restrict Last Appearance? n
  Active Station Ringing: single
                                     Per Station CPN - Send Calling Number?
        H.320 Conversion? n
       Service Link Mode: as-needed
         Multimedia Mode: basic
                                                   Audible Message Waiting? y
    MWI Served User Type:
                                                Display Client Redirection? y
                                               Select Last Used Appearance? n
                                                 Coverage After Forwarding? s
                                                   Multimedia Early Answer? n
                                               Direct IP-IP Audio Connections? y
 Emergency Location Ext: 2004
                                                      IP Audio Hairpinning? y
```





Acronyms

Acronym	Definitions
CAMA	Centralized Automatic Message Accounting
PSAP	Public Safety Answering Point
CER	Cisco Emergency Responder
CUCM	Cisco Unified Communications Manager



Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.





Corporate **Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 LISA

www.cisco.com Tel: 408 526-4000

800 553-NETS (6387) Fax: 408 526-4100

European **Headquarters**

Cisco Systems International Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 LISA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com Tel: +65 317 7777

Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

© 2007 Cisco Systems, Inc. All rights reserved.

CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0709R)

Printed in the USA