

End-of-Sale and End-of-Life Announcement for the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 64 MB

EOL5018—Amended

Cisco[®] announces the end-of-sale and end-of life dates for the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 64 MB. The last day to order the affected product(s) is December 29, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Customers are encouraged to buy the 128-512 MB flash memory options.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 30, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 29, 2006
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 29, 2007
End of Routine Failure Analysis Date: HW	- · · · · · · · · · · · · · · · · · · ·	
End of New Service Attachment Date: HW	· · · · · · · · · · · · · · · · · · ·	
End of Service Contract Renewal Date: HW		
Last Date of Support: HW The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.		December 28, 2011

 Table 1.
 End-of-Life Milestones and Dates for the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 64 MB

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2.	Product Part Numbers Affected by This Announcement
----------	--

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
MEM-C6K-CPTFL64M	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL128M	Cat6500 Sup720/Sup32 Compact Flash Mem 128MB
MEM-C6K-CPTFL64M	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL256M	Cat6500 Sup720/Sup32 Compact Flash Mem 256MB
MEM-C6K-CPTFL64M	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL512M	Catalyst 6500 Sup720/Sup32 Compact Flash Mem 512MB

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
MEM-C6K-CPTFL64M=	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL128M=	Cat6500 Sup720/Sup32 Compact Flash Mem 128MB
MEM-C6K-CPTFL64M=	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL256M=	Cat6500 Sup720/Sup32 Compact Flash Mem 256MB
MEM-C6K-CPTFL64M=	Cat6500 Sup720/Sup32 Compact Flash Mem 64MB	MEM-C6K-CPTFL512M=	Catalyst 6500 Sup720/Sup32 Compact Flash Mem 512MB

Product Migration Options

The Cisco Catalyst 6500 Supervisor Engine 720/32 now requires at least 128 MB of compact flash memory. The recommended replacement for the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 64 MB is the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 128 MB,256 MB,or 512 MB Flash Memory.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco Catalyst 6500 Supervisor Engine 720/32 Compact Flash Memory 64 MB through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam. The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco Stadium/Vision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTinet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, I.e., and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0809R)

Printed in USA

C51-518103-00 01/09