

# Products with Impacted Component

Product Family	Product IDs (PIDs)
4300ISR	C1-CISCO4321/K9, C1-CISCO4331/K9 C1-CISCO4351/K9, ISR4321/K9, ISR4321-AX/K9, ISR4321-AXV/K9, ISR4321-SEC/K9, ISR4321-V/K9, ISR4321-VSEC/K9, ISR4331/K9, ISR4331-AX/K9, ISR4331-AXV/K9, ISR4331-SEC/K9, ISR4331-V/K9, ISR4331-VSEC/K9, ISR4351/K9, ISR4351-AX/K9, ISR4351-AXV/K9, ISR4351-SEC/K9, ISR4351-V/K9, ISR4351-VSEC/K9
APP	UCS-EN120E-108/K9, UCS-EN120E-208/K9, UCS- EN120E-54/K9, UCS-EN120E-58/K9
NCS1000	NCS1K-CNTLR
NCS5500	NC55-18H18F,NC55-24H12F-SE, NC55-24X100G- SE, NC55-36X100G, NCS-5508

# Products with Impacted Component (cont.)

Product Family	Product IDs (PIDs)
N9500	N9K-C9504-FM-E, N9K-C9508-FM-E, N9K-X9732C-EX
INDAPPL	1783-SAD2T2SBK9, 1783-SAD2T2SPK9, 1783-SAD4T0SBK9, 1783-SAD4T0SPK9, ISA-3000-2C2F-K9, ISA-3000-4C-K9
M2M800	IR809G-LTE-GA-K9, IR809G-LTE-NA-K9, IR809G-LTE-VZ-K9, IR829GW-LTE-GA-EK9, IR829GW-LTE-GA-ZK9, IR829GW-LTE-NA-AK9, IR829GW-LTE-VZ-AK9
CNSEC	MX84-HW

# Products with Impacted Component (cont.)

Product Family	Product IDs (PIDs)
CNSWTCH	MS350-24-HW, MS350-24P-HW, MS350-48-HW, MS350-48LP-HW, MS350-48FP-HW, MS350-24X-HW
ASALOW	ASA5506H-K9, ASA5506H-SP-BUN-K9, ASA5506-K8, ASA5506-K9, ASA5506-SEC-BUN-K8, ASA5506-SEC-BUN-K9, ASA5506W-A-K9, ASA5506W-B-K9, ASA5506W-E-K9, ASA5506W-Q-K9, ASA5506W-Z-K9
ASAMID	ASA5508-K8, ASA5508-K9, ASA5516-FPWR-K8, ASA5516-FPWR-K9