



## Caveats

- [Open Caveats in Cisco Smart PHY 22.1, on page 1](#)
- [Resolved Caveats in Cisco Smart PHY 22.1, on page 1](#)
- [Cisco Bug Search, on page 2](#)

### Open Caveats in Cisco Smart PHY 22.1

Caveat ID Number	Description
<a href="#">CSCwb20669</a>	RF power adjustment configuration not cleaned up properly in cBR8.
<a href="#">CSCwb06506</a>	No error message shown when 2x2 specific service definition changes are pushed to 1x1 RPDs.
<a href="#">CSCwb22367</a>	NDF/NDR profiles are not cleaned up properly in cBR8.
<a href="#">CSCwb33213</a>	OOB profiles are not cleaned up properly in cBR8.
<a href="#">CSCwb33603</a>	RPD edit operation not working for 1x2 RPD from Smart PHY UI; DS / US data service groups show "-".
<a href="#">CSCwb33699</a>	All RPDs are not listed in the UI on performing 'save & assign' after editing Service Definition.


### Resolved Caveats in Cisco Smart PHY 22.1

Caveat ID Number	Description
<a href="#">CSCwa16318</a>	'Container KPI Details' & 'Container KPI Overview' Dashboards are missing Data.
<a href="#">CSCwa22340</a>	Smart PHY 21.3 autodeployer mandates private-key-file tag in day 0.
<a href="#">CSCwa31101</a>	Sample Inventory and RPD Association CSV templates are broken.

# Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.



You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

