

## **New and Changed Information**

• New and Changed Information for This Release, on page 1

## **New and Changed Information for This Release**

The following table provides an overview of the significant changes to this guide for this current release. The table does not provide an exhaustive list of all changes made to this guide or of all new features in this release.

Table 1: New Features and Changed Behavior in Cisco UCS Manager, 3.2(3a)

| Feature   | Description   | Where Documented                    |
|---|---|-------------------------------------|
| 6G-12G Mixed Mode   | 6G-12G Mixed Mode is available for SAS Expander Configuration Policy.   |                                     |
| Single Path support for UCS S3260<br>Dual Pass Through<br>(UCS-S3260-DHBA) controller | In Cisco UCS S3260 M5 servers,<br>Cisco UCS Manager enables single<br>path access to disks by configuring<br>a single DiskPort per disk slot. | Disk Zoning Policies                |
| Extended support for Cisco UCS<br>S3260 M5 Server                                     | Cisco UCS Manager support for the UCS S3260 M5 rack-mount server.   | About the Cisco UCS S3260<br>System |

**New and Changed Information for This Release**