



New and Changed Information

- [New and Changed Information for This Release, on page 1](#)

New and Changed Information for This Release

This section provides information on new features and changed behavior in Cisco UCS Manager, Release 4.3.

Table 1: New Features and Changed Behavior in Cisco UCS Manager, 4.3(2c)

Feature	Description	Where Documented
Support Cisco UCS X-Series Server	Cisco UCS Manager supports Cisco UCS X410c M7 Compute Node. Cisco UCS X-Series servers support Intelligent Fabric Modules (IFM), which function similarly to the Input/Output Module (IOM) in Cisco UCS B-Series servers.	—

The following table provides an overview of the significant changes to this guide for this current release.

Table 2: New Features and Changed Behavior in Cisco UCS Manager, 4.3(2b)

Feature	Description	Where Documented
Deprecated support for Cisco UCS S3260 M4 server.	Cisco UCS Manager support for Cisco UCS S3260 M4 server is deprecated.	—
Deprecated support for Cisco UCS 6200 series Fabric Interconnect.	Cisco UCS Manager support for Cisco UCS 6200 Series Fabric Interconnect is deprecated.	—

