



Caveats

- [Open Caveats for Cisco cnBR 21.2, on page 1](#)
- [Resolved Caveats for Cisco cnBR 21.2, on page 2](#)
- [Cisco Bug Search, on page 2](#)

Open Caveats for Cisco cnBR 21.2

Caveat ID Number	Description
CSCvu83104	After Power outage, the cnBR is having issues with PTP pods sync and RPDs with late maps or no maps
CSCvw83313	No UGS US throughput if EMTA has PHS enabled
CSCvx49463	cnBR REST API returns 401 Unauthorized after UCS reboot
CSCvx77870	[voice] Arris 402p failed to ping after SG moves
CSCvx77873	48 SC-QAMs configured as Primary causes the CMs to fall offline and never recover
CSCvx81685	Cisco DPQ3212 failed to ping after UCS reloads
CSCvx85084	[voice] voice dropped with vswitch crash
CSCvy73075	Fail to ping D3.1 CMs after OFDM config is applied on DP successful
CSCvy77172	License consumption is not updated after deleting RPD
CSCvy79288	OOB-DS configs via Opshub API is not reflected in RPD
CSCvy79292	OPSHUB: OOB-DS :Duplicate entry of the channel ID is appended in RPD configs
CSCvy80627	redis cluster leader failure after 2 UCS Reload
CSCvy81922	D2.0 CMs dropped offline after usscheduler and vswitch restart
CSCvy82627	IPDR : Channels 48 and above are not exported to collector
CSCvy84288	Not getting any logs under auto-deploy-lo file while deploying the operations hub and cnBR

Caveat ID Number	Description
CSCvy86613	No data is displayed on OpsHub after fresh deployment
CSCvy88266	CM becomes unreachable after reboot one UCS
CSCvy88538	It takes an extra 13 min for one DP pod becomes ready after UCS reload
CSCvz00752	usscheduler keeps crash after run reboot_ccmts due to "Failed to connect to vswitch"

Resolved Caveats for Cisco cnBR 21.2

Caveat ID Number	Description
CSCvx81709	Audit log shows username field empty
CSCvx85079	[voice] making new calls failed after UCS reloads due to CMs being stuck at DbcInProgress and caused
CSCvx85128	Getting home page of Operations Hub while going to the edit mode of Cable Modem Basic Info panel und
CSCvx85151	RPD Add Operations with Video Services Fails when selected port is Downstream 1 (DS-1)
CSCvx86135	Default entitlements blocked when cmts-cp-mgmt-service is not ready
CSCvx86438	Failed to move SGs from Operations Hub for the first time after fresh deployment
CSCvx87009	The ranging pod wrongly mark down the upstream during startup
CSCvx87423	Video QAM: Operations Hub UI should support IPv6 format for the Source ID and Group ID fields.
CSCvx87738	cmts-entitlements service does not restart after config map update.

Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

Save Search Load Saved Search Clear Search Email Current Search

If you have a specific bug ID, enter it here

Search For:

Examples: CSCId10124, router crash, etc...

Product: Series/Model

Start typing product name to view suggestions or expand list to choose your product


Releases: Affecting or Fixed in these Releases

Enter release number

368025

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.


Save Search Load Saved Search Clear Search Email Current Search

Search For: 
Examples: CSCtd10124, router crash, etc...

Product: [Select from list](#)

Releases:

Filter:

Viewing 1 - 25 of 132 results Sort by  Export Results to Excel

368026

