



## Caveats

---

- [Cisco Bug Search](#), page 1
- [Open Caveats for Cisco ROMMON Release 15.0\(1r\)SQ1](#), page 1
- [Resolved Caveats for Cisco ROMMON Release 15.0\(1r\)SQ1](#), page 1
- [Open Caveats for Cisco ROMMON Release 15.0\(1r\)SQ](#), page 2

## Cisco Bug Search

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>.

## Open Caveats for Cisco ROMMON Release 15.0(1r)SQ1

Bug	Description
<a href="#">CSCtx44255</a>	date command incorrect in rommon

## Resolved Caveats for Cisco ROMMON Release 15.0(1r)SQ1

Bug	Description
<a href="#">CSCur17716</a>	Sg11 rommon:Usb is not detecting in sg11 rommon mode

## Open Caveats for Cisco ROMMON Release 15.0(1r)SQ

Bug	Description
CSCub34955	<p><b>Symptom:</b> On the first attempt, ROMMON for Cisco RFGW-10 Supervisor Engine 7-E fails to "dir usb0".</p> <p><b>Conditions:</b> This issue occurs under normal conditions.</p> <p><b>Workaround:</b> There is no workaround.</p>