



New and Changed Information

This document provides release-specific information for each new and changed feature in Cisco Data Mobility Manager.

The *Cisco MDS 9000 Family Data Mobility Manager Configuration Guide* applies to Cisco NX-OS Release 6.2(3) and earlier, but includes all features in Cisco SAN-OS releases. If you are running Cisco SAN-OS 3.x or lower software on an MDS switch, refer to the *Cisco MDS 9000 Family Data Mobility Manager Configuration Guide* for the release train that applies to the release on your switch.



Note

As of NX-OS Release 4.1(1b), SAN-OS has been changed to NX-OS. References to SAN-OS releases before 4.1(1b) still apply.

To check for additional information about this release, refer to the *Cisco MDS 9000 Family Release Notes for Cisco MDS NX-OS Releases* available at the following Cisco Systems website:

http://www.cisco.com/en/US/products/ps5989/prod_release_notes_list.html

Table 1 summarizes the new and changed features as described in the *Cisco MDS 9000 Family Data Mobility Manager Configuration Guide*, and tells you where they are documented. The table includes a brief description of each new feature and the release in which the change occurred.

Table 1 **New and Changed Features for Cisco Data Mobility Manager**

Feature	Description	Changed in Release	Where Documented
DMM	Updated the Limitations and Restrictions section for the bulk notification feature.	6.2(7)	Chapter 1, “Cisco MDS DMM Overview”
Cisco MDS 9250i Multiservice Fabric Switch	Added the support for Cisco MDS 9250i Multiservice Fabric Switch.	6.2(5)	Chapter 1, “Cisco MDS DMM Overview” Chapter 2, “Getting Started” Chapter 3, “Understanding DMM SAN Topologies”
Method 3	Deprecated Method 3	6.2(3)	—

Table 1 *New and Changed Features for Cisco Data Mobility Manager*

Feature	Description	Changed in Release	Where Documented
Greater than 2 Terabyte LUN support (Method 1 Only)	Added capability to migrate LUNs greater than 2TB (Method 1 Jobs only).	6.2(3)	Chapter 1, “Cisco MDS DMM Overview”
FC-Redirect on Cisco MDS 9710	Added support for hosts and storages connected to MDS 9710.	6.2(3)	Chapter 1, “Cisco MDS DMM Overview” Chapter 3, “Understanding DMM SAN Topologies”
There are no changes since 5.0(1a).	—	—	—
DMM Pre-Configuration Wizard	Steps and screenshots added to configure the MDS modules using the DMM Pre-Configuration Wizard.	5.0(1a)	Chapter 2, “Using the DMM Pre-Configuration Wizard”
CPP and default-gateway	Note added about configuring CPP interface default-gateway on Fabric Manager.	4.2(1)	Chapter 2, “Getting Started”