



## New and Changed Information

- [New and Changed Information for This Release, on page 1](#)

### New and Changed Information for This Release

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.0(4m).

**Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(4m)**

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect supports 16 unified ports.	With release 4.0(4m) and later Cisco UCS 6454 Fabric Interconnect supports 16 unified ports (ports 1 - 16).	<a href="#">Cisco UCS 6454 Fabric Interconnect</a>

The following table provides an overview of the significant changes to this guide for this current release. The table does not provide an exhaustive list of all changes made to this guide or of all new features in this release.

**Table 2: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(2)**

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect Enhancements	<p>This release introduces support for the following features on the Cisco UCS 6454 Fabric Interconnect:</p> <ul style="list-style-type: none"> <li>• Support for Ethernet and Fibre Channel switching modes.</li> <li>• Support for splitting a single 40/100G QSFP port into four 10/25G ports using a supported breakout cable.</li> <li>• Support for MAC Security on Cisco UCS 6454 Fabric Interconnects.</li> </ul>	<a href="#">Software Feature Configuration</a>

*Table 3: New Features and Changed Behavior in Cisco UCS Manager, Release 4.0(1)*

Feature	Description	Where Documented
Cisco UCS 6454 Fabric Interconnect	This release introduces Cisco UCS 6454 Fabric Interconnects that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	<a href="#">Cisco UCS 6454 Fabric Interconnect Overview</a>